

REPORT OF 040311

last update on Thu Mar 11 12:47:30 GMT 2004

1. [Introduction](#)
2. [Summary](#)
 - [Instrument Unavailability](#)
 - [Browse Visual Inspection](#)
 - [Module Stepping Results](#)
 - [Data Analysis](#)
3. [Module Stepping](#)
4. [Internal Calibration pulses](#)
 - [Daily statistics](#)
 - [Cyclic statistics](#)
 - [cal pulses monitoring \(all rows\)](#)
5. [Raw Data Statistics](#)
 - [raw data mean I and Q](#)
 - [raw data stdev I and Q](#)
 - [raw gain imbalance](#)
6. [Wave Doppler analysis](#)
 - [Unbiased Doppler Error](#)
 - [Absolute Doppler](#)
 - [Doppler evolution versus ANX](#)

1 - Introduction

This report is based on the analysis of wave mode level-1 cross spectra (ASA_WVS_1P) products, which are the available few hours after the acquisition, on the high rate browse (BP) products and on the Module Stepping (MS) product.

2 - Summary

2.1 - Instrument Unavailability

ASAR Antenna reset on 10-MAR-2004 14:36: to 14:41:24 due to OOL identified on tile E4 on 02:55:05 to 03:00:12.

2.2 - Browse Visual Inspection

No browse product acquired during the anomaly period has been received.

2.3 - Data Analysis

Internal cal pulse analysis of Wave products confirmed the anomaly detected on tile E4.
 All rows within the second part of the antenna (rows 17 to 32) are affected by a power drop in Tx of 1.5 to 6dB for P1 depending on the PSU affected.
 Anomaly has began on 2004-03-10 01:40:38 and has been stopped by the antenna reset.

- Stable raw data statistics.
- Nominal Doppler behavior.

3 - Module Stepping Mode

The MS mode provides an internal health check on an individual module basis.
 The purpose of this mode is to identify to identify any malfunctioning modules and to identify modules for which calibration offsets are to be applied.
 No anomalies observed on available MS products:

Polarisation	Start Time
V	20040304 202539
H	20040304 202419

MSM in V/V polarisation

Pre-launch Reference	DDS-B (2003-06-12) reference
⊗	⊗
⊗	⊗
⊗	⊗
⊗	⊗

MSM in H/H polarisation

Pre-launch Reference	DDS-B (2003-06-12) reference
⊗	⊗
⊗	⊗
⊗	⊗
⊗	⊗

4 - Internal calibration Results

Internal cal pulse analysis of Wave products confirmed the anomaly detected on tile E4.
 All rows within the second part of the antenna (rows 17 to 32) are affected by a power drop in Tx of 1.5 to 6dB for P1 depending on the PSU affected.

Anomaly has began on 2004-03-10 01:40:38 and has been stopped by the antenna reset.

4.1 - Daily statistics



4.2 - Cyclic statistics



4.3 - cal pulses monitoring (all rows)



5 - RAW data statistics

No anomalies observed.

5.1 - Input mean I/Q

channel	stat	DSS-B
MEAN I	mean	0.000466508
	stdev	2.43015e-07
MEAN Q	mean	0.000470080
	stdev	2.76986e-07



5.2 - Input stdev I/Q

channel	stat	DSS-B
STDEV I	mean	0.125771
	stdev	0.00117467
STDEV Q	mean	0.125998
	stdev	0.00118795



5.3 - Gain imbalance I/Q



6 - Wave Doppler Analysis

Preliminary report. The data is not yet controlled

6.1 - Unbiased Doppler Error

Evolution of unbiased Doppler error (Real - Expected)

Ascending

Descending

6.2 - Absolute Doppler

Evolution of Absolute Doppler




Ascending


Descending

6.3 - Doppler evolution versus ANX

Evolution Doppler error versus ANX








No browse product acquired during the anomaly period has been received.


Internal cal pulse analysis of Wave products confirmed the anomaly detected on tile E4.
All rows within the second part of the antenna (rows 17 to 32) are affected by a power drop in Tx of 1.5 to 6dB for P1 depending on the PSU affected.
Anomaly has began on 2004-03-10 01:40:38 and has been stopped by the antenna reset.




Internal cal pulse analysis of Wave products confirmed the anomaly detected on tile E4.
All rows within the second part of the antenna (rows 17 to 32) are affected by a power drop in Tx of 1.5 to 6dB for P1 depending on the PSU affected.
Anomaly has began on 2004-03-10 01:40:38 and has been stopped by the antenna reset.



- Stable raw data statistics.
- Nominal Doppler behavior.

Doppler 'WVS' 'IS2' 'H/H'




Doppler 'WVS' 'ISZ' 'V/V'






Doppler difference, estimated-predicted 'WVS' 'IS2' 'H/H' -error mean of -30.604329 Hz







Doppler difference, estimated-predicted 'WVS' 'IS2' 'V/V' -error mean of -29.046081 Hz






The MS mode provides an internal health check on an individual module basis.
The purpose of this mode is to identify to identify any malfunctioning modules and
to identify modules for which calibration offsets are to be applied.
No anomalies observed on available MS products:

No anomalies observed.







ASAR Antenna reset on 10-MAR-2004 14:36: to 14:41:24 due to OOL identified on tile E4 on 02:55:05 to 03:00:12.