

# PRELIMINARY REPORT OF 040416

ATTENTION: This report is automatically generated no comments are provided on data analysis

**last update on Fri Apr 16 12:40:01 GMT 2004**

1. [Introduction](#)
2. [Summary](#)
  - [Instrument Unavailability](#)
  - [Browse Visual Inspection](#)
  - [Module Stepping Results](#)
  - [Data Analysis](#)
3. [Module Stepping](#)
4. [Internal Calibration pulses](#)
  - [Daily statistics \(row 3 and 24\)](#)
  - [Cyclic statistics \(row 3 and 24\)](#)
  - [cal pulses monitoring \(all rows\)](#)
5. [Raw Data Statistics](#)
  - [raw data mean I and Q](#)
  - [raw data stdev I and Q](#)
  - [raw gain imbalance](#)
6. [Wave Doppler analysis](#)
  - [Doppler evolution versus ANX](#)

## 1 - Introduction

This report is based on the analysis of wave mode level-1 cross spectra (ASA\_WVS\_1P) products, which are the available few hours after the acquisition, on the high rate browse (BP) products and on the Module Stepping (MS) product.

## 2 - Summary

### 2.1 - Instrument Unavailability

No unavailabilities during the reported period.

### 2.2 - Browse Visual Inspection

No anomalies observed on available browse products.

## 2.3 - Data Analysis

- Stable wave internal calibration pulses gain and phase.
- Stable raw data statistics.
- Nominal Doppler behavior.

## 3 - Module Stepping Mode

The MS mode provides an internal health check on an individual module basis. The purpose of this mode is to identify any malfunctioning modules and to identify modules for which calibration offsets are to be applied. The MS products analysis shows a failure in TX module 30 tile B2, since 12-APR-2004. Investigations are on going.

- ASA\_MS\_\_0PNPDK20040415\_200410\_000000152026\_00042\_11118\_0074.N1
- ASA\_MS\_\_0PNPDK20040415\_200530\_000000152026\_00042\_11118\_0075.N1

Polarisation	Start Time
V	20040415 200530
H	20040415 200410

### MSM in V/V polarisation

Pre-launch Reference	DDS-B (2003-06-12) reference
<input type="checkbox"/>	<input type="checkbox"/>

### MSM in H/H polarisation

Pre-launch Reference	DDS-B (2003-06-12) reference
<input type="checkbox"/>	<input type="checkbox"/>

## 4 - Internal calibration Results

No anomalies observed.

#### 4.1 - Daily statistics



#### 4.2 - Cyclic statistics



#### 4.3 - cal pulses monitoring (all rows)



### 5 - RAW data statistics

No anomalies observed.

#### 5.1 - Input mean I/Q

channel	stat	DSS-B
MEAN I	mean	0.000476632
	stdev	2.38120e-07
MEAN Q	mean	0.000482490
	stdev	2.69359e-07



#### 5.2 - Input stdev I/Q

channel	stat	DSS-B
STDEV I	mean	0.127629
	stdev	0.00118623
STDEV Q	mean	0.127882
	stdev	0.00119985



### 5.3 - Gain imbalance I/Q



## 6 - Doppler Analysis

Analysis performed over the last 35 days.

The difference from the reference trend is due to the OCM (manoeuvre) occurred on 14-APR-2004.

### 6.1 - Unbiased Doppler Error

#### Evolution of unbiased Doppler error (Real - Expected)

Ascending
Descending

### 6.2 - Absolute Doppler

#### Evolution of Absolute Doppler

Ascending
Descending




### 6.3 - Doppler evolution versus ANX

#### Evolution Doppler error versus ANX




#### Evolution Doppler error versus ANX






rows: \_ 3 \_ 7 \_ 11 \_ 15 \_ 19 \_ 22 \_ 24 \_ 28



No anomalies observed on available browse products.


No anomalies observed.




- Stable wave internal calibration pulses gain and phase.
- Stable raw data statistics.
- Nominal Doppler behavior.



Analysis performed over the last 35 days.  
The difference from the reference trend is due to the OCM (manoeuvre) occurred on 14-APR-2004.



Doppler 'WVS' 'IS2' 'H/H'




Doppler 'WVS' 'IS2' 'V/V'








Doppler difference, estimated-predicted 'WVS' 'IS2' 'H/H' -error mean of -35.856091 Hz



Doppler difference, estimated-predicted 'WVS' 'IS2' 'V/V' -error mean of -32.531538 Hz



The MS mode provides an internal health check on an individual module basis.  
The purpose of this mode is to identify to identify any malfunctioning modules and  
to identify modules for which calibration offsets are to be applied.  
The MS products analysis shows a failure in TX module 30 tile B2, since 12-APR-2004.  
Investigations are on going.

- ASA\_MS\_\_0PNPDK20040415\_200410\_000000152026\_00042\_11118\_0074.N1
- ASA\_MS\_\_0PNPDK20040415\_200530\_000000152026\_00042\_11118\_0075.N1

No anomalies observed.
















































































No unavailabilities during the reported period.