Analysis from 29-SEP-2008 00:00:00 to 29-SEP-2008 23:59:59. Page generated on 30-SEP-2008 07:48:25.
View log file: ASAR_Daily_Report_20080930_0730.log. For any anomalies please contact mtranfaglia@serco.it,gscarpino@serco.it.

This report is automatically generated every day, every 2 hours. No comments are provided on the results.

SUMMARY

1. DATA SUMMARY
1.1 Summary tables
1.2 Lists of products used

2. AUXILIARY FILES ANALYSIS
2.1 IECF operational ADFs list
2.2 Products with wrong ADFs

3. MODULE STEPPING PRODUCTS ANALYSIS
3.1 V/V polarisation
3.2 H/H polarisation

4. CALIBRATION PULSES ANALYSIS
4.1 Analysis for WVS IS2 V/V
4.1.1 Temporal Evolution Analysis for WVS IS2 V/V
4.1.2 All Rows Analysis for WVS IS2 V/V
4.2 Analysis for GM1 SS3 H/H
4.2.1 Temporal Evolution Analysis for GM1 SS3 H/H
4.2.2 All Rows Analysis for GM1 SS3 H/H

5. DOPPLER ANALYSIS
5.1 Analysis for WVS IS2 V/V
5.1.1 Doppler MAP Analysis for WVS IS2 V/V
5.1.2 Doppler ANX Analysis for WVS IS2 V/V
5.2 Analysis for GM1 SS1 H/H
5.2.1 Doppler MAP Analysis for GM1 SS1 H/H
5.2.2 Doppler ANX Analysis for GM1 SS1 H/H
5.3 Doppler JUMPS Analysis for WSM

6. CHIRP ANALYSIS
6.1 Analysis for WSM SS1 H/H
6.1.1 ScaleFactor
6.2 Analysis for WSM SS1 V/V
6.2.1 ScaleFactor

7. RAW DATA ANALYSIS
7.1 Analysis for WVS
7.2 Analysis for IMM

8. TELEMETRY ANALYSIS
8.1 Number of Missing Lines
8.2 Number of Gaps

---

1 - DATA SUMMARY

1.1 - Summary tables

[BACK TO MENU]

WVS			
Center	Beam	Pol	#
PDE	IS1	V/V	3
PDE	IS2	V/V	26
PDK	IS2	V/V	24

GM1			
Center	Beam	Pol	#
PDE	WS	H/H	37
PDK	WS	H/H	41

APM			
Center	Beam	Pol	#
PDE	IS3	H/V	2
PDE	IS7	H/H	1
PDK	IS7	***	1

IMM			
Center	Beam	Pol	#
PDE	IS1	V/V	1
PDE	IS2	H/H	20
PDE	IS2	V/V	14
PDE	IS3	H/H	1
PDE	IS6	H/H	1
PDE	IS6	V/V	1
PDK	IS2	H/H	2
PDK	IS2	V/V	4
PDK	IS7	V/V	2

WSM			
Center	Beam	Pol	#
PDE	WS	H/H	16
PDE	WS	V/V	2

MS			
Center	Time	Pol	Modules
PDE	2008-09-29 01:59:21	H	320
PDK	2008-09-29 08:41:45	V	320

1.2 - Lists of products used

[BACK TO MENU]

[TXT] [XLS] List_WVS_products_used
[TXT] [XLS] List_GM1_products_used
[TXT] [XLS] List_APM_products_used
[TXT] [XLS] List_IMM_products_used
[TXT] [XLS] List_WSM_products_used
[TXT] [XLS] List_MS_products_used

2 - AUXILIARY FILES ANALYSIS

2.1 - IECF operational ADFs list

[BACK TO MENU]

ADFs disseminated for ASAR
ASA_CON_AXVIEC20080710_132557_20070204_165113_20081231_000000
ASA_INS_AXVIEC20071218_083603_20070307_060000_20081231_000000
ASA_XCH_AXVIEC20051219_162547_20020301_000000_20081231_000000
ASA_XCA_AXVIEC20080710_133546_20070204_165113_20081231_000000

2.2 - Products with wrong ADFs

[BACK TO MENU]

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
WVS	0	0	0	0
GM1	0	0	0	0
APM	0	0	0	0
IMM	0	0	0	0
WSM	0	0	0	0

[TXT] [XLS] Check_ADFs_WVS
[TXT] [XLS] Check_ADFs_GM1
[TXT] [XLS] Check_ADFs_APM
[TXT] [XLS] Check_ADFs_IMM
[TXT] [XLS] Check_ADFs_WSM

3 - MODULE STEPPING PRODUCTS ANALYSIS

SECOND FIXED REFERENCE	PREVIOUS PRODUCT REFERENCE
After antenna maintenance (2005-09-22/23)	Previous product in the same polarisation
	
	



3.2 - H/H polarisation

[BACK TO MENU]

SECOND FIXED REFERENCE	PREVIOUS PRODUCT REFERENCE
After antenna maintenance (2005-09-22/23)	Previous product in the same polarisation


Reference: 2005-09-22 06:26:51 H
Test : 2008-09-29 01:59:21 H
RxGain
A1 A3 B1 B3 C1 C3 D1 D3 E1 E3
A2 A4 B2 B4 C2 C4 D2 D4 E2 E4

Reference: 2008-09-27 03:02:35 H
Test : 2008-09-29 01:59:21 H
RxGain
A1 A3 B1 B3 C1 C3 D1 D3 E1 E3
A2 A4 B2 B4 C2 C4 D2 D4 E2 E4

Reference: 2005-09-22 06:26:51 H
Test : 2008-09-29 01:59:21 H
RxPhase
A1 A3 B1 B3 C1 C3 D1 D3 E1 E3
A2 A4 B2 B4 C2 C4 D2 D4 E2 E4

Reference: 2008-09-27 03:02:35 H
Test : 2008-09-29 01:59:21 H
RxPhase
A1 A3 B1 B3 C1 C3 D1 D3 E1 E3
A2 A4 B2 B4 C2 C4 D2 D4 E2 E4







---

4 - CALIBRATION PULSES ANALYSIS

4.1 - Analysis for WVS IS2 V/V

4.1.1 - Temporal Evolution Analysis for WVS IS2 V/V

[BACK TO MENU]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]	Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]





4.1.2 - **All Rows Analysis for WVS IS2 V/V**

[BACK TO MENU]



4.2 - Analysis for GM1 SS3 H/H

4.2.1 - Temporal Evolution Analysis for GM1 SS3 H/H

[BACK TO MENU]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]	Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]





4.2.2 - **All Rows Analysis for GM1 SS3 H/H**

[BACK TO MENU]



5 - DOPPLER ANALYSIS

5.1 - Analysis for WVS IS2 V/V

5.1.1 - Doppler MAP Analysis for WVS IS2 V/V

[BACK TO MENU]









5.1.2 - Doppler ANX Analysis for WVS IS2 V/V

[BACK TO MENU]



5.2 - Analysis for GM1 SS1 H/H

5.2.1 - Doppler MAP Analysis for GM1 SS1 H/H

[BACK TO MENU]









5.2.2 - Doppler ANX Analysis for GM1 SS1 H/H

[BACK TO MENU]



5.3 - **Doppler JUMPS Analysis for WSM**

[BACK TO MENU]





6 - CHIRP ANALYSIS

6.1 - Analysis for WSM SS1 H/H

6.1.1 - ScaleFactor

[BACK TO MENU]





6.2 - Analysis for WSM SS1 V/V

6.2.1 - ScaleFactor

[BACK TO MENU]





7 - RAW DATA ANALYSIS

7.1 - Analysis for WVS

[BACK TO MENU]







Channel	Statistics	DSS-B
MEAN I	mean	0.000515404
	stdev	1.95180e-07
MEAN Q	mean	0.000480520
	stdev	2.62693e-07
Channel	Statistics	DSS-B
STDEV I	mean	0.133094
	stdev	0.00128871
STDEV Q	mean	0.133502
	stdev	0.00130803

7.2 - Analysis for IMM

[BACK TO MENU]







Channel	Statistics	DSS-B
MEAN I	mean	0.000274084
	stdev	1.05894e-08
MEAN Q	mean	0.000503332
	stdev	7.96320e-09
Channel	Statistics	DSS-B
STDEV I	mean	0.0818193
	stdev	0.000803058
STDEV Q	mean	0.0821375
	stdev	0.000812077

8 - TELEMETRY ANALYSIS

Processing Center	Product	Gaps	Missing lines
PDE	ASA_WSM_1PNPDE20080929_000024_000000922072_00288_34410_1594.N1	0	35

8.1 - Number of Missing lines

[BACK TO MENU]



8.2 - Number of Gaps

[BACK TO MENU]



All rights reserved to Serco S.p.A., Via XX Settembre, 1 - 00187 Roma - Italy.
In particular, but not limited to:
(a) Modification, reverse engineering or distribution is not permitted in any form.
(b) Usage is restricted to Serco S.p.A. employee belonging to the above Contract Reference.
Any deviation from above rules requires an explicit prior written authorisation of Serco S.p.A.

```
######################################################################
ASAR DAILY REPORT for 080929
######################################################################

MODE: DAILY
ANALYSIS: ALL
DATE: YESTERDAY

Analysis will be performed from 2008-09-29 00:00:00 to 2008-09-29 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/080929/


DATA SUMMARY
######################################################################
Summary will be performed from 2008-09-29 00:00:00 to 2008-09-29 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/080929/DATA_SUMMARY

Creating directory ./RESULTS/DAILY/080929/DATA_SUMMARY...
Writing file ./RESULTS/DAILY/080929/DATA_SUMMARY/Data_summary.html...

**************************************************
Getting WVS products list from 2008-09-29 00:00:00 to 2008-09-29 23:59:59...
Writing file ./RESULTS/DAILY/080929/DATA_SUMMARY/List_WVS_products_used.xls...
Writing file ./RESULTS/DAILY/080929/DATA_SUMMARY/List_WVS_products_used.txt...

**************************************************
Getting GM1 products list from 2008-09-29 00:00:00 to 2008-09-29 23:59:59...
Writing file ./RESULTS/DAILY/080929/DATA_SUMMARY/List_GM1_products_used.xls...
Writing file ./RESULTS/DAILY/080929/DATA_SUMMARY/List_GM1_products_used.txt...

**************************************************
Getting APM products list from 2008-09-29 00:00:00 to 2008-09-29 23:59:59...
Writing file ./RESULTS/DAILY/080929/DATA_SUMMARY/List_APM_products_used.xls...
Writing file ./RESULTS/DAILY/080929/DATA_SUMMARY/List_APM_products_used.txt...

**************************************************
Getting IMM products list from 2008-09-29 00:00:00 to 2008-09-29 23:59:59...
Writing file ./RESULTS/DAILY/080929/DATA_SUMMARY/List_IMM_products_used.xls...
Writing file ./RESULTS/DAILY/080929/DATA_SUMMARY/List_IMM_products_used.txt...

**************************************************
Getting WSM products list from 2008-09-29 00:00:00 to 2008-09-29 23:59:59...
Writing file ./RESULTS/DAILY/080929/DATA_SUMMARY/List_WSM_products_used.xls...
Writing file ./RESULTS/DAILY/080929/DATA_SUMMARY/List_WSM_products_used.txt...

**************************************************
Getting MS products list from 2008-09-29 00:00:00 to 2008-09-29 23:59:59...
Writing file ./RESULTS/DAILY/080929/DATA_SUMMARY/List_MS_products_used.xls...
Writing file ./RESULTS/DAILY/080929/DATA_SUMMARY/List_MS_products_used.txt...

DATA SUMMARY completed
######################################################################



AUXILIARY FILES ANALYSIS
######################################################################
Analysis will be performed from 2008-09-29 00:00:00 to 2008-09-29 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/080929/AUXILIARY

Creating directory ./RESULTS/DAILY/080929/AUXILIARY...


**************************************************
Looking for the IECF operational ADFs list...
```

```
Found list 20080929_030001_current_3_IECF_ADFs.txt...
Extracting ADFs...

       ASA_CON_AXVIEC20080710_132557_20070204_165113_20081231_000000
       ASA_INS_AXVIEC20071218_083603_20070307_060000_20081231_000000
       ASA_XCH_AXVIEC20051219_162547_20020301_000000_20081231_000000
       ASA_XCA_AXVIEC20080710_133546_20070204_165113_20081231_000000

Writing file ./RESULTS/DAILY/080929/AUXILIARY/ASAR_ADFs_IECF_List3.html...
Writing file ./RESULTS/DAILY/080929/AUXILIARY/Auxiliary_files_summary.html...


*****************************************************
Analysing WVS products...

Writing file ./RESULTS/DAILY/080929/AUXILIARY/Check_ADFs_WVS.xls...
Writing file ./RESULTS/DAILY/080929/AUXILIARY/Check_ADFs_WVS.txt...


ASA_WVS_1PNPDE20080929_000154_000001342072_00288_34410_1478.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080929_001145_000002852072_00288_34410_1483.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080929_003621_000003142072_00288_34410_1488.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080929_004036_000004342072_00288_34410_1610.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080929_005110_000009442072_00288_34410_1615.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080929_013243_000008852072_00289_34411_1626.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080929_015054_000003752072_00289_34411_1629.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080929_021657_000000152072_00289_34411_1632.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080929_021657_000002852072_00289_34411_1783.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080929_031907_000008242072_00290_34412_1788.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080929_033236_000002402072_00290_34412_1885.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080929_040030_000009442072_00290_34412_1948.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080929_045957_000008542072_00291_34413_1951.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080929_051342_000002852072_00291_34413_2066.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080929_053809_000014542072_00291_34413_2097.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080929_064410_000001342072_00292_34414_2094.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080929_064749_000004642072_00292_34414_2091.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080929_195222_000018892072_00300_34422_2395.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080929_204332_000000452072_00300_34422_2403.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080929_204332_000001502072_00300_34422_2538.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080929_213509_000017542072_00301_34423_2547.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080929_222408_000002252072_00301_34423_2563.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080929_222708_000007792072_00301_34423_2692.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080929_224818_000005092072_00302_34424_2697.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080929_231413_000012442072_00302_34424_2704.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080929_234117_000002252072_00302_34424_2724.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080929_065519_000002252072_00292_34414_9225.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080929_071845_000018292072_00292_34414_9263.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080929_083227_000004202072_00293_34415_9327.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080929_085921_000019492072_00293_34415_9348.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080929_100414_000009592072_00294_34416_9511.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080929_103956_000002102072_00294_34416_9506.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080929_104524_000014092072_00294_34416_9521.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080929_112744_000007342072_00295_34417_9626.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080929_114205_000011242072_00295_34417_9631.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080929_122032_000003152072_00295_34417_9634.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080929_123036_000010212072_00295_34417_9650.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080929_130954_000005092072_00296_34418_9760.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080929_132040_000002092072_00296_34418_9778.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080929_140108_000003302072_00296_34418_9783.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080929_141300_000001492072_00296_34418_9771.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080929_141701_000001942072_00297_34419_9786.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080929_150902_000004042072_00297_34419_9896.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080929_151857_000001802072_00297_34419_9899.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080929_154144_000012442072_00297_34419_9908.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080929_164301_000011692072_00298_34420_0023.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080929_172220_000012442072_00298_34420_0033.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080929_181843_000014692072_00299_34421_0142.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080929_190459_000005692072_00299_34421_0147.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```

```
ASA_WVS_1PNPDK20080929_191617_000000742072_00299_34421_0152.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK


*****************************************************
Analysing GM1 products...

Writing file ./RESULTS/DAILY/080929/AUXILIARY/Check_ADFs_GM1.xls...
Writing file ./RESULTS/DAILY/080929/AUXILIARY/Check_ADFs_GM1.txt...


ASA_GM1_1PNPDE20080929_000447_000004162072_00288_34410_1480.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080929_001718_000003262072_00288_34410_1485.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080929_003226_000002292072_00288_34410_1495.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080929_004827_000001632072_00288_34410_1607.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080929_011419_000009302072_00289_34411_1612.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080929_013058_000001022072_00289_34411_1623.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080929_014806_000001692072_00289_34411_1621.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080929_015754_000000842072_00289_34411_1619.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080929_020455_000003742072_00289_34411_1634.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080929_021244_000002472072_00289_34411_1636.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080929_022226_000007732072_00289_34411_1769.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080929_024537_000004652072_00290_34412_1767.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080929_025410_000009902072_00290_34412_1845.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080929_031601_000001812072_00290_34412_1785.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080929_033948_000000782072_00290_34412_1882.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080929_035443_000003442072_00290_34412_1931.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080929_042133_000017402072_00291_34413_2023.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080929_045540_000002532072_00291_34413_1945.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080929_051906_000001812072_00291_34413_2061.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080929_053420_000002292072_00291_34413_2063.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080929_060314_000008212072_00292_34414_2068.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080929_061836_000001262072_00292_34414_2070.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080929_062718_000010092072_00292_34414_2163.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080929_193843_000008152072_00300_34422_2392.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080929_202429_000002352072_00300_34422_2388.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080929_203302_000000842072_00300_34422_2390.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080929_203859_000002712072_00300_34422_2405.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080929_205138_000010262072_00300_34422_2549.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080929_212343_000005432072_00301_34423_2540.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080929_220505_000001442072_00301_34423_2544.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080929_221145_000001502072_00301_34423_2542.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080929_222019_000002292072_00301_34423_2565.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080929_224045_000002292072_00302_34424_2694.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080929_230333_000004892072_00302_34424_2699.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080929_233548_000002232072_00302_34424_2701.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080929_233934_000001022072_00302_34424_2706.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080929_234541_000001262072_00302_34424_2721.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080929_065942_000002232072_00292_34414_9222.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080929_071409_000002712072_00292_34414_9227.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080929_075118_000000842072_00293_34415_9229.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080929_075402_000000782072_00293_34415_9231.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080929_080050_000001382072_00293_34415_9265.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080929_080223_000005612072_00293_34415_9320.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080929_082223_000006042072_00293_34415_9322.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080929_084018_000000842072_00293_34415_9324.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080929_084303_000009732072_00293_34415_9416.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080929_093227_000004342072_00294_34416_9338.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080929_095458_000003082072_00294_34416_9499.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080929_100212_000001202072_00294_34416_9501.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080929_102054_000002952072_00294_34416_9503.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080929_103320_000003922072_00294_34416_9508.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080929_111555_000001632072_00295_34417_9518.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080929_120130_000001322072_00295_34417_9628.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080929_121613_000002592072_00295_34417_9636.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080929_122632_000002412072_00295_34417_9638.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080929_124817_000002652072_00296_34418_9640.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080929_125624_000004412072_00296_34418_9647.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080929_130241_000004282072_00296_34418_9762.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```

```
ASA_GM1_1PNPDK20080929_132459_000006522072_00296_34418_9764.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080929_133558_000012572072_00296_34418_9856.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080929_135849_000001382072_00296_34418_9780.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080929_140724_000002832072_00296_34418_9775.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080929_142343_000001322072_00297_34419_9773.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080929_142657_000006882072_00297_34419_9793.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080929_144621_000005192072_00297_34419_9891.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080929_150422_000002772072_00297_34419_9893.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080929_152241_000011422072_00297_34419_9982.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080929_161057_000002292072_00298_34420_9905.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080929_162741_000009182072_00298_34420_0016.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080929_170317_000003562072_00298_34420_0020.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080929_171248_000002052072_00298_34420_0018.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080929_171927_000001692072_00298_34420_0025.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080929_174758_000004042072_00299_34421_0035.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080929_180933_000003862072_00299_34421_0137.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080929_184353_000003862072_00299_34421_0139.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080929_185253_000006042072_00299_34421_0144.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080929_191821_000001442072_00299_34421_0149.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080929_192515_000003202072_00300_34422_0159.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK


*****************************************************
Analysing APM products...

Writing file ./RESULTS/DAILY/080929/AUXILIARY/Check_ADFs_APM.xls...
Writing file ./RESULTS/DAILY/080929/AUXILIARY/Check_ADFs_APM.txt...


ASA_APM_1PNPDE20080929_082017_000001062072_00293_34415_2218.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20080929_082121_000000422072_00293_34415_2208.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20080929_142554_000000432072_00297_34419_2273.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDK20080929_193108_000000102072_00300_34422_0135.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

*****************************************************
Analysing IMM products...

Writing file ./RESULTS/DAILY/080929/AUXILIARY/Check_ADFs_IMM.xls...
Writing file ./RESULTS/DAILY/080929/AUXILIARY/Check_ADFs_IMM.txt...


ASA_IMM_1PNPDE20080929_002242_000005742072_00288_34410_1599.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080929_012956_000000502072_00289_34411_1617.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080929_021111_000000832072_00289_34411_1720.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080929_024448_000000372072_00290_34412_1753.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080929_025320_000000372072_00290_34412_1775.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080929_031036_000003152072_00290_34412_1847.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080929_034103_000003222072_00290_34412_1862.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080929_034703_000004502072_00290_34412_2015.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080929_045034_000002962072_00291_34413_2005.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080929_052203_000002032072_00291_34413_2025.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080929_052603_000004832072_00291_34413_2059.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080929_064714_000000282072_00292_34414_2057.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080929_070326_000003222072_00292_34414_2181.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080929_102547_000003222072_00294_34416_2243.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080929_141216_000000372072_00296_34418_2266.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080929_141603_000000522072_00296_34418_2271.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080929_145458_000000372072_00297_34419_2275.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080929_160413_000003932072_00298_34420_2299.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080929_170915_000002012072_00298_34420_2335.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080929_171612_000000832072_00298_34420_2305.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080929_171754_000000832072_00298_34420_2311.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080929_174348_000002382072_00299_34421_2343.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080929_181558_000001592072_00299_34421_2378.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080929_185020_000001412072_00299_34421_2380.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080929_191504_000000672072_00299_34421_2384.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080929_192046_000001282072_00300_34422_2525.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```

```
ASA_IMM_1PNPDE20080929_192329_000000952072_00300_34422_2382.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080929_202826_000002642072_00300_34422_2527.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080929_203426_000002612072_00300_34422_2529.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080929_211131_000000532072_00301_34423_2551.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080929_213314_000001092072_00301_34423_2654.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080929_221012_000000792072_00301_34423_2656.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080929_221416_000003532072_00301_34423_2674.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080929_224430_000002212072_00302_34424_2679.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080929_224430_000002212072_00302_34424_2681.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080929_224430_000002212072_00302_34424_2983.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080929_234749_000001212072_00302_34424_2806.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080929_235046_000005752072_00302_34424_2833.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20080929_070926_000002732072_00292_34414_9305.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20080929_074958_000000702072_00293_34415_9303.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20080929_094736_000000372072_00294_34416_9451.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20080929_095128_000000852072_00294_34416_9466.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20080929_120843_000004392072_00295_34417_9743.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20080929_193138_000004132072_00300_34422_0242.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20080929_211201_000000362072_00301_34423_0259.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20080929_225724_000000372072_00302_34424_0285.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK


*****************************************************
Analysing WSM products...

Writing file ./RESULTS/DAILY/080929/AUXILIARY/Check_ADFs_WSM.xls...
Writing file ./RESULTS/DAILY/080929/AUXILIARY/Check_ADFs_WSM.txt...


ASA_WSM_1PNPDE20080929_000024_000000922072_00288_34410_1594.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080929_010743_000003912072_00289_34411_1745.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080929_020146_000000732072_00289_34411_1714.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080929_020146_000001822072_00289_34411_1877.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080929_020400_000000482072_00289_34411_1718.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080929_061702_000000732072_00292_34414_2037.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080929_061702_000000732072_00292_34414_2177.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080929_061702_000000732072_00292_34414_2222.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080929_075914_000000912072_00293_34415_2210.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080929_135659_000001032072_00296_34418_2281.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080929_151628_000001352072_00297_34419_2283.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080929_162450_000001642072_00298_34420_2347.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080929_162603_000000902072_00298_34420_2341.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080929_180444_000001282072_00299_34421_2345.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080929_180541_000002262072_00299_34421_2386.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080929_204650_000002872072_00300_34422_2535.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080929_220736_000001342072_00301_34423_2683.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080929_231143_000001522072_00302_34424_2828.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK


AUXILIARY FILES ANALYSIS completed
#####################################################################




MODULE STEPPING ANALYSIS
#####################################################################
Analysis will be performed from 2008-09-29 00:00:00 to 2008-09-29 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/080929/MODULE_STEPPING

Creating directory ./RESULTS/DAILY/080929/MODULE_STEPPING...
Creating directory ./RESULTS/DAILY/080929/MODULE_STEPPING/FIRST_REFERENCE...
Creating directory ./RESULTS/DAILY/080929/MODULE_STEPPING/SECOND_REFERENCE...
Creating directory ./RESULTS/DAILY/080929/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE...
Deleting old files...

*****************************************************************************************************************
*****************************************************************************************************************
```

```
Creating images comparing with second reference...

Exporting results to the directory ../../RESULTS/DAILY/080929/MODULE_STEPPING/SECOND_REFERENCE...

Polarization:  H
Reference product:  ASA_MS__0PNPDK20050922_062651_000000152041_00034_18625_0041.N1
Test product: ASA_MS__0PNPDE20080929_015921_000000162072_00289_34411_0339.N1
      H
      H
../../RESULTS/DAILY/080929/MODULE_STEPPING/SECOND_REFERENCE/TGH_20080929_015921-20050922_062651.png
../../RESULTS/DAILY/080929/MODULE_STEPPING/SECOND_REFERENCE/TPH_20080929_015921-20050922_062651.png
../../RESULTS/DAILY/080929/MODULE_STEPPING/SECOND_REFERENCE/RGH_20080929_015921-20050922_062651.png
../../RESULTS/DAILY/080929/MODULE_STEPPING/SECOND_REFERENCE/RPH_20080929_015921-20050922_062651.png

Polarization:  V
Reference product:  ASA_MS__0PNPDK20050923_055514_000000152041_00048_18639_0042.N1
Test product: ASA_MS__0PNPDK20080929_084145_000000162072_00293_34415_0646.N1
      V
      V
../../RESULTS/DAILY/080929/MODULE_STEPPING/SECOND_REFERENCE/TGV_20080929_084145-20050923_055514.png
../../RESULTS/DAILY/080929/MODULE_STEPPING/SECOND_REFERENCE/TPV_20080929_084145-20050923_055514.png
../../RESULTS/DAILY/080929/MODULE_STEPPING/SECOND_REFERENCE/RGV_20080929_084145-20050923_055514.png
../../RESULTS/DAILY/080929/MODULE_STEPPING/SECOND_REFERENCE/RPV_20080929_084145-20050923_055514.png

**********************************************************************************************************
**********************************************************************************************************
Creating images comparing with previous product reference...

Exporting results to the directory ../../RESULTS/DAILY/080929/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE...

Polarization:  H
Reference product:  ASA_MS__0PNPDE20080927_030235_000000162072_00261_34383_0337.N1
Test product: ASA_MS__0PNPDE20080929_015921_000000162072_00289_34411_0339.N1
      H
      H
../../RESULTS/DAILY/080929/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TGH_20080929_015921-20080927_030235.png
../../RESULTS/DAILY/080929/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TPH_20080929_015921-20080927_030235.png
../../RESULTS/DAILY/080929/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RGH_20080929_015921-20080927_030235.png
../../RESULTS/DAILY/080929/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RPH_20080929_015921-20080927_030235.png

Polarization:  V
Reference product:  ASA_MS__0PNPDE20080928_023058_000000162072_00275_34397_0338.N1
Test product: ASA_MS__0PNPDK20080929_084145_000000162072_00293_34415_0646.N1
      V
      V
../../RESULTS/DAILY/080929/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TGV_20080929_084145-20080928_023058.png
../../RESULTS/DAILY/080929/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TPV_20080929_084145-20080928_023058.png
../../RESULTS/DAILY/080929/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RGV_20080929_084145-20080928_023058.png
../../RESULTS/DAILY/080929/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RPV_20080929_084145-20080928_023058.png

MODULE_STEPPING ANALYSIS completed
######################################################################




CALIBRATION PULSES ANALYSIS
######################################################################
Creating directory ./RESULTS/DAILY/080929/CALIBRATION_PULSES...


**********************************************************************************************
**********************************************************************************************
ALL ROWS Analysis will be performed from 2008-09-29 00:00:00 to 2008-09-29 23:59:59

Analysing products WVS IS2 V/V
Writing image ../.././RESULTS/DAILY/080929//CALIBRATION_PULSES/Calibration_pulses_all_rows_WVS_IS2_VV.png...
Analysing products GM1 SS3 H/H
```

```
Writing image ../.././RESULTS/DAILY/080929//CALIBRATION_PULSES/Calibration_pulses_all_rows_GM1_SS3_HH.png...


*****************************************************************************************
*****************************************************************************************
TEMPORAL EVOLUTION Analysis will be performed from 2008-09-29 00:00:00 to 2008-09-29 23:59:59

Analysing products WVS IS2 V/V
Getting calibration pulses data for WVS IS2 V/V from 2008-09-29 00:00:00 to 2008-09-29 23:59:59. Rows: 1/5/9/13/17/21/25/29
Writing file ./RESULTS/DAILY/080929/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2008-09-29_1.dat...
Writing ../.././RESULTS/DAILY/080929//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_1.png...
Writing ../.././RESULTS/DAILY/080929//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_1.png...


Getting calibration pulses data for WVS IS2 V/V from 2008-09-29 00:00:00 to 2008-09-29 23:59:59. Rows: 2/6/10/14/18/22/26/30
Writing file ./RESULTS/DAILY/080929/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2008-09-29_2.dat...
Writing ../.././RESULTS/DAILY/080929//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_2.png...
Writing ../.././RESULTS/DAILY/080929//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_2.png...


Getting calibration pulses data for WVS IS2 V/V from 2008-09-29 00:00:00 to 2008-09-29 23:59:59. Rows: 3/7/11/15/19/23/27/31
Writing file ./RESULTS/DAILY/080929/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2008-09-29_3.dat...
Writing ../.././RESULTS/DAILY/080929//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_3.png...
Writing ../.././RESULTS/DAILY/080929//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_3.png...


Getting calibration pulses data for WVS IS2 V/V from 2008-09-29 00:00:00 to 2008-09-29 23:59:59. Rows: 4/8/12/16/20/24/28/32
Writing file ./RESULTS/DAILY/080929/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2008-09-29_4.dat...
Writing ../.././RESULTS/DAILY/080929//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_4.png...
Writing ../.././RESULTS/DAILY/080929//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_4.png...


Analysing products GM1 SS3 H/H
Getting calibration pulses data for GM1 SS3 H/H from 2008-09-29 00:00:00 to 2008-09-29 23:59:59. Rows: 1/5/9/13/17/21/25/29
Writing file ./RESULTS/DAILY/080929/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2008-09-29_1.dat...
Writing ../.././RESULTS/DAILY/080929//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_1.png...
Writing ../.././RESULTS/DAILY/080929//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_1.png...


Getting calibration pulses data for GM1 SS3 H/H from 2008-09-29 00:00:00 to 2008-09-29 23:59:59. Rows: 2/6/10/14/18/22/26/30
Writing file ./RESULTS/DAILY/080929/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2008-09-29_2.dat...
Writing ../.././RESULTS/DAILY/080929//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_2.png...
Writing ../.././RESULTS/DAILY/080929//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_2.png...


Getting calibration pulses data for GM1 SS3 H/H from 2008-09-29 00:00:00 to 2008-09-29 23:59:59. Rows: 3/7/11/15/19/23/27/31
Writing file ./RESULTS/DAILY/080929/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2008-09-29_3.dat...
Writing ../.././RESULTS/DAILY/080929//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_3.png...
Writing ../.././RESULTS/DAILY/080929//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_3.png...


Getting calibration pulses data for GM1 SS3 H/H from 2008-09-29 00:00:00 to 2008-09-29 23:59:59. Rows: 4/8/12/16/20/24/28/32
Writing file ./RESULTS/DAILY/080929/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2008-09-29_4.dat...
Writing ../.././RESULTS/DAILY/080929//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_4.png...
Writing ../.././RESULTS/DAILY/080929//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_4.png...



CALIBRATION PULSES ANALYSIS completed
#####################################################################




DOPPLER ANALYSIS
#####################################################################
Creating directory ./RESULTS/DAILY/080929/DOPPLER...
```

```
********************************************************************************************
********************************************************************************************
DOPPLER ANX Analysis will be performed from 2008-09-29 00:00:00 to 2008-09-29 23:59:59

Analysing products WVS IS2 V/V
Getting doppler data for WVS IS2 V/V from 2008-09-29 00:00:00 to 2008-09-29 23:59:59...
Writing file ./RESULTS/DAILY/080929/DOPPLER/Doppler_data_WVS_IS2_VV_2008-09-29.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/080929/DOPPLER/DOPPLER_ANX_WVS_IS2_VV.png...

Analysing products GM1 SS1 H/H
Getting doppler data for GM1 SS1 H/H from 2008-09-29 00:00:00 to 2008-09-29 23:59:59...
Writing file ./RESULTS/DAILY/080929/DOPPLER/Doppler_data_GM1_SS1_HH_2008-09-29.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/080929/DOPPLER/DOPPLER_ANX_GM1_SS1_HH.png...



********************************************************************************************
********************************************************************************************
DOPPLER JUMPS Analysis will be performed on WSM products from 2008-09-29 00:00:00 to 2008-09-29 23:59:59

Analysing by default products WSM
Getting doppler jumps data for WSM from 2008-09-29 00:00:00 to 2008-09-29 23:59:59...
Writing file ./RESULTS/DAILY/080929/DOPPLER/Doppler_Jumps_data_WSM_2008-09-29.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/080929/DOPPLER/DOPPLER_JUMPS_ANX_WSM.png...
Writing file ../../RESULTS/DAILY/080929/DOPPLER/DOPPLER_JUMPS_Date_WSM.png...

********************************************************************************************
********************************************************************************************
DOPPLER MAP Analysis will be performed from 2008-09-29 00:00:00 to 2008-09-29 23:59:59

Analysing products WVS IS2 V/V
Loading predicted doppler values....
Phase: descending
Found data...
Computing mean error doppler estimated-predicted...
Mean error =  -27.778883 Hz
Writing file ../.././RESULTS/DAILY/080929//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_WVS_IS2_VV_desc.jpg...
Writing file ../.././RESULTS/DAILY/080929//DOPPLER/DOPPLER_Absolute_WVS_IS2_VV_desc.jpg...

*****************************************************
Loading predicted doppler values....
Phase: ascending
Found data...
Computing mean error doppler estimated-predicted...
Mean error =  -26.270173 Hz
Writing file ../.././RESULTS/DAILY/080929//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_WVS_IS2_VV_asc.jpg...
Writing file ../.././RESULTS/DAILY/080929//DOPPLER/DOPPLER_Absolute_WVS_IS2_VV_asc.jpg...

*****************************************************


Analysing products GM1 SS1 H/H
Loading predicted doppler values....
Phase: descending
Found data...
Computing mean error doppler estimated-predicted...
Mean error =  -15.024871 Hz
Writing file ../.././RESULTS/DAILY/080929//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_GM1_SS1_HH_desc.jpg...
Writing file ../.././RESULTS/DAILY/080929//DOPPLER/DOPPLER_Absolute_GM1_SS1_HH_desc.jpg...

*****************************************************
Loading predicted doppler values....
Phase: ascending
Found data...
```

```
Computing mean error doppler estimated-predicted...
Mean error =  -26.195876 Hz
Writing file ../.././RESULTS/DAILY/080929//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_GM1_SS1_HH_asc.jpg...
Writing file ../.././RESULTS/DAILY/080929//DOPPLER/DOPPLER_Absolute_GM1_SS1_HH_asc.jpg...

*******************************************************


DOPPLER ANALYSIS completed
######################################################################




CHIRP ANALYSIS
######################################################################
Creating directory ./RESULTS/DAILY/080929/CHIRP...


**********************************************************************************************
**********************************************************************************************
CHIRP Analysis will be performed from 2008-09-29 00:00:00 to 2008-09-29 23:59:59


Analysing products WSM SS1 H/H
************************************************************
Getting ScaleFactor data for WSM SS1 H/H from 2008-09-29 00:00:00 to 2008-09-29 23:59:59...
Writing file ./RESULTS/DAILY/080929/CHIRP/ScaleFactor_data_WSM_SS1_HH_2008-09-29.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/080929/CHIRP/ScaleFactor_ANX_WSM_SS1_HH.png...
Writing file ../../RESULTS/DAILY/080929/CHIRP/ScaleFactor_DATE_WSM_SS1_HH.png...


Analysing products WSM SS1 V/V
************************************************************
Getting ScaleFactor data for WSM SS1 V/V from 2008-09-29 00:00:00 to 2008-09-29 23:59:59...
Writing file ./RESULTS/DAILY/080929/CHIRP/ScaleFactor_data_WSM_SS1_VV_2008-09-29.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/080929/CHIRP/ScaleFactor_ANX_WSM_SS1_VV.png...
Writing file ../../RESULTS/DAILY/080929/CHIRP/ScaleFactor_DATE_WSM_SS1_VV.png...

CHIRP ANALYSIS completed
######################################################################




RAW DATA ANALYSIS
######################################################################
Analysis will be performed from 2008-09-29 00:00:00 to 2008-09-29 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/080929/RAW_DATA

Creating directory ./RESULTS/DAILY/080929/RAW_DATA...

**********************************************************************
Getting raw data for WVS from 2008-09-29 00:00:00 to 2008-09-29 23:59:59...
Writing file ./RESULTS/DAILY/080929/RAW_DATA/Raw_data_WVS_2008-09-29.dat...
Running IDL program to create graphs...

Creating image ../../RESULTS/DAILY/080929/RAW_DATA/Raw_data_WVS_input_mean.png...
Creating image ../../RESULTS/DAILY/080929/RAW_DATA/Raw_data_WVS_input_stdev.png...
Creating image ../../RESULTS/DAILY/080929/RAW_DATA/Raw_data_WVS_gain_imbalance.png...

**********************************************************************
Getting raw data for IMM from 2008-09-29 00:00:00 to 2008-09-29 23:59:59...
Writing file ./RESULTS/DAILY/080929/RAW_DATA/Raw_data_IMM_2008-09-29.dat...
Running IDL program to create graphs...
```

```
Creating image ../../RESULTS/DAILY/080929/RAW_DATA/Raw_data_IMM_input_mean.png...
Creating image ../../RESULTS/DAILY/080929/RAW_DATA/Raw_data_IMM_input_stdev.png...
Creating image ../../RESULTS/DAILY/080929/RAW_DATA/Raw_data_IMM_gain_imbalance.png...

RAW DATA ANALYSIS completed
######################################################################




TELEMETRY ANALYSIS
######################################################################
Analysis will be performed from 2008-09-29 00:00:00 to 2008-09-29 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/080929/TELEMETRY

Creating directory ./RESULTS/DAILY/080929/TELEMETRY...

Looking for gaps and missing lines in WVS products...
**********************************
Checking 26 products from PDE...
Checking 24 products from PDK...

Looking for gaps and missing lines in GM1 products...
**********************************
Checking 37 products from PDE...
Checking 41 products from PDK...

Looking for gaps and missing lines in APM products...
**********************************
Checking 3 products from PDE...
Checking 1 products from PDK...

Looking for gaps and missing lines in IMM products...
**********************************
Checking 38 products from PDE...
Checking 8 products from PDK...

Looking for gaps and missing lines in WSM products...
**********************************
Checking 18 products from PDE...
Found product...ASA_WSM_1PNPDE20080929_000024_000000922072_00288_34410_1594.N1 / 0 gaps / 35 missing lines
No products from PDK...

Creating graph of missing lines and gaps...
**************************************************************
Creating image: ./RESULTS/DAILY/080929/TELEMETRY/TELEMETRY_Missing_lines.png...
Creating image: ./RESULTS/DAILY/080929/TELEMETRY/TELEMETRY_Gaps.png...

TELEMETRY ANALYSIS completed
######################################################################




BROWSE PRODUCTS ANALYSIS
######################################################################
Analysis will be performed on 2008-09-29


**************************************************************
Scanning directory /nas3/ENVISAT/ASAR//ASA_GM__BP...
Results will be exported to the directory: /nas3/ENVISAT/ASAR//ASA_GM__BP/JPG/20080929/

Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM__BP/ASA_GM__BPZPDE20080929_193843_000008152072_00300_34422_2393.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM__BP/ASA_GM__BPZPDE20080929_202429_000002352072_00300_34422_2389.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM__BP/ASA_GM__BPZPDE20080929_203302_000000842072_00300_34422_2391.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM__BP/ASA_GM__BPZPDE20080929_203859_000002712072_00300_34422_2406.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM__BP/ASA_GM__BPZPDE20080929_205138_000010262072_00300_34422_2550.N1 ...
```

```
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM__BP/ASA_GM__BPZPDE20080929_212343_000005432072_00301_34423_2541.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM__BP/ASA_GM__BPZPDE20080929_220505_000001442072_00301_34423_2545.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM__BP/ASA_GM__BPZPDE20080929_221145_000001502072_00301_34423_2543.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM__BP/ASA_GM__BPZPDE20080929_222019_000002292072_00301_34423_2566.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM__BP/ASA_GM__BPZPDE20080929_224045_000002292072_00302_34424_2695.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM__BP/ASA_GM__BPZPDE20080929_230333_000004892072_00302_34424_2700.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM__BP/ASA_GM__BPZPDE20080929_233548_000002232072_00302_34424_2702.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM__BP/ASA_GM__BPZPDE20080929_233934_000001022072_00302_34424_2707.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM__BP/ASA_GM__BPZPDE20080929_234541_000001262072_00302_34424_2722.N1 ...

ANALYSIS COMPLETED: 14 GM browse products to see...
************************************************************

************************************************************
Scanning directory /nas3/ENVISAT/ASAR//ASA_AP__BP...
Results will be exported to the directory: /nas3/ENVISAT/ASAR//ASA_AP__BP/JPG/20080929/

Stripping browse product /nas3/ENVISAT/ASAR//ASA_AP__BP/ASA_AP__BPZPDE20080929_142554_000000432072_00297_34419_2274.N1 ...

ANALYSIS COMPLETED: 1 AP browse products to see...
************************************************************

************************************************************
Scanning directory /nas3/ENVISAT/ASAR//ASA_IM__BP...
Results will be exported to the directory: /nas3/ENVISAT/ASAR//ASA_IM__BP/JPG/20080929/

Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM__BP/ASA_IM__BPZPDE20080929_102547_000003222072_00294_34416_2244.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM__BP/ASA_IM__BPZPDE20080929_141216_000000372072_00296_34418_2267.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM__BP/ASA_IM__BPZPDE20080929_141603_000000522072_00296_34418_2272.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM__BP/ASA_IM__BPZPDE20080929_145458_000000372072_00297_34419_2276.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM__BP/ASA_IM__BPZPDE20080929_160413_000003932072_00298_34420_2300.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM__BP/ASA_IM__BPZPDE20080929_170915_000002012072_00298_34420_2336.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM__BP/ASA_IM__BPZPDE20080929_171612_000000832072_00298_34420_2306.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM__BP/ASA_IM__BPZPDE20080929_171754_000000832072_00298_34420_2312.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM__BP/ASA_IM__BPZPDE20080929_174348_000002382072_00299_34421_2344.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM__BP/ASA_IM__BPZPDE20080929_181558_000001592072_00299_34421_2379.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM__BP/ASA_IM__BPZPDE20080929_185020_000001412072_00299_34421_2381.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM__BP/ASA_IM__BPZPDE20080929_191504_000000672072_00299_34421_2385.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM__BP/ASA_IM__BPZPDE20080929_192046_000001282072_00300_34422_2526.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM__BP/ASA_IM__BPZPDE20080929_192329_000000952072_00300_34422_2383.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM__BP/ASA_IM__BPZPDE20080929_202826_000002642072_00300_34422_2528.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM__BP/ASA_IM__BPZPDE20080929_203426_000002612072_00300_34422_2530.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM__BP/ASA_IM__BPZPDE20080929_211131_000000532072_00301_34423_2552.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM__BP/ASA_IM__BPZPDE20080929_213314_000001092072_00301_34423_2655.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM__BP/ASA_IM__BPZPDE20080929_221012_000000792072_00301_34423_2657.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM__BP/ASA_IM__BPZPDE20080929_221416_000003532072_00301_34423_2675.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM__BP/ASA_IM__BPZPDE20080929_224430_000002212072_00302_34424_2680.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM__BP/ASA_IM__BPZPDE20080929_224430_000002212072_00302_34424_2682.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM__BP/ASA_IM__BPZPDE20080929_224430_000002212072_00302_34424_2984.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM__BP/ASA_IM__BPZPDE20080929_234749_000001212072_00302_34424_2807.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM__BP/ASA_IM__BPZPDE20080929_235046_000005752072_00302_34424_2834.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM__BP/ASA_IM__BPZPDK20080929_211201_000000362072_00301_34423_0260.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM__BP/ASA_IM__BPZPDK20080929_225724_000000372072_00302_34424_0286.N1 ...

ANALYSIS COMPLETED: 27 IM browse products to see...
************************************************************

************************************************************
Scanning directory /nas3/ENVISAT/ASAR//ASA_WS__BP...
Results will be exported to the directory: /nas3/ENVISAT/ASAR//ASA_WS__BP/JPG/20080929/

Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS__BP/ASA_WS__BPZPDE20080929_061702_000000732072_00292_34414_2223.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS__BP/ASA_WS__BPZPDE20080929_135659_000001032072_00296_34418_2282.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS__BP/ASA_WS__BPZPDE20080929_151628_000001352072_00297_34419_2284.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS__BP/ASA_WS__BPZPDE20080929_162450_000001642072_00298_34420_2348.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS__BP/ASA_WS__BPZPDE20080929_162603_000000902072_00298_34420_2342.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS__BP/ASA_WS__BPZPDE20080929_180444_000001282072_00299_34421_2346.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS__BP/ASA_WS__BPZPDE20080929_180541_000002262072_00299_34421_2387.N1 ...
```

```
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS__BP/ASA_WS__BPZPDE20080929_204650_000002872072_00300_34422_2536.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS__BP/ASA_WS__BPZPDE20080929_220736_000001342072_00301_34423_2684.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS__BP/ASA_WS__BPZPDE20080929_231143_000001522072_00302_34424_2829.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS__BP/ASA_WS__BPZPDK20080929_211323_000002452072_00301_34423_0282.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS__BP/ASA_WS__BPZPDK20080929_211757_000003422072_00301_34423_0284.N1 ...

ANALYSIS COMPLETED: 12 WS browse products to see...
************************************************************


BROWSE PRODUCTS ANALYSIS completed
######################################################################



HTML REPORT generation
######################################################################


Building file ./RESULTS/DAILY/080929/asarReport.html...
Building DATA SUMMARY section...
Building AUXILIARY FILES ANALYSIS section...
Building MODULE STEPPING ANALYSIS section...
Building CALIBRATION PULSES ANALYSIS section...
Building DOPPLER ANALYSIS section...
Building CHIRP ANALYSIS section...
Building RAW DATA ANALYSIS section...
Building TELEMETRY ANALYSIS section...

HTML REPORT generation completed
######################################################################
```

ENVISAT
ASAR Daily Report
esa
serco

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
ASA_APM_1PNPDE20080929_082017_000001062072_00293_34415_2218.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20080929_082121_000000422072_00293_34415_2208.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20080929_142554_000000432072_00297_34419_2273.N1	OK	OK	OK	OK
ASA_APM_1PNPDK20080929_193108_000000102072_00300_34422_0135.N1	OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
ASA_GM1_1PNPDE20080929_000447_000004162072_00288_34410_1480.N1	OK	OK	OK	OK
ASA_GM1_1PNPDE20080929_001718_000003262072_00288_34410_1485.N1	OK	OK	OK	OK
ASA_GM1_1PNPDE20080929_003226_000002292072_00288_34410_1495.N1	OK	OK	OK	OK
ASA_GM1_1PNPDE20080929_004827_000001632072_00288_34410_1607.N1	OK	OK	OK	OK
ASA_GM1_1PNPDE20080929_011419_000009302072_00289_34411_1612.N1	OK	OK	OK	OK
ASA_GM1_1PNPDE20080929_013058_000001022072_00289_34411_1623.N1	OK	OK	OK	OK
ASA_GM1_1PNPDE20080929_014806_000001692072_00289_34411_1621.N1	OK	OK	OK	OK
ASA_GM1_1PNPDE20080929_015754_000000842072_00289_34411_1619.N1	OK	OK	OK	OK
ASA_GM1_1PNPDE20080929_020455_000003742072_00289_34411_1634.N1	OK	OK	OK	OK
ASA_GM1_1PNPDE20080929_021244_000002472072_00289_34411_1636.N1	OK	OK	OK	OK
ASA_GM1_1PNPDE20080929_022226_000007732072_00289_34411_1769.N1	OK	OK	OK	OK
ASA_GM1_1PNPDE20080929_024537_000004652072_00290_34412_1767.N1	OK	OK	OK	OK
ASA_GM1_1PNPDE20080929_025410_000009902072_00290_34412_1845.N1	OK	OK	OK	OK
ASA_GM1_1PNPDE20080929_031601_000001812072_00290_34412_1785.N1	OK	OK	OK	OK
ASA_GM1_1PNPDE20080929_033948_000000782072_00290_34412_1882.N1	OK	OK	OK	OK
ASA_GM1_1PNPDE20080929_035443_000003442072_00290_34412_1931.N1	OK	OK	OK	OK
ASA_GM1_1PNPDE20080929_042133_000017402072_00291_34413_2023.N1	OK	OK	OK	OK
ASA_GM1_1PNPDE20080929_045540_000002532072_00291_34413_1945.N1	OK	OK	OK	OK
ASA_GM1_1PNPDE20080929_051906_000001812072_00291_34413_2061.N1	OK	OK	OK	OK
ASA_GM1_1PNPDE20080929_053420_000002292072_00291_34413_2063.N1	OK	OK	OK	OK
ASA_GM1_1PNPDE20080929_060314_000008212072_00292_34414_2068.N1	OK	OK	OK	OK
ASA_GM1_1PNPDE20080929_061836_000001262072_00292_34414_2070.N1	OK	OK	OK	OK
ASA_GM1_1PNPDE20080929_062718_000010092072_00292_34414_2163.N1	OK	OK	OK	OK
ASA_GM1_1PNPDE20080929_193843_000008152072_00300_34422_2392.N1	OK	OK	OK	OK
ASA_GM1_1PNPDE20080929_202429_000002352072_00300_34422_2388.N1	OK	OK	OK	OK
ASA_GM1_1PNPDE20080929_203302_000000842072_00300_34422_2390.N1	OK	OK	OK	OK
ASA_GM1_1PNPDE20080929_203859_000002712072_00300_34422_2405.N1	OK	OK	OK	OK
ASA_GM1_1PNPDE20080929_205138_000010262072_00300_34422_2549.N1	OK	OK	OK	OK
ASA_GM1_1PNPDE20080929_212343_000005432072_00301_34423_2540.N1	OK	OK	OK	OK
ASA_GM1_1PNPDE20080929_220505_000001442072_00301_34423_2544.N1	OK	OK	OK	OK
ASA_GM1_1PNPDE20080929_221145_000001502072_00301_34423_2542.N1	OK	OK	OK	OK
ASA_GM1_1PNPDE20080929_222019_000002292072_00301_34423_2565.N1	OK	OK	OK	OK
ASA_GM1_1PNPDE20080929_224045_000002292072_00302_34424_2694.N1	OK	OK	OK	OK
ASA_GM1_1PNPDE20080929_230333_000004892072_00302_34424_2699.N1	OK	OK	OK	OK
ASA_GM1_1PNPDE20080929_233548_000002232072_00302_34424_2701.N1	OK	OK	OK	OK
ASA_GM1_1PNPDE20080929_233934_000001022072_00302_34424_2706.N1	OK	OK	OK	OK
ASA_GM1_1PNPDE20080929_234541_000001262072_00302_34424_2721.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080929_065942_000002232072_00292_34414_9222.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080929_071409_000002712072_00292_34414_9227.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080929_075118_000000842072_00293_34415_9229.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080929_075402_000000782072_00293_34415_9231.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080929_080050_000001382072_00293_34415_9265.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080929_080223_000005612072_00293_34415_9320.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080929_082223_000006042072_00293_34415_9322.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080929_084018_000000842072_00293_34415_9324.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080929_084303_000009732072_00293_34415_9416.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080929_093227_000004342072_00294_34416_9338.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080929_095458_000003082072_00294_34416_9499.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080929_100212_000001202072_00294_34416_9501.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080929_102054_000002952072_00294_34416_9503.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080929_103320_000003922072_00294_34416_9508.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080929_111555_000001632072_00295_34417_9518.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080929_120130_000001322072_00295_34417_9628.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080929_121613_000002592072_00295_34417_9636.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080929_122632_000002412072_00295_34417_9638.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080929_124817_000002652072_00296_34418_9640.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080929_125624_000004412072_00296_34418_9647.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080929_130241_000004282072_00296_34418_9762.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080929_132459_000006522072_00296_34418_9764.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080929_133558_000012572072_00296_34418_9856.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080929_135849_000001382072_00296_34418_9780.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080929_140724_000002832072_00296_34418_9775.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080929_142343_000001322072_00297_34419_9773.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080929_142657_000006882072_00297_34419_9793.N1	OK	OK	OK	OK

ASA_GM1_1PNPDK20080929_144621_000005192072_00297_34419_9891.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080929_150422_000002772072_00297_34419_9893.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080929_152241_000011422072_00297_34419_9982.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080929_161057_000002292072_00298_34420_9905.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080929_162741_000009182072_00298_34420_0016.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080929_170317_000003562072_00298_34420_0020.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080929_171248_000002052072_00298_34420_0018.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080929_171927_000001692072_00298_34420_0025.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080929_174758_000004042072_00299_34421_0035.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080929_180933_000003862072_00299_34421_0137.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080929_184353_000003862072_00299_34421_0139.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080929_185253_000006042072_00299_34421_0144.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080929_191821_000001442072_00299_34421_0149.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080929_192515_000003202072_00300_34422_0159.N1	OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
ASA_IMM_1PNPDE20080929_002242_000005742072_00288_34410_1599.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20080929_012956_000000502072_00289_34411_1617.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20080929_021111_000000832072_00289_34411_1720.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20080929_024448_000000372072_00290_34412_1753.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20080929_025320_000000372072_00290_34412_1775.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20080929_031036_000003152072_00290_34412_1847.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20080929_034103_000003222072_00290_34412_1862.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20080929_034703_000004502072_00290_34412_2015.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20080929_045034_000002962072_00291_34413_2005.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20080929_052203_000002032072_00291_34413_2025.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20080929_052603_000004832072_00291_34413_2059.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20080929_064714_000000282072_00292_34414_2057.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20080929_070326_000003222072_00292_34414_2181.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20080929_102547_000003222072_00294_34416_2243.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20080929_141216_000000372072_00296_34418_2266.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20080929_141603_000000522072_00296_34418_2271.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20080929_145458_000000372072_00297_34419_2275.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20080929_160413_000003932072_00298_34420_2299.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20080929_170915_000002012072_00298_34420_2335.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20080929_171612_000000832072_00298_34420_2305.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20080929_171754_000000832072_00298_34420_2311.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20080929_174348_000002382072_00299_34421_2343.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20080929_181558_000001592072_00299_34421_2378.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20080929_185020_000001412072_00299_34421_2380.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20080929_191504_000000672072_00299_34421_2384.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20080929_192046_000001282072_00300_34422_2525.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20080929_192329_000000952072_00300_34422_2382.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20080929_202826_000002642072_00300_34422_2527.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20080929_203426_000002612072_00300_34422_2529.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20080929_211131_000000532072_00301_34423_2551.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20080929_213314_000001092072_00301_34423_2654.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20080929_221012_000000792072_00301_34423_2656.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20080929_221416_000003532072_00301_34423_2674.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20080929_224430_000002212072_00302_34424_2679.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20080929_224430_000002212072_00302_34424_2681.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20080929_224430_000002212072_00302_34424_2983.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20080929_234749_000001212072_00302_34424_2806.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20080929_235046_000005752072_00302_34424_2833.N1	OK	OK	OK	OK
ASA_IMM_1PNPDK20080929_070926_000002732072_00292_34414_9305.N1	OK	OK	OK	OK
ASA_IMM_1PNPDK20080929_074958_000000702072_00293_34415_9303.N1	OK	OK	OK	OK
ASA_IMM_1PNPDK20080929_094736_000000372072_00294_34416_9451.N1	OK	OK	OK	OK
ASA_IMM_1PNPDK20080929_095128_000000852072_00294_34416_9466.N1	OK	OK	OK	OK
ASA_IMM_1PNPDK20080929_120843_000004392072_00295_34417_9743.N1	OK	OK	OK	OK
ASA_IMM_1PNPDK20080929_193138_000004132072_00300_34422_0242.N1	OK	OK	OK	OK
ASA_IMM_1PNPDK20080929_211201_000000362072_00301_34423_0259.N1	OK	OK	OK	OK
ASA_IMM_1PNPDK20080929_225724_000000372072_00302_34424_0285.N1	OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
ASA_WSM_1PNPDE20080929_000024_000000922072_00288_34410_1594.N1	OK	OK	OK	OK
ASA_WSM_1PNPDE20080929_010743_000003912072_00289_34411_1745.N1	OK	OK	OK	OK
ASA_WSM_1PNPDE20080929_020146_000000732072_00289_34411_1714.N1	OK	OK	OK	OK
ASA_WSM_1PNPDE20080929_020146_000001822072_00289_34411_1877.N1	OK	OK	OK	OK
ASA_WSM_1PNPDE20080929_020400_000000482072_00289_34411_1718.N1	OK	OK	OK	OK
ASA_WSM_1PNPDE20080929_061702_000000732072_00292_34414_2037.N1	OK	OK	OK	OK
ASA_WSM_1PNPDE20080929_061702_000000732072_00292_34414_2177.N1	OK	OK	OK	OK
ASA_WSM_1PNPDE20080929_061702_000000732072_00292_34414_2222.N1	OK	OK	OK	OK
ASA_WSM_1PNPDE20080929_075914_000000912072_00293_34415_2210.N1	OK	OK	OK	OK
ASA_WSM_1PNPDE20080929_135659_000001032072_00296_34418_2281.N1	OK	OK	OK	OK
ASA_WSM_1PNPDE20080929_151628_000001352072_00297_34419_2283.N1	OK	OK	OK	OK
ASA_WSM_1PNPDE20080929_162450_000001642072_00298_34420_2347.N1	OK	OK	OK	OK
ASA_WSM_1PNPDE20080929_162603_000000902072_00298_34420_2341.N1	OK	OK	OK	OK
ASA_WSM_1PNPDE20080929_180444_000001282072_00299_34421_2345.N1	OK	OK	OK	OK
ASA_WSM_1PNPDE20080929_180541_000002262072_00299_34421_2386.N1	OK	OK	OK	OK
ASA_WSM_1PNPDE20080929_204650_000002872072_00300_34422_2535.N1	OK	OK	OK	OK
ASA_WSM_1PNPDE20080929_220736_000001342072_00301_34423_2683.N1	OK	OK	OK	OK
ASA_WSM_1PNPDE20080929_231143_000001522072_00302_34424_2828.N1	OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
ASA_WVS_1PNPDE20080929_000154_000001342072_00288_34410_1478.N1	OK	OK	OK	OK
ASA_WVS_1PNPDE20080929_001145_000002852072_00288_34410_1483.N1	OK	OK	OK	OK
ASA_WVS_1PNPDE20080929_003621_000003142072_00288_34410_1488.N1	OK	OK	OK	OK
ASA_WVS_1PNPDE20080929_004036_000004342072_00288_34410_1610.N1	OK	OK	OK	OK
ASA_WVS_1PNPDE20080929_005110_000009442072_00288_34410_1615.N1	OK	OK	OK	OK
ASA_WVS_1PNPDE20080929_013243_000008852072_00289_34411_1626.N1	OK	OK	OK	OK
ASA_WVS_1PNPDE20080929_015054_000003752072_00289_34411_1629.N1	OK	OK	OK	OK
ASA_WVS_1PNPDE20080929_021657_000000152072_00289_34411_1632.N1	OK	OK	OK	OK
ASA_WVS_1PNPDE20080929_021657_000002852072_00289_34411_1783.N1	OK	OK	OK	OK
ASA_WVS_1PNPDE20080929_031907_000008242072_00290_34412_1788.N1	OK	OK	OK	OK
ASA_WVS_1PNPDE20080929_033236_000002402072_00290_34412_1885.N1	OK	OK	OK	OK
ASA_WVS_1PNPDE20080929_040030_000009442072_00290_34412_1948.N1	OK	OK	OK	OK
ASA_WVS_1PNPDE20080929_045957_000008542072_00291_34413_1951.N1	OK	OK	OK	OK
ASA_WVS_1PNPDE20080929_051342_000002852072_00291_34413_2066.N1	OK	OK	OK	OK
ASA_WVS_1PNPDE20080929_053809_000014542072_00291_34413_2097.N1	OK	OK	OK	OK
ASA_WVS_1PNPDE20080929_064410_000001342072_00292_34414_2094.N1	OK	OK	OK	OK
ASA_WVS_1PNPDE20080929_064749_000004642072_00292_34414_2091.N1	OK	OK	OK	OK
ASA_WVS_1PNPDE20080929_195222_000018892072_00300_34422_2395.N1	OK	OK	OK	OK
ASA_WVS_1PNPDE20080929_204332_000000452072_00300_34422_2403.N1	OK	OK	OK	OK
ASA_WVS_1PNPDE20080929_204332_000001502072_00300_34422_2538.N1	OK	OK	OK	OK
ASA_WVS_1PNPDE20080929_213509_000017542072_00301_34423_2547.N1	OK	OK	OK	OK
ASA_WVS_1PNPDE20080929_222408_000002252072_00301_34423_2563.N1	OK	OK	OK	OK
ASA_WVS_1PNPDE20080929_222708_000007792072_00301_34423_2692.N1	OK	OK	OK	OK
ASA_WVS_1PNPDE20080929_224818_000005092072_00302_34424_2697.N1	OK	OK	OK	OK
ASA_WVS_1PNPDE20080929_231413_000012442072_00302_34424_2704.N1	OK	OK	OK	OK
ASA_WVS_1PNPDE20080929_234117_000002252072_00302_34424_2724.N1	OK	OK	OK	OK
ASA_WVS_1PNPDK20080929_065519_000002252072_00292_34414_9225.N1	OK	OK	OK	OK
ASA_WVS_1PNPDK20080929_071845_000018292072_00292_34414_9263.N1	OK	OK	OK	OK
ASA_WVS_1PNPDK20080929_083227_000004202072_00293_34415_9327.N1	OK	OK	OK	OK
ASA_WVS_1PNPDK20080929_085921_000019492072_00293_34415_9348.N1	OK	OK	OK	OK
ASA_WVS_1PNPDK20080929_100414_000009592072_00294_34416_9511.N1	OK	OK	OK	OK
ASA_WVS_1PNPDK20080929_103956_000002102072_00294_34416_9506.N1	OK	OK	OK	OK
ASA_WVS_1PNPDK20080929_104524_000014092072_00294_34416_9521.N1	OK	OK	OK	OK
ASA_WVS_1PNPDK20080929_112744_000007342072_00295_34417_9626.N1	OK	OK	OK	OK
ASA_WVS_1PNPDK20080929_114205_000011242072_00295_34417_9631.N1	OK	OK	OK	OK
ASA_WVS_1PNPDK20080929_122032_000003152072_00295_34417_9634.N1	OK	OK	OK	OK
ASA_WVS_1PNPDK20080929_123036_000010212072_00295_34417_9650.N1	OK	OK	OK	OK
ASA_WVS_1PNPDK20080929_130954_000005092072_00296_34418_9760.N1	OK	OK	OK	OK
ASA_WVS_1PNPDK20080929_132040_000002092072_00296_34418_9778.N1	OK	OK	OK	OK
ASA_WVS_1PNPDK20080929_140108_000003302072_00296_34418_9783.N1	OK	OK	OK	OK
ASA_WVS_1PNPDK20080929_141300_000001492072_00296_34418_9771.N1	OK	OK	OK	OK
ASA_WVS_1PNPDK20080929_141701_000001942072_00297_34419_9786.N1	OK	OK	OK	OK
ASA_WVS_1PNPDK20080929_150902_000004042072_00297_34419_9896.N1	OK	OK	OK	OK
ASA_WVS_1PNPDK20080929_151857_000001802072_00297_34419_9899.N1	OK	OK	OK	OK
ASA_WVS_1PNPDK20080929_154144_000012442072_00297_34419_9908.N1	OK	OK	OK	OK
ASA_WVS_1PNPDK20080929_164301_000011692072_00298_34420_0023.N1	OK	OK	OK	OK
ASA_WVS_1PNPDK20080929_172220_000012442072_00298_34420_0033.N1	OK	OK	OK	OK
ASA_WVS_1PNPDK20080929_181843_000014692072_00299_34421_0142.N1	OK	OK	OK	OK
ASA_WVS_1PNPDK20080929_190459_000005692072_00299_34421_0147.N1	OK	OK	OK	OK
ASA_WVS_1PNPDK20080929_191617_000000742072_00299_34421_0152.N1	OK	OK	OK	OK


Calibration pulses for GM1 SS3 H/H
Average P1 [dB]
0
−2
−4
−6
−8
03
06
09
12
15
18
21
29−Sep
Average P1a [dB]
−5
−10
−15
−20
−25
−30
−35
Average P2[dB]
Average P3 [dB]
−7.80
−7.90
−8.00
−8.10
−8.20
−8.30
−8.40
rows: _ 1 _ 5 _ 9 _ 13 _ 17 _ 21 _ 25 _ 29


Calibration pulses for GM1 SS3 H/H
Average P1 [dB]
−1
−2
−3
−4
−5
−6
−7
03
06
09
12
15
18
21
29−Sep
Average P1a [dB]
−5
−10
−15
−20
−25
03
06
09
12
15
18
21
29−Sep
Average P2[dB]
−5
−10
−15
−20
−25
03
06
09
12
15
18
21
29−Sep
Average P3 [dB]
−7.80
−7.90
−8.00
−8.10
−8.20
−8.30
−8.40
03
06
09
12
15
18
21
29−Sep
rows: _ 2 _ 6 _ 10 _ 14 _ 18 _ 22 _ 26 _ 30


Calibration pulses for GM1 SS3 H/H
Average P1 [dB]
0
−2
−4
−6
−8
03
06
09
12
15
18
21
29−Sep
Average P1a [dB]
−5
−10
−15
−20
−25
−30
Average P2[dB]
Average P3 [dB]
−7.80
−7.90
−8.00
−8.10
−8.20
−8.30
−8.40
rows: _ 3 _ 7 _ 11 _ 15 _ 19 _ 23 _ 27 _ 31


Calibration pulses for GM1 SS3 H/H
Average P1 [dB]
0
−2
−4
−6
−8
03
06
09
12
15
18
21
29−Sep
Average P1a [dB]
−8
−10
−12
−14
−16
−18
−20
−22
03
06
09
12
15
18
21
29−Sep
Average P2[dB]
0
−5
−10
−15
−20
−25
03
06
09
12
15
18
21
29−Sep
Average P3 [dB]
−7.80
−7.90
−8.00
−8.10
−8.20
−8.30
−8.40
03
06
09
12
15
18
21
29−Sep
rows: _ 4 _ 8 _ 12 _ 16 _ 20 _ 24 _ 28 _ 32


Calibration pulses for WVS IS2 V/V
Average P1 [dB]
0
−5
−10
−15
−20
03
06
09
12
15
18
21
29−Sep
Average P1a [dB]
−8
−10
−12
−14
−16
−18
−20
−22
Average P2[dB]
−25
Average P3 [dB]
−7.80
−7.90
−8.00
−8.10
−8.20
−8.30
−8.40
rows: 1 5 9 13 17 21 25 29


Calibration pulses for WVS IS2 V/V
Average P1 [dB]
−2
−4
−6
−8
−10
−12
03
06
09
12
15
18
21
29−Sep
Average P1a [dB]
−10
−12
−14
−16
−18
−20
−22
03
06
09
12
15
18
21
29−Sep
Average P2[dB]
−5
−10
−15
−20
−25
03
06
09
12
15
18
21
29−Sep
Average P3 [dB]
−7.80
−7.90
−8.00
−8.10
−8.20
−8.30
−8.40
03
06
09
12
15
18
21
29−Sep
rows: _ 2 _ 6 _ 10 _ 14 _ 18 _ 22 _ 26 _ 30


Calibration pulses for WVS IS2 V/V
Average P1 [dB]
0
−2
−4
−6
−8
03
06
09
12
15
18
21
29−Sep
Average P1a [dB]
−10
−12
−14
−16
−18
−20
−22
−24
Average P2[dB]
−5
−10
−15
−20
−25
Average P3 [dB]
−7.80
−7.90
−8.00
−8.10
−8.20
−8.30
−8.40
rows: _ 3 _ 7 _ 11 _ 15 _ 19 _ 23 _ 27 _ 31


Calibration pulses for WVS IS2 V/V
Average P1 [dB]
−1
−2
−3
−4
−5
−6
03
06
09
12
15
18
21
29−Sep
Average P1a [dB]
−10
−12
−14
−16
−18
−20
−22
−24
03
06
09
12
15
18
21
29−Sep
Average P2[dB]
0
−5
−10
−15
−20
−25
03
06
09
12
15
18
21
29−Sep
Average P3 [dB]
−7.80
−7.90
−8.00
−8.10
−8.20
−8.30
−8.40
03
06
09
12
15
18
21
29−Sep
rows: _ 4 _ 8 _ 12 _ 16 _ 20 _ 24 _ 28 _ 32


P1_AMP
dB
P1_PH
P3_AMP
dB
P3_PH
P1a_AMP
dB
P1a_PH
Tp_AMP (P1−P1a)
dB
Tp_PH (P1−P1a)
P2_AMP
dB
P2_PH


P1_AMP
dB
P1_PH
P3_AMP
dB
P3_PH
P1a_AMP
dB
P1a_PH
Tp_AMP (P1−P1a)
dB
Tp_PH (P1−P1a)
P2_AMP
dB
P2_PH


Transmit power (P1 – P1a) for GM1 SS3 H/H
0
−2
−4
−6
−8
−10
[dB]
03
06
09
12
15
18
21
29−Sep
Transmit power (P1 – P1a) for GM1 SS3 H/H
200
100
0
−100
−200
Phase [deg.]
03
06
09
12
15
18
21
29−Sep
rows: 1 5 9 13 17 21 25 29


Transmit power (P1 – P1a) for GM1 SS3 H/H
0
−2
−4
−6
−8
−10
[dB]
03
06
09
12
15
18
21
29–Sep
Transmit power (P1 – P1a) for GM1 SS3 H/H
200
100
0
−100
−200
Phase [deg.]
03
06
09
12
15
18
21
29–Sep
rows: 2 6 10 14 18 22 26 30


Transmit power (P1 – P1a) for GM1 SS3 H/H
0
−2
−4
−6
−8
−10
[dB]
03
06
09
12
15
18
21
29−Sep
Transmit power (P1 – P1a) for GM1 SS3 H/H
200
100
0
−100
−200
Phase [deg.]
03
06
09
12
15
18
21
29−Sep
rows: 3 7 11 15 19 23 27 31


Transmit power (P1 – P1a) for GM1 SS3 H/H
0
−2
−4
−6
−8
−10
[dB]
03
06
09
12
15
18
21
29–Sep
Transmit power (P1 – P1a) for GM1 SS3 H/H
200
100
0
−100
−200
Phase [deg.]
03
06
09
12
15
18
21
29–Sep
rows: 4 8 12 16 20 24 28 32


Transmit power (P1 – P1a) for WVS IS2 V/V
0
−2
−4
−6
−8
−10
[dB]
03
06
09
12
15
18
21
29−Sep
Transmit power (P1 – P1a) for WVS IS2 V/V
200
100
0
−100
−200
Phase [deg.]
03
06
09
12
15
18
21
29−Sep
rows: 1 5 9 13 17 21 25 29


Transmit power (P1 − P1a) for WVS IS2 V/V
0
−2
−4
−6
−8
−10
[dB]
03
06
09
12
15
18
21
29−Sep
Transmit power (P1 − P1a) for WVS IS2 V/V
200
100
0
−100
−200
Phase [deg.]
03
06
09
12
15
18
21
29−Sep
rows: 2 6 10 14 18 22 26 30


Transmit power (P1 – P1a) for WVS IS2 V/V
0
−2
−4
−6
−8
−10
[dB]
03
06
09
12
15
18
21
29−Sep
Transmit power (P1 – P1a) for WVS IS2 V/V
200
100
0
−100
−200
Phase [deg.]
03
06
09
12
15
18
21
29−Sep
rows: 3 7 11 15 19 23 27 31


Transmit power (P1 – P1a) for WVS IS2 V/V
0
−2
−4
−6
−8
−10
[dB]
03
06
09
12
15
18
21
29−Sep
Transmit power (P1 – P1a) for WVS IS2 V/V
200
100
0
−100
−200
Phase [deg.]
03
06
09
12
15
18
21
29−Sep
rows: 4 8 12 16 20 24 28 32


ScaleFactor vs ANX for WSM SS1 H/H
ScaleFactor
2.6
2.4
2.2
2.0
1.8
1.6
0
1000
2000
3000
4000
5000
6000
secs from ANX


ScaleFactor vs ANX for WSM SS1 V/V
ScaleFactor
1.6
1.4
1.2
1.0
0.8
0.6
0
1000
2000
3000
4000
5000
6000
secs from ANX


ScaleFactor vs Date for WSM SS1 H/H
ScaleFactor
2.6
2.4
2.2
2.0
1.8
1.6
02
04
06
08
10
12
14
16
18
20
22
29-Sep
Date


ScaleFactor vs Date for WSM SS1 V/V
ScaleFactor
1.6
1.4
1.2
1.0
0.8
0.6
02
04
06
08
10
12
14
16
18
20
29-Sep
Date

Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion
ASA_APM_1PNPDE20080929_082017_000001062072_00293_34415_2218.N1	IS3	H/V	72	34415	293	4.07
ASA_APM_1PNPDE20080929_082121_000000422072_00293_34415_2208.N1	IS3	H/V	72	34415	293	4.07
ASA_APM_1PNPDE20080929_142554_000000432072_00297_34419_2273.N1	IS7	H/H	72	34419	297	4.07
ASA_APM_1PNPDK20080929_193108_000000102072_00300_34422_0135.N1	IS7	***	72	34422	300	4.07

Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion			
ASA_GM1_1PNPDE20080929_000447_000004162072_00288_34410_1480.N1	SS1	H/H	72	34410	288	4.07			
ASA_GM1_1PNPDE20080929_001718_000003262072_00288_34410_1485.N1	SS1	H/H	72	34410	288	4.07			
ASA_GM1_1PNPDE20080929_003226_000002292072_00288_34410_1495.N1	SS1	H/H	72	34410	288	4.07			
ASA_GM1_1PNPDE20080929_004827_000001632072_00288_34410_1607.N1	SS1	H/H	72	34410	288	4.07			
ASA_GM1_1PNPDE20080929_011419_000009302072_00289_34411_1612.N1	SS1	H/H	72	34411	289	4.07			
ASA_GM1_1PNPDE20080929_013058_000001022072_00289_34411_1623.N1	SS1	H/H	72	34411	289	4.07			
ASA_GM1_1PNPDE20080929_014806_000001692072_00289_34411_1621.N1	SS1	H/H	72	34411	289	4.07			
ASA_GM1_1PNPDE20080929_015754_000000842072_00289_34411_1619.N1	SS1	H/H	72	34411	289	4.07			
ASA_GM1_1PNPDE20080929_020455_000003742072_00289_34411_1634.N1	SS1	H/H	72	34411	289	4.07			
ASA_GM1_1PNPDE20080929_021244_000002472072_00289_34411_1636.N1	SS1	H/H	72	34411	289	4.07			
ASA_GM1_1PNPDE20080929_022226_000007732072_00289_34411_1769.N1	SS1	H/H	72	34411	289	4.07			
ASA_GM1_1PNPDE20080929_024537_000004652072_00290_34412_1767.N1	SS1	H/H	72	34412	290	4.07			
ASA_GM1_1PNPDE20080929_025410_000009902072_00290_34412_1845.N1	SS1	H/H	72	34412	290	4.07			
ASA_GM1_1PNPDE20080929_031601_000001812072_00290_34412_1785.N1	SS1	H/H	72	34412	290	4.07			
ASA_GM1_1PNPDE20080929_033948_000000782072_00290_34412_1882.N1	SS1	H/H	72	34412	290	4.07			
ASA_GM1_1PNPDE20080929_035443_000003442072_00290_34412_1931.N1	SS1	H/H	72	34412	290	4.07			
ASA_GM1_1PNPDE20080929_042133_000017402072_00291_34413_2023.N1	SS1	H/H	72	34413	291	4.07			
ASA_GM1_1PNPDE20080929_045540_000002532072_00291_34413_1945.N1	SS1	H/H	72	34413	291	4.07			
ASA_GM1_1PNPDE20080929_051906_000001812072_00291_34413_2061.N1	SS1	H/H	72	34413	291	4.07			
ASA_GM1_1PNPDE20080929_053420_000002292072_00291_34413_2063.N1	SS1	H/H	72	34413	291	4.07			
ASA_GM1_1PNPDE20080929_060314_000008212072_00292_34414_2068.N1	SS1	H/H	72	34414	292	4.07			
ASA_GM1_1PNPDE20080929_061836_000001262072_00292_34414_2070.N1	SS1	H/H	72	34414	292	4.07			
ASA_GM1_1PNPDE20080929_062718_000010092072_00292_34414_2163.N1	SS1	H/H	72	34414	292	4.07			
ASA_GM1_1PNPDK20080929_065942_000002232072_00292_34414_9222.N1	SS1	H/H	72	34414	292	4.07			
ASA_GM1_1PNPDK20080929_071409_000002712072_00292_34414_9227.N1	SS1	H/H	72	34414	292	4.07			
ASA_GM1_1PNPDK20080929_075118_000000842072_00293_34415_9229.N1	SS1	H/H	72	34415	293	4.07			
ASA_GM1_1PNPDK20080929_075402_000000782072_00293_34415_9231.N1	SS1	H/H	72	34415	293	4.07			
ASA_GM1_1PNPDK20080929_080050_000001382072_00293_34415_9265.N1	SS1	H/H	72	34415	293	4.07			
ASA_GM1_1PNPDK20080929_080223_000005612072_00293_34415_9320.N1	SS1	H/H	72	34415	293	4.07			
ASA_GM1_1PNPDK20080929_082223_000006042072_00293_34415_9322.N1	SS1	H/H	72	34415	293	4.07			
ASA_GM1_1PNPDK20080929_084018_000000842072_00293_34415_9324.N1	SS1	H/H	72	34415	293	4.07			
ASA_GM1_1PNPDK20080929_084303_000009732072_00293_34415_9416.N1	SS1	H/H	72	34415	293	4.07			
ASA_GM1_1PNPDK20080929_093227_000004342072_00294_34416_9338.N1	SS1	H/H	72	34416	294	4.07			
ASA_GM1_1PNPDK20080929_095458_000003082072_00294_34416_9499.N1	SS1	H/H	72	34416	294	4.07			
ASA_GM1_1PNPDK20080929_100212_000001202072_00294_34416_9501.N1	SS1	H/H	72	34416	294	4.07			
ASA_GM1_1PNPDK20080929_102054_000002952072_00294_34416_9503.N1	SS1	H/H	72	34416	294	4.07			
ASA_GM1_1PNPDK20080929_103320_000003922072_00294_34416_9508.N1	SS1	H/H	72	34416	294	4.07			
ASA_GM1_1PNPDK20080929_111555_000001632072_00295_34417_9518.N1	SS1	H/H	72	34417	295	4.07			
ASA_GM1_1PNPDK20080929_120130_000001322072_00295_34417_9628.N1	SS1	H/H	72	34417	295	4.07			
ASA_GM1_1PNPDK20080929_121613_000002592072_00295_34417_9636.N1	SS1	H/H	72	34417	295	4.07			
ASA_GM1_1PNPDK20080929_122632_000002412072_00295_34417_9638.N1	SS1	H/H	72	34417	295	4.07			
ASA_GM1_1PNPDK20080929_124817_000002652072_00296_34418_9640.N1	SS1	H/H	72	34418	296	4.07			
ASA_GM1_1PNPDK20080929_125624_000004412072_00296_34418_9647.N1	SS1	H/H	72	34418	296	4.07			
ASA_GM1_1PNPDK20080929_130241_000004282072_00296_34418_9762.N1	SS1	H/H	72	34418	296	4.07			
ASA_GM1_1PNPDK20080929_132459_000006522072_00296_34418_9764.N1	SS1	H/H	72	34418	296	4.07			
ASA_GM1_1PNPDK20080929_133558_000012572072_00296_34418_9856.N1	SS1	H/H	72	34418	296	4.07			
ASA_GM1_1PNPDK20080929_135849_000001382072_00296_34418_9780.N1	SS1	H/H	72	34418	296	4.07			
ASA_GM1_1PNPDK20080929_140724_000002832072_00296_34418_9775.N1	SS1	H/H	72	34418	296	4.07			
ASA_GM1_1PNPDK20080929_142343_000001322072_00297_34419_9773.N1	SS1	H/H	72	34419	297	4.07			
ASA_GM1_1PNPDK20080929_142657_000006882072_00297_34419_9793.N1	SS1	H/H	72	34419	297	4.07			
ASA_GM1_1PNPDK20080929_144621_000005192072_00297_34419_9891.N1	SS1	H/H	72	34419	297	4.07			
ASA_GM1_1PNPDK20080929_150422_000002772072_00297_34419_9893.N1	SS1	H/H	72	34419	297	4.07			
ASA_GM1_1PNPDK20080929_152241_000011422072_00297_34419_9982.N1	SS1	H/H	72	34419	297	4.07			
ASA_GM1_1PNPDK20080929_161057_000002292072_00298_34420_9905.N1	SS1	H/H	72	34420	298	4.07			
ASA_GM1_1PNPDK20080929_162741_000009182072_00298_34420_0016.N1	SS1	H/H	72	34420	298	4.07			
ASA_GM1_1PNPDK20080929_170317_000003562072_00298_34420_0020.N1	SS1	H/H	72	34420	298	4.07			
ASA_GM1_1PNPDK20080929_171248_000002052072_00298_34420_0018.N1	SS1	H/H	72	34420	298	4.07			
ASA_GM1_1PNPDK20080929_171927_000001692072_00298_34420_0025.N1	SS1	H/H	72	34420	298	4.07			
ASA_GM1_1PNPDK20080929_174758_000004042072_00299_34421_0035.N1	SS1	H/H	72	34421	299	4.07			
ASA_GM1_1PNPDK20080929_180933_000003862072_00299_34421_0137.N1	SS1	H/H	72	34421	299	4.07			
ASA_GM1_1PNPDK20080929_184353_000003862072_00299_34421_0139.N1	SS1	H/H	72	34421	299	4.07			
ASA_GM1_1PNPDK20080929_185253_000006042072_00299_34421_0144.N1	SS1	H/H	72	34421	299	4.07			
ASA_GM1_1PNPDK20080929_191821_000001442072_00299_34421_0149.N1	SS1	H/H	72	34421	299	4.07			
ASA_GM1_1PNPDK20080929_192515_000003202072_00300_34422_0159.N1	SS1	H/H	72	34422	300	4.07			
ASA_GM1_1PNPDE20080929_193843_000008152072_00300_34422_2392.N1	SS1	H/H	72	34422	300	4.07			
ASA_GM1_1PNPDE20080929_202429_000002352072_00300_34422_2388.N1	SS1	H/H	72	34422	300	4.07			
ASA_GM1_1PNPDE20080929_203302_000000842072_00300_34422_2390.N1	SS1	H/H	72	34422	300	4.07			

ASA_GM1_1PNPDE20080929_203859_000002712072_00300_34422_2405.N1	SS1	H/H	72	34422	300	4.07
ASA_GM1_1PNPDE20080929_205138_000010262072_00300_34422_2549.N1	SS1	H/H	72	34422	300	4.07
ASA_GM1_1PNPDE20080929_212343_000005432072_00301_34423_2540.N1	SS1	H/H	72	34423	301	4.07
ASA_GM1_1PNPDE20080929_220505_000001442072_00301_34423_2544.N1	SS1	H/H	72	34423	301	4.07
ASA_GM1_1PNPDE20080929_221145_000001502072_00301_34423_2542.N1	SS1	H/H	72	34423	301	4.07
ASA_GM1_1PNPDE20080929_222019_000002292072_00301_34423_2565.N1	SS1	H/H	72	34423	301	4.07
ASA_GM1_1PNPDE20080929_224045_000002292072_00302_34424_2694.N1	SS1	H/H	72	34424	302	4.07
ASA_GM1_1PNPDE20080929_230333_000004892072_00302_34424_2699.N1	SS1	H/H	72	34424	302	4.07
ASA_GM1_1PNPDE20080929_233548_000002232072_00302_34424_2701.N1	SS1	H/H	72	34424	302	4.07
ASA_GM1_1PNPDE20080929_233934_000001022072_00302_34424_2706.N1	SS1	H/H	72	34424	302	4.07
ASA_GM1_1PNPDE20080929_234541_000001262072_00302_34424_2721.N1	SS1	H/H	72	34424	302	4.07

Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion				
ASA_IMM_1PNPDE20080929_002242_000005742072_00288_34410_1599.N1	IS2	H/H	72	34410	288	4.07				
ASA_IMM_1PNPDE20080929_012956_000000502072_00289_34411_1617.N1	IS2	V/V	72	34411	289	4.07				
ASA_IMM_1PNPDE20080929_021111_000000832072_00289_34411_1720.N1	IS2	H/H	72	34411	289	4.07				
ASA_IMM_1PNPDE20080929_024448_000000372072_00290_34412_1753.N1	IS2	H/H	72	34412	290	4.07				
ASA_IMM_1PNPDE20080929_025320_000000372072_00290_34412_1775.N1	IS2	H/H	72	34412	290	4.07				
ASA_IMM_1PNPDE20080929_031036_000003152072_00290_34412_1847.N1	IS2	V/V	72	34412	290	4.07				
ASA_IMM_1PNPDE20080929_034103_000003222072_00290_34412_1862.N1	IS2	H/H	72	34412	290	4.07				
ASA_IMM_1PNPDE20080929_034703_000004502072_00290_34412_2015.N1	IS2	H/H	72	34412	290	4.07				
ASA_IMM_1PNPDE20080929_045034_000002962072_00291_34413_2005.N1	IS2	V/V	72	34413	291	4.07				
ASA_IMM_1PNPDE20080929_052203_000002032072_00291_34413_2025.N1	IS2	H/H	72	34413	291	4.07				
ASA_IMM_1PNPDE20080929_052603_000004832072_00291_34413_2059.N1	IS2	H/H	72	34413	291	4.07				
ASA_IMM_1PNPDE20080929_064714_000000282072_00292_34414_2057.N1	IS2	V/V	72	34414	292	4.07				
ASA_IMM_1PNPDE20080929_070326_000003222072_00292_34414_2181.N1	IS2	H/H	72	34414	292	4.07				
ASA_IMM_1PNPDK20080929_070926_000002732072_00292_34414_9305.N1	IS2	H/H	72	34414	292	4.07				
ASA_IMM_1PNPDK20080929_074958_000000702072_00293_34415_9303.N1	IS2	V/V	72	34415	293	4.07				
ASA_IMM_1PNPDK20080929_094736_000000372072_00294_34416_9451.N1	IS7	V/V	72	34416	294	4.07				
ASA_IMM_1PNPDK20080929_095128_000000852072_00294_34416_9466.N1	IS2	V/V	72	34416	294	4.07				
ASA_IMM_1PNPDE20080929_102547_000003222072_00294_34416_2243.N1	IS2	H/H	72	34416	294	4.07				
ASA_IMM_1PNPDK20080929_120843_000004392072_00295_34417_9743.N1	IS2	H/H	72	34417	295	4.07				
ASA_IMM_1PNPDE20080929_141216_000000372072_00296_34418_2266.N1	IS2	V/V	72	34418	296	4.07				
ASA_IMM_1PNPDE20080929_141603_000000522072_00296_34418_2271.N1	IS1	V/V	72	34418	296	4.07				
ASA_IMM_1PNPDE20080929_145458_000000372072_00297_34419_2275.N1	IS3	H/H	72	34419	297	4.07				
ASA_IMM_1PNPDE20080929_160413_000003932072_00298_34420_2299.N1	IS2	V/V	72	34420	298	4.07				
ASA_IMM_1PNPDE20080929_170915_000002012072_00298_34420_2335.N1	IS2	H/H	72	34420	298	4.07				
ASA_IMM_1PNPDE20080929_171612_000000832072_00298_34420_2305.N1	IS2	H/H	72	34420	298	4.07				
ASA_IMM_1PNPDE20080929_171754_000000832072_00298_34420_2311.N1	IS2	H/H	72	34420	298	4.07				
ASA_IMM_1PNPDE20080929_174348_000002382072_00299_34421_2343.N1	IS6	V/V	72	34421	299	4.07				
ASA_IMM_1PNPDE20080929_181558_000001592072_00299_34421_2378.N1	IS2	V/V	72	34421	299	4.07				
ASA_IMM_1PNPDE20080929_185020_000001412072_00299_34421_2380.N1	IS2	H/H	72	34421	299	4.07				
ASA_IMM_1PNPDE20080929_191504_000000672072_00299_34421_2384.N1	IS6	H/H	72	34421	299	4.07				
ASA_IMM_1PNPDE20080929_192046_000001282072_00300_34422_2525.N1	IS2	V/V	72	34422	300	4.07				
ASA_IMM_1PNPDE20080929_192329_000000952072_00300_34422_2382.N1	IS2	V/V	72	34422	300	4.07				
ASA_IMM_1PNPDK20080929_193138_000004132072_00300_34422_0242.N1	IS2	V/V	72	34422	300	4.07				
ASA_IMM_1PNPDE20080929_202826_000002642072_00300_34422_2527.N1	IS2	H/H	72	34422	300	4.07				
ASA_IMM_1PNPDE20080929_203426_000002612072_00300_34422_2529.N1	IS2	H/H	72	34422	300	4.07				
ASA_IMM_1PNPDE20080929_211131_000000532072_00301_34423_2551.N1	IS2	V/V	72	34423	301	4.07				
ASA_IMM_1PNPDK20080929_211201_000000362072_00301_34423_0259.N1	IS2	V/V	72	34423	301	4.07				
ASA_IMM_1PNPDE20080929_213314_000001092072_00301_34423_2654.N1	IS2	V/V	72	34423	301	4.07				
ASA_IMM_1PNPDE20080929_221012_000000792072_00301_34423_2656.N1	IS2	H/H	72	34423	301	4.07				
ASA_IMM_1PNPDE20080929_221416_000003532072_00301_34423_2674.N1	IS2	H/H	72	34423	301	4.07				
ASA_IMM_1PNPDE20080929_224430_000002212072_00302_34424_2679.N1	IS2	V/V	72	34424	302	4.07				
ASA_IMM_1PNPDE20080929_224430_000002212072_00302_34424_2681.N1	IS2	V/V	72	34424	302	4.07				
ASA_IMM_1PNPDE20080929_224430_000002212072_00302_34424_2983.N1	IS2	V/V	72	34424	302	4.07				
ASA_IMM_1PNPDK20080929_225724_000000372072_00302_34424_0285.N1	IS7	V/V	72	34424	302	4.07				
ASA_IMM_1PNPDE20080929_234749_000001212072_00302_34424_2806.N1	IS2	H/H	72	34424	302	4.07				
ASA_IMM_1PNPDE20080929_235046_000005752072_00302_34424_2833.N1	IS2	H/H	72	34424	302	4.07				

Filename	Pol	Timestamp	count(Module)
ASA_MS__0PNPDE20080929_015921_000000162072_00289_34411_0339.N1	H	2008-09-29 01:59:21	320
ASA_MS__0PNPDK20080929_084145_000000162072_00293_34415_0646.N1	V	2008-09-29 08:41:45	320

Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion				
ASA_WSM_1PNPDE20080929_000024_000000922072_00288_34410_1594.N1	SS1	V/V	72	34410	288	4.07				
ASA_WSM_1PNPDE20080929_010743_000003912072_00289_34411_1745.N1	SS1	H/H	72	34411	289	4.07				
ASA_WSM_1PNPDE20080929_020146_000000732072_00289_34411_1714.N1	SS1	H/H	72	34411	289	4.07				
ASA_WSM_1PNPDE20080929_020146_000001822072_00289_34411_1877.N1	SS1	H/H	72	34411	289	4.07				
ASA_WSM_1PNPDE20080929_020400_000000482072_00289_34411_1718.N1	SS1	H/H	72	34411	289	4.07				
ASA_WSM_1PNPDE20080929_061702_000000732072_00292_34414_2037.N1	SS1	H/H	72	34414	292	4.07				
ASA_WSM_1PNPDE20080929_061702_000000732072_00292_34414_2177.N1	SS1	H/H	72	34414	292	4.07				
ASA_WSM_1PNPDE20080929_061702_000000732072_00292_34414_2222.N1	SS1	H/H	72	34414	292	4.07				
ASA_WSM_1PNPDE20080929_075914_000000912072_00293_34415_2210.N1	SS1	H/H	72	34415	293	4.07				
ASA_WSM_1PNPDE20080929_135659_000001032072_00296_34418_2281.N1	SS1	H/H	72	34418	296	4.07				
ASA_WSM_1PNPDE20080929_151628_000001352072_00297_34419_2283.N1	SS1	H/H	72	34419	297	4.07				
ASA_WSM_1PNPDE20080929_162450_000001642072_00298_34420_2347.N1	SS1	H/H	72	34420	298	4.07				
ASA_WSM_1PNPDE20080929_162603_000000902072_00298_34420_2341.N1	SS1	H/H	72	34420	298	4.07				
ASA_WSM_1PNPDE20080929_180444_000001282072_00299_34421_2345.N1	SS1	H/H	72	34421	299	4.07				
ASA_WSM_1PNPDE20080929_180541_000002262072_00299_34421_2386.N1	SS1	H/H	72	34421	299	4.07				
ASA_WSM_1PNPDE20080929_204650_000002872072_00300_34422_2535.N1	SS1	V/V	72	34422	300	4.07				
ASA_WSM_1PNPDE20080929_220736_000001342072_00301_34423_2683.N1	SS1	H/H	72	34423	301	4.07				
ASA_WSM_1PNPDE20080929_231143_000001522072_00302_34424_2828.N1	SS1	H/H	72	34424	302	4.07				

Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion				
ASA_WVS_1PNPDE20080929_000154_000001342072_00288_34410_1478.N1	IS2	V/V	72	34410	288	4.07				
ASA_WVS_1PNPDE20080929_001145_000002852072_00288_34410_1483.N1	IS2	V/V	72	34410	288	4.07				
ASA_WVS_1PNPDE20080929_003621_000003142072_00288_34410_1488.N1	IS2	V/V	72	34410	288	4.07				
ASA_WVS_1PNPDE20080929_004036_000004342072_00288_34410_1610.N1	IS2	V/V	72	34410	288	4.07				
ASA_WVS_1PNPDE20080929_003621_000003142072_00288_34410_1488.N1	IS1	V/V	72	34410	288	4.07				
ASA_WVS_1PNPDE20080929_005110_000009442072_00288_34410_1615.N1	IS2	V/V	72	34410	288	4.07				
ASA_WVS_1PNPDE20080929_013243_000008852072_00289_34411_1626.N1	IS2	V/V	72	34411	289	4.07				
ASA_WVS_1PNPDE20080929_015054_000003752072_00289_34411_1629.N1	IS2	V/V	72	34411	289	4.07				
ASA_WVS_1PNPDE20080929_021657_000000152072_00289_34411_1632.N1	IS2	V/V	72	34411	289	4.07				
ASA_WVS_1PNPDE20080929_021657_000002852072_00289_34411_1783.N1	IS2	V/V	72	34411	289	4.07				
ASA_WVS_1PNPDE20080929_031907_000008242072_00290_34412_1788.N1	IS2	V/V	72	34412	290	4.07				
ASA_WVS_1PNPDE20080929_033236_000002402072_00290_34412_1885.N1	IS2	V/V	72	34412	290	4.07				
ASA_WVS_1PNPDE20080929_031907_000008242072_00290_34412_1788.N1	IS1	V/V	72	34412	290	4.07				
ASA_WVS_1PNPDE20080929_040030_000009442072_00290_34412_1948.N1	IS2	V/V	72	34412	290	4.07				
ASA_WVS_1PNPDE20080929_045957_000008542072_00291_34413_1951.N1	IS2	V/V	72	34413	291	4.07				
ASA_WVS_1PNPDE20080929_051342_000002852072_00291_34413_2066.N1	IS2	V/V	72	34413	291	4.07				
ASA_WVS_1PNPDE20080929_045957_000008542072_00291_34413_1951.N1	IS1	V/V	72	34413	291	4.07				
ASA_WVS_1PNPDE20080929_053809_000014542072_00291_34413_2097.N1	IS2	V/V	72	34413	291	4.07				
ASA_WVS_1PNPDE20080929_064410_000001342072_00292_34414_2094.N1	IS2	V/V	72	34414	292	4.07				
ASA_WVS_1PNPDE20080929_064749_000004642072_00292_34414_2091.N1	IS2	V/V	72	34414	292	4.07				
ASA_WVS_1PNPDK20080929_065519_000002252072_00292_34414_9225.N1	IS2	V/V	72	34414	292	4.07				
ASA_WVS_1PNPDK20080929_071845_000018292072_00292_34414_9263.N1	IS2	V/V	72	34414	292	4.07				
ASA_WVS_1PNPDK20080929_083227_000004202072_00293_34415_9327.N1	IS2	V/V	72	34415	293	4.07				
ASA_WVS_1PNPDK20080929_085921_000019492072_00293_34415_9348.N1	IS2	V/V	72	34415	293	4.07				
ASA_WVS_1PNPDK20080929_100414_000009592072_00294_34416_9511.N1	IS2	V/V	72	34416	294	4.07				
ASA_WVS_1PNPDK20080929_103956_000002102072_00294_34416_9506.N1	IS2	V/V	72	34416	294	4.07				
ASA_WVS_1PNPDK20080929_104524_000014092072_00294_34416_9521.N1	IS2	V/V	72	34416	294	4.07				
ASA_WVS_1PNPDK20080929_112744_000007342072_00295_34417_9626.N1	IS2	V/V	72	34417	295	4.07				
ASA_WVS_1PNPDK20080929_114205_000011242072_00295_34417_9631.N1	IS2	V/V	72	34417	295	4.07				
ASA_WVS_1PNPDK20080929_122032_000003152072_00295_34417_9634.N1	IS2	V/V	72	34417	295	4.07				
ASA_WVS_1PNPDK20080929_123036_000010212072_00295_34417_9650.N1	IS2	V/V	72	34417	295	4.07				
ASA_WVS_1PNPDK20080929_130954_000005092072_00296_34418_9760.N1	IS2	V/V	72	34418	296	4.07				
ASA_WVS_1PNPDK20080929_132040_000002092072_00296_34418_9778.N1	IS2	V/V	72	34418	296	4.07				
ASA_WVS_1PNPDK20080929_140108_000003302072_00296_34418_9783.N1	IS2	V/V	72	34418	296	4.07				
ASA_WVS_1PNPDK20080929_141300_000001492072_00296_34418_9771.N1	IS2	V/V	72	34418	296	4.07				
ASA_WVS_1PNPDK20080929_141701_000001942072_00297_34419_9786.N1	IS2	V/V	72	34419	297	4.07				
ASA_WVS_1PNPDK20080929_150902_000004042072_00297_34419_9896.N1	IS2	V/V	72	34419	297	4.07				
ASA_WVS_1PNPDK20080929_151857_000001802072_00297_34419_9899.N1	IS2	V/V	72	34419	297	4.07				
ASA_WVS_1PNPDK20080929_154144_000012442072_00297_34419_9908.N1	IS2	V/V	72	34419	297	4.07				
ASA_WVS_1PNPDK20080929_164301_000011692072_00298_34420_0023.N1	IS2	V/V	72	34420	298	4.07				
ASA_WVS_1PNPDK20080929_172220_000012442072_00298_34420_0033.N1	IS2	V/V	72	34420	298	4.07				
ASA_WVS_1PNPDK20080929_181843_000014692072_00299_34421_0142.N1	IS2	V/V	72	34421	299	4.07				
ASA_WVS_1PNPDK20080929_190459_000005692072_00299_34421_0147.N1	IS2	V/V	72	34421	299	4.07				
ASA_WVS_1PNPDK20080929_191617_000000742072_00299_34421_0152.N1	IS2	V/V	72	34421	299	4.07				
ASA_WVS_1PNPDE20080929_195222_000018892072_00300_34422_2395.N1	IS2	V/V	72	34422	300	4.07				
ASA_WVS_1PNPDE20080929_204332_000000452072_00300_34422_2403.N1	IS2	V/V	72	34422	300	4.07				
ASA_WVS_1PNPDE20080929_204332_000001502072_00300_34422_2538.N1	IS2	V/V	72	34422	300	4.07				
ASA_WVS_1PNPDE20080929_213509_000017542072_00301_34423_2547.N1	IS2	V/V	72	34423	301	4.07				
ASA_WVS_1PNPDE20080929_222408_000002252072_00301_34423_2563.N1	IS2	V/V	72	34423	301	4.07				
ASA_WVS_1PNPDE20080929_222708_000007792072_00301_34423_2692.N1	IS2	V/V	72	34423	301	4.07				
ASA_WVS_1PNPDE20080929_224818_000005092072_00302_34424_2697.N1	IS2	V/V	72	34424	302	4.07				
ASA_WVS_1PNPDE20080929_231413_000012442072_00302_34424_2704.N1	IS2	V/V	72	34424	302	4.07				
ASA_WVS_1PNPDE20080929_234117_000002252072_00302_34424_2724.N1	IS2	V/V	72	34424	302	4.07				


Absolute Doppler 'GM1' 'SS1' H/H ascending
-1000Hz
+1000Hz


Absolute Doppler 'GM1' 'SS1' H/H descending
−1000Hz
+1000Hz


Absolute Doppler 'WVS' 'IS2' V/V ascending
−1000Hz
+1000Hz


Absolute Doppler 'WVS' 'IS2' V/V descending
−1000Hz
+1000Hz


GM1 SS1 H/H Doppler (predicted in red, actual in blue)
Doppler [Hz]
1000
500
0
−500
−1000
−1500
0
1000
2000
3000
4000
5000
6000
secs from ANX


GM1 SS1 H/H Doppler Bias vs ANX
Doppler Bias [Hz]
200
100
0
−100
−200
0
1000
2000
3000
4000
5000
6000
secs from ANX


GM1 SS1 H/H Doppler Bias vs Date
Doppler Bias [Hz]
200
100
0
−100
−200
02
04
06
08
10
12
14
16
18
20
22
29−Sep
Date


WVS IS2 V/V Doppler (predicted in red, actual in blue)
Doppler [Hz]
1000
500
0
−500
−1000
−1500
0
1000
2000
3000
4000
5000
6000
secs from ANX


WVS IS2 V/V Doppler Bias vs ANX
Doppler Bias [Hz]
200
100
0
−100
−200
0
1000
2000
3000
4000
5000
6000
secs from ANX


WVS IS2 V/V Doppler Bias vs Date
Doppler Bias [Hz]
200
100
0
−100
−200
02
04
06
08
10
12
14
16
18
20
22
29−Sep
Date


Doppler difference, Estimated – Predicted – MeanError 'GM1' 'SS1' H/H ascending
−100Hz
+100Hz


Doppler difference, Estimated – Predicted – MeanError 'GM1' 'SS1' H/H descending
−100Hz
+100Hz


Doppler difference, Estimated – Predicted – MeanError 'WVS' 'IS2' V/V ascending
−100Hz
+100Hz


Doppler difference, Estimated – Predicted – MeanError 'WVS' 'IS2' V/V descending
−100Hz
+100Hz


WSM Delta Doppler Coefficients (SCANSAR) vs ANX
Coeff 1 (SS1->SS2)
Coeff 2 (SS2->SS3)
Coeff 3 (SS3->SS4)
Coeff 4 (SS4->SS5)
150
100
50
0
−50
−100
−150
0
1000
2000
3000
4000
5000
6000
secs from ANX


WSM Delta Doppler Coefficients (SCANSAR) vs Date
Coeff 1 (SS1->SS2)
Coeff 2 (SS2->SS3)
Coeff 3 (SS3->SS4)
Coeff 4 (SS4->SS5)
150
100
50
0
−50
−100
−150
02
04
06
08
10
12
14
16
18
20
22
29−Sep
Date


Reference: 2008-09-27 03:02:35 H
Test : 2008-09-29 01:59:21 H
RxGain
A1
A3
B1
B3
C1
C3
D1
D3
E1
E3
A2
A4
B2
B4
C2
C4
D2
D4
E2
E4
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32


Reference: 2008-09-28 02:30:58 V
Test : 2008-09-29 08:41:45 V
RxGain
A1
A3
B1
B3
C1
C3
D1
D3
E1
E3
A2
A4
B2
B4
C2
C4
D2
D4
E2
E4
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32


Reference: 2008-09-27 03:02:35 H
Test : 2008-09-29 01:59:21 H
RxPhase
A1
A3
B1
B3
C1
C3
D1
D3
E1
E3
A2
A4
B2
B4
C2
C4
D2
D4
E2
E4
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32


Reference: 2008-09-28 02:30:58 V
RxPhase
Test : 2008-09-29 08:41:45 V
A1
A3
B1
B3
C1
C3
D1
D3
E1
E3
A2
A4
B2
B4
C2
C4
D2
D4
E2
E4
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32


Reference: 2008-09-27 03:02:35 H
Test : 2008-09-29 01:59:21 H
TxGain
A1
A3
B1
B3
C1
C3
D1
D3
E1
E3
A2
A4
B2
B4
C2
C4
D2
D4
E2
E4
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32


Reference: 2008-09-28 02:30:58 V
Test : 2008-09-29 08:41:45 V
TxGain
A1
A3
B1
B3
C1
C3
D1
D3
E1
E3
A2
A4
B2
B4
C2
C4
D2
D4
E2
E4
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32


Reference: 2008-09-27 03:02:35 H
Test : 2008-09-29 01:59:21 H
TxPhase
A1
A3
B1
B3
C1
C3
D1
D3
E1
E3
A2
A4
B2
B4
C2
C4
D2
D4
E2
E4
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32


Reference: 2008-09-28 02:30:58 V
Test : 2008-09-29 08:41:45 V
TxPhase
A1
A3
B1
B3
C1
C3
D1
D3
E1
E3
A2
A4
B2
B4
C2
C4
D2
D4
E2
E4
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32


I/Q Gain Imbalance
0.25
0.20
0.15
0.10
0.05
0.00
stdev Q
0.00
0.05
0.10
0.15
0.20
0.25
stdev I


SQADS input data MEAN I(black), Q(red)
linear scale
0.0020
0.0010
0.0000
−0.0010
−0.0020
02 04 06 08 10 12 14 16 18 20 22
29−Sep
SQADS input data MEAN I
linear scale
0.0020
0.0010
0.0000
−0.0010
−0.0020
02 04 06 08 10 12 14 16 18 20 22
29−Sep
SQADS input data MEAN Q
linear scale
0.0020
0.0010
0.0000
−0.0010
−0.0020
02 04 06 08 10 12 14 16 18 20 22
29−Sep


SQADS input data STDEV I(black), Q(red)
linear scale
0.30
0.20
0.10
0.00
−0.10
02 04 06 08 10 12 14 16 18 20 22
29−Sep
SQADS input data STDEV I
linear scale
0.30
0.20
0.10
0.00
−0.10
02 04 06 08 10 12 14 16 18 20 22
29−Sep
SQADS input data STDEV Q
linear scale
0.30
0.20
0.10
0.00
−0.10
02 04 06 08 10 12 14 16 18 20 22
29−Sep


I/Q Gain Imbalance
stdev Q
stdev I
0.00
0.05
0.10
0.15
0.20
0.25


SQADS input data MEAN I(black), Q(red)
linear scale
0.0020
0.0010
0.0000
−0.0010
−0.0020
02 04 06 08 10 12 14 16 18 20 22
29−Sep
SQADS input data MEAN I
linear scale
0.0020
0.0010
0.0000
−0.0010
−0.0020
02 04 06 08 10 12 14 16 18 20 22
29−Sep
SQADS input data MEAN Q
linear scale
0.0020
0.0010
0.0000
−0.0010
−0.0020
02 04 06 08 10 12 14 16 18 20 22
29−Sep


SQADS input data STDEV I(black), Q(red)
linear scale
0.30
0.20
0.10
0.00
−0.10
02 04 06 08 10 12 14 16 18 20 22
29−Sep
SQADS input data STDEV I
linear scale
0.30
0.20
0.10
0.00
−0.10
02 04 06 08 10 12 14 16 18 20 22
29−Sep
SQADS input data STDEV Q
linear scale
0.30
0.20
0.10
0.00
−0.10
02 04 06 08 10 12 14 16 18 20 22
29−Sep


Reference: 2005-09-22 06:26:51 H
Test : 2008-09-29 01:59:21 H
RxGain
A1
A3
B1
B3
C1
C3
D1
D3
E1
E3
A2
A4
B2
B4
C2
C4
D2
D4
E2
E4


Reference: 2005-09-23 05:55:14 V
Test : 2008-09-29 08:41:45 V
RxGain
A1
A3
B1
B3
C1
C3
D1
D3
E1
E3
A2
A4
B2
B4
C2
C4
D2
D4
E2
E4
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32


Reference: 2005-09-22 06:26:51 H
RxPhase
Test : 2008-09-29 01:59:21 H
A1
A3
B1
B3
C1
C3
D1
D3
E1
E3
A2
A4
B2
B4
C2
C4
D2
D4
E2
E4
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32


Reference: 2005-09-23 05:55:14 V
Test : 2008-09-29 08:41:45 V
RxPhase
A1
A3
B1
B3
C1
C3
D1
D3
E1
E3
A2
A4
B2
B4
C2
C4
D2
D4
E2
E4


Reference: 2005-09-22 06:26:51 H
Test : 2008-09-29 01:59:21 H
TxGain
A1
A3
B1
B3
C1
C3
D1
D3
E1
E3
A2
A4
B2
B4
C2
C4
D2
D4
E2
E4


Reference: 2005-09-23 05:55:14 V
Test : 2008-09-29 08:41:45 V
TxGain
A1
A3
B1
B3
C1
C3
D1
D3
E1
E3
A2
A4
B2
B4
C2
C4
D2
D4
E2
E4
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32


Reference: 2005-09-22 06:26:51 H
Test : 2008-09-29 01:59:21 H
TxPhase
A1
A3
B1
B3
C1
C3
D1
D3
E1
E3
A2
A4
B2
B4
C2
C4
D2
D4
E2
E4


Reference: 2005-09-23 05:55:14 V
Test : 2008-09-29 08:41:45 V
TxPhase
A1
A3
B1
B3
C1
C3
D1
D3
E1
E3
A2
A4
B2
B4
C2
C4
D2
D4
E2
E4
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32


1
0.5
0
-0.5
-1
Number of gaps
34410
34415
34420
34425
34430
Orbit
WVS_PDE
WVS_PDK
GM1_PDE
GM1_PDK
APM_PDE
APM_PDK
IMM_PDE
IMM_PDK
WSM_PDE


Number of missing lines
40
30
20
10
0
34410
34415
34420
34425
34430
Orbit
WVS_PDE
WVS_PDK
GM1_PDE
GM1_PDK
APM_PDE
APM_PDK
IMM_PDE
IMM_PDK
WSM_PDE