

ASAR DAILY REPORT for 070615
#####

MODE: DAILY
ANALYSIS: ALL
DATE: YESTERDAY

Analysis will be performed from 2007-06-15 00:00:00 to 2007-06-15 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/070615/

DATA SUMMARY

Summary will be performed from 2007-06-15 00:00:00 to 2007-06-15 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/070615/DATA_SUMMARY

Creating directory ./RESULTS/DAILY/070615/DATA_SUMMARY...
Writing file ./RESULTS/DAILY/070615/DATA_SUMMARY/Data_summary.html...

Getting WVS products list from 2007-06-15 00:00:00 to 2007-06-15 23:59:59...
Writing file ./RESULTS/DAILY/070615/DATA_SUMMARY/List_WVS_products_used.xls...
Writing file ./RESULTS/DAILY/070615/DATA_SUMMARY/List_WVS_products_used.txt...

Getting GM1 products list from 2007-06-15 00:00:00 to 2007-06-15 23:59:59...
Writing file ./RESULTS/DAILY/070615/DATA_SUMMARY/List_GM1_products_used.xls...
Writing file ./RESULTS/DAILY/070615/DATA_SUMMARY/List_GM1_products_used.txt...

Getting APM products list from 2007-06-15 00:00:00 to 2007-06-15 23:59:59...
Writing file ./RESULTS/DAILY/070615/DATA_SUMMARY/List_APM_products_used.xls...
Writing file ./RESULTS/DAILY/070615/DATA_SUMMARY/List_APM_products_used.txt...

Getting IMM products list from 2007-06-15 00:00:00 to 2007-06-15 23:59:59...
Writing file ./RESULTS/DAILY/070615/DATA_SUMMARY/List_IMM_products_used.xls...
Writing file ./RESULTS/DAILY/070615/DATA_SUMMARY/List_IMM_products_used.txt...

Getting WSM products list from 2007-06-15 00:00:00 to 2007-06-15 23:59:59...
Writing file ./RESULTS/DAILY/070615/DATA_SUMMARY/List_WSM_products_used.xls...
Writing file ./RESULTS/DAILY/070615/DATA_SUMMARY/List_WSM_products_used.txt...

Getting MS products list from 2007-06-15 00:00:00 to 2007-06-15 23:59:59...
Writing file ./RESULTS/DAILY/070615/DATA_SUMMARY/List_MS_products_used.xls...
Writing file ./RESULTS/DAILY/070615/DATA_SUMMARY/List_MS_products_used.txt...

DATA SUMMARY completed
#####

AUXILIARY FILES ANALYSIS

Analysis will be performed from 2007-06-15 00:00:00 to 2007-06-15 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/070615/AUXILIARY

Creating directory ./RESULTS/DAILY/070615/AUXILIARY...

Looking for the IECF operational ADFs list...

Found list 20070615_030001_current_3_IECF_ADFs.txt...
Extracting ADFs...

ASA_CON_AXVIEC20070410_140202_20070204_165113_20071231_000000
ASA_INS_AXVIEC20070306_164819_20070307_060000_20071231_000000
ASA_XCH_AXVIEC20051219_162547_20020301_000000_20081231_000000
ASA_XCA_AXVIEC20070517_153558_20070204_165113_20071231_000000

Writing file ./RESULTS/DAILY/070615/AUXILIARY/ASAR_ADFs_IECF_List3.html...
Writing file ./RESULTS/DAILY/070615/AUXILIARY/Auxiliary_files_summary.html...

Analysing WVS products...

Writing file ./RESULTS/DAILY/070615/AUXILIARY/Check_ADFs_WVS.xls...
Writing file ./RESULTS/DAILY/070615/AUXILIARY/Check_ADFs_WVS.txt...

ASA_WVS_1PNPDE20070615_001952_000011472059_00045_27654_9150.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20070615_004548_000004052059_00045_27654_9083.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20070615_010931_000003302059_00045_27654_9080.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20070615_011401_000002992059_00045_27654_9198.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20070615_012652_000007942059_00046_27655_9213.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20070615_021106_000008692059_00046_27655_9243.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20070615_022521_000004802059_00046_27655_9351.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20070615_025005_000002702059_00046_27655_9361.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20070615_031011_000001942059_00047_27656_9354.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20070615_035159_000009592059_00047_27656_9385.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20070615_040728_000001352059_00047_27656_9501.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20070615_043042_000012442059_00047_27656_9515.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20070615_053154_000006892059_00048_27657_9512.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20070615_054438_000001942059_00048_27657_9523.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20070615_202647_000018742059_00057_27666_0044.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20070615_211640_000003002059_00057_27666_0039.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20070615_212041_000001202059_00057_27666_0158.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20070615_220557_000001502059_00058_27667_0161.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20070615_220955_000018292059_00058_27667_0170.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20070615_225716_000002552059_00058_27667_0180.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20070615_230046_000009442059_00058_27667_0300.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20070615_231851_000007492059_00059_27668_0305.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20070615_235018_000010042059_00059_27668_0312.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070615_054738_000001342059_00048_27657_0140.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070615_055226_000001202059_00048_27657_0137.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070615_061117_000017542059_00048_27657_0147.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070615_072839_000002852059_00049_27658_0177.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070615_075153_000018742059_00049_27658_0217.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070615_090054_000008842059_00050_27659_0277.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070615_093229_000020092059_00050_27659_0313.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070615_103812_000010792059_00051_27660_0450.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070615_111423_000001202059_00051_27660_0486.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070615_111936_000015742059_00051_27660_0489.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070615_120254_000003452059_00052_27661_0467.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070615_121006_000006442059_00052_27661_0472.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070615_122745_000004502059_00052_27661_0508.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070615_125341_000003152059_00052_27661_0505.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070615_130623_000005692059_00052_27661_0511.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070615_131655_000001642059_00053_27662_0545.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070615_134700_000006442059_00053_27662_0542.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070615_141304_000002702059_00053_27662_0585.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070615_143417_000003902059_00053_27662_0573.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070615_144520_000004642059_00053_27662_0582.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070615_153432_000001342059_00054_27663_0683.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070615_153858_000001042059_00054_27663_0721.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070615_154251_000009142059_00054_27663_0730.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070615_161453_000012442059_00054_27663_0733.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070615_171546_000012742059_00055_27664_0836.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070615_175529_000012592059_00055_27664_0899.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

```
ASA_WVS_1PNPDK20070615_185007_000016492059_00056_27665_0964.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070615_193605_000000902059_00056_27665_0957.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070615_194108_000003742059_00056_27665_0954.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```

Analysing GM1 products...

Writing file ./RESULTS/DAILY/070615/AUXILIARY/Check_ADFs_GM1.xls...

Writing file ./RESULTS/DAILY/070615/AUXILIARY/Check_ADFs_GM1.txt...

```
ASA_GM1_1PNPDE20070615_000318_000009912059_00045_27654_9173.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070615_003948_000003562059_00045_27654_9077.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070615_011954_000003982059_00045_27654_9200.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070615_014050_00000902059_00046_27655_9202.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070615_014540_000011832059_00046_27655_9240.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070615_020746_000001812059_00046_27655_9237.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070615_023407_000001082059_00046_27655_9348.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070615_024817_000001082059_00046_27655_9346.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070615_025526_000001142059_00046_27655_9342.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070615_025730_000004532059_00046_27655_9369.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070615_030634_000002172059_00046_27655_9358.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070615_031416_000004042059_00047_27656_9371.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070615_032642_000000662059_00047_27656_9356.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070615_032841_000010442059_00047_27656_9449.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070615_034752_000002472059_00047_27656_9382.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070615_045218_000002592059_00048_27657_9503.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070615_045820_000002892059_00048_27657_9498.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070615_050434_000016362059_00048_27657_9591.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070615_201755_000002172059_00057_27666_0029.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070615_202447_000001202059_00057_27666_0031.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070615_210631_000006042059_00057_27666_0041.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070615_212806_000010332059_00057_27666_0270.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070615_214331_000001082059_00057_27666_0167.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070615_224118_000002772059_00058_27667_0163.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070615_225328_000002232059_00058_27667_0177.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070615_231726_000000842059_00059_27668_0302.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070615_233725_000006582059_00059_27668_0307.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_055952_000003502059_00048_27657_0144.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_060729_000002232059_00048_27657_0142.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_064544_000000842059_00049_27658_0183.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_065057_000003922059_00049_27658_0187.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_065648_000005012059_00049_27658_0191.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_070648_000004532059_00049_27658_0181.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_071636_000002712059_00049_27658_0179.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_072418_000002592059_00049_27658_0174.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_074505_000004042059_00049_27658_0185.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_082520_000008632059_00050_27659_0274.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_083901_000001692059_00050_27659_0300.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_084543_000001502059_00050_27659_0283.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_085105_000005862059_00050_27659_0302.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_091631_000002412059_00050_27659_0281.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_093041_000001082059_00050_27659_0279.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_100644_000003982059_00051_27660_0458.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_102715_000000722059_00051_27660_0454.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_103030_000004592059_00051_27660_0456.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_105706_000001082059_00051_27660_0452.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_110517_000000782059_00051_27660_0447.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_114645_000003742059_00052_27661_0491.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_115200_000000602059_00052_27661_0474.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_122133_000003682059_00052_27661_0478.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_124752_000003442059_00052_27661_0476.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_125942_000003982059_00052_27661_0469.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_132031_000001502059_00053_27662_0539.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_132429_000006462059_00053_27662_0559.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_133434_000005312059_00053_27662_0557.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_135831_000002412059_00053_27662_0553.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```

ASA_GM1_1PNPDK20070615_140418_000001202059_00053_27662_0555.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_140710_000002472059_00053_27662_0549.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_141818_000009242059_00053_27662_0551.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_144130_000002292059_00053_27662_0547.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_145551_000003202059_00054_27663_0680.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_150354_000003922059_00054_27663_0687.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_152137_000007732059_00054_27663_0692.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_153731_000008842059_00054_27663_0685.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_155854_000009242059_00054_27663_0689.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_163620_000002112059_00055_27664_0812.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_164102_000002952059_00055_27664_0810.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_164842_000001262059_00055_27664_0808.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_170536_000006102059_00055_27664_0806.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_174119_000003862059_00055_27664_0831.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_175132_000002352059_00055_27664_0833.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_182035_000004162059_00056_27665_0951.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_182803_000001142059_00056_27665_0966.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_182847_000001572059_00056_27665_0968.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_184512_000001382059_00056_27665_0961.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_192355_000007252059_00056_27665_0970.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_194817_000007972059_00056_27665_0959.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070615_200257_000002412059_00057_27666_1048.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

Analysing APM products...

Writing file ./RESULTS/DAILY/070615/AUXILIARY/Check_ADFs_APM.xls...

Writing file ./RESULTS/DAILY/070615/AUXILIARY/Check_ADFs_APM.txt...

ASA_APM_1PNPDE20070615_072110_000001602059_00049_27658_9681.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20070615_084814_00000422059_00050_27659_9688.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20070615_134541_000000722059_00053_27662_9919.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20070615_163954_00000402059_00055_27664_9921.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDK20070615_084435_00000422059_00050_27659_0116.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

Analysing IMM products...

Writing file ./RESULTS/DAILY/070615/AUXILIARY/Check_ADFs_IMM.xls...

Writing file ./RESULTS/DAILY/070615/AUXILIARY/Check_ADFs_IMM.txt...

ASA_IMM_1PNPDE20070615_020549_000001012059_00046_27655_9299.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20070615_030502_000000742059_00046_27655_9441.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20070615_032747_000000352059_00047_27656_9344.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20070615_045641_000000812059_00048_27657_9494.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20070615_050311_000000642059_00048_27657_9496.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20070615_054402_000000292059_00048_27657_9529.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20070615_070510_000000812059_00049_27658_9640.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20070615_071422_000001162059_00049_27658_9648.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20070615_084957_000000502059_00050_27659_9690.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20070615_120924_000000362059_00052_27661_9803.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20070615_140617_000000352059_00053_27662_9899.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20070615_141117_000000342059_00053_27662_9897.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20070615_154121_000000822059_00054_27663_9931.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20070615_170102_000000352059_00055_27664_9953.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20070615_200135_000000352059_00057_27666_0011.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20070615_214520_000000362059_00058_27667_0112.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20070615_220912_000000362059_00058_27667_0252.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20070615_234822_000001102059_00059_27668_0407.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20070615_082352_000000532059_00050_27659_0114.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20070615_201134_000000362059_00057_27666_0931.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20070615_201554_000001052059_00057_27666_1050.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20070615_201656_000000432059_00057_27666_0943.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

Analysing WSM products...

Writing file ./RESULTS/DAILY/070615/AUXILIARY/Check_ADFs_WSM.xls...

Writing file ./RESULTS/DAILY/070615/AUXILIARY/Check_ADFs_WSM.txt...

ASA_WSM_1PNPDE20070615_005330_000005992059_00045_27654_9312.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20070615_010407_000003242059_00045_27654_9230.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20070615_014233_000001762059_00046_27655_9310.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20070615_023606_000004832059_00046_27655_9468.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20070615_024443_000001832059_00046_27655_9314.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20070615_032108_000003242059_00047_27656_9484.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20070615_034618_000000852059_00047_27656_9451.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20070615_041442_000003852059_00047_27656_9617.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20070615_042139_000005452059_00047_27656_9642.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20070615_055718_000001412059_00048_27657_9634.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20070615_073409_000002022059_00049_27658_9683.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20070615_092045_000005862059_00050_27659_9854.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20070615_092152_000001152059_00050_27659_9811.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20070615_092450_000003412059_00050_27659_9812.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20070615_105906_000003612059_00051_27660_9801.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20070615_110643_000004582059_00051_27660_9860.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20070615_111713_000001462059_00051_27660_9831.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20070615_123557_000001402059_00052_27661_9856.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20070615_140245_000000852059_00053_27662_9923.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20070615_145357_000001042059_00054_27663_9925.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20070615_150119_000001472059_00054_27663_9929.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20070615_164609_000001402059_00055_27664_9945.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20070615_165809_000001282059_00055_27664_9943.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20070615_170202_000002022059_00055_27664_9985.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20070615_173746_000002012059_00055_27664_9995.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20070615_174754_000000862059_00055_27664_9967.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20070615_174958_000000852059_00055_27664_9983.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20070615_181714_000001842059_00056_27665_9998.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20070615_183829_000001462059_00056_27665_9993.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20070615_184121_000002192059_00056_27665_0025.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20070615_191822_000003232059_00056_27665_0027.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20070615_202144_000001712059_00057_27666_0133.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20070615_205857_000004472059_00057_27666_0250.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20070615_212332_000002632059_00057_27666_0248.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20070615_215737_000002082059_00058_27667_0393.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20070615_220144_000002262059_00058_27667_0295.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20070615_224606_000004282059_00058_27667_0297.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20070615_060555_000000852059_00048_27657_0108.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20070615_064250_000001652059_00049_27658_0110.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20070615_064722_000002012059_00049_27658_0112.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20070615_101334_000003852059_00051_27660_0441.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20070615_115310_000004832059_00052_27661_0443.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20070615_123841_000005392059_00052_27661_0537.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20070615_132315_000000612059_00053_27662_0445.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20070615_151037_000004842059_00054_27663_0668.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20070615_151901_000001462059_00054_27663_0663.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20070615_165058_000004702059_00055_27664_0789.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20070615_183134_000004582059_00056_27665_0923.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20070615_200706_000002022059_00057_27666_1052.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20070615_201311_000001642059_00057_27666_1059.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20070615_214707_000001222059_00058_27667_1097.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20070615_214933_000000912059_00058_27667_1099.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20070615_215144_000003972059_00058_27667_1101.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20070615_233205_000003062059_00059_27668_1113.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

AUXILIARY FILES ANALYSIS completed

#####

MODULE STEPPING ANALYSIS

#####

Analysis will be performed from 2007-06-15 00:00:00 to 2007-06-15 23:59:59

Results will be exported to the directory: ./RESULTS/DAILY/070615/MODULE_STEPPING

Creating directory ./RESULTS/DAILY/070615/MODULE_STEPPING...

Creating directory ./RESULTS/DAILY/070615/MODULE_STEPPING/FIRST_REFERENCE...

Creating directory ./RESULTS/DAILY/070615/MODULE_STEPPING/SECOND_REFERENCE...

Creating directory ./RESULTS/DAILY/070615/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE...

Deleting old files...

Creating images comparing with second reference...

Exporting results to the directory ../../RESULTS/DAILY/070615/MODULE_STEPPING/SECOND_REFERENCE...

Polarization: H

Reference product: ASA_MS__0PNPDK20050922_062651_00000152041_00034_18625_0041.N1

Test product: ASA_MS__0PNPDK20070614_062648_00000162059_00034_27643_0309.N1

H

H

../../RESULTS/DAILY/070615/MODULE_STEPPING/SECOND_REFERENCE/TGH_20070614_062648-20050922_062651.png

../../RESULTS/DAILY/070615/MODULE_STEPPING/SECOND_REFERENCE/TPH_20070614_062648-20050922_062651.png

../../RESULTS/DAILY/070615/MODULE_STEPPING/SECOND_REFERENCE/RGH_20070614_062648-20050922_062651.png

../../RESULTS/DAILY/070615/MODULE_STEPPING/SECOND_REFERENCE/RPH_20070614_062648-20050922_062651.png

Polarization: V

Reference product: ASA_MS__0PNPDK20050923_055514_00000152041_00048_18639_0042.N1

Test product: ASA_MS__0PNPDK20070615_055511_00000162059_00048_27657_0310.N1

V

V

../../RESULTS/DAILY/070615/MODULE_STEPPING/SECOND_REFERENCE/TGV_20070615_055511-20050923_055514.png

../../RESULTS/DAILY/070615/MODULE_STEPPING/SECOND_REFERENCE/TPV_20070615_055511-20050923_055514.png

../../RESULTS/DAILY/070615/MODULE_STEPPING/SECOND_REFERENCE/RGV_20070615_055511-20050923_055514.png

../../RESULTS/DAILY/070615/MODULE_STEPPING/SECOND_REFERENCE/RPV_20070615_055511-20050923_055514.png

Creating images comparing with previous product reference...

Exporting results to the directory ../../RESULTS/DAILY/070615/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE...

Polarization: H

Reference product: ASA_MS__0PNPDK20070612_173337_00000162059_00012_27621_0307.N1

Test product: ASA_MS__0PNPDK20070614_062648_00000162059_00034_27643_0309.N1

H

H

../../RESULTS/DAILY/070615/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TGH_20070614_062648-20070612_173337.png

../../RESULTS/DAILY/070615/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TPH_20070614_062648-20070612_173337.png

../../RESULTS/DAILY/070615/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RGH_20070614_062648-20070612_173337.png

../../RESULTS/DAILY/070615/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RPH_20070614_062648-20070612_173337.png

Polarization: V

Reference product: ASA_MS__0PNPDK20070613_170200_00000162059_00026_27635_0308.N1

Test product: ASA_MS__0PNPDK20070615_055511_00000162059_00048_27657_0310.N1

V

V

../../RESULTS/DAILY/070615/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TGV_20070615_055511-20070613_170200.png

../../RESULTS/DAILY/070615/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TPV_20070615_055511-20070613_170200.png

../../RESULTS/DAILY/070615/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RGV_20070615_055511-20070613_170200.png

../../RESULTS/DAILY/070615/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RPV_20070615_055511-20070613_170200.png

MODULE_STEPPING ANALYSIS completed

#####

CALIBRATION PULSES ANALYSIS

#####

Creating directory ./RESULTS/DAILY/070615/CALIBRATION_PULSES...

ALL ROWS Analysis will be performed from 2007-06-15 00:00:00 to 2007-06-15 23:59:59

Analysing products WVS IS2 V/V

Writing image ../../RESULTS/DAILY/070615//CALIBRATION_PULSES/Calibration_pulses_all_rows_WVS_IS2_VV.png...

Analysing products GM1 SS3 H/H

Writing image ../../RESULTS/DAILY/070615//CALIBRATION_PULSES/Calibration_pulses_all_rows_GM1_SS3_HH.png...

TEMPORAL EVOLUTION Analysis will be performed from 2007-06-15 00:00:00 to 2007-06-15 23:59:59

Analysing products WVS IS2 V/V

Getting calibration pulses data for WVS IS2 V/V from 2007-06-15 00:00:00 to 2007-06-15 23:59:59. Rows: 1/5/9/13/17/21/25/29

Writing file ./RESULTS/DAILY/070615/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2007-06-15_1.dat...

Writing ../../RESULTS/DAILY/070615//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_1.png...

Writing ../../RESULTS/DAILY/070615//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_1.png...

Getting calibration pulses data for WVS IS2 V/V from 2007-06-15 00:00:00 to 2007-06-15 23:59:59. Rows: 2/6/10/14/18/22/26/30

Writing file ./RESULTS/DAILY/070615/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2007-06-15_2.dat...

Writing ../../RESULTS/DAILY/070615//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_2.png...

Writing ../../RESULTS/DAILY/070615//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_2.png...

Getting calibration pulses data for WVS IS2 V/V from 2007-06-15 00:00:00 to 2007-06-15 23:59:59. Rows: 3/7/11/15/19/23/27/31

Writing file ./RESULTS/DAILY/070615/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2007-06-15_3.dat...

Writing ../../RESULTS/DAILY/070615//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_3.png...

Writing ../../RESULTS/DAILY/070615//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_3.png...

Getting calibration pulses data for WVS IS2 V/V from 2007-06-15 00:00:00 to 2007-06-15 23:59:59. Rows: 4/8/12/16/20/24/28/32

Writing file ./RESULTS/DAILY/070615/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2007-06-15_4.dat...

Writing ../../RESULTS/DAILY/070615//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_4.png...

Writing ../../RESULTS/DAILY/070615//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_4.png...

Analysing products GM1 SS3 H/H

Getting calibration pulses data for GM1 SS3 H/H from 2007-06-15 00:00:00 to 2007-06-15 23:59:59. Rows: 1/5/9/13/17/21/25/29

Writing file ./RESULTS/DAILY/070615/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2007-06-15_1.dat...

Writing ../../RESULTS/DAILY/070615//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_1.png...

Writing ../../RESULTS/DAILY/070615//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_1.png...

Getting calibration pulses data for GM1 SS3 H/H from 2007-06-15 00:00:00 to 2007-06-15 23:59:59. Rows: 2/6/10/14/18/22/26/30

Writing file ./RESULTS/DAILY/070615/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2007-06-15_2.dat...

Writing ../../RESULTS/DAILY/070615//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_2.png...

Writing ../../RESULTS/DAILY/070615//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_2.png...

Getting calibration pulses data for GM1 SS3 H/H from 2007-06-15 00:00:00 to 2007-06-15 23:59:59. Rows: 3/7/11/15/19/23/27/31

Writing file ./RESULTS/DAILY/070615/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2007-06-15_3.dat...

Writing ../../RESULTS/DAILY/070615//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_3.png...

Writing ../../RESULTS/DAILY/070615//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_3.png...

Getting calibration pulses data for GM1 SS3 H/H from 2007-06-15 00:00:00 to 2007-06-15 23:59:59. Rows: 4/8/12/16/20/24/28/32

Writing file ./RESULTS/DAILY/070615/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2007-06-15_4.dat...



Writing ../../RESULTS/DAILY/070615//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_4.png...
 Writing ../../RESULTS/DAILY/070615//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_4.png...

CALIBRATION PULSES ANALYSIS completed
 #####

DOPPLER ANALYSIS
 #####
 Creating directory ./RESULTS/DAILY/070615/DOPPLER...

 DOPPLER ANX Analysis will be performed from 2007-06-15 00:00:00 to 2007-06-15 23:59:59

Analysing products WVS IS2 V/V
 Getting doppler data for WVS IS2 V/V from 2007-06-15 00:00:00 to 2007-06-15 23:59:59...
 Writing file ./RESULTS/DAILY/070615/DOPPLER/Doppler_data_WVS_IS2_VV_2007-06-15.dat...
 Running IDL program...
 Writing file ../../RESULTS/DAILY/070615/DOPPLER/DOPPLER_ANX_WVS_IS2_VV.png...

Analysing products GM1 SS1 H/H
 Getting doppler data for GM1 SS1 H/H from 2007-06-15 00:00:00 to 2007-06-15 23:59:59...
 Writing file ./RESULTS/DAILY/070615/DOPPLER/Doppler_data_GM1_SS1_HH_2007-06-15.dat...
 Running IDL program...
 Writing file ../../RESULTS/DAILY/070615/DOPPLER/DOPPLER_ANX_GM1_SS1_HH.png...

 DOPPLER JUMPS Analysis will be performed on WSM products from 2007-06-15 00:00:00 to 2007-06-15 23:59:59

Analysing by default products WSM
 Getting doppler jumps data for WSM from 2007-06-15 00:00:00 to 2007-06-15 23:59:59...
 Writing file ./RESULTS/DAILY/070615/DOPPLER/Doppler_Jumps_data_WSM_2007-06-15.dat...
 Running IDL program...
 Writing file ../../RESULTS/DAILY/070615/DOPPLER/DOPPLER_JUMPS_ANX_WSM.png...
 Writing file ../../RESULTS/DAILY/070615/DOPPLER/DOPPLER_JUMPS_Date_WSM.png...

 DOPPLER MAP Analysis will be performed from 2007-06-15 00:00:00 to 2007-06-15 23:59:59

Analysing products WVS IS2 V/V
 Loading predicted doppler values....
 Phase: descending
 Found data...
 Computing mean error doppler estimated-predicted...
 Mean error = -17.424127 Hz
 Writing file ../../RESULTS/DAILY/070615//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_WVS_IS2_VV_desc.jpg...
 Writing file ../../RESULTS/DAILY/070615//DOPPLER/DOPPLER_Absolute_WVS_IS2_VV_desc.jpg...

 Loading predicted doppler values....
 Phase: ascending
 Found data...
 Computing mean error doppler estimated-predicted...
 Mean error = -7.9262425 Hz
 Writing file ../../RESULTS/DAILY/070615//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_WVS_IS2_VV_asc.jpg...
 Writing file ../../RESULTS/DAILY/070615//DOPPLER/DOPPLER_Absolute_WVS_IS2_VV_asc.jpg...

Analysing products GM1 SS1 H/H
Loading predicted doppler values....
Phase: descending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -6.6294436 Hz
Writing file ../../RESULTS/DAILY/070615//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_GM1_SS1_HH_desc.jpg...
Writing file ../../RESULTS/DAILY/070615//DOPPLER/DOPPLER_Absolute_GM1_SS1_HH_desc.jpg...

Loading predicted doppler values....
Phase: ascending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -16.759775 Hz
Writing file ../../RESULTS/DAILY/070615//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_GM1_SS1_HH_asc.jpg...
Writing file ../../RESULTS/DAILY/070615//DOPPLER/DOPPLER_Absolute_GM1_SS1_HH_asc.jpg...

DOPPLER ANALYSIS completed
#####

CHIRP ANALYSIS

Creating directory ./RESULTS/DAILY/070615/CHIRP...

CHIRP Analysis will be performed from 2007-06-15 00:00:00 to 2007-06-15 23:59:59

Analysing products WSM SS1

Getting ScaleFactor data for WSM SS1 from 2007-06-15 00:00:00 to 2007-06-15 23:59:59...
Writing file ./RESULTS/DAILY/070615/CHIRP/ScaleFactor_data_WSM_SS1__2007-06-15.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/070615/CHIRP/ScaleFactor_ANX_WSM_SS1_.png...
Writing file ../../RESULTS/DAILY/070615/CHIRP/ScaleFactor_DATE_WSM_SS1_.png...

CHIRP ANALYSIS completed
#####

RAW DATA ANALYSIS

Analysis will be performed from 2007-06-15 00:00:00 to 2007-06-15 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/070615/RAW_DATA

Creating directory ./RESULTS/DAILY/070615/RAW_DATA...

Getting raw data for WVS from 2007-06-15 00:00:00 to 2007-06-15 23:59:59...
Writing file ./RESULTS/DAILY/070615/RAW_DATA/Raw_data_WVS_2007-06-15.dat...
Running IDL program to create graphs...

Creating image ../../RESULTS/DAILY/070615/RAW_DATA/Raw_data_WVS_input_mean.png...
Creating image ../../RESULTS/DAILY/070615/RAW_DATA/Raw_data_WVS_input_stdev.png...
Creating image ../../RESULTS/DAILY/070615/RAW_DATA/Raw_data_WVS_gain_imbalance.png...

```
*****
Getting raw data for IMM from 2007-06-15 00:00:00 to 2007-06-15 23:59:59...
Writing file ./RESULTS/DAILY/070615/RAW_DATA/Raw_data_IMM_2007-06-15.dat...
Running IDL program to create graphs...
```

```
Creating image ../../RESULTS/DAILY/070615/RAW_DATA/Raw_data_IMM_input_mean.png...
Creating image ../../RESULTS/DAILY/070615/RAW_DATA/Raw_data_IMM_input_stdev.png...
Creating image ../../RESULTS/DAILY/070615/RAW_DATA/Raw_data_IMM_gain_imbalance.png...
```

```
RAW DATA ANALYSIS completed
#####
```

```
TELEMETRY ANALYSIS
#####
Analysis will be performed from 2007-06-15 00:00:00 to 2007-06-15 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/070615/TELEMETRY
```

```
Creating directory ./RESULTS/DAILY/070615/TELEMETRY...
```

```
Looking for gaps and missing lines in WVS products...
*****
Checking 24 products from PDE...
Checking 29 products from PDK...
```

```
Looking for gaps and missing lines in GM1 products...
*****
Checking 27 products from PDE...
Checking 51 products from PDK...
Found product...ASA_GM1_1PNPDK20070615_182803_000001142059_00056_27665_0966.N1 / 0 gaps / 37 missing lines
```

```
Looking for gaps and missing lines in APM products...
*****
Checking 4 products from PDE...
Checking 1 products from PDK...
```

```
Looking for gaps and missing lines in IMM products...
*****
Checking 18 products from PDE...
Checking 4 products from PDK...
```

```
Looking for gaps and missing lines in WSM products...
*****
Checking 37 products from PDE...
Found product...ASA_WSM_1PNPDE20070615_145357_000001042059_00054_27663_9925.N1 / 0 gaps / 55 missing lines
Found product...ASA_WSM_1PNPDE20070615_181714_000001842059_00056_27665_9998.N1 / 0 gaps / 29 missing lines
Checking 17 products from PDK...
```

```
Creating graph of missing lines and gaps...
*****
Creating image: ./RESULTS/DAILY/070615/TELEMETRY/TELEMETRY_Missing_lines.png...
Creating image: ./RESULTS/DAILY/070615/TELEMETRY/TELEMETRY_Gaps.png...
```

```
TELEMETRY ANALYSIS completed
#####
```

```
BROWSE PRODUCTS ANALYSIS
#####
Analysis will be performed on 2007-06-15
```

```
*****
```



Scanning directory /nas3/ENVISAT/ASAR//ASA_GM_BP...
 Results will be exported to the directory: /nas3/ENVISAT/ASAR//ASA_GM_BP/JPG/20070615/

ANALYSIS COMPLETED: 0 GM browse products to see...

Scanning directory /nas3/ENVISAT/ASAR//ASA_AP_BP...
 Results will be exported to the directory: /nas3/ENVISAT/ASAR//ASA_AP_BP/JPG/20070615/

Stripping browse product /nas3/ENVISAT/ASAR//ASA_AP_BP/ASA_AP_BPZPDE20070615_072110_000001602059_00049_27658_9682.N1 ...
 Stripping browse product /nas3/ENVISAT/ASAR//ASA_AP_BP/ASA_AP_BPZPDE20070615_084814_000000422059_00050_27659_9689.N1 ...
 Stripping browse product /nas3/ENVISAT/ASAR//ASA_AP_BP/ASA_AP_BPZPDE20070615_134541_000000722059_00053_27662_9920.N1 ...
 Stripping browse product /nas3/ENVISAT/ASAR//ASA_AP_BP/ASA_AP_BPZPDE20070615_163954_000000402059_00055_27664_9922.N1 ...

ANALYSIS COMPLETED: 4 AP browse products to see...

Scanning directory /nas3/ENVISAT/ASAR//ASA_IM_BP...
 Results will be exported to the directory: /nas3/ENVISAT/ASAR//ASA_IM_BP/JPG/20070615/

Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20070615_084957_000000502059_00050_27659_9691.N1 ...
 Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20070615_120924_000000362059_00052_27661_9804.N1 ...
 Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20070615_140617_000000352059_00053_27662_9900.N1 ...
 Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20070615_141117_000000342059_00053_27662_9898.N1 ...
 Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20070615_154121_000000822059_00054_27663_9932.N1 ...
 Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20070615_170102_000000352059_00055_27664_9954.N1 ...
 Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20070615_200135_000000352059_00057_27666_0012.N1 ...
 Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20070615_214520_000000362059_00058_27667_0113.N1 ...
 Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20070615_220912_000000362059_00058_27667_0253.N1 ...
 Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20070615_234822_000001102059_00059_27668_0408.N1 ...
 Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDK20070615_201134_000000362059_00057_27666_0932.N1 ...
 Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDK20070615_201554_000001052059_00057_27666_1051.N1 ...
 Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDK20070615_201656_000000432059_00057_27666_0944.N1 ...

ANALYSIS COMPLETED: 13 IM browse products to see...

Scanning directory /nas3/ENVISAT/ASAR//ASA_WS_BP...
 Results will be exported to the directory: /nas3/ENVISAT/ASAR//ASA_WS_BP/JPG/20070615/

ANALYSIS COMPLETED: 0 WS browse products to see...

BROWSE PRODUCTS ANALYSIS completed
 #####

HTML REPORT generation
 #####

Building file ./RESULTS/DAILY/070615/asarReport.html...
 Building DATA SUMMARY section...
 Building AUXILIARY FILES ANALYSIS section...
 Building MODULE STEPPING ANALYSIS section...
 Building CALIBRATION PULSES ANALYSIS section...
 Building DOPPLER ANALYSIS section...
 Building CHIRP ANALYSIS section...
 Building RAW DATA ANALYSIS section...
 Building TELEMETRY ANALYSIS section...

HTML REPORT generation completed

#####





ASAR Daily Report



Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
ASA_APM_1PNPDE20070615_072110_000001602059_00049_27658_9681.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20070615_084814_000000422059_00050_27659_9688.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20070615_134541_000000722059_00053_27662_9919.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20070615_163954_000000402059_00055_27664_9921.N1	OK	OK	OK	OK
ASA_APM_1PNPDK20070615_084435_000000422059_00050_27659_0116.N1	OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_GM1_1PNPDE20070615_000318_000009912059_00045_27654_9173.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070615_003948_000003562059_00045_27654_9077.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070615_011954_000003982059_00045_27654_9200.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070615_014050_000000902059_00046_27655_9202.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070615_014540_000011832059_00046_27655_9240.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070615_020746_000001812059_00046_27655_9237.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070615_023407_000001082059_00046_27655_9348.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070615_024817_000001082059_00046_27655_9346.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070615_025526_000001142059_00046_27655_9342.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070615_025730_000004532059_00046_27655_9369.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070615_030634_000002172059_00046_27655_9358.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070615_031416_000004042059_00047_27656_9371.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070615_032642_000000662059_00047_27656_9356.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070615_032841_000010442059_00047_27656_9449.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070615_034752_000002472059_00047_27656_9382.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070615_045218_000002592059_00048_27657_9503.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070615_045820_000002892059_00048_27657_9498.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070615_050434_000016362059_00048_27657_9591.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070615_201755_000002172059_00057_27666_0029.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070615_202447_000001202059_00057_27666_0031.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070615_210631_000006042059_00057_27666_0041.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070615_212806_000010332059_00057_27666_0270.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070615_214331_000001082059_00057_27666_0167.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070615_224118_000002772059_00058_27667_0163.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070615_225328_000002232059_00058_27667_0177.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070615_231726_000000842059_00059_27668_0302.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070615_233725_000006582059_00059_27668_0307.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_055952_000003502059_00048_27657_0144.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_060729_000002232059_00048_27657_0142.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_064544_000000842059_00049_27658_0183.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_065057_000003922059_00049_27658_0187.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_065648_000005012059_00049_27658_0191.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_070648_000004532059_00049_27658_0181.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_071636_000002712059_00049_27658_0179.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_072418_000002592059_00049_27658_0174.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_074505_000004042059_00049_27658_0185.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_082520_000008632059_00050_27659_0274.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_083901_000001692059_00050_27659_0300.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_084543_000001502059_00050_27659_0283.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_085105_000005862059_00050_27659_0302.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_091631_000002412059_00050_27659_0281.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_093041_000001082059_00050_27659_0279.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_100644_000003982059_00051_27660_0458.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_102715_000000722059_00051_27660_0454.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_103030_000004592059_00051_27660_0456.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_105706_000001082059_00051_27660_0452.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_110517_000000782059_00051_27660_0447.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_114645_000003742059_00052_27661_0491.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_115200_000000602059_00052_27661_0474.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_122133_000003682059_00052_27661_0478.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_124752_000003442059_00052_27661_0476.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_125942_000003982059_00052_27661_0469.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_132031_000001502059_00053_27662_0539.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_132429_000006462059_00053_27662_0559.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_133434_000005312059_00053_27662_0557.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_135831_000002412059_00053_27662_0553.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_140418_000001202059_00053_27662_0555.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_140710_000002472059_00053_27662_0549.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_141818_000009242059_00053_27662_0551.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_144130_000002292059_00053_27662_0547.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_145551_000003202059_00054_27663_0680.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_150354_000003922059_00054_27663_0687.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_152137_000007732059_00054_27663_0692.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_153731_000000842059_00054_27663_0685.N1					OK	OK	OK	OK

ASA_GM1_1PNPDK20070615_155854_000009242059_00054_27663_0689.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_163620_000002112059_00055_27664_0812.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_164102_000002952059_00055_27664_0810.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_164842_000001262059_00055_27664_0808.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_170536_000006102059_00055_27664_0806.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_174119_000003862059_00055_27664_0831.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_175132_000002352059_00055_27664_0833.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_182035_000004162059_00056_27665_0951.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_182803_000001142059_00056_27665_0966.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_182847_000001572059_00056_27665_0968.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_184512_000001382059_00056_27665_0961.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_192355_000007252059_00056_27665_0970.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_194817_000007972059_00056_27665_0959.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20070615_200257_000002412059_00057_27666_1048.N1	OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_IMM_1PNPDE20070615_020549_000001012059_00046_27655_9299.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20070615_030502_000000742059_00046_27655_9441.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20070615_032747_000000352059_00047_27656_9344.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20070615_045641_000000812059_00048_27657_9494.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20070615_050311_000000642059_00048_27657_9496.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20070615_054402_000000292059_00048_27657_9529.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20070615_070510_000000812059_00049_27658_9640.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20070615_071422_000001162059_00049_27658_9648.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20070615_084957_000000502059_00050_27659_9690.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20070615_120924_000000362059_00052_27661_9803.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20070615_140617_000000352059_00053_27662_9899.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20070615_141117_000000342059_00053_27662_9897.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20070615_154121_000000822059_00054_27663_9931.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20070615_170102_000000352059_00055_27664_9953.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20070615_200135_000000352059_00057_27666_0011.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20070615_214520_000000362059_00058_27667_0112.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20070615_220912_000000362059_00058_27667_0252.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20070615_234822_000001102059_00059_27668_0407.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20070615_082352_000000532059_00050_27659_0114.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20070615_201134_000000362059_00057_27666_0931.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20070615_201554_000001052059_00057_27666_1050.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20070615_201656_000000432059_00057_27666_0943.N1					OK	OK	OK	OK


Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WSM_1PNPDE20070615_005330_000005992059_00045_27654_9312.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070615_010407_000003242059_00045_27654_9230.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070615_014233_000001762059_00046_27655_9310.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070615_023606_000004832059_00046_27655_9468.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070615_024443_000001832059_00046_27655_9314.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070615_032108_000003242059_00047_27656_9484.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070615_034618_000000852059_00047_27656_9451.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070615_041442_000003852059_00047_27656_9617.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070615_042139_000005452059_00047_27656_9642.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070615_055718_000001412059_00048_27657_9634.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070615_073409_000002022059_00049_27658_9683.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070615_092045_000005862059_00050_27659_9854.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070615_092152_000001152059_00050_27659_9811.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070615_092450_000003412059_00050_27659_9812.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070615_105906_000003612059_00051_27660_9801.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070615_110643_000004582059_00051_27660_9860.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070615_111713_000001462059_00051_27660_9831.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070615_123557_000001402059_00052_27661_9856.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070615_140245_000000852059_00053_27662_9923.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070615_145357_000001042059_00054_27663_9925.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070615_150119_000001472059_00054_27663_9929.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070615_164609_000001402059_00055_27664_9945.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070615_165809_000001282059_00055_27664_9943.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070615_170202_000002022059_00055_27664_9985.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070615_173746_000002012059_00055_27664_9995.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070615_174754_000000862059_00055_27664_9967.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070615_174958_000000852059_00055_27664_9983.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070615_181714_000001842059_00056_27665_9998.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070615_183829_000001462059_00056_27665_9993.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070615_184121_000002192059_00056_27665_0025.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070615_191822_000003232059_00056_27665_0027.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070615_202144_000001712059_00057_27666_0133.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070615_205857_000004472059_00057_27666_0250.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070615_212332_000002632059_00057_27666_0248.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070615_215737_000002082059_00058_27667_0393.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070615_220144_000002262059_00058_27667_0295.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070615_224606_000004282059_00058_27667_0297.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20070615_060555_000000852059_00048_27657_0108.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20070615_064250_000001652059_00049_27658_0110.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20070615_064722_000002012059_00049_27658_0112.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20070615_101334_000003852059_00051_27660_0441.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20070615_115310_000004832059_00052_27661_0443.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20070615_123841_000005392059_00052_27661_0537.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20070615_132315_000000612059_00053_27662_0445.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20070615_151037_000004842059_00054_27663_0668.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20070615_151901_000001462059_00054_27663_0663.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20070615_165058_000004702059_00055_27664_0789.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20070615_183134_000004582059_00056_27665_0923.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20070615_200706_000002022059_00057_27666_1052.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20070615_201311_000001642059_00057_27666_1059.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20070615_214707_000001222059_00058_27667_1097.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20070615_214933_000000912059_00058_27667_1099.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20070615_215144_000003972059_00058_27667_1101.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20070615_233205_000003062059_00059_27668_1113.N1					OK	OK	OK	OK


Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WVS_1PNPDE20070615_001952_000011472059_00045_27654_9150.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20070615_004548_000004052059_00045_27654_9083.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20070615_010931_000003302059_00045_27654_9080.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20070615_011401_000002992059_00045_27654_9198.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20070615_012652_000007942059_00046_27655_9213.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20070615_021106_000008692059_00046_27655_9243.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20070615_022521_000004802059_00046_27655_9351.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20070615_025005_000002702059_00046_27655_9361.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20070615_031011_000001942059_00047_27656_9354.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20070615_035159_000009592059_00047_27656_9385.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20070615_040728_000001352059_00047_27656_9501.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20070615_043042_000012442059_00047_27656_9515.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20070615_053154_000006892059_00048_27657_9512.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20070615_054438_000001942059_00048_27657_9523.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20070615_202647_000018742059_00057_27666_0044.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20070615_211640_000003002059_00057_27666_0039.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20070615_212041_000001202059_00057_27666_0158.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20070615_220557_000001502059_00058_27667_0161.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20070615_220955_000018292059_00058_27667_0170.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20070615_225716_000002552059_00058_27667_0180.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20070615_230046_000009442059_00058_27667_0300.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20070615_231851_000007492059_00059_27668_0305.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20070615_235018_000010042059_00059_27668_0312.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070615_054738_000001342059_00048_27657_0140.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070615_055226_000001202059_00048_27657_0137.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070615_061117_000017542059_00048_27657_0147.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070615_072839_000002852059_00049_27658_0177.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070615_075153_000018742059_00049_27658_0217.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070615_090054_000008842059_00050_27659_0277.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070615_093229_000020092059_00050_27659_0313.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070615_103812_000010792059_00051_27660_0450.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070615_111423_000001202059_00051_27660_0486.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070615_111936_000015742059_00051_27660_0489.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070615_120254_000003452059_00052_27661_0467.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070615_121006_000006442059_00052_27661_0472.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070615_122745_000004502059_00052_27661_0508.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070615_125341_000003152059_00052_27661_0505.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070615_130623_000005692059_00052_27661_0511.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070615_131655_000001642059_00053_27662_0545.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070615_134700_000006442059_00053_27662_0542.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070615_141304_000002702059_00053_27662_0585.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070615_143417_000003902059_00053_27662_0573.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070615_144520_000004642059_00053_27662_0582.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070615_153432_000001342059_00054_27663_0683.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070615_153858_000001042059_00054_27663_0721.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070615_154251_000009142059_00054_27663_0730.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070615_161453_000012442059_00054_27663_0733.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070615_171546_000012742059_00055_27664_0836.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070615_175529_000012592059_00055_27664_0899.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070615_185007_000016492059_00056_27665_0964.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070615_193605_00000902059_00056_27665_0957.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070615_194108_000003742059_00056_27665_0954.N1					OK	OK	OK	OK


Calibration pulses for GM1 SS3 H/H




Calibration pulses for GM1 SS3 H/H




Calibration pulses for GM1 SS3 H/H




Calibration pulses for GM1 SS3 H/H




Calibration pulses for WVS IS2 V/V




Calibration pulses for WVS IS2 V/V





Calibration pulses for WVS IS2 V/V





Calibration pulses for WVS IS2 V/V

















15-Jun
rows: _ 1 _ 5 _ 9 _ 13 _ 17 _ 21 _ 25 _ 29











15-Jun
rows: _ 3 _ 7 _ 11 _ 15 _ 19 _ 23 _ 27 _ 31

















Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_APM_1PNPDE20070615_072110_000001602059_00049_27658_9681.N1						IS3	H/V	59	27658	49	4.04
ASA_APM_1PNPDK20070615_084435_000000422059_00050_27659_0116.N1						IS4	H/H	59	27659	50	4.04
ASA_APM_1PNPDE20070615_084814_000000422059_00050_27659_9688.N1						IS2	V/H	59	27659	50	4.04
ASA_APM_1PNPDE20070615_134541_000000722059_00053_27662_9919.N1						IS7	H/H	59	27662	53	4.04
ASA_APM_1PNPDE20070615_163954_000000402059_00055_27664_9921.N1						IS1	H/H	59	27664	55	4.04

Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_GM1_1PNPDE20070615_000318_000009912059_00045_27654_9173.N1						SS1	H/H	59	27654	45	4.04
ASA_GM1_1PNPDE20070615_003948_000003562059_00045_27654_9077.N1						SS1	H/H	59	27654	45	4.04
ASA_GM1_1PNPDE20070615_011954_000003982059_00045_27654_9200.N1						SS1	H/H	59	27654	45	4.04
ASA_GM1_1PNPDE20070615_014050_000000902059_00046_27655_9202.N1						SS1	H/H	59	27655	46	4.04
ASA_GM1_1PNPDE20070615_014540_000011832059_00046_27655_9240.N1						SS1	H/H	59	27655	46	4.04
ASA_GM1_1PNPDE20070615_020746_000001812059_00046_27655_9237.N1						SS1	H/H	59	27655	46	4.04
ASA_GM1_1PNPDE20070615_023407_000001082059_00046_27655_9348.N1						SS1	H/H	59	27655	46	4.04
ASA_GM1_1PNPDE20070615_024817_000001082059_00046_27655_9346.N1						SS1	H/H	59	27655	46	4.04
ASA_GM1_1PNPDE20070615_025526_000001142059_00046_27655_9342.N1						SS1	H/H	59	27655	46	4.04
ASA_GM1_1PNPDE20070615_025730_000004532059_00046_27655_9369.N1						SS1	H/H	59	27655	46	4.04
ASA_GM1_1PNPDE20070615_030634_000002172059_00046_27655_9358.N1						SS1	H/H	59	27655	46	4.04
ASA_GM1_1PNPDE20070615_031416_000004042059_00047_27656_9371.N1						SS1	H/H	59	27656	47	4.04
ASA_GM1_1PNPDE20070615_032642_000000662059_00047_27656_9356.N1						SS1	H/H	59	27656	47	4.04
ASA_GM1_1PNPDE20070615_032841_000010442059_00047_27656_9449.N1						SS1	H/H	59	27656	47	4.04
ASA_GM1_1PNPDE20070615_034752_000002472059_00047_27656_9382.N1						SS1	H/H	59	27656	47	4.04
ASA_GM1_1PNPDE20070615_045218_000002592059_00048_27657_9503.N1						SS1	H/H	59	27657	48	4.04
ASA_GM1_1PNPDE20070615_045820_000002892059_00048_27657_9498.N1						SS1	H/H	59	27657	48	4.04
ASA_GM1_1PNPDE20070615_050434_000016362059_00048_27657_9591.N1						SS1	H/H	59	27657	48	4.04
ASA_GM1_1PNPDK20070615_055952_000003502059_00048_27657_0144.N1						SS1	H/H	59	27657	48	4.04
ASA_GM1_1PNPDK20070615_060729_000002232059_00048_27657_0142.N1						SS1	H/H	59	27657	48	4.04
ASA_GM1_1PNPDK20070615_064544_000000842059_00049_27658_0183.N1						SS1	H/H	59	27658	49	4.04
ASA_GM1_1PNPDK20070615_065057_000003922059_00049_27658_0187.N1						SS1	H/H	59	27658	49	4.04
ASA_GM1_1PNPDK20070615_065648_000005012059_00049_27658_0191.N1						SS1	H/H	59	27658	49	4.04
ASA_GM1_1PNPDK20070615_070648_000004532059_00049_27658_0181.N1						SS1	H/H	59	27658	49	4.04
ASA_GM1_1PNPDK20070615_071636_000002712059_00049_27658_0179.N1						SS1	H/H	59	27658	49	4.04
ASA_GM1_1PNPDK20070615_072418_000002592059_00049_27658_0174.N1						SS1	H/H	59	27658	49	4.04
ASA_GM1_1PNPDK20070615_074505_000004042059_00049_27658_0185.N1						SS1	H/H	59	27658	49	4.04
ASA_GM1_1PNPDK20070615_082520_000008632059_00050_27659_0274.N1						SS1	H/H	59	27659	50	4.04
ASA_GM1_1PNPDK20070615_083901_000001692059_00050_27659_0300.N1						SS1	H/H	59	27659	50	4.04
ASA_GM1_1PNPDK20070615_084543_000001502059_00050_27659_0283.N1						SS1	H/H	59	27659	50	4.04
ASA_GM1_1PNPDK20070615_085105_000005862059_00050_27659_0302.N1						SS1	H/H	59	27659	50	4.04
ASA_GM1_1PNPDK20070615_091631_000002412059_00050_27659_0281.N1						SS1	H/H	59	27659	50	4.04
ASA_GM1_1PNPDK20070615_093041_000001082059_00050_27659_0279.N1						SS1	H/H	59	27659	50	4.04
ASA_GM1_1PNPDK20070615_100644_000003982059_00051_27660_0458.N1						SS1	H/H	59	27660	51	4.04
ASA_GM1_1PNPDK20070615_102715_000000722059_00051_27660_0454.N1						SS1	H/H	59	27660	51	4.04
ASA_GM1_1PNPDK20070615_103030_000004592059_00051_27660_0456.N1						SS1	H/H	59	27660	51	4.04
ASA_GM1_1PNPDK20070615_105706_000001082059_00051_27660_0452.N1						SS1	H/H	59	27660	51	4.04
ASA_GM1_1PNPDK20070615_110517_000000782059_00051_27660_0447.N1						SS1	H/H	59	27660	51	4.04
ASA_GM1_1PNPDK20070615_114645_000003742059_00052_27661_0491.N1						SS1	H/H	59	27661	52	4.04
ASA_GM1_1PNPDK20070615_115200_000000602059_00052_27661_0474.N1						SS1	H/H	59	27661	52	4.04
ASA_GM1_1PNPDK20070615_122133_000003682059_00052_27661_0478.N1						SS1	H/H	59	27661	52	4.04
ASA_GM1_1PNPDK20070615_124752_000003442059_00052_27661_0476.N1						SS1	H/H	59	27661	52	4.04
ASA_GM1_1PNPDK20070615_125942_000003982059_00052_27661_0469.N1						SS1	H/H	59	27661	52	4.04
ASA_GM1_1PNPDK20070615_132031_000001502059_00053_27662_0539.N1						SS1	H/H	59	27662	53	4.04
ASA_GM1_1PNPDK20070615_132429_000006462059_00053_27662_0559.N1						SS1	H/H	59	27662	53	4.04
ASA_GM1_1PNPDK20070615_133434_000005312059_00053_27662_0557.N1						SS1	H/H	59	27662	53	4.04
ASA_GM1_1PNPDK20070615_135831_000002412059_00053_27662_0553.N1						SS1	H/H	59	27662	53	4.04
ASA_GM1_1PNPDK20070615_140418_000001202059_00053_27662_0555.N1						SS1	H/H	59	27662	53	4.04
ASA_GM1_1PNPDK20070615_140710_000002472059_00053_27662_0549.N1						SS1	H/H	59	27662	53	4.04
ASA_GM1_1PNPDK20070615_141818_000009242059_00053_27662_0551.N1						SS1	H/H	59	27662	53	4.04
ASA_GM1_1PNPDK20070615_144130_000002292059_00053_27662_0547.N1						SS1	H/H	59	27662	53	4.04
ASA_GM1_1PNPDK20070615_145551_000003202059_00054_27663_0680.N1						SS1	H/H	59	27663	54	4.04
ASA_GM1_1PNPDK20070615_150354_000003922059_00054_27663_0687.N1						SS1	H/H	59	27663	54	4.04
ASA_GM1_1PNPDK20070615_152137_000007732059_00054_27663_0692.N1						SS1	H/H	59	27663	54	4.04
ASA_GM1_1PNPDK20070615_153731_000000842059_00054_27663_0685.N1						SS1	H/H	59	27663	54	4.04
ASA_GM1_1PNPDK20070615_155854_000009242059_00054_27663_0689.N1						SS1	H/H	59	27663	54	4.04
ASA_GM1_1PNPDK20070615_163620_000002112059_00055_27664_0812.N1						SS1	H/H	59	27664	55	4.04
ASA_GM1_1PNPDK20070615_164102_000002952059_00055_27664_0810.N1						SS1	H/H	59	27664	55	4.04
ASA_GM1_1PNPDK20070615_164842_000001262059_00055_27664_0808.N1						SS1	H/H	59	27664	55	4.04
ASA_GM1_1PNPDK20070615_170536_000006102059_00055_27664_0806.N1						SS1	H/H	59	27664	55	4.04
ASA_GM1_1PNPDK20070615_174119_000003862059_00055_27664_0831.N1						SS1	H/H	59	27664	55	4.04
ASA_GM1_1PNPDK20070615_175132_000002352059_00055_27664_0833.N1						SS1	H/H	59	27664	55	4.04
ASA_GM1_1PNPDK20070615_182035_000004162059_00056_27665_0951.N1						SS1	H/H	59	27665	56	4.04
ASA_GM1_1PNPDK20070615_182803_000001142059_00056_27665_0966.N1						SS1	H/H	59	27665	56	4.04
ASA_GM1_1PNPDK20070615_182847_000001572059_00056_27665_0968.N1						SS1	H/H	59	27665	56	4.04
ASA_GM1_1PNPDK20070615_184512_000001382059_00056_27665_0961.N1						SS1	H/H	59	27665	56	4.04
ASA_GM1_1PNPDK20070615_192355_000007252059_00056_27665_0970.N1						SS1	H/H	59	27665	56	4.04

ASA_GM1_1PNPDK20070615_194817_000007972059_00056_27665_0959.N1	SS1	H/H	59	27665	56	4.04
ASA_GM1_1PNPDK20070615_200257_000002412059_00057_27666_1048.N1	SS1	H/H	59	27666	57	4.04
ASA_GM1_1PNPDE20070615_201755_000002172059_00057_27666_0029.N1	SS1	H/H	59	27666	57	4.04
ASA_GM1_1PNPDE20070615_202447_000001202059_00057_27666_0031.N1	SS1	H/H	59	27666	57	4.04
ASA_GM1_1PNPDE20070615_210631_000006042059_00057_27666_0041.N1	SS1	H/H	59	27666	57	4.04
ASA_GM1_1PNPDE20070615_212806_000010332059_00057_27666_0270.N1	SS1	H/H	59	27666	57	4.04
ASA_GM1_1PNPDE20070615_214331_000001082059_00057_27666_0167.N1	SS1	H/H	59	27666	57	4.04
ASA_GM1_1PNPDE20070615_224118_000002772059_00058_27667_0163.N1	SS1	H/H	59	27667	58	4.04
ASA_GM1_1PNPDE20070615_225328_000002232059_00058_27667_0177.N1	SS1	H/H	59	27667	58	4.04
ASA_GM1_1PNPDE20070615_231726_000000842059_00059_27668_0302.N1	SS1	H/H	59	27668	59	4.04
ASA_GM1_1PNPDE20070615_233725_000006582059_00059_27668_0307.N1	SS1	H/H	59	27668	59	4.04


Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_IMM_1PNPDE20070615_020549_000001012059_00046_27655_9299.N1						IS3	V/V	59	27655	46	4.04
ASA_IMM_1PNPDE20070615_030502_000000742059_00046_27655_9441.N1						IS6	H/H	59	27655	46	4.04
ASA_IMM_1PNPDE20070615_032747_000000352059_00047_27656_9344.N1						IS5	V/V	59	27656	47	4.04
ASA_IMM_1PNPDE20070615_045641_000000812059_00048_27657_9494.N1						IS2	V/V	59	27657	48	4.04
ASA_IMM_1PNPDE20070615_050311_000000642059_00048_27657_9496.N1						IS4	V/V	59	27657	48	4.04
ASA_IMM_1PNPDE20070615_054402_000000292059_00048_27657_9529.N1						IS5	V/V	59	27657	48	4.04
ASA_IMM_1PNPDE20070615_070510_000000812059_00049_27658_9640.N1						IS2	V/V	59	27658	49	4.04
ASA_IMM_1PNPDE20070615_071422_000001162059_00049_27658_9648.N1						IS2	V/V	59	27658	49	4.04
ASA_IMM_1PNPDK20070615_082352_000000532059_00050_27659_0114.N1						IS2	V/V	59	27659	50	4.04
ASA_IMM_1PNPDE20070615_084957_000000502059_00050_27659_9690.N1						IS7	H/H	59	27659	50	4.04
ASA_IMM_1PNPDE20070615_120924_000000362059_00052_27661_9803.N1						IS2	V/V	59	27661	52	4.04
ASA_IMM_1PNPDE20070615_140617_000000352059_00053_27662_9899.N1						IS7	H/H	59	27662	53	4.04
ASA_IMM_1PNPDE20070615_141117_000000342059_00053_27662_9897.N1						IS2	V/V	59	27662	53	4.04
ASA_IMM_1PNPDE20070615_154121_000000822059_00054_27663_9931.N1						IS7	V/V	59	27663	54	4.04
ASA_IMM_1PNPDE20070615_170102_000000352059_00055_27664_9953.N1						IS6	V/V	59	27664	55	4.04
ASA_IMM_1PNPDE20070615_200135_000000352059_00057_27666_0011.N1						IS7	H/H	59	27666	57	4.04
ASA_IMM_1PNPDK20070615_201134_000000362059_00057_27666_0931.N1						IS2	V/V	59	27666	57	4.04
ASA_IMM_1PNPDK20070615_201554_000001052059_00057_27666_1050.N1						IS2	H/H	59	27666	57	4.04
ASA_IMM_1PNPDK20070615_201656_000000432059_00057_27666_0943.N1						IS2	H/H	59	27666	57	4.04
ASA_IMM_1PNPDE20070615_214520_000000362059_00058_27667_0112.N1						IS2	V/V	59	27667	58	4.04
ASA_IMM_1PNPDE20070615_220912_000000362059_00058_27667_0252.N1						IS2	V/V	59	27667	58	4.04
ASA_IMM_1PNPDE20070615_234822_000001102059_00059_27668_0407.N1						IS2	V/V	59	27668	59	4.04


Filename	Pol	Timestamp	count(Module)
ASA_MS__0PNPDK20070615_055511_000000162059_00048_27657_0310.N1	V	2007-06-15 05:55:11	320





Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WSM_1PNPDE20070615_005330_000005992059_00045_27654_9312.N1						SS1	H/H	59	27654	45	4.04
ASA_WSM_1PNPDE20070615_010407_000003242059_00045_27654_9230.N1						SS1	H/H	59	27654	45	4.04
ASA_WSM_1PNPDE20070615_014233_000001762059_00046_27655_9310.N1						SS1	H/H	59	27655	46	4.04
ASA_WSM_1PNPDE20070615_023606_000004832059_00046_27655_9468.N1						SS1	H/H	59	27655	46	4.04
ASA_WSM_1PNPDE20070615_024443_000001832059_00046_27655_9314.N1						SS1	H/H	59	27655	46	4.04
ASA_WSM_1PNPDE20070615_032108_000003242059_00047_27656_9484.N1						SS1	H/H	59	27656	47	4.04
ASA_WSM_1PNPDE20070615_034618_000000852059_00047_27656_9451.N1						SS1	V/V	59	27656	47	4.04
ASA_WSM_1PNPDE20070615_041442_000003852059_00047_27656_9617.N1						SS1	H/H	59	27656	47	4.04
ASA_WSM_1PNPDE20070615_042139_000005452059_00047_27656_9642.N1						SS1	H/H	59	27656	47	4.04
ASA_WSM_1PNPDE20070615_055718_000001412059_00048_27657_9634.N1						SS1	H/H	59	27657	48	4.04
ASA_WSM_1PNPDK20070615_060555_000000852059_00048_27657_0108.N1						SS1	H/H	59	27657	48	4.04
ASA_WSM_1PNPDK20070615_064250_000001652059_00049_27658_0110.N1						SS1	V/V	59	27658	49	4.04
ASA_WSM_1PNPDK20070615_064722_000002012059_00049_27658_0112.N1						SS1	H/H	59	27658	49	4.04
ASA_WSM_1PNPDE20070615_073409_000002022059_00049_27658_9683.N1						SS1	H/H	59	27658	49	4.04
ASA_WSM_1PNPDE20070615_092045_000005862059_00050_27659_9854.N1						SS1	H/H	59	27659	50	4.04
ASA_WSM_1PNPDE20070615_092152_000001152059_00050_27659_9811.N1						SS1	H/H	59	27659	50	4.04
ASA_WSM_1PNPDE20070615_092450_000003412059_00050_27659_9812.N1						SS1	H/H	59	27659	50	4.04
ASA_WSM_1PNPDK20070615_101334_000003852059_00051_27660_0441.N1						SS1	H/H	59	27660	51	4.04
ASA_WSM_1PNPDE20070615_105906_000003612059_00051_27660_9801.N1						SS1	H/H	59	27660	51	4.04
ASA_WSM_1PNPDE20070615_110643_000004582059_00051_27660_9860.N1						SS1	H/H	59	27660	51	4.04
ASA_WSM_1PNPDE20070615_111713_000001462059_00051_27660_9831.N1						SS1	V/V	59	27660	51	4.04
ASA_WSM_1PNPDK20070615_115310_000004832059_00052_27661_0443.N1						SS1	H/H	59	27661	52	4.04
ASA_WSM_1PNPDE20070615_123557_000001402059_00052_27661_9856.N1						SS1	H/H	59	27661	52	4.04
ASA_WSM_1PNPDK20070615_123841_000005392059_00052_27661_0537.N1						SS1	H/H	59	27661	52	4.04
ASA_WSM_1PNPDK20070615_132315_000000612059_00053_27662_0445.N1						SS1	H/H	59	27662	53	4.04
ASA_WSM_1PNPDE20070615_140245_000000852059_00053_27662_9923.N1						SS1	H/H	59	27662	53	4.04
ASA_WSM_1PNPDE20070615_145357_000001042059_00054_27663_9925.N1						SS1	H/H	59	27663	54	4.04
ASA_WSM_1PNPDE20070615_150119_000001472059_00054_27663_9929.N1						SS1	V/V	59	27663	54	4.04
ASA_WSM_1PNPDK20070615_151037_000004842059_00054_27663_0668.N1						SS1	H/H	59	27663	54	4.04
ASA_WSM_1PNPDK20070615_151901_000001462059_00054_27663_0663.N1						SS1	H/H	59	27663	54	4.04
ASA_WSM_1PNPDE20070615_164609_000001402059_00055_27664_9945.N1						SS1	H/H	59	27664	55	4.04
ASA_WSM_1PNPDK20070615_165058_000004702059_00055_27664_0789.N1						SS1	H/H	59	27664	55	4.04
ASA_WSM_1PNPDE20070615_165809_000001282059_00055_27664_9943.N1						SS1	H/H	59	27664	55	4.04
ASA_WSM_1PNPDE20070615_170202_000002022059_00055_27664_9985.N1						SS1	H/H	59	27664	55	4.04
ASA_WSM_1PNPDE20070615_173746_000002012059_00055_27664_9995.N1						SS1	H/H	59	27664	55	4.04
ASA_WSM_1PNPDE20070615_174754_000000862059_00055_27664_9967.N1						SS1	H/H	59	27664	55	4.04
ASA_WSM_1PNPDE20070615_174958_000000852059_00055_27664_9983.N1						SS1	H/H	59	27664	55	4.04
ASA_WSM_1PNPDE20070615_181714_000001842059_00056_27665_9998.N1						SS1	V/V	59	27665	56	4.04
ASA_WSM_1PNPDK20070615_183134_000004582059_00056_27665_0923.N1						SS1	H/H	59	27665	56	4.04
ASA_WSM_1PNPDE20070615_183829_000001462059_00056_27665_9993.N1						SS1	H/H	59	27665	56	4.04
ASA_WSM_1PNPDE20070615_184121_000002192059_00056_27665_0025.N1						SS1	H/H	59	27665	56	4.04
ASA_WSM_1PNPDE20070615_191822_000003232059_00056_27665_0027.N1						SS1	H/H	59	27665	56	4.04
ASA_WSM_1PNPDK20070615_200706_000002022059_00057_27666_1052.N1						SS1	V/V	59	27666	57	4.04
ASA_WSM_1PNPDK20070615_201311_000001642059_00057_27666_1059.N1						SS1	H/H	59	27666	57	4.04
ASA_WSM_1PNPDE20070615_202144_000001712059_00057_27666_0133.N1						SS1	H/H	59	27666	57	4.04
ASA_WSM_1PNPDE20070615_205857_000004472059_00057_27666_0250.N1						SS1	H/H	59	27666	57	4.04
ASA_WSM_1PNPDE20070615_212332_000002632059_00057_27666_0248.N1						SS1	V/V	59	27666	57	4.04
ASA_WSM_1PNPDK20070615_214707_000001222059_00058_27667_1097.N1						SS1	V/V	59	27667	58	4.04
ASA_WSM_1PNPDK20070615_214933_000000912059_00058_27667_1099.N1						SS1	V/V	59	27667	58	4.04
ASA_WSM_1PNPDK20070615_215144_000003972059_00058_27667_1101.N1						SS1	H/H	59	27667	58	4.04
ASA_WSM_1PNPDE20070615_215737_000002082059_00058_27667_0393.N1						SS1	H/H	59	27667	58	4.04
ASA_WSM_1PNPDE20070615_220144_000002262059_00058_27667_0295.N1						SS1	H/H	59	27667	58	4.04
ASA_WSM_1PNPDE20070615_224606_000004282059_00058_27667_0297.N1						SS1	H/H	59	27667	58	4.04
ASA_WSM_1PNPDK20070615_233205_000003062059_00059_27668_1113.N1						SS1	H/H	59	27668	59	4.04




Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WVS_1PNPDE20070614_233314_000017542059_00044_27653_9064.N1						IS2	V/V	59	27653	44	4.04
ASA_WVS_1PNPDE20070615_001952_000011472059_00045_27654_9150.N1						IS2	V/V	59	27654	45	4.04
ASA_WVS_1PNPDE20070615_004548_000004052059_00045_27654_9083.N1						IS2	V/V	59	27654	45	4.04
ASA_WVS_1PNPDE20070615_010931_000003302059_00045_27654_9080.N1						IS2	V/V	59	27654	45	4.04
ASA_WVS_1PNPDE20070615_011401_000002992059_00045_27654_9198.N1						IS2	V/V	59	27654	45	4.04
ASA_WVS_1PNPDE20070615_012652_000007942059_00046_27655_9213.N1						IS2	V/V	59	27655	46	4.04
ASA_WVS_1PNPDE20070615_021106_000008692059_00046_27655_9243.N1						IS2	V/V	59	27655	46	4.04
ASA_WVS_1PNPDE20070615_022521_000004802059_00046_27655_9351.N1						IS2	V/V	59	27655	46	4.04
ASA_WVS_1PNPDE20070615_025005_000002702059_00046_27655_9361.N1						IS2	V/V	59	27655	46	4.04
ASA_WVS_1PNPDE20070615_031011_000001942059_00047_27656_9354.N1						IS2	V/V	59	27656	47	4.04
ASA_WVS_1PNPDE20070615_035159_000009592059_00047_27656_9385.N1						IS2	V/V	59	27656	47	4.04
ASA_WVS_1PNPDE20070615_040728_000001352059_00047_27656_9501.N1						IS2	V/V	59	27656	47	4.04
ASA_WVS_1PNPDE20070615_035159_000009592059_00047_27656_9385.N1						IS1	V/V	59	27656	47	4.04
ASA_WVS_1PNPDE20070615_043042_000012442059_00047_27656_9515.N1						IS2	V/V	59	27656	47	4.04
ASA_WVS_1PNPDE20070615_053154_000006892059_00048_27657_9512.N1						IS2	V/V	59	27657	48	4.04
ASA_WVS_1PNPDE20070615_054438_000001942059_00048_27657_9523.N1						IS2	V/V	59	27657	48	4.04
ASA_WVS_1PNPDK20070615_054738_000001342059_00048_27657_0140.N1						IS2	V/V	59	27657	48	4.04
ASA_WVS_1PNPDK20070615_055226_000001202059_00048_27657_0137.N1						IS2	V/V	59	27657	48	4.04
ASA_WVS_1PNPDK20070615_061117_000017542059_00048_27657_0147.N1						IS2	V/V	59	27657	48	4.04
ASA_WVS_1PNPDK20070615_072839_000002852059_00049_27658_0177.N1						IS2	V/V	59	27658	49	4.04
ASA_WVS_1PNPDK20070615_075153_000018742059_00049_27658_0217.N1						IS2	V/V	59	27658	49	4.04
ASA_WVS_1PNPDK20070615_090054_000008842059_00050_27659_0277.N1						IS2	V/V	59	27659	50	4.04
ASA_WVS_1PNPDK20070615_093229_000020092059_00050_27659_0313.N1						IS2	V/V	59	27659	50	4.04
ASA_WVS_1PNPDK20070615_103812_000010792059_00051_27660_0450.N1						IS2	V/V	59	27660	51	4.04
ASA_WVS_1PNPDK20070615_111423_000001202059_00051_27660_0486.N1						IS2	V/V	59	27660	51	4.04
ASA_WVS_1PNPDK20070615_111936_000015742059_00051_27660_0489.N1						IS2	V/V	59	27660	51	4.04
ASA_WVS_1PNPDK20070615_120254_000003452059_00052_27661_0467.N1						IS2	V/V	59	27661	52	4.04
ASA_WVS_1PNPDK20070615_121006_000006442059_00052_27661_0472.N1						IS2	V/V	59	27661	52	4.04
ASA_WVS_1PNPDK20070615_122745_000004502059_00052_27661_0508.N1						IS2	V/V	59	27661	52	4.04
ASA_WVS_1PNPDK20070615_125341_000003152059_00052_27661_0505.N1						IS2	V/V	59	27661	52	4.04
ASA_WVS_1PNPDK20070615_130623_000005692059_00052_27661_0511.N1						IS2	V/V	59	27661	52	4.04
ASA_WVS_1PNPDK20070615_131655_000001642059_00053_27662_0545.N1						IS2	V/V	59	27662	53	4.04
ASA_WVS_1PNPDK20070615_134700_000006442059_00053_27662_0542.N1						IS2	V/V	59	27662	53	4.04
ASA_WVS_1PNPDK20070615_141304_000002702059_00053_27662_0585.N1						IS2	V/V	59	27662	53	4.04
ASA_WVS_1PNPDK20070615_143417_000003902059_00053_27662_0573.N1						IS2	V/V	59	27662	53	4.04
ASA_WVS_1PNPDK20070615_144520_000004642059_00053_27662_0582.N1						IS2	V/V	59	27662	53	4.04
ASA_WVS_1PNPDK20070615_153432_000001342059_00054_27663_0683.N1						IS2	V/V	59	27663	54	4.04
ASA_WVS_1PNPDK20070615_153858_000001042059_00054_27663_0721.N1						IS2	V/V	59	27663	54	4.04
ASA_WVS_1PNPDK20070615_154251_000009142059_00054_27663_0730.N1						IS2	V/V	59	27663	54	4.04
ASA_WVS_1PNPDK20070615_161453_000012442059_00054_27663_0733.N1						IS2	V/V	59	27663	54	4.04
ASA_WVS_1PNPDK20070615_171546_000012742059_00055_27664_0836.N1						IS2	V/V	59	27664	55	4.04
ASA_WVS_1PNPDK20070615_175529_000012592059_00055_27664_0899.N1						IS2	V/V	59	27664	55	4.04
ASA_WVS_1PNPDK20070615_185007_000016492059_00056_27665_0964.N1						IS2	V/V	59	27665	56	4.04
ASA_WVS_1PNPDK20070615_193605_000000902059_00056_27665_0957.N1						IS2	V/V	59	27665	56	4.04
ASA_WVS_1PNPDK20070615_194108_000003742059_00056_27665_0954.N1						IS2	V/V	59	27665	56	4.04
ASA_WVS_1PNPDE20070615_202647_000018742059_00057_27666_0044.N1						IS2	V/V	59	27666	57	4.04
ASA_WVS_1PNPDE20070615_211640_000003002059_00057_27666_0039.N1						IS2	V/V	59	27666	57	4.04
ASA_WVS_1PNPDE20070615_212041_000001202059_00057_27666_0158.N1						IS2	V/V	59	27666	57	4.04
ASA_WVS_1PNPDE20070615_220557_000001502059_00058_27667_0161.N1						IS2	V/V	59	27667	58	4.04
ASA_WVS_1PNPDE20070615_220955_000018292059_00058_27667_0170.N1						IS2	V/V	59	27667	58	4.04
ASA_WVS_1PNPDE20070615_225716_000002552059_00058_27667_0180.N1						IS2	V/V	59	27667	58	4.04
ASA_WVS_1PNPDE20070615_230046_000009442059_00058_27667_0300.N1						IS2	V/V	59	27667	58	4.04
ASA_WVS_1PNPDE20070615_231851_000007492059_00059_27668_0305.N1						IS2	V/V	59	27668	59	4.04
ASA_WVS_1PNPDE20070615_235018_000010042059_00059_27668_0312.N1						IS2	V/V	59	27668	59	4.04














































15-Jun




15-Jun




15-Jun




15-Jun




15-Jun




15-Jun







15-Jun




15-Jun




15-Jun



15-Jun



15-Jun



15-Jun

