

Analysis from 31-OCT-2007 00:00:00 to 31-OCT-2007 23:00:05. Page generated on 31-OCT-2007 23:13:12.
View log file: ASAR_Daily_Report_20071031_2300.log. For any anomalies please contact msantuari@serco.it, mtranfaglia@serco.it, gscarpino@serco.it.

This report is automatically generated every day, every 2 hours. No comments are provided on the results.

SUMMARY

1. DATA SUMMARY
 - 1.1 Summary tables
 - 1.2 Lists of products used
2. AUXILIARY FILES ANALYSIS
 - 2.1 IECF operational ADFs list
 - 2.2 Products with wrong ADFs
3. MODULE STEPPING PRODUCTS ANALYSIS
 - 3.1 V/V polarisation
 - 3.2 H/H polarisation
4. CALIBRATION PULSES ANALYSIS
 - 4.1 Analysis for WVS IS2 V/V
 - 4.1.1 Temporal Evolution Analysis for WVS IS2 V/V
 - 4.1.2 All Rows Analysis for WVS IS2 V/V
 - 4.2 Analysis for GM1 SS3 H/H
 - 4.2.1 Temporal Evolution Analysis for GM1 SS3 H/H
 - 4.2.2 All Rows Analysis for GM1 SS3 H/H
5. DOPPLER ANALYSIS
 - 5.1 Analysis for WVS IS2 V/V
 - 5.1.1 Doppler MAP Analysis for WVS IS2 V/V
 - 5.1.2 Doppler ANX Analysis for WVS IS2 V/V
 - 5.2 Analysis for GM1 SS1 H/H
 - 5.2.1 Doppler MAP Analysis for GM1 SS1 H/H
 - 5.2.2 Doppler ANX Analysis for GM1 SS1 H/H
 - 5.3 Doppler JUMPS Analysis for WSM
6. CHIRP ANALYSIS
 - 6.1 Analysis for WSM SS1 H/H
 - 6.1.1 ScaleFactor
 - 6.2 Analysis for WSM SS1 V/V
 - 6.2.1 ScaleFactor
7. RAW DATA ANALYSIS
 - 7.1 Analysis for WVS
 - 7.2 Analysis for IMM
8. TELEMETRY ANALYSIS
 - 8.1 Number of Missing Lines
 - 8.2 Number of Gaps

1 - DATA SUMMARY

1.1 - Summary tables

[[BACK TO MENU](#)]

WVS				GM1				APM				IMM				WSM				MS			
Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Time	Pol	Modules
PDE	IS1	V/V	2	PDE	WS	H/H	17	PDE	IS2	H/H	2	PDE	IS1	H/H	1	PDE	WS	H/H	30	PDE	2007-10-31 17:01:55	V	320
PDE	IS2	V/V	17	PDK	WS	H/H	46	PDE	IS3	H/H	1	PDE	IS2	V/V	13	PDE	WS	V/V	4				
PDK	IS2	V/V	23					PDE	IS4	H/H	2	PDE	IS4	H/H	1	PDK	WS	H/H	6				
								PDE	IS6	H/H	1	PDE	IS6	V/V	2	PDK	WS	V/V	2				
								PDK	IS1	H/H	1	PDE	IS7	V/V	1								
												PDK	IS2	V/V	9								
												PDK	IS5	H/H	1								

1.2 - Lists of products used

[[BACK TO MENU](#)]

[[TXT](#)] [[XLS](#)] [List_WVS_products_used](#)
 [[TXT](#)] [[XLS](#)] [List_GM1_products_used](#)
 [[TXT](#)] [[XLS](#)] [List_APM_products_used](#)
 [[TXT](#)] [[XLS](#)] [List_IMM_products_used](#)
 [[TXT](#)] [[XLS](#)] [List_WSM_products_used](#)
 [[TXT](#)] [[XLS](#)] [List_MS_products_used](#)

2 - AUXILIARY FILES ANALYSIS

2.1 - IECF operational ADFs list

[[BACK TO MENU](#)]

ADFs disseminated for ASAR
ASA_CON_AXVIEC20070410_140202_20070204_165113_20071231_000000
ASA_INS_AXVIEC20070306_164819_20070307_060000_20071231_000000
ASA_XCH_AXVIEC20051219_162547_20020301_000000_20081231_000000
ASA_XCA_AXVIEC20070517_153558_20070204_165113_20071231_000000

2.2 - Products with wrong ADFs





[[BACK TO MENU](#)]

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
WVS	0	0	0	0
GM1	0	0	0	0
APM	0	0	0	0
IMM	0	0	0	0
WSM	0	0	0	0

[[TXT](#)] [[XLS](#)] [Check_ADFs_WVS](#)
 [[TXT](#)] [[XLS](#)] [Check_ADFs_GM1](#)
 [[TXT](#)] [[XLS](#)] [Check_ADFs_APM](#)
 [[TXT](#)] [[XLS](#)] [Check_ADFs_IMM](#)
 [[TXT](#)] [[XLS](#)] [Check_ADFs_WSM](#)

3 - MODULE STEPPING PRODUCTS ANALYSIS












3.2 - H/H polarisation

[BACK TO MENU]

SECOND FIXED REFERENCE	PREVIOUS PRODUCT REFERENCE
After antenna maintenance (2005-09-22/23)	Previous product in the same polarisation





4 - CALIBRATION PULSES ANALYSIS

4.1 - Analysis for WVS IS2 V/V


4.1.1 - Temporal Evolution Analysis for WVS IS2 V/V

[BACK TO MENU]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]


Calibration pulses for WVS IS2 V/V




31-Oct



31-Oct




31-Oct



31-Oct


rows: - 1 - 5 - 9 - 13 - 17 - 21 - 25 - 29

Transmit power (P1 - P1a) for WVS IS2 V/V



31-Oct

Transmit power (P1 - P1a) for WVS IS2 V/V




31-Oct

rows: - 1 - 5 - 9 - 13 - 17 - 21 - 25 - 29

4.1.2 - All Rows Analysis for WVS IS2 V/V

[[BACK TO MENU](#)]





4.2 - Analysis for GM1 SS3 H/H


4.2.1 - Temporal Evolution Analysis for GM1 SS3 H/H

[BACK TO MENU]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Calibration pulses for GM1 SS3 H/H




Transmit power (P1 - P1a) for GM1 SS3 H/H



4.2.2 - All Rows Analysis for GM1 SS3 H/H

[[BACK TO MENU](#)]






5 - DOPPLER ANALYSIS

5.1 - Analysis for WVS IS2 V/V

5.1.1 - Doppler MAP Analysis for WVS IS2 V/V

[[BACK TO MENU](#)]






5.1.2 - Doppler ANX Analysis for WVS IS2 V/V

[[BACK TO MENU](#)]






5.2 - Analysis for GM1 SS1 H/H

5.2.1 - Doppler MAP Analysis for GM1 SS1 H/H

[[BACK TO MENU](#)]






5.2.2 - Doppler ANX Analysis for GM1 SS1 H/H

[[BACK TO MENU](#)]






5.3 - Doppler JUMPS Analysis for WSM

[[BACK TO MENU](#)]







6 - CHIRP ANALYSIS

6.1 - Analysis for WSM SS1 H/H

6.1.1 - ScaleFactor

[[BACK TO MENU](#)]







6.2 - Analysis for WSM SS1 V/V

6.2.1 - ScaleFactor

[[BACK TO MENU](#)]






7 - RAW DATA ANALYSIS

7.1 - Analysis for WVS

[[BACK TO MENU](#)]


--	--	--




Channel	Statistics	DSS-B
MEAN I	mean	0.000523042
	stdev	1.84437e-07
MEAN Q	mean	0.000540762
	stdev	2.25736e-07
Channel	Statistics	DSS-B
STDEV I	mean	0.134496
	stdev	0.000894871
STDEV Q	mean	0.134856
	stdev	0.000907866

7.2 - Analysis for IMM

[[BACK TO MENU](#)]






8 - TELEMETRY ANALYSIS

Processing Center	Product	Gaps	Missing lines
PDK	ASA_IMM_1PNPDK20071031_123942_00000352063_00024_29637_4646.N1	0	14

8.1 - Number of Missing lines


[[BACK TO MENU](#)]





8.2 - Number of Gaps

[\[BACK TO MENU \]](#)



ASAR DAILY REPORT for 071031
#####

MODE: DAILY
ANALYSIS: ALL
DATE: TODAY

Analysis will be performed from 2007-10-31 00:00:00 to 2007-10-31 23:00:05
Results will be exported to the directory: ./RESULTS/DAILY/071031/

DATA SUMMARY

Summary will be performed from 2007-10-31 00:00:00 to 2007-10-31 23:00:05
Results will be exported to the directory: ./RESULTS/DAILY/071031/DATA_SUMMARY

Creating directory ./RESULTS/DAILY/071031/DATA_SUMMARY...
Writing file ./RESULTS/DAILY/071031/DATA_SUMMARY/Data_summary.html...

Getting WVS products list from 2007-10-31 00:00:00 to 2007-10-31 23:00:05...
Writing file ./RESULTS/DAILY/071031/DATA_SUMMARY/List_WVS_products_used.xls...
Writing file ./RESULTS/DAILY/071031/DATA_SUMMARY/List_WVS_products_used.txt...

Getting GM1 products list from 2007-10-31 00:00:00 to 2007-10-31 23:00:05...
Writing file ./RESULTS/DAILY/071031/DATA_SUMMARY/List_GM1_products_used.xls...
Writing file ./RESULTS/DAILY/071031/DATA_SUMMARY/List_GM1_products_used.txt...

Getting APM products list from 2007-10-31 00:00:00 to 2007-10-31 23:00:05...
Writing file ./RESULTS/DAILY/071031/DATA_SUMMARY/List_APM_products_used.xls...
Writing file ./RESULTS/DAILY/071031/DATA_SUMMARY/List_APM_products_used.txt...

Getting IMM products list from 2007-10-31 00:00:00 to 2007-10-31 23:00:05...
Writing file ./RESULTS/DAILY/071031/DATA_SUMMARY/List_IMM_products_used.xls...
Writing file ./RESULTS/DAILY/071031/DATA_SUMMARY/List_IMM_products_used.txt...

Getting WSM products list from 2007-10-31 00:00:00 to 2007-10-31 23:00:05...
Writing file ./RESULTS/DAILY/071031/DATA_SUMMARY/List_WSM_products_used.xls...
Writing file ./RESULTS/DAILY/071031/DATA_SUMMARY/List_WSM_products_used.txt...

Getting MS products list from 2007-10-31 00:00:00 to 2007-10-31 23:00:05...
Writing file ./RESULTS/DAILY/071031/DATA_SUMMARY/List_MS_products_used.xls...
Writing file ./RESULTS/DAILY/071031/DATA_SUMMARY/List_MS_products_used.txt...

DATA SUMMARY completed
#####

AUXILIARY FILES ANALYSIS

Analysis will be performed from 2007-10-31 00:00:00 to 2007-10-31 23:00:05
Results will be exported to the directory: ./RESULTS/DAILY/071031/AUXILIARY

Creating directory ./RESULTS/DAILY/071031/AUXILIARY...

Looking for the IECF operational ADFs list...



Found list 20071031_030001_current_3_IECF_ADFs.txt...
Extracting ADFs...

ASA_CON_AXVIEC20070410_140202_20070204_165113_20071231_000000
ASA_INS_AXVIEC20070306_164819_20070307_060000_20071231_000000
ASA_XCH_AXVIEC20051219_162547_20020301_000000_20081231_000000
ASA_XCA_AXVIEC20070517_153558_20070204_165113_20071231_000000

Writing file ./RESULTS/DAILY/071031/AUXILIARY/ASAR_ADFs_IECF_List3.html...
Writing file ./RESULTS/DAILY/071031/AUXILIARY/Auxiliary_files_summary.html...

Analysing WVS products...

Writing file ./RESULTS/DAILY/071031/AUXILIARY/Check_ADFs_WVS.xls...
Writing file ./RESULTS/DAILY/071031/AUXILIARY/Check_ADFs_WVS.txt...

ASA_WVS_1PNPDE20071031_000858_000003752063_00016_29629_8145.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20071031_003320_000001952063_00016_29629_8142.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20071031_003535_000005692063_00016_29629_8273.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20071031_004814_000009742063_00016_29629_8288.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20071031_012955_000008682063_00017_29630_8298.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20071031_014823_000004502063_00017_29630_8295.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20071031_021238_000001342063_00017_29630_8303.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20071031_021353_000003002063_00017_29630_8435.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20071031_031627_000007792063_00018_29631_8443.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20071031_032857_000002852063_00018_29631_8552.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20071031_035801_000006592063_00018_29631_8547.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20071031_041035_000001642063_00019_29632_8560.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20071031_045728_000007942063_00019_29632_8595.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20071031_051013_000003602063_00019_29632_8725.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20071031_053341_000008552063_00019_29632_8758.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20071031_064105_000005992063_00020_29633_8776.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20071031_065035_000004202063_00020_29633_4238.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20071031_071426_000019042063_00020_29633_4250.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20071031_082951_000004952063_00021_29634_4329.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20071031_085502_0000020392063_00021_29634_4334.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20071031_100120_000009442063_00022_29635_4452.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20071031_103529_000003302063_00022_29635_4455.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20071031_104216_000014392063_00022_29635_4465.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20071031_112503_000007192063_00023_29636_4553.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20071031_113916_000011092063_00023_29636_4558.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20071031_121615_000004202063_00023_29636_4563.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20071031_122738_000006592063_00023_29636_4568.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20071031_124024_000002542063_00024_29637_4576.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20071031_130646_000008842063_00024_29637_4706.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20071031_135649_000004202063_00024_29637_4711.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20071031_140933_000005542063_00024_29637_4727.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20071031_150628_000008542063_00025_29638_4832.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20071031_153740_000013192063_00025_29638_4847.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20071031_164007_000012742063_00026_29639_4959.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20071031_171920_000013042063_00026_29639_4969.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20071031_181533_000015292063_00027_29640_5080.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20071031_190210_000007642063_00027_29640_5089.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20071031_194935_000019642063_00028_29641_5199.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20071031_203913_000004052063_00028_29641_5207.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

Analysing GM1 products...

Writing file ./RESULTS/DAILY/071031/AUXILIARY/Check_ADFs_GM1.xls...
Writing file ./RESULTS/DAILY/071031/AUXILIARY/Check_ADFs_GM1.txt...

ASA_GM1_1PNPDE20071031_000206_000004102063_00016_29629_8126.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

ASA_GM1_1PNPDE20071031_004554_000001382063_00016_29629_8270.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071031_010523_000012272063_00017_29630_8376.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071031_012826_000000842063_00017_29630_8290.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071031_014518_000001812063_00017_29630_8292.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071031_021050_000001082063_00017_29630_8300.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071031_021945_000007612063_00017_29630_8427.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071031_024307_000004472063_00018_29631_8425.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071031_025128_000010082063_00018_29631_8500.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071031_031125_000003022063_00018_29631_8446.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071031_035414_000002232063_00018_29631_8549.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071031_041848_000019692063_00019_29632_8649.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071031_045249_000002772063_00019_29632_8592.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071031_060015_000001382063_00020_29633_8727.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071031_060427_000007972063_00020_29633_8755.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071031_062430_000002052063_00020_29633_8753.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071031_063125_000005792063_00020_29633_8794.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071031_065827_000001082063_00020_29633_4284.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071031_070301_000002352063_00020_29633_4235.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071031_071251_000000902063_00020_29633_4286.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071031_074835_000005922063_00021_29634_4247.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071031_075729_000000602063_00021_29634_4320.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071031_075937_000005012063_00021_29634_4324.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071031_081437_000001632063_00021_29634_4322.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071031_081927_000006222063_00021_29634_4326.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071031_083903_000009242063_00021_29634_4331.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071031_092945_000005312063_00022_29635_4341.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071031_095504_000003742063_00022_29635_4457.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071031_110711_000007062063_00023_29636_4467.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071031_112149_000001932063_00023_29636_4555.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071031_120603_000000962063_00023_29636_4560.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071031_122402_000002112063_00023_29636_4565.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071031_124733_000007062063_00024_29637_4578.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071031_125809_000005132063_00024_29637_4697.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071031_132218_000006462063_00024_29637_4699.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071031_133315_000003682063_00024_29637_4703.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071031_134051_000001572063_00024_29637_4701.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071031_134624_000006222063_00024_29637_4708.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071031_140441_000002892063_00024_29637_4713.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071031_142100_000005132063_00025_29638_4715.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071031_143057_000001752063_00025_29638_4729.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071031_144438_000004952063_00025_29638_4823.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071031_150137_000002892063_00025_29638_4827.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071031_152127_000000962063_00025_29638_4825.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071031_152646_000001872063_00025_29638_4829.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071031_153237_000000902063_00025_29638_4834.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071031_160144_000006582063_00026_29639_4843.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071031_162239_000008272063_00026_29639_4949.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071031_170837_000002892063_00026_29639_4951.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071031_174520_000003502063_00027_29640_4961.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071031_174950_000001752063_00027_29640_5075.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071031_180156_000001082063_00027_29640_5073.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071031_180441_000003862063_00027_29640_5077.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071031_184928_000005492063_00027_29640_5082.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071031_191547_000001322063_00028_29641_5084.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071031_192012_000004342063_00028_29641_5086.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071031_192838_000001992063_00028_29641_5096.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071031_193043_000002592063_00028_29641_5188.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071031_193647_000001202063_00028_29641_5190.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071031_194117_000003202063_00028_29641_5192.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071031_194746_000001082063_00028_29641_5194.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071031_203625_000001692063_00028_29641_5196.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071031_204650_000011482063_00028_29641_5285.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

Analysing APM products...

Writing file ./RESULTS/DAILY/071031/AUXILIARY/Check_ADFs_APM.xls...

Writing file ./RESULTS/DAILY/071031/AUXILIARY/Check_ADFs_APM.txt...

ASA_APM_1PNPDE20071031_012707_000000532063_00017_29630_8268.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20071031_024156_000000432063_00018_29631_8505.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20071031_045142_000000422063_00019_29632_8647.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20071031_160036_000000422063_00026_29639_9078.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20071031_181111_000000422063_00027_29640_9128.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20071031_194637_000000412063_00028_29641_9164.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDK20071031_124525_000001012063_00024_29637_4652.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

Analysing IMM products...

Writing file ./RESULTS/DAILY/071031/AUXILIARY/Check_ADFs_IMM.xls...

Writing file ./RESULTS/DAILY/071031/AUXILIARY/Check_ADFs_IMM.txt...

ASA_IMM_1PNPDE20071031_012551_000000542063_00017_29630_8244.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20071031_025033_000000372063_00018_29631_8507.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20071031_030816_000000802063_00018_29631_8421.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20071031_040935_000000542063_00018_29631_8645.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20071031_060233_000000952063_00020_29633_8998.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20071031_062758_000000502063_00020_29633_8986.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20071031_062934_000000932063_00020_29633_8996.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20071031_081719_000001082063_00021_29634_8881.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20071031_104134_000000362063_00022_29635_8936.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20071031_113748_000000812063_00023_29636_8943.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20071031_141923_000000622063_00025_29638_9022.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20071031_141923_000000802063_00025_29638_9045.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20071031_142935_000000652063_00025_29638_9043.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20071031_174143_000001992063_00027_29640_9120.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20071031_180346_000000372063_00027_29640_9080.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20071031_181228_000001392063_00027_29640_9136.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20071031_191801_000001132063_00028_29641_9176.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20071031_191903_000000512063_00028_29641_9168.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20071031_062010_000002402063_00020_29633_4229.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20071031_075830_000000512063_00021_29634_4257.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20071031_093836_000003962063_00022_29635_4438.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20071031_094840_000000802063_00022_29635_4419.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20071031_111857_000001552063_00023_29636_4541.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20071031_123942_000000352063_00024_29637_4646.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20071031_143351_000000662063_00025_29638_4797.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20071031_161242_000003522063_00026_29639_4935.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20071031_175248_000003522063_00027_29640_5048.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20071031_210826_000001252063_00029_29642_5287.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

Analysing WSM products...

Writing file ./RESULTS/DAILY/071031/AUXILIARY/Check_ADFs_WSM.xls...

Writing file ./RESULTS/DAILY/071031/AUXILIARY/Check_ADFs_WSM.txt...

ASA_WSM_1PNPDE20071031_001644_000005452063_00016_29629_8378.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071031_015639_000005372063_00017_29630_8502.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071031_020616_000000672063_00017_29630_8386.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071031_020616_000002612063_00017_29630_8772.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071031_020824_000001332063_00017_29630_8423.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071031_023546_000000912063_00018_29631_8509.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071031_023732_000002132063_00018_29631_8542.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071031_030954_000000672063_00018_29631_8494.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071031_033715_000003852063_00018_29631_8544.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071031_034452_000001282063_00018_29631_8691.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071031_034452_000004762063_00018_29631_8770.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071031_034755_000002932063_00018_29631_8692.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

ASA_WSM_1PNPDE20071031_051706_000003672063_00019_29632_8711.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071031_052351_000005742063_00019_29632_8886.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071031_070027_000001402063_00020_29633_8846.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071031_101754_000000852063_00022_29635_8912.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071031_101901_00000182063_00022_29635_8902.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071031_101938_000003062063_00022_29635_8960.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071031_101938_000005392063_00022_29635_8982.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071031_102545_000001722063_00022_29635_8961.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071031_102809_000000912063_00022_29635_8958.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071031_103015_000002932063_00022_29635_8964.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071031_115829_000004472063_00023_29636_8984.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071031_134336_000001592063_00024_29637_9068.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071031_134336_000001592063_00024_29637_9076.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071031_145301_000001032063_00025_29638_9072.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071031_152312_000002022063_00025_29638_9074.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071031_152312_000002022063_00025_29638_9126.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071031_153003_000001472063_00025_29638_9016.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071031_153416_000002022063_00025_29638_9070.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071031_170403_000002632063_00026_29639_9124.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071031_171339_000003422063_00026_29639_9122.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071031_184154_000004462063_00027_29640_9154.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071031_203047_000001462063_00028_29641_9162.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20071031_061755_000000852063_00020_29633_4231.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20071031_070704_000003352063_00020_29633_4318.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20071031_074701_000000852063_00021_29634_4316.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20071031_120751_000005022063_00023_29636_4689.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20071031_143555_000005142063_00025_29638_4841.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20071031_162002_000001472063_00026_29639_4947.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20071031_175935_000001282063_00027_29640_5050.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20071031_193513_000000852063_00028_29641_5172.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20071031_193856_000001282063_00028_29641_5177.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20071031_211740_000001832063_00029_29642_5306.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

AUXILIARY FILES ANALYSIS completed

#####

MODULE STEPPING ANALYSIS

#####

Analysis will be performed from 2007-10-31 00:00:00 to 2007-10-31 23:00:05

Results will be exported to the directory: ./RESULTS/DAILY/071031/MODULE_STEPPING

Creating directory ./RESULTS/DAILY/071031/MODULE_STEPPING...

Creating directory ./RESULTS/DAILY/071031/MODULE_STEPPING/FIRST_REFERENCE...

Creating directory ./RESULTS/DAILY/071031/MODULE_STEPPING/SECOND_REFERENCE...

Creating directory ./RESULTS/DAILY/071031/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE...

Deleting old files...

Creating images comparing with second reference...

Exporting results to the directory ../../RESULTS/DAILY/071031/MODULE_STEPPING/SECOND_REFERENCE...

Polarization: H

Reference product: ASA_MS_0PNPDK20050922_062651_00000152041_00034_18625_0041.N1

Test product: ASA_MS_0PNPDK20071030_173332_00000162063_00012_29625_0403.N1

H

H

../../RESULTS/DAILY/071031/MODULE_STEPPING/SECOND_REFERENCE/TGH_20071030_173332-20050922_062651.png

../../RESULTS/DAILY/071031/MODULE_STEPPING/SECOND_REFERENCE/TPH_20071030_173332-20050922_062651.png

../../RESULTS/DAILY/071031/MODULE_STEPPING/SECOND_REFERENCE/RGH_20071030_173332-20050922_062651.png

../../RESULTS/DAILY/071031/MODULE_STEPPING/SECOND_REFERENCE/RPH_20071030_173332-20050922_062651.png

Polarization: V

Reference product: ASA_MS__0PNPDK20050923_055514_000000152041_00048_18639_0042.N1
Test product: ASA_MS__0PNPDK20071031_170155_000000162063_00026_29639_0404.N1

V
V

.././RESULTS/DAILY/071031/MODULE_STEPPING/SECOND_REFERENCE/TGV_20071031_170155-20050923_055514.png
.././RESULTS/DAILY/071031/MODULE_STEPPING/SECOND_REFERENCE/TPV_20071031_170155-20050923_055514.png
.././RESULTS/DAILY/071031/MODULE_STEPPING/SECOND_REFERENCE/RGV_20071031_170155-20050923_055514.png
.././RESULTS/DAILY/071031/MODULE_STEPPING/SECOND_REFERENCE/RPV_20071031_170155-20050923_055514.png

Creating images comparing with previous product reference...

Exporting results to the directory .././RESULTS/DAILY/071031/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE...

Polarization: H
Reference product: ASA_MS__0PNPDK20071028_183646_000000162062_00485_29597_0401.N1
Test product: ASA_MS__0PNPDK20071030_173332_000000162063_00012_29625_0403.N1

H
H

.././RESULTS/DAILY/071031/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TGH_20071030_173332-20071028_183646.png
.././RESULTS/DAILY/071031/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TPH_20071030_173332-20071028_183646.png
.././RESULTS/DAILY/071031/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RGH_20071030_173332-20071028_183646.png
.././RESULTS/DAILY/071031/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RPH_20071030_173332-20071028_183646.png

Polarization: V
Reference product: ASA_MS__0PNPDK20071029_180509_000000162062_00499_29611_0402.N1
Test product: ASA_MS__0PNPDK20071031_170155_000000162063_00026_29639_0404.N1

V
V

.././RESULTS/DAILY/071031/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TGV_20071031_170155-20071029_180509.png
.././RESULTS/DAILY/071031/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TPV_20071031_170155-20071029_180509.png
.././RESULTS/DAILY/071031/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RGV_20071031_170155-20071029_180509.png
.././RESULTS/DAILY/071031/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RPV_20071031_170155-20071029_180509.png

MODULE_STEPPING ANALYSIS completed

#####

CALIBRATION PULSES ANALYSIS

#####

Creating directory ./RESULTS/DAILY/071031/CALIBRATION_PULSES...

ALL ROWS Analysis will be performed from 2007-10-31 00:00:00 to 2007-10-31 23:00:05

Analysing products WVS IS2 V/V
Writing image .././RESULTS/DAILY/071031//CALIBRATION_PULSES/Calibration_pulses_all_rows_WVS_IS2_VV.png...
Analysing products GM1 SS3 H/H
Writing image .././RESULTS/DAILY/071031//CALIBRATION_PULSES/Calibration_pulses_all_rows_GM1_SS3_HH.png...

TEMPORAL EVOLUTION Analysis will be performed from 2007-10-31 00:00:00 to 2007-10-31 23:00:05

Analysing products WVS IS2 V/V
Getting calibration pulses data for WVS IS2 V/V from 2007-10-31 00:00:00 to 2007-10-31 23:00:05. Rows: 1/5/9/13/17/21/25/29
Writing file ./RESULTS/DAILY/071031/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2007-10-31_1.dat...
Writing .././RESULTS/DAILY/071031//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_1.png...
Writing .././RESULTS/DAILY/071031//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_1.png...

Getting calibration pulses data for WVS IS2 V/V from 2007-10-31 00:00:00 to 2007-10-31 23:00:05. Rows: 2/6/10/14/18/22/26/30



Writing file ./RESULTS/DAILY/071031/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2007-10-31_2.dat...
Writing ../../RESULTS/DAILY/071031//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_2.png...
Writing ../../RESULTS/DAILY/071031//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_2.png...

Getting calibration pulses data for WVS IS2 V/V from 2007-10-31 00:00:00 to 2007-10-31 23:00:05. Rows: 3/7/11/15/19/23/27/31
Writing file ./RESULTS/DAILY/071031/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2007-10-31_3.dat...
Writing ../../RESULTS/DAILY/071031//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_3.png...
Writing ../../RESULTS/DAILY/071031//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_3.png...

Getting calibration pulses data for WVS IS2 V/V from 2007-10-31 00:00:00 to 2007-10-31 23:00:05. Rows: 4/8/12/16/20/24/28/32
Writing file ./RESULTS/DAILY/071031/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2007-10-31_4.dat...
Writing ../../RESULTS/DAILY/071031//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_4.png...
Writing ../../RESULTS/DAILY/071031//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_4.png...

Analysing products GM1 SS3 H/H
Getting calibration pulses data for GM1 SS3 H/H from 2007-10-31 00:00:00 to 2007-10-31 23:00:05. Rows: 1/5/9/13/17/21/25/29
Writing file ./RESULTS/DAILY/071031/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2007-10-31_1.dat...
Writing ../../RESULTS/DAILY/071031//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_1.png...
Writing ../../RESULTS/DAILY/071031//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_1.png...

Getting calibration pulses data for GM1 SS3 H/H from 2007-10-31 00:00:00 to 2007-10-31 23:00:05. Rows: 2/6/10/14/18/22/26/30
Writing file ./RESULTS/DAILY/071031/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2007-10-31_2.dat...
Writing ../../RESULTS/DAILY/071031//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_2.png...
Writing ../../RESULTS/DAILY/071031//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_2.png...

Getting calibration pulses data for GM1 SS3 H/H from 2007-10-31 00:00:00 to 2007-10-31 23:00:05. Rows: 3/7/11/15/19/23/27/31
Writing file ./RESULTS/DAILY/071031/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2007-10-31_3.dat...
Writing ../../RESULTS/DAILY/071031//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_3.png...
Writing ../../RESULTS/DAILY/071031//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_3.png...

Getting calibration pulses data for GM1 SS3 H/H from 2007-10-31 00:00:00 to 2007-10-31 23:00:05. Rows: 4/8/12/16/20/24/28/32
Writing file ./RESULTS/DAILY/071031/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2007-10-31_4.dat...
Writing ../../RESULTS/DAILY/071031//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_4.png...
Writing ../../RESULTS/DAILY/071031//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_4.png...

CALIBRATION PULSES ANALYSIS completed
#####

DOPPLER ANALYSIS

Creating directory ./RESULTS/DAILY/071031/DOPPLER...

DOPPLER ANX Analysis will be performed from 2007-10-31 00:00:00 to 2007-10-31 23:00:05

Analysing products WVS IS2 V/V
Getting doppler data for WVS IS2 V/V from 2007-10-31 00:00:00 to 2007-10-31 23:00:05...
Writing file ./RESULTS/DAILY/071031/DOPPLER/Doppler_data_WVS_IS2_VV_2007-10-31.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/071031/DOPPLER/DOPPLER_ANX_WVS_IS2_VV.png...

Analysing products GM1 SS1 H/H
Getting doppler data for GM1 SS1 H/H from 2007-10-31 00:00:00 to 2007-10-31 23:00:05...
Writing file ./RESULTS/DAILY/071031/DOPPLER/Doppler_data_GM1_SS1_HH_2007-10-31.dat...
Running IDL program...

Writing file ../../RESULTS/DAILY/071031/DOPPLER/DOPPLER_ANX_GM1_SS1_HH.png...

DOPPLER JUMPS Analysis will be performed on WSM products from 2007-10-31 00:00:00 to 2007-10-31 23:00:05

Analysing by default products WSM
Getting doppler jumps data for WSM from 2007-10-31 00:00:00 to 2007-10-31 23:00:05...
Writing file ./RESULTS/DAILY/071031/DOPPLER/Doppler_Jumps_data_WSM_2007-10-31.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/071031/DOPPLER/DOPPLER_JUMPS_ANX_WSM.png...
Writing file ../../RESULTS/DAILY/071031/DOPPLER/DOPPLER_JUMPS_Date_WSM.png...

DOPPLER MAP Analysis will be performed from 2007-10-31 00:00:00 to 2007-10-31 23:00:05

Analysing products WVS IS2 V/V
Loading predicted doppler values....
Phase: descending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -23.484271 Hz
Writing file ../../RESULTS/DAILY/071031//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_WVS_IS2_VV_desc.jpg...
Writing file ../../RESULTS/DAILY/071031//DOPPLER/DOPPLER_Absolute_WVS_IS2_VV_desc.jpg...

Loading predicted doppler values....
Phase: ascending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -24.428838 Hz
Writing file ../../RESULTS/DAILY/071031//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_WVS_IS2_VV_asc.jpg...
Writing file ../../RESULTS/DAILY/071031//DOPPLER/DOPPLER_Absolute_WVS_IS2_VV_asc.jpg...

Analysing products GM1 SS1 H/H
Loading predicted doppler values....
Phase: descending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -13.031176 Hz
Writing file ../../RESULTS/DAILY/071031//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_GM1_SS1_HH_desc.jpg...
Writing file ../../RESULTS/DAILY/071031//DOPPLER/DOPPLER_Absolute_GM1_SS1_HH_desc.jpg...

Loading predicted doppler values....
Phase: ascending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -23.409356 Hz
Writing file ../../RESULTS/DAILY/071031//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_GM1_SS1_HH_asc.jpg...
Writing file ../../RESULTS/DAILY/071031//DOPPLER/DOPPLER_Absolute_GM1_SS1_HH_asc.jpg...

DOPPLER ANALYSIS completed
#####

#####

Creating directory ./RESULTS/DAILY/071031/CHIRP...

CHIRP Analysis will be performed from 2007-10-31 00:00:00 to 2007-10-31 23:00:05

Analysing products WSM SS1 H/H

Getting ScaleFactor data for WSM SS1 H/H from 2007-10-31 00:00:00 to 2007-10-31 23:00:05...
Writing file ./RESULTS/DAILY/071031/CHIRP/ScaleFactor_data_WSM_SS1_HH_2007-10-31.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/071031/CHIRP/ScaleFactor_ANX_WSM_SS1_HH.png...
Writing file ../../RESULTS/DAILY/071031/CHIRP/ScaleFactor_DATE_WSM_SS1_HH.png...

Analysing products WSM SS1 V/V

Getting ScaleFactor data for WSM SS1 V/V from 2007-10-31 00:00:00 to 2007-10-31 23:00:05...
Writing file ./RESULTS/DAILY/071031/CHIRP/ScaleFactor_data_WSM_SS1_VV_2007-10-31.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/071031/CHIRP/ScaleFactor_ANX_WSM_SS1_VV.png...
Writing file ../../RESULTS/DAILY/071031/CHIRP/ScaleFactor_DATE_WSM_SS1_VV.png...

CHIRP ANALYSIS completed

#####

RAW DATA ANALYSIS

Analysis will be performed from 2007-10-31 00:00:00 to 2007-10-31 23:00:05
Results will be exported to the directory: ./RESULTS/DAILY/071031/RAW_DATA

Creating directory ./RESULTS/DAILY/071031/RAW_DATA...

Getting raw data for WVS from 2007-10-31 00:00:00 to 2007-10-31 23:00:05...
Writing file ./RESULTS/DAILY/071031/RAW_DATA/Raw_data_WVS_2007-10-31.dat...
Running IDL program to create graphs...

Creating image ../../RESULTS/DAILY/071031/RAW_DATA/Raw_data_WVS_input_mean.png...
Creating image ../../RESULTS/DAILY/071031/RAW_DATA/Raw_data_WVS_input_stdev.png...
Creating image ../../RESULTS/DAILY/071031/RAW_DATA/Raw_data_WVS_gain_imbalance.png...

Getting raw data for IMM from 2007-10-31 00:00:00 to 2007-10-31 23:00:05...
Writing file ./RESULTS/DAILY/071031/RAW_DATA/Raw_data_IMM_2007-10-31.dat...
Running IDL program to create graphs...

Creating image ../../RESULTS/DAILY/071031/RAW_DATA/Raw_data_IMM_input_mean.png...
Creating image ../../RESULTS/DAILY/071031/RAW_DATA/Raw_data_IMM_input_stdev.png...
Creating image ../../RESULTS/DAILY/071031/RAW_DATA/Raw_data_IMM_gain_imbalance.png...

RAW DATA ANALYSIS completed

#####

TELEMETRY ANALYSIS

Analysis will be performed from 2007-10-31 00:00:00 to 2007-10-31 23:00:05
Results will be exported to the directory: ./RESULTS/DAILY/071031/TELEMETRY

Creating directory ./RESULTS/DAILY/071031/TELEMETRY...

Looking for gaps and missing lines in WVS products...

Checking 17 products from PDE...

Checking 23 products from PDK...

Looking for gaps and missing lines in GM1 products...

Checking 17 products from PDE...

Checking 46 products from PDK...

Looking for gaps and missing lines in APM products...

Checking 6 products from PDE...

Checking 1 products from PDK...

Looking for gaps and missing lines in IMM products...

Checking 18 products from PDE...

Checking 10 products from PDK...

Found product..ASA_IMM_1PNPDK20071031_123942_00000352063_00024_29637_4646.N1 / 0 gaps / 14 missing lines

Looking for gaps and missing lines in WSM products...

Checking 34 products from PDE...

Checking 10 products from PDK...

Creating graph of missing lines and gaps...

Creating image: ./RESULTS/DAILY/071031/TELEMETRY/TELEMETRY_Missing_lines.png...

Creating image: ./RESULTS/DAILY/071031/TELEMETRY/TELEMETRY_Gaps.png...

TELEMETRY ANALYSIS completed

#####

BROWSE PRODUCTS ANALYSIS

#####

Analysis will be performed on 2007-10-31

Scanning directory /nas3/ENVISAT/ASAR//ASA_GM_BP...

Results will be exported to the directory: /nas3/ENVISAT/ASAR//ASA_GM_BP/JPG/20071031/

ANALYSIS COMPLETED: 0 GM browse products to see...

Scanning directory /nas3/ENVISAT/ASAR//ASA_AP_BP...

Results will be exported to the directory: /nas3/ENVISAT/ASAR//ASA_AP_BP/JPG/20071031/

ANALYSIS COMPLETED: 0 AP browse products to see...

Scanning directory /nas3/ENVISAT/ASAR//ASA_IM_BP...

Results will be exported to the directory: /nas3/ENVISAT/ASAR//ASA_IM_BP/JPG/20071031/

ANALYSIS COMPLETED: 0 IM browse products to see...

Scanning directory /nas3/ENVISAT/ASAR//ASA_WS__BP...
Results will be exported to the directory: /nas3/ENVISAT/ASAR//ASA_WS__BP/JPG/20071031/

ANALYSIS COMPLETED: 0 WS browse products to see...

BROWSE PRODUCTS ANALYSIS completed
#####

HTML REPORT generation
#####

Building file ./RESULTS/DAILY/071031/asarReport.html...
Building DATA SUMMARY section...
Building AUXILIARY FILES ANALYSIS section...
Building MODULE STEPPING ANALYSIS section...
Building CALIBRATION PULSES ANALYSIS section...
Building DOPPLER ANALYSIS section...
Building CHIRP ANALYSIS section...
Building RAW DATA ANALYSIS section...
Building TELEMETRY ANALYSIS section...

HTML REPORT generation completed
#####



ASAR Daily Report



Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
ASA_APM_1PNPDE20071031_012707_000000532063_00017_29630_8268.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20071031_024156_000000432063_00018_29631_8505.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20071031_045142_000000422063_00019_29632_8647.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20071031_160036_000000422063_00026_29639_9078.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20071031_181111_000000422063_00027_29640_9128.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20071031_194637_000000412063_00028_29641_9164.N1	OK	OK	OK	OK
ASA_APM_1PNPDK20071031_124525_000001012063_00024_29637_4652.N1	OK	OK	OK	OK



Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_GM1_1PNPDE20071031_000206_000004102063_00016_29629_8126.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071031_004554_000001382063_00016_29629_8270.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071031_010523_000012272063_00017_29630_8376.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071031_012826_000000842063_00017_29630_8290.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071031_014518_000001812063_00017_29630_8292.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071031_021050_000001082063_00017_29630_8300.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071031_021945_000007612063_00017_29630_8427.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071031_024307_000004472063_00018_29631_8425.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071031_025128_000010082063_00018_29631_8500.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071031_031125_000003022063_00018_29631_8446.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071031_035414_000002232063_00018_29631_8549.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071031_041848_000019692063_00019_29632_8649.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071031_045249_000002772063_00019_29632_8592.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071031_060015_000001382063_00020_29633_8727.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071031_060427_000007972063_00020_29633_8755.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071031_062430_000002052063_00020_29633_8753.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071031_063125_000005792063_00020_29633_8794.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071031_065827_000001082063_00020_29633_4284.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071031_070301_000002352063_00020_29633_4235.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071031_071251_000000902063_00020_29633_4286.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071031_074835_000005922063_00021_29634_4247.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071031_075729_000000602063_00021_29634_4320.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071031_075937_000005012063_00021_29634_4324.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071031_081437_000001632063_00021_29634_4322.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071031_081927_000006222063_00021_29634_4326.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071031_083903_000009242063_00021_29634_4331.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071031_092945_000005312063_00022_29635_4341.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071031_095504_000003742063_00022_29635_4457.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071031_110711_000007062063_00023_29636_4467.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071031_112149_000001932063_00023_29636_4555.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071031_120603_000000962063_00023_29636_4560.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071031_122402_000002112063_00023_29636_4565.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071031_124733_000007062063_00024_29637_4578.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071031_125809_000005132063_00024_29637_4697.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071031_132218_000006462063_00024_29637_4699.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071031_133315_000003682063_00024_29637_4703.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071031_134051_000001572063_00024_29637_4701.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071031_134624_000006222063_00024_29637_4708.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071031_140441_000002892063_00024_29637_4713.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071031_142100_000005132063_00025_29638_4715.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071031_143057_000001752063_00025_29638_4729.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071031_144438_000004952063_00025_29638_4823.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071031_150137_000002892063_00025_29638_4827.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071031_152127_000000962063_00025_29638_4825.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071031_152646_000001872063_00025_29638_4829.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071031_153237_000000902063_00025_29638_4834.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071031_160144_000006582063_00026_29639_4843.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071031_162239_000008272063_00026_29639_4949.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071031_170837_000002892063_00026_29639_4951.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071031_174520_000003502063_00027_29640_4961.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071031_174950_000001752063_00027_29640_5075.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071031_180156_000001082063_00027_29640_5073.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071031_180441_000003862063_00027_29640_5077.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071031_184928_000005492063_00027_29640_5082.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071031_191547_000001322063_00028_29641_5084.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071031_192012_000004342063_00028_29641_5086.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071031_192838_000001992063_00028_29641_5096.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071031_193043_000002592063_00028_29641_5188.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071031_193647_000001202063_00028_29641_5190.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071031_194117_000003202063_00028_29641_5192.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071031_194746_000001082063_00028_29641_5194.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071031_203625_000001692063_00028_29641_5196.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071031_204650_000011482063_00028_29641_5285.N1					OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_IMM_1PNPDE20071031_012551_000000542063_00017_29630_8244.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20071031_025033_000000372063_00018_29631_8507.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20071031_030816_000000802063_00018_29631_8421.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20071031_040935_000000542063_00018_29631_8645.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20071031_060233_000000952063_00020_29633_8998.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20071031_062758_000000502063_00020_29633_8986.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20071031_062934_000000932063_00020_29633_8996.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20071031_081719_000001082063_00021_29634_8881.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20071031_104134_000000362063_00022_29635_8936.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20071031_113748_000000812063_00023_29636_8943.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20071031_141923_000000622063_00025_29638_9022.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20071031_141923_000000802063_00025_29638_9045.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20071031_142935_000000652063_00025_29638_9043.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20071031_174143_000001992063_00027_29640_9120.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20071031_180346_000000372063_00027_29640_9080.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20071031_181228_000001392063_00027_29640_9136.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20071031_191801_000001132063_00028_29641_9176.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20071031_191903_000000512063_00028_29641_9168.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20071031_062010_000002402063_00020_29633_4229.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20071031_075830_000000512063_00021_29634_4257.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20071031_093836_000003962063_00022_29635_4438.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20071031_094840_000000802063_00022_29635_4419.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20071031_111857_000001552063_00023_29636_4541.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20071031_123942_000000352063_00024_29637_4646.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20071031_143351_000000662063_00025_29638_4797.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20071031_161242_000003522063_00026_29639_4935.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20071031_175248_000003522063_00027_29640_5048.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20071031_210826_000001252063_00029_29642_5287.N1					OK	OK	OK	OK


Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WSM_1PNPDE20071031_001644_000005452063_00016_29629_8378.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071031_015639_000005372063_00017_29630_8502.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071031_020616_000000672063_00017_29630_8386.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071031_020616_000002612063_00017_29630_8772.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071031_020824_000001332063_00017_29630_8423.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071031_023546_000000912063_00018_29631_8509.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071031_023732_000002132063_00018_29631_8542.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071031_030954_000000672063_00018_29631_8494.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071031_033715_000003852063_00018_29631_8544.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071031_034452_000001282063_00018_29631_8691.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071031_034452_000004762063_00018_29631_8770.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071031_034755_000002932063_00018_29631_8692.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071031_051706_000003672063_00019_29632_8711.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071031_052351_000005742063_00019_29632_8886.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071031_070027_000001402063_00020_29633_8846.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071031_101754_000000852063_00022_29635_8912.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071031_101901_000000182063_00022_29635_8902.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071031_101938_000003062063_00022_29635_8960.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071031_101938_000005392063_00022_29635_8982.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071031_102545_000001722063_00022_29635_8961.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071031_102809_000000912063_00022_29635_8958.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071031_103015_000002932063_00022_29635_8964.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071031_115829_000004472063_00023_29636_8984.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071031_134336_000001592063_00024_29637_9068.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071031_134336_000001592063_00024_29637_9076.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071031_145301_000001032063_00025_29638_9072.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071031_152312_000002022063_00025_29638_9074.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071031_152312_000002022063_00025_29638_9126.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071031_153003_000001472063_00025_29638_9016.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071031_153416_000002022063_00025_29638_9070.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071031_170403_000002632063_00026_29639_9124.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071031_171339_000003422063_00026_29639_9122.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071031_184154_000004462063_00027_29640_9154.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071031_203047_000001462063_00028_29641_9162.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20071031_061755_000000852063_00020_29633_4231.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20071031_070704_000003352063_00020_29633_4318.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20071031_074701_000000852063_00021_29634_4316.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20071031_120751_000005022063_00023_29636_4689.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20071031_143555_000005142063_00025_29638_4841.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20071031_162002_000001472063_00026_29639_4947.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20071031_175935_000001282063_00027_29640_5050.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20071031_193513_000000852063_00028_29641_5172.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20071031_193856_000001282063_00028_29641_5177.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20071031_211740_000001832063_00029_29642_5306.N1					OK	OK	OK	OK


Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WVS_1PNPDE20071031_000858_000003752063_00016_29629_8145.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20071031_003320_000001952063_00016_29629_8142.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20071031_003535_000005692063_00016_29629_8273.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20071031_004814_000009742063_00016_29629_8288.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20071031_012955_000008682063_00017_29630_8298.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20071031_014823_000004502063_00017_29630_8295.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20071031_021238_000001342063_00017_29630_8303.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20071031_021353_000003002063_00017_29630_8435.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20071031_031627_000007792063_00018_29631_8443.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20071031_032857_000002852063_00018_29631_8552.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20071031_035801_000006592063_00018_29631_8547.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20071031_041035_000001642063_00019_29632_8560.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20071031_045728_000007942063_00019_29632_8595.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20071031_051013_000003602063_00019_29632_8725.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20071031_053341_000008552063_00019_29632_8758.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20071031_064105_000005992063_00020_29633_8776.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20071031_065035_000004202063_00020_29633_4238.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20071031_071426_000019042063_00020_29633_4250.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20071031_082951_000004952063_00021_29634_4329.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20071031_085502_000020392063_00021_29634_4334.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20071031_100120_000009442063_00022_29635_4452.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20071031_103529_000003302063_00022_29635_4455.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20071031_104216_000014392063_00022_29635_4465.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20071031_112503_000007192063_00023_29636_4553.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20071031_113916_000011092063_00023_29636_4558.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20071031_121615_000004202063_00023_29636_4563.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20071031_122738_000006592063_00023_29636_4568.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20071031_124024_000002542063_00024_29637_4576.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20071031_130646_000008842063_00024_29637_4706.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20071031_135649_000004202063_00024_29637_4711.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20071031_140933_000005542063_00024_29637_4727.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20071031_150628_000008542063_00025_29638_4832.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20071031_153740_000013192063_00025_29638_4847.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20071031_164007_000012742063_00026_29639_4959.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20071031_171920_000013042063_00026_29639_4969.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20071031_181533_000015292063_00027_29640_5080.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20071031_190210_000007642063_00027_29640_5089.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20071031_194935_000019642063_00028_29641_5199.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20071031_203913_000004052063_00028_29641_5207.N1					OK	OK	OK	OK


Calibration pulses for GM1 SS3 H/H




Calibration pulses for GM1 SS3 H/H




Calibration pulses for GM1 SS3 H/H




Calibration pulses for GM1 SS3 H/H




Calibration pulses for WVS IS2 V/V




Calibration pulses for WVS IS2 V/V





Calibration pulses for WVS IS2 V/V







Calibration pulses for WVS IS2 V/V















































Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_APM_1PNPDE20071031_012707_000000532063_00017_29630_8268.N1						IS3	H/H	63	29630	17	4.04
ASA_APM_1PNPDE20071031_024156_000000432063_00018_29631_8505.N1						IS2	H/H	63	29631	18	4.04
ASA_APM_1PNPDE20071031_045142_000000422063_00019_29632_8647.N1						IS2	H/H	63	29632	19	4.04
ASA_APM_1PNPDK20071031_124525_000001012063_00024_29637_4652.N1						IS1	H/H	63	29637	24	4.05
ASA_APM_1PNPDE20071031_160036_000000422063_00026_29639_9078.N1						IS4	H/H	63	29639	26	4.05
ASA_APM_1PNPDE20071031_181111_000000422063_00027_29640_9128.N1						IS4	H/H	63	29640	27	4.05
ASA_APM_1PNPDE20071031_194637_000000412063_00028_29641_9164.N1						IS6	H/H	63	29641	28	4.05


Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_IMM_1PNPDE20071031_012551_000000542063_00017_29630_8244.N1						IS2	V/V	63	29630	17	4.04
ASA_IMM_1PNPDE20071031_025033_000000372063_00018_29631_8507.N1						IS2	V/V	63	29631	18	4.04
ASA_IMM_1PNPDE20071031_030816_000000802063_00018_29631_8421.N1						IS2	V/V	63	29631	18	4.04
ASA_IMM_1PNPDE20071031_040935_000000542063_00018_29631_8645.N1						IS2	V/V	63	29631	18	4.04
ASA_IMM_1PNPDE20071031_060233_000000952063_00020_29633_8998.N1						IS6	V/V	63	29633	20	4.05
ASA_IMM_1PNPDK20071031_062010_000002402063_00020_29633_4229.N1						IS2	V/V	63	29633	20	4.05
ASA_IMM_1PNPDE20071031_062758_000000502063_00020_29633_8986.N1						IS7	V/V	63	29633	20	4.05
ASA_IMM_1PNPDE20071031_062934_000000932063_00020_29633_8996.N1						IS2	V/V	63	29633	20	4.05
ASA_IMM_1PNPDK20071031_075830_000000512063_00021_29634_4257.N1						IS2	V/V	63	29634	21	4.05
ASA_IMM_1PNPDE20071031_081719_000001082063_00021_29634_8881.N1						IS4	H/H	63	29634	21	4.04
ASA_IMM_1PNPDK20071031_093836_000003962063_00022_29635_4438.N1						IS2	V/V	63	29635	22	4.05
ASA_IMM_1PNPDK20071031_094840_000000802063_00022_29635_4419.N1						IS2	V/V	63	29635	22	4.05
ASA_IMM_1PNPDE20071031_104134_000000362063_00022_29635_8936.N1						IS2	V/V	63	29635	22	4.05
ASA_IMM_1PNPDK20071031_111857_000001552063_00023_29636_4541.N1						IS2	V/V	63	29636	23	4.05
ASA_IMM_1PNPDE20071031_113748_000000812063_00023_29636_8943.N1						IS2	V/V	63	29636	23	4.05
ASA_IMM_1PNPDK20071031_123942_000000352063_00024_29637_4646.N1						IS5	H/H	63	29637	24	4.05
ASA_IMM_1PNPDE20071031_141923_000000622063_00025_29638_9022.N1						IS2	V/V	63	29638	25	4.05
ASA_IMM_1PNPDE20071031_141923_000000802063_00025_29638_9045.N1						IS2	V/V	63	29638	25	4.05
ASA_IMM_1PNPDE20071031_142935_000000652063_00025_29638_9043.N1						IS2	V/V	63	29638	25	4.05
ASA_IMM_1PNPDK20071031_143351_000000662063_00025_29638_4797.N1						IS2	V/V	63	29638	25	4.05
ASA_IMM_1PNPDK20071031_161242_000003522063_00026_29639_4935.N1						IS2	V/V	63	29639	26	4.05
ASA_IMM_1PNPDE20071031_174143_000001992063_00027_29640_9120.N1						IS6	V/V	63	29640	27	4.05
ASA_IMM_1PNPDK20071031_175248_000003522063_00027_29640_5048.N1						IS2	V/V	63	29640	27	4.05
ASA_IMM_1PNPDE20071031_180346_000000372063_00027_29640_9080.N1						IS1	H/H	63	29640	27	4.05
ASA_IMM_1PNPDE20071031_181228_000001392063_00027_29640_9136.N1						IS2	V/V	63	29640	27	4.05
ASA_IMM_1PNPDE20071031_191801_000001132063_00028_29641_9176.N1						IS2	V/V	63	29641	28	4.05
ASA_IMM_1PNPDE20071031_191903_000000512063_00028_29641_9168.N1						IS2	V/V	63	29641	28	4.05
ASA_IMM_1PNPDK20071031_210826_000001252063_00029_29642_5287.N1						IS2	V/V	63	29642	29	4.05


Filename	Pol	Timestamp	count(Module)
ASA_MS__0PNPDK20071031_170155_000000162063_00026_29639_0404.N1	V	2007-10-31 17:01:55	320





Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WSM_1PNPDE20071031_001644_000005452063_00016_29629_8378.N1						SS1	H/H	63	29629	16	4.04
ASA_WSM_1PNPDE20071031_015639_000005372063_00017_29630_8502.N1						SS1	H/H	63	29630	17	4.04
ASA_WSM_1PNPDE20071031_020616_000002612063_00017_29630_8772.N1						SS1	H/H	63	29630	17	4.04
ASA_WSM_1PNPDE20071031_020616_000000672063_00017_29630_8386.N1						SS1	H/H	63	29630	17	4.04
ASA_WSM_1PNPDE20071031_020824_000001332063_00017_29630_8423.N1						SS1	H/H	63	29630	17	4.04
ASA_WSM_1PNPDE20071031_023546_000000912063_00018_29631_8509.N1						SS1	V/V	63	29631	18	4.04
ASA_WSM_1PNPDE20071031_023732_000002132063_00018_29631_8542.N1						SS1	V/V	63	29631	18	4.04
ASA_WSM_1PNPDE20071031_030954_000000672063_00018_29631_8494.N1						SS1	V/V	63	29631	18	4.04
ASA_WSM_1PNPDE20071031_033715_000003852063_00018_29631_8544.N1						SS1	H/H	63	29631	18	4.04
ASA_WSM_1PNPDE20071031_034452_000001282063_00018_29631_8691.N1						SS1	H/H	63	29631	18	4.04
ASA_WSM_1PNPDE20071031_034452_000004762063_00018_29631_8770.N1						SS1	H/H	63	29631	18	4.04
ASA_WSM_1PNPDE20071031_034755_000002932063_00018_29631_8692.N1						SS1	H/H	63	29631	18	4.04
ASA_WSM_1PNPDE20071031_051706_000003672063_00019_29632_8711.N1						SS1	H/H	63	29632	19	4.04
ASA_WSM_1PNPDE20071031_052351_000005742063_00019_29632_8886.N1						SS1	H/H	63	29632	19	4.04
ASA_WSM_1PNPDK20071031_061755_000000852063_00020_29633_4231.N1						SS1	H/H	63	29633	20	4.05
ASA_WSM_1PNPDE20071031_070027_000001402063_00020_29633_8846.N1						SS1	H/H	63	29633	20	4.04
ASA_WSM_1PNPDK20071031_070704_000003352063_00020_29633_4318.N1						SS1	H/H	63	29633	20	4.05
ASA_WSM_1PNPDK20071031_074701_000000852063_00021_29634_4316.N1						SS1	V/V	63	29634	21	4.05
ASA_WSM_1PNPDE20071031_101754_000000852063_00022_29635_8912.N1						SS1	H/H	63	29635	22	4.05
ASA_WSM_1PNPDE20071031_101901_000000182063_00022_29635_8902.N1						SS1	H/H	63	29635	22	4.05
ASA_WSM_1PNPDE20071031_101938_000003062063_00022_29635_8960.N1						SS1	H/H	63	29635	22	4.05
ASA_WSM_1PNPDE20071031_101938_000005392063_00022_29635_8982.N1						SS1	H/H	63	29635	22	4.05
ASA_WSM_1PNPDE20071031_102545_000001722063_00022_29635_8961.N1						SS1	H/H	63	29635	22	4.05
ASA_WSM_1PNPDE20071031_102809_000000912063_00022_29635_8958.N1						SS1	H/H	63	29635	22	4.05
ASA_WSM_1PNPDE20071031_103015_000002932063_00022_29635_8964.N1						SS1	H/H	63	29635	22	4.05
ASA_WSM_1PNPDE20071031_115829_000004472063_00023_29636_8984.N1						SS1	H/H	63	29636	23	4.05
ASA_WSM_1PNPDK20071031_120751_000005022063_00023_29636_4689.N1						SS1	H/H	63	29636	23	4.05
ASA_WSM_1PNPDE20071031_134336_000001592063_00024_29637_9068.N1						SS1	H/H	63	29637	24	4.05
ASA_WSM_1PNPDE20071031_134336_000001592063_00024_29637_9076.N1						SS1	H/H	63	29637	24	4.05
ASA_WSM_1PNPDK20071031_143555_000005142063_00025_29638_4841.N1						SS1	H/H	63	29638	25	4.05
ASA_WSM_1PNPDE20071031_145301_000001032063_00025_29638_9072.N1						SS1	V/V	63	29638	25	4.05
ASA_WSM_1PNPDE20071031_152312_000002022063_00025_29638_9074.N1						SS1	H/H	63	29638	25	4.05
ASA_WSM_1PNPDE20071031_152312_000002022063_00025_29638_9126.N1						SS1	H/H	63	29638	25	4.05
ASA_WSM_1PNPDE20071031_153003_000001472063_00025_29638_9016.N1						SS1	H/H	63	29638	25	4.05
ASA_WSM_1PNPDE20071031_153416_000002022063_00025_29638_9070.N1						SS1	H/H	63	29638	25	4.05
ASA_WSM_1PNPDK20071031_162002_000001472063_00026_29639_4947.N1						SS1	H/H	63	29639	26	4.05
ASA_WSM_1PNPDE20071031_170403_000002632063_00026_29639_9124.N1						SS1	H/H	63	29639	26	4.05
ASA_WSM_1PNPDE20071031_171339_000003422063_00026_29639_9122.N1						SS1	H/H	63	29639	26	4.05
ASA_WSM_1PNPDK20071031_175935_000001282063_00027_29640_5050.N1						SS1	H/H	63	29640	27	4.05
ASA_WSM_1PNPDE20071031_184154_000004462063_00027_29640_9154.N1						SS1	H/H	63	29640	27	4.05
ASA_WSM_1PNPDK20071031_193513_000000852063_00028_29641_5172.N1						SS1	V/V	63	29641	28	4.05
ASA_WSM_1PNPDE20071031_203047_000001462063_00028_29641_9162.N1						SS1	H/H	63	29641	28	4.05




Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WVS_1PNPDE20071030_234439_000009892063_00016_29629_8129.N1						IS2	V/V	63	29629	16	4.04
ASA_WVS_1PNPDE20071031_000858_000003752063_00016_29629_8145.N1						IS2	V/V	63	29629	16	4.04
ASA_WVS_1PNPDE20071031_003320_000001952063_00016_29629_8142.N1						IS2	V/V	63	29629	16	4.04
ASA_WVS_1PNPDE20071031_003535_000005692063_00016_29629_8273.N1						IS2	V/V	63	29629	16	4.04
ASA_WVS_1PNPDE20071031_004814_000009742063_00016_29629_8288.N1						IS2	V/V	63	29629	16	4.04
ASA_WVS_1PNPDE20071031_012955_000008682063_00017_29630_8298.N1						IS2	V/V	63	29630	17	4.04
ASA_WVS_1PNPDE20071031_014823_000004502063_00017_29630_8295.N1						IS2	V/V	63	29630	17	4.04
ASA_WVS_1PNPDE20071031_021238_000001342063_00017_29630_8303.N1						IS2	V/V	63	29630	17	4.04
ASA_WVS_1PNPDE20071031_021353_000003002063_00017_29630_8435.N1						IS2	V/V	63	29630	17	4.04
ASA_WVS_1PNPDE20071031_021238_000001342063_00017_29630_8303.N1						IS1	V/V	63	29630	17	4.04
ASA_WVS_1PNPDE20071031_031627_000007792063_00018_29631_8443.N1						IS2	V/V	63	29631	18	4.04
ASA_WVS_1PNPDE20071031_032857_000002852063_00018_29631_8552.N1						IS2	V/V	63	29631	18	4.04
ASA_WVS_1PNPDE20071031_035801_000006592063_00018_29631_8547.N1						IS2	V/V	63	29631	18	4.04
ASA_WVS_1PNPDE20071031_041035_000001642063_00019_29632_8560.N1						IS2	V/V	63	29632	19	4.04
ASA_WVS_1PNPDE20071031_045728_000007942063_00019_29632_8595.N1						IS2	V/V	63	29632	19	4.04
ASA_WVS_1PNPDE20071031_051013_000003602063_00019_29632_8725.N1						IS2	V/V	63	29632	19	4.04
ASA_WVS_1PNPDE20071031_045728_000007942063_00019_29632_8595.N1						IS1	V/V	63	29632	19	4.04
ASA_WVS_1PNPDE20071031_053341_000008552063_00019_29632_8758.N1						IS2	V/V	63	29632	19	4.04
ASA_WVS_1PNPDE20071031_064105_000005992063_00020_29633_8776.N1						IS2	V/V	63	29633	20	4.04
ASA_WVS_1PNPDK20071031_065035_000004202063_00020_29633_4238.N1						IS2	V/V	63	29633	20	4.05
ASA_WVS_1PNPDK20071031_071426_000019042063_00020_29633_4250.N1						IS2	V/V	63	29633	20	4.05
ASA_WVS_1PNPDK20071031_082951_000004952063_00021_29634_4329.N1						IS2	V/V	63	29634	21	4.05
ASA_WVS_1PNPDK20071031_085502_000020392063_00021_29634_4334.N1						IS2	V/V	63	29634	21	4.05
ASA_WVS_1PNPDK20071031_100120_000009442063_00022_29635_4452.N1						IS2	V/V	63	29635	22	4.05
ASA_WVS_1PNPDK20071031_103529_000003302063_00022_29635_4455.N1						IS2	V/V	63	29635	22	4.05
ASA_WVS_1PNPDK20071031_104216_000014392063_00022_29635_4465.N1						IS2	V/V	63	29635	22	4.05
ASA_WVS_1PNPDK20071031_112503_000007192063_00023_29636_4553.N1						IS2	V/V	63	29636	23	4.05
ASA_WVS_1PNPDK20071031_113916_000011092063_00023_29636_4558.N1						IS2	V/V	63	29636	23	4.05
ASA_WVS_1PNPDK20071031_121615_000004202063_00023_29636_4563.N1						IS2	V/V	63	29636	23	4.05
ASA_WVS_1PNPDK20071031_122738_000006592063_00023_29636_4568.N1						IS2	V/V	63	29636	23	4.05
ASA_WVS_1PNPDK20071031_124024_000002542063_00024_29637_4576.N1						IS2	V/V	63	29637	24	4.05
ASA_WVS_1PNPDK20071031_130646_000008842063_00024_29637_4706.N1						IS2	V/V	63	29637	24	4.05
ASA_WVS_1PNPDK20071031_135649_000004202063_00024_29637_4711.N1						IS2	V/V	63	29637	24	4.05
ASA_WVS_1PNPDK20071031_140933_000005542063_00024_29637_4727.N1						IS2	V/V	63	29637	24	4.05
ASA_WVS_1PNPDK20071031_150628_000008542063_00025_29638_4832.N1						IS2	V/V	63	29638	25	4.05
ASA_WVS_1PNPDK20071031_153740_000013192063_00025_29638_4847.N1						IS2	V/V	63	29638	25	4.05
ASA_WVS_1PNPDK20071031_164007_000012742063_00026_29639_4959.N1						IS2	V/V	63	29639	26	4.05
ASA_WVS_1PNPDK20071031_171920_000013042063_00026_29639_4969.N1						IS2	V/V	63	29639	26	4.05
ASA_WVS_1PNPDK20071031_181533_000015292063_00027_29640_5080.N1						IS2	V/V	63	29640	27	4.05
ASA_WVS_1PNPDK20071031_190210_000007642063_00027_29640_5089.N1						IS2	V/V	63	29640	27	4.05
ASA_WVS_1PNPDK20071031_194935_000019642063_00028_29641_5199.N1						IS2	V/V	63	29641	28	4.05
ASA_WVS_1PNPDK20071031_203913_000004052063_00028_29641_5207.N1						IS2	V/V	63	29641	28	4.05



















































31-Oct





31-Oct




31-Oct








31-Oct



31-Oct



31-Oct

