



ASAR Daily Report



Analysis from 27-DEC-2007 00:00:00 to 27-DEC-2007 23:59:59. Page generated on 28-DEC-2007 08:51:18.
View log file: ASAR_Daily_Report_20071228_0730.log. For any anomalies please contact mtranfaglia@serco.it, gscarpino@serco.it.

This report is automatically generated every day, every 2 hours. No comments are provided on the results.

SUMMARY

1. DATA SUMMARY
 - 1.1 Summary tables
 - 1.2 Lists of products used
2. AUXILIARY FILES ANALYSIS
 - 2.1 IECF operational ADFs list
 - 2.2 Products with wrong ADFs
3. MODULE STEPPING PRODUCTS ANALYSIS
 - 3.1 V/V polarisation
 - 3.2 H/H polarisation
4. CALIBRATION PULSES ANALYSIS
 - 4.1 Analysis for WVS IS2 V/V
 - 4.1.1 Temporal Evolution Analysis for WVS IS2 V/V
 - 4.1.2 All Rows Analysis for WVS IS2 V/V
 - 4.2 Analysis for GM1 SS3 H/H
 - 4.2.1 Temporal Evolution Analysis for GM1 SS3 H/H
 - 4.2.2 All Rows Analysis for GM1 SS3 H/H
5. DOPPLER ANALYSIS
 - 5.1 Analysis for WVS IS2 V/V
 - 5.1.1 Doppler MAP Analysis for WVS IS2 V/V
 - 5.1.2 Doppler ANX Analysis for WVS IS2 V/V
 - 5.2 Analysis for GM1 SS1 H/H
 - 5.2.1 Doppler MAP Analysis for GM1 SS1 H/H
 - 5.2.2 Doppler ANX Analysis for GM1 SS1 H/H
 - 5.3 Doppler JUMPS Analysis for WSM
6. CHIRP ANALYSIS
 - 6.1 Analysis for WSM SS1 H/H
 - 6.1.1 ScaleFactor
 - 6.2 Analysis for WSM SS1 V/V
 - 6.2.1 ScaleFactor
7. RAW DATA ANALYSIS
 - 7.1 Analysis for WVS
 - 7.2 Analysis for IMM
8. TELEMETRY ANALYSIS
 - 8.1 Number of Missing Lines
 - 8.2 Number of Gaps

1 - DATA SUMMARY

1.1 - Summary tables

[[BACK TO MENU](#)]

WVS				GM1				APM				IMM				WSM				MS			
Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Time	Pol	Modules
PDE	IS1	V/V	3	PDE	WS	H/H	39	PDE	IS2	H/H	3	PDE	IS2	H/H	3	PDE	WS	H/H	52	PDK	2007-12-27 07:06:55	H	320
PDE	IS2	V/V	31	PDK	WS	H/H	44					PDE	IS2	V/V	9	PDE	WS	V/V	9				
PDK	IS2	V/V	22									PDE	IS3	H/H	1	PDK	WS	H/H	10				
												PDE	IS3	V/V	1	PDK	WS	V/V	2				
												PDE	IS6	***	2								
												PDE	IS6	H/H	7								
												PDE	IS6	V/V	4								
												PDE	IS7	H/H	1								
												PDK	IS1	V/V	1								
												PDK	IS2	H/H	1								
												PDK	IS2	V/V	15								
												PDK	IS3	V/V	1								

1.2 - Lists of products used

[BACK TO MENU]

[TXT] [XLS] List_WVS_products_used
 [TXT] [XLS] List_GM1_products_used
 [TXT] [XLS] List_APM_products_used
 [TXT] [XLS] List_IMM_products_used
 [TXT] [XLS] List_WSM_products_used
 [TXT] [XLS] List_MS_products_used

2 - AUXILIARY FILES ANALYSIS

2.1 - IECF operational ADFs list

[BACK TO MENU]

ADFs disseminated for ASAR
ASA_CON_AXVIEC20071218_084201_20070204_165113_20081231_000000
ASA_INS_AXVIEC20071218_083603_20070307_060000_20081231_000000
ASA_XCH_AXVIEC20051219_162547_20020301_000000_20081231_000000
ASA_XCA_AXVIEC20071218_082742_20070204_165113_20081231_000000





2.2 - Products with wrong ADFs

[BACK TO MENU]

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
WVS	0	0	0	0
GM1	0	0	0	0
APM	0	0	0	0
IMM	0	0	0	0
WSM	0	0	0	0

3 - MODULE STEPPING PRODUCTS ANALYSIS














3.2 - H/H polarisation

[[BACK TO MENU](#)]

SECOND FIXED REFERENCE	PREVIOUS PRODUCT REFERENCE
After antenna maintenance (2005-09-22/23)	Previous product in the same polarisation





4 - CALIBRATION PULSES ANALYSIS

4.1 - Analysis for WVS IS2 V/V


4.1.1 - Temporal Evolution Analysis for WVS IS2 V/V

[BACK TO MENU]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]


Calibration pulses for WVS IS2 V/V




27-Dec



27-Dec




27-Dec



27-Dec


rows: - 1 - 5 - 9 - 13 - 17 - 21 - 25 - 29

Transmit power (P1 - P1a) for WVS IS2 V/V



27-Dec

Transmit power (P1 - P1a) for WVS IS2 V/V




27-Dec

rows: - 1 - 5 - 9 - 13 - 17 - 21 - 25 - 29

4.1.2 - All Rows Analysis for WVS IS2 V/V

[[BACK TO MENU](#)]





4.2 - Analysis for GM1 SS3 H/H


4.2.1 - Temporal Evolution Analysis for GM1 SS3 H/H

[BACK TO MENU]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Calibration pulses for GM1 SS3 H/H




Transmit power (P1 - P1a) for GM1 SS3 H/H



4.2.2 - All Rows Analysis for GM1 SS3 H/H

[BACK TO MENU]






5 - DOPPLER ANALYSIS

5.1 - Analysis for WVS IS2 V/V

5.1.1 - Doppler MAP Analysis for WVS IS2 V/V

[[BACK TO MENU](#)]






5.1.2 - Doppler ANX Analysis for WVS IS2 V/V

[[BACK TO MENU](#)]






5.2 - Analysis for GM1 SS1 H/H

5.2.1 - Doppler MAP Analysis for GM1 SS1 H/H

[[BACK TO MENU](#)]






5.2.2 - Doppler ANX Analysis for GM1 SS1 H/H


[[BACK TO MENU](#)]






5.3 - Doppler JUMPS Analysis for WSM

[[BACK TO MENU](#)]







6 - CHIRP ANALYSIS

6.1 - Analysis for WSM SS1 H/H

6.1.1 - ScaleFactor

[[BACK TO MENU](#)]







6.2 - Analysis for WSM SS1 V/V

6.2.1 - ScaleFactor

[[BACK TO MENU](#)]






7 - RAW DATA ANALYSIS

7.1 - Analysis for WVS

[[BACK TO MENU](#)]

--	--	--




Channel	Statistics	DSS-B
MEAN I	mean	0.000543234
	stdev	1.68232e-07
MEAN Q	mean	0.000513814
	stdev	2.16896e-07
Channel	Statistics	DSS-B
STDEV I	mean	0.139510
	stdev	0.00113050
STDEV Q	mean	0.139917
	stdev	0.00115108

7.2 - Analysis for IMM

[[BACK TO MENU](#)]

--	--	--





8 - TELEMETRY ANALYSIS

Processing Center	Product	Gaps	Missing lines
PDE	ASA_IMM_1PNPDE20071227_175125_00000612064_00342_30456_4063.N1	1	0
PDE	ASA_IMM_1PNPDE20071227_175125_00000812064_00342_30456_4089.N1	1	0
PDK	ASA_IMM_1PNPDK20071227_125052_00000342064_00339_30453_8498.N1	1	0

8.1 - Number of Missing lines


[BACK TO MENU]





8.2 - Number of Gaps

[[BACK TO MENU](#)]



ASAR DAILY REPORT for 071227
#####

MODE: DAILY
ANALYSIS: ALL
DATE: YESTERDAY

Analysis will be performed from 2007-12-27 00:00:00 to 2007-12-27 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/071227/

DATA SUMMARY

Summary will be performed from 2007-12-27 00:00:00 to 2007-12-27 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/071227/DATA_SUMMARY

Creating directory ./RESULTS/DAILY/071227/DATA_SUMMARY...
Writing file ./RESULTS/DAILY/071227/DATA_SUMMARY/Data_summary.html...

Getting WVS products list from 2007-12-27 00:00:00 to 2007-12-27 23:59:59...
Writing file ./RESULTS/DAILY/071227/DATA_SUMMARY/List_WVS_products_used.xls...
Writing file ./RESULTS/DAILY/071227/DATA_SUMMARY/List_WVS_products_used.txt...

Getting GM1 products list from 2007-12-27 00:00:00 to 2007-12-27 23:59:59...
Writing file ./RESULTS/DAILY/071227/DATA_SUMMARY/List_GM1_products_used.xls...
Writing file ./RESULTS/DAILY/071227/DATA_SUMMARY/List_GM1_products_used.txt...

Getting APM products list from 2007-12-27 00:00:00 to 2007-12-27 23:59:59...
Writing file ./RESULTS/DAILY/071227/DATA_SUMMARY/List_APM_products_used.xls...
Writing file ./RESULTS/DAILY/071227/DATA_SUMMARY/List_APM_products_used.txt...

Getting IMM products list from 2007-12-27 00:00:00 to 2007-12-27 23:59:59...
Writing file ./RESULTS/DAILY/071227/DATA_SUMMARY/List_IMM_products_used.xls...
Writing file ./RESULTS/DAILY/071227/DATA_SUMMARY/List_IMM_products_used.txt...

Getting WSM products list from 2007-12-27 00:00:00 to 2007-12-27 23:59:59...
Writing file ./RESULTS/DAILY/071227/DATA_SUMMARY/List_WSM_products_used.xls...
Writing file ./RESULTS/DAILY/071227/DATA_SUMMARY/List_WSM_products_used.txt...

Getting MS products list from 2007-12-27 00:00:00 to 2007-12-27 23:59:59...
Writing file ./RESULTS/DAILY/071227/DATA_SUMMARY/List_MS_products_used.xls...
Writing file ./RESULTS/DAILY/071227/DATA_SUMMARY/List_MS_products_used.txt...

DATA SUMMARY completed
#####

AUXILIARY FILES ANALYSIS

Analysis will be performed from 2007-12-27 00:00:00 to 2007-12-27 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/071227/AUXILIARY

Creating directory ./RESULTS/DAILY/071227/AUXILIARY...

Looking for the IECF operational ADFs list...



Found list 20071227_030004_current_3_IECF_ADFs.txt...
Extracting ADFs...

ASA_CON_AXVIEC20071218_084201_20070204_165113_20081231_000000
ASA_INS_AXVIEC20071218_083603_20070307_060000_20081231_000000
ASA_XCH_AXVIEC20051219_162547_20020301_000000_20081231_000000
ASA_XCA_AXVIEC20071218_082742_20070204_165113_20081231_000000

Writing file ./RESULTS/DAILY/071227/AUXILIARY/ASAR_ADFs_IECF_List3.html...
Writing file ./RESULTS/DAILY/071227/AUXILIARY/Auxiliary_files_summary.html...

Analysing WVS products...

Writing file ./RESULTS/DAILY/071227/AUXILIARY/Check_ADFs_WVS.xls...
Writing file ./RESULTS/DAILY/071227/AUXILIARY/Check_ADFs_WVS.txt...

ASA_WVS_1PNPDE20071227_001914_000002702064_00331_30445_3151.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20071227_004155_000003152064_00331_30445_3154.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20071227_004625_000003742064_00331_30445_3286.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20071227_005658_000009442064_00331_30445_3289.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20071227_014214_000003142064_00332_30446_3292.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20071227_014859_000002542064_00332_30446_3295.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20071227_015719_000003152064_00332_30446_3306.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20071227_022113_000000442064_00332_30446_3311.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20071227_022113_000003302064_00332_30446_3474.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20071227_024132_000002392064_00333_30447_3471.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20071227_032433_000008242064_00333_30447_3477.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20071227_033748_000002402064_00333_30447_3564.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20071227_040535_000010042064_00333_30447_3583.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20071227_050501_000009292064_00334_30448_3618.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20071227_052016_000002102064_00334_30448_3730.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20071227_054344_000015142064_00334_30448_3765.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20071227_065025_000001042064_00335_30449_3770.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20071227_065503_000002692064_00335_30449_3786.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20071227_195803_000005992064_00343_30457_4143.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20071227_200951_000011692064_00343_30457_4156.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20071227_204749_000000742064_00343_30457_4164.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20071227_204804_000002252064_00343_30457_4290.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20071227_213830_000004042064_00344_30458_4293.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20071227_214735_000009442064_00344_30458_4296.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20071227_220516_000002702064_00344_30458_4303.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20071227_222943_000002702064_00344_30458_4310.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20071227_223313_000007492064_00344_30458_4447.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20071227_225314_000005692064_00345_30459_4452.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20071227_231911_000012742064_00345_30459_4472.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20071227_234658_000002102064_00345_30459_4467.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20071227_065903_000003302064_00335_30449_8092.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20071227_072302_000019642064_00335_30449_8102.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20071227_083729_000004652064_00336_30450_8176.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20071227_090337_000020242064_00336_30450_8181.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20071227_101001_000010492064_00337_30451_8300.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20071227_104532_000017542064_00337_30451_8305.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20071227_113339_000019492064_00338_30452_8413.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20071227_122449_000003752064_00338_30452_8408.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20071227_123746_000007442064_00338_30452_8416.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20071227_125134_000000892064_00339_30453_8421.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20071227_131538_000008542064_00339_30453_8542.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20071227_140525_000002852064_00339_30453_8551.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20071227_141737_000002092064_00339_30453_8554.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20071227_142228_000002842064_00339_30453_8559.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20071227_150155_000016342064_00340_30454_8670.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20071227_154719_000006002064_00340_30454_8667.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20071227_160051_000004342064_00340_30454_8686.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20071227_164837_000011692064_00341_30455_8799.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20071227_172637_000013942064_00341_30455_8811.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

```
ASA_WVS_1PNPDK20071227_182359_000014842064_00342_30456_8917.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20071227_190713_000005252064_00342_30456_8920.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20071227_191917_000002242064_00342_30456_8932.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```

Analysing GM1 products...

Writing file ./RESULTS/DAILY/071227/AUXILIARY/Check_ADFs_GM1.xls...

Writing file ./RESULTS/DAILY/071227/AUXILIARY/Check_ADFs_GM1.txt...

```
ASA_GM1_1PNPDE20071227_001052_000003922064_00331_30445_3148.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071227_002439_000006822064_00331_30445_3156.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071227_005334_000002052064_00331_30445_3283.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071227_012015_000010882064_00332_30446_3385.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071227_020803_000007852064_00332_30446_3308.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071227_022727_000004832064_00332_30446_3523.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071227_023703_000002652064_00332_30446_3517.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071227_025126_000004592064_00333_30447_3521.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071227_030000_000003382064_00333_30447_3519.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071227_030857_000007492064_00333_30447_3525.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071227_032217_000001322064_00333_30447_3515.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071227_035139_000000962064_00333_30447_3561.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071227_040246_000001692064_00333_30447_3566.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071227_042302_000010022064_00334_30448_3626.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071227_044330_000008152064_00334_30448_3576.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071227_045801_000001082064_00334_30448_3574.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071227_050059_000002412064_00334_30448_3615.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071227_052816_000001932064_00334_30448_3732.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071227_060951_000001322064_00335_30449_3734.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071227_061308_000007912064_00335_30449_3736.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071227_063154_000002712064_00335_30449_3762.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071227_064011_000006102064_00335_30449_3767.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071227_065306_000001142064_00335_30449_3778.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071227_193908_000001442064_00343_30457_4140.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071227_194318_000002352064_00343_30457_4138.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071227_194949_000004952064_00343_30457_4151.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071227_203439_000002772064_00343_30457_4153.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071227_204201_000003442064_00343_30457_4166.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071227_205625_000010442064_00343_30457_4312.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071227_212327_000001632064_00344_30458_4287.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071227_212920_000005492064_00344_30458_4298.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071227_221815_000000962064_00344_30458_4300.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071227_222137_000001932064_00344_30458_4307.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071227_224632_000003982064_00345_30459_4449.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071227_230938_000005732064_00345_30459_4464.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071227_234120_000002352064_00345_30459_4474.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071227_234526_000000902064_00345_30459_4476.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071227_235450_000000782064_00345_30459_4469.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20071227_235750_000002172064_00345_30459_4486.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071227_070819_000008822064_00335_30449_8094.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071227_075630_000006222064_00336_30450_8104.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071227_082451_000000662064_00336_30450_8169.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071227_082756_000005732064_00336_30450_8171.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071227_084739_000009242064_00336_30450_8178.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071227_093815_000005372064_00337_30451_8188.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071227_095249_000000962064_00337_30451_8295.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071227_100153_000002352064_00337_30451_8297.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071227_102815_000000662064_00337_30451_8302.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071227_111542_000006762064_00338_30452_8312.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071227_112546_000001202064_00338_30452_8401.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071227_112955_000002232064_00338_30452_8403.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071227_121339_000000782064_00338_30452_8405.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071227_122101_000002232064_00338_30452_8410.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071227_123241_000003022064_00338_30452_8418.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071227_125355_000008512064_00339_30453_8428.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071227_130656_000003142064_00339_30453_8529.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```


ASA_GM1_1PNPDK20071227_131332_000001262064_00339_30453_8531.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071227_133047_000000902064_00339_30453_8533.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071227_133308_000005132064_00339_30453_8535.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071227_134150_000003622064_00339_30453_8537.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071227_134927_000009242064_00339_30453_8546.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071227_141315_000002592064_00339_30453_8544.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071227_143158_000003742064_00340_30454_8556.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071227_143933_000001442064_00340_30454_8548.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071227_144349_000000962064_00340_30454_8561.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071227_144635_000002832064_00340_30454_8662.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071227_145304_000003922064_00340_30454_8664.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071227_153003_000008632064_00340_30454_8672.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071227_160858_000000842064_00341_30455_8674.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071227_161118_000003742064_00341_30455_8676.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071227_162310_000001022064_00341_30455_8683.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071227_162333_000001022064_00341_30455_8790.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071227_162711_000000722064_00341_30455_8788.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071227_163217_000002412064_00341_30455_8792.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071227_163825_000006102064_00341_30455_8794.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071227_171527_000002172064_00341_30455_8796.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071227_172249_000002232064_00341_30455_8801.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071227_175303_000004222064_00342_30456_8803.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071227_180145_000002052064_00342_30456_8912.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071227_181312_000004222064_00342_30456_8914.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071227_185803_000005492064_00342_30456_8922.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071227_192850_000002412064_00343_30457_8924.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20071227_193342_000004102064_00343_30457_8934.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

Analysing APM products...

Writing file ./RESULTS/DAILY/071227/AUXILIARY/Check_ADFs_APM.xls...

Writing file ./RESULTS/DAILY/071227/AUXILIARY/Check_ADFs_APM.txt...

ASA_APM_1PNPDE20071227_045952_000000422064_00334_30448_3622.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20071227_082601_000000892064_00336_30450_3904.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20071227_143035_000000562064_00340_30454_4005.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

Analysing IMM products...

Writing file ./RESULTS/DAILY/071227/AUXILIARY/Check_ADFs_IMM.xls...

Writing file ./RESULTS/DAILY/071227/AUXILIARY/Check_ADFs_IMM.txt...

ASA_IMM_1PNPDE20071227_000944_000000502064_00331_30445_3252.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20071227_001732_000000962064_00331_30445_3277.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20071227_014803_000000492064_00332_30446_3397.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20071227_015507_000001252064_00332_30446_3426.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20071227_023530_000000752064_00332_30446_3424.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20071227_024827_000000812064_00333_30447_3529.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20071227_025905_000000372064_00333_30447_3434.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20071227_032124_000000362064_00333_30447_3527.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20071227_045709_000000362064_00334_30448_3620.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20071227_100551_000001782064_00337_30451_3920.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20071227_133215_000000362064_00339_30453_3995.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20071227_141045_000000612064_00339_30453_4007.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20071227_141045_000001252064_00339_30453_4041.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20071227_141246_000000042064_00339_30453_4011.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20071227_142145_000000362064_00339_30453_4003.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20071227_143810_000000652064_00340_30454_4021.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20071227_145934_000000622064_00340_30454_4017.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20071227_145934_000001122064_00340_30454_4043.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20071227_155753_000001712064_00340_30454_4039.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20071227_161026_000000362064_00341_30455_4023.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

ASA_IMM_1PNPDE20071227_175125_000000612064_00342_30456_4063.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20071227_175125_000000812064_00342_30456_4089.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20071227_182015_000000372064_00342_30456_4095.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20071227_182130_000001422064_00342_30456_4106.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20071227_193250_000000362064_00343_30457_4108.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20071227_200842_000000612064_00343_30457_4234.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20071227_220405_000000622064_00344_30458_4416.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20071227_220506_000000222064_00344_30458_4393.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20071227_062846_000001722064_00335_30449_8087.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20071227_080651_000000662064_00336_30450_8140.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20071227_080907_000004412064_00336_30450_8164.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20071227_094712_000003202064_00337_30451_8288.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20071227_095538_000001362064_00337_30451_8283.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20071227_112747_000001132064_00338_30452_8384.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20071227_123148_000000362064_00338_30452_8496.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20071227_125052_000000342064_00339_30453_8498.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20071227_131209_000000672064_00339_30453_8504.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20071227_144156_000000962064_00340_30454_8644.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20071227_144527_000000512064_00340_30454_8638.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20071227_162016_000001572064_00341_30455_8770.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20071227_162518_000000962064_00341_30455_8772.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20071227_180007_000000812064_00342_30456_8893.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20071227_180507_000001282064_00342_30456_8895.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20071227_194131_000000902064_00343_30457_9010.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20071227_212608_000001752064_00344_30458_9044.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20071227_230425_000000662064_00345_30459_9056.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

Analysing WSM products...

Writing file ./RESULTS/DAILY/071227/AUXILIARY/Check_ADFs_WSM.xls...

Writing file ./RESULTS/DAILY/071227/AUXILIARY/Check_ADFs_WSM.txt...

ASA_WSM_1PNPDE20071227_003614_000001842064_00331_30445_3279.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_003614_000003422064_00331_30445_3446.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_004019_000000962064_00331_30445_3280.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_011341_000003862064_00332_30446_3551.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_013952_000000852064_00332_30446_3444.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_020329_000002632064_00332_30446_3448.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_024614_000001042064_00333_30447_3549.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_030546_000001832064_00333_30447_3559.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_034605_000003242064_00333_30447_3624.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_035326_000000672064_00333_30447_3628.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_035326_000004712064_00333_30447_3796.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_035535_000003422064_00333_30447_3724.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_043954_000002082064_00334_30448_3722.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_052442_000002022064_00334_30448_3855.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_052550_000000612064_00334_30448_3713.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_053142_000001292064_00334_30448_3895.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_053142_000005872064_00334_30448_3910.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_053446_000004032064_00334_30448_3896.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_054203_000001042064_00334_30448_3859.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_063636_000000862064_00335_30449_3857.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_063835_000000862064_00335_30449_3881.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_070518_000000862064_00335_30449_3883.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_102930_000003672064_00337_30451_3942.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_102930_000004032064_00337_30451_3991.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_103651_000003672064_00337_30451_3978.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_103651_000005182064_00337_30451_3989.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_104359_000000912064_00337_30451_3979.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_120705_000003852064_00338_30452_3993.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_120812_000003182064_00338_30452_3986.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_154439_000001582064_00340_30454_4031.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_161740_000001402064_00341_30455_4045.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_163027_000000672064_00341_30455_4055.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_163027_000000972064_00341_30455_4098.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK


```
ASA_WSM_1PNPDE20071227_163626_000001092064_00341_30455_4087.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_170853_000003852064_00341_30455_4091.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_171915_000002012064_00341_30455_4071.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_181138_000000672064_00342_30456_4067.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_181138_000000852064_00342_30456_4093.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_184929_000005002064_00342_30456_4136.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_191654_000001462064_00342_30456_4134.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_192448_000002322064_00343_30457_4277.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_203005_000001832064_00343_30457_4275.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_203005_000002632064_00343_30457_4305.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_203927_000001462064_00343_30457_4252.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_205242_000000672064_00343_30457_4244.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_205242_000002132064_00343_30457_4385.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_205450_000000852064_00343_30457_4273.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_214611_000000852064_00344_30458_4418.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_221041_000001282064_00344_30458_4442.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_221041_000004462064_00344_30458_4601.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_221344_000002632064_00344_30458_4443.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_222003_000000852064_00344_30458_4395.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_222110_00000182064_00344_30458_4281.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_222503_000002792064_00344_30458_4560.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_222610_000002132064_00344_30458_4436.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_230704_000001402064_00345_30459_4893.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_230811_000000722064_00345_30459_4581.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_235117_000002012064_00345_30459_4889.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_235224_000001332064_00345_30459_4603.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_235617_000000672064_00345_30459_4438.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20071227_235617_000000852064_00345_30459_4570.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20071227_062630_000000862064_00335_30449_8089.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20071227_084557_000000672064_00336_30450_8173.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20071227_095433_000000672064_00337_30451_8256.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20071227_121505_000000672064_00338_30452_8506.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20071227_121505_000003482064_00338_30452_8539.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20071227_121714_000002192064_00338_30452_8527.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20071227_145130_000000852064_00340_30454_8646.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20071227_162834_000001592064_00341_30455_8786.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20071227_180806_000001282064_00342_30456_8910.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20071227_194726_000001282064_00343_30457_9015.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20071227_211718_000003612064_00344_30458_9046.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20071227_230611_000000912064_00345_30459_9058.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```

AUXILIARY FILES ANALYSIS completed

#####

MODULE STEPPING ANALYSIS

#####

Analysis will be performed from 2007-12-27 00:00:00 to 2007-12-27 23:59:59

Results will be exported to the directory: ./RESULTS/DAILY/071227/MODULE_STEPPING

Creating directory ./RESULTS/DAILY/071227/MODULE_STEPPING...

Creating directory ./RESULTS/DAILY/071227/MODULE_STEPPING/FIRST_REFERENCE...

Creating directory ./RESULTS/DAILY/071227/MODULE_STEPPING/SECOND_REFERENCE...

Creating directory ./RESULTS/DAILY/071227/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE...

Deleting old files...

Creating images comparing with second reference...

Exporting results to the directory ././RESULTS/DAILY/071227/MODULE_STEPPING/SECOND_REFERENCE...

Polarization: H

Reference product: ASA_MS__0PNPDK20050922_062651_00000152041_00034_18625_0041.N1

Test product: ASA_MS__0PNPDK20071227_070655_00000162064_00335_30449_0444.N1



H
H
.././RESULTS/DAILY/071227/MODULE_STEPPING/SECOND_REFERENCE/TGH_20071227_070655-20050922_062651.png
.././RESULTS/DAILY/071227/MODULE_STEPPING/SECOND_REFERENCE/TPH_20071227_070655-20050922_062651.png
.././RESULTS/DAILY/071227/MODULE_STEPPING/SECOND_REFERENCE/RGH_20071227_070655-20050922_062651.png
.././RESULTS/DAILY/071227/MODULE_STEPPING/SECOND_REFERENCE/RPH_20071227_070655-20050922_062651.png

Polarization: V
Reference product: ASA_MS__0PNPDK20050923_055514_000000152041_00048_18639_0042.N1
Test product: ASA_MS__0PNPDK20071226_073832_000000162064_00321_30435_0443.N1

V
V
.././RESULTS/DAILY/071227/MODULE_STEPPING/SECOND_REFERENCE/TGV_20071226_073832-20050923_055514.png
.././RESULTS/DAILY/071227/MODULE_STEPPING/SECOND_REFERENCE/TPV_20071226_073832-20050923_055514.png
.././RESULTS/DAILY/071227/MODULE_STEPPING/SECOND_REFERENCE/RGV_20071226_073832-20050923_055514.png
.././RESULTS/DAILY/071227/MODULE_STEPPING/SECOND_REFERENCE/RPV_20071226_073832-20050923_055514.png

Creating images comparing with previous product reference...

Exporting results to the directory .././RESULTS/DAILY/071227/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE...

Polarization: H
Reference product: ASA_MS__0PNPDK20071225_081009_000000162064_00307_30421_0442.N1
Test product: ASA_MS__0PNPDK20071227_070655_000000162064_00335_30449_0444.N1

H
H
.././RESULTS/DAILY/071227/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TGH_20071227_070655-20071225_081009.png
.././RESULTS/DAILY/071227/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TPH_20071227_070655-20071225_081009.png
.././RESULTS/DAILY/071227/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RGH_20071227_070655-20071225_081009.png
.././RESULTS/DAILY/071227/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RPH_20071227_070655-20071225_081009.png

Polarization: V
Reference product: ASA_MS__0PNPDK20071224_084146_000000162064_00293_30407_0441.N1
Test product: ASA_MS__0PNPDK20071226_073832_000000162064_00321_30435_0443.N1

V
V
.././RESULTS/DAILY/071227/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TGV_20071226_073832-20071224_084146.png
.././RESULTS/DAILY/071227/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TPV_20071226_073832-20071224_084146.png
.././RESULTS/DAILY/071227/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RGV_20071226_073832-20071224_084146.png
.././RESULTS/DAILY/071227/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RPV_20071226_073832-20071224_084146.png

MODULE_STEPPING ANALYSIS completed
#####

CALIBRATION PULSES ANALYSIS

Creating directory ./RESULTS/DAILY/071227/CALIBRATION_PULSES...

ALL ROWS Analysis will be performed from 2007-12-27 00:00:00 to 2007-12-27 23:59:59

Analysing products WVS IS2 V/V
Writing image .././RESULTS/DAILY/071227//CALIBRATION_PULSES/Calibration_pulses_all_rows_WVS_IS2_VV.png...
Analysing products GM1 SS3 H/H
Writing image .././RESULTS/DAILY/071227//CALIBRATION_PULSES/Calibration_pulses_all_rows_GM1_SS3_HH.png...

TEMPORAL EVOLUTION Analysis will be performed from 2007-12-27 00:00:00 to 2007-12-27 23:59:59



Analysing products WVS IS2 V/V
 Getting calibration pulses data for WVS IS2 V/V from 2007-12-27 00:00:00 to 2007-12-27 23:59:59. Rows: 1/5/9/13/17/21/25/29
 Writing file ./RESULTS/DAILY/071227/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2007-12-27_1.dat...
 Writing ../../RESULTS/DAILY/071227//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_1.png...
 Writing ../../RESULTS/DAILY/071227//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_1.png...

Getting calibration pulses data for WVS IS2 V/V from 2007-12-27 00:00:00 to 2007-12-27 23:59:59. Rows: 2/6/10/14/18/22/26/30
 Writing file ./RESULTS/DAILY/071227/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2007-12-27_2.dat...
 Writing ../../RESULTS/DAILY/071227//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_2.png...
 Writing ../../RESULTS/DAILY/071227//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_2.png...

Getting calibration pulses data for WVS IS2 V/V from 2007-12-27 00:00:00 to 2007-12-27 23:59:59. Rows: 3/7/11/15/19/23/27/31
 Writing file ./RESULTS/DAILY/071227/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2007-12-27_3.dat...
 Writing ../../RESULTS/DAILY/071227//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_3.png...
 Writing ../../RESULTS/DAILY/071227//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_3.png...

Getting calibration pulses data for WVS IS2 V/V from 2007-12-27 00:00:00 to 2007-12-27 23:59:59. Rows: 4/8/12/16/20/24/28/32
 Writing file ./RESULTS/DAILY/071227/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2007-12-27_4.dat...
 Writing ../../RESULTS/DAILY/071227//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_4.png...
 Writing ../../RESULTS/DAILY/071227//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_4.png...

Analysing products GM1 SS3 H/H
 Getting calibration pulses data for GM1 SS3 H/H from 2007-12-27 00:00:00 to 2007-12-27 23:59:59. Rows: 1/5/9/13/17/21/25/29
 Writing file ./RESULTS/DAILY/071227/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2007-12-27_1.dat...
 Writing ../../RESULTS/DAILY/071227//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_1.png...
 Writing ../../RESULTS/DAILY/071227//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_1.png...

Getting calibration pulses data for GM1 SS3 H/H from 2007-12-27 00:00:00 to 2007-12-27 23:59:59. Rows: 2/6/10/14/18/22/26/30
 Writing file ./RESULTS/DAILY/071227/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2007-12-27_2.dat...
 Writing ../../RESULTS/DAILY/071227//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_2.png...
 Writing ../../RESULTS/DAILY/071227//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_2.png...

Getting calibration pulses data for GM1 SS3 H/H from 2007-12-27 00:00:00 to 2007-12-27 23:59:59. Rows: 3/7/11/15/19/23/27/31
 Writing file ./RESULTS/DAILY/071227/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2007-12-27_3.dat...
 Writing ../../RESULTS/DAILY/071227//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_3.png...
 Writing ../../RESULTS/DAILY/071227//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_3.png...

Getting calibration pulses data for GM1 SS3 H/H from 2007-12-27 00:00:00 to 2007-12-27 23:59:59. Rows: 4/8/12/16/20/24/28/32
 Writing file ./RESULTS/DAILY/071227/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2007-12-27_4.dat...
 Writing ../../RESULTS/DAILY/071227//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_4.png...
 Writing ../../RESULTS/DAILY/071227//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_4.png...

CALIBRATION PULSES ANALYSIS completed
 #####

DOPPLER ANALYSIS
 #####
 Creating directory ./RESULTS/DAILY/071227/DOPPLER...

 DOPPLER ANX Analysis will be performed from 2007-12-27 00:00:00 to 2007-12-27 23:59:59

Analysing products WVS IS2 V/V
 Getting doppler data for WVS IS2 V/V from 2007-12-27 00:00:00 to 2007-12-27 23:59:59...



Writing file ./RESULTS/DAILY/071227/DOPPLER/Doppler_data_WVS_IS2_VV_2007-12-27.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/071227/DOPPLER/DOPPLER_ANX_WVS_IS2_VV.png...

Analysing products GM1 SS1 H/H
Getting doppler data for GM1 SS1 H/H from 2007-12-27 00:00:00 to 2007-12-27 23:59:59...
Writing file ./RESULTS/DAILY/071227/DOPPLER/Doppler_data_GM1_SS1_HH_2007-12-27.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/071227/DOPPLER/DOPPLER_ANX_GM1_SS1_HH.png...

DOPPLER JUMPS Analysis will be performed on WSM products from 2007-12-27 00:00:00 to 2007-12-27 23:59:59

Analysing by default products WSM
Getting doppler jumps data for WSM from 2007-12-27 00:00:00 to 2007-12-27 23:59:59...
Writing file ./RESULTS/DAILY/071227/DOPPLER/Doppler_Jumps_data_WSM_2007-12-27.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/071227/DOPPLER/DOPPLER_JUMPS_ANX_WSM.png...
Writing file ../../RESULTS/DAILY/071227/DOPPLER/DOPPLER_JUMPS_Date_WSM.png...

DOPPLER MAP Analysis will be performed from 2007-12-27 00:00:00 to 2007-12-27 23:59:59

Analysing products WVS IS2 V/V
Loading predicted doppler values....
Phase: descending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -27.162729 Hz
Writing file ../../RESULTS/DAILY/071227//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_WVS_IS2_VV_desc.jpg...
Writing file ../../RESULTS/DAILY/071227//DOPPLER/DOPPLER_Absolute_WVS_IS2_VV_desc.jpg...

Loading predicted doppler values....
Phase: ascending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -22.674947 Hz
Writing file ../../RESULTS/DAILY/071227//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_WVS_IS2_VV_asc.jpg...
Writing file ../../RESULTS/DAILY/071227//DOPPLER/DOPPLER_Absolute_WVS_IS2_VV_asc.jpg...

Analysing products GM1 SS1 H/H
Loading predicted doppler values....
Phase: descending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -24.747351 Hz
Writing file ../../RESULTS/DAILY/071227//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_GM1_SS1_HH_desc.jpg...
Writing file ../../RESULTS/DAILY/071227//DOPPLER/DOPPLER_Absolute_GM1_SS1_HH_desc.jpg...

Loading predicted doppler values....
Phase: ascending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -27.053519 Hz
Writing file ../../RESULTS/DAILY/071227//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_GM1_SS1_HH_asc.jpg...
Writing file ../../RESULTS/DAILY/071227//DOPPLER/DOPPLER_Absolute_GM1_SS1_HH_asc.jpg...

DOPPLER ANALYSIS completed

#####

CHIRP ANALYSIS

#####

Creating directory ./RESULTS/DAILY/071227/CHIRP...

CHIRP Analysis will be performed from 2007-12-27 00:00:00 to 2007-12-27 23:59:59

Analysing products WSM SS1 H/H

Getting ScaleFactor data for WSM SS1 H/H from 2007-12-27 00:00:00 to 2007-12-27 23:59:59...

Writing file ./RESULTS/DAILY/071227/CHIRP/ScaleFactor_data_WSM_SS1_HH_2007-12-27.dat...

Running IDL program...

Writing file ../../RESULTS/DAILY/071227/CHIRP/ScaleFactor_ANX_WSM_SS1_HH.png...

Writing file ../../RESULTS/DAILY/071227/CHIRP/ScaleFactor_DATE_WSM_SS1_HH.png...

Analysing products WSM SS1 V/V

Getting ScaleFactor data for WSM SS1 V/V from 2007-12-27 00:00:00 to 2007-12-27 23:59:59...

Writing file ./RESULTS/DAILY/071227/CHIRP/ScaleFactor_data_WSM_SS1_VV_2007-12-27.dat...

Running IDL program...

Writing file ../../RESULTS/DAILY/071227/CHIRP/ScaleFactor_ANX_WSM_SS1_VV.png...

Writing file ../../RESULTS/DAILY/071227/CHIRP/ScaleFactor_DATE_WSM_SS1_VV.png...

CHIRP ANALYSIS completed

#####

RAW DATA ANALYSIS

#####

Analysis will be performed from 2007-12-27 00:00:00 to 2007-12-27 23:59:59

Results will be exported to the directory: ./RESULTS/DAILY/071227/RAW_DATA

Creating directory ./RESULTS/DAILY/071227/RAW_DATA...

Getting raw data for WVS from 2007-12-27 00:00:00 to 2007-12-27 23:59:59...

Writing file ./RESULTS/DAILY/071227/RAW_DATA/Raw_data_WVS_2007-12-27.dat...

Running IDL program to create graphs...

Creating image ../../RESULTS/DAILY/071227/RAW_DATA/Raw_data_WVS_input_mean.png...

Creating image ../../RESULTS/DAILY/071227/RAW_DATA/Raw_data_WVS_input_stdev.png...

Creating image ../../RESULTS/DAILY/071227/RAW_DATA/Raw_data_WVS_gain_imbalance.png...

Getting raw data for IMM from 2007-12-27 00:00:00 to 2007-12-27 23:59:59...

Writing file ./RESULTS/DAILY/071227/RAW_DATA/Raw_data_IMM_2007-12-27.dat...

Running IDL program to create graphs...

Creating image ../../RESULTS/DAILY/071227/RAW_DATA/Raw_data_IMM_input_mean.png...

Creating image ../../RESULTS/DAILY/071227/RAW_DATA/Raw_data_IMM_input_stdev.png...

Creating image ../../RESULTS/DAILY/071227/RAW_DATA/Raw_data_IMM_gain_imbalance.png...

RAW DATA ANALYSIS completed

#####

TELEMETRY ANALYSIS

Analysis will be performed from 2007-12-27 00:00:00 to 2007-12-27 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/071227/TELEMETRY

Creating directory ./RESULTS/DAILY/071227/TELEMETRY...

Looking for gaps and missing lines in WVS products...

Checking 31 products from PDE...
Checking 22 products from PDK...

Looking for gaps and missing lines in GM1 products...

Checking 39 products from PDE...
Checking 44 products from PDK...

Looking for gaps and missing lines in APM products...

Checking 3 products from PDE...
No products from PDK...

Looking for gaps and missing lines in IMM products...

Checking 28 products from PDE...
Found product...ASA_IMM_1PNPDE20071227_175125_00000612064_00342_30456_4063.N1 / 1 gaps / 0 missing lines
Found product...ASA_IMM_1PNPDE20071227_175125_00000812064_00342_30456_4089.N1 / 1 gaps / 0 missing lines
Checking 18 products from PDK...
Found product...ASA_IMM_1PNPDK20071227_125052_00000342064_00339_30453_8498.N1 / 1 gaps / 0 missing lines

Looking for gaps and missing lines in WSM products...

Checking 61 products from PDE...
Checking 12 products from PDK...

Creating graph of missing lines and gaps...

Creating image: ./RESULTS/DAILY/071227/TELEMETRY/TELEMETRY_Missing_lines.png...
Creating image: ./RESULTS/DAILY/071227/TELEMETRY/TELEMETRY_Gaps.png...

TELEMETRY ANALYSIS completed

#####

BROWSE PRODUCTS ANALYSIS

Analysis will be performed on 2007-12-27

Scanning directory /nas3/ENVISAT/ASAR//ASA_GM_BP...
Results will be exported to the directory: /nas3/ENVISAT/ASAR//ASA_GM_BP/JPG/20071227/

Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDE20071227_193908_000001442064_00343_30457_4141.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDE20071227_194318_000002352064_00343_30457_4139.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDE20071227_194949_000004952064_00343_30457_4152.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDE20071227_203439_000002772064_00343_30457_4154.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDE20071227_204201_000003442064_00343_30457_4167.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDE20071227_205625_000010442064_00343_30457_4313.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDE20071227_212327_000001632064_00344_30458_4288.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDE20071227_212920_000005492064_00344_30458_4299.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDE20071227_221815_000000962064_00344_30458_4301.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDE20071227_222137_000001932064_00344_30458_4308.N1 ...


```
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDE20071227_224632_000003982064_00345_30459_4450.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDE20071227_230938_000005732064_00345_30459_4465.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDE20071227_234120_000002352064_00345_30459_4475.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDE20071227_234526_000000902064_00345_30459_4477.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDE20071227_235450_000000782064_00345_30459_4470.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDE20071227_235750_000002172064_00345_30459_4487.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDK20071227_180145_000002052064_00342_30456_8913.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDK20071227_181312_000004222064_00342_30456_8915.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDK20071227_185803_000005492064_00342_30456_8923.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDK20071227_192850_000002412064_00343_30457_8925.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDK20071227_193342_000004102064_00343_30457_8935.N1 ...
```

ANALYSIS COMPLETED: 21 GM browse products to see...

Scanning directory /nas3/ENVISAT/ASAR//ASA_AP_BP...

Results will be exported to the directory: /nas3/ENVISAT/ASAR//ASA_AP_BP/JPG/20071227/

```
Stripping browse product /nas3/ENVISAT/ASAR//ASA_AP_BP/ASA_AP_BPZPDE20071227_143035_000000562064_00340_30454_4006.N1 ...
```

ANALYSIS COMPLETED: 1 AP browse products to see...

Scanning directory /nas3/ENVISAT/ASAR//ASA_IM_BP...

Results will be exported to the directory: /nas3/ENVISAT/ASAR//ASA_IM_BP/JPG/20071227/

```
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20071227_100551_000001782064_00337_30451_3921.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20071227_133215_000000362064_00339_30453_3996.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20071227_141045_000000612064_00339_30453_4008.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20071227_141045_000001252064_00339_30453_4042.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20071227_141246_000000042064_00339_30453_4012.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20071227_142145_000000362064_00339_30453_4004.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20071227_143810_000000652064_00340_30454_4022.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20071227_145934_000000622064_00340_30454_4018.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20071227_145934_000001122064_00340_30454_4044.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20071227_155753_000001712064_00340_30454_4040.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20071227_161026_000000362064_00341_30455_4024.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20071227_175125_000000612064_00342_30456_4064.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20071227_175125_000000812064_00342_30456_4090.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20071227_182015_000000372064_00342_30456_4096.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20071227_182130_000001422064_00342_30456_4107.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20071227_193250_000000362064_00343_30457_4109.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20071227_200842_000000612064_00343_30457_4235.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20071227_220405_000000622064_00344_30458_4417.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20071227_220506_000000022064_00344_30458_4394.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDK20071227_194131_000000902064_00343_30457_9011.N1 ...
```

ANALYSIS COMPLETED: 20 IM browse products to see...

Scanning directory /nas3/ENVISAT/ASAR//ASA_WS_BP...

Results will be exported to the directory: /nas3/ENVISAT/ASAR//ASA_WS_BP/JPG/20071227/

```
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20071227_053142_000005872064_00334_30448_3911.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20071227_102930_000003672064_00337_30451_3943.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20071227_102930_000004032064_00337_30451_3992.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20071227_103651_000003672064_00337_30451_3980.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20071227_103651_000005182064_00337_30451_3990.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20071227_104359_000000912064_00337_30451_3981.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20071227_120705_000003852064_00338_30452_3994.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20071227_120812_000003182064_00338_30452_3987.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20071227_154439_000001582064_00340_30454_4032.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20071227_161740_000001402064_00341_30455_4046.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20071227_163027_000000672064_00341_30455_4056.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20071227_163027_000000972064_00341_30455_4099.N1 ...
```

Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20071227_163626_000001092064_00341_30455_4088.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20071227_170853_000003852064_00341_30455_4092.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20071227_171915_000002012064_00341_30455_4072.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20071227_181138_000000672064_00342_30456_4068.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20071227_181138_000000852064_00342_30456_4094.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20071227_184929_000005002064_00342_30456_4137.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20071227_191654_000001462064_00342_30456_4135.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20071227_192448_000002322064_00343_30457_4278.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20071227_203005_000001832064_00343_30457_4276.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20071227_203005_000002632064_00343_30457_4306.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20071227_203927_000001462064_00343_30457_4253.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20071227_205242_000000672064_00343_30457_4245.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20071227_205242_000002132064_00343_30457_4386.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20071227_205450_000000852064_00343_30457_4274.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20071227_214611_000000852064_00344_30458_4419.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20071227_221041_000001282064_00344_30458_4444.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20071227_221041_000004462064_00344_30458_4602.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20071227_221344_000002632064_00344_30458_4445.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20071227_222003_000000852064_00344_30458_4396.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20071227_222110_000000182064_00344_30458_4282.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20071227_222503_000002792064_00344_30458_4561.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20071227_222610_000002132064_00344_30458_4437.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20071227_230811_000000722064_00345_30459_4582.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20071227_235224_000001332064_00345_30459_4604.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20071227_235617_000000672064_00345_30459_4439.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20071227_235617_000000852064_00345_30459_4571.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDK20071227_194726_000001282064_00343_30457_9016.N1 ...

ANALYSIS COMPLETED: 39 WS browse products to see...

BROWSE PRODUCTS ANALYSIS completed
#####

HTML REPORT generation
#####

Building file ./RESULTS/DAILY/071227/asarReport.html...
Building DATA SUMMARY section...
Building AUXILIARY FILES ANALYSIS section...
Building MODULE STEPPING ANALYSIS section...
Building CALIBRATION PULSES ANALYSIS section...
Building DOPPLER ANALYSIS section...
Building CHIRP ANALYSIS section...
Building RAW DATA ANALYSIS section...
Building TELEMETRY ANALYSIS section...

HTML REPORT generation completed
#####



ASAR Daily Report



Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
ASA_APM_1PNPDE20071227_045952_000000422064_00334_30448_3622.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20071227_082601_000000892064_00336_30450_3904.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20071227_143035_000000562064_00340_30454_4005.N1	OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_GM1_1PNPDE20071227_001052_000003922064_00331_30445_3148.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071227_002439_000006822064_00331_30445_3156.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071227_005334_000002052064_00331_30445_3283.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071227_012015_000010882064_00332_30446_3385.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071227_020803_000007852064_00332_30446_3308.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071227_022727_000004832064_00332_30446_3523.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071227_023703_000002652064_00332_30446_3517.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071227_025126_000004592064_00333_30447_3521.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071227_030000_000003382064_00333_30447_3519.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071227_030857_000007492064_00333_30447_3525.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071227_032217_000001322064_00333_30447_3515.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071227_035139_000000962064_00333_30447_3561.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071227_040246_000001692064_00333_30447_3566.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071227_042302_000010022064_00334_30448_3626.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071227_044330_000008152064_00334_30448_3576.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071227_045801_000001082064_00334_30448_3574.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071227_050059_000002412064_00334_30448_3615.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071227_052816_000001932064_00334_30448_3732.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071227_060951_000001322064_00335_30449_3734.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071227_061308_000007912064_00335_30449_3736.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071227_063154_000002712064_00335_30449_3762.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071227_064011_000006102064_00335_30449_3767.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071227_065306_000001142064_00335_30449_3778.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071227_193908_000001442064_00343_30457_4140.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071227_194318_000002352064_00343_30457_4138.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071227_194949_000004952064_00343_30457_4151.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071227_203439_000002772064_00343_30457_4153.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071227_204201_000003442064_00343_30457_4166.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071227_205625_000010442064_00343_30457_4312.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071227_212327_000001632064_00344_30458_4287.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071227_212920_000005492064_00344_30458_4298.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071227_221815_000000962064_00344_30458_4300.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071227_222137_000001932064_00344_30458_4307.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071227_224632_000003982064_00345_30459_4449.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071227_230938_000005732064_00345_30459_4464.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071227_234120_000002352064_00345_30459_4474.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071227_234526_000000902064_00345_30459_4476.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071227_235450_000000782064_00345_30459_4469.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20071227_235750_000002172064_00345_30459_4486.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071227_070819_000008822064_00335_30449_8094.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071227_075630_000006222064_00336_30450_8104.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071227_082451_000000662064_00336_30450_8169.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071227_082756_000005732064_00336_30450_8171.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071227_084739_000009242064_00336_30450_8178.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071227_093815_000005372064_00337_30451_8188.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071227_095249_000000962064_00337_30451_8295.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071227_100153_000002352064_00337_30451_8297.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071227_102815_000000662064_00337_30451_8302.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071227_111542_000006762064_00338_30452_8312.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071227_112546_000001202064_00338_30452_8401.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071227_112955_000002232064_00338_30452_8403.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071227_121339_000000782064_00338_30452_8405.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071227_122101_000002232064_00338_30452_8410.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071227_123241_000003022064_00338_30452_8418.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071227_125355_000008512064_00339_30453_8428.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071227_130656_000003142064_00339_30453_8529.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071227_131332_000001262064_00339_30453_8531.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071227_133047_000000902064_00339_30453_8533.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071227_133308_000005132064_00339_30453_8535.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071227_134150_000003622064_00339_30453_8537.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071227_134927_000009242064_00339_30453_8546.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071227_141315_000002592064_00339_30453_8544.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071227_143158_000003742064_00340_30454_8556.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20071227_143933_000001442064_00340_30454_8548.N1					OK	OK	OK	OK

ASA_GM1_1PNPDK20071227_144349_00000962064_00340_30454_8561.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20071227_144635_000002832064_00340_30454_8662.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20071227_145304_000003922064_00340_30454_8664.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20071227_153003_000008632064_00340_30454_8672.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20071227_160858_000008842064_00341_30455_8674.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20071227_161118_000003742064_00341_30455_8676.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20071227_162310_000001022064_00341_30455_8683.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20071227_162333_000001022064_00341_30455_8790.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20071227_162711_000000722064_00341_30455_8788.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20071227_163217_000002412064_00341_30455_8792.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20071227_163825_000006102064_00341_30455_8794.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20071227_171527_000002172064_00341_30455_8796.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20071227_172249_000002232064_00341_30455_8801.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20071227_175303_000004222064_00342_30456_8803.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20071227_180145_000002052064_00342_30456_8912.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20071227_181312_000004222064_00342_30456_8914.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20071227_185803_000005492064_00342_30456_8922.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20071227_192850_000002412064_00343_30457_8924.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20071227_193342_000004102064_00343_30457_8934.N1	OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_IMM_1PNPDE20071227_000944_000000502064_00331_30445_3252.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20071227_001732_000000962064_00331_30445_3277.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20071227_014803_000000492064_00332_30446_3397.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20071227_015507_000001252064_00332_30446_3426.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20071227_023530_000000752064_00332_30446_3424.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20071227_024827_000000812064_00333_30447_3529.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20071227_025905_000000372064_00333_30447_3434.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20071227_032124_000000362064_00333_30447_3527.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20071227_045709_000000362064_00334_30448_3620.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20071227_100551_000001782064_00337_30451_3920.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20071227_133215_000000362064_00339_30453_3995.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20071227_141045_000000612064_00339_30453_4007.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20071227_141045_000001252064_00339_30453_4041.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20071227_141246_000000042064_00339_30453_4011.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20071227_142145_000000362064_00339_30453_4003.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20071227_143810_000000652064_00340_30454_4021.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20071227_145934_000000622064_00340_30454_4017.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20071227_145934_000001122064_00340_30454_4043.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20071227_155753_000001712064_00340_30454_4039.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20071227_161026_000000362064_00341_30455_4023.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20071227_175125_000000612064_00342_30456_4063.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20071227_175125_000000812064_00342_30456_4089.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20071227_182015_000000372064_00342_30456_4095.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20071227_182130_000001422064_00342_30456_4106.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20071227_193250_000000362064_00343_30457_4108.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20071227_200842_000000612064_00343_30457_4234.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20071227_220405_000000622064_00344_30458_4416.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20071227_220506_000000022064_00344_30458_4393.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20071227_062846_000001722064_00335_30449_8087.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20071227_080651_000000662064_00336_30450_8140.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20071227_080907_000004412064_00336_30450_8164.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20071227_094712_000003202064_00337_30451_8288.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20071227_095538_000001362064_00337_30451_8283.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20071227_112747_000001132064_00338_30452_8384.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20071227_123148_000000362064_00338_30452_8496.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20071227_125052_000000342064_00339_30453_8498.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20071227_131209_000000672064_00339_30453_8504.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20071227_144156_000000962064_00340_30454_8644.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20071227_144527_000000512064_00340_30454_8638.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20071227_162016_000001572064_00341_30455_8770.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20071227_162518_000000962064_00341_30455_8772.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20071227_180007_000000812064_00342_30456_8893.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20071227_180507_000001282064_00342_30456_8895.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20071227_194131_000000902064_00343_30457_9010.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20071227_212608_000001752064_00344_30458_9044.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20071227_230425_000000662064_00345_30459_9056.N1					OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.


Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WSM_1PNPDE20071227_003614_000001842064_00331_30445_3279.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_003614_000003422064_00331_30445_3446.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_004019_000000962064_00331_30445_3280.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_011341_000003862064_00332_30446_3551.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_013952_000000852064_00332_30446_3444.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_020329_000002632064_00332_30446_3448.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_024614_000001042064_00333_30447_3549.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_030546_000001832064_00333_30447_3559.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_034605_000003242064_00333_30447_3624.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_035326_000000672064_00333_30447_3628.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_035326_000004712064_00333_30447_3796.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_035535_000003422064_00333_30447_3724.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_043954_000002082064_00334_30448_3722.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_052442_000002022064_00334_30448_3855.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_052550_000000612064_00334_30448_3713.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_053142_000001292064_00334_30448_3895.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_053142_000005872064_00334_30448_3910.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_053446_000004032064_00334_30448_3896.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_054203_000001042064_00334_30448_3859.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_063636_000000862064_00335_30449_3857.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_063835_000000862064_00335_30449_3881.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_070518_000000862064_00335_30449_3883.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_102930_000003672064_00337_30451_3942.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_102930_000004032064_00337_30451_3991.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_103651_000003672064_00337_30451_3978.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_103651_000005182064_00337_30451_3989.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_104359_000000912064_00337_30451_3979.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_120705_000003852064_00338_30452_3993.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_120812_000003182064_00338_30452_3986.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_154439_000001582064_00340_30454_4031.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_161740_000001402064_00341_30455_4045.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_163027_000000672064_00341_30455_4055.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_163027_000000972064_00341_30455_4098.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_163626_000001092064_00341_30455_4087.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_170853_000003852064_00341_30455_4091.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_171915_000002012064_00341_30455_4071.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_181138_000000672064_00342_30456_4067.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_181138_000000852064_00342_30456_4093.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_184929_000005002064_00342_30456_4136.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_191654_000001462064_00342_30456_4134.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_192448_000002322064_00343_30457_4277.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_203005_000001832064_00343_30457_4275.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_203005_000002632064_00343_30457_4305.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_203927_000001462064_00343_30457_4252.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_205242_000000672064_00343_30457_4244.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_205242_000002132064_00343_30457_4385.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_205450_000000852064_00343_30457_4273.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_214611_000000852064_00344_30458_4418.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_221041_000001282064_00344_30458_4442.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_221041_000004462064_00344_30458_4601.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_221344_000002632064_00344_30458_4443.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_222003_000000852064_00344_30458_4395.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_222110_000000182064_00344_30458_4281.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_222503_000002792064_00344_30458_4560.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_222610_000002132064_00344_30458_4436.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_230704_000001402064_00345_30459_4893.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_230811_000000722064_00345_30459_4581.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_235117_000002012064_00345_30459_4889.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_235224_000001332064_00345_30459_4603.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_235617_000000672064_00345_30459_4438.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20071227_235617_000000852064_00345_30459_4570.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20071227_062630_000000862064_00335_30449_8089.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20071227_084557_000000672064_00336_30450_8173.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20071227_095433_000000672064_00337_30451_8256.N1					OK	OK	OK	OK

ASA_WSM_1PNPDK20071227_121505_000000672064_00338_30452_8506.N1	OK	OK	OK	OK
ASA_WSM_1PNPDK20071227_121505_000003482064_00338_30452_8539.N1	OK	OK	OK	OK
ASA_WSM_1PNPDK20071227_121714_000002192064_00338_30452_8527.N1	OK	OK	OK	OK
ASA_WSM_1PNPDK20071227_145130_000000852064_00340_30454_8646.N1	OK	OK	OK	OK
ASA_WSM_1PNPDK20071227_162834_000001592064_00341_30455_8786.N1	OK	OK	OK	OK
ASA_WSM_1PNPDK20071227_180806_000001282064_00342_30456_8910.N1	OK	OK	OK	OK
ASA_WSM_1PNPDK20071227_194726_000001282064_00343_30457_9015.N1	OK	OK	OK	OK
ASA_WSM_1PNPDK20071227_211718_000003612064_00344_30458_9046.N1	OK	OK	OK	OK
ASA_WSM_1PNPDK20071227_230611_000000912064_00345_30459_9058.N1	OK	OK	OK	OK


Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WVS_1PNPDE20071227_001914_000002702064_00331_30445_3151.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20071227_004155_000003152064_00331_30445_3154.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20071227_004625_000003742064_00331_30445_3286.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20071227_005658_000009442064_00331_30445_3289.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20071227_014214_000003142064_00332_30446_3292.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20071227_014859_000002542064_00332_30446_3295.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20071227_015719_000003152064_00332_30446_3306.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20071227_022113_00000442064_00332_30446_3311.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20071227_022113_000003302064_00332_30446_3474.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20071227_024132_000002392064_00333_30447_3471.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20071227_032433_000008242064_00333_30447_3477.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20071227_033748_000002402064_00333_30447_3564.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20071227_040535_000010042064_00333_30447_3583.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20071227_050501_000009292064_00334_30448_3618.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20071227_052016_000002102064_00334_30448_3730.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20071227_054344_000015142064_00334_30448_3765.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20071227_065025_000001042064_00335_30449_3770.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20071227_065503_000002692064_00335_30449_3786.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20071227_195803_000005992064_00343_30457_4143.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20071227_200951_000011692064_00343_30457_4156.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20071227_204749_000000742064_00343_30457_4164.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20071227_204804_000002252064_00343_30457_4290.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20071227_213830_000004042064_00344_30458_4293.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20071227_214735_000009442064_00344_30458_4296.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20071227_220516_000002702064_00344_30458_4303.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20071227_222943_000002702064_00344_30458_4310.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20071227_223313_000007492064_00344_30458_4447.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20071227_225314_000005692064_00345_30459_4452.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20071227_231911_000012742064_00345_30459_4472.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20071227_234658_000002102064_00345_30459_4467.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20071227_065903_000003302064_00335_30449_8092.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20071227_072302_000019642064_00335_30449_8102.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20071227_083729_000004652064_00336_30450_8176.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20071227_090337_000020242064_00336_30450_8181.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20071227_101001_000010492064_00337_30451_8300.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20071227_104532_000017542064_00337_30451_8305.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20071227_113339_000019492064_00338_30452_8413.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20071227_122449_000003752064_00338_30452_8408.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20071227_123746_000007442064_00338_30452_8416.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20071227_125134_000000892064_00339_30453_8421.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20071227_131538_000008542064_00339_30453_8542.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20071227_140525_000002852064_00339_30453_8551.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20071227_141737_000002092064_00339_30453_8554.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20071227_142228_000002842064_00339_30453_8559.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20071227_150155_000016342064_00340_30454_8670.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20071227_154719_000006002064_00340_30454_8667.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20071227_160051_000004342064_00340_30454_8686.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20071227_164837_000011692064_00341_30455_8799.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20071227_172637_000013942064_00341_30455_8811.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20071227_182359_000014842064_00342_30456_8917.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20071227_190713_000005252064_00342_30456_8920.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20071227_191917_000002242064_00342_30456_8932.N1					OK	OK	OK	OK


Calibration pulses for GM1 SS3 H/H




Calibration pulses for GM1 SS3 H/H




Calibration pulses for GM1 SS3 H/H




Calibration pulses for GM1 SS3 H/H




Calibration pulses for WVS IS2 V/V




Calibration pulses for WVS IS2 V/V





Calibration pulses for WVS IS2 V/V







Calibration pulses for WVS IS2 V/V





























rows: _ 1 _ 5 _ 9 _ 13 _ 17 _ 21 _ 25 _ 29








27-Dec
rows: _ 3 _ 7 _ 11 _ 15 _ 19 _ 23 _ 27 _ 31




rows: _ 4 _ 8 _ 12 _ 16 _ 20 _ 24 _ 28 _ 32









Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_APM_1PNPDE20071227_045952_000000422064_00334_30448_3622.N1						IS2	H/H	64	30448	334	4.05
ASA_APM_1PNPDE20071227_082601_000000892064_00336_30450_3904.N1						IS2	H/H	64	30450	336	4.05
ASA_APM_1PNPDE20071227_143035_000000562064_00340_30454_4005.N1						IS2	H/H	64	30454	340	4.05

Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_GM1_1PNPDE20071227_001052_000003922064_00331_30445_3148.N1						SS1	H/H	64	30445	331	4.05
ASA_GM1_1PNPDE20071227_002439_000006822064_00331_30445_3156.N1						SS1	H/H	64	30445	331	4.05
ASA_GM1_1PNPDE20071227_005334_000002052064_00331_30445_3283.N1						SS1	H/H	64	30445	331	4.05
ASA_GM1_1PNPDE20071227_012015_000010882064_00332_30446_3385.N1						SS1	H/H	64	30446	332	4.05
ASA_GM1_1PNPDE20071227_020803_000007852064_00332_30446_3308.N1						SS1	H/H	64	30446	332	4.05
ASA_GM1_1PNPDE20071227_022727_000004832064_00332_30446_3523.N1						SS1	H/H	64	30446	332	4.05
ASA_GM1_1PNPDE20071227_023703_000002652064_00332_30446_3517.N1						SS1	H/H	64	30446	332	4.05
ASA_GM1_1PNPDE20071227_025126_000004592064_00333_30447_3521.N1						SS1	H/H	64	30447	333	4.05
ASA_GM1_1PNPDE20071227_030000_000003382064_00333_30447_3519.N1						SS1	H/H	64	30447	333	4.05
ASA_GM1_1PNPDE20071227_030857_000007492064_00333_30447_3525.N1						SS1	H/H	64	30447	333	4.05
ASA_GM1_1PNPDE20071227_032217_000001322064_00333_30447_3515.N1						SS1	H/H	64	30447	333	4.05
ASA_GM1_1PNPDE20071227_035139_000000962064_00333_30447_3561.N1						SS1	H/H	64	30447	333	4.05
ASA_GM1_1PNPDE20071227_040246_000001692064_00333_30447_3566.N1						SS1	H/H	64	30447	333	4.05
ASA_GM1_1PNPDE20071227_042302_000010022064_00334_30448_3626.N1						SS1	H/H	64	30448	334	4.05
ASA_GM1_1PNPDE20071227_044330_000008152064_00334_30448_3576.N1						SS1	H/H	64	30448	334	4.05
ASA_GM1_1PNPDE20071227_045801_000001082064_00334_30448_3574.N1						SS1	H/H	64	30448	334	4.05
ASA_GM1_1PNPDE20071227_050059_000002412064_00334_30448_3615.N1						SS1	H/H	64	30448	334	4.05
ASA_GM1_1PNPDE20071227_052816_000001932064_00334_30448_3732.N1						SS1	H/H	64	30448	334	4.05
ASA_GM1_1PNPDE20071227_060951_000001322064_00335_30449_3734.N1						SS1	H/H	64	30449	335	4.05
ASA_GM1_1PNPDE20071227_061308_000007912064_00335_30449_3736.N1						SS1	H/H	64	30449	335	4.05
ASA_GM1_1PNPDE20071227_063154_000002712064_00335_30449_3762.N1						SS1	H/H	64	30449	335	4.05
ASA_GM1_1PNPDE20071227_064011_000006102064_00335_30449_3767.N1						SS1	H/H	64	30449	335	4.05
ASA_GM1_1PNPDE20071227_065306_000001142064_00335_30449_3778.N1						SS1	H/H	64	30449	335	4.05
ASA_GM1_1PNPDK20071227_070819_000008822064_00335_30449_8094.N1						SS1	H/H	64	30449	335	4.05
ASA_GM1_1PNPDK20071227_075630_000006222064_00336_30450_8104.N1						SS1	H/H	64	30450	336	4.05
ASA_GM1_1PNPDK20071227_082451_000000662064_00336_30450_8169.N1						SS1	H/H	64	30450	336	4.05
ASA_GM1_1PNPDK20071227_082756_000005732064_00336_30450_8171.N1						SS1	H/H	64	30450	336	4.05
ASA_GM1_1PNPDK20071227_084739_000009242064_00336_30450_8178.N1						SS1	H/H	64	30450	336	4.05
ASA_GM1_1PNPDK20071227_093815_000005372064_00337_30451_8188.N1						SS1	H/H	64	30451	337	4.05
ASA_GM1_1PNPDK20071227_095249_000000962064_00337_30451_8295.N1						SS1	H/H	64	30451	337	4.05
ASA_GM1_1PNPDK20071227_100153_000002352064_00337_30451_8297.N1						SS1	H/H	64	30451	337	4.05
ASA_GM1_1PNPDK20071227_102815_000000662064_00337_30451_8302.N1						SS1	H/H	64	30451	337	4.05
ASA_GM1_1PNPDK20071227_111542_000006762064_00338_30452_8312.N1						SS1	H/H	64	30452	338	4.05
ASA_GM1_1PNPDK20071227_112546_000001202064_00338_30452_8401.N1						SS1	H/H	64	30452	338	4.05
ASA_GM1_1PNPDK20071227_112955_000002232064_00338_30452_8403.N1						SS1	H/H	64	30452	338	4.05
ASA_GM1_1PNPDK20071227_121339_000000782064_00338_30452_8405.N1						SS1	H/H	64	30452	338	4.05
ASA_GM1_1PNPDK20071227_122101_000002232064_00338_30452_8410.N1						SS1	H/H	64	30452	338	4.05
ASA_GM1_1PNPDK20071227_123241_000003022064_00338_30452_8418.N1						SS1	H/H	64	30452	338	4.05
ASA_GM1_1PNPDK20071227_125355_000008512064_00339_30453_8428.N1						SS1	H/H	64	30453	339	4.05
ASA_GM1_1PNPDK20071227_130656_000003142064_00339_30453_8529.N1						SS1	H/H	64	30453	339	4.05
ASA_GM1_1PNPDK20071227_131332_000001262064_00339_30453_8531.N1						SS1	H/H	64	30453	339	4.05
ASA_GM1_1PNPDK20071227_133047_000000902064_00339_30453_8533.N1						SS1	H/H	64	30453	339	4.05
ASA_GM1_1PNPDK20071227_133308_000005132064_00339_30453_8535.N1						SS1	H/H	64	30453	339	4.05
ASA_GM1_1PNPDK20071227_134150_000003622064_00339_30453_8537.N1						SS1	H/H	64	30453	339	4.05
ASA_GM1_1PNPDK20071227_134927_000009242064_00339_30453_8546.N1						SS1	H/H	64	30453	339	4.05
ASA_GM1_1PNPDK20071227_141315_000002592064_00339_30453_8544.N1						SS1	H/H	64	30453	339	4.05
ASA_GM1_1PNPDK20071227_143158_000003742064_00340_30454_8556.N1						SS1	H/H	64	30454	340	4.05
ASA_GM1_1PNPDK20071227_143933_000001442064_00340_30454_8548.N1						SS1	H/H	64	30454	340	4.05
ASA_GM1_1PNPDK20071227_144349_000000962064_00340_30454_8561.N1						SS1	H/H	64	30454	340	4.05
ASA_GM1_1PNPDK20071227_144635_000002832064_00340_30454_8662.N1						SS1	H/H	64	30454	340	4.05
ASA_GM1_1PNPDK20071227_145304_000003922064_00340_30454_8664.N1						SS1	H/H	64	30454	340	4.05
ASA_GM1_1PNPDK20071227_153003_000008632064_00340_30454_8672.N1						SS1	H/H	64	30454	340	4.05
ASA_GM1_1PNPDK20071227_160858_000000842064_00341_30455_8674.N1						SS1	H/H	64	30455	341	4.05
ASA_GM1_1PNPDK20071227_161118_000003742064_00341_30455_8676.N1						SS1	H/H	64	30455	341	4.05
ASA_GM1_1PNPDK20071227_162310_000001022064_00341_30455_8683.N1						SS1	H/H	64	30455	341	4.05
ASA_GM1_1PNPDK20071227_162333_000001022064_00341_30455_8790.N1						SS1	H/H	64	30455	341	4.05
ASA_GM1_1PNPDK20071227_162711_000000722064_00341_30455_8788.N1						SS1	H/H	64	30455	341	4.05
ASA_GM1_1PNPDK20071227_163217_000002412064_00341_30455_8792.N1						SS1	H/H	64	30455	341	4.05
ASA_GM1_1PNPDK20071227_163825_000006102064_00341_30455_8794.N1						SS1	H/H	64	30455	341	4.05
ASA_GM1_1PNPDK20071227_171527_000002172064_00341_30455_8796.N1						SS1	H/H	64	30455	341	4.05
ASA_GM1_1PNPDK20071227_172249_000002232064_00341_30455_8801.N1						SS1	H/H	64	30455	341	4.05
ASA_GM1_1PNPDK20071227_175303_000004222064_00342_30456_8803.N1						SS1	H/H	64	30456	342	4.05
ASA_GM1_1PNPDK20071227_180145_000002052064_00342_30456_8912.N1						SS1	H/H	64	30456	342	4.05
ASA_GM1_1PNPDK20071227_181312_000004222064_00342_30456_8914.N1						SS1	H/H	64	30456	342	4.05
ASA_GM1_1PNPDK20071227_185803_000005492064_00342_30456_8922.N1						SS1	H/H	64	30456	342	4.05
ASA_GM1_1PNPDK20071227_192850_000002412064_00343_30457_8924.N1						SS1	H/H	64	30457	343	4.05
ASA_GM1_1PNPDK20071227_193342_000004102064_00343_30457_8934.N1						SS1	H/H	64	30457	343	4.05

ASA_GM1_1PNPDE20071227_193908_000001442064_00343_30457_4140.N1	SS1	H/H	64	30457	343	4.05
ASA_GM1_1PNPDE20071227_194318_000002352064_00343_30457_4138.N1	SS1	H/H	64	30457	343	4.05
ASA_GM1_1PNPDE20071227_194949_000004952064_00343_30457_4151.N1	SS1	H/H	64	30457	343	4.05
ASA_GM1_1PNPDE20071227_203439_000002772064_00343_30457_4153.N1	SS1	H/H	64	30457	343	4.05
ASA_GM1_1PNPDE20071227_204201_000003442064_00343_30457_4166.N1	SS1	H/H	64	30457	343	4.05
ASA_GM1_1PNPDE20071227_205625_000010442064_00343_30457_4312.N1	SS1	H/H	64	30457	343	4.05
ASA_GM1_1PNPDE20071227_212327_000001632064_00344_30458_4287.N1	SS1	H/H	64	30458	344	4.05
ASA_GM1_1PNPDE20071227_212920_000005492064_00344_30458_4298.N1	SS1	H/H	64	30458	344	4.05
ASA_GM1_1PNPDE20071227_221815_000000962064_00344_30458_4300.N1	SS1	H/H	64	30458	344	4.05
ASA_GM1_1PNPDE20071227_222137_000001932064_00344_30458_4307.N1	SS1	H/H	64	30458	344	4.05
ASA_GM1_1PNPDE20071227_224632_000003982064_00345_30459_4449.N1	SS1	H/H	64	30459	345	4.05
ASA_GM1_1PNPDE20071227_230938_000005732064_00345_30459_4464.N1	SS1	H/H	64	30459	345	4.05
ASA_GM1_1PNPDE20071227_234120_000002352064_00345_30459_4474.N1	SS1	H/H	64	30459	345	4.05
ASA_GM1_1PNPDE20071227_234526_000000902064_00345_30459_4476.N1	SS1	H/H	64	30459	345	4.05
ASA_GM1_1PNPDE20071227_235450_000000782064_00345_30459_4469.N1	SS1	H/H	64	30459	345	4.05
ASA_GM1_1PNPDE20071227_235750_000002172064_00345_30459_4486.N1	SS1	H/H	64	30459	345	4.05

Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_IMM_1PNPDE20071227_000944_000000502064_00331_30445_3252.N1						IS6	H/H	64	30445	331	4.05
ASA_IMM_1PNPDE20071227_001732_000000962064_00331_30445_3277.N1						IS6	H/H	64	30445	331	4.05
ASA_IMM_1PNPDE20071227_014803_000000492064_00332_30446_3397.N1						IS7	H/H	64	30446	332	4.05
ASA_IMM_1PNPDE20071227_015507_000001252064_00332_30446_3426.N1						IS6	H/H	64	30446	332	4.05
ASA_IMM_1PNPDE20071227_023530_000000752064_00332_30446_3424.N1						IS2	H/H	64	30446	332	4.05
ASA_IMM_1PNPDE20071227_024827_000000812064_00333_30447_3529.N1						IS2	V/V	64	30447	333	4.05
ASA_IMM_1PNPDE20071227_025905_000000372064_00333_30447_3434.N1						IS3	H/H	64	30447	333	4.05
ASA_IMM_1PNPDE20071227_032124_000000362064_00333_30447_3527.N1						IS2	V/V	64	30447	333	4.05
ASA_IMM_1PNPDE20071227_045709_000000362064_00334_30448_3620.N1						IS2	V/V	64	30448	334	4.05
ASA_IMM_1PNPDK20071227_062846_000001722064_00335_30449_8087.N1						IS2	V/V	64	30449	335	4.05
ASA_IMM_1PNPDK20071227_080651_000000662064_00336_30450_8140.N1						IS2	V/V	64	30450	336	4.05
ASA_IMM_1PNPDK20071227_080907_000004412064_00336_30450_8164.N1						IS2	V/V	64	30450	336	4.05
ASA_IMM_1PNPDK20071227_094712_000003202064_00337_30451_8288.N1						IS2	V/V	64	30451	337	4.05
ASA_IMM_1PNPDK20071227_095538_000001362064_00337_30451_8283.N1						IS2	V/V	64	30451	337	4.05
ASA_IMM_1PNPDE20071227_100551_000001782064_00337_30451_3920.N1						IS2	V/V	64	30451	337	4.05
ASA_IMM_1PNPDK20071227_112747_000001132064_00338_30452_8384.N1						IS2	V/V	64	30452	338	4.05
ASA_IMM_1PNPDK20071227_123148_000000362064_00338_30452_8496.N1						IS1	V/V	64	30452	338	4.05
ASA_IMM_1PNPDK20071227_125052_000000342064_00339_30453_8498.N1						IS3	V/V	64	30453	339	4.05
ASA_IMM_1PNPDK20071227_131209_000000672064_00339_30453_8504.N1						IS2	V/V	64	30453	339	4.05
ASA_IMM_1PNPDE20071227_133215_000000362064_00339_30453_3995.N1						IS2	H/H	64	30453	339	4.05
ASA_IMM_1PNPDE20071227_141045_000000612064_00339_30453_4007.N1						IS6	H/H	64	30453	339	4.05
ASA_IMM_1PNPDE20071227_141045_000001252064_00339_30453_4041.N1						IS6	H/H	64	30453	339	4.05
ASA_IMM_1PNPDE20071227_141246_000000042064_00339_30453_4011.N1						IS6	***	64	30453	339	4.05
ASA_IMM_1PNPDE20071227_142145_000000362064_00339_30453_4003.N1						IS2	H/H	64	30453	339	4.05
ASA_IMM_1PNPDE20071227_143810_000000652064_00340_30454_4021.N1						IS2	V/V	64	30454	340	4.05
ASA_IMM_1PNPDK20071227_144156_000000962064_00340_30454_8644.N1						IS2	V/V	64	30454	340	4.05
ASA_IMM_1PNPDK20071227_144527_000000512064_00340_30454_8638.N1						IS2	V/V	64	30454	340	4.05
ASA_IMM_1PNPDE20071227_145934_000000622064_00340_30454_4017.N1						IS2	V/V	64	30454	340	4.05
ASA_IMM_1PNPDE20071227_145934_000001122064_00340_30454_4043.N1						IS2	V/V	64	30454	340	4.05
ASA_IMM_1PNPDE20071227_155753_000001712064_00340_30454_4039.N1						IS6	H/H	64	30454	340	4.05
ASA_IMM_1PNPDE20071227_161026_000000362064_00341_30455_4023.N1						IS3	V/V	64	30455	341	4.05
ASA_IMM_1PNPDK20071227_162016_000001572064_00341_30455_8770.N1						IS2	V/V	64	30455	341	4.05
ASA_IMM_1PNPDK20071227_162518_000000962064_00341_30455_8772.N1						IS2	V/V	64	30455	341	4.05
ASA_IMM_1PNPDE20071227_175125_000000612064_00342_30456_4063.N1						IS6	V/V	64	30456	342	4.05
ASA_IMM_1PNPDE20071227_175125_000000812064_00342_30456_4089.N1						IS6	V/V	64	30456	342	4.05
ASA_IMM_1PNPDK20071227_180007_000000812064_00342_30456_8893.N1						IS2	V/V	64	30456	342	4.05
ASA_IMM_1PNPDK20071227_180507_000001282064_00342_30456_8895.N1						IS2	V/V	64	30456	342	4.05
ASA_IMM_1PNPDE20071227_182015_000000372064_00342_30456_4095.N1						IS6	V/V	64	30456	342	4.05
ASA_IMM_1PNPDE20071227_182130_000001422064_00342_30456_4106.N1						IS2	V/V	64	30456	342	4.05
ASA_IMM_1PNPDE20071227_193250_000000362064_00343_30457_4108.N1						IS2	V/V	64	30457	343	4.05
ASA_IMM_1PNPDK20071227_194131_000000902064_00343_30457_9010.N1						IS2	V/V	64	30457	343	4.05
ASA_IMM_1PNPDE20071227_200842_000000612064_00343_30457_4234.N1						IS6	V/V	64	30457	343	4.05
ASA_IMM_1PNPDK20071227_212608_000001752064_00344_30458_9044.N1						IS2	H/H	64	30458	344	4.05
ASA_IMM_1PNPDE20071227_220405_000000622064_00344_30458_4416.N1						IS6	H/H	64	30458	344	4.05
ASA_IMM_1PNPDE20071227_220506_000000022064_00344_30458_4393.N1						IS6	***	64	30458	344	4.05
ASA_IMM_1PNPDK20071227_230425_000000662064_00345_30459_9056.N1						IS2	V/V	64	30459	345	4.05


Filename	Pol	Timestamp	count(Module)
ASA_MS__0PNPDK20071227_070655_000000162064_00335_30449_0444.N1	H	2007-12-27 07:06:55	320





Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WSM_1PNPDE20071227_003614_000001842064_00331_30445_3279.N1						SS1	H/H	64	30445	331	4.05
ASA_WSM_1PNPDE20071227_003614_000003422064_00331_30445_3446.N1						SS1	H/H	64	30445	331	4.05
ASA_WSM_1PNPDE20071227_004019_000000962064_00331_30445_3280.N1						SS1	H/H	64	30445	331	4.05
ASA_WSM_1PNPDE20071227_011341_000003862064_00332_30446_3551.N1						SS1	H/H	64	30446	332	4.05
ASA_WSM_1PNPDE20071227_013952_000000852064_00332_30446_3444.N1						SS1	V/V	64	30446	332	4.05
ASA_WSM_1PNPDE20071227_020329_000002632064_00332_30446_3448.N1						SS1	H/H	64	30446	332	4.05
ASA_WSM_1PNPDE20071227_024614_000001042064_00333_30447_3549.N1						SS1	V/V	64	30447	333	4.05
ASA_WSM_1PNPDE20071227_030546_000001832064_00333_30447_3559.N1						SS1	V/V	64	30447	333	4.05
ASA_WSM_1PNPDE20071227_034605_000003242064_00333_30447_3624.N1						SS1	H/H	64	30447	333	4.05
ASA_WSM_1PNPDE20071227_035326_000000672064_00333_30447_3628.N1						SS1	H/H	64	30447	333	4.05
ASA_WSM_1PNPDE20071227_035326_000004712064_00333_30447_3796.N1						SS1	H/H	64	30447	333	4.05
ASA_WSM_1PNPDE20071227_035535_000003422064_00333_30447_3724.N1						SS1	H/H	64	30447	333	4.05
ASA_WSM_1PNPDE20071227_043954_000002082064_00334_30448_3722.N1						SS1	H/H	64	30448	334	4.05
ASA_WSM_1PNPDE20071227_052442_000002022064_00334_30448_3855.N1						SS1	H/H	64	30448	334	4.05
ASA_WSM_1PNPDE20071227_052550_000000612064_00334_30448_3713.N1						SS1	H/H	64	30448	334	4.05
ASA_WSM_1PNPDE20071227_053142_000001292064_00334_30448_3895.N1						SS1	H/H	64	30448	334	4.05
ASA_WSM_1PNPDE20071227_053142_000005872064_00334_30448_3910.N1						SS1	H/H	64	30448	334	4.05
ASA_WSM_1PNPDE20071227_053446_000004032064_00334_30448_3896.N1						SS1	H/H	64	30448	334	4.05
ASA_WSM_1PNPDE20071227_054203_000001042064_00334_30448_3859.N1						SS1	H/H	64	30448	334	4.05
ASA_WSM_1PNPDK20071227_062630_000000862064_00335_30449_8089.N1						SS1	H/H	64	30449	335	4.05
ASA_WSM_1PNPDE20071227_063636_000000862064_00335_30449_3857.N1						SS1	H/H	64	30449	335	4.05
ASA_WSM_1PNPDE20071227_063835_000000862064_00335_30449_3881.N1						SS1	V/V	64	30449	335	4.05
ASA_WSM_1PNPDE20071227_070518_000000862064_00335_30449_3883.N1						SS1	H/H	64	30449	335	4.05
ASA_WSM_1PNPDK20071227_084557_000000672064_00336_30450_8173.N1						SS1	H/H	64	30450	336	4.05
ASA_WSM_1PNPDK20071227_095433_000000672064_00337_30451_8256.N1						SS1	V/V	64	30451	337	4.05
ASA_WSM_1PNPDE20071227_102930_000003672064_00337_30451_3942.N1						SS1	H/H	64	30451	337	4.05
ASA_WSM_1PNPDE20071227_102930_000004032064_00337_30451_3991.N1						SS1	H/H	64	30451	337	4.05
ASA_WSM_1PNPDE20071227_103651_000003672064_00337_30451_3978.N1						SS1	H/H	64	30451	337	4.05
ASA_WSM_1PNPDE20071227_103651_000005182064_00337_30451_3989.N1						SS1	H/H	64	30451	337	4.05
ASA_WSM_1PNPDE20071227_104359_000000912064_00337_30451_3979.N1						SS1	H/H	64	30451	337	4.05
ASA_WSM_1PNPDE20071227_120705_000003852064_00338_30452_3993.N1						SS1	H/H	64	30452	338	4.05
ASA_WSM_1PNPDE20071227_120812_000003182064_00338_30452_3986.N1						SS1	H/H	64	30452	338	4.05
ASA_WSM_1PNPDK20071227_121505_000000672064_00338_30452_8506.N1						SS1	H/H	64	30452	338	4.05
ASA_WSM_1PNPDK20071227_121505_000003482064_00338_30452_8539.N1						SS1	H/H	64	30452	338	4.05
ASA_WSM_1PNPDK20071227_121714_000002192064_00338_30452_8527.N1						SS1	H/H	64	30452	338	4.05
ASA_WSM_1PNPDK20071227_145130_000000852064_00340_30454_8646.N1						SS1	H/H	64	30454	340	4.05
ASA_WSM_1PNPDE20071227_154439_000001582064_00340_30454_4031.N1						SS1	H/H	64	30454	340	4.05
ASA_WSM_1PNPDE20071227_161740_000001402064_00341_30455_4045.N1						SS1	H/H	64	30455	341	4.05
ASA_WSM_1PNPDK20071227_162834_000001592064_00341_30455_8786.N1						SS1	H/H	64	30455	341	4.05
ASA_WSM_1PNPDE20071227_163027_000000672064_00341_30455_4055.N1						SS1	H/H	64	30455	341	4.05
ASA_WSM_1PNPDE20071227_163027_000000972064_00341_30455_4098.N1						SS1	H/H	64	30455	341	4.05
ASA_WSM_1PNPDE20071227_163626_000001092064_00341_30455_4087.N1						SS1	H/H	64	30455	341	4.05
ASA_WSM_1PNPDE20071227_170853_000003852064_00341_30455_4091.N1						SS1	H/H	64	30455	341	4.05
ASA_WSM_1PNPDE20071227_171915_000002012064_00341_30455_4071.N1						SS1	H/H	64	30455	341	4.05
ASA_WSM_1PNPDK20071227_180806_000001282064_00342_30456_8910.N1						SS1	H/H	64	30456	342	4.05
ASA_WSM_1PNPDE20071227_181138_000000672064_00342_30456_4067.N1						SS1	H/H	64	30456	342	4.05
ASA_WSM_1PNPDE20071227_181138_000000852064_00342_30456_4093.N1						SS1	H/H	64	30456	342	4.05
ASA_WSM_1PNPDE20071227_184929_000005002064_00342_30456_4136.N1						SS1	H/H	64	30456	342	4.05
ASA_WSM_1PNPDE20071227_191654_000001462064_00342_30456_4134.N1						SS1	V/V	64	30456	342	4.05
ASA_WSM_1PNPDE20071227_192448_000002322064_00343_30457_4277.N1						SS1	H/H	64	30457	343	4.05
ASA_WSM_1PNPDK20071227_194726_000001282064_00343_30457_9015.N1						SS1	H/H	64	30457	343	4.05
ASA_WSM_1PNPDE20071227_203005_000001832064_00343_30457_4275.N1						SS1	H/H	64	30457	343	4.05
ASA_WSM_1PNPDE20071227_203005_000002632064_00343_30457_4305.N1						SS1	H/H	64	30457	343	4.05
ASA_WSM_1PNPDE20071227_203927_000001462064_00343_30457_4252.N1						SS1	H/H	64	30457	343	4.05
ASA_WSM_1PNPDE20071227_205242_000000672064_00343_30457_4244.N1						SS1	V/V	64	30457	343	4.05
ASA_WSM_1PNPDE20071227_205242_000002132064_00343_30457_4385.N1						SS1	V/V	64	30457	343	4.05
ASA_WSM_1PNPDE20071227_205450_000000852064_00343_30457_4273.N1						SS1	V/V	64	30457	343	4.05
ASA_WSM_1PNPDK20071227_211718_000003612064_00344_30458_9046.N1						SS1	V/V	64	30458	344	4.05
ASA_WSM_1PNPDE20071227_214611_000000852064_00344_30458_4418.N1						SS1	V/V	64	30458	344	4.05
ASA_WSM_1PNPDE20071227_221041_000001282064_00344_30458_4442.N1						SS1	H/H	64	30458	344	4.05
ASA_WSM_1PNPDE20071227_221041_000004462064_00344_30458_4601.N1						SS1	H/H	64	30458	344	4.05
ASA_WSM_1PNPDE20071227_221344_000002632064_00344_30458_4443.N1						SS1	H/H	64	30458	344	4.05
ASA_WSM_1PNPDE20071227_222003_000000852064_00344_30458_4395.N1						SS1	H/H	64	30458	344	4.05
ASA_WSM_1PNPDE20071227_222110_000000182064_00344_30458_4281.N1						SS1	H/H	64	30458	344	4.05
ASA_WSM_1PNPDE20071227_222503_000002792064_00344_30458_4560.N1						SS1	H/H	64	30458	344	4.05
ASA_WSM_1PNPDE20071227_222610_000002132064_00344_30458_4436.N1						SS1	H/H	64	30458	344	4.05
ASA_WSM_1PNPDK20071227_230611_000000912064_00345_30459_9058.N1						SS1	H/H	64	30459	345	4.05


ASA_WSM_1PNPDE20071227_230704_000001402064_00345_30459_4893.N1	SS1	H/H	64	30459	345	4.05
ASA_WSM_1PNPDE20071227_230811_000000722064_00345_30459_4581.N1	SS1	H/H	64	30459	345	4.05
ASA_WSM_1PNPDE20071227_235117_000002012064_00345_30459_4889.N1	SS1	H/H	64	30459	345	4.05
ASA_WSM_1PNPDE20071227_235224_000001332064_00345_30459_4603.N1	SS1	H/H	64	30459	345	4.05
ASA_WSM_1PNPDE20071227_235617_000000672064_00345_30459_4438.N1	SS1	H/H	64	30459	345	4.05
ASA_WSM_1PNPDE20071227_235617_000000852064_00345_30459_4570.N1	SS1	H/H	64	30459	345	4.05




Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WVS_1PNPDE20071226_235311_000009592064_00331_30445_3146.N1						IS2	V/V	64	30445	331	4.05
ASA_WVS_1PNPDE20071227_001914_000002702064_00331_30445_3151.N1						IS2	V/V	64	30445	331	4.05
ASA_WVS_1PNPDE20071227_004155_000003152064_00331_30445_3154.N1						IS2	V/V	64	30445	331	4.05
ASA_WVS_1PNPDE20071227_004625_000003742064_00331_30445_3286.N1						IS2	V/V	64	30445	331	4.05
ASA_WVS_1PNPDE20071227_005658_000009442064_00331_30445_3289.N1						IS2	V/V	64	30445	331	4.05
ASA_WVS_1PNPDE20071227_014214_000003142064_00332_30446_3292.N1						IS2	V/V	64	30446	332	4.05
ASA_WVS_1PNPDE20071227_014859_000002542064_00332_30446_3295.N1						IS2	V/V	64	30446	332	4.05
ASA_WVS_1PNPDE20071227_015719_000003152064_00332_30446_3306.N1						IS2	V/V	64	30446	332	4.05
ASA_WVS_1PNPDE20071227_022113_000000442064_00332_30446_3311.N1						IS2	V/V	64	30446	332	4.05
ASA_WVS_1PNPDE20071227_022113_000003302064_00332_30446_3474.N1						IS2	V/V	64	30446	332	4.05
ASA_WVS_1PNPDE20071227_022113_000000442064_00332_30446_3311.N1						IS1	V/V	64	30446	332	4.05
ASA_WVS_1PNPDE20071227_024132_000002392064_00333_30447_3471.N1						IS2	V/V	64	30447	333	4.05
ASA_WVS_1PNPDE20071227_032433_000008242064_00333_30447_3477.N1						IS2	V/V	64	30447	333	4.05
ASA_WVS_1PNPDE20071227_033748_000002402064_00333_30447_3564.N1						IS2	V/V	64	30447	333	4.05
ASA_WVS_1PNPDE20071227_032433_000008242064_00333_30447_3477.N1						IS1	V/V	64	30447	333	4.05
ASA_WVS_1PNPDE20071227_040535_000010042064_00333_30447_3583.N1						IS2	V/V	64	30447	333	4.05
ASA_WVS_1PNPDE20071227_050501_000009292064_00334_30448_3618.N1						IS2	V/V	64	30448	334	4.05
ASA_WVS_1PNPDE20071227_052016_000002102064_00334_30448_3730.N1						IS2	V/V	64	30448	334	4.05
ASA_WVS_1PNPDE20071227_054344_000015142064_00334_30448_3765.N1						IS2	V/V	64	30448	334	4.05
ASA_WVS_1PNPDE20071227_065025_000001042064_00335_30449_3770.N1						IS2	V/V	64	30449	335	4.05
ASA_WVS_1PNPDE20071227_065503_000002692064_00335_30449_3786.N1						IS2	V/V	64	30449	335	4.05
ASA_WVS_1PNPDK20071227_065903_000003302064_00335_30449_8092.N1						IS2	V/V	64	30449	335	4.05
ASA_WVS_1PNPDK20071227_072302_000019642064_00335_30449_8102.N1						IS2	V/V	64	30449	335	4.05
ASA_WVS_1PNPDK20071227_083729_000004652064_00336_30450_8176.N1						IS2	V/V	64	30450	336	4.05
ASA_WVS_1PNPDK20071227_090337_000020242064_00336_30450_8181.N1						IS2	V/V	64	30450	336	4.05
ASA_WVS_1PNPDK20071227_101001_000010492064_00337_30451_8300.N1						IS2	V/V	64	30451	337	4.05
ASA_WVS_1PNPDK20071227_104532_000017542064_00337_30451_8305.N1						IS2	V/V	64	30451	337	4.05
ASA_WVS_1PNPDK20071227_113339_000019492064_00338_30452_8413.N1						IS2	V/V	64	30452	338	4.05
ASA_WVS_1PNPDK20071227_122449_000003752064_00338_30452_8408.N1						IS2	V/V	64	30452	338	4.05
ASA_WVS_1PNPDK20071227_123746_000007442064_00338_30452_8416.N1						IS2	V/V	64	30452	338	4.05
ASA_WVS_1PNPDK20071227_125134_000000892064_00339_30453_8421.N1						IS2	V/V	64	30453	339	4.05
ASA_WVS_1PNPDK20071227_131538_000008542064_00339_30453_8542.N1						IS2	V/V	64	30453	339	4.05
ASA_WVS_1PNPDK20071227_140525_000002852064_00339_30453_8551.N1						IS2	V/V	64	30453	339	4.05
ASA_WVS_1PNPDK20071227_141737_000002092064_00339_30453_8554.N1						IS2	V/V	64	30453	339	4.05
ASA_WVS_1PNPDK20071227_142228_000002842064_00339_30453_8559.N1						IS2	V/V	64	30453	339	4.05
ASA_WVS_1PNPDK20071227_150155_000016342064_00340_30454_8670.N1						IS2	V/V	64	30454	340	4.05
ASA_WVS_1PNPDK20071227_154719_000006002064_00340_30454_8667.N1						IS2	V/V	64	30454	340	4.05
ASA_WVS_1PNPDK20071227_160051_000004342064_00340_30454_8686.N1						IS2	V/V	64	30454	340	4.05
ASA_WVS_1PNPDK20071227_164837_000011692064_00341_30455_8799.N1						IS2	V/V	64	30455	341	4.05
ASA_WVS_1PNPDK20071227_172637_000013942064_00341_30455_8811.N1						IS2	V/V	64	30455	341	4.05
ASA_WVS_1PNPDK20071227_182359_000014842064_00342_30456_8917.N1						IS2	V/V	64	30456	342	4.05
ASA_WVS_1PNPDK20071227_190713_000005252064_00342_30456_8920.N1						IS2	V/V	64	30456	342	4.05
ASA_WVS_1PNPDK20071227_191917_000002242064_00342_30456_8932.N1						IS2	V/V	64	30456	342	4.05
ASA_WVS_1PNPDE20071227_195803_000005992064_00343_30457_4143.N1						IS2	V/V	64	30457	343	4.05
ASA_WVS_1PNPDE20071227_200951_000011692064_00343_30457_4156.N1						IS2	V/V	64	30457	343	4.05
ASA_WVS_1PNPDE20071227_204749_000000742064_00343_30457_4164.N1						IS2	V/V	64	30457	343	4.05
ASA_WVS_1PNPDE20071227_204804_000002252064_00343_30457_4290.N1						IS2	V/V	64	30457	343	4.05
ASA_WVS_1PNPDE20071227_204749_000000742064_00343_30457_4164.N1						IS1	V/V	64	30457	343	4.05
ASA_WVS_1PNPDE20071227_213830_000004042064_00344_30458_4293.N1						IS2	V/V	64	30458	344	4.05
ASA_WVS_1PNPDE20071227_214735_000009442064_00344_30458_4296.N1						IS2	V/V	64	30458	344	4.05
ASA_WVS_1PNPDE20071227_220516_000002702064_00344_30458_4303.N1						IS2	V/V	64	30458	344	4.05
ASA_WVS_1PNPDE20071227_222943_000002702064_00344_30458_4310.N1						IS2	V/V	64	30458	344	4.05
ASA_WVS_1PNPDE20071227_223313_000007492064_00344_30458_4447.N1						IS2	V/V	64	30458	344	4.05
ASA_WVS_1PNPDE20071227_225314_000005692064_00345_30459_4452.N1						IS2	V/V	64	30459	345	4.05
ASA_WVS_1PNPDE20071227_231911_000012742064_00345_30459_4472.N1						IS2	V/V	64	30459	345	4.05
ASA_WVS_1PNPDE20071227_234658_000002102064_00345_30459_4467.N1						IS2	V/V	64	30459	345	4.05

















































27-Dec




27-Dec




27-Dec




27-Dec




27-Dec




27-Dec






27-Dec



27-Dec



27-Dec

