



# ASAR Daily Report



Analysis from 15-APR-2008 00:00:00 to 15-APR-2008 23:59:59. Page generated on 16-APR-2008 07:50:09.  
View log file: ASAR\_Daily\_Report\_20080416\_0730.log. For any anomalies please contact [mtranfaglia@serco.it](mailto:mtranfaglia@serco.it), [gscarpino@serco.it](mailto:gscarpino@serco.it).

This report is automatically generated every day, every 2 hours. No comments are provided on the results.

## SUMMARY

1. DATA SUMMARY
  - 1.1 Summary tables
  - 1.2 Lists of products used
2. AUXILIARY FILES ANALYSIS
  - 2.1 IECF operational ADFs list
  - 2.2 Products with wrong ADFs
3. MODULE STEPPING PRODUCTS ANALYSIS
  - 3.1 V/V polarisation
  - 3.2 H/H polarisation
4. CALIBRATION PULSES ANALYSIS
  - 4.1 Analysis for WVS IS2 V/V
    - 4.1.1 Temporal Evolution Analysis for WVS IS2 V/V
    - 4.1.2 All Rows Analysis for WVS IS2 V/V
  - 4.2 Analysis for GM1 SS3 H/H
    - 4.2.1 Temporal Evolution Analysis for GM1 SS3 H/H
    - 4.2.2 All Rows Analysis for GM1 SS3 H/H
5. DOPPLER ANALYSIS
  - 5.1 Analysis for WVS IS2 V/V
    - 5.1.1 Doppler MAP Analysis for WVS IS2 V/V
    - 5.1.2 Doppler ANX Analysis for WVS IS2 V/V
  - 5.2 Analysis for GM1 SS1 H/H
    - 5.2.1 Doppler MAP Analysis for GM1 SS1 H/H
    - 5.2.2 Doppler ANX Analysis for GM1 SS1 H/H
  - 5.3 Doppler JUMPS Analysis for WSM
6. CHIRP ANALYSIS
  - 6.1 Analysis for WSM SS1 H/H
    - 6.1.1 ScaleFactor
  - 6.2 Analysis for WSM SS1 V/V
    - 6.2.1 ScaleFactor
7. RAW DATA ANALYSIS
  - 7.1 Analysis for WVS
  - 7.2 Analysis for IMM
8. TELEMETRY ANALYSIS
  - 8.1 Number of Missing Lines
  - 8.2 Number of Gaps

---

## 1 - DATA SUMMARY

### 1.1 - Summary tables

[ [BACK TO MENU](#) ]

WVS				GM1				APM				IMM				WSM				MS			
Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Time	Pol	Modules
PDE	IS1	V/V	6	PDE	WS	H/H	51	PDE	IS1	H/H	4	PDE	IS1	V/V	2	PDE	WS	H/H	38	PDE	2008-04-15 04:28:50	V	320
PDE	IS2	V/V	44	PDK	WS	H/H	38	PDE	IS4	H/H	3	PDE	IS2	V/V	13	PDE	WS	V/V	9				
PDK	IS2	V/V	25					PDE	IS6	H/H	1	PDE	IS4	H/H	1								
								PDK	IS1	H/V	1	PDE	IS5	H/H	1								
												PDE	IS5	V/V	2								
												PDE	IS6	V/V	5								
												PDE	IS7	H/H	2								
												PDK	IS2	V/V	2								
												PDK	IS4	V/V	1								

## 1.2 - Lists of products used

[ [BACK TO MENU](#) ]

[[TXT](#)] [[XLS](#)] [List\\_WVS\\_products\\_used](#)  
 [[TXT](#)] [[XLS](#)] [List\\_GM1\\_products\\_used](#)  
 [[TXT](#)] [[XLS](#)] [List\\_APM\\_products\\_used](#)  
 [[TXT](#)] [[XLS](#)] [List\\_IMM\\_products\\_used](#)  
 [[TXT](#)] [[XLS](#)] [List\\_WSM\\_products\\_used](#)  
 [[TXT](#)] [[XLS](#)] [List\\_MS\\_products\\_used](#)

## 2 - AUXILIARY FILES ANALYSIS

### 2.1 - IECF operational ADFs list

[ [BACK TO MENU](#) ]

ADFs disseminated for ASAR
ASA_CON_AXVIEC20071218_084201_20070204_165113_20081231_000000
ASA_INS_AXVIEC20071218_083603_20070307_060000_20081231_000000
ASA_XCH_AXVIEC20051219_162547_20020301_000000_20081231_000000
ASA_XCA_AXVIEC20071218_082742_20070204_165113_20081231_000000

### 2.2 - Products with wrong ADFs

[ [BACK TO MENU](#) ]



Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
WVS	0	0	0	0
GM1	0	0	0	0
APM	0	0	0	0
IMM	0	0	0	0
WSM	0	0	0	0

[[TXT](#)] [[XLS](#)] [Check\\_ADFs\\_WVS](#)  
 [[TXT](#)] [[XLS](#)] [Check\\_ADFs\\_GM1](#)  
 [[TXT](#)] [[XLS](#)] [Check\\_ADFs\\_APM](#)  
 [[TXT](#)] [[XLS](#)] [Check\\_ADFs\\_IMM](#)  
 [[TXT](#)] [[XLS](#)] [Check\\_ADFs\\_WSM](#)

### 3 - MODULE STEPPING PRODUCTS ANALYSIS












### 3.2 - H/H polarisation

[ [BACK TO MENU](#) ]

SECOND FIXED REFERENCE	PREVIOUS PRODUCT REFERENCE
After antenna maintenance (2005-09-22/23)	Previous product in the same polarisation







## 4 - CALIBRATION PULSES ANALYSIS

### 4.1 - Analysis for WVS IS2 V/V

#### 4.1.1 - Temporal Evolution Analysis for WVS IS2 V/V


[ BACK TO MENU ]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]




Calibration pulses for WVS IS2 V/V




15-Apr



15-Apr




15-Apr



15-Apr


rows: \_ 1 \_ 5 \_ 9 \_ 13 \_ 17 \_ 21 \_ 25 \_ 29

Transmit power (P1 - P1a) for WVS IS2 V/V



15-Apr

Transmit power (P1 - P1a) for WVS IS2 V/V




15-Apr

rows: \_ 1 \_ 5 \_ 9 \_ 13 \_ 17 \_ 21 \_ 25 \_ 29

#### 4.1.2 - All Rows Analysis for WVS IS2 V/V

[ [BACK TO MENU](#) ]





## 4.2 - Analysis for GM1 SS3 H/H

### 4.2.1 - Temporal Evolution Analysis for GM1 SS3 H/H


[ BACK TO MENU ]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]



Calibration pulses for GM1 SS3 H/H




Transmit power (P1 - P1a) for GM1 SS3 H/H



#### 4.2.2 - All Rows Analysis for GM1 SS3 H/H

[ [BACK TO MENU](#) ]





## 5 - DOPPLER ANALYSIS


### 5.1 - Analysis for WVS IS2 V/V

#### 5.1.1 - Doppler MAP Analysis for WVS IS2 V/V

[ [BACK TO MENU](#) ]








### 5.1.2 - Doppler ANX Analysis for WVS IS2 V/V

[ [BACK TO MENU](#) ]






## 5.2 - Analysis for GM1 SS1 H/H

### 5.2.1 - Doppler MAP Analysis for GM1 SS1 H/H

[ [BACK TO MENU](#) ]








### 5.2.2 - Doppler ANX Analysis for GM1 SS1 H/H

[ [BACK TO MENU](#) ]






### 5.3 - Doppler JUMPS Analysis for WSM

[ [BACK TO MENU](#) ]

--	--







## 6 - CHIRP ANALYSIS

### 6.1 - Analysis for WSM SS1 H/H

#### 6.1.1 - ScaleFactor

[ [BACK TO MENU](#) ]







## 6.2 - Analysis for WSM SS1 V/V

### 6.2.1 - ScaleFactor

[ [BACK TO MENU](#) ]






## 7 - RAW DATA ANALYSIS

### 7.1 - Analysis for WVS

[ [BACK TO MENU](#) ]

--	--	--







Channel	Statistics	DSS-B
MEAN I	mean	0.000558560
	stdev	1.64116e-07
MEAN Q	mean	0.000516839
	stdev	2.26881e-07
Channel	Statistics	DSS-B
STDEV I	mean	0.138530
	stdev	0.00110530
STDEV Q	mean	0.138944
	stdev	0.00112384

## 7.2 - Analysis for IMM

[ [BACK TO MENU](#) ]





## 8 - TELEMETRY ANALYSIS


Processing Center	Product	Gaps	Missing lines
PDE	ASA_WSM_1PNPDE20080415_150736_00000672067_00412_32029_1678.N1	0	11

### 8.1 - Number of Missing lines

[ [BACK TO MENU](#) ]








## 8.2 - Number of Gaps

[ [BACK TO MENU](#) ]



#####  
ASAR DAILY REPORT for 080415  
#####

MODE: DAILY  
ANALYSIS: ALL  
DATE: YESTERDAY

Analysis will be performed from 2008-04-15 00:00:00 to 2008-04-15 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/080415/

DATA SUMMARY

#####  
Summary will be performed from 2008-04-15 00:00:00 to 2008-04-15 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/080415/DATA\_SUMMARY

Creating directory ./RESULTS/DAILY/080415/DATA\_SUMMARY...  
Writing file ./RESULTS/DAILY/080415/DATA\_SUMMARY/Data\_summary.html...

\*\*\*\*\*  
Getting WVS products list from 2008-04-15 00:00:00 to 2008-04-15 23:59:59...  
Writing file ./RESULTS/DAILY/080415/DATA\_SUMMARY/List\_WVS\_products\_used.xls...  
Writing file ./RESULTS/DAILY/080415/DATA\_SUMMARY/List\_WVS\_products\_used.txt...

\*\*\*\*\*  
Getting GM1 products list from 2008-04-15 00:00:00 to 2008-04-15 23:59:59...  
Writing file ./RESULTS/DAILY/080415/DATA\_SUMMARY/List\_GM1\_products\_used.xls...  
Writing file ./RESULTS/DAILY/080415/DATA\_SUMMARY/List\_GM1\_products\_used.txt...

\*\*\*\*\*  
Getting APM products list from 2008-04-15 00:00:00 to 2008-04-15 23:59:59...  
Writing file ./RESULTS/DAILY/080415/DATA\_SUMMARY/List\_APM\_products\_used.xls...  
Writing file ./RESULTS/DAILY/080415/DATA\_SUMMARY/List\_APM\_products\_used.txt...

\*\*\*\*\*  
Getting IMM products list from 2008-04-15 00:00:00 to 2008-04-15 23:59:59...  
Writing file ./RESULTS/DAILY/080415/DATA\_SUMMARY/List\_IMM\_products\_used.xls...  
Writing file ./RESULTS/DAILY/080415/DATA\_SUMMARY/List\_IMM\_products\_used.txt...

\*\*\*\*\*  
Getting WSM products list from 2008-04-15 00:00:00 to 2008-04-15 23:59:59...  
Writing file ./RESULTS/DAILY/080415/DATA\_SUMMARY/List\_WSM\_products\_used.xls...  
Writing file ./RESULTS/DAILY/080415/DATA\_SUMMARY/List\_WSM\_products\_used.txt...

\*\*\*\*\*  
Getting MS products list from 2008-04-15 00:00:00 to 2008-04-15 23:59:59...  
Writing file ./RESULTS/DAILY/080415/DATA\_SUMMARY/List\_MS\_products\_used.xls...  
Writing file ./RESULTS/DAILY/080415/DATA\_SUMMARY/List\_MS\_products\_used.txt...

DATA SUMMARY completed  
#####

AUXILIARY FILES ANALYSIS

#####  
Analysis will be performed from 2008-04-15 00:00:00 to 2008-04-15 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/080415/AUXILIARY

Creating directory ./RESULTS/DAILY/080415/AUXILIARY...

\*\*\*\*\*  
Looking for the IECF operational ADFs list...





Found list 20080415\_030001\_current\_3\_IECF\_ADFs.txt...  
Extracting ADFs...

ASA\_CON\_AXVIEC20071218\_084201\_20070204\_165113\_20081231\_000000  
ASA\_INS\_AXVIEC20071218\_083603\_20070307\_060000\_20081231\_000000  
ASA\_XCH\_AXVIEC20051219\_162547\_20020301\_000000\_20081231\_000000  
ASA\_XCA\_AXVIEC20071218\_082742\_20070204\_165113\_20081231\_000000

Writing file ./RESULTS/DAILY/080415/AUXILIARY/ASAR\_ADFs\_IECF\_List3.html...  
Writing file ./RESULTS/DAILY/080415/AUXILIARY/Auxiliary\_files\_summary.html...

\*\*\*\*\*  
Analysing WVS products...

Writing file ./RESULTS/DAILY/080415/AUXILIARY/Check\_ADFs\_WVS.xls...  
Writing file ./RESULTS/DAILY/080415/AUXILIARY/Check\_ADFs\_WVS.txt...

ASA_WVS_1PNPDE20080415_003411_000011432067_00403_32020_2541.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080415_003411_000011432067_00403_32020_3089.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080415_010032_000003902067_00403_32020_2528.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080415_010032_000003902067_00403_32020_3080.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080415_012344_000002552067_00403_32020_2525.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080415_012344_000002552067_00403_32020_3077.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080415_012714_000002852067_00403_32020_2513.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080415_012714_000002852067_00403_32020_2814.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080415_014224_000007042067_00404_32021_2518.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080415_014224_000007042067_00404_32021_2817.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080415_022650_000011842067_00404_32021_2474.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080415_022650_000011842067_00404_32021_2787.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080415_024605_00000902067_00404_32021_2359.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080415_024605_00000902067_00404_32021_2754.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080415_030420_000002102067_00404_32021_2233.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080415_030420_000002102067_00404_32021_2708.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080415_032414_000001942067_00405_32022_2109.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080415_032414_000001942067_00405_32022_2682.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080415_040615_000009442067_00405_32022_2106.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080415_040615_000009442067_00405_32022_2622.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080415_042144_000001352067_00405_32022_3460.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080415_042144_000001352067_00405_32022_3808.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080415_042705_00000602067_00405_32022_3466.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080415_042705_00000602067_00405_32022_3811.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080415_044456_000012742067_00405_32022_3864.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080415_054530_000010642067_00406_32023_3867.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080415_204214_000019192067_00415_32032_2905.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080415_204214_000019192067_00415_32032_3333.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080415_213055_000002092067_00415_32032_2900.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080415_213055_000002092067_00415_32032_3346.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080415_213340_000001042067_00415_32032_3033.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080415_213340_000001042067_00415_32032_3545.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080415_214312_000002992067_00415_32032_3040.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080415_214312_000002992067_00415_32032_3556.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080415_220222_000001052067_00416_32033_3057.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080415_220222_000001052067_00416_32033_3559.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080415_222130_000019942067_00416_32033_3072.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080415_222130_000019942067_00416_32033_3570.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080415_231131_000003602067_00416_32033_3256.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080415_231131_000003602067_00416_32033_3582.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080415_231646_000012892067_00416_32033_3689.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080415_233956_000003452067_00417_32034_3676.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080415_060300_000003452067_00406_32023_0721.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080415_062532_000019642067_00406_32023_0738.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080415_074515_000002402067_00407_32024_0808.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080415_080608_000012592067_00407_32024_0811.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080415_082917_000006742067_00408_32025_0837.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080415_091353_000009592067_00408_32025_1040.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080415_094644_000019342067_00408_32025_1105.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK





ASA_GM1_1PNPDE20080415_213940_000002112067_00415_32032_3035.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080415_213940_000002112067_00415_32032_3553.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080415_214903_000003502067_00416_32033_3063.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080415_214903_000003502067_00416_32033_3567.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080415_225815_000001382067_00416_32033_3061.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080415_225815_000001382067_00416_32033_3563.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080415_230401_000004472067_00416_32033_3253.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080415_230401_000004472067_00416_32033_3592.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080415_235131_000004222067_00417_32034_3673.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080415_235131_000004222067_00417_32034_4123.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080415_060934_000009242067_00406_32023_0735.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080415_070814_000002592067_00407_32024_0757.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080415_071157_000003742067_00407_32024_0801.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080415_072715_000000662067_00407_32024_0803.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080415_073015_000006882067_00407_32024_0805.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080415_075252_000007912067_00407_32024_0813.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080415_084120_000003742067_00408_32025_0896.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080415_085048_000001202067_00408_32025_0840.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080415_085208_000000662067_00408_32025_1035.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080415_090944_000002472067_00408_32025_1037.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080415_093428_000007312067_00408_32025_1048.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080415_104621_000001872067_00409_32026_1218.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080415_111121_000009242067_00409_32026_1223.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080415_120034_000001872067_00410_32027_1230.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080415_125157_000009242067_00410_32027_1350.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080415_131352_000004652067_00410_32027_1352.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080415_133945_000003622067_00411_32028_1366.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080415_135204_000004472067_00411_32028_1547.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080415_141231_000002772067_00411_32028_1549.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080415_141841_000001322067_00411_32028_1554.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080415_143233_000009242067_00411_32028_1564.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080415_145535_000002112067_00411_32028_1559.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080415_150859_000002652067_00412_32029_1568.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080415_151809_000000782067_00412_32029_1566.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080415_152128_000001142067_00412_32029_1578.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080415_153514_000007552067_00412_32029_1707.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080415_155006_000001322067_00412_32029_1712.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080415_161309_000009242067_00412_32029_1717.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080415_164843_000003562067_00413_32030_1719.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080415_165548_000001932067_00413_32030_1729.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080415_171853_000005792067_00413_32030_1837.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080415_175345_000001202067_00413_32030_1835.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080415_175927_000006162067_00413_32030_1842.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080415_183114_000003082067_00414_32031_1844.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080415_190028_000001262067_00414_32031_1960.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080415_193903_000006762067_00414_32031_1962.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080415_200153_000005732067_00414_32031_1967.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080415_201603_000000842067_00415_32032_1974.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

\*\*\*\*\*

Analysing APM products...

Writing file ./RESULTS/DAILY/080415/AUXILIARY/Check\_ADFs\_APM.xls...

Writing file ./RESULTS/DAILY/080415/AUXILIARY/Check\_ADFs\_APM.txt...

ASA_APM_1PNPDE20080415_031727_000000422067_00404_32021_2093.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20080415_031727_000000422067_00404_32021_2548.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20080415_040413_000000702067_00405_32022_2397.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20080415_040413_000000702067_00405_32022_2784.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20080415_072822_000000852067_00407_32024_1325.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20080415_165440_000000412067_00413_32030_1708.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20080415_172833_000000422067_00413_32030_2083.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20080415_172833_000000422067_00413_32030_2141.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDK20080415_133537_000002212067_00411_32028_1457.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

\*\*\*\*\*

Analysing IMM products...

Writing file ./RESULTS/DAILY/080415/AUXILIARY/Check\_ADFs\_IMM.xls...

Writing file ./RESULTS/DAILY/080415/AUXILIARY/Check\_ADFs\_IMM.txt...

ASA_IMM_1PNPDE20080415_021938_000000822067_00404_32021_2809.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080415_021938_000000822067_00404_32021_2823.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080415_022351_000000812067_00404_32021_2805.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080415_022351_000000812067_00404_32021_2807.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080415_031339_000000352067_00404_32021_2099.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080415_031339_000000352067_00404_32021_2550.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080415_034157_000000372067_00405_32022_2097.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080415_034157_000000372067_00405_32022_2365.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080415_090752_000000952067_00408_32025_1279.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080415_104150_000001222067_00409_32026_1340.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080415_104150_000002532067_00409_32026_1380.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080415_104452_000000712067_00409_32026_1341.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080415_104925_000000912067_00409_32026_1295.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080415_141708_000000742067_00411_32028_1672.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080415_151328_000000352067_00412_32029_1676.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080415_155524_000000842067_00412_32029_1716.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080415_171513_000000372067_00413_32030_1941.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080415_171513_000000372067_00413_32030_2111.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080415_183625_000000352067_00414_32031_2095.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080415_183625_000000352067_00414_32031_2143.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080415_183720_000001252067_00414_32031_2502.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080415_183720_000001252067_00414_32031_2532.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080415_201126_000000802067_00415_32032_3059.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080415_201126_000000802067_00415_32032_3424.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080415_215454_000000802067_00416_32033_3335.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080415_215454_000000802067_00416_32033_3542.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20080415_082750_000000792067_00408_32025_0920.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20080415_183947_000001942067_00414_32031_1929.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20080415_201953_000001132067_00415_32032_2054.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

\*\*\*\*\*

Analysing WSM products...

Writing file ./RESULTS/DAILY/080415/AUXILIARY/Check\_ADFs\_WSM.xls...

Writing file ./RESULTS/DAILY/080415/AUXILIARY/Check\_ADFs\_WSM.txt...

ASA_WSM_1PNPDE20080415_002658_000001042067_00403_32020_2858.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080415_002658_000001042067_00403_32020_2864.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080415_011622_000002632067_00403_32020_3011.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080415_011622_000002632067_00403_32020_3037.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080415_020144_000003482067_00404_32021_2922.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080415_020144_000003482067_00404_32021_2988.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080415_022201_000000972067_00404_32021_2862.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080415_022201_000000972067_00404_32021_2873.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080415_033423_000004282067_00405_32022_2395.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080415_033423_000004282067_00405_32022_2758.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080415_040018_000002392067_00405_32022_2510.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080415_040018_000002392067_00405_32022_2811.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080415_052852_000003542067_00406_32023_3341.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080415_071821_000001032067_00407_32024_1328.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080415_074152_000002012067_00407_32024_1330.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080415_093154_000001402067_00408_32025_1362.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080415_101948_000003852067_00409_32026_1382.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080415_120350_000001762067_00410_32027_1462.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080415_123458_000005182067_00410_32027_1666.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080415_150736_000000672067_00412_32029_1678.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080415_151534_000001472067_00412_32029_1758.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080415_151934_000001042067_00412_32029_1754.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080415_152332_000001032067_00412_32029_1756.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK



ASA_WSM_1PNPDE20080415_165912_000001642067_00413_32030_2178.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080415_171320_000000852067_00413_32030_2181.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080415_171620_000001462067_00413_32030_2379.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080415_171620_000001462067_00413_32030_2536.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080415_175554_000002012067_00413_32030_2391.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080415_175554_000002012067_00413_32030_2543.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080415_185332_000000862067_00414_32031_2624.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080415_185332_000000862067_00414_32031_2751.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080415_185426_000003542067_00414_32031_3231.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080415_193529_000002022067_00414_32031_3211.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080415_193529_000002022067_00414_32031_3263.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080415_203159_000000912067_00415_32032_3251.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080415_203159_000000912067_00415_32032_3506.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080415_203405_000003362067_00415_32032_3343.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080415_203405_000003362067_00415_32032_3565.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080415_204019_000001152067_00415_32032_3422.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080415_204019_000001152067_00415_32032_3561.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080415_213610_000001712067_00415_32032_3443.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080415_213610_000001712067_00415_32032_3584.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080415_221122_000001842067_00416_32033_3498.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080415_221512_000003672067_00416_32033_3533.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080415_225641_000000852067_00416_32033_3508.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080415_230041_000001842067_00416_32033_3445.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080415_230041_000001842067_00416_32033_3654.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

AUXILIARY FILES ANALYSIS completed

#####

MODULE STEPPING ANALYSIS

#####

Analysis will be performed from 2008-04-15 00:00:00 to 2008-04-15 23:59:59

Results will be exported to the directory: ./RESULTS/DAILY/080415/MODULE\_STEPPING

Creating directory ./RESULTS/DAILY/080415/MODULE\_STEPPING...

Creating directory ./RESULTS/DAILY/080415/MODULE\_STEPPING/FIRST\_REFERENCE...

Creating directory ./RESULTS/DAILY/080415/MODULE\_STEPPING/SECOND\_REFERENCE...

Creating directory ./RESULTS/DAILY/080415/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE...

Deleting old files...

\*\*\*\*\*  
\*\*\*\*\*

Creating images comparing with second reference...

Exporting results to the directory ../../RESULTS/DAILY/080415/MODULE\_STEPPING/SECOND\_REFERENCE...

Polarization: H

Reference product: ASA\_MS\_0PNPDK20050922\_062651\_00000152041\_00034\_18625\_0041.N1

Test product: ASA\_MS\_0PNPDE20080414\_050027\_00000162067\_00391\_32008\_0276.N1

H

H

../../RESULTS/DAILY/080415/MODULE\_STEPPING/SECOND\_REFERENCE/TGH\_20080414\_050027-20050922\_062651.png

../../RESULTS/DAILY/080415/MODULE\_STEPPING/SECOND\_REFERENCE/TPH\_20080414\_050027-20050922\_062651.png

../../RESULTS/DAILY/080415/MODULE\_STEPPING/SECOND\_REFERENCE/RGH\_20080414\_050027-20050922\_062651.png

../../RESULTS/DAILY/080415/MODULE\_STEPPING/SECOND\_REFERENCE/RPH\_20080414\_050027-20050922\_062651.png

Polarization: V

Reference product: ASA\_MS\_0PNPDK20050923\_055514\_00000152041\_00048\_18639\_0042.N1

Test product: ASA\_MS\_0PNPDE20080415\_042850\_00000162067\_00405\_32022\_0277.N1

V

V

../../RESULTS/DAILY/080415/MODULE\_STEPPING/SECOND\_REFERENCE/TGV\_20080415\_042850-20050923\_055514.png

../../RESULTS/DAILY/080415/MODULE\_STEPPING/SECOND\_REFERENCE/TPV\_20080415\_042850-20050923\_055514.png

../../RESULTS/DAILY/080415/MODULE\_STEPPING/SECOND\_REFERENCE/RGV\_20080415\_042850-20050923\_055514.png

../../RESULTS/DAILY/080415/MODULE\_STEPPING/SECOND\_REFERENCE/RPV\_20080415\_042850-20050923\_055514.png

\*\*\*\*\*  
\*\*\*\*\*

Creating images comparing with previous product reference...

Exporting results to the directory ../../RESULTS/DAILY/080415/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE...

Polarization: H

Reference product: ASA\_MS\_\_0PNPDK20080412\_060341\_000000162067\_00363\_31980\_0523.N1

Test product: ASA\_MS\_\_0PNPDE20080414\_050027\_000000162067\_00391\_32008\_0276.N1

H

H

../../RESULTS/DAILY/080415/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/TGH\_20080414\_050027-20080412\_060341.png

../../RESULTS/DAILY/080415/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/TPH\_20080414\_050027-20080412\_060341.png

../../RESULTS/DAILY/080415/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/RGH\_20080414\_050027-20080412\_060341.png

../../RESULTS/DAILY/080415/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/RPH\_20080414\_050027-20080412\_060341.png

Polarization: V

Reference product: ASA\_MS\_\_0PNPDE20080413\_053204\_000000162067\_00377\_31994\_0275.N1

Test product: ASA\_MS\_\_0PNPDE20080415\_042850\_000000162067\_00405\_32022\_0277.N1

V

V

../../RESULTS/DAILY/080415/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/TGV\_20080415\_042850-20080413\_053204.png

../../RESULTS/DAILY/080415/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/TPV\_20080415\_042850-20080413\_053204.png

../../RESULTS/DAILY/080415/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/RGV\_20080415\_042850-20080413\_053204.png

../../RESULTS/DAILY/080415/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/RPV\_20080415\_042850-20080413\_053204.png

MODULE\_STEPPING ANALYSIS completed

#####

CALIBRATION PULSES ANALYSIS

#####

Creating directory ./RESULTS/DAILY/080415/CALIBRATION\_PULSES...

\*\*\*\*\*

\*\*\*\*\*

ALL ROWS Analysis will be performed from 2008-04-15 00:00:00 to 2008-04-15 23:59:59

Analysing products WVS IS2 V/V

Writing image ../../RESULTS/DAILY/080415//CALIBRATION\_PULSES/Calibration\_pulses\_all\_rows\_WVS\_IS2\_VV.png...

Analysing products GM1 SS3 H/H

Writing image ../../RESULTS/DAILY/080415//CALIBRATION\_PULSES/Calibration\_pulses\_all\_rows\_GM1\_SS3\_HH.png...

\*\*\*\*\*

\*\*\*\*\*

TEMPORAL EVOLUTION Analysis will be performed from 2008-04-15 00:00:00 to 2008-04-15 23:59:59

Analysing products WVS IS2 V/V

Getting calibration pulses data for WVS IS2 V/V from 2008-04-15 00:00:00 to 2008-04-15 23:59:59. Rows: 1/5/9/13/17/21/25/29

Writing file ./RESULTS/DAILY/080415/CALIBRATION\_PULSES/Calibration\_pulses\_data\_WVS\_IS2\_VV\_2008-04-15\_1.dat...

Writing ../../RESULTS/DAILY/080415//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_WVS\_IS2\_VV\_1.png...

Writing ../../RESULTS/DAILY/080415//CALIBRATION\_PULSES/Transmit\_Power\_WVS\_IS2\_VV\_1.png...

Getting calibration pulses data for WVS IS2 V/V from 2008-04-15 00:00:00 to 2008-04-15 23:59:59. Rows: 2/6/10/14/18/22/26/30

Writing file ./RESULTS/DAILY/080415/CALIBRATION\_PULSES/Calibration\_pulses\_data\_WVS\_IS2\_VV\_2008-04-15\_2.dat...

Writing ../../RESULTS/DAILY/080415//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_WVS\_IS2\_VV\_2.png...

Writing ../../RESULTS/DAILY/080415//CALIBRATION\_PULSES/Transmit\_Power\_WVS\_IS2\_VV\_2.png...

Getting calibration pulses data for WVS IS2 V/V from 2008-04-15 00:00:00 to 2008-04-15 23:59:59. Rows: 3/7/11/15/19/23/27/31

Writing file ./RESULTS/DAILY/080415/CALIBRATION\_PULSES/Calibration\_pulses\_data\_WVS\_IS2\_VV\_2008-04-15\_3.dat...

Writing ../../RESULTS/DAILY/080415//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_WVS\_IS2\_VV\_3.png...



Writing ../../RESULTS/DAILY/080415//CALIBRATION\_PULSES/Transmit\_Power\_WVS\_IS2\_VV\_3.png...

Getting calibration pulses data for WVS IS2 V/V from 2008-04-15 00:00:00 to 2008-04-15 23:59:59. Rows: 4/8/12/16/20/24/28/32

Writing file ./RESULTS/DAILY/080415/CALIBRATION\_PULSES/Calibration\_pulses\_data\_WVS\_IS2\_VV\_2008-04-15\_4.dat...

Writing ../../RESULTS/DAILY/080415//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_WVS\_IS2\_VV\_4.png...

Writing ../../RESULTS/DAILY/080415//CALIBRATION\_PULSES/Transmit\_Power\_WVS\_IS2\_VV\_4.png...

Analysing products GM1 SS3 H/H

Getting calibration pulses data for GM1 SS3 H/H from 2008-04-15 00:00:00 to 2008-04-15 23:59:59. Rows: 1/5/9/13/17/21/25/29

Writing file ./RESULTS/DAILY/080415/CALIBRATION\_PULSES/Calibration\_pulses\_data\_GM1\_SS3\_HH\_2008-04-15\_1.dat...

Writing ../../RESULTS/DAILY/080415//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_GM1\_SS3\_HH\_1.png...

Writing ../../RESULTS/DAILY/080415//CALIBRATION\_PULSES/Transmit\_Power\_GM1\_SS3\_HH\_1.png...

Getting calibration pulses data for GM1 SS3 H/H from 2008-04-15 00:00:00 to 2008-04-15 23:59:59. Rows: 2/6/10/14/18/22/26/30

Writing file ./RESULTS/DAILY/080415/CALIBRATION\_PULSES/Calibration\_pulses\_data\_GM1\_SS3\_HH\_2008-04-15\_2.dat...

Writing ../../RESULTS/DAILY/080415//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_GM1\_SS3\_HH\_2.png...

Writing ../../RESULTS/DAILY/080415//CALIBRATION\_PULSES/Transmit\_Power\_GM1\_SS3\_HH\_2.png...

Getting calibration pulses data for GM1 SS3 H/H from 2008-04-15 00:00:00 to 2008-04-15 23:59:59. Rows: 3/7/11/15/19/23/27/31

Writing file ./RESULTS/DAILY/080415/CALIBRATION\_PULSES/Calibration\_pulses\_data\_GM1\_SS3\_HH\_2008-04-15\_3.dat...

Writing ../../RESULTS/DAILY/080415//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_GM1\_SS3\_HH\_3.png...

Writing ../../RESULTS/DAILY/080415//CALIBRATION\_PULSES/Transmit\_Power\_GM1\_SS3\_HH\_3.png...

Getting calibration pulses data for GM1 SS3 H/H from 2008-04-15 00:00:00 to 2008-04-15 23:59:59. Rows: 4/8/12/16/20/24/28/32

Writing file ./RESULTS/DAILY/080415/CALIBRATION\_PULSES/Calibration\_pulses\_data\_GM1\_SS3\_HH\_2008-04-15\_4.dat...

Writing ../../RESULTS/DAILY/080415//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_GM1\_SS3\_HH\_4.png...

Writing ../../RESULTS/DAILY/080415//CALIBRATION\_PULSES/Transmit\_Power\_GM1\_SS3\_HH\_4.png...

CALIBRATION PULSES ANALYSIS completed

#####

DOPPLER ANALYSIS

#####

Creating directory ./RESULTS/DAILY/080415/DOPPLER...

\*\*\*\*\*  
\*\*\*\*\*

DOPPLER ANX Analysis will be performed from 2008-04-15 00:00:00 to 2008-04-15 23:59:59

Analysing products WVS IS2 V/V

Getting doppler data for WVS IS2 V/V from 2008-04-15 00:00:00 to 2008-04-15 23:59:59...

Writing file ./RESULTS/DAILY/080415/DOPPLER/Doppler\_data\_WVS\_IS2\_VV\_2008-04-15.dat...

Running IDL program...

Writing file ../../RESULTS/DAILY/080415/DOPPLER/DOPPLER\_ANX\_WVS\_IS2\_VV.png...

Analysing products GM1 SS1 H/H

Getting doppler data for GM1 SS1 H/H from 2008-04-15 00:00:00 to 2008-04-15 23:59:59...

Writing file ./RESULTS/DAILY/080415/DOPPLER/Doppler\_data\_GM1\_SS1\_HH\_2008-04-15.dat...

Running IDL program...

Writing file ../../RESULTS/DAILY/080415/DOPPLER/DOPPLER\_ANX\_GM1\_SS1\_HH.png...

\*\*\*\*\*  
\*\*\*\*\*

DOPPLER JUMPS Analysis will be performed on WSM products from 2008-04-15 00:00:00 to 2008-04-15 23:59:59

```
Analysing by default products WSM
Getting doppler jumps data for WSM from 2008-04-15 00:00:00 to 2008-04-15 23:59:59...
Writing file ./RESULTS/DAILY/080415/DOPPLER/Doppler_Jumps_data_WSM_2008-04-15.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/080415/DOPPLER/DOPPLER_JUMPS_ANX_WSM.png...
Writing file ../../RESULTS/DAILY/080415/DOPPLER/DOPPLER_JUMPS_Date_WSM.png...
```

```
*****
*****
DOPPLER MAP Analysis will be performed from 2008-04-15 00:00:00 to 2008-04-15 23:59:59
```

```
Analysing products WVS IS2 V/V
Loading predicted doppler values....
Phase: descending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -25.653430 Hz
Writing file ../../RESULTS/DAILY/080415//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_WVS_IS2_VV_desc.jpg...
Writing file ../../RESULTS/DAILY/080415//DOPPLER/DOPPLER_Absolute_WVS_IS2_VV_desc.jpg...
```

```
*****
Loading predicted doppler values....
Phase: ascending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -17.762731 Hz
Writing file ../../RESULTS/DAILY/080415//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_WVS_IS2_VV_asc.jpg...
Writing file ../../RESULTS/DAILY/080415//DOPPLER/DOPPLER_Absolute_WVS_IS2_VV_asc.jpg...
```

```
*****
Analysing products GM1 SS1 H/H
Loading predicted doppler values....
Phase: descending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -21.944596 Hz
Writing file ../../RESULTS/DAILY/080415//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_GM1_SS1_HH_desc.jpg...
Writing file ../../RESULTS/DAILY/080415//DOPPLER/DOPPLER_Absolute_GM1_SS1_HH_desc.jpg...
```

```
*****
Loading predicted doppler values....
Phase: ascending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -24.368871 Hz
Writing file ../../RESULTS/DAILY/080415//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_GM1_SS1_HH_asc.jpg...
Writing file ../../RESULTS/DAILY/080415//DOPPLER/DOPPLER_Absolute_GM1_SS1_HH_asc.jpg...
```

```
*****
DOPPLER ANALYSIS completed
#####
```

```
CHIRP ANALYSIS
#####
Creating directory ./RESULTS/DAILY/080415/CHIRP...
```

```
*****
*****
CHIRP Analysis will be performed from 2008-04-15 00:00:00 to 2008-04-15 23:59:59
```



Analysing products WSM SS1 H/H

```
*****
Getting ScaleFactor data for WSM SS1 H/H from 2008-04-15 00:00:00 to 2008-04-15 23:59:59...
Writing file ./RESULTS/DAILY/080415/CHIRP/ScaleFactor_data_WSM_SS1_HH_2008-04-15.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/080415/CHIRP/ScaleFactor_ANX_WSM_SS1_HH.png...
Writing file ../../RESULTS/DAILY/080415/CHIRP/ScaleFactor_DATE_WSM_SS1_HH.png...
```

Analysing products WSM SS1 V/V

```
*****
Getting ScaleFactor data for WSM SS1 V/V from 2008-04-15 00:00:00 to 2008-04-15 23:59:59...
Writing file ./RESULTS/DAILY/080415/CHIRP/ScaleFactor_data_WSM_SS1_VV_2008-04-15.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/080415/CHIRP/ScaleFactor_ANX_WSM_SS1_VV.png...
Writing file ../../RESULTS/DAILY/080415/CHIRP/ScaleFactor_DATE_WSM_SS1_VV.png...
```

CHIRP ANALYSIS completed

#####

RAW DATA ANALYSIS

```
#####
Analysis will be performed from 2008-04-15 00:00:00 to 2008-04-15 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/080415/RAW_DATA
```

Creating directory ./RESULTS/DAILY/080415/RAW\_DATA...

\*\*\*\*\*

```
Getting raw data for WVS from 2008-04-15 00:00:00 to 2008-04-15 23:59:59...
Writing file ./RESULTS/DAILY/080415/RAW_DATA/Raw_data_WVS_2008-04-15.dat...
Running IDL program to create graphs...
```

```
Creating image ../../RESULTS/DAILY/080415/RAW_DATA/Raw_data_WVS_input_mean.png...
Creating image ../../RESULTS/DAILY/080415/RAW_DATA/Raw_data_WVS_input_stdev.png...
Creating image ../../RESULTS/DAILY/080415/RAW_DATA/Raw_data_WVS_gain_imbalance.png...
```

\*\*\*\*\*

```
Getting raw data for IMM from 2008-04-15 00:00:00 to 2008-04-15 23:59:59...
Writing file ./RESULTS/DAILY/080415/RAW_DATA/Raw_data_IMM_2008-04-15.dat...
Running IDL program to create graphs...
```

```
Creating image ../../RESULTS/DAILY/080415/RAW_DATA/Raw_data_IMM_input_mean.png...
Creating image ../../RESULTS/DAILY/080415/RAW_DATA/Raw_data_IMM_input_stdev.png...
Creating image ../../RESULTS/DAILY/080415/RAW_DATA/Raw_data_IMM_gain_imbalance.png...
```

RAW DATA ANALYSIS completed

#####

TELEMETRY ANALYSIS

```
#####
Analysis will be performed from 2008-04-15 00:00:00 to 2008-04-15 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/080415/TELEMETRY
```

Creating directory ./RESULTS/DAILY/080415/TELEMETRY...

Looking for gaps and missing lines in WVS products...

\*\*\*\*\*

```
Checking 44 products from PDE...
Checking 25 products from PDK...
```

Looking for gaps and missing lines in GM1 products...

\*\*\*\*\*

Checking 51 products from PDE...  
Checking 38 products from PDK...

Looking for gaps and missing lines in APM products...

\*\*\*\*\*

Checking 8 products from PDE...  
Checking 1 products from PDK...

Looking for gaps and missing lines in IMM products...

\*\*\*\*\*

Checking 26 products from PDE...  
Checking 3 products from PDK...

Looking for gaps and missing lines in WSM products...

\*\*\*\*\*

Checking 47 products from PDE...  
Found product...ASA\_WSM\_1PNPDE20080415\_150736\_00000672067\_00412\_32029\_1678.N1 / 0 gaps / 11 missing lines  
No products from PDK...

Creating graph of missing lines and gaps...

\*\*\*\*\*

Creating image: ./RESULTS/DAILY/080415/TELEMETRY/TELEMETRY\_Missing\_lines.png...  
Creating image: ./RESULTS/DAILY/080415/TELEMETRY/TELEMETRY\_Gaps.png...

TELEMETRY ANALYSIS completed

#####

BROWSE PRODUCTS ANALYSIS

#####

Analysis will be performed on 2008-04-15

\*\*\*\*\*

Scanning directory /nas3/ENVISAT/ASAR//ASA\_GM\_BP...  
Results will be exported to the directory: /nas3/ENVISAT/ASAR//ASA\_GM\_BP/JPG/20080415/

Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20080415\_002854\_000003142067\_00403\_32020\_2535.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20080415\_002854\_000003142067\_00403\_32020\_3087.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20080415\_005406\_000003802067\_00403\_32020\_2539.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20080415\_005406\_000003802067\_00403\_32020\_3085.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20080415\_010746\_000005072067\_00403\_32020\_2531.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20080415\_010746\_000005072067\_00403\_32020\_3083.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20080415\_012056\_000001692067\_00403\_32020\_2523.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20080415\_012056\_000001692067\_00403\_32020\_3075.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20080415\_013351\_000005132067\_00403\_32020\_2521.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20080415\_013351\_000005132067\_00403\_32020\_2822.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20080415\_015454\_000003982067\_00404\_32021\_2516.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20080415\_015454\_000003982067\_00404\_32021\_2820.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20080415\_020741\_000007182067\_00404\_32021\_2412.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20080415\_020741\_000007182067\_00404\_32021\_2778.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20080415\_024822\_000009242067\_00404\_32021\_2362.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20080415\_024822\_000009242067\_00404\_32021\_2757.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20080415\_030837\_000001752067\_00404\_32021\_2354.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20080415\_030837\_000001752067\_00404\_32021\_2711.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20080415\_031145\_000001142067\_00404\_32021\_2352.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20080415\_031145\_000001142067\_00404\_32021\_2713.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20080415\_031432\_000001752067\_00404\_32021\_2348.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20080415\_031432\_000001752067\_00404\_32021\_2701.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20080415\_031834\_000003322067\_00404\_32021\_2236.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20080415\_031834\_000003322067\_00404\_32021\_2699.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20080415\_032821\_000003502067\_00405\_32022\_2244.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20080415\_032821\_000003502067\_00405\_32022\_2697.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20080415\_034252\_000010382067\_00405\_32022\_2394.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20080415\_034252\_000010382067\_00405\_32022\_2761.N1 ...



```
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDE20080415_043014_000008822067_00405_32022_3473.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDE20080415_050703_000001262067_00406_32023_3469.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDE20080415_051022_000001082067_00406_32023_3471.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDE20080415_051418_000001872067_00406_32023_3475.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDE20080415_051834_000001322067_00406_32023_3477.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDE20080415_211457_000009242067_00415_32032_2903.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDE20080415_211457_000009242067_00415_32032_3349.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDE20080415_213940_000002112067_00415_32032_3036.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDE20080415_213940_000002112067_00415_32032_3554.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDE20080415_214903_000003502067_00416_32033_3064.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDE20080415_214903_000003502067_00416_32033_3568.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDE20080415_225815_000001382067_00416_32033_3062.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDE20080415_225815_000001382067_00416_32033_3564.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDE20080415_230401_000004472067_00416_32033_3254.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDE20080415_230401_000004472067_00416_32033_3593.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDK20080415_153514_000007552067_00412_32029_1708.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDK20080415_161309_000009242067_00412_32029_1718.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDK20080415_164843_000003562067_00413_32030_1720.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDK20080415_165548_000001932067_00413_32030_1730.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDK20080415_171853_000005792067_00413_32030_1838.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDK20080415_175345_000001202067_00413_32030_1836.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDK20080415_175927_000006162067_00413_32030_1843.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDK20080415_183114_000003082067_00414_32031_1845.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDK20080415_190028_000001262067_00414_32031_1961.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDK20080415_193903_000006762067_00414_32031_1963.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDK20080415_200153_000005732067_00414_32031_1968.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDK20080415_201603_00000842067_00415_32032_1975.N1 ...
```

ANALYSIS COMPLETED: 55 GM browse products to see...

\*\*\*\*\*

\*\*\*\*\*

Scanning directory /nas3/ENVISAT/ASAR//ASA\_AP\_BP...

Results will be exported to the directory: /nas3/ENVISAT/ASAR//ASA\_AP\_BP/JPG/20080415/

```
Stripping browse product /nas3/ENVISAT/ASAR//ASA_AP_BP/ASA_AP_BPZPDE20080415_031727_000000422067_00404_32021_2094.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_AP_BP/ASA_AP_BPZPDE20080415_031727_000000422067_00404_32021_2549.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_AP_BP/ASA_AP_BPZPDE20080415_040413_000000702067_00405_32022_2398.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_AP_BP/ASA_AP_BPZPDE20080415_040413_000000702067_00405_32022_2785.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_AP_BP/ASA_AP_BPZPDE20080415_072822_000000852067_00407_32024_1326.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_AP_BP/ASA_AP_BPZPDE20080415_165440_000000412067_00413_32030_1709.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_AP_BP/ASA_AP_BPZPDE20080415_172833_000000422067_00413_32030_2084.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_AP_BP/ASA_AP_BPZPDE20080415_172833_000000422067_00413_32030_2142.N1 ...
```

ANALYSIS COMPLETED: 8 AP browse products to see...

\*\*\*\*\*

\*\*\*\*\*

Scanning directory /nas3/ENVISAT/ASAR//ASA\_IM\_BP...

Results will be exported to the directory: /nas3/ENVISAT/ASAR//ASA\_IM\_BP/JPG/20080415/

```
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20080415_021938_000000822067_00404_32021_2810.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20080415_021938_000000822067_00404_32021_2824.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20080415_022351_000000812067_00404_32021_2806.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20080415_022351_000000812067_00404_32021_2808.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20080415_031339_000000352067_00404_32021_2100.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20080415_031339_000000352067_00404_32021_2551.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20080415_034157_000000372067_00405_32022_2098.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20080415_034157_000000372067_00405_32022_2366.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20080415_072024_000003932067_00407_32024_1337.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20080415_090752_000000952067_00408_32025_1280.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20080415_104150_000001222067_00409_32026_1342.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20080415_104150_000002532067_00409_32026_1381.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20080415_104452_000000712067_00409_32026_1343.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20080415_104925_000000912067_00409_32026_1296.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20080415_141708_000000742067_00411_32028_1673.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20080415_151328_000000352067_00412_32029_1677.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20080415_155524_000000842067_00412_32029_1717.N1 ...
```



```
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20080415_171513_000000372067_00413_32030_1942.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20080415_171513_000000372067_00413_32030_2112.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20080415_183625_000000352067_00414_32031_2096.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20080415_183625_000000352067_00414_32031_2144.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20080415_183720_000001252067_00414_32031_2503.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20080415_183720_000001252067_00414_32031_2533.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20080415_201126_000000802067_00415_32032_3060.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20080415_201126_000000802067_00415_32032_3425.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20080415_215454_000000802067_00416_32033_3336.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20080415_215454_000000802067_00416_32033_3543.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDK20080415_183947_000001942067_00414_32031_1930.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDK20080415_201953_000001132067_00415_32032_2055.N1 ...
```

ANALYSIS COMPLETED: 29 IM browse products to see...

\*\*\*\*\*

\*\*\*\*\*

Scanning directory /nas3/ENVISAT/ASAR//ASA\_WS\_BP...

Results will be exported to the directory: /nas3/ENVISAT/ASAR//ASA\_WS\_BP/JPG/20080415/

```
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_002658_000001042067_00403_32020_2859.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_002658_000001042067_00403_32020_2865.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_011622_000002632067_00403_32020_3012.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_011622_000002632067_00403_32020_3038.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_020144_000003482067_00404_32021_2923.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_020144_000003482067_00404_32021_2989.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_022201_000000972067_00404_32021_2863.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_022201_000000972067_00404_32021_2874.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_033423_000000672067_00405_32022_2477.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_033423_000004282067_00405_32022_2396.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_033632_000002982067_00405_32022_2759.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_040018_000002392067_00405_32022_2511.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_040018_000002392067_00405_32022_2812.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_052852_000003542067_00406_32023_3342.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_071821_000001032067_00407_32024_1329.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_074152_000002012067_00407_32024_1331.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_084744_000001702067_00408_32025_1333.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_093154_000001402067_00408_32025_1363.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_101948_000003852067_00409_32026_1383.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_102704_000000852067_00409_32026_1335.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_120350_000001762067_00410_32027_1463.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_123458_000005182067_00410_32027_1667.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_150736_000000672067_00412_32029_1679.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_151534_000001472067_00412_32029_1759.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_151934_000001042067_00412_32029_1755.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_152332_000001032067_00412_32029_1757.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_165912_000001642067_00413_32030_2179.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_171320_000000852067_00413_32030_2182.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_171620_000001462067_00413_32030_2380.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_171620_000001462067_00413_32030_2537.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_175554_000002012067_00413_32030_2392.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_175554_000002012067_00413_32030_2544.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_185332_000000862067_00414_32031_2625.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_185332_000000862067_00414_32031_2752.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_185426_000003542067_00414_32031_3232.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_193529_000002022067_00414_32031_3212.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_193529_000002022067_00414_32031_3264.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_203159_000000912067_00415_32032_3252.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_203159_000000912067_00415_32032_3507.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_203405_000003362067_00415_32032_3566.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_204019_000001152067_00415_32032_3423.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_204019_000001152067_00415_32032_3562.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_213610_000001712067_00415_32032_3444.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_213610_000001712067_00415_32032_3585.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_221122_000001842067_00416_32033_3499.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_221512_000003672067_00416_32033_3534.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_225641_000000852067_00416_32033_3509.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20080415_230041_000001842067_00416_32033_3655.N1 ...
```





Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_BP/ASA\_WS\_BPZPDK20080415\_170250\_000006002067\_00413\_32030\_1834.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_BP/ASA\_WS\_BPZPDK20080415\_184344\_000005432067\_00414\_32031\_1959.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_BP/ASA\_WS\_BPZPDK20080415\_202222\_000000912067\_00415\_32032\_2057.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_BP/ASA\_WS\_BPZPDK20080415\_202419\_000004842067\_00415\_32032\_2090.N1 ...

ANALYSIS COMPLETED: 52 WS browse products to see...  
\*\*\*\*\*

BROWSE PRODUCTS ANALYSIS completed  
#####

HTML REPORT generation  
#####

Building file ./RESULTS/DAILY/080415/asarReport.html...  
Building DATA SUMMARY section...  
Building AUXILIARY FILES ANALYSIS section...  
Building MODULE STEPPING ANALYSIS section...  
Building CALIBRATION PULSES ANALYSIS section...  
Building DOPPLER ANALYSIS section...  
Building CHIRP ANALYSIS section...  
Building RAW DATA ANALYSIS section...  
Building TELEMETRY ANALYSIS section...

HTML REPORT generation completed  
#####



# ASAR Daily Report





Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
ASA_APM_1PNPDE20080415_031727_000000422067_00404_32021_2093.N1				
ASA_APM_1PNPDE20080415_031727_000000422067_00404_32021_2548.N1				
ASA_APM_1PNPDE20080415_040413_000000702067_00405_32022_2397.N1				
ASA_APM_1PNPDE20080415_040413_000000702067_00405_32022_2784.N1				
ASA_APM_1PNPDE20080415_072822_000000852067_00407_32024_1325.N1				
ASA_APM_1PNPDE20080415_165440_000000412067_00413_32030_1708.N1				
ASA_APM_1PNPDE20080415_172833_000000422067_00413_32030_2083.N1				
ASA_APM_1PNPDE20080415_172833_000000422067_00413_32030_2141.N1				
ASA_APM_1PNPDK20080415_133537_000002212067_00411_32028_1457.N1				

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_GM1_1PNPDE20080415_002854_000003142067_00403_32020_2534.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_002854_000003142067_00403_32020_3086.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_005406_000003802067_00403_32020_2538.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_005406_000003802067_00403_32020_3084.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_010746_000005072067_00403_32020_2530.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_010746_000005072067_00403_32020_3082.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_012056_000001692067_00403_32020_2522.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_012056_000001692067_00403_32020_3074.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_013351_000005132067_00403_32020_2520.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_013351_000005132067_00403_32020_2821.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_015454_000003982067_00404_32021_2515.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_015454_000003982067_00404_32021_2819.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_020741_000007182067_00404_32021_2411.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_020741_000007182067_00404_32021_2777.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_024822_000009242067_00404_32021_2361.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_024822_000009242067_00404_32021_2756.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_030837_000001752067_00404_32021_2353.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_030837_000001752067_00404_32021_2710.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_031145_000001142067_00404_32021_2351.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_031145_000001142067_00404_32021_2712.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_031432_000001752067_00404_32021_2347.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_031432_000001752067_00404_32021_2700.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_031834_000003322067_00404_32021_2235.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_031834_000003322067_00404_32021_2698.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_032821_000003502067_00405_32022_2243.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_032821_000003502067_00405_32022_2696.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_034252_000010382067_00405_32022_2393.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_034252_000010382067_00405_32022_2760.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_043014_000008822067_00405_32022_3472.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_043014_000008822067_00405_32022_3813.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_050703_000001262067_00406_32023_3468.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_050703_000001262067_00406_32023_3831.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_051022_000001082067_00406_32023_3470.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_051022_000001082067_00406_32023_3833.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_051418_000001872067_00406_32023_3474.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_051418_000001872067_00406_32023_3835.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_051834_000001322067_00406_32023_3476.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_051834_000001322067_00406_32023_3849.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_053458_000006282067_00406_32023_3869.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_211457_000009242067_00415_32032_2902.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_211457_000009242067_00415_32032_3348.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_213940_000002112067_00415_32032_3035.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_213940_000002112067_00415_32032_3553.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_214903_000003502067_00416_32033_3063.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_214903_000003502067_00416_32033_3567.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_225815_000001382067_00416_32033_3061.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_225815_000001382067_00416_32033_3563.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_230401_000004472067_00416_32033_3253.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_230401_000004472067_00416_32033_3592.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_235131_000004222067_00417_32034_3673.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080415_235131_000004222067_00417_32034_4123.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080415_060934_000009242067_00406_32023_0735.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080415_070814_000002592067_00407_32024_0757.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080415_071157_000003742067_00407_32024_0801.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080415_072715_000000662067_00407_32024_0803.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080415_073015_000006882067_00407_32024_0805.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080415_075252_000007912067_00407_32024_0813.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080415_084120_000003742067_00408_32025_0896.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080415_085048_000001202067_00408_32025_0840.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080415_085208_000000662067_00408_32025_1035.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080415_090944_000002472067_00408_32025_1037.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080415_093428_000007312067_00408_32025_1048.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080415_104621_000001872067_00409_32026_1218.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080415_111121_000009242067_00409_32026_1223.N1					OK	OK	OK	OK



ASA_GM1_1PNPDK20080415_120034_000001872067_00410_32027_1230.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080415_125157_000009242067_00410_32027_1350.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080415_131352_000004652067_00410_32027_1352.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080415_133945_000003622067_00411_32028_1366.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080415_135204_000004472067_00411_32028_1547.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080415_141231_000002772067_00411_32028_1549.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080415_141841_000001322067_00411_32028_1554.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080415_143233_000009242067_00411_32028_1564.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080415_145535_000002112067_00411_32028_1559.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080415_150859_000002652067_00412_32029_1568.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080415_151809_000000782067_00412_32029_1566.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080415_152128_000001142067_00412_32029_1578.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080415_153514_000007552067_00412_32029_1707.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080415_155006_000001322067_00412_32029_1712.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080415_161309_000009242067_00412_32029_1717.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080415_164843_000003562067_00413_32030_1719.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080415_165548_000001932067_00413_32030_1729.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080415_171853_000005792067_00413_32030_1837.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080415_175345_000001202067_00413_32030_1835.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080415_175927_000006162067_00413_32030_1842.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080415_183114_000003082067_00414_32031_1844.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080415_190028_000001262067_00414_32031_1960.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080415_193903_000006762067_00414_32031_1962.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080415_200153_000005732067_00414_32031_1967.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080415_201603_000000842067_00415_32032_1974.N1	OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_IMM_1PNPDE20080415_021938_000000822067_00404_32021_2809.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080415_021938_000000822067_00404_32021_2823.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080415_022351_000000812067_00404_32021_2805.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080415_022351_000000812067_00404_32021_2807.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080415_031339_000000352067_00404_32021_2099.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080415_031339_000000352067_00404_32021_2550.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080415_034157_000000372067_00405_32022_2097.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080415_034157_000000372067_00405_32022_2365.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080415_090752_000000952067_00408_32025_1279.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080415_104150_000001222067_00409_32026_1340.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080415_104150_000002532067_00409_32026_1380.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080415_104452_000000712067_00409_32026_1341.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080415_104925_000000912067_00409_32026_1295.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080415_141708_000000742067_00411_32028_1672.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080415_151328_000000352067_00412_32029_1676.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080415_155524_000000842067_00412_32029_1716.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080415_171513_000000372067_00413_32030_1941.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080415_171513_000000372067_00413_32030_2111.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080415_183625_000000352067_00414_32031_2095.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080415_183625_000000352067_00414_32031_2143.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080415_183720_000001252067_00414_32031_2502.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080415_183720_000001252067_00414_32031_2532.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080415_201126_000000802067_00415_32032_3059.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080415_201126_000000802067_00415_32032_3424.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080415_215454_000000802067_00416_32033_3335.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080415_215454_000000802067_00416_32033_3542.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20080415_082750_000000792067_00408_32025_0920.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20080415_183947_000001942067_00414_32031_1929.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20080415_201953_000001132067_00415_32032_2054.N1					OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WSM_1PNPDE20080415_002658_000001042067_00403_32020_2858.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080415_002658_000001042067_00403_32020_2864.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080415_011622_000002632067_00403_32020_3011.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080415_011622_000002632067_00403_32020_3037.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080415_020144_000003482067_00404_32021_2922.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080415_020144_000003482067_00404_32021_2988.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080415_022201_000000972067_00404_32021_2862.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080415_022201_000000972067_00404_32021_2873.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080415_033423_000004282067_00405_32022_2395.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080415_033423_000004282067_00405_32022_2758.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080415_040018_000002392067_00405_32022_2510.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080415_040018_000002392067_00405_32022_2811.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080415_052852_000003542067_00406_32023_3341.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080415_071821_000001032067_00407_32024_1328.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080415_074152_000002012067_00407_32024_1330.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080415_093154_000001402067_00408_32025_1362.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080415_101948_000003852067_00409_32026_1382.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080415_120350_000001762067_00410_32027_1462.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080415_123458_000005182067_00410_32027_1666.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080415_150736_000000672067_00412_32029_1678.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080415_151534_000001472067_00412_32029_1758.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080415_151934_000001042067_00412_32029_1754.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080415_152332_000001032067_00412_32029_1756.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080415_165912_000001642067_00413_32030_2178.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080415_171320_000000852067_00413_32030_2181.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080415_171620_000001462067_00413_32030_2379.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080415_171620_000001462067_00413_32030_2536.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080415_175554_000002012067_00413_32030_2391.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080415_175554_000002012067_00413_32030_2543.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080415_185332_000000862067_00414_32031_2624.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080415_185332_000000862067_00414_32031_2751.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080415_185426_000003542067_00414_32031_3231.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080415_193529_000002022067_00414_32031_3211.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080415_193529_000002022067_00414_32031_3263.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080415_203159_000000912067_00415_32032_3251.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080415_203159_000000912067_00415_32032_3506.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080415_203405_000003362067_00415_32032_3343.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080415_203405_000003362067_00415_32032_3565.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080415_204019_000001152067_00415_32032_3422.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080415_204019_000001152067_00415_32032_3561.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080415_213610_000001712067_00415_32032_3443.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080415_213610_000001712067_00415_32032_3584.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080415_221122_000001842067_00416_32033_3498.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080415_221512_000003672067_00416_32033_3533.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080415_225641_000000852067_00416_32033_3508.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080415_230041_000001842067_00416_32033_3445.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080415_230041_000001842067_00416_32033_3654.N1					OK	OK	OK	OK




Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WVS_1PNPDE20080415_003411_000011432067_00403_32020_2541.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080415_003411_000011432067_00403_32020_3089.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080415_010032_000003902067_00403_32020_2528.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080415_010032_000003902067_00403_32020_3080.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080415_012344_000002552067_00403_32020_2525.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080415_012344_000002552067_00403_32020_3077.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080415_012714_000002852067_00403_32020_2513.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080415_012714_000002852067_00403_32020_2814.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080415_014224_000007042067_00404_32021_2518.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080415_014224_000007042067_00404_32021_2817.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080415_022650_000011842067_00404_32021_2474.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080415_022650_000011842067_00404_32021_2787.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080415_024605_00000902067_00404_32021_2359.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080415_024605_00000902067_00404_32021_2754.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080415_030420_000002102067_00404_32021_2233.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080415_030420_000002102067_00404_32021_2708.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080415_032414_000001942067_00405_32022_2109.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080415_032414_000001942067_00405_32022_2682.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080415_040615_000009442067_00405_32022_2106.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080415_040615_000009442067_00405_32022_2622.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080415_042144_000001352067_00405_32022_3460.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080415_042144_000001352067_00405_32022_3808.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080415_042705_00000602067_00405_32022_3466.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080415_042705_00000602067_00405_32022_3811.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080415_044456_000012742067_00405_32022_3864.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080415_054530_000010642067_00406_32023_3867.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080415_204214_000019192067_00415_32032_2905.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080415_204214_000019192067_00415_32032_3333.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080415_213055_000002092067_00415_32032_2900.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080415_213055_000002092067_00415_32032_3346.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080415_213340_000001042067_00415_32032_3033.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080415_213340_000001042067_00415_32032_3545.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080415_214312_000002992067_00415_32032_3040.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080415_214312_000002992067_00415_32032_3556.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080415_220222_000001052067_00416_32033_3057.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080415_220222_000001052067_00416_32033_3559.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080415_222130_000019942067_00416_32033_3072.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080415_222130_000019942067_00416_32033_3570.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080415_231131_000003602067_00416_32033_3256.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080415_231131_000003602067_00416_32033_3582.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080415_231646_000012892067_00416_32033_3689.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080415_233956_000003452067_00417_32034_3676.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080415_060300_000003452067_00406_32023_0721.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080415_062532_000019642067_00406_32023_0738.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080415_074515_000002402067_00407_32024_0808.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080415_080608_000012592067_00407_32024_0811.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080415_082917_000006742067_00408_32025_0837.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080415_091353_000009592067_00408_32025_1040.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080415_094644_000019342067_00408_32025_1105.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080415_105134_000011392067_00409_32026_1221.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080415_112720_000019492067_00409_32026_1235.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080415_121637_000010492067_00410_32027_1342.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080415_124439_000003902067_00410_32027_1345.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080415_130756_000003002067_00410_32027_1348.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080415_132136_000007882067_00410_32027_1429.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080415_140231_000005542067_00411_32028_1552.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080415_142057_000006452067_00411_32028_1557.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080415_144832_000003752067_00411_32028_1562.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080415_145911_000004492067_00411_32028_1571.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080415_154752_00000892067_00412_32029_1705.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080415_155220_000001492067_00412_32029_1710.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080415_155655_000009292067_00412_32029_1715.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080415_162908_000011242067_00412_32029_1727.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080415_172921_000014092067_00413_32030_1840.N1					OK	OK	OK	OK

ASA_WVS_1PNPDK20080415_181331_000010192067_00413_32030_1852.N1	OK	OK	OK	OK
ASA_WVS_1PNPDK20080415_190237_000018592067_00414_32031_1965.N1	OK	OK	OK	OK
ASA_WVS_1PNPDK20080415_195020_000006452067_00414_32031_1977.N1	OK	OK	OK	OK




Calibration pulses for GM1 SS3 H/H







Calibration pulses for GM1 SS3 H/H



### Calibration pulses for GM1 SS3 H/H




### Calibration pulses for GM1 SS3 H/H







### Calibration pulses for WVS IS2 V/V



### Calibration pulses for WVS IS2 V/V





### Calibration pulses for WVS IS2 V/V








Calibration pulses for WVS IS2 V/V































rows: \_ 4 \_ 8 \_ 12 \_ 16 \_ 20 \_ 24 \_ 28 \_ 32











rows: **3** **7** **11** **15** **19** **23** **27** **31**







15-Apr  
rows: \_ 4 \_ 8 \_ 12 \_ 16 \_ 20 \_ 24 \_ 28 \_ 32











Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_APM_1PNPDE20080415_031727_000000422067_00404_32021_2093.N1						IS1	H/H	67	32021	404	4.06
ASA_APM_1PNPDE20080415_031727_000000422067_00404_32021_2548.N1						IS1	H/H	67	32021	404	4.06
ASA_APM_1PNPDE20080415_040413_000000702067_00405_32022_2397.N1						IS4	H/H	67	32022	405	4.06
ASA_APM_1PNPDE20080415_040413_000000702067_00405_32022_2784.N1						IS4	H/H	67	32022	405	4.06
ASA_APM_1PNPDE20080415_072822_000000852067_00407_32024_1325.N1						IS4	H/H	67	32024	407	4.06
ASA_APM_1PNPDK20080415_133537_000002212067_00411_32028_1457.N1						IS1	H/V	67	32028	411	4.06
ASA_APM_1PNPDE20080415_165440_000000412067_00413_32030_1708.N1						IS6	H/H	67	32030	413	4.06
ASA_APM_1PNPDE20080415_172833_000000422067_00413_32030_2083.N1						IS1	H/H	67	32030	413	4.06
ASA_APM_1PNPDE20080415_172833_000000422067_00413_32030_2141.N1						IS1	H/H	67	32030	413	4.06

Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_GM1_1PNPDE20080415_002854_000003142067_00403_32020_2534.N1						SS1	H/H	67	32020	403	4.06
ASA_GM1_1PNPDE20080415_002854_000003142067_00403_32020_3086.N1						SS1	H/H	67	32020	403	4.06
ASA_GM1_1PNPDE20080415_005406_000003802067_00403_32020_2538.N1						SS1	H/H	67	32020	403	4.06
ASA_GM1_1PNPDE20080415_005406_000003802067_00403_32020_3084.N1						SS1	H/H	67	32020	403	4.06
ASA_GM1_1PNPDE20080415_010746_000005072067_00403_32020_2530.N1						SS1	H/H	67	32020	403	4.06
ASA_GM1_1PNPDE20080415_010746_000005072067_00403_32020_3082.N1						SS1	H/H	67	32020	403	4.06
ASA_GM1_1PNPDE20080415_012056_000001692067_00403_32020_2522.N1						SS1	H/H	67	32020	403	4.06
ASA_GM1_1PNPDE20080415_012056_000001692067_00403_32020_3074.N1						SS1	H/H	67	32020	403	4.06
ASA_GM1_1PNPDE20080415_013351_000005132067_00403_32020_2821.N1						SS1	H/H	67	32020	403	4.06
ASA_GM1_1PNPDE20080415_013351_000005132067_00403_32020_2520.N1						SS1	H/H	67	32020	403	4.06
ASA_GM1_1PNPDE20080415_015454_000003982067_00404_32021_2819.N1						SS1	H/H	67	32021	404	4.06
ASA_GM1_1PNPDE20080415_015454_000003982067_00404_32021_2515.N1						SS1	H/H	67	32021	404	4.06
ASA_GM1_1PNPDE20080415_020741_000007182067_00404_32021_2777.N1						SS1	H/H	67	32021	404	4.06
ASA_GM1_1PNPDE20080415_020741_000007182067_00404_32021_2411.N1						SS1	H/H	67	32021	404	4.06
ASA_GM1_1PNPDE20080415_024822_000009242067_00404_32021_2361.N1						SS1	H/H	67	32021	404	4.06
ASA_GM1_1PNPDE20080415_024822_000009242067_00404_32021_2756.N1						SS1	H/H	67	32021	404	4.06
ASA_GM1_1PNPDE20080415_030837_000001752067_00404_32021_2353.N1						SS1	H/H	67	32021	404	4.06
ASA_GM1_1PNPDE20080415_030837_000001752067_00404_32021_2710.N1						SS1	H/H	67	32021	404	4.06
ASA_GM1_1PNPDE20080415_031145_000001142067_00404_32021_2351.N1						SS1	H/H	67	32021	404	4.06
ASA_GM1_1PNPDE20080415_031145_000001142067_00404_32021_2712.N1						SS1	H/H	67	32021	404	4.06
ASA_GM1_1PNPDE20080415_031432_000001752067_00404_32021_2347.N1						SS1	H/H	67	32021	404	4.06
ASA_GM1_1PNPDE20080415_031432_000001752067_00404_32021_2700.N1						SS1	H/H	67	32021	404	4.06
ASA_GM1_1PNPDE20080415_031834_000003322067_00404_32021_2235.N1						SS1	H/H	67	32021	404	4.06
ASA_GM1_1PNPDE20080415_031834_000003322067_00404_32021_2698.N1						SS1	H/H	67	32021	404	4.06
ASA_GM1_1PNPDE20080415_032821_000003502067_00405_32022_2243.N1						SS1	H/H	67	32022	405	4.06
ASA_GM1_1PNPDE20080415_032821_000003502067_00405_32022_2696.N1						SS1	H/H	67	32022	405	4.06
ASA_GM1_1PNPDE20080415_034252_000010382067_00405_32022_2393.N1						SS1	H/H	67	32022	405	4.06
ASA_GM1_1PNPDE20080415_034252_000010382067_00405_32022_2760.N1						SS1	H/H	67	32022	405	4.06
ASA_GM1_1PNPDE20080415_043014_000008822067_00405_32022_3472.N1						SS1	H/H	67	32022	405	4.06
ASA_GM1_1PNPDE20080415_043014_000008822067_00405_32022_3813.N1						SS1	H/H	67	32022	405	4.06
ASA_GM1_1PNPDE20080415_050703_000001262067_00406_32023_3468.N1						SS1	H/H	67	32023	406	4.06
ASA_GM1_1PNPDE20080415_050703_000001262067_00406_32023_3831.N1						SS1	H/H	67	32023	406	4.06
ASA_GM1_1PNPDE20080415_051022_000001082067_00406_32023_3470.N1						SS1	H/H	67	32023	406	4.06
ASA_GM1_1PNPDE20080415_051022_000001082067_00406_32023_3833.N1						SS1	H/H	67	32023	406	4.06
ASA_GM1_1PNPDE20080415_051418_000001872067_00406_32023_3474.N1						SS1	H/H	67	32023	406	4.06
ASA_GM1_1PNPDE20080415_051418_000001872067_00406_32023_3835.N1						SS1	H/H	67	32023	406	4.06
ASA_GM1_1PNPDE20080415_051834_000001322067_00406_32023_3476.N1						SS1	H/H	67	32023	406	4.06
ASA_GM1_1PNPDE20080415_051834_000001322067_00406_32023_3849.N1						SS1	H/H	67	32023	406	4.06
ASA_GM1_1PNPDE20080415_053458_000006282067_00406_32023_3869.N1						SS1	H/H	67	32023	406	4.06
ASA_GM1_1PNPDK20080415_060934_000009242067_00406_32023_0735.N1						SS1	H/H	67	32023	406	4.06
ASA_GM1_1PNPDK20080415_070814_000002592067_00407_32024_0757.N1						SS1	H/H	67	32024	407	4.06
ASA_GM1_1PNPDK20080415_071157_000003742067_00407_32024_0801.N1						SS1	H/H	67	32024	407	4.06
ASA_GM1_1PNPDK20080415_072715_000000662067_00407_32024_0803.N1						SS1	H/H	67	32024	407	4.06
ASA_GM1_1PNPDK20080415_073015_000006882067_00407_32024_0805.N1						SS1	H/H	67	32024	407	4.06
ASA_GM1_1PNPDK20080415_075252_000007912067_00407_32024_0813.N1						SS1	H/H	67	32024	407	4.06
ASA_GM1_1PNPDK20080415_084120_000003742067_00408_32025_0896.N1						SS1	H/H	67	32025	408	4.06
ASA_GM1_1PNPDK20080415_085048_000001202067_00408_32025_0840.N1						SS1	H/H	67	32025	408	4.06
ASA_GM1_1PNPDK20080415_085208_000000662067_00408_32025_1035.N1						SS1	H/H	67	32025	408	4.06
ASA_GM1_1PNPDK20080415_090944_000002472067_00408_32025_1037.N1						SS1	H/H	67	32025	408	4.06
ASA_GM1_1PNPDK20080415_093428_000007312067_00408_32025_1048.N1						SS1	H/H	67	32025	408	4.06
ASA_GM1_1PNPDK20080415_104621_000001872067_00409_32026_1218.N1						SS1	H/H	67	32026	409	4.06
ASA_GM1_1PNPDK20080415_111121_000009242067_00409_32026_1223.N1						SS1	H/H	67	32026	409	4.06
ASA_GM1_1PNPDK20080415_120034_000001872067_00410_32027_1230.N1						SS1	H/H	67	32027	410	4.06
ASA_GM1_1PNPDK20080415_125157_000009242067_00410_32027_1350.N1						SS1	H/H	67	32027	410	4.06
ASA_GM1_1PNPDK20080415_131352_000004652067_00410_32027_1352.N1						SS1	H/H	67	32027	410	4.06
ASA_GM1_1PNPDK20080415_133945_000003622067_00411_32028_1366.N1						SS1	H/H	67	32028	411	4.06
ASA_GM1_1PNPDK20080415_135204_000004472067_00411_32028_1547.N1						SS1	H/H	67	32028	411	4.06
ASA_GM1_1PNPDK20080415_141231_000002772067_00411_32028_1549.N1						SS1	H/H	67	32028	411	4.06
ASA_GM1_1PNPDK20080415_141841_000001322067_00411_32028_1554.N1						SS1	H/H	67	32028	411	4.06
ASA_GM1_1PNPDK20080415_143233_000009242067_00411_32028_1564.N1						SS1	H/H	67	32028	411	4.06
ASA_GM1_1PNPDK20080415_145535_000002112067_00411_32028_1559.N1						SS1	H/H	67	32028	411	4.06
ASA_GM1_1PNPDK20080415_150859_000002652067_00412_32029_1568.N1						SS1	H/H	67	32029	412	4.06
ASA_GM1_1PNPDK20080415_151809_000000782067_00412_32029_1566.N1						SS1	H/H	67	32029	412	4.06
ASA_GM1_1PNPDK20080415_152128_000001142067_00412_32029_1578.N1						SS1	H/H	67	32029	412	4.06
ASA_GM1_1PNPDK20080415_153514_000007552067_00412_32029_1707.N1						SS1	H/H	67	32029	412	4.06
ASA_GM1_1PNPDK20080415_155006_000001322067_00412_32029_1712.N1						SS1	H/H	67	32029	412	4.06
ASA_GM1_1PNPDK20080415_161309_000009242067_00412_32029_1717.N1						SS1	H/H	67	32029	412	4.06

ASA_GM1_1PNPDK20080415_164843_000003562067_00413_32030_1719.N1	SS1	H/H	67	32030	413	4.06
ASA_GM1_1PNPDK20080415_165548_000001932067_00413_32030_1729.N1	SS1	H/H	67	32030	413	4.06
ASA_GM1_1PNPDK20080415_171853_000005792067_00413_32030_1837.N1	SS1	H/H	67	32030	413	4.06
ASA_GM1_1PNPDK20080415_175345_000001202067_00413_32030_1835.N1	SS1	H/H	67	32030	413	4.06
ASA_GM1_1PNPDK20080415_175927_000006162067_00413_32030_1842.N1	SS1	H/H	67	32030	413	4.06
ASA_GM1_1PNPDK20080415_183114_000003082067_00414_32031_1844.N1	SS1	H/H	67	32031	414	4.06
ASA_GM1_1PNPDK20080415_190028_000001262067_00414_32031_1960.N1	SS1	H/H	67	32031	414	4.06
ASA_GM1_1PNPDK20080415_193903_000006762067_00414_32031_1962.N1	SS1	H/H	67	32031	414	4.06
ASA_GM1_1PNPDK20080415_200153_000005732067_00414_32031_1967.N1	SS1	H/H	67	32031	414	4.06
ASA_GM1_1PNPDK20080415_201603_000000842067_00415_32032_1974.N1	SS1	H/H	67	32032	415	4.06
ASA_GM1_1PNPDE20080415_211457_000009242067_00415_32032_2902.N1	SS1	H/H	67	32032	415	4.06
ASA_GM1_1PNPDE20080415_211457_000009242067_00415_32032_3348.N1	SS1	H/H	67	32032	415	4.06
ASA_GM1_1PNPDE20080415_213940_000002112067_00415_32032_3035.N1	SS1	H/H	67	32032	415	4.06
ASA_GM1_1PNPDE20080415_213940_000002112067_00415_32032_3553.N1	SS1	H/H	67	32032	415	4.06
ASA_GM1_1PNPDE20080415_214903_000003502067_00416_32033_3063.N1	SS1	H/H	67	32033	416	4.06
ASA_GM1_1PNPDE20080415_214903_000003502067_00416_32033_3567.N1	SS1	H/H	67	32033	416	4.06
ASA_GM1_1PNPDE20080415_225815_000001382067_00416_32033_3061.N1	SS1	H/H	67	32033	416	4.06
ASA_GM1_1PNPDE20080415_225815_000001382067_00416_32033_3563.N1	SS1	H/H	67	32033	416	4.06
ASA_GM1_1PNPDE20080415_230401_000004472067_00416_32033_3253.N1	SS1	H/H	67	32033	416	4.06
ASA_GM1_1PNPDE20080415_230401_000004472067_00416_32033_3592.N1	SS1	H/H	67	32033	416	4.06
ASA_GM1_1PNPDE20080415_235131_000004222067_00417_32034_3673.N1	SS1	H/H	67	32034	417	4.06
ASA_GM1_1PNPDE20080415_235131_000004222067_00417_32034_4123.N1	SS1	H/H	67	32034	417	4.06



Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_IMM_1PNPDE20080415_021938_000000822067_00404_32021_2809.N1						IS1	V/V	67	32021	404	4.06
ASA_IMM_1PNPDE20080415_021938_000000822067_00404_32021_2823.N1						IS1	V/V	67	32021	404	4.06
ASA_IMM_1PNPDE20080415_022351_000000812067_00404_32021_2805.N1						IS2	V/V	67	32021	404	4.06
ASA_IMM_1PNPDE20080415_022351_000000812067_00404_32021_2807.N1						IS2	V/V	67	32021	404	4.06
ASA_IMM_1PNPDE20080415_031339_000000352067_00404_32021_2099.N1						IS6	V/V	67	32021	404	4.06
ASA_IMM_1PNPDE20080415_031339_000000352067_00404_32021_2550.N1						IS6	V/V	67	32021	404	4.06
ASA_IMM_1PNPDE20080415_034157_000000372067_00405_32022_2097.N1						IS7	H/H	67	32022	405	4.06
ASA_IMM_1PNPDE20080415_034157_000000372067_00405_32022_2365.N1						IS7	H/H	67	32022	405	4.06
ASA_IMM_1PNPDK20080415_082750_000000792067_00408_32025_0920.N1						IS4	V/V	67	32025	408	4.06
ASA_IMM_1PNPDE20080415_090752_000000952067_00408_32025_1279.N1						IS2	V/V	67	32025	408	4.06
ASA_IMM_1PNPDE20080415_104150_000001222067_00409_32026_1340.N1						IS2	V/V	67	32026	409	4.06
ASA_IMM_1PNPDE20080415_104150_000002532067_00409_32026_1380.N1						IS2	V/V	67	32026	409	4.06
ASA_IMM_1PNPDE20080415_104452_000000712067_00409_32026_1341.N1						IS2	V/V	67	32026	409	4.06
ASA_IMM_1PNPDE20080415_104925_000000912067_00409_32026_1295.N1						IS4	H/H	67	32026	409	4.06
ASA_IMM_1PNPDE20080415_141708_000000742067_00411_32028_1672.N1						IS5	H/H	67	32028	411	4.06
ASA_IMM_1PNPDE20080415_151328_000000352067_00412_32029_1676.N1						IS6	V/V	67	32029	412	4.06
ASA_IMM_1PNPDE20080415_155524_000000842067_00412_32029_1716.N1						IS2	V/V	67	32029	412	4.06
ASA_IMM_1PNPDE20080415_171513_000000372067_00413_32030_1941.N1						IS5	V/V	67	32030	413	4.06
ASA_IMM_1PNPDE20080415_171513_000000372067_00413_32030_2111.N1						IS5	V/V	67	32030	413	4.06
ASA_IMM_1PNPDE20080415_183625_000000352067_00414_32031_2095.N1						IS6	V/V	67	32031	414	4.06
ASA_IMM_1PNPDE20080415_183625_000000352067_00414_32031_2143.N1						IS6	V/V	67	32031	414	4.06
ASA_IMM_1PNPDE20080415_183720_000001252067_00414_32031_2502.N1						IS2	V/V	67	32031	414	4.06
ASA_IMM_1PNPDE20080415_183720_000001252067_00414_32031_2532.N1						IS2	V/V	67	32031	414	4.06
ASA_IMM_1PNPDK20080415_183947_000001942067_00414_32031_1929.N1						IS2	V/V	67	32031	414	4.06
ASA_IMM_1PNPDE20080415_201126_000000802067_00415_32032_3059.N1						IS2	V/V	67	32032	415	4.06
ASA_IMM_1PNPDE20080415_201126_000000802067_00415_32032_3424.N1						IS2	V/V	67	32032	415	4.06
ASA_IMM_1PNPDK20080415_201953_000001132067_00415_32032_2054.N1						IS2	V/V	67	32032	415	4.06
ASA_IMM_1PNPDE20080415_215454_000000802067_00416_32033_3335.N1						IS2	V/V	67	32033	416	4.06
ASA_IMM_1PNPDE20080415_215454_000000802067_00416_32033_3542.N1						IS2	V/V	67	32033	416	4.06

Filename	Pol	Timestamp	count(Module)
ASA_MS__0PNPDE20080415_042850_000000162067_00405_32022_0277.N1	V	2008-04-15 04:28:50	320





Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WSM_1PNPDE20080415_002658_000001042067_00403_32020_2858.N1						SS1	H/H	67	32020	403	4.06
ASA_WSM_1PNPDE20080415_002658_000001042067_00403_32020_2864.N1						SS1	H/H	67	32020	403	4.06
ASA_WSM_1PNPDE20080415_011622_000002632067_00403_32020_3011.N1						SS1	H/H	67	32020	403	4.06
ASA_WSM_1PNPDE20080415_011622_000002632067_00403_32020_3037.N1						SS1	H/H	67	32020	403	4.06
ASA_WSM_1PNPDE20080415_020144_000003482067_00404_32021_2922.N1						SS1	H/H	67	32021	404	4.06
ASA_WSM_1PNPDE20080415_020144_000003482067_00404_32021_2988.N1						SS1	H/H	67	32021	404	4.06
ASA_WSM_1PNPDE20080415_022201_000000972067_00404_32021_2862.N1						SS1	H/H	67	32021	404	4.06
ASA_WSM_1PNPDE20080415_022201_000000972067_00404_32021_2873.N1						SS1	H/H	67	32021	404	4.06
ASA_WSM_1PNPDE20080415_033423_000004282067_00405_32022_2395.N1						SS1	H/H	67	32022	405	4.06
ASA_WSM_1PNPDE20080415_033423_000004282067_00405_32022_2758.N1						SS1	H/H	67	32022	405	4.06
ASA_WSM_1PNPDE20080415_040018_000002392067_00405_32022_2510.N1						SS1	V/V	67	32022	405	4.06
ASA_WSM_1PNPDE20080415_040018_000002392067_00405_32022_2811.N1						SS1	V/V	67	32022	405	4.06
ASA_WSM_1PNPDE20080415_052852_000003542067_00406_32023_3341.N1						SS1	H/H	67	32023	406	4.06
ASA_WSM_1PNPDE20080415_071821_000001032067_00407_32024_1328.N1						SS1	H/H	67	32024	407	4.06
ASA_WSM_1PNPDE20080415_074152_000002012067_00407_32024_1330.N1						SS1	V/V	67	32024	407	4.06
ASA_WSM_1PNPDE20080415_093154_000001402067_00408_32025_1362.N1						SS1	H/H	67	32025	408	4.06
ASA_WSM_1PNPDE20080415_101948_000003852067_00409_32026_1382.N1						SS1	H/H	67	32026	409	4.06
ASA_WSM_1PNPDE20080415_120350_000001762067_00410_32027_1462.N1						SS1	H/H	67	32027	410	4.06
ASA_WSM_1PNPDE20080415_123458_000005182067_00410_32027_1666.N1						SS1	V/V	67	32027	410	4.06
ASA_WSM_1PNPDE20080415_150736_000000672067_00412_32029_1678.N1						SS1	H/H	67	32029	412	4.06
ASA_WSM_1PNPDE20080415_151534_000001472067_00412_32029_1758.N1						SS1	V/V	67	32029	412	4.06
ASA_WSM_1PNPDE20080415_151934_000001042067_00412_32029_1754.N1						SS1	H/H	67	32029	412	4.06
ASA_WSM_1PNPDE20080415_152332_000001032067_00412_32029_1756.N1						SS1	H/H	67	32029	412	4.06
ASA_WSM_1PNPDE20080415_165912_000001642067_00413_32030_2178.N1						SS1	H/H	67	32030	413	4.06
ASA_WSM_1PNPDE20080415_171320_000000852067_00413_32030_2181.N1						SS1	H/H	67	32030	413	4.06
ASA_WSM_1PNPDE20080415_171620_000001462067_00413_32030_2379.N1						SS1	H/H	67	32030	413	4.06
ASA_WSM_1PNPDE20080415_171620_000001462067_00413_32030_2536.N1						SS1	H/H	67	32030	413	4.06
ASA_WSM_1PNPDE20080415_175554_000002012067_00413_32030_2391.N1						SS1	H/H	67	32030	413	4.06
ASA_WSM_1PNPDE20080415_175554_000002012067_00413_32030_2543.N1						SS1	H/H	67	32030	413	4.06
ASA_WSM_1PNPDE20080415_185332_000000862067_00414_32031_2624.N1						SS1	H/H	67	32031	414	4.06
ASA_WSM_1PNPDE20080415_185332_000000862067_00414_32031_2751.N1						SS1	H/H	67	32031	414	4.06
ASA_WSM_1PNPDE20080415_185426_000003542067_00414_32031_3231.N1						SS1	H/H	67	32031	414	4.06
ASA_WSM_1PNPDE20080415_193529_000002022067_00414_32031_3211.N1						SS1	H/H	67	32031	414	4.06
ASA_WSM_1PNPDE20080415_193529_000002022067_00414_32031_3263.N1						SS1	H/H	67	32031	414	4.06
ASA_WSM_1PNPDE20080415_203159_000000912067_00415_32032_3251.N1						SS1	H/H	67	32032	415	4.06
ASA_WSM_1PNPDE20080415_203159_000000912067_00415_32032_3506.N1						SS1	H/H	67	32032	415	4.06
ASA_WSM_1PNPDE20080415_203405_000003362067_00415_32032_3343.N1						SS1	H/H	67	32032	415	4.06
ASA_WSM_1PNPDE20080415_203405_000003362067_00415_32032_3565.N1						SS1	H/H	67	32032	415	4.06
ASA_WSM_1PNPDE20080415_204019_000001152067_00415_32032_3422.N1						SS1	V/V	67	32032	415	4.06
ASA_WSM_1PNPDE20080415_204019_000001152067_00415_32032_3561.N1						SS1	V/V	67	32032	415	4.06
ASA_WSM_1PNPDE20080415_213610_000001712067_00415_32032_3443.N1						SS1	V/V	67	32032	415	4.06
ASA_WSM_1PNPDE20080415_213610_000001712067_00415_32032_3584.N1						SS1	V/V	67	32032	415	4.06
ASA_WSM_1PNPDE20080415_221122_000001842067_00416_32033_3498.N1						SS1	H/H	67	32033	416	4.06
ASA_WSM_1PNPDE20080415_221512_000003672067_00416_32033_3533.N1						SS1	H/H	67	32033	416	4.06
ASA_WSM_1PNPDE20080415_225641_000000852067_00416_32033_3508.N1						SS1	H/H	67	32033	416	4.06
ASA_WSM_1PNPDE20080415_230041_000001842067_00416_32033_3445.N1						SS1	H/H	67	32033	416	4.06
ASA_WSM_1PNPDE20080415_230041_000001842067_00416_32033_3654.N1						SS1	H/H	67	32033	416	4.06


Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WVS_1PNPDE20080414_234911_000016042067_00402_32019_2546.N1						IS2	V/V	67	32019	402	4.06
ASA_WVS_1PNPDE20080414_234911_000016042067_00402_32019_3463.N1						IS2	V/V	67	32019	402	4.06
ASA_WVS_1PNPDE20080415_003411_000011432067_00403_32020_2541.N1						IS2	V/V	67	32020	403	4.06
ASA_WVS_1PNPDE20080415_003411_000011432067_00403_32020_3089.N1						IS2	V/V	67	32020	403	4.06
ASA_WVS_1PNPDE20080415_010032_000003902067_00403_32020_2528.N1						IS2	V/V	67	32020	403	4.06
ASA_WVS_1PNPDE20080415_010032_000003902067_00403_32020_3080.N1						IS2	V/V	67	32020	403	4.06
ASA_WVS_1PNPDE20080415_012344_000002552067_00403_32020_2525.N1						IS2	V/V	67	32020	403	4.06
ASA_WVS_1PNPDE20080415_012344_000002552067_00403_32020_3077.N1						IS2	V/V	67	32020	403	4.06
ASA_WVS_1PNPDE20080415_012714_000002852067_00403_32020_2814.N1						IS2	V/V	67	32020	403	4.06
ASA_WVS_1PNPDE20080415_012714_000002852067_00403_32020_2513.N1						IS2	V/V	67	32020	403	4.06
ASA_WVS_1PNPDE20080415_014224_000007042067_00404_32021_2817.N1						IS2	V/V	67	32021	404	4.06
ASA_WVS_1PNPDE20080415_014224_000007042067_00404_32021_2518.N1						IS2	V/V	67	32021	404	4.06
ASA_WVS_1PNPDE20080415_022650_000011842067_00404_32021_2787.N1						IS2	V/V	67	32021	404	4.06
ASA_WVS_1PNPDE20080415_022650_000011842067_00404_32021_2474.N1						IS2	V/V	67	32021	404	4.06
ASA_WVS_1PNPDE20080415_024605_00000902067_00404_32021_2359.N1						IS2	V/V	67	32021	404	4.06
ASA_WVS_1PNPDE20080415_024605_00000902067_00404_32021_2754.N1						IS2	V/V	67	32021	404	4.06
ASA_WVS_1PNPDE20080415_022650_000011842067_00404_32021_2787.N1						IS1	V/V	67	32021	404	4.06
ASA_WVS_1PNPDE20080415_022650_000011842067_00404_32021_2474.N1						IS1	V/V	67	32021	404	4.06
ASA_WVS_1PNPDE20080415_030420_000002102067_00404_32021_2233.N1						IS2	V/V	67	32021	404	4.06
ASA_WVS_1PNPDE20080415_030420_000002102067_00404_32021_2708.N1						IS2	V/V	67	32021	404	4.06
ASA_WVS_1PNPDE20080415_032414_000001942067_00405_32022_2109.N1						IS2	V/V	67	32022	405	4.06
ASA_WVS_1PNPDE20080415_032414_000001942067_00405_32022_2682.N1						IS2	V/V	67	32022	405	4.06
ASA_WVS_1PNPDE20080415_040615_000009442067_00405_32022_2106.N1						IS2	V/V	67	32022	405	4.06
ASA_WVS_1PNPDE20080415_040615_000009442067_00405_32022_2622.N1						IS2	V/V	67	32022	405	4.06
ASA_WVS_1PNPDE20080415_042144_000001352067_00405_32022_3460.N1						IS2	V/V	67	32022	405	4.06
ASA_WVS_1PNPDE20080415_042144_000001352067_00405_32022_3808.N1						IS2	V/V	67	32022	405	4.06
ASA_WVS_1PNPDE20080415_040615_000009442067_00405_32022_2106.N1						IS1	V/V	67	32022	405	4.06
ASA_WVS_1PNPDE20080415_040615_000009442067_00405_32022_2622.N1						IS1	V/V	67	32022	405	4.06
ASA_WVS_1PNPDE20080415_042705_00000602067_00405_32022_3466.N1						IS2	V/V	67	32022	405	4.06
ASA_WVS_1PNPDE20080415_042705_00000602067_00405_32022_3811.N1						IS2	V/V	67	32022	405	4.06
ASA_WVS_1PNPDE20080415_044456_000012742067_00405_32022_3864.N1						IS2	V/V	67	32022	405	4.06
ASA_WVS_1PNPDE20080415_054530_000010642067_00406_32023_3867.N1						IS2	V/V	67	32023	406	4.06
ASA_WVS_1PNPDK20080415_060300_000003452067_00406_32023_0721.N1						IS2	V/V	67	32023	406	4.06
ASA_WVS_1PNPDK20080415_062532_000019642067_00406_32023_0738.N1						IS2	V/V	67	32023	406	4.06
ASA_WVS_1PNPDK20080415_074515_000002402067_00407_32024_0808.N1						IS2	V/V	67	32024	407	4.06
ASA_WVS_1PNPDK20080415_080608_000012592067_00407_32024_0811.N1						IS2	V/V	67	32024	407	4.06
ASA_WVS_1PNPDK20080415_082917_000006742067_00408_32025_0837.N1						IS2	V/V	67	32025	408	4.06
ASA_WVS_1PNPDK20080415_091353_000009592067_00408_32025_1040.N1						IS2	V/V	67	32025	408	4.06
ASA_WVS_1PNPDK20080415_094644_000019342067_00408_32025_1105.N1						IS2	V/V	67	32025	408	4.06
ASA_WVS_1PNPDK20080415_105134_000011392067_00409_32026_1221.N1						IS2	V/V	67	32026	409	4.06
ASA_WVS_1PNPDK20080415_112720_000019492067_00409_32026_1235.N1						IS2	V/V	67	32026	409	4.06
ASA_WVS_1PNPDK20080415_121637_000010492067_00410_32027_1342.N1						IS2	V/V	67	32027	410	4.06
ASA_WVS_1PNPDK20080415_124439_000003902067_00410_32027_1345.N1						IS2	V/V	67	32027	410	4.06
ASA_WVS_1PNPDK20080415_130756_000003002067_00410_32027_1348.N1						IS2	V/V	67	32027	410	4.06
ASA_WVS_1PNPDK20080415_132136_000007882067_00410_32027_1429.N1						IS2	V/V	67	32027	410	4.06
ASA_WVS_1PNPDK20080415_140231_000005542067_00411_32028_1552.N1						IS2	V/V	67	32028	411	4.06
ASA_WVS_1PNPDK20080415_142057_000006452067_00411_32028_1557.N1						IS2	V/V	67	32028	411	4.06
ASA_WVS_1PNPDK20080415_144832_000003752067_00411_32028_1562.N1						IS2	V/V	67	32028	411	4.06
ASA_WVS_1PNPDK20080415_145911_000004492067_00411_32028_1571.N1						IS2	V/V	67	32028	411	4.06
ASA_WVS_1PNPDK20080415_154752_00000892067_00412_32029_1705.N1						IS2	V/V	67	32029	412	4.06
ASA_WVS_1PNPDK20080415_155220_000001492067_00412_32029_1710.N1						IS2	V/V	67	32029	412	4.06
ASA_WVS_1PNPDK20080415_155655_000009292067_00412_32029_1715.N1						IS2	V/V	67	32029	412	4.06
ASA_WVS_1PNPDK20080415_162908_000011242067_00412_32029_1727.N1						IS2	V/V	67	32029	412	4.06
ASA_WVS_1PNPDK20080415_172921_000014092067_00413_32030_1840.N1						IS2	V/V	67	32030	413	4.06
ASA_WVS_1PNPDK20080415_181331_000010192067_00413_32030_1852.N1						IS2	V/V	67	32030	413	4.06
ASA_WVS_1PNPDK20080415_190237_000018592067_00414_32031_1965.N1						IS2	V/V	67	32031	414	4.06
ASA_WVS_1PNPDK20080415_195020_000006452067_00414_32031_1977.N1						IS2	V/V	67	32031	414	4.06
ASA_WVS_1PNPDE20080415_204214_000019192067_00415_32032_2905.N1						IS2	V/V	67	32032	415	4.06
ASA_WVS_1PNPDE20080415_204214_000019192067_00415_32032_3333.N1						IS2	V/V	67	32032	415	4.06
ASA_WVS_1PNPDE20080415_213055_000002092067_00415_32032_2900.N1						IS2	V/V	67	32032	415	4.06
ASA_WVS_1PNPDE20080415_213055_000002092067_00415_32032_3346.N1						IS2	V/V	67	32032	415	4.06
ASA_WVS_1PNPDE20080415_213340_000001042067_00415_32032_3033.N1						IS2	V/V	67	32032	415	4.06
ASA_WVS_1PNPDE20080415_213340_000001042067_00415_32032_3545.N1						IS2	V/V	67	32032	415	4.06
ASA_WVS_1PNPDE20080415_213055_000002092067_00415_32032_2900.N1						IS1	V/V	67	32032	415	4.06
ASA_WVS_1PNPDE20080415_213055_000002092067_00415_32032_3346.N1						IS1	V/V	67	32032	415	4.06
ASA_WVS_1PNPDE20080415_214312_000002992067_00415_32032_3040.N1						IS2	V/V	67	32032	415	4.06
ASA_WVS_1PNPDE20080415_214312_000002992067_00415_32032_3556.N1						IS2	V/V	67	32032	415	4.06




ASA_WVS_1PNPDE20080415_220222_000001052067_00416_32033_3057.N1	IS2	V/V	67	32033	416	4.06
ASA_WVS_1PNPDE20080415_220222_000001052067_00416_32033_3559.N1	IS2	V/V	67	32033	416	4.06
ASA_WVS_1PNPDE20080415_222130_000019942067_00416_32033_3072.N1	IS2	V/V	67	32033	416	4.06
ASA_WVS_1PNPDE20080415_222130_000019942067_00416_32033_3570.N1	IS2	V/V	67	32033	416	4.06
ASA_WVS_1PNPDE20080415_231131_000003602067_00416_32033_3256.N1	IS2	V/V	67	32033	416	4.06
ASA_WVS_1PNPDE20080415_231131_000003602067_00416_32033_3582.N1	IS2	V/V	67	32033	416	4.06
ASA_WVS_1PNPDE20080415_231646_000012892067_00416_32033_3689.N1	IS2	V/V	67	32033	416	4.06
ASA_WVS_1PNPDE20080415_233956_000003452067_00417_32034_3676.N1	IS2	V/V	67	32034	417	4.06
















































































15-Apr




15-Apr




15-Apr



15-Apr





15-Apr




15-Apr









15-Apr




15-Apr




15-Apr



15-Apr



15-Apr



15-Apr

