



# ASAR Daily Report



Analysis from 20-MAY-2008 00:00:00 to 20-MAY-2008 23:59:59. Page generated on 21-MAY-2008 07:37:53.  
View log file: ASAR\_Daily\_Report\_20080521\_0730.log. For any anomalies please contact [mtranfaglia@serco.it](mailto:mtranfaglia@serco.it), [gscarpino@serco.it](mailto:gscarpino@serco.it).

This report is automatically generated every day, every 2 hours. No comments are provided on the results.

## SUMMARY

1. DATA SUMMARY
  - 1.1 Summary tables
  - 1.2 Lists of products used
2. AUXILIARY FILES ANALYSIS
  - 2.1 IECF operational ADFs list
  - 2.2 Products with wrong ADFs
3. MODULE STEPPING PRODUCTS ANALYSIS
  - 3.1 V/V polarisation
  - 3.2 H/H polarisation
4. CALIBRATION PULSES ANALYSIS
  - 4.1 Analysis for WVS IS2 V/V
    - 4.1.1 Temporal Evolution Analysis for WVS IS2 V/V
    - 4.1.2 All Rows Analysis for WVS IS2 V/V
  - 4.2 Analysis for GM1 SS3 H/H
    - 4.2.1 Temporal Evolution Analysis for GM1 SS3 H/H
    - 4.2.2 All Rows Analysis for GM1 SS3 H/H
5. DOPPLER ANALYSIS
  - 5.1 Analysis for WVS IS2 V/V
    - 5.1.1 Doppler MAP Analysis for WVS IS2 V/V
    - 5.1.2 Doppler ANX Analysis for WVS IS2 V/V
  - 5.2 Analysis for GM1 SS1 H/H
    - 5.2.1 Doppler MAP Analysis for GM1 SS1 H/H
    - 5.2.2 Doppler ANX Analysis for GM1 SS1 H/H
  - 5.3 Doppler JUMPS Analysis for WSM
6. CHIRP ANALYSIS
  - 6.1 Analysis for WSM SS1 H/H
    - 6.1.1 ScaleFactor
  - 6.2 Analysis for WSM SS1 V/V
    - 6.2.1 ScaleFactor
7. RAW DATA ANALYSIS
  - 7.1 Analysis for WVS
  - 7.2 Analysis for IMM
8. TELEMETRY ANALYSIS
  - 8.1 Number of Missing Lines
  - 8.2 Number of Gaps

---

## 1 - DATA SUMMARY

### 1.1 - Summary tables

[ [BACK TO MENU](#) ]

WVS				GM1				APM				IMM				WSM				MS			
Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Time	Pol	Modules
PDE	IS1	H/H	3	PDE	WS	H/H	28	PDE	IS1	H/H	2	PDE	IS2	H/H	1	PDE	WS	H/H	29	PDE	2008-05-20 04:28:51	V	320
PDE	IS1	V/V	3	PDK	WS	H/H	43	PDE	IS2	H/H	2	PDE	IS2	V/V	11	PDE	WS	V/V	17				
PDE	IS2	V/V	36					PDE	IS3	H/H	1	PDE	IS4	H/H	1	PDK	WS	H/H	2				
PDK	IS2	V/V	28					PDE	IS4	H/H	2	PDE	IS5	H/H	1								
								PDK	IS1	H/H	1	PDE	IS5	V/V	1								
								PDK	IS3	H/H	1	PDE	IS6	V/V	2								
												PDE	IS7	H/H	1								
												PDE	IS7	V/V	2								
												PDK	IS2	H/H	4								
												PDK	IS2	V/V	3								
												PDK	IS3	***	1								
												PDK	IS4	V/V	1								

## 1.2 - Lists of products used

[ [BACK TO MENU](#) ]

[[TXT](#)] [[XLS](#)] [List\\_WVS\\_products\\_used](#)  
 [[TXT](#)] [[XLS](#)] [List\\_GM1\\_products\\_used](#)  
 [[TXT](#)] [[XLS](#)] [List\\_APM\\_products\\_used](#)  
 [[TXT](#)] [[XLS](#)] [List\\_IMM\\_products\\_used](#)  
 [[TXT](#)] [[XLS](#)] [List\\_WSM\\_products\\_used](#)  
 [[TXT](#)] [[XLS](#)] [List\\_MS\\_products\\_used](#)

## 2 - AUXILIARY FILES ANALYSIS

### 2.1 - IECF operational ADFs list

[ [BACK TO MENU](#) ]

ADFs disseminated for ASAR
ASA_CON_AXVIEC20071218_084201_20070204_165113_20081231_000000
ASA_INS_AXVIEC20071218_083603_20070307_060000_20081231_000000
ASA_XCH_AXVIEC20051219_162547_20020301_000000_20081231_000000
ASA_XCA_AXVIEC20071218_082742_20070204_165113_20081231_000000

### 2.2 - Products with wrong ADFs

[ [BACK TO MENU](#) ]

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
WVS	0	0	0	0
GM1	0	0	0	0
APM	0	0	0	0
IMM	0	0	0	0
WSM	0	0	0	0

### 3 - MODULE STEPPING PRODUCTS ANALYSIS

SECOND FIXED REFERENCE	PREVIOUS PRODUCT REFERENCE
After antenna maintenance (2005-09-22/23)	Previous product in the same polarisation
<p>Reference: 2005-09-23 05:55:14 V RxGain            Test : 2008-05-20 04:28:51 V</p>	<p>Reference: 2008-05-18 05:32:05 V RxGain            Test : 2008-05-20 04:28:51 V</p>
<p>Reference: 2005-09-23 05:55:14 V RxPhase            Test : 2008-05-20 04:28:51 V</p>	<p>Reference: 2008-05-18 05:32:05 V RxPhase            Test : 2008-05-20 04:28:51 V</p>









### 3.2 - H/H polarisation

[ [BACK TO MENU](#) ]

SECOND FIXED REFERENCE	PREVIOUS PRODUCT REFERENCE
After antenna maintenance (2005-09-22/23)	Previous product in the same polarisation







## 4 - CALIBRATION PULSES ANALYSIS

### 4.1 - Analysis for WVS IS2 V/V

#### 4.1.1 - Temporal Evolution Analysis for WVS IS2 V/V


[ BACK TO MENU ]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]




Calibration pulses for WVS IS2 V/V




20-May



20-May




20-May



20-May


rows: \_ 1 \_ 5 \_ 9 \_ 13 \_ 17 \_ 21 \_ 25 \_ 29

Transmit power (P1 - P1a) for WVS IS2 V/V



20-May

Transmit power (P1 - P1a) for WVS IS2 V/V




20-May

rows: \_ 1 \_ 5 \_ 9 \_ 13 \_ 17 \_ 21 \_ 25 \_ 29

#### 4.1.2 - All Rows Analysis for WVS IS2 V/V

[ [BACK TO MENU](#) ]





## 4.2 - Analysis for GM1 SS3 H/H

### 4.2.1 - Temporal Evolution Analysis for GM1 SS3 H/H


[ BACK TO MENU ]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]



Calibration pulses for GM1 SS3 H/H




Transmit power (P1 - P1a) for GM1 SS3 H/H



#### 4.2.2 - All Rows Analysis for GM1 SS3 H/H

[ [BACK TO MENU](#) ]





## 5 - DOPPLER ANALYSIS


### 5.1 - Analysis for WVS IS2 V/V

#### 5.1.1 - Doppler MAP Analysis for WVS IS2 V/V

[ [BACK TO MENU](#) ]








### 5.1.2 - Doppler ANX Analysis for WVS IS2 V/V

[ [BACK TO MENU](#) ]






## 5.2 - Analysis for GM1 SS1 H/H

### 5.2.1 - Doppler MAP Analysis for GM1 SS1 H/H

[ [BACK TO MENU](#) ]








### 5.2.2 - Doppler ANX Analysis for GM1 SS1 H/H

[ [BACK TO MENU](#) ]






### 5.3 - Doppler JUMPS Analysis for WSM

[ [BACK TO MENU](#) ]

--	--







## 6 - CHIRP ANALYSIS

### 6.1 - Analysis for WSM SS1 H/H

#### 6.1.1 - ScaleFactor

[ [BACK TO MENU](#) ]







## 6.2 - Analysis for WSM SS1 V/V

### 6.2.1 - ScaleFactor

[ [BACK TO MENU](#) ]






## 7 - RAW DATA ANALYSIS

### 7.1 - Analysis for WVS

[ [BACK TO MENU](#) ]

--	--	--






Channel	Statistics	DSS-B
MEAN I	mean	0.000511313
	stdev	2.06303e-07
MEAN Q	mean	0.000498165
	stdev	2.35676e-07
Channel	Statistics	DSS-B
STDEV I	mean	0.134241
	stdev	0.00114688
STDEV Q	mean	0.134624
	stdev	0.00116382

## 7.2 - Analysis for IMM

[ [BACK TO MENU](#) ]

--	--	--




## 8 - TELEMETRY ANALYSIS


Processing Center	Product	Gaps	Missing lines
PDE	ASA_WVS_1PNPDE20080520_223516_00000002068_00416_32534_9576.N1	1	0
PDE	ASA_WVS_1PNPDE20080520_223731_00000002068_00416_32534_9647.N1	1	0
PDE	ASA_WVS_1PNPDE20080520_223746_00000002068_00416_32534_9660.N1	1	0
PDE	ASA_WSM_1PNPDE20080520_150715_000000922068_00412_32530_9358.N1	0	15
PDE	ASA_WSM_1PNPDE20080520_164737_000001832068_00413_32531_9362.N1	0	9
PDE	ASA_WSM_1PNPDE20080520_183057_000000912068_00414_32532_9406.N1	0	19

### 8.1 - Number of Missing lines

[ BACK TO MENU ]








## 8.2 - Number of Gaps

[ [BACK TO MENU](#) ]



#####  
ASAR DAILY REPORT for 080520  
#####

MODE: DAILY  
ANALYSIS: ALL  
DATE: YESTERDAY

Analysis will be performed from 2008-05-20 00:00:00 to 2008-05-20 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/080520/

DATA SUMMARY

#####  
Summary will be performed from 2008-05-20 00:00:00 to 2008-05-20 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/080520/DATA\_SUMMARY

Creating directory ./RESULTS/DAILY/080520/DATA\_SUMMARY...  
Writing file ./RESULTS/DAILY/080520/DATA\_SUMMARY/Data\_summary.html...

\*\*\*\*\*  
Getting WVS products list from 2008-05-20 00:00:00 to 2008-05-20 23:59:59...  
Writing file ./RESULTS/DAILY/080520/DATA\_SUMMARY/List\_WVS\_products\_used.xls...  
Writing file ./RESULTS/DAILY/080520/DATA\_SUMMARY/List\_WVS\_products\_used.txt...

\*\*\*\*\*  
Getting GM1 products list from 2008-05-20 00:00:00 to 2008-05-20 23:59:59...  
Writing file ./RESULTS/DAILY/080520/DATA\_SUMMARY/List\_GM1\_products\_used.xls...  
Writing file ./RESULTS/DAILY/080520/DATA\_SUMMARY/List\_GM1\_products\_used.txt...

\*\*\*\*\*  
Getting APM products list from 2008-05-20 00:00:00 to 2008-05-20 23:59:59...  
Writing file ./RESULTS/DAILY/080520/DATA\_SUMMARY/List\_APM\_products\_used.xls...  
Writing file ./RESULTS/DAILY/080520/DATA\_SUMMARY/List\_APM\_products\_used.txt...

\*\*\*\*\*  
Getting IMM products list from 2008-05-20 00:00:00 to 2008-05-20 23:59:59...  
Writing file ./RESULTS/DAILY/080520/DATA\_SUMMARY/List\_IMM\_products\_used.xls...  
Writing file ./RESULTS/DAILY/080520/DATA\_SUMMARY/List\_IMM\_products\_used.txt...

\*\*\*\*\*  
Getting WSM products list from 2008-05-20 00:00:00 to 2008-05-20 23:59:59...  
Writing file ./RESULTS/DAILY/080520/DATA\_SUMMARY/List\_WSM\_products\_used.xls...  
Writing file ./RESULTS/DAILY/080520/DATA\_SUMMARY/List\_WSM\_products\_used.txt...

\*\*\*\*\*  
Getting MS products list from 2008-05-20 00:00:00 to 2008-05-20 23:59:59...  
Writing file ./RESULTS/DAILY/080520/DATA\_SUMMARY/List\_MS\_products\_used.xls...  
Writing file ./RESULTS/DAILY/080520/DATA\_SUMMARY/List\_MS\_products\_used.txt...

DATA SUMMARY completed  
#####

AUXILIARY FILES ANALYSIS

#####  
Analysis will be performed from 2008-05-20 00:00:00 to 2008-05-20 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/080520/AUXILIARY

Creating directory ./RESULTS/DAILY/080520/AUXILIARY...

\*\*\*\*\*  
Looking for the IECF operational ADFs list...





Found list 20080520\_030001\_current\_3\_IECF\_ADFs.txt...  
Extracting ADFs...

ASA\_CON\_AXVIEC20071218\_084201\_20070204\_165113\_20081231\_000000  
ASA\_INS\_AXVIEC20071218\_083603\_20070307\_060000\_20081231\_000000  
ASA\_XCH\_AXVIEC20051219\_162547\_20020301\_000000\_20081231\_000000  
ASA\_XCA\_AXVIEC20071218\_082742\_20070204\_165113\_20081231\_000000

Writing file ./RESULTS/DAILY/080520/AUXILIARY/ASAR\_ADFs\_IECF\_List3.html...  
Writing file ./RESULTS/DAILY/080520/AUXILIARY/Auxiliary\_files\_summary.html...

\*\*\*\*\*  
Analysing WVS products...

Writing file ./RESULTS/DAILY/080520/AUXILIARY/Check\_ADFs\_WVS.xls...  
Writing file ./RESULTS/DAILY/080520/AUXILIARY/Check\_ADFs\_WVS.txt...

ASA_WVS_1PNPDE20080520_003544_000010522068_00403_32521_8513.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080520_010033_000002852068_00403_32521_8518.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080520_012345_000002252068_00403_32521_8523.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080520_012645_000003752068_00403_32521_8671.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080520_014225_000007042068_00404_32522_8666.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080520_022522_000000592068_00404_32522_8658.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080520_022838_000010792068_00404_32522_8661.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080520_024608_000000902068_00404_32522_8784.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080520_030421_000002102068_00404_32522_8789.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080520_032415_000001942068_00405_32523_8802.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080520_040616_000009592068_00405_32523_8807.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080520_042200_000001202068_00405_32523_8919.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080520_042706_000000602068_00405_32523_8922.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080520_044457_000012742068_00405_32523_8939.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080520_054553_000010192068_00406_32524_8949.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080520_204129_000005242068_00415_32533_9417.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080520_205142_000009592068_00415_32533_9425.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080520_210942_000002702068_00415_32533_9420.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080520_213057_000002842068_00415_32533_9433.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080520_213442_000002542068_00415_32533_9554.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080520_214313_000002992068_00415_32533_9559.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080520_220259_000001202068_00416_32534_9564.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080520_222247_000006742068_00416_32534_9570.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080520_223416_000000442068_00416_32534_9567.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080520_223516_000000002068_00416_32534_9576.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080520_223531_000000292068_00416_32534_9634.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080520_223616_000000002068_00416_32534_9637.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080520_223631_000000142068_00416_32534_9618.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080520_223701_000000142068_00416_32534_9656.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080520_223731_000000002068_00416_32534_9647.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080520_223746_000000002068_00416_32534_9660.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080520_223801_000000002068_00416_32534_9672.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080520_223816_000000002068_00416_32534_9668.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080520_223831_000009292068_00416_32534_9694.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080520_231132_000004202068_00416_32534_9686.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080520_231748_000008392068_00416_32534_9789.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080520_233340_000002392068_00417_32535_9786.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20080520_233957_000003602068_00417_32535_9792.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080520_060223_000003752068_00406_32524_0578.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080520_062533_000019642068_00406_32524_0589.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080520_074516_000002402068_00407_32525_0653.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080520_080609_000012592068_00407_32525_0662.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080520_082918_000004642068_00408_32526_0659.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080520_083853_000001052068_00408_32526_0720.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080520_091345_000008692068_00408_32526_0800.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080520_094645_000019942068_00408_32526_0826.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080520_105135_000011392068_00409_32527_0936.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080520_112721_000002702068_00409_32527_0939.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080520_113410_000014692068_00409_32527_1019.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

```
ASA_WVS_1PNPDK20080520_121709_000010192068_00410_32528_1061.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080520_124440_000003902068_00410_32528_1064.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080520_130757_000003002068_00410_32528_1069.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080520_132137_000007882068_00410_32528_1152.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080520_140202_000005842068_00411_32529_1232.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080520_142058_000006452068_00411_32529_1239.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080520_144833_000003752068_00411_32529_1249.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080520_145913_000001942068_00411_32529_1242.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080520_150409_000001492068_00411_32529_1252.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080520_154753_000000892068_00412_32530_1366.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080520_155221_000001492068_00412_32530_1363.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080520_155656_000009292068_00412_32530_1371.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080520_162909_000010642068_00412_32530_1385.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080520_172923_000014092068_00413_32531_1490.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080520_181332_000010042068_00413_32531_1495.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080520_190257_000018292068_00414_32532_1595.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20080520_195021_000005852068_00414_32532_1605.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```

\*\*\*\*\*

Analysing GM1 products...

Writing file ./RESULTS/DAILY/080520/AUXILIARY/Check\_ADFs\_GM1.xls...

Writing file ./RESULTS/DAILY/080520/AUXILIARY/Check\_ADFs\_GM1.txt...

```
ASA_GM1_1PNPDE20080520_002010_000005372068_00403_32521_8510.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080520_005401_000003922068_00403_32521_8515.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080520_010741_000005732068_00403_32521_8520.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080520_012150_000001142068_00403_32521_8525.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080520_013346_000005192068_00403_32521_8673.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080520_015449_000008212068_00404_32522_8668.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080520_021722_000001382068_00404_32522_8663.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080520_022111_000001632068_00404_32522_8655.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080520_024817_000009302068_00404_32522_8786.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080520_030832_000001812068_00404_32522_8781.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080520_031140_000007492068_00404_32522_8791.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080520_032816_000008212068_00405_32523_8793.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080520_034247_000004532068_00405_32523_8799.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080520_040009_000001262068_00405_32523_8804.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080520_043403_000006522068_00405_32523_8928.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080520_050658_000001322068_00406_32524_8926.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080520_051458_000001502068_00406_32524_8924.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080520_051829_000006702068_00406_32524_8936.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080520_053736_000001442068_00406_32524_8946.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080520_211452_000005132068_00415_32533_9422.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080520_212701_000002352068_00415_32533_9435.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080520_213936_000002172068_00415_32533_9551.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080520_214858_000005672068_00416_32534_9556.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080520_215927_000000902068_00416_32534_9561.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080520_220726_000005192068_00416_32534_9681.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080520_225816_000001442068_00416_32534_9679.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080520_230505_000003862068_00416_32534_9696.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20080520_235045_000004652068_00417_32535_9794.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080520_060929_000009302068_00406_32524_0586.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080520_070151_000006102068_00407_32525_0596.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080520_073010_000006942068_00407_32525_0655.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080520_075005_000009302068_00407_32525_0668.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080520_084115_000007252068_00408_32526_0727.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080520_090743_000001022068_00408_32526_0797.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080520_094051_000003502068_00408_32526_0802.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080520_102043_000004282068_00409_32527_0804.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080520_103018_000001262068_00409_32527_0806.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080520_103138_000000782068_00409_32527_0931.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080520_104529_000002352068_00409_32527_0933.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080520_111117_000009302068_00409_32527_0941.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080520_120053_000001872068_00410_32528_0943.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080520_120715_000002112068_00410_32528_0945.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```



ASA_GM1_1PNPDK20080520_121216_000002172068_00410_32528_1058.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080520_125152_000009302068_00410_32528_1066.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080520_131347_000004712068_00410_32528_1071.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080520_133523_000002052068_00411_32529_1149.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080520_134728_000002472068_00411_32529_1154.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080520_135049_000002232068_00411_32529_1225.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080520_135707_000001442068_00411_32529_1227.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080520_141226_000002832068_00411_32529_1229.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080520_141836_000001382068_00411_32529_1234.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080520_143228_000009302068_00411_32529_1246.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080520_145531_000002172068_00411_32529_1244.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080520_150850_000006342068_00412_32530_1319.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080520_152853_000001442068_00412_32530_1358.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080520_153510_000007612068_00412_32530_1360.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080520_155002_000001382068_00412_32530_1368.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080520_161304_000009302068_00412_32530_1373.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080520_165046_000002412068_00413_32531_1375.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080520_165633_000002052068_00413_32531_1382.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080520_170918_000001142068_00413_32531_1483.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080520_171255_000001382068_00413_32531_1485.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080520_171948_000003742068_00413_32531_1487.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080520_175340_000009302068_00413_32531_1492.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080520_183957_000002712068_00414_32532_1502.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080520_184320_000004342068_00414_32532_1588.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080520_185249_00000962068_00414_32532_1586.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080520_185602_000001812068_00414_32532_1590.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080520_193416_000005372068_00414_32532_1592.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080520_194714_000001872068_00414_32532_1597.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20080520_200322_000007672068_00414_32532_1608.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

\*\*\*\*\*

Analysing APM products...

Writing file ./RESULTS/DAILY/080520/AUXILIARY/Check\_ADFs\_APM.xls...

Writing file ./RESULTS/DAILY/080520/AUXILIARY/Check\_ADFs\_APM.txt...

ASA_APM_1PNPDE20080520_040405_00000802068_00405_32523_9187.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20080520_050914_00000422068_00406_32524_8914.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20080520_072822_00000872068_00407_32525_9135.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20080520_152228_00000422068_00412_32530_9302.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20080520_172833_00000432068_00413_32531_9280.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20080520_205052_00000432068_00415_32533_9504.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20080520_222157_00000432068_00416_32534_9724.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDK20080520_152340_00000442068_00412_32530_1236.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDK20080520_220210_00000432068_00416_32534_1715.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

\*\*\*\*\*

Analysing IMM products...

Writing file ./RESULTS/DAILY/080520/AUXILIARY/Check\_ADFs\_IMM.xls...

Writing file ./RESULTS/DAILY/080520/AUXILIARY/Check\_ADFs\_IMM.txt...

ASA_IMM_1PNPDE20080520_034157_00000382068_00405_32523_8767.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080520_040211_00000372068_00405_32523_9177.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080520_051124_000002022068_00406_32524_9022.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080520_051726_00000522068_00406_32524_9012.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080520_054002_000003452068_00406_32524_9046.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080520_072554_000001442068_00407_32525_9118.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080520_104152_00000372068_00409_32527_9164.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080520_104925_00000942068_00409_32527_9183.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080520_113225_00000982068_00409_32527_9239.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080520_141708_00000772068_00411_32529_9378.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080520_150306_00000572068_00411_32529_9338.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080520_155524_00000852068_00412_32530_9310.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

```
ASA_IMM_1PNPDE20080520_165448_000000932068_00413_32531_9348.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080520_171513_000000382068_00413_32531_9282.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080520_172602_000001422068_00413_32531_9346.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080520_183555_000000662068_00414_32532_9304.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080520_203841_000001552068_00415_32533_9537.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080520_215824_000000522068_00416_32534_9716.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080520_233227_000000672068_00417_32535_9779.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20080520_234710_000000822068_00417_32535_9816.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20080520_065903_000001572068_00407_32525_0629.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20080520_082750_000000812068_00408_32526_0754.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20080520_083738_000000702068_00408_32526_0760.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20080520_121043_000000822068_00410_32528_1042.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20080520_121550_000000732068_00410_32528_1044.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20080520_135434_000001422068_00411_32529_1194.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20080520_220137_000000102068_00416_32534_1713.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20080520_220540_000000952068_00416_32534_1721.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20080520_234808_000001472068_00417_32535_1729.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```

\*\*\*\*\*

Analysing WSM products...

Writing file ./RESULTS/DAILY/080520/AUXILIARY/Check\_ADFs\_WSM.xls...

Writing file ./RESULTS/DAILY/080520/AUXILIARY/Check\_ADFs\_WSM.txt...

```
ASA_WSM_1PNPDE20080520_001636_000001352068_00403_32521_8646.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080520_001636_000002082068_00403_32521_8795.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080520_001946_000000182068_00403_32521_8611.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080520_002912_0000003912068_00403_32521_8742.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080520_010555_000000922068_00403_32521_8603.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080520_011716_000002692068_00403_32521_8653.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080520_020838_000001762068_00404_32522_8765.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080520_021148_000003302068_00404_32522_8779.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080520_035024_000005812068_00405_32523_9092.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080520_043029_000002082068_00405_32523_8916.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080520_053255_000002742068_00406_32524_9083.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080520_071832_000000972068_00407_32525_9120.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080520_072016_000000732068_00407_32525_9122.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080520_072016_000003122068_00407_32525_9144.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080520_072231_000001762068_00407_32525_9140.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080520_074147_000002082068_00407_32525_9137.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080520_090932_000001892068_00408_32526_9159.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080520_091045_000001152068_00408_32526_9152.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080520_092855_000005932068_00408_32526_9245.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080520_093917_000000912068_00408_32526_9185.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080520_115919_000000912068_00410_32528_9249.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080520_120402_000001902068_00410_32528_9247.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080520_123459_000001342068_00410_32528_9270.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080520_123459_000005252068_00410_32528_9275.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080520_123809_000003352068_00410_32528_9271.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080520_140032_000000912068_00411_32529_9402.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080520_150715_000000922068_00412_32530_9358.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080520_151929_000001472068_00412_32530_9376.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080520_164737_000001832068_00413_32531_9362.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080520_170006_000001892068_00413_32531_9366.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080520_171615_000001892068_00413_32531_9408.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080520_171728_000001152068_00413_32531_9364.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080520_183057_000000912068_00414_32532_9406.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080520_183152_000002202068_00414_32532_9360.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080520_185428_000000912068_00414_32532_9404.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080520_185907_000002312068_00414_32532_9414.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080520_194319_000002322068_00414_32532_9410.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080520_200045_000001532068_00414_32532_9412.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080520_203154_000002312068_00415_32533_9543.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080520_203615_000000922068_00415_32533_9539.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080520_210830_000000732068_00415_32533_9506.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080520_212327_000002082068_00415_32533_9541.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```



```
ASA_WSM_1PNPDE20080520_221607_000003122068_00416_32534_9771.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080520_225442_000002082068_00416_32534_9765.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080520_230042_000002512068_00416_32534_9763.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20080520_235836_000002692068_00417_32535_9949.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20080520_052945_000002812068_00406_32524_0575.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20080520_071206_000004282068_00407_32525_0650.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```

AUXILIARY FILES ANALYSIS completed

#####

MODULE STEPPING ANALYSIS

#####

Analysis will be performed from 2008-05-20 00:00:00 to 2008-05-20 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/080520/MODULE\_STEPPING

Creating directory ./RESULTS/DAILY/080520/MODULE\_STEPPING...  
Creating directory ./RESULTS/DAILY/080520/MODULE\_STEPPING/FIRST\_REFERENCE...  
Creating directory ./RESULTS/DAILY/080520/MODULE\_STEPPING/SECOND\_REFERENCE...  
Creating directory ./RESULTS/DAILY/080520/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE...  
Deleting old files...

\*\*\*\*\*  
\*\*\*\*\*

Creating images comparing with second reference...

Exporting results to the directory ../../RESULTS/DAILY/080520/MODULE\_STEPPING/SECOND\_REFERENCE...

Polarization: H  
Reference product: ASA\_MS\_\_0PNPDK20050922\_062651\_00000152041\_00034\_18625\_0041.N1  
Test product: ASA\_MS\_\_0PNPDE20080519\_050028\_00000162068\_00391\_32509\_0288.N1  
H  
H  
../../RESULTS/DAILY/080520/MODULE\_STEPPING/SECOND\_REFERENCE/TGH\_20080519\_050028-20050922\_062651.png  
../../RESULTS/DAILY/080520/MODULE\_STEPPING/SECOND\_REFERENCE/TPH\_20080519\_050028-20050922\_062651.png  
../../RESULTS/DAILY/080520/MODULE\_STEPPING/SECOND\_REFERENCE/RGH\_20080519\_050028-20050922\_062651.png  
../../RESULTS/DAILY/080520/MODULE\_STEPPING/SECOND\_REFERENCE/RPH\_20080519\_050028-20050922\_062651.png

Polarization: V  
Reference product: ASA\_MS\_\_0PNPDK20050923\_055514\_00000152041\_00048\_18639\_0042.N1  
Test product: ASA\_MS\_\_0PNPDE20080520\_042851\_00000162068\_00405\_32523\_0289.N1  
V  
V  
../../RESULTS/DAILY/080520/MODULE\_STEPPING/SECOND\_REFERENCE/TGV\_20080520\_042851-20050923\_055514.png  
../../RESULTS/DAILY/080520/MODULE\_STEPPING/SECOND\_REFERENCE/TPV\_20080520\_042851-20050923\_055514.png  
../../RESULTS/DAILY/080520/MODULE\_STEPPING/SECOND\_REFERENCE/RGV\_20080520\_042851-20050923\_055514.png  
../../RESULTS/DAILY/080520/MODULE\_STEPPING/SECOND\_REFERENCE/RPV\_20080520\_042851-20050923\_055514.png

\*\*\*\*\*  
\*\*\*\*\*

Creating images comparing with previous product reference...

Exporting results to the directory ../../RESULTS/DAILY/080520/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE...

Polarization: H  
Reference product: ASA\_MS\_\_0PNPDK20080517\_060342\_00000162068\_00363\_32481\_0547.N1  
Test product: ASA\_MS\_\_0PNPDE20080519\_050028\_00000162068\_00391\_32509\_0288.N1  
H  
H  
../../RESULTS/DAILY/080520/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/TGH\_20080519\_050028-20080517\_060342.png  
../../RESULTS/DAILY/080520/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/TPH\_20080519\_050028-20080517\_060342.png  
../../RESULTS/DAILY/080520/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/RGH\_20080519\_050028-20080517\_060342.png  
../../RESULTS/DAILY/080520/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/RPH\_20080519\_050028-20080517\_060342.png

Polarization: V

Reference product: ASA\_MS\_0PNPDE20080518\_053205\_000000162068\_00377\_32495\_0287.N1

Test product: ASA\_MS\_0PNPDE20080520\_042851\_000000162068\_00405\_32523\_0289.N1

V  
V

../RESULTS/DAILY/080520/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/TGV\_20080520\_042851-20080518\_053205.png  
../RESULTS/DAILY/080520/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/TPV\_20080520\_042851-20080518\_053205.png  
../RESULTS/DAILY/080520/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/RGV\_20080520\_042851-20080518\_053205.png  
../RESULTS/DAILY/080520/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/RPV\_20080520\_042851-20080518\_053205.png

MODULE\_STEPPING ANALYSIS completed

#####

CALIBRATION PULSES ANALYSIS

#####

Creating directory ./RESULTS/DAILY/080520/CALIBRATION\_PULSES...

\*\*\*\*\*

\*\*\*\*\*

ALL ROWS Analysis will be performed from 2008-05-20 00:00:00 to 2008-05-20 23:59:59

Analysing products WVS IS2 V/V

Writing image ../RESULTS/DAILY/080520//CALIBRATION\_PULSES/Calibration\_pulses\_all\_rows\_WVS\_IS2\_VV.png...

Analysing products GM1 SS3 H/H

Writing image ../RESULTS/DAILY/080520//CALIBRATION\_PULSES/Calibration\_pulses\_all\_rows\_GM1\_SS3\_HH.png...

\*\*\*\*\*

\*\*\*\*\*

TEMPORAL EVOLUTION Analysis will be performed from 2008-05-20 00:00:00 to 2008-05-20 23:59:59

Analysing products WVS IS2 V/V

Getting calibration pulses data for WVS IS2 V/V from 2008-05-20 00:00:00 to 2008-05-20 23:59:59. Rows: 1/5/9/13/17/21/25/29

Writing file ./RESULTS/DAILY/080520/CALIBRATION\_PULSES/Calibration\_pulses\_data\_WVS\_IS2\_VV\_2008-05-20\_1.dat...

Writing ../RESULTS/DAILY/080520//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_WVS\_IS2\_VV\_1.png...

Writing ../RESULTS/DAILY/080520//CALIBRATION\_PULSES/Transmit\_Power\_WVS\_IS2\_VV\_1.png...

Getting calibration pulses data for WVS IS2 V/V from 2008-05-20 00:00:00 to 2008-05-20 23:59:59. Rows: 2/6/10/14/18/22/26/30

Writing file ./RESULTS/DAILY/080520/CALIBRATION\_PULSES/Calibration\_pulses\_data\_WVS\_IS2\_VV\_2008-05-20\_2.dat...

Writing ../RESULTS/DAILY/080520//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_WVS\_IS2\_VV\_2.png...

Writing ../RESULTS/DAILY/080520//CALIBRATION\_PULSES/Transmit\_Power\_WVS\_IS2\_VV\_2.png...

Getting calibration pulses data for WVS IS2 V/V from 2008-05-20 00:00:00 to 2008-05-20 23:59:59. Rows: 3/7/11/15/19/23/27/31

Writing file ./RESULTS/DAILY/080520/CALIBRATION\_PULSES/Calibration\_pulses\_data\_WVS\_IS2\_VV\_2008-05-20\_3.dat...

Writing ../RESULTS/DAILY/080520//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_WVS\_IS2\_VV\_3.png...

Writing ../RESULTS/DAILY/080520//CALIBRATION\_PULSES/Transmit\_Power\_WVS\_IS2\_VV\_3.png...

Getting calibration pulses data for WVS IS2 V/V from 2008-05-20 00:00:00 to 2008-05-20 23:59:59. Rows: 4/8/12/16/20/24/28/32

Writing file ./RESULTS/DAILY/080520/CALIBRATION\_PULSES/Calibration\_pulses\_data\_WVS\_IS2\_VV\_2008-05-20\_4.dat...

Writing ../RESULTS/DAILY/080520//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_WVS\_IS2\_VV\_4.png...

Writing ../RESULTS/DAILY/080520//CALIBRATION\_PULSES/Transmit\_Power\_WVS\_IS2\_VV\_4.png...

Analysing products GM1 SS3 H/H

Getting calibration pulses data for GM1 SS3 H/H from 2008-05-20 00:00:00 to 2008-05-20 23:59:59. Rows: 1/5/9/13/17/21/25/29

Writing file ./RESULTS/DAILY/080520/CALIBRATION\_PULSES/Calibration\_pulses\_data\_GM1\_SS3\_HH\_2008-05-20\_1.dat...

Writing ../RESULTS/DAILY/080520//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_GM1\_SS3\_HH\_1.png...

Writing ../RESULTS/DAILY/080520//CALIBRATION\_PULSES/Transmit\_Power\_GM1\_SS3\_HH\_1.png...

Getting calibration pulses data for GM1 SS3 H/H from 2008-05-20 00:00:00 to 2008-05-20 23:59:59. Rows: 2/6/10/14/18/22/26/30

Writing file ./RESULTS/DAILY/080520/CALIBRATION\_PULSES/Calibration\_pulses\_data\_GM1\_SS3\_HH\_2008-05-20\_2.dat...



Writing ../../RESULTS/DAILY/080520//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_GM1\_SS3\_HH\_2.png...  
Writing ../../RESULTS/DAILY/080520//CALIBRATION\_PULSES/Transmit\_Power\_GM1\_SS3\_HH\_2.png...

Getting calibration pulses data for GM1 SS3 H/H from 2008-05-20 00:00:00 to 2008-05-20 23:59:59. Rows: 3/7/11/15/19/23/27/31  
Writing file ./RESULTS/DAILY/080520/CALIBRATION\_PULSES/Calibration\_pulses\_data\_GM1\_SS3\_HH\_2008-05-20\_3.dat...  
Writing ../../RESULTS/DAILY/080520//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_GM1\_SS3\_HH\_3.png...  
Writing ../../RESULTS/DAILY/080520//CALIBRATION\_PULSES/Transmit\_Power\_GM1\_SS3\_HH\_3.png...

Getting calibration pulses data for GM1 SS3 H/H from 2008-05-20 00:00:00 to 2008-05-20 23:59:59. Rows: 4/8/12/16/20/24/28/32  
Writing file ./RESULTS/DAILY/080520/CALIBRATION\_PULSES/Calibration\_pulses\_data\_GM1\_SS3\_HH\_2008-05-20\_4.dat...  
Writing ../../RESULTS/DAILY/080520//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_GM1\_SS3\_HH\_4.png...  
Writing ../../RESULTS/DAILY/080520//CALIBRATION\_PULSES/Transmit\_Power\_GM1\_SS3\_HH\_4.png...

CALIBRATION PULSES ANALYSIS completed  
#####

DOPPLER ANALYSIS  
#####  
Creating directory ./RESULTS/DAILY/080520/DOPPLER...

\*\*\*\*\*  
\*\*\*\*\*  
DOPPLER ANX Analysis will be performed from 2008-05-20 00:00:00 to 2008-05-20 23:59:59

Analysing products WVS IS2 V/V  
Getting doppler data for WVS IS2 V/V from 2008-05-20 00:00:00 to 2008-05-20 23:59:59...  
Writing file ./RESULTS/DAILY/080520/DOPPLER/Doppler\_data\_WVS\_IS2\_VV\_2008-05-20.dat...  
Running IDL program...  
Writing file ../../RESULTS/DAILY/080520/DOPPLER/DOPPLER\_ANX\_WVS\_IS2\_VV.png...

Analysing products GM1 SS1 H/H  
Getting doppler data for GM1 SS1 H/H from 2008-05-20 00:00:00 to 2008-05-20 23:59:59...  
Writing file ./RESULTS/DAILY/080520/DOPPLER/Doppler\_data\_GM1\_SS1\_HH\_2008-05-20.dat...  
Running IDL program...  
Writing file ../../RESULTS/DAILY/080520/DOPPLER/DOPPLER\_ANX\_GM1\_SS1\_HH.png...

\*\*\*\*\*  
\*\*\*\*\*  
DOPPLER JUMPS Analysis will be performed on WSM products from 2008-05-20 00:00:00 to 2008-05-20 23:59:59

Analysing by default products WSM  
Getting doppler jumps data for WSM from 2008-05-20 00:00:00 to 2008-05-20 23:59:59...  
Writing file ./RESULTS/DAILY/080520/DOPPLER/Doppler\_Jumps\_data\_WSM\_2008-05-20.dat...  
Running IDL program...  
Writing file ../../RESULTS/DAILY/080520/DOPPLER/DOPPLER\_JUMPS\_ANX\_WSM.png...  
Writing file ../../RESULTS/DAILY/080520/DOPPLER/DOPPLER\_JUMPS\_Date\_WSM.png...

\*\*\*\*\*  
\*\*\*\*\*  
DOPPLER MAP Analysis will be performed from 2008-05-20 00:00:00 to 2008-05-20 23:59:59

Analysing products WVS IS2 V/V  
Loading predicted doppler values....  
Phase: descending  
Found data...  
Computing mean error doppler estimated-predicted...  
Mean error = -20.280405 Hz  
Writing file ../../RESULTS/DAILY/080520//DOPPLER/DOPPLER\_Estimated-Predicted-MeanError\_WVS\_IS2\_VV\_desc.jpg...

Writing file ../../RESULTS/DAILY/080520//DOPPLER/DOPPLER\_Absolute\_WVS\_IS2\_VV\_desc.jpg...

\*\*\*\*\*

Loading predicted doppler values....

Phase: ascending

Found data...

Computing mean error doppler estimated-predicted...

Mean error = -19.906980 Hz

Writing file ../../RESULTS/DAILY/080520//DOPPLER/DOPPLER\_Estimated-Predicted-MeanError\_WVS\_IS2\_VV\_asc.jpg...

Writing file ../../RESULTS/DAILY/080520//DOPPLER/DOPPLER\_Absolute\_WVS\_IS2\_VV\_asc.jpg...

\*\*\*\*\*

Analysing products GM1 SS1 H/H

Loading predicted doppler values....

Phase: descending

Found data...

Computing mean error doppler estimated-predicted...

Mean error = -11.635883 Hz

Writing file ../../RESULTS/DAILY/080520//DOPPLER/DOPPLER\_Estimated-Predicted-MeanError\_GM1\_SS1\_HH\_desc.jpg...

Writing file ../../RESULTS/DAILY/080520//DOPPLER/DOPPLER\_Absolute\_GM1\_SS1\_HH\_desc.jpg...

\*\*\*\*\*

Loading predicted doppler values....

Phase: ascending

Found data...

Computing mean error doppler estimated-predicted...

Mean error = -22.240194 Hz

Writing file ../../RESULTS/DAILY/080520//DOPPLER/DOPPLER\_Estimated-Predicted-MeanError\_GM1\_SS1\_HH\_asc.jpg...

Writing file ../../RESULTS/DAILY/080520//DOPPLER/DOPPLER\_Absolute\_GM1\_SS1\_HH\_asc.jpg...

\*\*\*\*\*

DOPPLER ANALYSIS completed

#####

CHIRP ANALYSIS

#####

Creating directory ./RESULTS/DAILY/080520/CHIRP...

\*\*\*\*\*

\*\*\*\*\*

CHIRP Analysis will be performed from 2008-05-20 00:00:00 to 2008-05-20 23:59:59

Analysing products WSM SS1 H/H

\*\*\*\*\*

Getting ScaleFactor data for WSM SS1 H/H from 2008-05-20 00:00:00 to 2008-05-20 23:59:59...

Writing file ./RESULTS/DAILY/080520/CHIRP/ScaleFactor\_data\_WSM\_SS1\_HH\_2008-05-20.dat...

Running IDL program...

Writing file ../../RESULTS/DAILY/080520/CHIRP/ScaleFactor\_ANX\_WSM\_SS1\_HH.png...

Writing file ../../RESULTS/DAILY/080520/CHIRP/ScaleFactor\_DATE\_WSM\_SS1\_HH.png...

Analysing products WSM SS1 V/V

\*\*\*\*\*

Getting ScaleFactor data for WSM SS1 V/V from 2008-05-20 00:00:00 to 2008-05-20 23:59:59...

Writing file ./RESULTS/DAILY/080520/CHIRP/ScaleFactor\_data\_WSM\_SS1\_VV\_2008-05-20.dat...

Running IDL program...

Writing file ../../RESULTS/DAILY/080520/CHIRP/ScaleFactor\_ANX\_WSM\_SS1\_VV.png...

Writing file ../../RESULTS/DAILY/080520/CHIRP/ScaleFactor\_DATE\_WSM\_SS1\_VV.png...



CHIRP ANALYSIS completed  
#####

RAW DATA ANALYSIS  
#####

Analysis will be performed from 2008-05-20 00:00:00 to 2008-05-20 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/080520/RAW\_DATA

Creating directory ./RESULTS/DAILY/080520/RAW\_DATA...

\*\*\*\*\*

Getting raw data for WVS from 2008-05-20 00:00:00 to 2008-05-20 23:59:59...  
Writing file ./RESULTS/DAILY/080520/RAW\_DATA/Raw\_data\_WVS\_2008-05-20.dat...  
Running IDL program to create graphs...

Creating image ../RESULTS/DAILY/080520/RAW\_DATA/Raw\_data\_WVS\_input\_mean.png...  
Creating image ../RESULTS/DAILY/080520/RAW\_DATA/Raw\_data\_WVS\_input\_stdev.png...  
Creating image ../RESULTS/DAILY/080520/RAW\_DATA/Raw\_data\_WVS\_gain\_imbalance.png...

\*\*\*\*\*

Getting raw data for IMM from 2008-05-20 00:00:00 to 2008-05-20 23:59:59...  
Writing file ./RESULTS/DAILY/080520/RAW\_DATA/Raw\_data\_IMM\_2008-05-20.dat...  
Running IDL program to create graphs...

Creating image ../RESULTS/DAILY/080520/RAW\_DATA/Raw\_data\_IMM\_input\_mean.png...  
Creating image ../RESULTS/DAILY/080520/RAW\_DATA/Raw\_data\_IMM\_input\_stdev.png...  
Creating image ../RESULTS/DAILY/080520/RAW\_DATA/Raw\_data\_IMM\_gain\_imbalance.png...

RAW DATA ANALYSIS completed  
#####

TELEMETRY ANALYSIS  
#####

Analysis will be performed from 2008-05-20 00:00:00 to 2008-05-20 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/080520/TELEMETRY

Creating directory ./RESULTS/DAILY/080520/TELEMETRY...

Looking for gaps and missing lines in WVS products...

\*\*\*\*\*

Checking 39 products from PDE...  
Found product...ASA\_WVS\_1PNPDE20080520\_223516\_00000002068\_00416\_32534\_9576.N1 / 1 gaps / 0 missing lines  
Found product...ASA\_WVS\_1PNPDE20080520\_223731\_00000002068\_00416\_32534\_9647.N1 / 1 gaps / 0 missing lines  
Found product...ASA\_WVS\_1PNPDE20080520\_223746\_00000002068\_00416\_32534\_9660.N1 / 1 gaps / 0 missing lines  
Checking 28 products from PDK...

Looking for gaps and missing lines in GM1 products...

\*\*\*\*\*

Checking 28 products from PDE...  
Checking 43 products from PDK...

Looking for gaps and missing lines in APM products...

\*\*\*\*\*

Checking 7 products from PDE...  
Checking 2 products from PDK...

Looking for gaps and missing lines in IMM products...

\*\*\*\*\*

Checking 20 products from PDE...  
Checking 9 products from PDK...

Looking for gaps and missing lines in WSM products...

```
*****
Checking 46 products from PDE...
Found product...ASA_WSM_1PNPDE20080520_150715_00000922068_00412_32530_9358.N1 / 0 gaps / 15 missing lines
Found product...ASA_WSM_1PNPDE20080520_164737_000001832068_00413_32531_9362.N1 / 0 gaps / 9 missing lines
Found product...ASA_WSM_1PNPDE20080520_183057_00000912068_00414_32532_9406.N1 / 0 gaps / 19 missing lines
Checking 2 products from PDK...
```

```
Creating graph of missing lines and gaps...
*****
Creating image: ./RESULTS/DAILY/080520/TELEMETRY/TELEMETRY_Missing_lines.png...
Creating image: ./RESULTS/DAILY/080520/TELEMETRY/TELEMETRY_Gaps.png...
```

```
TELEMETRY ANALYSIS completed
#####
```

```
BROWSE PRODUCTS ANALYSIS
#####
Analysis will be performed on 2008-05-20
```

```
*****
Scanning directory /nas3/ENVISAT/ASAR//ASA_GM__BP...
Results will be exported to the directory: /nas3/ENVISAT/ASAR//ASA_GM__BP/JPG/20080520/
```

```
ANALYSIS COMPLETED: 0 GM browse products to see...
*****
```

```
*****
Scanning directory /nas3/ENVISAT/ASAR//ASA_AP__BP...
Results will be exported to the directory: /nas3/ENVISAT/ASAR//ASA_AP__BP/JPG/20080520/
```

```
Stripping browse product /nas3/ENVISAT/ASAR//ASA_AP__BP/ASA_AP__BPZPDK20080520_220210_00000432068_00416_32534_1716.N1 ...
```

```
ANALYSIS COMPLETED: 1 AP browse products to see...
*****
```

```
*****
Scanning directory /nas3/ENVISAT/ASAR//ASA_IM__BP...
Results will be exported to the directory: /nas3/ENVISAT/ASAR//ASA_IM__BP/JPG/20080520/
```

```
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM__BP/ASA_IM__BPZPDK20080520_220137_00000102068_00416_32534_1714.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM__BP/ASA_IM__BPZPDK20080520_220540_00000952068_00416_32534_1722.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM__BP/ASA_IM__BPZPDK20080520_234808_000001472068_00417_32535_1730.N1 ...
```

```
ANALYSIS COMPLETED: 3 IM browse products to see...
*****
```

```
*****
Scanning directory /nas3/ENVISAT/ASAR//ASA_WS__BP...
Results will be exported to the directory: /nas3/ENVISAT/ASAR//ASA_WS__BP/JPG/20080520/
```

```
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS__BP/ASA_WS__BPZPDK20080520_201954_000003422068_00415_32533_1710.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS__BP/ASA_WS__BPZPDK20080520_202622_000003732068_00415_32533_1712.N1 ...
```

```
ANALYSIS COMPLETED: 2 WS browse products to see...
*****
```

```
BROWSE PRODUCTS ANALYSIS completed
#####
```



#####

Building file ./RESULTS/DAILY/080520/asarReport.html...  
Building DATA SUMMARY section...  
Building AUXILIARY FILES ANALYSIS section...  
Building MODULE STEPPING ANALYSIS section...  
Building CALIBRATION PULSES ANALYSIS section...  
Building DOPPLER ANALYSIS section...  
Building CHIRP ANALYSIS section...  
Building RAW DATA ANALYSIS section...  
Building TELEMETRY ANALYSIS section...

HTML REPORT generation completed

#####



# ASAR Daily Report





Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
ASA_APM_1PNPDE20080520_040405_000000802068_00405_32523_9187.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20080520_050914_000000422068_00406_32524_8914.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20080520_072822_000000872068_00407_32525_9135.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20080520_152228_000000422068_00412_32530_9302.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20080520_172833_000000432068_00413_32531_9280.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20080520_205052_000000432068_00415_32533_9504.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20080520_222157_000000432068_00416_32534_9724.N1	OK	OK	OK	OK
ASA_APM_1PNPDK20080520_152340_000000442068_00412_32530_1236.N1	OK	OK	OK	OK
ASA_APM_1PNPDK20080520_220210_000000432068_00416_32534_1715.N1	OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_GM1_1PNPDE20080520_002010_000005372068_00403_32521_8510.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080520_005401_000003922068_00403_32521_8515.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080520_010741_000005732068_00403_32521_8520.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080520_012150_000001142068_00403_32521_8525.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080520_013346_000005192068_00403_32521_8673.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080520_015449_000008212068_00404_32522_8668.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080520_021722_000001382068_00404_32522_8663.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080520_022111_000001632068_00404_32522_8655.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080520_024817_000009302068_00404_32522_8786.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080520_030832_000001812068_00404_32522_8781.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080520_031140_000007492068_00404_32522_8791.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080520_032816_000008212068_00405_32523_8793.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080520_034247_000004532068_00405_32523_8799.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080520_040009_000001262068_00405_32523_8804.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080520_043403_000006522068_00405_32523_8928.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080520_050658_000001322068_00406_32524_8926.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080520_051458_000001502068_00406_32524_8924.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080520_051829_000006702068_00406_32524_8936.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080520_053736_000001442068_00406_32524_8946.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080520_211452_000005132068_00415_32533_9422.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080520_212701_000002352068_00415_32533_9435.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080520_213936_000002172068_00415_32533_9551.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080520_214858_000005672068_00416_32534_9556.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080520_215927_00000902068_00416_32534_9561.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080520_220726_000005192068_00416_32534_9681.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080520_225816_000001442068_00416_32534_9679.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080520_230505_000003862068_00416_32534_9696.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080520_235045_000004652068_00417_32535_9794.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080520_060929_000009302068_00406_32524_0586.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080520_070151_000006102068_00407_32525_0596.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080520_073010_000006942068_00407_32525_0655.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080520_075005_000009302068_00407_32525_0668.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080520_084115_000007252068_00408_32526_0727.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080520_090743_000001022068_00408_32526_0797.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080520_094051_000003502068_00408_32526_0802.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080520_102043_000004282068_00409_32527_0804.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080520_103018_000001262068_00409_32527_0806.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080520_103138_000000782068_00409_32527_0931.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080520_104529_000002352068_00409_32527_0933.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080520_111117_000009302068_00409_32527_0941.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080520_120053_000001872068_00410_32528_0943.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080520_120715_000002112068_00410_32528_0945.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080520_121216_000002172068_00410_32528_1058.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080520_125152_000009302068_00410_32528_1066.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080520_131347_000004712068_00410_32528_1071.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080520_133523_000002052068_00411_32529_1149.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080520_134728_000002472068_00411_32529_1154.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080520_135049_000002232068_00411_32529_1225.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080520_135707_000001442068_00411_32529_1227.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080520_141226_000002832068_00411_32529_1229.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080520_141836_000001382068_00411_32529_1234.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080520_143228_000009302068_00411_32529_1246.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080520_145531_000002172068_00411_32529_1244.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080520_150850_000006342068_00412_32530_1319.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080520_152853_000001442068_00412_32530_1358.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080520_153510_000007612068_00412_32530_1360.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080520_155002_000001382068_00412_32530_1368.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080520_161304_000009302068_00412_32530_1373.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080520_165046_000002412068_00413_32531_1375.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080520_165633_000002052068_00413_32531_1382.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080520_170918_000001142068_00413_32531_1483.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080520_171255_000001382068_00413_32531_1485.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080520_171948_000003742068_00413_32531_1487.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080520_175340_000009302068_00413_32531_1492.N1					OK	OK	OK	OK



ASA_GM1_1PNPDK20080520_183957_000002712068_00414_32532_1502.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080520_184320_000004342068_00414_32532_1588.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080520_185249_000000962068_00414_32532_1586.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080520_185602_000001812068_00414_32532_1590.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080520_193416_000005372068_00414_32532_1592.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080520_194714_000001872068_00414_32532_1597.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080520_200322_000007672068_00414_32532_1608.N1	OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_IMM_1PNPDE20080520_034157_000000382068_00405_32523_8767.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080520_040211_000000372068_00405_32523_9177.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080520_051124_000002022068_00406_32524_9022.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080520_051726_000000522068_00406_32524_9012.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080520_054002_000003452068_00406_32524_9046.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080520_072554_000001442068_00407_32525_9118.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080520_104152_000000372068_00409_32527_9164.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080520_104925_000000942068_00409_32527_9183.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080520_113225_000000982068_00409_32527_9239.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080520_141708_000000772068_00411_32529_9378.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080520_150306_000000572068_00411_32529_9338.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080520_155524_000000852068_00412_32530_9310.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080520_165448_000000932068_00413_32531_9348.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080520_171513_000000382068_00413_32531_9282.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080520_172602_000001422068_00413_32531_9346.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080520_183555_000000662068_00414_32532_9304.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080520_203841_000001552068_00415_32533_9537.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080520_215824_000000522068_00416_32534_9716.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080520_233227_000000672068_00417_32535_9779.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080520_234710_000000822068_00417_32535_9816.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20080520_065903_000001572068_00407_32525_0629.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20080520_082750_000000812068_00408_32526_0754.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20080520_083738_000000702068_00408_32526_0760.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20080520_121043_000000822068_00410_32528_1042.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20080520_121550_000000732068_00410_32528_1044.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20080520_135434_000001422068_00411_32529_1194.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20080520_220137_000000102068_00416_32534_1713.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20080520_220540_000000952068_00416_32534_1721.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20080520_234808_000001472068_00417_32535_1729.N1					OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WSM_1PNPDE20080520_001636_000001352068_00403_32521_8646.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080520_001636_000002082068_00403_32521_8795.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080520_001946_000000182068_00403_32521_8611.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080520_002912_000003912068_00403_32521_8742.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080520_010555_000000922068_00403_32521_8603.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080520_011716_000002692068_00403_32521_8653.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080520_020838_000001762068_00404_32522_8765.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080520_021148_000003302068_00404_32522_8779.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080520_035024_000005812068_00405_32523_9092.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080520_043029_000002082068_00405_32523_8916.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080520_053255_000002742068_00406_32524_9083.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080520_071832_000000972068_00407_32525_9120.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080520_072016_000000732068_00407_32525_9122.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080520_072016_000003122068_00407_32525_9144.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080520_072231_000001762068_00407_32525_9140.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080520_074147_000002082068_00407_32525_9137.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080520_090932_000001892068_00408_32526_9159.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080520_091045_000001152068_00408_32526_9152.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080520_092855_000005932068_00408_32526_9245.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080520_093917_000000912068_00408_32526_9185.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080520_115919_000000912068_00410_32528_9249.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080520_120402_000001902068_00410_32528_9247.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080520_123459_000001342068_00410_32528_9270.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080520_123459_000005252068_00410_32528_9275.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080520_123809_000003352068_00410_32528_9271.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080520_140032_000000912068_00411_32529_9402.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080520_150715_000000922068_00412_32530_9358.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080520_151929_000001472068_00412_32530_9376.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080520_164737_000001832068_00413_32531_9362.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080520_170006_000001892068_00413_32531_9366.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080520_171615_000001892068_00413_32531_9408.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080520_171728_000001152068_00413_32531_9364.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080520_183057_000000912068_00414_32532_9406.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080520_183152_000002202068_00414_32532_9360.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080520_185428_000000912068_00414_32532_9404.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080520_185907_000002312068_00414_32532_9414.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080520_194319_000002322068_00414_32532_9410.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080520_200045_000001532068_00414_32532_9412.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080520_203154_000002312068_00415_32533_9543.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080520_203615_000000922068_00415_32533_9539.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080520_210830_000000732068_00415_32533_9506.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080520_212327_000002082068_00415_32533_9541.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080520_221607_000003122068_00416_32534_9771.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080520_225442_000002082068_00416_32534_9765.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080520_230042_000002512068_00416_32534_9763.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20080520_235836_000002692068_00417_32535_9949.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20080520_052945_000002812068_00406_32524_0575.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20080520_071206_000004282068_00407_32525_0650.N1					OK	OK	OK	OK




Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WVS_1PNPDE20080520_003544_000010522068_00403_32521_8513.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080520_010033_000002852068_00403_32521_8518.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080520_012345_000002252068_00403_32521_8523.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080520_012645_000003752068_00403_32521_8671.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080520_014225_000007042068_00404_32522_8666.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080520_022522_000000592068_00404_32522_8658.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080520_022838_000010792068_00404_32522_8661.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080520_024608_000000902068_00404_32522_8784.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080520_030421_000002102068_00404_32522_8789.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080520_032415_000001942068_00405_32523_8802.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080520_040616_000009592068_00405_32523_8807.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080520_042200_000001202068_00405_32523_8919.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080520_042706_000000602068_00405_32523_8922.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080520_044457_000012742068_00405_32523_8939.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080520_054553_000010192068_00406_32524_8949.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080520_204129_000005242068_00415_32533_9417.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080520_205142_000009592068_00415_32533_9425.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080520_210942_000002702068_00415_32533_9420.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080520_213057_000002842068_00415_32533_9433.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080520_213442_000002542068_00415_32533_9554.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080520_214313_000002992068_00415_32533_9559.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080520_220259_000001202068_00416_32534_9564.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080520_222247_000006742068_00416_32534_9570.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080520_223416_000000442068_00416_32534_9567.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080520_223516_000000002068_00416_32534_9576.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080520_223531_000000292068_00416_32534_9634.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080520_223616_000000002068_00416_32534_9637.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080520_223631_000000142068_00416_32534_9618.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080520_223701_000000142068_00416_32534_9656.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080520_223731_000000002068_00416_32534_9647.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080520_223746_000000002068_00416_32534_9660.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080520_223801_000000002068_00416_32534_9672.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080520_223816_000000002068_00416_32534_9668.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080520_223831_000009292068_00416_32534_9694.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080520_231132_000004202068_00416_32534_9686.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080520_231748_000008392068_00416_32534_9789.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080520_233340_000002392068_00417_32535_9786.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080520_233957_000003602068_00417_32535_9792.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080520_060223_000003752068_00406_32524_0578.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080520_062533_000019642068_00406_32524_0589.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080520_074516_000002402068_00407_32525_0653.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080520_080609_000012592068_00407_32525_0662.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080520_082918_000004642068_00408_32526_0659.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080520_083853_000001052068_00408_32526_0720.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080520_091345_000008692068_00408_32526_0800.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080520_094645_000019942068_00408_32526_0826.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080520_105135_000011392068_00409_32527_0936.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080520_112721_000002702068_00409_32527_0939.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080520_113410_000014692068_00409_32527_1019.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080520_121709_000010192068_00410_32528_1061.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080520_124440_000003902068_00410_32528_1064.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080520_130757_000003002068_00410_32528_1069.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080520_132137_000007882068_00410_32528_1152.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080520_140202_000005842068_00411_32529_1232.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080520_142058_000006452068_00411_32529_1239.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080520_144833_000003752068_00411_32529_1249.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080520_145913_000001942068_00411_32529_1242.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080520_150409_000001492068_00411_32529_1252.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080520_154753_000000892068_00412_32530_1366.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080520_155221_000001492068_00412_32530_1363.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080520_155656_000009292068_00412_32530_1371.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080520_162909_000010642068_00412_32530_1385.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080520_172923_000014092068_00413_32531_1490.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080520_181332_000010042068_00413_32531_1495.N1					OK	OK	OK	OK

ASA_WVS_1PNPDK20080520_190257_000018292068_00414_32532_1595.N1	OK	OK	OK	OK
ASA_WVS_1PNPDK20080520_195021_000005852068_00414_32532_1605.N1	OK	OK	OK	OK




### Calibration pulses for GM1 SS3 H/H







Calibration pulses for GM1 SS3 H/H



### Calibration pulses for GM1 SS3 H/H




Calibration pulses for GM1 SS3 H/H







### Calibration pulses for WVS IS2 V/V



### Calibration pulses for WVS IS2 V/V





Calibration pulses for WVS IS2 V/V








### Calibration pulses for WVS IS2 V/V



















rows: \_ 1 \_ 5 \_ 9 \_ 13 \_ 17 \_ 21 \_ 25 \_ 29


















rows: \_ 1 \_ 5 \_ 9 \_ 13 \_ 17 \_ 21 \_ 25 \_ 29






















Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_APM_1PNPDE20080520_040405_000000802068_00405_32523_9187.N1						IS4	H/H	68	32523	405	4.07
ASA_APM_1PNPDE20080520_050914_000000422068_00406_32524_8914.N1						IS1	H/H	68	32524	406	4.07
ASA_APM_1PNPDE20080520_072822_000000872068_00407_32525_9135.N1						IS4	H/H	68	32525	407	4.07
ASA_APM_1PNPDE20080520_152228_000000422068_00412_32530_9302.N1						IS3	H/H	68	32530	412	4.07
ASA_APM_1PNPDK20080520_152340_000000442068_00412_32530_1236.N1						IS3	H/H	68	32530	412	4.07
ASA_APM_1PNPDE20080520_172833_000000432068_00413_32531_9280.N1						IS1	H/H	68	32531	413	4.07
ASA_APM_1PNPDE20080520_205052_000000432068_00415_32533_9504.N1						IS2	H/H	68	32533	415	4.07
ASA_APM_1PNPDK20080520_220210_000000432068_00416_32534_1715.N1						IS1	H/H	68	32534	416	4.07
ASA_APM_1PNPDE20080520_222157_000000432068_00416_32534_9724.N1						IS2	H/H	68	32534	416	4.07

Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_GM1_1PNPDE20080520_002010_000005372068_00403_32521_8510.N1						SS1	H/H	68	32521	403	4.07
ASA_GM1_1PNPDE20080520_005401_000003922068_00403_32521_8515.N1						SS1	H/H	68	32521	403	4.07
ASA_GM1_1PNPDE20080520_010741_000005732068_00403_32521_8520.N1						SS1	H/H	68	32521	403	4.07
ASA_GM1_1PNPDE20080520_012150_000001142068_00403_32521_8525.N1						SS1	H/H	68	32521	403	4.07
ASA_GM1_1PNPDE20080520_013346_000005192068_00403_32521_8673.N1						SS1	H/H	68	32521	403	4.07
ASA_GM1_1PNPDE20080520_015449_000008212068_00404_32522_8668.N1						SS1	H/H	68	32522	404	4.07
ASA_GM1_1PNPDE20080520_021722_000001382068_00404_32522_8663.N1						SS1	H/H	68	32522	404	4.07
ASA_GM1_1PNPDE20080520_022111_000001632068_00404_32522_8655.N1						SS1	H/H	68	32522	404	4.07
ASA_GM1_1PNPDE20080520_024817_000009302068_00404_32522_8786.N1						SS1	H/H	68	32522	404	4.07
ASA_GM1_1PNPDE20080520_030832_000001812068_00404_32522_8781.N1						SS1	H/H	68	32522	404	4.07
ASA_GM1_1PNPDE20080520_031140_000007492068_00404_32522_8791.N1						SS1	H/H	68	32522	404	4.07
ASA_GM1_1PNPDE20080520_032816_000008212068_00405_32523_8793.N1						SS1	H/H	68	32523	405	4.07
ASA_GM1_1PNPDE20080520_034247_000004532068_00405_32523_8799.N1						SS1	H/H	68	32523	405	4.07
ASA_GM1_1PNPDE20080520_040009_000001262068_00405_32523_8804.N1						SS1	H/H	68	32523	405	4.07
ASA_GM1_1PNPDE20080520_043403_000006522068_00405_32523_8928.N1						SS1	H/H	68	32523	405	4.07
ASA_GM1_1PNPDE20080520_050658_000001322068_00406_32524_8926.N1						SS1	H/H	68	32524	406	4.07
ASA_GM1_1PNPDE20080520_051458_000001502068_00406_32524_8924.N1						SS1	H/H	68	32524	406	4.07
ASA_GM1_1PNPDE20080520_051829_000006702068_00406_32524_8936.N1						SS1	H/H	68	32524	406	4.07
ASA_GM1_1PNPDE20080520_053736_000001442068_00406_32524_8946.N1						SS1	H/H	68	32524	406	4.07
ASA_GM1_1PNPDK20080520_060929_000009302068_00406_32524_0586.N1						SS1	H/H	68	32524	406	4.07
ASA_GM1_1PNPDK20080520_070151_000006102068_00407_32525_0596.N1						SS1	H/H	68	32525	407	4.07
ASA_GM1_1PNPDK20080520_073010_000006942068_00407_32525_0655.N1						SS1	H/H	68	32525	407	4.07
ASA_GM1_1PNPDK20080520_075005_000009302068_00407_32525_0668.N1						SS1	H/H	68	32525	407	4.07
ASA_GM1_1PNPDK20080520_084115_000007252068_00408_32526_0727.N1						SS1	H/H	68	32526	408	4.07
ASA_GM1_1PNPDK20080520_090743_000001022068_00408_32526_0797.N1						SS1	H/H	68	32526	408	4.07
ASA_GM1_1PNPDK20080520_094051_000003502068_00408_32526_0802.N1						SS1	H/H	68	32526	408	4.07
ASA_GM1_1PNPDK20080520_102043_000004282068_00409_32527_0804.N1						SS1	H/H	68	32527	409	4.07
ASA_GM1_1PNPDK20080520_103018_000001262068_00409_32527_0806.N1						SS1	H/H	68	32527	409	4.07
ASA_GM1_1PNPDK20080520_103138_000000782068_00409_32527_0931.N1						SS1	H/H	68	32527	409	4.07
ASA_GM1_1PNPDK20080520_104529_000002352068_00409_32527_0933.N1						SS1	H/H	68	32527	409	4.07
ASA_GM1_1PNPDK20080520_111117_000009302068_00409_32527_0941.N1						SS1	H/H	68	32527	409	4.07
ASA_GM1_1PNPDK20080520_120053_000001872068_00410_32528_0943.N1						SS1	H/H	68	32528	410	4.07
ASA_GM1_1PNPDK20080520_120715_000002112068_00410_32528_0945.N1						SS1	H/H	68	32528	410	4.07
ASA_GM1_1PNPDK20080520_121216_000002172068_00410_32528_1058.N1						SS1	H/H	68	32528	410	4.07
ASA_GM1_1PNPDK20080520_125152_000009302068_00410_32528_1066.N1						SS1	H/H	68	32528	410	4.07
ASA_GM1_1PNPDK20080520_131347_000004712068_00410_32528_1071.N1						SS1	H/H	68	32528	410	4.07
ASA_GM1_1PNPDK20080520_133523_000002052068_00411_32529_1149.N1						SS1	H/H	68	32529	411	4.07
ASA_GM1_1PNPDK20080520_134728_000002472068_00411_32529_1154.N1						SS1	H/H	68	32529	411	4.07
ASA_GM1_1PNPDK20080520_135049_000002232068_00411_32529_1225.N1						SS1	H/H	68	32529	411	4.07
ASA_GM1_1PNPDK20080520_135707_000001442068_00411_32529_1227.N1						SS1	H/H	68	32529	411	4.07
ASA_GM1_1PNPDK20080520_141226_000002832068_00411_32529_1229.N1						SS1	H/H	68	32529	411	4.07
ASA_GM1_1PNPDK20080520_141836_000001382068_00411_32529_1234.N1						SS1	H/H	68	32529	411	4.07
ASA_GM1_1PNPDK20080520_143228_000009302068_00411_32529_1246.N1						SS1	H/H	68	32529	411	4.07
ASA_GM1_1PNPDK20080520_145531_000002172068_00411_32529_1244.N1						SS1	H/H	68	32529	411	4.07
ASA_GM1_1PNPDK20080520_150850_000006342068_00412_32530_1319.N1						SS1	H/H	68	32530	412	4.07
ASA_GM1_1PNPDK20080520_152853_000001442068_00412_32530_1358.N1						SS1	H/H	68	32530	412	4.07
ASA_GM1_1PNPDK20080520_153510_000007612068_00412_32530_1360.N1						SS1	H/H	68	32530	412	4.07
ASA_GM1_1PNPDK20080520_155002_000001382068_00412_32530_1368.N1						SS1	H/H	68	32530	412	4.07
ASA_GM1_1PNPDK20080520_161304_000009302068_00412_32530_1373.N1						SS1	H/H	68	32530	412	4.07
ASA_GM1_1PNPDK20080520_165046_000002412068_00413_32531_1375.N1						SS1	H/H	68	32531	413	4.07
ASA_GM1_1PNPDK20080520_165633_000002052068_00413_32531_1382.N1						SS1	H/H	68	32531	413	4.07
ASA_GM1_1PNPDK20080520_170918_000001142068_00413_32531_1483.N1						SS1	H/H	68	32531	413	4.07
ASA_GM1_1PNPDK20080520_171255_000001382068_00413_32531_1485.N1						SS1	H/H	68	32531	413	4.07
ASA_GM1_1PNPDK20080520_171948_000003742068_00413_32531_1487.N1						SS1	H/H	68	32531	413	4.07
ASA_GM1_1PNPDK20080520_175340_000009302068_00413_32531_1492.N1						SS1	H/H	68	32531	413	4.07
ASA_GM1_1PNPDK20080520_183957_000002712068_00414_32532_1502.N1						SS1	H/H	68	32532	414	4.07
ASA_GM1_1PNPDK20080520_184320_000004342068_00414_32532_1588.N1						SS1	H/H	68	32532	414	4.07
ASA_GM1_1PNPDK20080520_185249_000000962068_00414_32532_1586.N1						SS1	H/H	68	32532	414	4.07
ASA_GM1_1PNPDK20080520_185602_000001812068_00414_32532_1590.N1						SS1	H/H	68	32532	414	4.07
ASA_GM1_1PNPDK20080520_193416_000005372068_00414_32532_1592.N1						SS1	H/H	68	32532	414	4.07
ASA_GM1_1PNPDK20080520_194714_000001872068_00414_32532_1597.N1						SS1	H/H	68	32532	414	4.07
ASA_GM1_1PNPDK20080520_200322_000007672068_00414_32532_1608.N1						SS1	H/H	68	32532	414	4.07
ASA_GM1_1PNPDE20080520_211452_000005132068_00415_32533_9422.N1						SS1	H/H	68	32533	415	4.07
ASA_GM1_1PNPDE20080520_212701_000002352068_00415_32533_9435.N1						SS1	H/H	68	32533	415	4.07
ASA_GM1_1PNPDE20080520_213936_000002172068_00415_32533_9551.N1						SS1	H/H	68	32533	415	4.07
ASA_GM1_1PNPDE20080520_214858_000005672068_00416_32534_9556.N1						SS1	H/H	68	32534	416	4.07
ASA_GM1_1PNPDE20080520_215927_000000902068_00416_32534_9561.N1						SS1	H/H	68	32534	416	4.07

ASA_GM1_1PNPDE20080520_220726_000005192068_00416_32534_9681.N1	SS1	H/H	68	32534	416	4.07
ASA_GM1_1PNPDE20080520_225816_000001442068_00416_32534_9679.N1	SS1	H/H	68	32534	416	4.07
ASA_GM1_1PNPDE20080520_230505_000003862068_00416_32534_9696.N1	SS1	H/H	68	32534	416	4.07
ASA_GM1_1PNPDE20080520_235045_000004652068_00417_32535_9794.N1	SS1	H/H	68	32535	417	4.07



Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_IMM_1PNPDE20080520_034157_000000382068_00405_32523_8767.N1						IS7	H/H	68	32523	405	4.07
ASA_IMM_1PNPDE20080520_040211_000000372068_00405_32523_9177.N1						IS2	V/V	68	32523	405	4.07
ASA_IMM_1PNPDE20080520_051124_000002022068_00406_32524_9022.N1						IS2	V/V	68	32524	406	4.07
ASA_IMM_1PNPDE20080520_051726_000000522068_00406_32524_9012.N1						IS7	V/V	68	32524	406	4.07
ASA_IMM_1PNPDE20080520_054002_000003452068_00406_32524_9046.N1						IS2	V/V	68	32524	406	4.07
ASA_IMM_1PNPDK20080520_065903_000001572068_00407_32525_0629.N1						IS2	V/V	68	32525	407	4.07
ASA_IMM_1PNPDE20080520_072554_000001442068_00407_32525_9118.N1						IS2	V/V	68	32525	407	4.07
ASA_IMM_1PNPDK20080520_082750_000000812068_00408_32526_0754.N1						IS4	V/V	68	32526	408	4.07
ASA_IMM_1PNPDK20080520_083738_000000702068_00408_32526_0760.N1						IS2	V/V	68	32526	408	4.07
ASA_IMM_1PNPDE20080520_104152_000000372068_00409_32527_9164.N1						IS2	V/V	68	32527	409	4.07
ASA_IMM_1PNPDE20080520_104925_000000942068_00409_32527_9183.N1						IS4	H/H	68	32527	409	4.07
ASA_IMM_1PNPDE20080520_113225_000000982068_00409_32527_9239.N1						IS2	V/V	68	32527	409	4.07
ASA_IMM_1PNPDK20080520_121043_000000822068_00410_32528_1042.N1						IS2	H/H	68	32528	410	4.07
ASA_IMM_1PNPDK20080520_121550_000000732068_00410_32528_1044.N1						IS2	V/V	68	32528	410	4.07
ASA_IMM_1PNPDK20080520_135434_000001422068_00411_32529_1194.N1						IS2	H/H	68	32529	411	4.07
ASA_IMM_1PNPDE20080520_141708_000000772068_00411_32529_9378.N1						IS5	H/H	68	32529	411	4.07
ASA_IMM_1PNPDE20080520_150306_000000572068_00411_32529_9338.N1						IS2	V/V	68	32529	411	4.07
ASA_IMM_1PNPDE20080520_155524_000000852068_00412_32530_9310.N1						IS2	V/V	68	32530	412	4.07
ASA_IMM_1PNPDE20080520_165448_000000932068_00413_32531_9348.N1						IS6	V/V	68	32531	413	4.07
ASA_IMM_1PNPDE20080520_171513_000000382068_00413_32531_9282.N1						IS5	V/V	68	32531	413	4.07
ASA_IMM_1PNPDE20080520_172602_000001422068_00413_32531_9346.N1						IS2	V/V	68	32531	413	4.07
ASA_IMM_1PNPDE20080520_183555_000000662068_00414_32532_9304.N1						IS6	V/V	68	32532	414	4.07
ASA_IMM_1PNPDE20080520_203841_000001552068_00415_32533_9537.N1						IS2	V/V	68	32533	415	4.07
ASA_IMM_1PNPDE20080520_215824_000000522068_00416_32534_9716.N1						IS7	V/V	68	32534	416	4.07
ASA_IMM_1PNPDK20080520_220137_000000102068_00416_32534_1713.N1						IS3	***	68	32534	416	4.07
ASA_IMM_1PNPDK20080520_220540_000000952068_00416_32534_1721.N1						IS2	H/H	68	32534	416	4.07
ASA_IMM_1PNPDE20080520_233227_000000672068_00417_32535_9779.N1						IS2	V/V	68	32535	417	4.07
ASA_IMM_1PNPDE20080520_234710_000000822068_00417_32535_9816.N1						IS2	H/H	68	32535	417	4.07
ASA_IMM_1PNPDK20080520_234808_000001472068_00417_32535_1729.N1						IS2	H/H	68	32535	417	4.07

Filename	Pol	Timestamp	count(Module)
ASA_MS__0PNPDE20080520_042851_000000162068_00405_32523_0289.N1	V	2008-05-20 04:28:51	320





Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WSM_1PNPDE20080520_001636_000001352068_00403_32521_8646.N1						SS1	H/H	68	32521	403	4.07
ASA_WSM_1PNPDE20080520_001636_000002082068_00403_32521_8795.N1						SS1	H/H	68	32521	403	4.07
ASA_WSM_1PNPDE20080520_001946_00000182068_00403_32521_8611.N1						SS1	H/H	68	32521	403	4.07
ASA_WSM_1PNPDE20080520_002912_000003912068_00403_32521_8742.N1						SS1	H/H	68	32521	403	4.07
ASA_WSM_1PNPDE20080520_010555_000000922068_00403_32521_8603.N1						SS1	H/H	68	32521	403	4.07
ASA_WSM_1PNPDE20080520_011716_000002692068_00403_32521_8653.N1						SS1	H/H	68	32521	403	4.07
ASA_WSM_1PNPDE20080520_020838_000001762068_00404_32522_8765.N1						SS1	V/V	68	32522	404	4.07
ASA_WSM_1PNPDE20080520_021148_000003302068_00404_32522_8779.N1						SS1	H/H	68	32522	404	4.07
ASA_WSM_1PNPDE20080520_035024_000005812068_00405_32523_9092.N1						SS1	H/H	68	32523	405	4.07
ASA_WSM_1PNPDE20080520_043029_000002082068_00405_32523_8916.N1						SS1	H/H	68	32523	405	4.07
ASA_WSM_1PNPDK20080520_052945_000002812068_00406_32524_0575.N1						SS1	H/H	68	32524	406	4.07
ASA_WSM_1PNPDE20080520_053255_000002742068_00406_32524_9083.N1						SS1	H/H	68	32524	406	4.07
ASA_WSM_1PNPDK20080520_071206_000004282068_00407_32525_0650.N1						SS1	H/H	68	32525	407	4.07
ASA_WSM_1PNPDE20080520_071832_000000972068_00407_32525_9120.N1						SS1	H/H	68	32525	407	4.07
ASA_WSM_1PNPDE20080520_072016_000000732068_00407_32525_9122.N1						SS1	V/V	68	32525	407	4.07
ASA_WSM_1PNPDE20080520_072016_000003122068_00407_32525_9144.N1						SS1	V/V	68	32525	407	4.07
ASA_WSM_1PNPDE20080520_072231_000001762068_00407_32525_9140.N1						SS1	V/V	68	32525	407	4.07
ASA_WSM_1PNPDE20080520_074147_000002082068_00407_32525_9137.N1						SS1	V/V	68	32525	407	4.07
ASA_WSM_1PNPDE20080520_090932_000001892068_00408_32526_9159.N1						SS1	V/V	68	32526	408	4.07
ASA_WSM_1PNPDE20080520_091045_000001152068_00408_32526_9152.N1						SS1	V/V	68	32526	408	4.07
ASA_WSM_1PNPDE20080520_092855_000005932068_00408_32526_9245.N1						SS1	H/H	68	32526	408	4.07
ASA_WSM_1PNPDE20080520_093917_000000912068_00408_32526_9185.N1						SS1	H/H	68	32526	408	4.07
ASA_WSM_1PNPDE20080520_115919_000000912068_00410_32528_9249.N1						SS1	H/H	68	32528	410	4.07
ASA_WSM_1PNPDE20080520_120402_000001902068_00410_32528_9247.N1						SS1	V/V	68	32528	410	4.07
ASA_WSM_1PNPDE20080520_123459_000001342068_00410_32528_9270.N1						SS1	V/V	68	32528	410	4.07
ASA_WSM_1PNPDE20080520_123459_000005252068_00410_32528_9275.N1						SS1	V/V	68	32528	410	4.07
ASA_WSM_1PNPDE20080520_123809_000003352068_00410_32528_9271.N1						SS1	V/V	68	32528	410	4.07
ASA_WSM_1PNPDE20080520_140032_000000912068_00411_32529_9402.N1						SS1	H/H	68	32529	411	4.07
ASA_WSM_1PNPDE20080520_150715_000000922068_00412_32530_9358.N1						SS1	V/V	68	32530	412	4.07
ASA_WSM_1PNPDE20080520_151929_000001472068_00412_32530_9376.N1						SS1	H/H	68	32530	412	4.07
ASA_WSM_1PNPDE20080520_164737_000001832068_00413_32531_9362.N1						SS1	V/V	68	32531	413	4.07
ASA_WSM_1PNPDE20080520_170006_000001892068_00413_32531_9366.N1						SS1	H/H	68	32531	413	4.07
ASA_WSM_1PNPDE20080520_171615_000001892068_00413_32531_9408.N1						SS1	H/H	68	32531	413	4.07
ASA_WSM_1PNPDE20080520_171728_000001152068_00413_32531_9364.N1						SS1	H/H	68	32531	413	4.07
ASA_WSM_1PNPDE20080520_183057_000000912068_00414_32532_9406.N1						SS1	V/V	68	32532	414	4.07
ASA_WSM_1PNPDE20080520_183152_000002202068_00414_32532_9360.N1						SS1	V/V	68	32532	414	4.07
ASA_WSM_1PNPDE20080520_185428_000000912068_00414_32532_9404.N1						SS1	H/H	68	32532	414	4.07
ASA_WSM_1PNPDE20080520_185907_000002312068_00414_32532_9414.N1						SS1	V/V	68	32532	414	4.07
ASA_WSM_1PNPDE20080520_194319_000002322068_00414_32532_9410.N1						SS1	H/H	68	32532	414	4.07
ASA_WSM_1PNPDE20080520_200045_000001532068_00414_32532_9412.N1						SS1	H/H	68	32532	414	4.07
ASA_WSM_1PNPDE20080520_203154_000002312068_00415_32533_9543.N1						SS1	H/H	68	32533	415	4.07
ASA_WSM_1PNPDE20080520_203615_000000922068_00415_32533_9539.N1						SS1	H/H	68	32533	415	4.07
ASA_WSM_1PNPDE20080520_210830_000000732068_00415_32533_9506.N1						SS1	V/V	68	32533	415	4.07
ASA_WSM_1PNPDE20080520_212327_000002082068_00415_32533_9541.N1						SS1	H/H	68	32533	415	4.07
ASA_WSM_1PNPDE20080520_221607_000003122068_00416_32534_9771.N1						SS1	H/H	68	32534	416	4.07
ASA_WSM_1PNPDE20080520_225442_000002082068_00416_32534_9765.N1						SS1	H/H	68	32534	416	4.07
ASA_WSM_1PNPDE20080520_230042_000002512068_00416_32534_9763.N1						SS1	H/H	68	32534	416	4.07
ASA_WSM_1PNPDE20080520_235836_000002692068_00417_32535_9949.N1						SS1	H/H	68	32535	417	4.07


Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WVS_1PNPDE20080519_234742_000016942068_00402_32520_8508.N1						IS2	V/V	68	32520	402	4.07
ASA_WVS_1PNPDE20080520_003544_000010522068_00403_32521_8513.N1						IS2	V/V	68	32521	403	4.07
ASA_WVS_1PNPDE20080520_010033_000002852068_00403_32521_8518.N1						IS2	V/V	68	32521	403	4.07
ASA_WVS_1PNPDE20080520_012345_000002252068_00403_32521_8523.N1						IS2	V/V	68	32521	403	4.07
ASA_WVS_1PNPDE20080520_012645_000003752068_00403_32521_8671.N1						IS2	V/V	68	32521	403	4.07
ASA_WVS_1PNPDE20080520_014225_000007042068_00404_32522_8666.N1						IS2	V/V	68	32522	404	4.07
ASA_WVS_1PNPDE20080520_022522_000000592068_00404_32522_8658.N1						IS2	V/V	68	32522	404	4.07
ASA_WVS_1PNPDE20080520_022838_000010792068_00404_32522_8661.N1						IS2	V/V	68	32522	404	4.07
ASA_WVS_1PNPDE20080520_024608_000000902068_00404_32522_8784.N1						IS2	V/V	68	32522	404	4.07
ASA_WVS_1PNPDE20080520_030421_000002102068_00404_32522_8789.N1						IS2	V/V	68	32522	404	4.07
ASA_WVS_1PNPDE20080520_032415_000001942068_00405_32523_8802.N1						IS2	V/V	68	32523	405	4.07
ASA_WVS_1PNPDE20080520_040616_000009592068_00405_32523_8807.N1						IS2	V/V	68	32523	405	4.07
ASA_WVS_1PNPDE20080520_042200_000001202068_00405_32523_8919.N1						IS2	V/V	68	32523	405	4.07
ASA_WVS_1PNPDE20080520_042706_000000602068_00405_32523_8922.N1						IS2	V/V	68	32523	405	4.07
ASA_WVS_1PNPDE20080520_044457_000012742068_00405_32523_8939.N1						IS2	V/V	68	32523	405	4.07
ASA_WVS_1PNPDE20080520_054553_000010192068_00406_32524_8949.N1						IS2	V/V	68	32524	406	4.07
ASA_WVS_1PNPDK20080520_060223_000003752068_00406_32524_0578.N1						IS2	V/V	68	32524	406	4.07
ASA_WVS_1PNPDE20080520_054553_000010192068_00406_32524_8949.N1						IS1	V/V	68	32524	406	4.07
ASA_WVS_1PNPDK20080520_062533_000019642068_00406_32524_0589.N1						IS2	V/V	68	32524	406	4.07
ASA_WVS_1PNPDK20080520_074516_000002402068_00407_32525_0653.N1						IS2	V/V	68	32525	407	4.07
ASA_WVS_1PNPDK20080520_080609_000012592068_00407_32525_0662.N1						IS2	V/V	68	32525	407	4.07
ASA_WVS_1PNPDK20080520_082918_000004642068_00408_32526_0659.N1						IS2	V/V	68	32526	408	4.07
ASA_WVS_1PNPDK20080520_083853_000001052068_00408_32526_0720.N1						IS2	V/V	68	32526	408	4.07
ASA_WVS_1PNPDK20080520_091345_000008692068_00408_32526_0800.N1						IS2	V/V	68	32526	408	4.07
ASA_WVS_1PNPDK20080520_094645_000019942068_00408_32526_0826.N1						IS2	V/V	68	32526	408	4.07
ASA_WVS_1PNPDK20080520_105135_000011392068_00409_32527_0936.N1						IS2	V/V	68	32527	409	4.07
ASA_WVS_1PNPDK20080520_112721_000002702068_00409_32527_0939.N1						IS2	V/V	68	32527	409	4.07
ASA_WVS_1PNPDK20080520_113410_000014692068_00409_32527_1019.N1						IS2	V/V	68	32527	409	4.07
ASA_WVS_1PNPDK20080520_121709_000010192068_00410_32528_1061.N1						IS2	V/V	68	32528	410	4.07
ASA_WVS_1PNPDK20080520_124440_000003902068_00410_32528_1064.N1						IS2	V/V	68	32528	410	4.07
ASA_WVS_1PNPDK20080520_130757_000003002068_00410_32528_1069.N1						IS2	V/V	68	32528	410	4.07
ASA_WVS_1PNPDK20080520_132137_000007882068_00410_32528_1152.N1						IS2	V/V	68	32528	410	4.07
ASA_WVS_1PNPDK20080520_140202_000005842068_00411_32529_1232.N1						IS2	V/V	68	32529	411	4.07
ASA_WVS_1PNPDK20080520_142058_000006452068_00411_32529_1239.N1						IS2	V/V	68	32529	411	4.07
ASA_WVS_1PNPDK20080520_144833_000003752068_00411_32529_1249.N1						IS2	V/V	68	32529	411	4.07
ASA_WVS_1PNPDK20080520_145913_000001942068_00411_32529_1242.N1						IS2	V/V	68	32529	411	4.07
ASA_WVS_1PNPDK20080520_150409_000001492068_00411_32529_1252.N1						IS2	V/V	68	32529	411	4.07
ASA_WVS_1PNPDK20080520_154753_000000892068_00412_32530_1366.N1						IS2	V/V	68	32530	412	4.07
ASA_WVS_1PNPDK20080520_155221_000001492068_00412_32530_1363.N1						IS2	V/V	68	32530	412	4.07
ASA_WVS_1PNPDK20080520_155656_000009292068_00412_32530_1371.N1						IS2	V/V	68	32530	412	4.07
ASA_WVS_1PNPDK20080520_162909_000010642068_00412_32530_1385.N1						IS2	V/V	68	32530	412	4.07
ASA_WVS_1PNPDK20080520_172923_000014092068_00413_32531_1490.N1						IS2	V/V	68	32531	413	4.07
ASA_WVS_1PNPDK20080520_181332_000010042068_00413_32531_1495.N1						IS2	V/V	68	32531	413	4.07
ASA_WVS_1PNPDK20080520_190257_000018292068_00414_32532_1595.N1						IS2	V/V	68	32532	414	4.07
ASA_WVS_1PNPDK20080520_195021_000005852068_00414_32532_1605.N1						IS2	V/V	68	32532	414	4.07
ASA_WVS_1PNPDE20080520_204129_000005242068_00415_32533_9417.N1						IS2	V/V	68	32533	415	4.07
ASA_WVS_1PNPDE20080520_205142_000009592068_00415_32533_9425.N1						IS2	V/V	68	32533	415	4.07
ASA_WVS_1PNPDE20080520_210942_000002702068_00415_32533_9420.N1						IS2	V/V	68	32533	415	4.07
ASA_WVS_1PNPDE20080520_213057_000002842068_00415_32533_9433.N1						IS2	V/V	68	32533	415	4.07
ASA_WVS_1PNPDE20080520_213442_000002542068_00415_32533_9554.N1						IS2	V/V	68	32533	415	4.07
ASA_WVS_1PNPDE20080520_213057_000002842068_00415_32533_9433.N1						IS1	V/V	68	32533	415	4.07
ASA_WVS_1PNPDE20080520_214313_000002992068_00415_32533_9559.N1						IS2	V/V	68	32533	415	4.07
ASA_WVS_1PNPDE20080520_220259_000001202068_00416_32534_9564.N1						IS2	V/V	68	32534	416	4.07
ASA_WVS_1PNPDE20080520_222247_000006742068_00416_32534_9570.N1						IS2	V/V	68	32534	416	4.07
ASA_WVS_1PNPDE20080520_223416_000000442068_00416_32534_9567.N1						IS2	V/V	68	32534	416	4.07
ASA_WVS_1PNPDE20080520_223516_000000002068_00416_32534_9576.N1						IS2	V/V	68	32534	416	4.07
ASA_WVS_1PNPDE20080520_223531_000000292068_00416_32534_9634.N1						IS2	V/V	68	32534	416	4.07
ASA_WVS_1PNPDE20080520_223531_000000292068_00416_32534_9634.N1						IS1	V/V	68	32534	416	4.07
ASA_WVS_1PNPDE20080520_223616_000000002068_00416_32534_9637.N1						IS1	H/H	68	32534	416	4.07
ASA_WVS_1PNPDE20080520_223631_000000142068_00416_32534_9618.N1						IS2	V/V	68	32534	416	4.07
ASA_WVS_1PNPDE20080520_223701_000000142068_00416_32534_9656.N1						IS2	V/V	68	32534	416	4.07
ASA_WVS_1PNPDE20080520_223731_000000002068_00416_32534_9647.N1						IS2	V/V	68	32534	416	4.07
ASA_WVS_1PNPDE20080520_223746_000000002068_00416_32534_9660.N1						IS2	V/V	68	32534	416	4.07
ASA_WVS_1PNPDE20080520_223801_000000002068_00416_32534_9672.N1						IS1	H/H	68	32534	416	4.07
ASA_WVS_1PNPDE20080520_223816_000000002068_00416_32534_9668.N1						IS1	H/H	68	32534	416	4.07
ASA_WVS_1PNPDE20080520_223831_000009292068_00416_32534_9694.N1						IS2	V/V	68	32534	416	4.07
ASA_WVS_1PNPDE20080520_231132_000004202068_00416_32534_9686.N1						IS2	V/V	68	32534	416	4.07




ASA_WVS_1PNPDE20080520_231748_000008392068_00416_32534_9789.N1	IS2	V/V	68	32534	416	4.07
ASA_WVS_1PNPDE20080520_233340_000002392068_00417_32535_9786.N1	IS2	V/V	68	32535	417	4.07
ASA_WVS_1PNPDE20080520_233957_000003602068_00417_32535_9792.N1	IS2	V/V	68	32535	417	4.07














































































20-May




20-May




20-May











20-May



20-May



20-May

