



# ASAR Daily Report



Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
ASA_APM_1PNPDE20080627_072612_000000432069_00450_33069_1202.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20080627_073402_000000892069_00450_33069_1210.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20080627_090722_000000502069_00451_33070_1236.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20080627_152133_000000412069_00455_33074_1462.N1	OK	OK	OK	OK
ASA_APM_1PNPDK20080627_090549_000000432069_00451_33070_7880.N1	OK	OK	OK	OK
ASA_APM_1PNPDK20080627_153819_000000442069_00455_33074_8421.N1	OK	OK	OK	OK
ASA_APM_1PNPDK20080627_202552_000000432069_00458_33077_8689.N1	OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_GM1_1PNPDE20080627_002423_000009302069_00446_33065_0656.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080627_005948_000003862069_00446_33065_0658.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080627_011157_000001382069_00446_33065_0663.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080627_012736_000002052069_00446_33065_0676.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080627_013907_000005432069_00446_33065_0810.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080627_015912_000002292069_00447_33066_0806.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080627_020559_000004952069_00447_33066_0808.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080627_021544_000002472069_00447_33066_0823.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080627_021544_000005792069_00447_33066_1275.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080627_022657_000002172069_00447_33066_1272.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080627_025233_000001442069_00447_33066_0906.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080627_030906_000001502069_00447_33066_0904.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080627_031410_000001992069_00447_33066_0897.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080627_031814_000001502069_00447_33066_0899.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080627_032157_000004892069_00447_33066_0911.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080627_033436_000001202069_00448_33067_0913.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080627_033912_000020052069_00448_33067_0992.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080627_043309_000001632069_00448_33067_1055.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080627_044224_000005862069_00448_33067_1085.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080627_051344_000001442069_00449_33068_1077.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080627_052044_000008942069_00449_33068_1090.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080627_054322_000001502069_00449_33068_1075.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080627_054743_000002772069_00449_33068_1073.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080627_203053_000002052069_00458_33077_1560.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080627_203924_000002952069_00458_33077_1564.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080627_211909_000002112069_00458_33077_1562.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080627_213438_000001502069_00458_33077_1571.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080627_213438_000002112069_00458_33077_1692.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080627_215441_000000842069_00459_33078_1710.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080627_215441_000000842069_00459_33078_2089.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080627_215739_000003262069_00459_33078_1718.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080627_215739_000003262069_00459_33078_2091.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080627_222022_000003742069_00459_33078_1723.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080627_222022_000003742069_00459_33078_2103.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080627_225944_000001572069_00459_33078_1725.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080627_225944_000001572069_00459_33078_2101.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080627_231438_000002472069_00459_33078_1738.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20080627_231438_000002472069_00459_33078_2099.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080627_061345_000002052069_00449_33068_7663.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080627_061941_000007852069_00449_33068_7668.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080627_070733_000005792069_00450_33069_7676.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080627_071624_000001142069_00450_33069_7760.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080627_072715_000004042069_00450_33069_7764.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080627_073551_000001812069_00450_33069_7762.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080627_074008_000001262069_00450_33069_7766.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080627_075421_000001142069_00450_33069_7848.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080627_084700_000006642069_00451_33070_7853.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080627_085717_000001082069_00451_33070_7900.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080627_093457_000001932069_00451_33070_7902.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080627_094643_000004342069_00451_33070_7907.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080627_102623_000005372069_00452_33071_7959.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080627_105140_000002112069_00452_33071_8046.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080627_111533_000001502069_00452_33071_8044.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080627_112237_000001502069_00452_33071_8051.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080627_112958_000002772069_00452_33071_8056.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080627_120603_000002232069_00453_33072_8058.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080627_121116_000001752069_00453_33072_8129.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080627_124106_000005732069_00453_33072_8177.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080627_125609_000001692069_00453_33072_8175.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080627_130827_000004042069_00453_33072_8185.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080627_131930_000004712069_00453_33072_8187.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080627_134228_000008822069_00454_33073_8194.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080627_135622_000006402069_00454_33073_8319.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20080627_141812_000002832069_00454_33073_8317.N1					OK	OK	OK	OK

ASA_GM1_1PNPDK20080627_142422_000001082069_00454_33073_8333.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080627_143645_000000842069_00454_33073_8328.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080627_143930_000000842069_00454_33073_8326.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080627_144525_000006222069_00454_33073_8324.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080627_150111_000001932069_00454_33073_8340.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080627_151416_000003142069_00455_33074_8347.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080627_152015_000000782069_00455_33074_8338.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080627_152236_000005612069_00455_33074_8349.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080627_154112_000007492069_00455_33074_8452.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080627_155544_000001322069_00455_33074_8454.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080627_161721_000006042069_00455_33074_8459.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080627_162959_000003802069_00455_33074_8461.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080627_165406_000003802069_00456_33075_8463.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080627_170225_000003802069_00456_33075_8468.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080627_172533_000004532069_00456_33075_8571.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080627_175757_000007732069_00456_33075_8576.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080627_183646_000005192069_00457_33076_8586.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080627_190609_000001142069_00457_33076_8687.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080627_193833_000002472069_00457_33076_8691.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080627_194715_000006162069_00457_33076_8693.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20080627_200912_000009972069_00457_33076_8779.N1	OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_IMM_1PNPDE20080627_004531_000000842069_00446_33065_0758.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080627_011416_000005612069_00446_33065_0795.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080627_012416_000001892069_00446_33065_0760.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080627_022524_000000822069_00447_33066_0872.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080627_025459_000004422069_00447_33066_0893.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080627_030259_000003562069_00447_33066_1014.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080627_031725_000000382069_00447_33066_1006.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080627_043551_000002612069_00448_33067_1035.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080627_044051_000000812069_00448_33067_1103.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080627_051610_000002632069_00449_33068_1183.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080627_054554_000000972069_00449_33068_1101.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080627_061708_000000632069_00449_33068_1105.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080627_061708_000001402069_00449_33068_1185.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080627_061910_000000192069_00449_33068_1109.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080627_073850_000000662069_00450_33069_1216.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080627_093811_000005002069_00451_33070_1406.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080627_105509_000001002069_00452_33071_1370.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080627_111804_000002622069_00452_33071_1382.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080627_112504_000002832069_00452_33071_1432.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080627_113756_000000832069_00452_33071_1430.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080627_113900_000000192069_00452_33071_1418.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080627_142254_000000772069_00454_33073_1478.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080627_144052_000002622069_00454_33073_1488.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080627_151927_000000372069_00455_33074_1456.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080627_162726_000001422069_00455_33074_1450.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080627_162929_000000192069_00455_33074_1448.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080627_170025_000001092069_00456_33075_1490.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080627_172057_000000392069_00456_33075_1498.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080627_173303_000000372069_00456_33075_1500.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080627_181049_000002232069_00456_33075_1518.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080627_185813_000001142069_00457_33076_1526.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080627_194242_000002622069_00457_33076_1554.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080627_204417_000001662069_00458_33077_1672.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080627_212239_000002612069_00458_33077_1708.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080627_212739_000004062069_00458_33077_1687.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080627_222904_000000672069_00459_33078_1828.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080627_222904_000000672069_00459_33078_2267.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080627_230222_000002012069_00459_33078_1849.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080627_230622_000004832069_00459_33078_1851.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080627_233754_000000862069_00460_33079_1869.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20080627_233754_000000862069_00460_33079_2336.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20080627_053854_000000372069_00449_33068_7653.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20080627_070448_000001532069_00450_33069_7716.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20080627_083334_000000992069_00451_33070_7844.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20080627_084309_000000812069_00451_33070_7882.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20080627_122132_000000592069_00453_33072_8137.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20080627_125854_0000005622069_00453_33072_8315.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20080627_134100_000000622069_00454_33073_8278.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20080627_202714_000000372069_00458_33077_8698.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20080627_221136_000000742069_00459_33078_8810.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20080627_235406_000001172069_00460_33079_8830.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20080627_235509_000000542069_00460_33079_8828.N1					OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.


Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
ASA_WSM_1PNPDE20080627_002219_000001212069_00446_33065_0748.N1	OK	OK	OK	OK
ASA_WSM_1PNPDE20080627_020303_000001702069_00447_33066_0895.N1	OK	OK	OK	OK
ASA_WSM_1PNPDE20080627_021415_000000732069_00447_33066_0852.N1	OK	OK	OK	OK
ASA_WSM_1PNPDE20080627_023351_000001892069_00447_33066_0870.N1	OK	OK	OK	OK
ASA_WSM_1PNPDE20080627_033201_000001522069_00448_33067_1045.N1	OK	OK	OK	OK
ASA_WSM_1PNPDE20080627_033638_000001462069_00448_33067_1043.N1	OK	OK	OK	OK
ASA_WSM_1PNPDE20080627_053945_000000732069_00449_33068_1047.N1	OK	OK	OK	OK
ASA_WSM_1PNPDE20080627_053945_000002132069_00449_33068_1190.N1	OK	OK	OK	OK
ASA_WSM_1PNPDE20080627_054159_000000792069_00449_33068_1181.N1	OK	OK	OK	OK
ASA_WSM_1PNPDE20080627_072417_000000982069_00450_33069_1208.N1	OK	OK	OK	OK
ASA_WSM_1PNPDE20080627_074217_000005252069_00450_33069_1242.N1	OK	OK	OK	OK
ASA_WSM_1PNPDE20080627_091345_000001352069_00451_33070_1340.N1	OK	OK	OK	OK
ASA_WSM_1PNPDE20080627_091345_000002812069_00451_33070_1350.N1	OK	OK	OK	OK
ASA_WSM_1PNPDE20080627_091655_000000902069_00451_33070_1341.N1	OK	OK	OK	OK
ASA_WSM_1PNPDE20080627_104832_000000732069_00452_33071_1348.N1	OK	OK	OK	OK
ASA_WSM_1PNPDE20080627_120948_000000732069_00453_33072_1402.N1	OK	OK	OK	OK
ASA_WSM_1PNPDE20080627_151242_000000912069_00455_33074_1492.N1	OK	OK	OK	OK
ASA_WSM_1PNPDE20080627_153933_000000972069_00455_33074_1494.N1	OK	OK	OK	OK
ASA_WSM_1PNPDE20080627_171850_000000912069_00456_33075_1496.N1	OK	OK	OK	OK
ASA_WSM_1PNPDE20080627_172154_000002142069_00456_33075_1520.N1	OK	OK	OK	OK
ASA_WSM_1PNPDE20080627_190108_000002992069_00457_33076_1558.N1	OK	OK	OK	OK
ASA_WSM_1PNPDE20080627_200552_000001902069_00457_33076_1556.N1	OK	OK	OK	OK
ASA_WSM_1PNPDE20080627_203735_000001042069_00458_33077_1706.N1	OK	OK	OK	OK



Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.


Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WVS_1PNPDE20080627_004000_000003002069_00446_33065_0651.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080627_004701_000007202069_00446_33065_0661.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080627_010618_000003002069_00446_33065_0666.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080627_013100_000001342069_00446_33065_0674.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080627_013215_000003752069_00446_33065_0798.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080627_014812_000006142069_00447_33066_0826.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080627_023704_000008392069_00447_33066_1278.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080627_025019_000009092069_00447_33066_0902.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080627_031136_000001052069_00447_33066_0909.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080627_033013_00000592069_00448_33067_0916.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080627_041237_000008692069_00448_33067_0930.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080627_042637_000002102069_00448_33067_1058.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080627_045212_000012442069_00448_33067_1093.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080627_055222_000009892069_00449_33068_1088.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080627_204713_000018742069_00458_33077_1574.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080627_213811_000002242069_00458_33077_1690.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080627_214056_000007792069_00458_33077_1713.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080627_214056_000007792069_00458_33077_2195.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080627_220908_000001052069_00459_33078_1716.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080627_220908_000001052069_00459_33078_2097.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080627_222636_000001052069_00459_33078_1721.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080627_222636_000001052069_00459_33078_2094.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080627_223017_000017242069_00459_33078_1728.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080627_223017_000017242069_00459_33078_2111.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080627_231847_000002092069_00459_33078_1731.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20080627_231847_000002092069_00459_33078_2106.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080627_060836_000002702069_00449_33068_7666.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080627_063248_000018892069_00449_33068_7684.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080627_075102_000001502069_00450_33069_7780.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080627_081324_000011692069_00450_33069_7790.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080627_083520_000004342069_00451_33070_7787.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080627_084437_000001052069_00451_33070_7851.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080627_091829_000009442069_00451_33070_7905.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080627_095400_000019042069_00451_33070_7962.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080627_104305_000000452069_00452_33071_8042.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080627_105657_000010642069_00452_33071_8054.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080627_113436_000001652069_00452_33071_8049.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080627_113925_000015592069_00452_33071_8127.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080627_122236_000010642069_00453_33072_8173.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080627_125043_000002852069_00453_33072_8183.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080627_131512_000002102069_00453_33072_8180.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080627_132721_000007762069_00453_33072_8251.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080627_140702_000006292069_00454_33073_8322.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080627_142615_000005852069_00454_33073_8331.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080627_145547_000002852069_00454_33073_8336.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080627_150426_000004492069_00454_33073_8352.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080627_155341_000000742069_00455_33074_8450.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080627_155756_000011242069_00455_33074_8457.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080627_163623_000010192069_00455_33074_8466.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080627_173421_000013642069_00456_33075_8574.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080627_181948_000009742069_00456_33075_8579.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080627_190807_000017842069_00457_33076_8696.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20080627_200039_000002702069_00457_33076_8710.N1					OK	OK	OK	OK

Calibration pulses for GM1 SS3 H/H







Calibration pulses for GM1 SS3 H/H




Calibration pulses for GM1 SS3 H/H




### Calibration pulses for GM1 SS3 H/H




### Calibration pulses for WVS IS2 V/V



### Calibration pulses for WVS IS2 V/V





### Calibration pulses for WVS IS2 V/V








Calibration pulses for WVS IS2 V/V

















rows: \_ 1 \_ 5 \_ 9 \_ 13 \_ 17 \_ 21 \_ 25 \_ 29





































Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_APM_1PNPDE20080627_072612_000000432069_00450_33069_1202.N1						IS7	V/H	69	0	450	4.07
ASA_APM_1PNPDE20080627_073402_000000892069_00450_33069_1210.N1						IS2	H/H	69	0	450	4.07
ASA_APM_1PNPDK20080627_090549_000000432069_00451_33070_7880.N1						IS2	V/H	69	0	451	4.07
ASA_APM_1PNPDE20080627_090722_000000502069_00451_33070_1236.N1						IS4	V/H	69	0	451	4.07
ASA_APM_1PNPDE20080627_152133_000000412069_00455_33074_1462.N1						IS7	H/H	69	0	455	4.07
ASA_APM_1PNPDK20080627_153819_000000442069_00455_33074_8421.N1						IS6	H/H	69	0	455	4.07
ASA_APM_1PNPDK20080627_202552_000000432069_00458_33077_8689.N1						IS2	H/H	69	0	458	4.07

Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_GM1_1PNPDE20080627_002423_000009302069_00446_33065_0656.N1						SS1	H/H	69	0	446	4.07
ASA_GM1_1PNPDE20080627_005948_000003862069_00446_33065_0658.N1						SS1	H/H	69	0	446	4.07
ASA_GM1_1PNPDE20080627_011157_000001382069_00446_33065_0663.N1						SS1	H/H	69	0	446	4.07
ASA_GM1_1PNPDE20080627_012736_000002052069_00446_33065_0676.N1						SS1	H/H	69	0	446	4.07
ASA_GM1_1PNPDE20080627_013907_000005432069_00446_33065_0810.N1						SS1	H/H	69	0	446	4.07
ASA_GM1_1PNPDE20080627_015912_000002292069_00447_33066_0806.N1						SS1	H/H	69	0	447	4.07
ASA_GM1_1PNPDE20080627_020559_000004952069_00447_33066_0808.N1						SS1	H/H	69	0	447	4.07
ASA_GM1_1PNPDE20080627_021544_000002472069_00447_33066_0823.N1						SS1	H/H	69	0	447	4.07
ASA_GM1_1PNPDE20080627_021544_000005792069_00447_33066_1275.N1						SS1	H/H	69	0	447	4.07
ASA_GM1_1PNPDE20080627_022657_000002172069_00447_33066_1272.N1						SS1	H/H	69	0	447	4.07
ASA_GM1_1PNPDE20080627_025233_000001442069_00447_33066_0906.N1						SS1	H/H	69	0	447	4.07
ASA_GM1_1PNPDE20080627_030906_000001502069_00447_33066_0904.N1						SS1	H/H	69	0	447	4.07
ASA_GM1_1PNPDE20080627_031410_000001992069_00447_33066_0897.N1						SS1	H/H	69	0	447	4.07
ASA_GM1_1PNPDE20080627_031814_000001502069_00447_33066_0899.N1						SS1	H/H	69	0	447	4.07
ASA_GM1_1PNPDE20080627_032157_000004892069_00447_33066_0911.N1						SS1	H/H	69	0	447	4.07
ASA_GM1_1PNPDE20080627_033436_000001202069_00448_33067_0913.N1						SS1	H/H	69	0	448	4.07
ASA_GM1_1PNPDE20080627_033912_000020052069_00448_33067_0992.N1						SS1	H/H	69	0	448	4.07
ASA_GM1_1PNPDE20080627_043309_000001632069_00448_33067_1055.N1						SS1	H/H	69	0	448	4.07
ASA_GM1_1PNPDE20080627_044224_000005862069_00448_33067_1085.N1						SS1	H/H	69	0	448	4.07
ASA_GM1_1PNPDE20080627_051344_000001442069_00449_33068_1077.N1						SS1	H/H	69	0	449	4.07
ASA_GM1_1PNPDE20080627_052044_000008942069_00449_33068_1090.N1						SS1	H/H	69	0	449	4.07
ASA_GM1_1PNPDE20080627_054322_000001502069_00449_33068_1075.N1						SS1	H/H	69	0	449	4.07
ASA_GM1_1PNPDE20080627_054743_000002772069_00449_33068_1073.N1						SS1	H/H	69	0	449	4.07
ASA_GM1_1PNPDK20080627_061345_000002052069_00449_33068_7663.N1						SS1	H/H	69	0	449	4.07
ASA_GM1_1PNPDK20080627_061941_000007852069_00449_33068_7668.N1						SS1	H/H	69	0	449	4.07
ASA_GM1_1PNPDK20080627_070733_000005792069_00450_33069_7676.N1						SS1	H/H	69	0	450	4.07
ASA_GM1_1PNPDK20080627_071624_000001142069_00450_33069_7760.N1						SS1	H/H	69	0	450	4.07
ASA_GM1_1PNPDK20080627_072715_000004042069_00450_33069_7764.N1						SS1	H/H	69	0	450	4.07
ASA_GM1_1PNPDK20080627_073551_000001812069_00450_33069_7762.N1						SS1	H/H	69	0	450	4.07
ASA_GM1_1PNPDK20080627_074008_000001262069_00450_33069_7766.N1						SS1	H/H	69	0	450	4.07
ASA_GM1_1PNPDK20080627_075421_0000011422069_00450_33069_7848.N1						SS1	H/H	69	0	450	4.07
ASA_GM1_1PNPDK20080627_084700_000006642069_00451_33070_7853.N1						SS1	H/H	69	0	451	4.07
ASA_GM1_1PNPDK20080627_085717_000001082069_00451_33070_7900.N1						SS1	H/H	69	0	451	4.07
ASA_GM1_1PNPDK20080627_093457_000001932069_00451_33070_7902.N1						SS1	H/H	69	0	451	4.07
ASA_GM1_1PNPDK20080627_094643_000004342069_00451_33070_7907.N1						SS1	H/H	69	0	451	4.07
ASA_GM1_1PNPDK20080627_102623_000005372069_00452_33071_7959.N1						SS1	H/H	69	0	452	4.07
ASA_GM1_1PNPDK20080627_105140_000002112069_00452_33071_8046.N1						SS1	H/H	69	0	452	4.07
ASA_GM1_1PNPDK20080627_111533_000001502069_00452_33071_8044.N1						SS1	H/H	69	0	452	4.07
ASA_GM1_1PNPDK20080627_112237_000001502069_00452_33071_8051.N1						SS1	H/H	69	0	452	4.07
ASA_GM1_1PNPDK20080627_112958_000002772069_00452_33071_8056.N1						SS1	H/H	69	0	452	4.07
ASA_GM1_1PNPDK20080627_120603_000002232069_00453_33072_8058.N1						SS1	H/H	69	0	453	4.07
ASA_GM1_1PNPDK20080627_121116_000001752069_00453_33072_8129.N1						SS1	H/H	69	0	453	4.07
ASA_GM1_1PNPDK20080627_124106_000005732069_00453_33072_8177.N1						SS1	H/H	69	0	453	4.07
ASA_GM1_1PNPDK20080627_125609_000001692069_00453_33072_8175.N1						SS1	H/H	69	0	453	4.07
ASA_GM1_1PNPDK20080627_130827_000004042069_00453_33072_8185.N1						SS1	H/H	69	0	453	4.07
ASA_GM1_1PNPDK20080627_131930_000004712069_00453_33072_8187.N1						SS1	H/H	69	0	453	4.07
ASA_GM1_1PNPDK20080627_134228_000008822069_00454_33073_8194.N1						SS1	H/H	69	0	454	4.07
ASA_GM1_1PNPDK20080627_135622_000006402069_00454_33073_8319.N1						SS1	H/H	69	0	454	4.07
ASA_GM1_1PNPDK20080627_141812_000002832069_00454_33073_8317.N1						SS1	H/H	69	0	454	4.07
ASA_GM1_1PNPDK20080627_142422_000001082069_00454_33073_8333.N1						SS1	H/H	69	0	454	4.07
ASA_GM1_1PNPDK20080627_143645_000000842069_00454_33073_8328.N1						SS1	H/H	69	0	454	4.07
ASA_GM1_1PNPDK20080627_143930_000000842069_00454_33073_8326.N1						SS1	H/H	69	0	454	4.07
ASA_GM1_1PNPDK20080627_144525_000006222069_00454_33073_8324.N1						SS1	H/H	69	0	454	4.07
ASA_GM1_1PNPDK20080627_150111_000001932069_00454_33073_8340.N1						SS1	H/H	69	0	454	4.07
ASA_GM1_1PNPDK20080627_151416_000003142069_00455_33074_8347.N1						SS1	H/H	69	0	455	4.07
ASA_GM1_1PNPDK20080627_152015_000000782069_00455_33074_8338.N1						SS1	H/H	69	0	455	4.07
ASA_GM1_1PNPDK20080627_152236_000005612069_00455_33074_8349.N1						SS1	H/H	69	0	455	4.07
ASA_GM1_1PNPDK20080627_154112_000007492069_00455_33074_8452.N1						SS1	H/H	69	0	455	4.07
ASA_GM1_1PNPDK20080627_155544_000001322069_00455_33074_8454.N1						SS1	H/H	69	0	455	4.07
ASA_GM1_1PNPDK20080627_161721_000006042069_00455_33074_8459.N1						SS1	H/H	69	0	455	4.07
ASA_GM1_1PNPDK20080627_162959_000003802069_00455_33074_8461.N1						SS1	H/H	69	0	455	4.07
ASA_GM1_1PNPDK20080627_165406_000003802069_00456_33075_8463.N1						SS1	H/H	69	0	456	4.07
ASA_GM1_1PNPDK20080627_170225_000003802069_00456_33075_8468.N1						SS1	H/H	69	0	456	4.07
ASA_GM1_1PNPDK20080627_172533_000004532069_00456_33075_8571.N1						SS1	H/H	69	0	456	4.07
ASA_GM1_1PNPDK20080627_175757_000007732069_00456_33075_8576.N1						SS1	H/H	69	0	456	4.07
ASA_GM1_1PNPDK20080627_183646_000005192069_00457_33076_8586.N1						SS1	H/H	69	0	457	4.07
ASA_GM1_1PNPDK20080627_190609_000001142069_00457_33076_8687.N1						SS1	H/H	69	0	457	4.07

ASA_GM1_1PNPDK20080627_193833_000002472069_00457_33076_8691.N1	SS1	H/H	69	0	457	4.07
ASA_GM1_1PNPDK20080627_194715_000006162069_00457_33076_8693.N1	SS1	H/H	69	0	457	4.07
ASA_GM1_1PNPDK20080627_200912_000009972069_00457_33076_8779.N1	SS1	H/H	69	0	457	4.07
ASA_GM1_1PNPDE20080627_203053_000002052069_00458_33077_1560.N1	SS1	H/H	69	0	458	4.07
ASA_GM1_1PNPDE20080627_203924_000002952069_00458_33077_1564.N1	SS1	H/H	69	0	458	4.07
ASA_GM1_1PNPDE20080627_211909_000002112069_00458_33077_1562.N1	SS1	H/H	69	0	458	4.07
ASA_GM1_1PNPDE20080627_213438_000001502069_00458_33077_1571.N1	SS1	H/H	69	0	458	4.07
ASA_GM1_1PNPDE20080627_213438_000002112069_00458_33077_1692.N1	SS1	H/H	69	0	458	4.07
ASA_GM1_1PNPDE20080627_215441_000000842069_00459_33078_1710.N1	SS1	H/H	69	0	459	4.07
ASA_GM1_1PNPDE20080627_215441_000000842069_00459_33078_2089.N1	SS1	H/H	69	0	459	4.07
ASA_GM1_1PNPDE20080627_215739_000003262069_00459_33078_1718.N1	SS1	H/H	69	0	459	4.07
ASA_GM1_1PNPDE20080627_215739_000003262069_00459_33078_2091.N1	SS1	H/H	69	0	459	4.07
ASA_GM1_1PNPDE20080627_222022_000003742069_00459_33078_1723.N1	SS1	H/H	69	0	459	4.07
ASA_GM1_1PNPDE20080627_222022_000003742069_00459_33078_2103.N1	SS1	H/H	69	0	459	4.07
ASA_GM1_1PNPDE20080627_225944_000001572069_00459_33078_1725.N1	SS1	H/H	69	0	459	4.07
ASA_GM1_1PNPDE20080627_225944_000001572069_00459_33078_2101.N1	SS1	H/H	69	0	459	4.07
ASA_GM1_1PNPDE20080627_231438_000002472069_00459_33078_1738.N1	SS1	H/H	69	0	459	4.07
ASA_GM1_1PNPDE20080627_231438_000002472069_00459_33078_2099.N1	SS1	H/H	69	0	459	4.07

Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_IMM_1PNPDE20080627_004531_000000842069_00446_33065_0758.N1						IS4	H/H	69	0	446	4.07
ASA_IMM_1PNPDE20080627_011416_000005612069_00446_33065_0795.N1						IS2	H/H	69	0	446	4.07
ASA_IMM_1PNPDE20080627_012416_000001892069_00446_33065_0760.N1						IS2	H/H	69	0	446	4.07
ASA_IMM_1PNPDE20080627_022524_000000822069_00447_33066_0872.N1						IS2	V/V	69	0	447	4.07
ASA_IMM_1PNPDE20080627_025459_000004422069_00447_33066_0893.N1						IS2	H/H	69	0	447	4.07
ASA_IMM_1PNPDE20080627_030259_000003562069_00447_33066_1014.N1						IS2	H/H	69	0	447	4.07
ASA_IMM_1PNPDE20080627_031725_000000382069_00447_33066_1006.N1						IS4	V/V	69	0	447	4.07
ASA_IMM_1PNPDE20080627_043551_000002612069_00448_33067_1035.N1						IS2	H/H	69	0	448	4.07
ASA_IMM_1PNPDE20080627_044051_000000812069_00448_33067_1103.N1						IS2	H/H	69	0	448	4.07
ASA_IMM_1PNPDE20080627_051610_000002632069_00449_33068_1183.N1						IS2	V/V	69	0	449	4.07
ASA_IMM_1PNPDK20080627_053854_000000372069_00449_33068_7653.N1						IS2	V/V	69	0	449	4.07
ASA_IMM_1PNPDE20080627_054554_000000972069_00449_33068_1101.N1						IS2	V/V	69	0	449	4.07
ASA_IMM_1PNPDE20080627_061708_000000632069_00449_33068_1105.N1						IS2	H/H	69	0	449	4.07
ASA_IMM_1PNPDE20080627_061708_000001402069_00449_33068_1185.N1						IS2	H/H	69	0	449	4.07
ASA_IMM_1PNPDE20080627_061910_000000192069_00449_33068_1109.N1						IS2	***	69	0	449	4.07
ASA_IMM_1PNPDK20080627_070448_000001532069_00450_33069_7716.N1						IS2	V/V	69	0	450	4.07
ASA_IMM_1PNPDE20080627_073850_000000662069_00450_33069_1216.N1						IS7	V/V	69	0	450	4.07
ASA_IMM_1PNPDK20080627_083334_000000992069_00451_33070_7844.N1						IS6	V/V	69	0	451	4.07
ASA_IMM_1PNPDK20080627_084309_000000812069_00451_33070_7882.N1						IS2	V/V	69	0	451	4.07
ASA_IMM_1PNPDE20080627_093811_000005002069_00451_33070_1406.N1						IS2	H/H	69	0	451	4.07
ASA_IMM_1PNPDE20080627_105509_000001002069_00452_33071_1370.N1						IS3	H/H	69	0	452	4.07
ASA_IMM_1PNPDE20080627_111804_000002622069_00452_33071_1382.N1						IS2	H/H	69	0	452	4.07
ASA_IMM_1PNPDE20080627_112504_000002832069_00452_33071_1432.N1						IS2	H/H	69	0	452	4.07
ASA_IMM_1PNPDE20080627_113756_000000832069_00452_33071_1430.N1						IS2	V/V	69	0	452	4.07
ASA_IMM_1PNPDE20080627_113900_000000192069_00452_33071_1418.N1						IS2	***	69	0	452	4.07
ASA_IMM_1PNPDK20080627_122132_000000592069_00453_33072_8137.N1						IS2	V/V	69	0	453	4.07
ASA_IMM_1PNPDK20080627_125854_000005622069_00453_33072_8315.N1						IS2	H/H	69	0	453	4.07
ASA_IMM_1PNPDK20080627_134100_000000622069_00454_33073_8278.N1						IS1	V/V	69	0	454	4.07
ASA_IMM_1PNPDE20080627_142254_000000772069_00454_33073_1478.N1						IS4	V/V	69	0	454	4.07
ASA_IMM_1PNPDE20080627_144052_000002622069_00454_33073_1488.N1						IS2	H/H	69	0	454	4.07
ASA_IMM_1PNPDE20080627_151927_000000372069_00455_33074_1456.N1						IS7	H/H	69	0	455	4.07
ASA_IMM_1PNPDE20080627_162726_000001422069_00455_33074_1450.N1						IS2	H/H	69	0	455	4.07
ASA_IMM_1PNPDE20080627_162929_000000192069_00455_33074_1448.N1						IS2	***	69	0	455	4.07
ASA_IMM_1PNPDE20080627_170025_000001092069_00456_33075_1490.N1						IS6	V/V	69	0	456	4.07
ASA_IMM_1PNPDE20080627_172057_000000392069_00456_33075_1498.N1						IS4	V/V	69	0	456	4.07
ASA_IMM_1PNPDE20080627_173303_000000372069_00456_33075_1500.N1						IS2	V/V	69	0	456	4.07
ASA_IMM_1PNPDE20080627_181049_000002232069_00456_33075_1518.N1						IS2	H/H	69	0	456	4.07
ASA_IMM_1PNPDE20080627_185813_000001142069_00457_33076_1526.N1						IS2	H/H	69	0	457	4.07
ASA_IMM_1PNPDE20080627_194242_000002622069_00457_33076_1554.N1						IS2	H/H	69	0	457	4.07
ASA_IMM_1PNPDK20080627_202714_000000372069_00458_33077_8698.N1						IS2	V/V	69	0	458	4.07
ASA_IMM_1PNPDE20080627_204417_000001662069_00458_33077_1672.N1						IS2	V/V	69	0	458	4.07
ASA_IMM_1PNPDE20080627_212239_000002612069_00458_33077_1708.N1						IS2	H/H	69	0	458	4.07
ASA_IMM_1PNPDE20080627_212739_000004062069_00458_33077_1687.N1						IS2	H/H	69	0	458	4.07
ASA_IMM_1PNPDK20080627_221136_000000742069_00459_33078_8810.N1						IS2	H/H	69	0	459	4.07
ASA_IMM_1PNPDE20080627_222904_000000672069_00459_33078_1828.N1						IS2	V/V	69	0	459	4.07
ASA_IMM_1PNPDE20080627_222904_000000672069_00459_33078_2267.N1						IS2	V/V	69	0	459	4.07
ASA_IMM_1PNPDE20080627_230222_000002012069_00459_33078_1849.N1						IS2	H/H	69	0	459	4.07
ASA_IMM_1PNPDE20080627_230622_000004832069_00459_33078_1851.N1						IS2	H/H	69	0	459	4.07
ASA_IMM_1PNPDE20080627_233754_000000862069_00460_33079_1869.N1						IS2	V/V	69	0	460	4.07
ASA_IMM_1PNPDE20080627_233754_000000862069_00460_33079_2336.N1						IS2	V/V	69	0	460	4.07
ASA_IMM_1PNPDK20080627_235406_000001172069_00460_33079_8830.N1						IS2	H/H	69	0	460	4.07
ASA_IMM_1PNPDK20080627_235509_000000542069_00460_33079_8828.N1						IS2	H/H	69	0	460	4.07


Filename	Pol	Timestamp	count(Module)
ASA_MS__0PNPDK20080627_143812_000000162069_00454_33073_0575.N1	H	2008-06-27 14:38:12	320







Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WSM_1PNPDE20080627_002219_000001212069_00446_33065_0748.N1						SS1	H/H	69	0	446	4.07
ASA_WSM_1PNPDE20080627_020303_000001702069_00447_33066_0895.N1						SS1	H/H	69	0	447	4.07
ASA_WSM_1PNPDE20080627_021415_000000732069_00447_33066_0852.N1						SS1	V/V	69	0	447	4.07
ASA_WSM_1PNPDE20080627_023351_000001892069_00447_33066_0870.N1						SS1	V/V	69	0	447	4.07
ASA_WSM_1PNPDE20080627_033201_000001522069_00448_33067_1045.N1						SS1	V/V	69	0	448	4.07
ASA_WSM_1PNPDE20080627_033638_000001462069_00448_33067_1043.N1						SS1	H/H	69	0	448	4.07
ASA_WSM_1PNPDE20080627_053945_000000732069_00449_33068_1047.N1						SS1	H/H	69	0	449	4.07
ASA_WSM_1PNPDE20080627_053945_000002132069_00449_33068_1190.N1						SS1	H/H	69	0	449	4.07
ASA_WSM_1PNPDE20080627_054159_000000792069_00449_33068_1181.N1						SS1	H/H	69	0	449	4.07
ASA_WSM_1PNPDE20080627_072417_000000982069_00450_33069_1208.N1						SS1	H/H	69	0	450	4.07
ASA_WSM_1PNPDE20080627_074217_000005252069_00450_33069_1242.N1						SS1	V/V	69	0	450	4.07
ASA_WSM_1PNPDE20080627_091345_000001352069_00451_33070_1340.N1						SS1	V/V	69	0	451	4.07
ASA_WSM_1PNPDE20080627_091345_000002812069_00451_33070_1350.N1						SS1	V/V	69	0	451	4.07
ASA_WSM_1PNPDE20080627_091655_000000902069_00451_33070_1341.N1						SS1	V/V	69	0	451	4.07
ASA_WSM_1PNPDE20080627_104832_000000732069_00452_33071_1348.N1						SS1	V/V	69	0	452	4.07
ASA_WSM_1PNPDE20080627_120948_000000732069_00453_33072_1402.N1						SS1	V/V	69	0	453	4.07
ASA_WSM_1PNPDE20080627_151242_000000912069_00455_33074_1492.N1						SS1	V/V	69	0	455	4.07
ASA_WSM_1PNPDE20080627_153933_000000972069_00455_33074_1494.N1						SS1	H/H	69	0	455	4.07
ASA_WSM_1PNPDE20080627_171850_000000912069_00456_33075_1496.N1						SS1	H/H	69	0	456	4.07
ASA_WSM_1PNPDE20080627_172154_000002142069_00456_33075_1520.N1						SS1	H/H	69	0	456	4.07
ASA_WSM_1PNPDE20080627_190108_000002992069_00457_33076_1558.N1						SS1	H/H	69	0	457	4.07
ASA_WSM_1PNPDE20080627_200552_000001902069_00457_33076_1556.N1						SS1	H/H	69	0	457	4.07
ASA_WSM_1PNPDE20080627_203735_000001042069_00458_33077_1706.N1						SS1	H/H	69	0	458	4.07


Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WVS_1PNPDE20080626_235409_000016492069_00445_33064_0654.N1						IS2	V/V	69	0	445	4.07
ASA_WVS_1PNPDE20080627_004000_000003002069_00446_33065_0651.N1						IS2	V/V	69	0	446	4.07
ASA_WVS_1PNPDE20080627_004701_000007202069_00446_33065_0661.N1						IS2	V/V	69	0	446	4.07
ASA_WVS_1PNPDE20080627_010618_000003002069_00446_33065_0666.N1						IS2	V/V	69	0	446	4.07
ASA_WVS_1PNPDE20080627_013100_000001342069_00446_33065_0674.N1						IS2	V/V	69	0	446	4.07
ASA_WVS_1PNPDE20080627_013215_000003752069_00446_33065_0798.N1						IS2	V/V	69	0	446	4.07
ASA_WVS_1PNPDE20080627_013100_000001342069_00446_33065_0674.N1						IS1	V/V	69	0	446	4.07
ASA_WVS_1PNPDE20080627_014812_000006142069_00447_33066_0826.N1						IS2	V/V	69	0	447	4.07
ASA_WVS_1PNPDE20080627_023704_000008392069_00447_33066_1278.N1						IS2	V/V	69	0	447	4.07
ASA_WVS_1PNPDE20080627_025019_000000902069_00447_33066_0902.N1						IS2	V/V	69	0	447	4.07
ASA_WVS_1PNPDE20080627_031136_000001052069_00447_33066_0909.N1						IS2	V/V	69	0	447	4.07
ASA_WVS_1PNPDE20080627_033013_000000592069_00448_33067_0916.N1						IS2	V/V	69	0	448	4.07
ASA_WVS_1PNPDE20080627_041237_000008692069_00448_33067_0930.N1						IS2	V/V	69	0	448	4.07
ASA_WVS_1PNPDE20080627_042637_000002102069_00448_33067_1058.N1						IS2	V/V	69	0	448	4.07
ASA_WVS_1PNPDE20080627_045212_000012442069_00448_33067_1093.N1						IS2	V/V	69	0	448	4.07
ASA_WVS_1PNPDE20080627_055222_000009892069_00449_33068_1088.N1						IS2	V/V	69	0	449	4.07
ASA_WVS_1PNPDK20080627_060836_000002702069_00449_33068_7666.N1						IS2	V/V	69	0	449	4.07
ASA_WVS_1PNPDK20080627_063248_000018892069_00449_33068_7684.N1						IS2	V/V	69	0	449	4.07
ASA_WVS_1PNPDK20080627_075102_000001502069_00450_33069_7780.N1						IS2	V/V	69	0	450	4.07
ASA_WVS_1PNPDK20080627_081324_000011692069_00450_33069_7790.N1						IS2	V/V	69	0	450	4.07
ASA_WVS_1PNPDK20080627_083520_000004342069_00451_33070_7787.N1						IS2	V/V	69	0	451	4.07
ASA_WVS_1PNPDK20080627_084437_000001052069_00451_33070_7851.N1						IS2	V/V	69	0	451	4.07
ASA_WVS_1PNPDK20080627_091829_000009442069_00451_33070_7905.N1						IS2	V/V	69	0	451	4.07
ASA_WVS_1PNPDK20080627_095400_000019042069_00451_33070_7962.N1						IS2	V/V	69	0	451	4.07
ASA_WVS_1PNPDK20080627_104305_000000452069_00452_33071_8042.N1						IS2	V/V	69	0	452	4.07
ASA_WVS_1PNPDK20080627_105657_000010642069_00452_33071_8054.N1						IS2	V/V	69	0	452	4.07
ASA_WVS_1PNPDK20080627_113436_000001652069_00452_33071_8049.N1						IS2	V/V	69	0	452	4.07
ASA_WVS_1PNPDK20080627_113925_000015592069_00452_33071_8127.N1						IS2	V/V	69	0	452	4.07
ASA_WVS_1PNPDK20080627_122236_000010642069_00453_33072_8173.N1						IS2	V/V	69	0	453	4.07
ASA_WVS_1PNPDK20080627_125043_000002852069_00453_33072_8183.N1						IS2	V/V	69	0	453	4.07
ASA_WVS_1PNPDK20080627_131512_000002102069_00453_33072_8180.N1						IS2	V/V	69	0	453	4.07
ASA_WVS_1PNPDK20080627_132721_000007762069_00453_33072_8251.N1						IS2	V/V	69	0	453	4.07
ASA_WVS_1PNPDK20080627_140702_000006292069_00454_33073_8322.N1						IS2	V/V	69	0	454	4.07
ASA_WVS_1PNPDK20080627_142615_000005852069_00454_33073_8331.N1						IS2	V/V	69	0	454	4.07
ASA_WVS_1PNPDK20080627_145547_000002852069_00454_33073_8336.N1						IS2	V/V	69	0	454	4.07
ASA_WVS_1PNPDK20080627_150426_000004492069_00454_33073_8352.N1						IS2	V/V	69	0	454	4.07
ASA_WVS_1PNPDK20080627_155341_000000742069_00455_33074_8450.N1						IS2	V/V	69	0	455	4.07
ASA_WVS_1PNPDK20080627_155756_000011242069_00455_33074_8457.N1						IS2	V/V	69	0	455	4.07
ASA_WVS_1PNPDK20080627_163623_000010192069_00455_33074_8466.N1						IS2	V/V	69	0	455	4.07
ASA_WVS_1PNPDK20080627_173421_000013642069_00456_33075_8574.N1						IS2	V/V	69	0	456	4.07
ASA_WVS_1PNPDK20080627_181948_000009742069_00456_33075_8579.N1						IS2	V/V	69	0	456	4.07
ASA_WVS_1PNPDK20080627_190807_000017842069_00457_33076_8696.N1						IS2	V/V	69	0	457	4.07
ASA_WVS_1PNPDK20080627_200039_000002702069_00457_33076_8710.N1						IS2	V/V	69	0	457	4.07
ASA_WVS_1PNPDE20080627_204713_000018742069_00458_33077_1574.N1						IS2	V/V	69	0	458	4.07
ASA_WVS_1PNPDE20080627_213811_000002242069_00458_33077_1690.N1						IS2	V/V	69	0	458	4.07
ASA_WVS_1PNPDE20080627_214056_000007792069_00458_33077_1713.N1						IS2	V/V	69	0	458	4.07
ASA_WVS_1PNPDE20080627_214056_000007792069_00458_33077_2195.N1						IS2	V/V	69	0	458	4.07
ASA_WVS_1PNPDE20080627_213811_000002242069_00458_33077_1690.N1						IS1	V/V	69	0	458	4.07
ASA_WVS_1PNPDE20080627_220908_000001052069_00459_33078_1716.N1						IS2	V/V	69	0	459	4.07
ASA_WVS_1PNPDE20080627_220908_000001052069_00459_33078_2097.N1						IS2	V/V	69	0	459	4.07
ASA_WVS_1PNPDE20080627_222636_000001052069_00459_33078_1721.N1						IS2	V/V	69	0	459	4.07
ASA_WVS_1PNPDE20080627_222636_000001052069_00459_33078_2094.N1						IS2	V/V	69	0	459	4.07
ASA_WVS_1PNPDE20080627_223017_000017242069_00459_33078_1728.N1						IS2	V/V	69	0	459	4.07
ASA_WVS_1PNPDE20080627_223017_000017242069_00459_33078_2111.N1						IS2	V/V	69	0	459	4.07
ASA_WVS_1PNPDE20080627_231847_000002092069_00459_33078_1731.N1						IS2	V/V	69	0	459	4.07
ASA_WVS_1PNPDE20080627_231847_000002092069_00459_33078_2106.N1						IS2	V/V	69	0	459	4.07
ASA_WVS_1PNPDE20080627_231847_000002092069_00459_33078_1731.N1						IS1	V/V	69	0	459	4.07
ASA_WVS_1PNPDE20080627_231847_000002092069_00459_33078_2106.N1						IS1	V/V	69	0	459	4.07







































































27-Jun




27-Jun




27-Jun







27-Jun




27-Jun




27-Jun







27-Jun




27-Jun




27-Jun



27-Jun



27-Jun



27-Jun

