



# ASAR Daily Report



Analysis from 27-DEC-2008 00:00:00 to 27-DEC-2008 23:59:59. Page generated on 28-DEC-2008 07:42:04.  
View log file: ASAR\_Daily\_Report\_20081228\_0730.log. For any anomalies please contact [mtranfaglia@serco.it](mailto:mtranfaglia@serco.it), [gscarpino@serco.it](mailto:gscarpino@serco.it), [Emma.Griffiths@vega.co.uk](mailto:Emma.Griffiths@vega.co.uk).

This report is automatically generated every day, every 2 hours. No comments are provided on the results.

## SUMMARY

1. DATA SUMMARY
  - 1.1 Summary tables
  - 1.2 Lists of products used
2. AUXILIARY FILES ANALYSIS
  - 2.1 IECF operational ADFs list
  - 2.2 Products with wrong ADFs
3. MODULE STEPPING PRODUCTS ANALYSIS
  - 3.1 V/V polarisation
  - 3.2 H/H polarisation
4. CALIBRATION PULSES ANALYSIS
  - 4.1 Analysis for WVS IS2 V/V
    - 4.1.1 Temporal Evolution Analysis for WVS IS2 V/V
    - 4.1.2 All Rows Analysis for WVS IS2 V/V
  - 4.2 Analysis for GM1 SS3 H/H
    - 4.2.1 Temporal Evolution Analysis for GM1 SS3 H/H
    - 4.2.2 All Rows Analysis for GM1 SS3 H/H
5. DOPPLER ANALYSIS
  - 5.1 Analysis for WVS IS2 V/V
    - 5.1.1 Doppler MAP Analysis for WVS IS2 V/V
    - 5.1.2 Doppler ANX Analysis for WVS IS2 V/V
  - 5.2 Analysis for GM1 SS1 H/H
    - 5.2.1 Doppler MAP Analysis for GM1 SS1 H/H
    - 5.2.2 Doppler ANX Analysis for GM1 SS1 H/H
  - 5.3 Doppler JUMPS Analysis for WSM
6. CHIRP ANALYSIS
  - 6.1 Analysis for WSM SS1 H/H
    - 6.1.1 ScaleFactor
  - 6.2 Analysis for WSM SS1 V/V
    - 6.2.1 ScaleFactor
7. RAW DATA ANALYSIS
  - 7.1 Analysis for WVS
  - 7.2 Analysis for IMM
8. TELEMETRY ANALYSIS
  - 8.1 Number of Missing Lines
  - 8.2 Number of Gaps

---

## 1 - DATA SUMMARY

### 1.1 - Summary tables

[ [BACK TO MENU](#) ]

WVS				GM1				APM				IMM				WSM				MS			
Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Time	Pol	Modules
PDE	IS1	V/V	4	PDE	WS	H/H	39	PDE	IS2	H/H	1	PDE	IS2	H/H	1	PDE	WS	H/H	53	PDK	2008-12-27 08:44:37	H	320
PDE	IS2	V/V	29	PDK	WS	H/H	42	PDK	IS7	V/H	1	PDE	IS2	V/V	17	PDE	WS	V/V	4				
PDK	IS2	V/V	25									PDE	IS3	H/H	1								
												PDE	IS4	H/H	1								
												PDE	IS6	H/H	1								
												PDE	IS6	V/V	1								
												PDK	IS2	H/H	1								
												PDK	IS2	V/V	1								
												PDK	IS6	V/V	1								

## 1.2 - Lists of products used

[ [BACK TO MENU](#) ]

[[TXT](#)] [[XLS](#)] [List\\_WVS\\_products\\_used](#)  
 [[TXT](#)] [[XLS](#)] [List\\_GM1\\_products\\_used](#)  
 [[TXT](#)] [[XLS](#)] [List\\_APM\\_products\\_used](#)  
 [[TXT](#)] [[XLS](#)] [List\\_IMM\\_products\\_used](#)  
 [[TXT](#)] [[XLS](#)] [List\\_WSM\\_products\\_used](#)  
 [[TXT](#)] [[XLS](#)] [List\\_MS\\_products\\_used](#)

## 2 - AUXILIARY FILES ANALYSIS

### 2.1 - IECF operational ADFs list

[ [BACK TO MENU](#) ]

ADFs disseminated for ASAR
ASA_CON_AXVIEC20081215_141339_20070204_165113_20091231_000000
ASA_INS_AXVIEC20081215_140905_20070307_060000_20091231_000000
ASA_XCH_AXVIEC20081215_143642_20020301_000000_20091231_000000
ASA_XCA_AXVIEC20081215_141741_20070204_165113_20091231_000000

### 2.2 - Products with wrong ADFs

[ [BACK TO MENU](#) ]

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
WVS	0	0	0	0
GM1	0	0	0	0
APM	0	0	0	0
IMM	0	0	0	0
WSM	0	0	0	0

[[TXT](#)] [[XLS](#)] [Check\\_ADFs\\_WVS](#)  
 [[TXT](#)] [[XLS](#)] [Check\\_ADFs\\_GM1](#)  
 [[TXT](#)] [[XLS](#)] [Check\\_ADFs\\_APM](#)  
 [[TXT](#)] [[XLS](#)] [Check\\_ADFs\\_IMM](#)  
 [[TXT](#)] [[XLS](#)] [Check\\_ADFs\\_WSM](#)

### 3 - MODULE STEPPING PRODUCTS ANALYSIS






### 3.2 - H/H polarisation


[ BACK TO MENU ]

SECOND FIXED REFERENCE	PREVIOUS PRODUCT REFERENCE
After antenna maintenance (2005-09-22/23)	Previous product in the same polarisation

Reference: 2005-09-22 06:26:51 H RxGain  
 Test : 2008-12-27 08:44:37 H






Reference: 2008-12-25 06:26:40 H RxGain  
 Test : 2008-12-27 08:44:37 H






Reference: 2005-09-22 06:26:51 H RxPhase  
 Test : 2008-12-27 08:44:37 H



Reference: 2008-12-25 06:26:40 H RxPhase  
 Test : 2008-12-27 08:44:37 H





## 4 - CALIBRATION PULSES ANALYSIS

### 4.1 - Analysis for WVS IS2 V/V


#### 4.1.1 - Temporal Evolution Analysis for WVS IS2 V/V

[ BACK TO MENU ]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Calibration pulses for WVS IS2 V/V




Transmit power (P1 - P1a) for WVS IS2 V/V



#### 4.1.2 - All Rows Analysis for WVS IS2 V/V

[ BACK TO MENU ]





## 4.2 - Analysis for GM1 SS3 H/H

### 4.2.1 - Temporal Evolution Analysis for GM1 SS3 H/H


[ BACK TO MENU ]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]



Calibration pulses for GM1 SS3 H/H




Transmit power (P1 - P1a) for GM1 SS3 H/H



4.2.2 - All Rows Analysis for GM1 SS3 H/H

[ BACK TO MENU ]






## 5 - DOPPLER ANALYSIS

### 5.1 - Analysis for WVS IS2 V/V

#### 5.1.1 - Doppler MAP Analysis for WVS IS2 V/V

[ [BACK TO MENU](#) ]






### 5.1.2 - Doppler ANX Analysis for WVS IS2 V/V

[ [BACK TO MENU](#) ]







## 5.2 - Analysis for GM1 SS1 H/H

### 5.2.1 - Doppler MAP Analysis for GM1 SS1 H/H

[ [BACK TO MENU](#) ]






### 5.2.2 - Doppler ANX Analysis for GM1 SS1 H/H


[ [BACK TO MENU](#) ]






### 5.3 - Doppler JUMPS Analysis for WSM

[ [BACK TO MENU](#) ]







## 6 - CHIRP ANALYSIS

### 6.1 - Analysis for WSM SS1 H/H

#### 6.1.1 - ScaleFactor

[ [BACK TO MENU](#) ]







## 6.2 - Analysis for WSM SS1 V/V

### 6.2.1 - ScaleFactor

[ [BACK TO MENU](#) ]






## 7 - RAW DATA ANALYSIS

### 7.1 - Analysis for WVS

[ [BACK TO MENU](#) ]

--	--	--






Channel	Statistics	DSS-B
MEAN I	mean	0.000517802
	stdev	1.90058e-07
MEAN Q	mean	0.000512938
	stdev	2.28081e-07
Channel	Statistics	DSS-B
STDEV I	mean	0.135738
	stdev	0.00113563
STDEV Q	mean	0.136134
	stdev	0.00115371

## 7.2 - Analysis for IMM

[ [BACK TO MENU](#) ]

--	--	--





## 8 - TELEMETRY ANALYSIS

Processing Center	Product	Gaps	Missing lines
PDE	ASA_WSM_1PNPDE20081227_045322_000001892075_00062_35687_2645.N1	0	1
PDE	ASA_WSM_1PNPDE20081227_045322_000003732075_00062_35687_2808.N1	0	1
PDE	ASA_WSM_1PNPDE20081227_160546_000001902075_00069_35694_3385.N1	0	35

### 8.1 - Number of Missing lines


[ BACK TO MENU ]





## 8.2 - Number of Gaps

[ [BACK TO MENU](#) ]



#####  
ASAR DAILY REPORT for 081227  
#####

MODE: DAILY  
ANALYSIS: ALL  
DATE: YESTERDAY

Analysis will be performed from 2008-12-27 00:00:00 to 2008-12-27 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/081227/

DATA SUMMARY

#####  
Summary will be performed from 2008-12-27 00:00:00 to 2008-12-27 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/081227/DATA\_SUMMARY

Creating directory ./RESULTS/DAILY/081227/DATA\_SUMMARY...  
Writing file ./RESULTS/DAILY/081227/DATA\_SUMMARY/Data\_summary.html...

\*\*\*\*\*  
Getting WVS products list from 2008-12-27 00:00:00 to 2008-12-27 23:59:59...  
Writing file ./RESULTS/DAILY/081227/DATA\_SUMMARY/List\_WVS\_products\_used.xls...  
Writing file ./RESULTS/DAILY/081227/DATA\_SUMMARY/List\_WVS\_products\_used.txt...

\*\*\*\*\*  
Getting GM1 products list from 2008-12-27 00:00:00 to 2008-12-27 23:59:59...  
Writing file ./RESULTS/DAILY/081227/DATA\_SUMMARY/List\_GM1\_products\_used.xls...  
Writing file ./RESULTS/DAILY/081227/DATA\_SUMMARY/List\_GM1\_products\_used.txt...

\*\*\*\*\*  
Getting APM products list from 2008-12-27 00:00:00 to 2008-12-27 23:59:59...  
Writing file ./RESULTS/DAILY/081227/DATA\_SUMMARY/List\_APM\_products\_used.xls...  
Writing file ./RESULTS/DAILY/081227/DATA\_SUMMARY/List\_APM\_products\_used.txt...

\*\*\*\*\*  
Getting IMM products list from 2008-12-27 00:00:00 to 2008-12-27 23:59:59...  
Writing file ./RESULTS/DAILY/081227/DATA\_SUMMARY/List\_IMM\_products\_used.xls...  
Writing file ./RESULTS/DAILY/081227/DATA\_SUMMARY/List\_IMM\_products\_used.txt...

\*\*\*\*\*  
Getting WSM products list from 2008-12-27 00:00:00 to 2008-12-27 23:59:59...  
Writing file ./RESULTS/DAILY/081227/DATA\_SUMMARY/List\_WSM\_products\_used.xls...  
Writing file ./RESULTS/DAILY/081227/DATA\_SUMMARY/List\_WSM\_products\_used.txt...

\*\*\*\*\*  
Getting MS products list from 2008-12-27 00:00:00 to 2008-12-27 23:59:59...  
Writing file ./RESULTS/DAILY/081227/DATA\_SUMMARY/List\_MS\_products\_used.xls...  
Writing file ./RESULTS/DAILY/081227/DATA\_SUMMARY/List\_MS\_products\_used.txt...

DATA SUMMARY completed  
#####

AUXILIARY FILES ANALYSIS

#####  
Analysis will be performed from 2008-12-27 00:00:00 to 2008-12-27 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/081227/AUXILIARY

Creating directory ./RESULTS/DAILY/081227/AUXILIARY...

\*\*\*\*\*  
Looking for the IECF operational ADFs list...



Found list 20081227\_030002\_current\_3\_IECF\_ADFs.txt...  
Extracting ADFs...

ASA\_CON\_AXVIEC20081215\_141339\_20070204\_165113\_20091231\_000000  
ASA\_INS\_AXVIEC20081215\_140905\_20070307\_060000\_20091231\_000000  
ASA\_XCH\_AXVIEC20081215\_143642\_20020301\_000000\_20091231\_000000  
ASA\_XCA\_AXVIEC20081215\_141741\_20070204\_165113\_20091231\_000000

Writing file ./RESULTS/DAILY/081227/AUXILIARY/ASAR\_ADFs\_IECF\_List3.html...  
Writing file ./RESULTS/DAILY/081227/AUXILIARY/Auxiliary\_files\_summary.html...

\*\*\*\*\*  
Analysing WVS products...

Writing file ./RESULTS/DAILY/081227/AUXILIARY/Check\_ADFs\_WVS.xls...  
Writing file ./RESULTS/DAILY/081227/AUXILIARY/Check\_ADFs\_WVS.txt...

ASA_WVS_1PNPDE20081227_001435_000003752075_00059_35684_2092.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20081227_003744_000004342075_00059_35684_2095.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20081227_004359_000003892075_00059_35684_2211.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20081227_005402_000009592075_00059_35684_2221.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20081227_013534_000001642075_00060_35685_2218.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20081227_013921_000006592075_00060_35685_2224.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20081227_015328_000004802075_00060_35685_2233.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20081227_021820_000006062075_00060_35685_2236.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20081227_021835_000003302075_00060_35685_2374.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20081227_023839_000004192075_00061_35686_2379.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20081227_032358_000006892075_00061_35686_2387.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20081227_033513_000002552075_00061_35686_2491.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20081227_040301_000006892075_00061_35686_2498.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20081227_041617_000001792075_00062_35687_2511.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20081227_050228_000009142075_00062_35687_2545.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20081227_051728_000003152075_00062_35687_2690.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20081227_053932_000015742075_00062_35687_2742.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20081227_064717_000001192075_00063_35688_2729.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20081227_065149_000003452075_00063_35688_2732.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20081227_195512_000017992075_00071_35696_3434.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20081227_204455_000000142075_00071_35696_3442.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20081227_204455_000002402075_00071_35696_3509.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20081227_213543_000019792075_00072_35697_3516.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20081227_222522_000004042075_00072_35697_3526.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20081227_223107_000007042075_00072_35697_3645.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20081227_225028_000004942075_00073_35698_3650.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20081227_231607_000013042075_00073_35698_3666.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20081227_234407_000003152075_00073_35698_3663.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20081227_065719_000003602075_00063_35688_6495.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20081227_072008_000019642075_00063_35688_6507.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20081227_083501_000005402075_00064_35689_6585.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20081227_090044_000000452075_00064_35689_6582.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20081227_090416_000018142075_00064_35689_6599.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20081227_100712_000010342075_00065_35690_6714.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20081227_104120_000018442075_00065_35690_6728.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20081227_113036_000001052075_00066_35691_6827.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20081227_113530_000017692075_00066_35691_6832.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20081227_122434_000001952075_00066_35691_6837.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20081227_123336_000010002075_00066_35691_6847.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20081227_131236_000008692075_00067_35692_6980.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20081227_140231_000004202075_00067_35692_6985.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20081227_141454_000001942075_00067_35692_6988.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20081227_141953_000002242075_00068_35693_6998.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20081227_145902_000005842075_00068_35693_7089.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20081227_151141_000007342075_00068_35693_7096.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20081227_154307_000009742075_00068_35693_7101.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20081227_160230_000001492075_00069_35694_7104.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20081227_164555_000012592075_00069_35694_7157.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20081227_172343_000013792075_00069_35694_7169.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK



ASA_WVS_1PNPDK20081227_182122_000013042075_00070_35695_7240.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20081227_190419_000000602075_00070_35695_7208.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20081227_190737_000003452075_00070_35695_7235.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20081227_191743_000001642075_00070_35695_7220.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

\*\*\*\*\*

Analysing GM1 products...

Writing file ./RESULTS/DAILY/081227/AUXILIARY/Check\_ADFs\_GM1.xls...

Writing file ./RESULTS/DAILY/081227/AUXILIARY/Check\_ADFs\_GM1.txt...

ASA_GM1_1PNPDE20081227_000737_000004162075_00059_35684_2089.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081227_002639_000006642075_00059_35684_2102.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081227_005108_000001692075_00059_35684_2215.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081227_011838_000001812075_00060_35685_2213.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081227_012315_000007372075_00060_35685_2226.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081227_015102_000001442075_00060_35685_2230.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081227_020215_000001502075_00060_35685_2228.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081227_021026_000004712075_00060_35685_2238.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081227_022442_000008332075_00060_35685_2376.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081227_024840_000001572075_00061_35686_2371.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081227_025302_000001872075_00061_35686_2369.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081227_025718_000002172075_00061_35686_2367.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081227_030231_000006342075_00061_35686_2389.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081227_034251_000007492075_00061_35686_2488.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081227_040017_000001632075_00061_35686_2495.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081227_041956_000001022075_00062_35687_2493.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081227_042237_000012812075_00062_35687_2592.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081227_044719_000003562075_00062_35687_2508.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081227_045943_000001632075_00062_35687_2542.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081227_052327_000003022075_00062_35687_2687.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081227_053010_000002472075_00062_35687_2692.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081227_053708_000001442075_00062_35687_2694.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081227_060629_000010202075_00063_35688_2789.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081227_063156_000000962075_00063_35688_2700.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081227_063508_000004222075_00063_35688_2726.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081227_064316_000002412075_00063_35688_2739.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081227_193605_000002832075_00071_35696_3427.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081227_195127_000002232075_00071_35696_3429.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081227_202851_000004532075_00071_35696_3431.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081227_204101_000002292075_00071_35696_3444.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081227_205419_000010812075_00071_35696_3595.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081227_211502_000000722075_00072_35697_3504.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081227_212717_000002472075_00072_35697_3506.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081227_221209_000001992075_00072_35697_3523.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081227_224335_000004102075_00073_35698_3647.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081227_230708_000004162075_00073_35698_3656.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081227_233835_000002232075_00073_35698_3654.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081227_234226_000000962075_00073_35698_3660.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081227_235813_000000842075_00073_35698_3658.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081227_070403_000001812075_00063_35688_6497.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081227_071716_000001692075_00063_35688_6499.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081227_075332_000007002075_00064_35689_6509.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081227_080403_000002292075_00064_35689_6575.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081227_082126_000001082075_00064_35689_6577.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081227_082444_000006162075_00064_35689_6579.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081227_084555_000008882075_00064_35689_6587.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081227_093517_000005732075_00065_35690_6601.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081227_095830_000000722075_00065_35690_6707.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081227_100030_000003982075_00065_35690_6709.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081227_102515_000003022075_00065_35690_6711.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081227_103948_000000902075_00065_35690_6716.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081227_111244_000001442075_00066_35691_6718.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081227_111947_000000962075_00066_35691_6720.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081227_121441_000004342075_00066_35691_6829.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081227_123210_000000842075_00066_35691_6834.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

ASA_GM1_1PNPDK20081227_125103_000009302075_00067_35692_6839.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081227_130527_000002292075_00067_35692_6971.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081227_132749_000006582075_00067_35692_6973.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081227_133851_000003682075_00067_35692_6975.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081227_134738_000008882075_00067_35692_6977.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081227_141017_000002772075_00067_35692_6982.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081227_142600_000001022075_00068_35693_6990.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081227_142839_000006162075_00068_35693_7000.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081227_144818_000001022075_00068_35693_7084.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081227_145321_000001322075_00068_35693_7086.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081227_145713_000001082075_00068_35693_7091.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081227_152703_000005732075_00068_35693_7093.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081227_153931_000002172075_00068_35693_7098.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081227_160918_000005192075_00069_35694_7106.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081227_161648_000000662075_00069_35694_7148.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081227_162814_000001382075_00069_35694_7150.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081227_163456_000005862075_00069_35694_7152.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081227_170739_000005732075_00069_35694_7154.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081227_172212_000000902075_00069_35694_7159.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081227_174911_000004412075_00070_35695_7166.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081227_175516_000001382075_00070_35695_7201.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081227_181113_000002172075_00070_35695_7203.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081227_181554_000001142075_00070_35695_7205.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081227_184815_000009302075_00070_35695_7215.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081227_192104_000001322075_00070_35695_7237.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081227_192557_000006822075_00071_35696_7217.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

\*\*\*\*\*

Analysing APM products...

Writing file ./RESULTS/DAILY/081227/AUXILIARY/Check\_ADFs\_APM.xls...

Writing file ./RESULTS/DAILY/081227/AUXILIARY/Check\_ADFs\_APM.txt...

ASA_APM_1PNPDE20081227_151041_000000432075_00068_35693_3357.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDK20081227_080754_000000432075_00064_35689_6552.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

\*\*\*\*\*

Analysing IMM products...

Writing file ./RESULTS/DAILY/081227/AUXILIARY/Check\_ADFs\_IMM.xls...

Writing file ./RESULTS/DAILY/081227/AUXILIARY/Check\_ADFs\_IMM.txt...

ASA_IMM_1PNPDE20081227_025611_000000562075_00061_35686_2355.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20081227_031301_000001232075_00061_35686_2463.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20081227_031301_000003692075_00061_35686_2612.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20081227_031604_000001872075_00061_35686_2464.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20081227_041502_000000682075_00061_35686_2589.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20081227_044400_000001892075_00062_35687_2486.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20081227_053415_000001622075_00062_35687_2681.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20081227_062707_000001222075_00063_35688_2685.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20081227_062707_000002782075_00063_35688_2791.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20081227_064212_000000532075_00063_35688_2663.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20081227_065007_000000282075_00063_35688_2683.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20081227_082312_000000822075_00064_35689_2921.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20081227_095942_000000372075_00065_35690_3084.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20081227_141840_000000672075_00067_35692_3355.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20081227_142743_000000452075_00068_35693_3353.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20081227_152438_000000942075_00068_35693_3371.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20081227_163033_000000542075_00069_35694_3388.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20081227_164443_000000632075_00069_35694_3396.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20081227_174722_000000982075_00070_35695_3419.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20081227_194923_000001142075_00071_35696_3482.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20081227_213121_000001152075_00072_35697_3611.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20081227_230416_000001622075_00073_35698_3777.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

```
ASA_IMM_1PNPDK20081227_095028_000000372075_00065_35690_6680.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20081227_130915_000000822075_00067_35692_6942.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20081227_144545_000001422075_00068_35693_7051.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```

\*\*\*\*\*

Analysing WSM products...

Writing file ./RESULTS/DAILY/081227/AUXILIARY/Check\_ADFs\_WSM.xls...

Writing file ./RESULTS/DAILY/081227/AUXILIARY/Check\_ADFs\_WSM.txt...

```
ASA_WSM_1PNPDE20081227_002248_000002252075_00059_35684_2203.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_011112_000001892075_00060_35685_2391.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_011112_000004342075_00060_35685_2655.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_011725_000000612075_00060_35685_2346.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_012141_000000912075_00060_35685_2353.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_020448_000001902075_00060_35685_2361.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_020448_000003362075_00060_35685_2638.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_020859_000000842075_00060_35685_2362.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_024725_000000732075_00061_35686_2351.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_025118_000000982075_00061_35686_2436.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_030057_000000732075_00061_35686_2365.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_031928_000002502075_00061_35686_2476.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_031928_000002692075_00061_35686_2610.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_035528_000002862075_00061_35686_2640.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_045322_000001892075_00062_35687_2645.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_045322_000003732075_00062_35687_2808.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_045732_000001232075_00062_35687_2646.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_052836_000000912075_00062_35687_2679.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_063334_000000912075_00063_35688_2787.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_070712_000002502075_00063_35688_2855.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_095447_000000922075_00065_35690_3142.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_095601_000000182075_00065_35690_3088.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_103023_000000732075_00065_35690_3144.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_103023_000002382075_00065_35690_3243.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_103238_000001032075_00065_35690_3196.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_103345_000003602075_00065_35690_3241.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_111513_000001902075_00066_35691_3245.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_111513_000002692075_00066_35691_3287.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_111924_000000182075_00066_35691_3229.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_120543_000003112075_00066_35691_3295.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_120656_000001762075_00066_35691_3248.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_134507_000001352075_00067_35692_3379.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_145005_000001902075_00068_35693_3381.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_153639_000001652075_00068_35693_3383.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_153752_000000922075_00068_35693_3369.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_160000_000001532075_00068_35693_3421.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_160546_000001902075_00069_35694_3385.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_163215_000001592075_00069_35694_3425.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_163430_000000242075_00069_35694_3417.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_171715_000002932075_00069_35694_3423.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_192323_000001522075_00071_35696_3498.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_194637_000001042075_00071_35696_3496.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_202558_000000732075_00071_35696_3457.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_203627_000002692075_00071_35696_3502.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_203740_000000612075_00071_35696_3471.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_203937_000000782075_00071_35696_3494.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_204943_000002752075_00071_35696_3500.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_212535_000000982075_00072_35697_3618.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_213349_000001152075_00072_35697_3616.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_221035_000000732075_00072_35697_3597.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_221535_000005502075_00072_35697_3652.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_231410_000001152075_00073_35698_3788.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_235111_000000732075_00073_35698_3751.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_235311_000000732075_00073_35698_3757.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_235311_000002992075_00073_35698_3882.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081227_235722_000000482075_00073_35698_3765.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```





ASA\_WSM\_1PNPDE20081227\_235939\_000002922075\_00073\_35698\_3790.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK

AUXILIARY FILES ANALYSIS completed

#####

MODULE STEPPING ANALYSIS

#####

Analysis will be performed from 2008-12-27 00:00:00 to 2008-12-27 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/081227/MODULE\_STEPPING

Creating directory ./RESULTS/DAILY/081227/MODULE\_STEPPING...
Creating directory ./RESULTS/DAILY/081227/MODULE\_STEPPING/FIRST\_REFERENCE...
Creating directory ./RESULTS/DAILY/081227/MODULE\_STEPPING/SECOND\_REFERENCE...
Creating directory ./RESULTS/DAILY/081227/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE...
Deleting old files...

\*\*\*\*\*

\*\*\*\*\*

Creating images comparing with second reference...

Exporting results to the directory ../../RESULTS/DAILY/081227/MODULE\_STEPPING/SECOND\_REFERENCE...

Polarization: H
Reference product: ASA\_MS\_0PNPDK20050922\_062651\_00000152041\_00034\_18625\_0041.N1
Test product: ASA\_MS\_0PNPDK20081227\_084437\_00000162075\_00064\_35689\_0711.N1

H
H
../../RESULTS/DAILY/081227/MODULE\_STEPPING/SECOND\_REFERENCE/TGH\_20081227\_084437-20050922\_062651.png
../../RESULTS/DAILY/081227/MODULE\_STEPPING/SECOND\_REFERENCE/TPH\_20081227\_084437-20050922\_062651.png
../../RESULTS/DAILY/081227/MODULE\_STEPPING/SECOND\_REFERENCE/RGH\_20081227\_084437-20050922\_062651.png
../../RESULTS/DAILY/081227/MODULE\_STEPPING/SECOND\_REFERENCE/RPH\_20081227\_084437-20050922\_062651.png

Polarization: V
Reference product: ASA\_MS\_0PNPDK20050923\_055514\_00000152041\_00048\_18639\_0042.N1
Test product: ASA\_MS\_0PNPDK20081226\_055503\_00000162075\_00048\_35673\_0710.N1

V
V
../../RESULTS/DAILY/081227/MODULE\_STEPPING/SECOND\_REFERENCE/TGV\_20081226\_055503-20050923\_055514.png
../../RESULTS/DAILY/081227/MODULE\_STEPPING/SECOND\_REFERENCE/TPV\_20081226\_055503-20050923\_055514.png
../../RESULTS/DAILY/081227/MODULE\_STEPPING/SECOND\_REFERENCE/RGV\_20081226\_055503-20050923\_055514.png
../../RESULTS/DAILY/081227/MODULE\_STEPPING/SECOND\_REFERENCE/RPV\_20081226\_055503-20050923\_055514.png

\*\*\*\*\*

\*\*\*\*\*

Creating images comparing with previous product reference...

Exporting results to the directory ../../RESULTS/DAILY/081227/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE...

Polarization: H
Reference product: ASA\_MS\_0PNPDK20081225\_062640\_00000162075\_00034\_35659\_0709.N1
Test product: ASA\_MS\_0PNPDK20081227\_084437\_00000162075\_00064\_35689\_0711.N1

H
H
../../RESULTS/DAILY/081227/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/TGH\_20081227\_084437-20081225\_062640.png
../../RESULTS/DAILY/081227/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/TPH\_20081227\_084437-20081225\_062640.png
../../RESULTS/DAILY/081227/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/RGH\_20081227\_084437-20081225\_062640.png
../../RESULTS/DAILY/081227/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/RPH\_20081227\_084437-20081225\_062640.png

Polarization: V
Reference product: ASA\_MS\_0PNPDK20081224\_170152\_00000162075\_00026\_35651\_0708.N1
Test product: ASA\_MS\_0PNPDK20081226\_055503\_00000162075\_00048\_35673\_0710.N1

V
V
../../RESULTS/DAILY/081227/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/TGV\_20081226\_055503-20081224\_170152.png

../../RESULTS/DAILY/081227/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/TPV\_20081226\_055503-20081224\_170152.png  
../../RESULTS/DAILY/081227/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/RGV\_20081226\_055503-20081224\_170152.png  
../../RESULTS/DAILY/081227/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/RPV\_20081226\_055503-20081224\_170152.png

MODULE\_STEPPING ANALYSIS completed

#####

CALIBRATION PULSES ANALYSIS

#####

Creating directory ./RESULTS/DAILY/081227/CALIBRATION\_PULSES...

\*\*\*\*\*  
\*\*\*\*\*

ALL ROWS Analysis will be performed from 2008-12-27 00:00:00 to 2008-12-27 23:59:59

Analysing products WVS IS2 V/V

Writing image ../../RESULTS/DAILY/081227//CALIBRATION\_PULSES/Calibration\_pulses\_all\_rows\_WVS\_IS2\_VV.png...

Analysing products GM1 SS3 H/H

Writing image ../../RESULTS/DAILY/081227//CALIBRATION\_PULSES/Calibration\_pulses\_all\_rows\_GM1\_SS3\_HH.png...

\*\*\*\*\*  
\*\*\*\*\*

TEMPORAL EVOLUTION Analysis will be performed from 2008-12-27 00:00:00 to 2008-12-27 23:59:59

Analysing products WVS IS2 V/V

Getting calibration pulses data for WVS IS2 V/V from 2008-12-27 00:00:00 to 2008-12-27 23:59:59. Rows: 1/5/9/13/17/21/25/29

Writing file ./RESULTS/DAILY/081227/CALIBRATION\_PULSES/Calibration\_pulses\_data\_WVS\_IS2\_VV\_2008-12-27\_1.dat...

Writing ../../RESULTS/DAILY/081227//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_WVS\_IS2\_VV\_1.png...

Writing ../../RESULTS/DAILY/081227//CALIBRATION\_PULSES/Transmit\_Power\_WVS\_IS2\_VV\_1.png...

Getting calibration pulses data for WVS IS2 V/V from 2008-12-27 00:00:00 to 2008-12-27 23:59:59. Rows: 2/6/10/14/18/22/26/30

Writing file ./RESULTS/DAILY/081227/CALIBRATION\_PULSES/Calibration\_pulses\_data\_WVS\_IS2\_VV\_2008-12-27\_2.dat...

Writing ../../RESULTS/DAILY/081227//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_WVS\_IS2\_VV\_2.png...

Writing ../../RESULTS/DAILY/081227//CALIBRATION\_PULSES/Transmit\_Power\_WVS\_IS2\_VV\_2.png...

Getting calibration pulses data for WVS IS2 V/V from 2008-12-27 00:00:00 to 2008-12-27 23:59:59. Rows: 3/7/11/15/19/23/27/31

Writing file ./RESULTS/DAILY/081227/CALIBRATION\_PULSES/Calibration\_pulses\_data\_WVS\_IS2\_VV\_2008-12-27\_3.dat...

Writing ../../RESULTS/DAILY/081227//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_WVS\_IS2\_VV\_3.png...

Writing ../../RESULTS/DAILY/081227//CALIBRATION\_PULSES/Transmit\_Power\_WVS\_IS2\_VV\_3.png...

Getting calibration pulses data for WVS IS2 V/V from 2008-12-27 00:00:00 to 2008-12-27 23:59:59. Rows: 4/8/12/16/20/24/28/32

Writing file ./RESULTS/DAILY/081227/CALIBRATION\_PULSES/Calibration\_pulses\_data\_WVS\_IS2\_VV\_2008-12-27\_4.dat...

Writing ../../RESULTS/DAILY/081227//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_WVS\_IS2\_VV\_4.png...

Writing ../../RESULTS/DAILY/081227//CALIBRATION\_PULSES/Transmit\_Power\_WVS\_IS2\_VV\_4.png...

Analysing products GM1 SS3 H/H

Getting calibration pulses data for GM1 SS3 H/H from 2008-12-27 00:00:00 to 2008-12-27 23:59:59. Rows: 1/5/9/13/17/21/25/29

Writing file ./RESULTS/DAILY/081227/CALIBRATION\_PULSES/Calibration\_pulses\_data\_GM1\_SS3\_HH\_2008-12-27\_1.dat...

Writing ../../RESULTS/DAILY/081227//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_GM1\_SS3\_HH\_1.png...

Writing ../../RESULTS/DAILY/081227//CALIBRATION\_PULSES/Transmit\_Power\_GM1\_SS3\_HH\_1.png...

Getting calibration pulses data for GM1 SS3 H/H from 2008-12-27 00:00:00 to 2008-12-27 23:59:59. Rows: 2/6/10/14/18/22/26/30

Writing file ./RESULTS/DAILY/081227/CALIBRATION\_PULSES/Calibration\_pulses\_data\_GM1\_SS3\_HH\_2008-12-27\_2.dat...

Writing ../../RESULTS/DAILY/081227//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_GM1\_SS3\_HH\_2.png...

Writing ../../RESULTS/DAILY/081227//CALIBRATION\_PULSES/Transmit\_Power\_GM1\_SS3\_HH\_2.png...

Getting calibration pulses data for GM1 SS3 H/H from 2008-12-27 00:00:00 to 2008-12-27 23:59:59. Rows: 3/7/11/15/19/23/27/31



Writing file ./RESULTS/DAILY/081227/CALIBRATION\_PULSES/Calibration\_pulses\_data\_GM1\_SS3\_HH\_2008-12-27\_3.dat...  
Writing ../../RESULTS/DAILY/081227//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_GM1\_SS3\_HH\_3.png...  
Writing ../../RESULTS/DAILY/081227//CALIBRATION\_PULSES/Transmit\_Power\_GM1\_SS3\_HH\_3.png...

Getting calibration pulses data for GM1 SS3 H/H from 2008-12-27 00:00:00 to 2008-12-27 23:59:59. Rows: 4/8/12/16/20/24/28/32  
Writing file ./RESULTS/DAILY/081227/CALIBRATION\_PULSES/Calibration\_pulses\_data\_GM1\_SS3\_HH\_2008-12-27\_4.dat...  
Writing ../../RESULTS/DAILY/081227//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_GM1\_SS3\_HH\_4.png...  
Writing ../../RESULTS/DAILY/081227//CALIBRATION\_PULSES/Transmit\_Power\_GM1\_SS3\_HH\_4.png...

CALIBRATION PULSES ANALYSIS completed  
#####

DOPPLER ANALYSIS  
#####  
Creating directory ./RESULTS/DAILY/081227/DOPPLER...

\*\*\*\*\*  
\*\*\*\*\*  
DOPPLER ANX Analysis will be performed from 2008-12-27 00:00:00 to 2008-12-27 23:59:59

Analysing products WVS IS2 V/V  
Getting doppler data for WVS IS2 V/V from 2008-12-27 00:00:00 to 2008-12-27 23:59:59...  
Writing file ./RESULTS/DAILY/081227/DOPPLER/Doppler\_data\_WVS\_IS2\_VV\_2008-12-27.dat...  
Running IDL program...  
Writing file ../../RESULTS/DAILY/081227/DOPPLER/DOPPLER\_ANX\_WVS\_IS2\_VV.png...

Analysing products GM1 SS1 H/H  
Getting doppler data for GM1 SS1 H/H from 2008-12-27 00:00:00 to 2008-12-27 23:59:59...  
Writing file ./RESULTS/DAILY/081227/DOPPLER/Doppler\_data\_GM1\_SS1\_HH\_2008-12-27.dat...  
Running IDL program...  
Writing file ../../RESULTS/DAILY/081227/DOPPLER/DOPPLER\_ANX\_GM1\_SS1\_HH.png...

\*\*\*\*\*  
\*\*\*\*\*  
DOPPLER JUMPS Analysis will be performed on WSM products from 2008-12-27 00:00:00 to 2008-12-27 23:59:59

Analysing by default products WSM  
Getting doppler jumps data for WSM from 2008-12-27 00:00:00 to 2008-12-27 23:59:59...  
Writing file ./RESULTS/DAILY/081227/DOPPLER/Doppler\_Jumps\_data\_WSM\_2008-12-27.dat...  
Running IDL program...  
Writing file ../../RESULTS/DAILY/081227/DOPPLER/DOPPLER\_JUMPS\_ANX\_WSM.png...  
Writing file ../../RESULTS/DAILY/081227/DOPPLER/DOPPLER\_JUMPS\_Date\_WSM.png...

\*\*\*\*\*  
\*\*\*\*\*  
DOPPLER MAP Analysis will be performed from 2008-12-27 00:00:00 to 2008-12-27 23:59:59

Analysing products WVS IS2 V/V  
Loading predicted doppler values....  
Phase: descending  
Found data...  
Computing mean error doppler estimated-predicted...  
Mean error = -34.846851 Hz  
Writing file ../../RESULTS/DAILY/081227//DOPPLER/DOPPLER\_Estimated-Predicted-MeanError\_WVS\_IS2\_VV\_desc.jpg...  
Writing file ../../RESULTS/DAILY/081227//DOPPLER/DOPPLER\_Absolute\_WVS\_IS2\_VV\_desc.jpg...

\*\*\*\*\*  
Loading predicted doppler values....  
Phase: ascending

```
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -24.553363 Hz
Writing file ../../RESULTS/DAILY/081227//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_WVS_IS2_VV_asc.jpg...
Writing file ../../RESULTS/DAILY/081227//DOPPLER/DOPPLER_Absolute_WVS_IS2_VV_asc.jpg...
```

\*\*\*\*\*

```
Analysing products GM1 SS1 H/H
Loading predicted doppler values....
Phase: descending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -23.330302 Hz
Writing file ../../RESULTS/DAILY/081227//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_GM1_SS1_HH_desc.jpg...
Writing file ../../RESULTS/DAILY/081227//DOPPLER/DOPPLER_Absolute_GM1_SS1_HH_desc.jpg...
```

\*\*\*\*\*

```
Loading predicted doppler values....
Phase: ascending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -22.408545 Hz
Writing file ../../RESULTS/DAILY/081227//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_GM1_SS1_HH_asc.jpg...
Writing file ../../RESULTS/DAILY/081227//DOPPLER/DOPPLER_Absolute_GM1_SS1_HH_asc.jpg...
```

\*\*\*\*\*

```
DOPPLER ANALYSIS completed
#####
```

```
CHIRP ANALYSIS
#####
Creating directory ./RESULTS/DAILY/081227/CHIRP...
```

```
*****
*****
CHIRP Analysis will be performed from 2008-12-27 00:00:00 to 2008-12-27 23:59:59
```

```
Analysing products WSM SS1 H/H
*****
Getting ScaleFactor data for WSM SS1 H/H from 2008-12-27 00:00:00 to 2008-12-27 23:59:59...
Writing file ./RESULTS/DAILY/081227/CHIRP/ScaleFactor_data_WSM_SS1_HH_2008-12-27.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/081227/CHIRP/ScaleFactor_ANX_WSM_SS1_HH.png...
Writing file ../../RESULTS/DAILY/081227/CHIRP/ScaleFactor_DATE_WSM_SS1_HH.png...
```

```
Analysing products WSM SS1 V/V
*****
Getting ScaleFactor data for WSM SS1 V/V from 2008-12-27 00:00:00 to 2008-12-27 23:59:59...
Writing file ./RESULTS/DAILY/081227/CHIRP/ScaleFactor_data_WSM_SS1_VV_2008-12-27.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/081227/CHIRP/ScaleFactor_ANX_WSM_SS1_VV.png...
Writing file ../../RESULTS/DAILY/081227/CHIRP/ScaleFactor_DATE_WSM_SS1_VV.png...
```

```
CHIRP ANALYSIS completed
#####
```

RAW DATA ANALYSIS

#####  
Analysis will be performed from 2008-12-27 00:00:00 to 2008-12-27 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/081227/RAW\_DATA

Creating directory ./RESULTS/DAILY/081227/RAW\_DATA...

\*\*\*\*\*  
Getting raw data for WVS from 2008-12-27 00:00:00 to 2008-12-27 23:59:59...  
Writing file ./RESULTS/DAILY/081227/RAW\_DATA/Raw\_data\_WVS\_2008-12-27.dat...  
Running IDL program to create graphs...

Creating image ../../RESULTS/DAILY/081227/RAW\_DATA/Raw\_data\_WVS\_input\_mean.png...  
Creating image ../../RESULTS/DAILY/081227/RAW\_DATA/Raw\_data\_WVS\_input\_stddev.png...  
Creating image ../../RESULTS/DAILY/081227/RAW\_DATA/Raw\_data\_WVS\_gain\_imbalance.png...

\*\*\*\*\*  
Getting raw data for IMM from 2008-12-27 00:00:00 to 2008-12-27 23:59:59...  
Writing file ./RESULTS/DAILY/081227/RAW\_DATA/Raw\_data\_IMM\_2008-12-27.dat...  
Running IDL program to create graphs...

Creating image ../../RESULTS/DAILY/081227/RAW\_DATA/Raw\_data\_IMM\_input\_mean.png...  
Creating image ../../RESULTS/DAILY/081227/RAW\_DATA/Raw\_data\_IMM\_input\_stddev.png...  
Creating image ../../RESULTS/DAILY/081227/RAW\_DATA/Raw\_data\_IMM\_gain\_imbalance.png...

RAW DATA ANALYSIS completed

#####

TELEMETRY ANALYSIS

#####  
Analysis will be performed from 2008-12-27 00:00:00 to 2008-12-27 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/081227/TELEMETRY

Creating directory ./RESULTS/DAILY/081227/TELEMETRY...

Looking for gaps and missing lines in WVS products...  
\*\*\*\*\*  
Checking 29 products from PDE...  
Checking 25 products from PDK...

Looking for gaps and missing lines in GM1 products...  
\*\*\*\*\*  
Checking 39 products from PDE...  
Checking 42 products from PDK...

Looking for gaps and missing lines in APM products...  
\*\*\*\*\*  
Checking 1 products from PDE...  
Checking 1 products from PDK...

Looking for gaps and missing lines in IMM products...  
\*\*\*\*\*  
Checking 22 products from PDE...  
Checking 3 products from PDK...

Looking for gaps and missing lines in WSM products...  
\*\*\*\*\*  
Checking 57 products from PDE...  
Found product...ASA\_WSM\_1PNPDE20081227\_045322\_000001892075\_00062\_35687\_2645.N1 / 0 gaps / 1 missing lines  
Found product...ASA\_WSM\_1PNPDE20081227\_045322\_000003732075\_00062\_35687\_2808.N1 / 0 gaps / 1 missing lines  
Found product...ASA\_WSM\_1PNPDE20081227\_160546\_000001902075\_00069\_35694\_3385.N1 / 0 gaps / 35 missing lines  
No products from PDK...

Creating graph of missing lines and gaps...

\*\*\*\*\*  
Creating image: ./RESULTS/DAILY/081227/TELEMETRY/TELEMETRY\_Missing\_lines.png...  
Creating image: ./RESULTS/DAILY/081227/TELEMETRY/TELEMETRY\_Gaps.png...

TELEMETRY ANALYSIS completed  
#####

BROWSE PRODUCTS ANALYSIS  
#####  
Analysis will be performed on 2008-12-27

\*\*\*\*\*  
Scanning directory /nas3/ENVISAT/ASAR//ASA\_GM\_BP...  
Results will be exported to the directory: /nas3/ENVISAT/ASAR//ASA\_GM\_BP/JPG/20081227/

Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20081227\_193605\_000002832075\_00071\_35696\_3428.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20081227\_195127\_000002232075\_00071\_35696\_3430.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20081227\_202851\_000004532075\_00071\_35696\_3432.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20081227\_204101\_000002292075\_00071\_35696\_3445.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20081227\_205419\_000010812075\_00071\_35696\_3596.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20081227\_211502\_000000722075\_00072\_35697\_3505.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20081227\_212717\_000002472075\_00072\_35697\_3507.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20081227\_221209\_000001992075\_00072\_35697\_3524.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20081227\_224335\_000004102075\_00073\_35698\_3648.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20081227\_230708\_000004162075\_00073\_35698\_3657.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20081227\_233835\_000002232075\_00073\_35698\_3655.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20081227\_234226\_000000962075\_00073\_35698\_3661.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20081227\_235813\_000000842075\_00073\_35698\_3659.N1 ...

ANALYSIS COMPLETED: 13 GM browse products to see...  
\*\*\*\*\*

\*\*\*\*\*  
Scanning directory /nas3/ENVISAT/ASAR//ASA\_AP\_BP...  
Results will be exported to the directory: /nas3/ENVISAT/ASAR//ASA\_AP\_BP/JPG/20081227/

Stripping browse product /nas3/ENVISAT/ASAR//ASA\_AP\_BP/ASA\_AP\_BPZPDE20081227\_151041\_000000432075\_00068\_35693\_3358.N1 ...

ANALYSIS COMPLETED: 1 AP browse products to see...  
\*\*\*\*\*

\*\*\*\*\*  
Scanning directory /nas3/ENVISAT/ASAR//ASA\_IM\_BP...  
Results will be exported to the directory: /nas3/ENVISAT/ASAR//ASA\_IM\_BP/JPG/20081227/

Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20081227\_141840\_000000672075\_00067\_35692\_3356.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20081227\_142743\_000000452075\_00068\_35693\_3354.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20081227\_152438\_000000942075\_00068\_35693\_3372.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20081227\_163033\_000000542075\_00069\_35694\_3389.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20081227\_164443\_000000632075\_00069\_35694\_3397.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20081227\_174722\_000000982075\_00070\_35695\_3420.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20081227\_194923\_000001142075\_00071\_35696\_3483.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20081227\_213121\_000001152075\_00072\_35697\_3612.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20081227\_230416\_000001622075\_00073\_35698\_3778.N1 ...

ANALYSIS COMPLETED: 9 IM browse products to see...  
\*\*\*\*\*

\*\*\*\*\*  
Scanning directory /nas3/ENVISAT/ASAR//ASA\_WS\_BP...  
Results will be exported to the directory: /nas3/ENVISAT/ASAR//ASA\_WS\_BP/JPG/20081227/

Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_BP/ASA\_WS\_BPZPDE20081227\_095447\_000000922075\_00065\_35690\_3143.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_BP/ASA\_WS\_BPZPDE20081227\_095601\_000000182075\_00065\_35690\_3089.N1 ...



```

Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20081227_103023_000000732075_00065_35690_3145.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20081227_103023_000002382075_00065_35690_3244.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20081227_103238_000001032075_00065_35690_3197.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20081227_103345_000003602075_00065_35690_3242.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20081227_111513_000001902075_00066_35691_3246.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20081227_111513_000002692075_00066_35691_3288.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20081227_111924_000000182075_00066_35691_3230.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20081227_120543_000003112075_00066_35691_3296.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20081227_120656_000001762075_00066_35691_3249.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20081227_134507_000001352075_00067_35692_3380.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20081227_145005_000001902075_00068_35693_3382.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20081227_153639_000001652075_00068_35693_3384.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20081227_153752_000000922075_00068_35693_3370.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20081227_160000_000001532075_00068_35693_3422.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20081227_160546_000001902075_00069_35694_3386.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20081227_163215_000001592075_00069_35694_3426.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20081227_163430_000000242075_00069_35694_3418.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20081227_171715_000002932075_00069_35694_3424.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20081227_192323_000001522075_00071_35696_3499.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20081227_194637_000001042075_00071_35696_3497.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20081227_202558_000000732075_00071_35696_3458.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20081227_203627_000002692075_00071_35696_3503.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20081227_203740_000000612075_00071_35696_3472.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20081227_203937_000000782075_00071_35696_3495.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20081227_204943_000002752075_00071_35696_3501.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20081227_212535_000000982075_00072_35697_3619.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20081227_213349_000001152075_00072_35697_3617.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20081227_221035_000000732075_00072_35697_3598.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20081227_221535_000005502075_00072_35697_3653.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20081227_231410_000001152075_00073_35698_3789.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20081227_235111_000000732075_00073_35698_3752.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20081227_235311_000000732075_00073_35698_3758.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20081227_235311_000002992075_00073_35698_3883.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20081227_235722_000000482075_00073_35698_3766.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20081227_235939_000002922075_00073_35698_3791.N1 ...

```

ANALYSIS COMPLETED: 37 WS browse products to see...

\*\*\*\*\*

BROWSE PRODUCTS ANALYSIS completed

#####

HTML REPORT generation

#####

Building file ./RESULTS/DAILY/081227/asarReport.html...

Building DATA SUMMARY section...

Building AUXILIARY FILES ANALYSIS section...

Building MODULE STEPPING ANALYSIS section...

Building CALIBRATION PULSES ANALYSIS section...

Building DOPPLER ANALYSIS section...

Building CHIRP ANALYSIS section...

Building RAW DATA ANALYSIS section...

Building TELEMETRY ANALYSIS section...

HTML REPORT generation completed

#####



# ASAR Daily Report





Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
ASA_APM_1PNPDE20081227_151041_000000432075_00068_35693_3357.N1	OK	OK	OK	OK
ASA_APM_1PNPDK20081227_080754_000000432075_00064_35689_6552.N1	OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_GM1_1PNPDE20081227_000737_000004162075_00059_35684_2089.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081227_002639_000006642075_00059_35684_2102.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081227_005108_000001692075_00059_35684_2215.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081227_011838_000001812075_00060_35685_2213.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081227_012315_000007372075_00060_35685_2226.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081227_015102_000001442075_00060_35685_2230.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081227_020215_000001502075_00060_35685_2228.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081227_021026_000004712075_00060_35685_2238.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081227_022442_000008332075_00060_35685_2376.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081227_024840_000001572075_00061_35686_2371.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081227_025302_000001872075_00061_35686_2369.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081227_025718_000002172075_00061_35686_2367.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081227_030231_000006342075_00061_35686_2389.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081227_034251_000007492075_00061_35686_2488.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081227_040017_000001632075_00061_35686_2495.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081227_041956_000001022075_00062_35687_2493.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081227_042237_000012812075_00062_35687_2592.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081227_044719_000003562075_00062_35687_2508.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081227_045943_000001632075_00062_35687_2542.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081227_052327_000003022075_00062_35687_2687.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081227_053010_000002472075_00062_35687_2692.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081227_053708_000001442075_00062_35687_2694.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081227_060629_000010202075_00063_35688_2789.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081227_063156_000000962075_00063_35688_2700.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081227_063508_000004222075_00063_35688_2726.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081227_064316_000002412075_00063_35688_2739.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081227_193605_000002832075_00071_35696_3427.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081227_195127_000002232075_00071_35696_3429.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081227_202851_000004532075_00071_35696_3431.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081227_204101_000002292075_00071_35696_3444.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081227_205419_000010812075_00071_35696_3595.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081227_211502_000000722075_00072_35697_3504.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081227_212717_000002472075_00072_35697_3506.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081227_221209_000001992075_00072_35697_3523.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081227_224335_000004102075_00073_35698_3647.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081227_230708_000004162075_00073_35698_3656.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081227_233835_000002232075_00073_35698_3654.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081227_234226_000000962075_00073_35698_3660.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081227_235813_000000842075_00073_35698_3658.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081227_070403_000001812075_00063_35688_6497.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081227_071716_000001692075_00063_35688_6499.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081227_075332_000007002075_00064_35689_6509.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081227_080403_000002292075_00064_35689_6575.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081227_082126_000001082075_00064_35689_6577.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081227_082444_000006162075_00064_35689_6579.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081227_084555_000008882075_00064_35689_6587.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081227_093517_000005732075_00065_35690_6601.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081227_095830_000000722075_00065_35690_6707.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081227_100030_000003982075_00065_35690_6709.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081227_102515_000003022075_00065_35690_6711.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081227_103948_000000902075_00065_35690_6716.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081227_111244_000001442075_00066_35691_6718.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081227_111947_000000962075_00066_35691_6720.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081227_121441_000004342075_00066_35691_6829.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081227_123210_000000842075_00066_35691_6834.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081227_125103_000009302075_00067_35692_6839.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081227_130527_000002292075_00067_35692_6971.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081227_132749_000006582075_00067_35692_6973.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081227_133851_000003682075_00067_35692_6975.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081227_134738_000008882075_00067_35692_6977.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081227_141017_000002772075_00067_35692_6982.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081227_142600_000001022075_00068_35693_6990.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081227_142839_000006162075_00068_35693_7000.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081227_144818_000001022075_00068_35693_7084.N1					OK	OK	OK	OK

ASA_GM1_1PNPDK20081227_145321_000001322075_00068_35693_7086.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20081227_145713_000001082075_00068_35693_7091.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20081227_152703_000005732075_00068_35693_7093.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20081227_153931_000002172075_00068_35693_7098.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20081227_160918_000005192075_00069_35694_7106.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20081227_161648_000000662075_00069_35694_7148.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20081227_162814_000001382075_00069_35694_7150.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20081227_163456_000005862075_00069_35694_7152.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20081227_170739_000005732075_00069_35694_7154.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20081227_172212_000000902075_00069_35694_7159.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20081227_174911_000004412075_00070_35695_7166.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20081227_175516_000001382075_00070_35695_7201.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20081227_181113_000002172075_00070_35695_7203.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20081227_181554_000001142075_00070_35695_7205.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20081227_184815_000009302075_00070_35695_7215.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20081227_192104_000001322075_00070_35695_7237.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20081227_192557_000006822075_00071_35696_7217.N1	OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_IMM_1PNPDE20081227_025611_000000562075_00061_35686_2355.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20081227_031301_000001232075_00061_35686_2463.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20081227_031301_000003692075_00061_35686_2612.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20081227_031604_000001872075_00061_35686_2464.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20081227_041502_000000682075_00061_35686_2589.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20081227_044400_000001892075_00062_35687_2486.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20081227_053415_000001622075_00062_35687_2681.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20081227_062707_000001222075_00063_35688_2685.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20081227_062707_000002782075_00063_35688_2791.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20081227_064212_000000532075_00063_35688_2663.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20081227_065007_000000282075_00063_35688_2683.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20081227_082312_000000822075_00064_35689_2921.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20081227_095942_000000372075_00065_35690_3084.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20081227_141840_000000672075_00067_35692_3355.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20081227_142743_000000452075_00068_35693_3353.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20081227_152438_000000942075_00068_35693_3371.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20081227_163033_000000542075_00069_35694_3388.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20081227_164443_000000632075_00069_35694_3396.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20081227_174722_000000982075_00070_35695_3419.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20081227_194923_000001142075_00071_35696_3482.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20081227_213121_000001152075_00072_35697_3611.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20081227_230416_000001622075_00073_35698_3777.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20081227_095028_000000372075_00065_35690_6680.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20081227_130915_000000822075_00067_35692_6942.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20081227_144545_000001422075_00068_35693_7051.N1					OK	OK	OK	OK


Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WSM_1PNPDE20081227_002248_000002252075_00059_35684_2203.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_011112_000001892075_00060_35685_2391.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_011112_000004342075_00060_35685_2655.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_011725_000000612075_00060_35685_2346.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_012141_000000912075_00060_35685_2353.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_020448_000001902075_00060_35685_2361.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_020448_000003362075_00060_35685_2638.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_020859_000000842075_00060_35685_2362.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_024725_000000732075_00061_35686_2351.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_025118_000000982075_00061_35686_2436.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_030057_000000732075_00061_35686_2365.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_031928_000002502075_00061_35686_2476.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_031928_000002692075_00061_35686_2610.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_035528_000002862075_00061_35686_2640.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_045322_000001892075_00062_35687_2645.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_045322_000003732075_00062_35687_2808.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_045732_000001232075_00062_35687_2646.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_052836_000000912075_00062_35687_2679.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_063334_000000912075_00063_35688_2787.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_070712_000002502075_00063_35688_2855.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_095447_000000922075_00065_35690_3142.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_095601_000000182075_00065_35690_3088.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_103023_000000732075_00065_35690_3144.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_103023_000002382075_00065_35690_3243.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_103238_000001032075_00065_35690_3196.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_103345_000003602075_00065_35690_3241.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_111513_000001902075_00066_35691_3245.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_111513_000002692075_00066_35691_3287.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_111924_000000182075_00066_35691_3229.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_120543_000003112075_00066_35691_3295.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_120656_000001762075_00066_35691_3248.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_134507_000001352075_00067_35692_3379.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_145005_000001902075_00068_35693_3381.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_153639_000001652075_00068_35693_3383.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_153752_000000922075_00068_35693_3369.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_160000_000001532075_00068_35693_3421.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_160546_000001902075_00069_35694_3385.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_163215_000001592075_00069_35694_3425.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_163430_000000242075_00069_35694_3417.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_171715_000002932075_00069_35694_3423.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_192323_000001522075_00071_35696_3498.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_194637_000001042075_00071_35696_3496.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_202558_000000732075_00071_35696_3457.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_203627_000002692075_00071_35696_3502.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_203740_000000612075_00071_35696_3471.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_203937_000000782075_00071_35696_3494.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_204943_000002752075_00071_35696_3500.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_212535_000000982075_00072_35697_3618.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_213349_000001152075_00072_35697_3616.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_221035_000000732075_00072_35697_3597.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_221535_000005502075_00072_35697_3652.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_231410_000001152075_00073_35698_3788.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_235111_000000732075_00073_35698_3751.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_235311_000000732075_00073_35698_3757.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_235311_000002992075_00073_35698_3882.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_235722_000000482075_00073_35698_3765.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081227_235939_000002922075_00073_35698_3790.N1					OK	OK	OK	OK


Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WVS_1PNPDE20081227_001435_000003752075_00059_35684_2092.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20081227_003744_000004342075_00059_35684_2095.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20081227_004359_000003892075_00059_35684_2211.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20081227_005402_000009592075_00059_35684_2221.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20081227_013534_000001642075_00060_35685_2218.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20081227_013921_000006592075_00060_35685_2224.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20081227_015328_000004802075_00060_35685_2233.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20081227_021820_00000602075_00060_35685_2236.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20081227_021835_000003302075_00060_35685_2374.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20081227_023839_000004192075_00061_35686_2379.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20081227_032358_000006892075_00061_35686_2387.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20081227_033513_000002552075_00061_35686_2491.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20081227_040301_000006892075_00061_35686_2498.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20081227_041617_000001792075_00062_35687_2511.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20081227_050228_000009142075_00062_35687_2545.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20081227_051728_000003152075_00062_35687_2690.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20081227_053932_000015742075_00062_35687_2742.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20081227_064717_000001192075_00063_35688_2729.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20081227_065149_000003452075_00063_35688_2732.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20081227_195512_000017992075_00071_35696_3434.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20081227_204455_000000142075_00071_35696_3442.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20081227_204455_000002402075_00071_35696_3509.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20081227_213543_000019792075_00072_35697_3516.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20081227_222522_000004042075_00072_35697_3526.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20081227_223107_000007042075_00072_35697_3645.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20081227_225028_000004942075_00073_35698_3650.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20081227_231607_000013042075_00073_35698_3666.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20081227_234407_000003152075_00073_35698_3663.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20081227_065719_000003602075_00063_35688_6495.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20081227_072008_000019642075_00063_35688_6507.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20081227_083501_000005402075_00064_35689_6585.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20081227_090044_000000452075_00064_35689_6582.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20081227_090416_000018142075_00064_35689_6599.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20081227_100712_000010342075_00065_35690_6714.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20081227_104120_000018442075_00065_35690_6728.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20081227_113036_000001052075_00066_35691_6827.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20081227_113530_000017692075_00066_35691_6832.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20081227_122434_000001952075_00066_35691_6837.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20081227_123336_000010002075_00066_35691_6847.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20081227_131236_000008692075_00067_35692_6980.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20081227_140231_000004202075_00067_35692_6985.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20081227_141454_000001942075_00067_35692_6988.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20081227_141953_000002242075_00068_35693_6998.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20081227_145902_000005842075_00068_35693_7089.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20081227_151141_000007342075_00068_35693_7096.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20081227_154307_000009742075_00068_35693_7101.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20081227_160230_000001492075_00069_35694_7104.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20081227_164555_000012592075_00069_35694_7157.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20081227_172343_000013792075_00069_35694_7169.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20081227_182122_000013042075_00070_35695_7240.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20081227_190419_00000602075_00070_35695_7208.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20081227_190737_000003452075_00070_35695_7235.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20081227_191743_000001642075_00070_35695_7220.N1					OK	OK	OK	OK

Calibration pulses for GM1 SS3 H/H




### Calibration pulses for GM1 SS3 H/H







### Calibration pulses for GM1 SS3 H/H




Calibration pulses for GM1 SS3 H/H




27-Dec



27-Dec




27-Dec




27-Dec

rows: \_ 4 \_ 8 \_ 12 \_ 16 \_ 20 \_ 24 \_ 28 \_ 32


Calibration pulses for WVS IS2 V/V




### Calibration pulses for WVS IS2 V/V





Calibration pulses for WVS IS2 V/V





### Calibration pulses for WVS IS2 V/V

















rows: \_ 1 \_ 5 \_ 9 \_ 13 \_ 17 \_ 21 \_ 25 \_ 29





rows: \_ 2 \_ 6 \_ 10 \_ 14 \_ 18 \_ 22 \_ 26 \_ 30









27-Dec  
rows: \_ 4 \_ 8 \_ 12 \_ 16 \_ 20 \_ 24 \_ 28 \_ 32





rows: \_ 1 \_ 5 \_ 9 \_ 13 \_ 17 \_ 21 \_ 25 \_ 29




rows: \_ 2 \_ 6 \_ 10 \_ 14 \_ 18 \_ 22 \_ 26 \_ 30





27-Dec  
rows: \_ 3 \_ 7 \_ 11 \_ 15 \_ 19 \_ 23 \_ 27 \_ 31














Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion			
ASA_APM_1PNPDK20081227_080754_000000432075_00064_35689_6552.N1						IS7	V/H	75	35689 64 4.07
ASA_APM_1PNPDE20081227_151041_000000432075_00068_35693_3357.N1						IS2	H/H	75	35693 68 4.07

Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_GM1_1PNPDE20081227_000737_000004162075_00059_35684_2089.N1						SS1	H/H	75	35684	59	4.07
ASA_GM1_1PNPDE20081227_002639_000006642075_00059_35684_2102.N1						SS1	H/H	75	35684	59	4.07
ASA_GM1_1PNPDE20081227_005108_000001692075_00059_35684_2215.N1						SS1	H/H	75	35684	59	4.07
ASA_GM1_1PNPDE20081227_011838_000001812075_00060_35685_2213.N1						SS1	H/H	75	35685	60	4.07
ASA_GM1_1PNPDE20081227_012315_000007372075_00060_35685_2226.N1						SS1	H/H	75	35685	60	4.07
ASA_GM1_1PNPDE20081227_015102_000001442075_00060_35685_2230.N1						SS1	H/H	75	35685	60	4.07
ASA_GM1_1PNPDE20081227_020215_000001502075_00060_35685_2228.N1						SS1	H/H	75	35685	60	4.07
ASA_GM1_1PNPDE20081227_021026_000004712075_00060_35685_2238.N1						SS1	H/H	75	35685	60	4.07
ASA_GM1_1PNPDE20081227_022442_000008332075_00060_35685_2376.N1						SS1	H/H	75	35685	60	4.07
ASA_GM1_1PNPDE20081227_024840_000001572075_00061_35686_2371.N1						SS1	H/H	75	35686	61	4.07
ASA_GM1_1PNPDE20081227_025302_000001872075_00061_35686_2369.N1						SS1	H/H	75	35686	61	4.07
ASA_GM1_1PNPDE20081227_025718_000002172075_00061_35686_2367.N1						SS1	H/H	75	35686	61	4.07
ASA_GM1_1PNPDE20081227_030231_000006342075_00061_35686_2389.N1						SS1	H/H	75	35686	61	4.07
ASA_GM1_1PNPDE20081227_034251_000007492075_00061_35686_2488.N1						SS1	H/H	75	35686	61	4.07
ASA_GM1_1PNPDE20081227_040017_000001632075_00061_35686_2495.N1						SS1	H/H	75	35686	61	4.07
ASA_GM1_1PNPDE20081227_041956_000001022075_00062_35687_2493.N1						SS1	H/H	75	35687	62	4.07
ASA_GM1_1PNPDE20081227_042237_000012812075_00062_35687_2592.N1						SS1	H/H	75	35687	62	4.07
ASA_GM1_1PNPDE20081227_044719_000003562075_00062_35687_2508.N1						SS1	H/H	75	35687	62	4.07
ASA_GM1_1PNPDE20081227_045943_000001632075_00062_35687_2542.N1						SS1	H/H	75	35687	62	4.07
ASA_GM1_1PNPDE20081227_052327_000003022075_00062_35687_2687.N1						SS1	H/H	75	35687	62	4.07
ASA_GM1_1PNPDE20081227_053010_000002472075_00062_35687_2692.N1						SS1	H/H	75	35687	62	4.07
ASA_GM1_1PNPDE20081227_053708_000001442075_00062_35687_2694.N1						SS1	H/H	75	35687	62	4.07
ASA_GM1_1PNPDE20081227_060629_000010202075_00063_35688_2789.N1						SS1	H/H	75	35688	63	4.07
ASA_GM1_1PNPDE20081227_063156_000000962075_00063_35688_2700.N1						SS1	H/H	75	35688	63	4.07
ASA_GM1_1PNPDE20081227_063508_000004222075_00063_35688_2726.N1						SS1	H/H	75	35688	63	4.07
ASA_GM1_1PNPDE20081227_064316_000002412075_00063_35688_2739.N1						SS1	H/H	75	35688	63	4.07
ASA_GM1_1PNPDK20081227_070403_000001812075_00063_35688_6497.N1						SS1	H/H	75	35688	63	4.07
ASA_GM1_1PNPDK20081227_071716_000001692075_00063_35688_6499.N1						SS1	H/H	75	35688	63	4.07
ASA_GM1_1PNPDK20081227_075332_000007002075_00064_35689_6509.N1						SS1	H/H	75	35689	64	4.07
ASA_GM1_1PNPDK20081227_080403_000002292075_00064_35689_6575.N1						SS1	H/H	75	35689	64	4.07
ASA_GM1_1PNPDK20081227_082126_000001082075_00064_35689_6577.N1						SS1	H/H	75	35689	64	4.07
ASA_GM1_1PNPDK20081227_082444_000006162075_00064_35689_6579.N1						SS1	H/H	75	35689	64	4.07
ASA_GM1_1PNPDK20081227_084555_000008882075_00064_35689_6587.N1						SS1	H/H	75	35689	64	4.07
ASA_GM1_1PNPDK20081227_093517_000005732075_00065_35690_6601.N1						SS1	H/H	75	35690	65	4.07
ASA_GM1_1PNPDK20081227_095830_000000722075_00065_35690_6707.N1						SS1	H/H	75	35690	65	4.07
ASA_GM1_1PNPDK20081227_100030_000003982075_00065_35690_6709.N1						SS1	H/H	75	35690	65	4.07
ASA_GM1_1PNPDK20081227_102515_000003022075_00065_35690_6711.N1						SS1	H/H	75	35690	65	4.07
ASA_GM1_1PNPDK20081227_103948_000000902075_00065_35690_6716.N1						SS1	H/H	75	35690	65	4.07
ASA_GM1_1PNPDK20081227_111244_000001442075_00066_35691_6718.N1						SS1	H/H	75	35691	66	4.07
ASA_GM1_1PNPDK20081227_111947_000000962075_00066_35691_6720.N1						SS1	H/H	75	35691	66	4.07
ASA_GM1_1PNPDK20081227_121441_000004342075_00066_35691_6829.N1						SS1	H/H	75	35691	66	4.07
ASA_GM1_1PNPDK20081227_123210_000000842075_00066_35691_6834.N1						SS1	H/H	75	35691	66	4.07
ASA_GM1_1PNPDK20081227_125103_000009302075_00067_35692_6839.N1						SS1	H/H	75	35692	67	4.07
ASA_GM1_1PNPDK20081227_130527_000002292075_00067_35692_6971.N1						SS1	H/H	75	35692	67	4.07
ASA_GM1_1PNPDK20081227_132749_000006582075_00067_35692_6973.N1						SS1	H/H	75	35692	67	4.07
ASA_GM1_1PNPDK20081227_133851_000003682075_00067_35692_6975.N1						SS1	H/H	75	35692	67	4.07
ASA_GM1_1PNPDK20081227_134738_000008882075_00067_35692_6977.N1						SS1	H/H	75	35692	67	4.07
ASA_GM1_1PNPDK20081227_141017_000002772075_00067_35692_6982.N1						SS1	H/H	75	35692	67	4.07
ASA_GM1_1PNPDK20081227_142600_000001022075_00068_35693_6990.N1						SS1	H/H	75	35693	68	4.07
ASA_GM1_1PNPDK20081227_142839_000006162075_00068_35693_7000.N1						SS1	H/H	75	35693	68	4.07
ASA_GM1_1PNPDK20081227_144818_000001022075_00068_35693_7084.N1						SS1	H/H	75	35693	68	4.07
ASA_GM1_1PNPDK20081227_145321_000001322075_00068_35693_7086.N1						SS1	H/H	75	35693	68	4.07
ASA_GM1_1PNPDK20081227_145713_000001082075_00068_35693_7091.N1						SS1	H/H	75	35693	68	4.07
ASA_GM1_1PNPDK20081227_152703_000005732075_00068_35693_7093.N1						SS1	H/H	75	35693	68	4.07
ASA_GM1_1PNPDK20081227_153931_000002172075_00068_35693_7098.N1						SS1	H/H	75	35693	68	4.07
ASA_GM1_1PNPDK20081227_160918_000005192075_00069_35694_7106.N1						SS1	H/H	75	35694	69	4.07
ASA_GM1_1PNPDK20081227_161648_000000662075_00069_35694_7148.N1						SS1	H/H	75	35694	69	4.07
ASA_GM1_1PNPDK20081227_162814_000001382075_00069_35694_7150.N1						SS1	H/H	75	35694	69	4.07
ASA_GM1_1PNPDK20081227_163456_000005862075_00069_35694_7152.N1						SS1	H/H	75	35694	69	4.07
ASA_GM1_1PNPDK20081227_170739_000005732075_00069_35694_7154.N1						SS1	H/H	75	35694	69	4.07
ASA_GM1_1PNPDK20081227_172212_000000902075_00069_35694_7159.N1						SS1	H/H	75	35694	69	4.07
ASA_GM1_1PNPDK20081227_174911_000004412075_00070_35695_7166.N1						SS1	H/H	75	35695	70	4.07
ASA_GM1_1PNPDK20081227_175516_000001382075_00070_35695_7201.N1						SS1	H/H	75	35695	70	4.07
ASA_GM1_1PNPDK20081227_181113_000002172075_00070_35695_7203.N1						SS1	H/H	75	35695	70	4.07
ASA_GM1_1PNPDK20081227_181554_000001142075_00070_35695_7205.N1						SS1	H/H	75	35695	70	4.07
ASA_GM1_1PNPDK20081227_184815_000009302075_00070_35695_7215.N1						SS1	H/H	75	35695	70	4.07
ASA_GM1_1PNPDK20081227_192104_000001322075_00070_35695_7237.N1						SS1	H/H	75	35695	70	4.07

ASA_GM1_1PNPDK20081227_192557_000006822075_00071_35696_7217.N1	SS1	H/H	75	35696	71	4.07
ASA_GM1_1PNPDE20081227_193605_000002832075_00071_35696_3427.N1	SS1	H/H	75	35696	71	4.07
ASA_GM1_1PNPDE20081227_195127_000002232075_00071_35696_3429.N1	SS1	H/H	75	35696	71	4.07
ASA_GM1_1PNPDE20081227_202851_000004532075_00071_35696_3431.N1	SS1	H/H	75	35696	71	4.07
ASA_GM1_1PNPDE20081227_204101_000002292075_00071_35696_3444.N1	SS1	H/H	75	35696	71	4.07
ASA_GM1_1PNPDE20081227_205419_000010812075_00071_35696_3595.N1	SS1	H/H	75	35696	71	4.07
ASA_GM1_1PNPDE20081227_211502_000000722075_00072_35697_3504.N1	SS1	H/H	75	35697	72	4.07
ASA_GM1_1PNPDE20081227_212717_000002472075_00072_35697_3506.N1	SS1	H/H	75	35697	72	4.07
ASA_GM1_1PNPDE20081227_221209_000001992075_00072_35697_3523.N1	SS1	H/H	75	35697	72	4.07
ASA_GM1_1PNPDE20081227_224335_000004102075_00073_35698_3647.N1	SS1	H/H	75	35698	73	4.07
ASA_GM1_1PNPDE20081227_230708_000004162075_00073_35698_3656.N1	SS1	H/H	75	35698	73	4.07
ASA_GM1_1PNPDE20081227_233835_000002232075_00073_35698_3654.N1	SS1	H/H	75	35698	73	4.07
ASA_GM1_1PNPDE20081227_234226_000000962075_00073_35698_3660.N1	SS1	H/H	75	35698	73	4.07
ASA_GM1_1PNPDE20081227_235813_000000842075_00073_35698_3658.N1	SS1	H/H	75	35698	73	4.07

Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_IMM_1PNPDE20081227_025611_000000562075_00061_35686_2355.N1						IS2	V/V	75	35686	61	4.07
ASA_IMM_1PNPDE20081227_031301_000001232075_00061_35686_2463.N1						IS2	V/V	75	35686	61	4.07
ASA_IMM_1PNPDE20081227_031301_000003692075_00061_35686_2612.N1						IS2	V/V	75	35686	61	4.07
ASA_IMM_1PNPDE20081227_031604_000001872075_00061_35686_2464.N1						IS2	V/V	75	35686	61	4.07
ASA_IMM_1PNPDE20081227_041502_000000682075_00061_35686_2589.N1						IS2	V/V	75	35686	61	4.07
ASA_IMM_1PNPDE20081227_044400_000001892075_00062_35687_2486.N1						IS2	V/V	75	35687	62	4.07
ASA_IMM_1PNPDE20081227_053415_000001622075_00062_35687_2681.N1						IS4	H/H	75	35687	62	4.07
ASA_IMM_1PNPDE20081227_062707_000001222075_00063_35688_2685.N1						IS2	V/V	75	35688	63	4.07
ASA_IMM_1PNPDE20081227_062707_000002782075_00063_35688_2791.N1						IS2	V/V	75	35688	63	4.07
ASA_IMM_1PNPDE20081227_064212_000000532075_00063_35688_2663.N1						IS2	V/V	75	35688	63	4.07
ASA_IMM_1PNPDE20081227_065007_000000282075_00063_35688_2683.N1						IS2	V/V	75	35688	63	4.07
ASA_IMM_1PNPDE20081227_082312_000000822075_00064_35689_2921.N1						IS3	H/H	75	35689	64	4.07
ASA_IMM_1PNPDK20081227_095028_000000372075_00065_35690_6680.N1						IS6	V/V	75	35690	65	4.07
ASA_IMM_1PNPDE20081227_095942_000000372075_00065_35690_3084.N1						IS2	V/V	75	35690	65	4.07
ASA_IMM_1PNPDK20081227_130915_000000822075_00067_35692_6942.N1						IS2	V/V	75	35692	67	4.07
ASA_IMM_1PNPDE20081227_141840_000000672075_00067_35692_3355.N1						IS2	V/V	75	35692	67	4.07
ASA_IMM_1PNPDE20081227_142743_000000452075_00068_35693_3353.N1						IS2	V/V	75	35693	68	4.07
ASA_IMM_1PNPDK20081227_144545_000001422075_00068_35693_7051.N1						IS2	H/H	75	35693	68	4.07
ASA_IMM_1PNPDE20081227_152438_000000942075_00068_35693_3371.N1						IS6	H/H	75	35693	68	4.07
ASA_IMM_1PNPDE20081227_163033_000000542075_00069_35694_3388.N1						IS2	V/V	75	35694	69	4.07
ASA_IMM_1PNPDE20081227_164443_000000632075_00069_35694_3396.N1						IS2	V/V	75	35694	69	4.07
ASA_IMM_1PNPDE20081227_174722_000000982075_00070_35695_3419.N1						IS6	V/V	75	35695	70	4.07
ASA_IMM_1PNPDE20081227_194923_000001142075_00071_35696_3482.N1						IS2	V/V	75	35696	71	4.07
ASA_IMM_1PNPDE20081227_213121_000001152075_00072_35697_3611.N1						IS2	V/V	75	35697	72	4.07
ASA_IMM_1PNPDE20081227_230416_000001622075_00073_35698_3777.N1						IS2	H/H	75	35698	73	4.07





Filename	Pol	Timestamp	count(Module)
ASA_MS__0PNPDK20081227_084437_000000162075_00064_35689_0711.N1	H	2008-12-27 08:44:37	320





Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WSM_1PNPDE20081227_002248_000002252075_00059_35684_2203.N1						SS1	H/H	75	35684	59	4.07
ASA_WSM_1PNPDE20081227_011112_000001892075_00060_35685_2391.N1						SS1	H/H	75	35685	60	4.07
ASA_WSM_1PNPDE20081227_011112_000004342075_00060_35685_2655.N1						SS1	H/H	75	35685	60	4.07
ASA_WSM_1PNPDE20081227_011725_000000612075_00060_35685_2346.N1						SS1	H/H	75	35685	60	4.07
ASA_WSM_1PNPDE20081227_012141_000000912075_00060_35685_2353.N1						SS1	H/H	75	35685	60	4.07
ASA_WSM_1PNPDE20081227_020448_000001902075_00060_35685_2361.N1						SS1	H/H	75	35685	60	4.07
ASA_WSM_1PNPDE20081227_020448_000003362075_00060_35685_2638.N1						SS1	H/H	75	35685	60	4.07
ASA_WSM_1PNPDE20081227_020859_000000842075_00060_35685_2362.N1						SS1	H/H	75	35685	60	4.07
ASA_WSM_1PNPDE20081227_024725_000000732075_00061_35686_2351.N1						SS1	H/H	75	35686	61	4.07
ASA_WSM_1PNPDE20081227_025118_000000982075_00061_35686_2436.N1						SS1	H/H	75	35686	61	4.07
ASA_WSM_1PNPDE20081227_030057_000000732075_00061_35686_2365.N1						SS1	H/H	75	35686	61	4.07
ASA_WSM_1PNPDE20081227_031928_000002502075_00061_35686_2476.N1						SS1	H/H	75	35686	61	4.07
ASA_WSM_1PNPDE20081227_031928_000002692075_00061_35686_2610.N1						SS1	H/H	75	35686	61	4.07
ASA_WSM_1PNPDE20081227_035528_000002862075_00061_35686_2640.N1						SS1	H/H	75	35686	61	4.07
ASA_WSM_1PNPDE20081227_045322_000001892075_00062_35687_2645.N1						SS1	H/H	75	35687	62	4.07
ASA_WSM_1PNPDE20081227_045322_000003732075_00062_35687_2808.N1						SS1	H/H	75	35687	62	4.07
ASA_WSM_1PNPDE20081227_045732_000001232075_00062_35687_2646.N1						SS1	H/H	75	35687	62	4.07
ASA_WSM_1PNPDE20081227_052836_000000912075_00062_35687_2679.N1						SS1	H/H	75	35687	62	4.07
ASA_WSM_1PNPDE20081227_063334_000000912075_00063_35688_2787.N1						SS1	H/H	75	35688	63	4.07
ASA_WSM_1PNPDE20081227_070712_000002502075_00063_35688_2855.N1						SS1	H/H	75	35688	63	4.07
ASA_WSM_1PNPDE20081227_095447_000000922075_00065_35690_3142.N1						SS1	V/V	75	35690	65	4.07
ASA_WSM_1PNPDE20081227_095601_000000182075_00065_35690_3088.N1						SS1	V/V	75	35690	65	4.07
ASA_WSM_1PNPDE20081227_103023_000000732075_00065_35690_3144.N1						SS1	H/H	75	35690	65	4.07
ASA_WSM_1PNPDE20081227_103023_000002382075_00065_35690_3243.N1						SS1	H/H	75	35690	65	4.07
ASA_WSM_1PNPDE20081227_103238_000001032075_00065_35690_3196.N1						SS1	H/H	75	35690	65	4.07
ASA_WSM_1PNPDE20081227_103345_000003602075_00065_35690_3241.N1						SS1	H/H	75	35690	65	4.07
ASA_WSM_1PNPDE20081227_111513_000001902075_00066_35691_3245.N1						SS1	H/H	75	35691	66	4.07
ASA_WSM_1PNPDE20081227_111513_000002692075_00066_35691_3287.N1						SS1	H/H	75	35691	66	4.07
ASA_WSM_1PNPDE20081227_111924_000000182075_00066_35691_3229.N1						SS1	H/H	75	35691	66	4.07
ASA_WSM_1PNPDE20081227_120543_000003112075_00066_35691_3295.N1						SS1	H/H	75	35691	66	4.07
ASA_WSM_1PNPDE20081227_120656_000001762075_00066_35691_3248.N1						SS1	H/H	75	35691	66	4.07
ASA_WSM_1PNPDE20081227_134507_000001352075_00067_35692_3379.N1						SS1	H/H	75	35692	67	4.07
ASA_WSM_1PNPDE20081227_145005_000001902075_00068_35693_3381.N1						SS1	H/H	75	35693	68	4.07
ASA_WSM_1PNPDE20081227_153639_000001652075_00068_35693_3383.N1						SS1	H/H	75	35693	68	4.07
ASA_WSM_1PNPDE20081227_153752_000000922075_00068_35693_3369.N1						SS1	H/H	75	35693	68	4.07
ASA_WSM_1PNPDE20081227_160000_000001532075_00068_35693_3421.N1						SS1	V/V	75	35693	68	4.07
ASA_WSM_1PNPDE20081227_160546_000001902075_00069_35694_3385.N1						SS1	H/H	75	35694	69	4.07
ASA_WSM_1PNPDE20081227_163215_000001592075_00069_35694_3425.N1						SS1	H/H	75	35694	69	4.07
ASA_WSM_1PNPDE20081227_163430_000000242075_00069_35694_3417.N1						SS1	H/H	75	35694	69	4.07
ASA_WSM_1PNPDE20081227_171715_000002932075_00069_35694_3423.N1						SS1	H/H	75	35694	69	4.07
ASA_WSM_1PNPDE20081227_192323_000001522075_00071_35696_3498.N1						SS1	H/H	75	35696	71	4.07
ASA_WSM_1PNPDE20081227_194637_000001042075_00071_35696_3496.N1						SS1	H/H	75	35696	71	4.07
ASA_WSM_1PNPDE20081227_202558_000000732075_00071_35696_3457.N1						SS1	H/H	75	35696	71	4.07
ASA_WSM_1PNPDE20081227_203627_000002692075_00071_35696_3502.N1						SS1	H/H	75	35696	71	4.07
ASA_WSM_1PNPDE20081227_203740_000000612075_00071_35696_3471.N1						SS1	H/H	75	35696	71	4.07
ASA_WSM_1PNPDE20081227_203937_000000782075_00071_35696_3494.N1						SS1	H/H	75	35696	71	4.07
ASA_WSM_1PNPDE20081227_204943_000002752075_00071_35696_3500.N1						SS1	V/V	75	35696	71	4.07
ASA_WSM_1PNPDE20081227_212535_000000982075_00072_35697_3618.N1						SS1	H/H	75	35697	72	4.07
ASA_WSM_1PNPDE20081227_213349_000001152075_00072_35697_3616.N1						SS1	H/H	75	35697	72	4.07
ASA_WSM_1PNPDE20081227_221035_000000732075_00072_35697_3597.N1						SS1	H/H	75	35697	72	4.07
ASA_WSM_1PNPDE20081227_221535_000005502075_00072_35697_3652.N1						SS1	H/H	75	35697	72	4.07
ASA_WSM_1PNPDE20081227_231410_000001152075_00073_35698_3788.N1						SS1	H/H	75	35698	73	4.07
ASA_WSM_1PNPDE20081227_235111_000000732075_00073_35698_3751.N1						SS1	H/H	75	35698	73	4.07
ASA_WSM_1PNPDE20081227_235311_000000732075_00073_35698_3757.N1						SS1	H/H	75	35698	73	4.07
ASA_WSM_1PNPDE20081227_235311_000002992075_00073_35698_3882.N1						SS1	H/H	75	35698	73	4.07
ASA_WSM_1PNPDE20081227_235722_000000482075_00073_35698_3765.N1						SS1	H/H	75	35698	73	4.07
ASA_WSM_1PNPDE20081227_235939_000002922075_00073_35698_3790.N1						SS1	H/H	75	35698	73	4.07




Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WVS_1PNPDE20081226_235010_000010042075_00059_35684_2087.N1						IS2	V/V	75	35684	59	4.07
ASA_WVS_1PNPDE20081227_001435_000003752075_00059_35684_2092.N1						IS2	V/V	75	35684	59	4.07
ASA_WVS_1PNPDE20081227_003744_000004342075_00059_35684_2095.N1						IS2	V/V	75	35684	59	4.07
ASA_WVS_1PNPDE20081227_004359_000003892075_00059_35684_2211.N1						IS2	V/V	75	35684	59	4.07
ASA_WVS_1PNPDE20081227_003744_000004342075_00059_35684_2095.N1						IS1	V/V	75	35684	59	4.07
ASA_WVS_1PNPDE20081227_005402_000009592075_00059_35684_2221.N1						IS2	V/V	75	35684	59	4.07
ASA_WVS_1PNPDE20081227_013534_000001642075_00060_35685_2218.N1						IS2	V/V	75	35685	60	4.07
ASA_WVS_1PNPDE20081227_013921_000006592075_00060_35685_2224.N1						IS2	V/V	75	35685	60	4.07
ASA_WVS_1PNPDE20081227_015328_000004802075_00060_35685_2233.N1						IS2	V/V	75	35685	60	4.07
ASA_WVS_1PNPDE20081227_021820_000000602075_00060_35685_2236.N1						IS2	V/V	75	35685	60	4.07
ASA_WVS_1PNPDE20081227_021835_000003302075_00060_35685_2374.N1						IS2	V/V	75	35685	60	4.07
ASA_WVS_1PNPDE20081227_023839_000004192075_00061_35686_2379.N1						IS2	V/V	75	35686	61	4.07
ASA_WVS_1PNPDE20081227_032358_000006892075_00061_35686_2387.N1						IS2	V/V	75	35686	61	4.07
ASA_WVS_1PNPDE20081227_033513_000002552075_00061_35686_2491.N1						IS2	V/V	75	35686	61	4.07
ASA_WVS_1PNPDE20081227_040301_000006892075_00061_35686_2498.N1						IS2	V/V	75	35686	61	4.07
ASA_WVS_1PNPDE20081227_041617_000001792075_00062_35687_2511.N1						IS2	V/V	75	35687	62	4.07
ASA_WVS_1PNPDE20081227_050228_000009142075_00062_35687_2545.N1						IS2	V/V	75	35687	62	4.07
ASA_WVS_1PNPDE20081227_051728_000003152075_00062_35687_2690.N1						IS2	V/V	75	35687	62	4.07
ASA_WVS_1PNPDE20081227_053932_000015742075_00062_35687_2742.N1						IS2	V/V	75	35687	62	4.07
ASA_WVS_1PNPDE20081227_064717_000001192075_00063_35688_2729.N1						IS2	V/V	75	35688	63	4.07
ASA_WVS_1PNPDE20081227_065149_000003452075_00063_35688_2732.N1						IS2	V/V	75	35688	63	4.07
ASA_WVS_1PNPDK20081227_065719_000003602075_00063_35688_6495.N1						IS2	V/V	75	35688	63	4.07
ASA_WVS_1PNPDE20081227_065149_000003452075_00063_35688_2732.N1						IS1	V/V	75	35688	63	4.07
ASA_WVS_1PNPDK20081227_072008_000019642075_00063_35688_6507.N1						IS2	V/V	75	35688	63	4.07
ASA_WVS_1PNPDK20081227_083501_000005402075_00064_35689_6585.N1						IS2	V/V	75	35689	64	4.07
ASA_WVS_1PNPDK20081227_090044_000000452075_00064_35689_6582.N1						IS2	V/V	75	35689	64	4.07
ASA_WVS_1PNPDK20081227_090416_000018142075_00064_35689_6599.N1						IS2	V/V	75	35689	64	4.07
ASA_WVS_1PNPDK20081227_100712_000010342075_00065_35690_6714.N1						IS2	V/V	75	35690	65	4.07
ASA_WVS_1PNPDK20081227_104120_000018442075_00065_35690_6728.N1						IS2	V/V	75	35690	65	4.07
ASA_WVS_1PNPDK20081227_113036_000001052075_00066_35691_6827.N1						IS2	V/V	75	35691	66	4.07
ASA_WVS_1PNPDK20081227_113530_000017692075_00066_35691_6832.N1						IS2	V/V	75	35691	66	4.07
ASA_WVS_1PNPDK20081227_122434_000001952075_00066_35691_6837.N1						IS2	V/V	75	35691	66	4.07
ASA_WVS_1PNPDK20081227_123336_000010002075_00066_35691_6847.N1						IS2	V/V	75	35691	66	4.07
ASA_WVS_1PNPDK20081227_131236_000008692075_00067_35692_6980.N1						IS2	V/V	75	35692	67	4.07
ASA_WVS_1PNPDK20081227_140231_000004202075_00067_35692_6985.N1						IS2	V/V	75	35692	67	4.07
ASA_WVS_1PNPDK20081227_141454_000001942075_00067_35692_6988.N1						IS2	V/V	75	35692	67	4.07
ASA_WVS_1PNPDK20081227_141953_000002242075_00068_35693_6998.N1						IS2	V/V	75	35693	68	4.07
ASA_WVS_1PNPDK20081227_145902_000005842075_00068_35693_7089.N1						IS2	V/V	75	35693	68	4.07
ASA_WVS_1PNPDK20081227_151141_000007342075_00068_35693_7096.N1						IS2	V/V	75	35693	68	4.07
ASA_WVS_1PNPDK20081227_154307_000009742075_00068_35693_7101.N1						IS2	V/V	75	35693	68	4.07
ASA_WVS_1PNPDK20081227_160230_000001492075_00069_35694_7104.N1						IS2	V/V	75	35694	69	4.07
ASA_WVS_1PNPDK20081227_164555_000012592075_00069_35694_7157.N1						IS2	V/V	75	35694	69	4.07
ASA_WVS_1PNPDK20081227_172343_000013792075_00069_35694_7169.N1						IS2	V/V	75	35694	69	4.07
ASA_WVS_1PNPDK20081227_182122_000013042075_00070_35695_7240.N1						IS2	V/V	75	35695	70	4.07
ASA_WVS_1PNPDK20081227_190419_000000602075_00070_35695_7208.N1						IS2	V/V	75	35695	70	4.07
ASA_WVS_1PNPDK20081227_190737_000003452075_00070_35695_7235.N1						IS2	V/V	75	35695	70	4.07
ASA_WVS_1PNPDK20081227_191743_000001642075_00070_35695_7220.N1						IS2	V/V	75	35695	70	4.07
ASA_WVS_1PNPDE20081227_195512_000017992075_00071_35696_3434.N1						IS2	V/V	75	35696	71	4.07
ASA_WVS_1PNPDE20081227_204455_000000142075_00071_35696_3442.N1						IS2	V/V	75	35696	71	4.07
ASA_WVS_1PNPDE20081227_204455_000002402075_00071_35696_3509.N1						IS2	V/V	75	35696	71	4.07
ASA_WVS_1PNPDE20081227_204455_000000142075_00071_35696_3442.N1						IS1	V/V	75	35696	71	4.07
ASA_WVS_1PNPDE20081227_213543_000019792075_00072_35697_3516.N1						IS2	V/V	75	35697	72	4.07
ASA_WVS_1PNPDE20081227_222522_000004042075_00072_35697_3526.N1						IS2	V/V	75	35697	72	4.07
ASA_WVS_1PNPDE20081227_223107_000007042075_00072_35697_3645.N1						IS2	V/V	75	35697	72	4.07
ASA_WVS_1PNPDE20081227_222522_000004042075_00072_35697_3526.N1						IS1	V/V	75	35697	72	4.07
ASA_WVS_1PNPDE20081227_225028_000004942075_00073_35698_3650.N1						IS2	V/V	75	35698	73	4.07
ASA_WVS_1PNPDE20081227_231607_000013042075_00073_35698_3666.N1						IS2	V/V	75	35698	73	4.07
ASA_WVS_1PNPDE20081227_234407_000003152075_00073_35698_3663.N1						IS2	V/V	75	35698	73	4.07







































































27-Dec




27-Dec




27-Dec




27-Dec




27-Dec




27-Dec







27-Dec




27-Dec




27-Dec



27-Dec



27-Dec



27-Dec

