



Analysis from 06-NOV-2009 00:00:00 to 06-NOV-2009 23:59:59. Page generated on 07-NOV-2009 08:34:22.
View log file: ASAR_Daily_Report_20091107_0831.log. For any anomalies please contact emma.griffiths@vega.co.uk.

This report is automatically generated every day, every 2 hours. No comments are provided on the results.

SUMMARY

1. DATA SUMMARY

- 1.1 Summary tables
- 1.2 Lists of products used

2. AUXILIARY FILES ANALYSIS

- 2.1 IECF operational ADFs list
- 2.2 Products with wrong ADFs

3. MODULE STEPPING PRODUCTS ANALYSIS

- 3.1 V/V polarisation
- 3.2 H/H polarisation

4. CALIBRATION PULSES ANALYSIS

- 4.1 Analysis for WVS IS2 V/V
 - 4.1.1 Temporal Evolution Analysis for WVS IS2 V/V
 - 4.1.2 All Rows Analysis for WVS IS2 V/V
- 4.2 Analysis for GM1 SS3 H/H
 - 4.2.1 Temporal Evolution Analysis for GM1 SS3 H/H
 - 4.2.2 All Rows Analysis for GM1 SS3 H/H

5. DOPPLER ANALYSIS

- 5.1 Analysis for WVS IS2 V/V
 - 5.1.1 Doppler MAP Analysis for WVS IS2 V/V
 - 5.1.2 Doppler ANX Analysis for WVS IS2 V/V
- 5.2 Analysis for GM1 SS1 H/H
 - 5.2.1 Doppler MAP Analysis for GM1 SS1 H/H
 - 5.2.2 Doppler ANX Analysis for GM1 SS1 H/H
- 5.3 Doppler JUMPS Analysis for WSM

6. CHIRP ANALYSIS

- 6.1 Analysis for WSM SS1 H/H
 - 6.1.1 ScaleFactor
- 6.2 Analysis for WSM SS1 V/V
 - 6.2.1 ScaleFactor

7. RAW DATA ANALYSIS

- 7.1 Analysis for WVS
- 7.2 Analysis for IMM

8. TELEMETRY ANALYSIS

- 8.1 Number of Missing Lines
- 8.2 Number of Gaps

1 - DATA SUMMARY

1.1 - Summary tables

[[BACK TO MENU](#)]

WVS				GM1				APM				IMM				WSM				MS			
Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Time	Pol	Modules
PDE	IS1	V/V	2	PDE	WS	H/H	34	PDE	IS3	V/H	1	PDE	IS2	H/H	3	PDE	WS	H/H	48	PDK	2009-11-06 05:54:58	V	320
PDE	IS2	V/V	23	PDK	WS	H/H	48	PDE	IS7	H/H	1	PDE	IS2	V/V	14	PDE	WS	V/V	11				
PDK	IS2	V/V	27									PDE	IS3	V/V	1	PDK	WS	H/H	11				
												PDE	IS4	V/V	1	PDK	WS	V/V	3				
												PDE	IS5	H/H	1								
												PDE	IS5	V/V	1								
												PDK	IS2	V/V	4								

1.2 - Lists of products used

[[BACK TO MENU](#)]

[TXT] [XLS] [List_WVS_products_used](#)
 [TXT] [XLS] [List_GM1_products_used](#)
 [TXT] [XLS] [List_APM_products_used](#)
 [TXT] [XLS] [List_IMM_products_used](#)
 [TXT] [XLS] [List_WSM_products_used](#)
 [TXT] [XLS] [List_MS_products_used](#)

2 - AUXILIARY FILES ANALYSIS

2.1 - IECF operational ADFs list

[[BACK TO MENU](#)]

ADFs disseminated for ASAR
ASA_CON_AXVIEC20081215_141339_20070204_165113_20091231_000000
ASA_INS_AXVIEC20090525_114808_20090428_100000_20091231_235959
ASA_XCH_AXVIEC20081215_143642_20020301_000000_20091231_000000
ASA_XCA_AXVIEC20090311_104501_20080801_000000_20091231_235959

2.2 - Products with wrong ADFs

[[BACK TO MENU](#)]

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
WVS	0	0	0	0
GM1	0	0	0	0
APM	0	0	0	0
IMM	0	0	0	0
WSM	0	0	0	0

[TXT] [XLS] [Check_ADFs_WVS](#)
 [TXT] [XLS] [Check_ADFs_GM1](#)
 [TXT] [XLS] [Check_ADFs_APM](#)
 [TXT] [XLS] [Check_ADFs_IMM](#)
 [TXT] [XLS] [Check_ADFs_WSM](#)

3 - MODULE STEPPING PRODUCTS ANALYSIS

SECOND FIXED REFERENCE	PREVIOUS PRODUCT REFERENCE
After antenna maintenance (2005-09-22/23)	Previous product in the same polarisation
<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>

3.2 - H/H polarisation

[BACK TO MENU]

SECOND FIXED REFERENCE	PREVIOUS PRODUCT REFERENCE
After antenna maintenance (2005-09-22/23)	Previous product in the same polarisation
<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>

4 - CALIBRATION PULSES ANALYSIS

4.1 - Analysis for WVS IS2 V/V

4.1.1 - Temporal Evolution Analysis for WVS IS2 V/V

[BACK TO MENU]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32] <input type="checkbox"/>	Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32] <input type="checkbox"/>
---	---

4.1.2 - All Rows Analysis for WVS IS2 V/V

[BACK TO MENU]



4.2 - Analysis for GM1 SS3 H/H

4.2.1 - Temporal Evolution Analysis for GM1 SS3 H/H

[BACK TO MENU]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32] <input type="checkbox"/>	Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32] <input type="checkbox"/>
---	---

4.2.2 - All Rows Analysis for GM1 SS3 H/H

[BACK TO MENU]



5 - DOPPLER ANALYSIS

5.1 - Analysis for WVS IS2 V/V

5.1.1 - Doppler MAP Analysis for WVS IS2 V/V

[BACK TO MENU]



5.1.2 - Doppler ANX Analysis for WVS IS2 V/V

[BACK TO MENU]



5.2 - Analysis for GM1 SS1 H/H

5.2.1 - Doppler MAP Analysis for GM1 SS1 H/H

[BACK TO MENU]



5.2.2 - Doppler ANX Analysis for GM1 SS1 H/H

[BACK TO MENU]



5.3 - Doppler JUMPS Analysis for WSM

[BACK TO MENU]



6 - CHIRP ANALYSIS

6.1 - Analysis for WSM SS1 H/H

6.1.1 - ScaleFactor

[BACK TO MENU]



6.2 - Analysis for WSM SS1 V/V

6.2.1 - ScaleFactor



7 - RAW DATA ANALYSIS

7.1 - Analysis for WVS

☒		
Channel	Statistics	DSS-B
MEAN I	mean	0.000484760
	stdev	2.27099e-07
MEAN Q	mean	0.000497180
	stdev	2.39238e-07
Channel	Statistics	DSS-B
STDEV I	mean	0.131827
	stdev	0.00117418
STDEV Q	mean	0.132158
	stdev	0.00119197

7.2 - Analysis for IMM

☒		
Channel	Statistics	DSS-B
MEAN I	mean	0.000295537
	stdev	4.90652e-09
MEAN Q	mean	0.000559872
	stdev	5.15774e-09
Channel	Statistics	DSS-B
STDEV I	mean	0.0726775
	stdev	0.00120437
STDEV Q	mean	0.0729714
	stdev	0.00121694

8 - TELEMETRY ANALYSIS

Processing Center	Product	Gaps	Missing lines
PDE	ASA_IMM_1PNPDE20091106_054344_000000372084_00048_40182_8840.N1	1	0
PDE	ASA_WSM_1PNPDE20091106_181655_000001652084_00056_40190_9141.N1	0	29

8.1 - Number of Missing lines



8.2 - Number of Gaps



ASAR Daily Report V1.00

Document Reference: OSME-DPQC-SEDA-RP-06-0348/0349

Contract Reference: ESA/Esrin 19049/05/1-OL

All rights reserved to Serco S.p.A., Via XX Settembre, 1 - 00187 Roma - Italy.

In particular, but not limited to:

(a) Modification, reverse engineering or distribution is not permitted in any form.

(b) Usage is restricted to Serco S.p.A. employee belonging to the above Contract Reference.

Any deviation from above rules requires an explicit prior written authorisation of Serco S.p.A.

ASAR DAILY REPORT for 091106
#####

MODE: DAILY
ANALYSIS: ALL
DATE: YESTERDAY

Analysis will be performed from 2009-11-06 00:00:00 to 2009-11-06 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/091106/

DATA SUMMARY

Summary will be performed from 2009-11-06 00:00:00 to 2009-11-06 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/091106/DATA_SUMMARY

Creating directory ./RESULTS/DAILY/091106/DATA_SUMMARY...
Writing file ./RESULTS/DAILY/091106/DATA_SUMMARY/Data_summary.html...

Getting WVS products list from 2009-11-06 00:00:00 to 2009-11-06 23:59:59...
Writing file ./RESULTS/DAILY/091106/DATA_SUMMARY/List_WVS_products_used.xls...
Writing file ./RESULTS/DAILY/091106/DATA_SUMMARY/List_WVS_products_used.txt...

Getting GM1 products list from 2009-11-06 00:00:00 to 2009-11-06 23:59:59...
Writing file ./RESULTS/DAILY/091106/DATA_SUMMARY/List_GM1_products_used.xls...
Writing file ./RESULTS/DAILY/091106/DATA_SUMMARY/List_GM1_products_used.txt...

Getting APM products list from 2009-11-06 00:00:00 to 2009-11-06 23:59:59...
Writing file ./RESULTS/DAILY/091106/DATA_SUMMARY/List_APM_products_used.xls...
Writing file ./RESULTS/DAILY/091106/DATA_SUMMARY/List_APM_products_used.txt...

Getting IMM products list from 2009-11-06 00:00:00 to 2009-11-06 23:59:59...
Writing file ./RESULTS/DAILY/091106/DATA_SUMMARY/List_IMM_products_used.xls...
Writing file ./RESULTS/DAILY/091106/DATA_SUMMARY/List_IMM_products_used.txt...

Getting WSM products list from 2009-11-06 00:00:00 to 2009-11-06 23:59:59...
Writing file ./RESULTS/DAILY/091106/DATA_SUMMARY/List_WSM_products_used.xls...
Writing file ./RESULTS/DAILY/091106/DATA_SUMMARY/List_WSM_products_used.txt...

Getting MS products list from 2009-11-06 00:00:00 to 2009-11-06 23:59:59...
Writing file ./RESULTS/DAILY/091106/DATA_SUMMARY/List_MS_products_used.xls...
Writing file ./RESULTS/DAILY/091106/DATA_SUMMARY/List_MS_products_used.txt...

DATA SUMMARY completed
#####

AUXILIARY FILES ANALYSIS

Analysis will be performed from 2009-11-06 00:00:00 to 2009-11-06 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/091106/AUXILIARY

Creating directory ./RESULTS/DAILY/091106/AUXILIARY...

Looking for the IECF operational ADFs list...



ADF filter 20091106*current_3_IECF_ADFs.txt
 Found list 20091106_030002_current_3_IECF_ADFs.txt...
 Extracting ADFs...

ASA_CON_AXVIEC20081215_141339_20070204_165113_20091231_000000
 ASA_INS_AXVIEC20090525_114808_20090428_100000_20091231_235959
 ASA_XCH_AXVIEC20081215_143642_20020301_000000_20091231_000000
 ASA_XCA_AXVIEC20090311_104501_20080801_000000_20091231_235959

Writing file ./RESULTS/DAILY/091106/AUXILIARY/ASAR_ADFs_IECF_List3.html...
 Writing file ./RESULTS/DAILY/091106/AUXILIARY/Auxiliary_files_summary.html...

Analysing WVS products...

Writing file ./RESULTS/DAILY/091106/AUXILIARY/Check_ADFs_WVS.xls...
 Writing file ./RESULTS/DAILY/091106/AUXILIARY/Check_ADFs_WVS.txt...

ASA_WVS_1PNPDE20091106_002125_000010412084_00045_40179_8593.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091106_004535_000003302084_00045_40179_8600.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091106_011037_000001192084_00045_40179_8603.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091106_011137_000004052084_00045_40179_8657.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091106_012639_000007942084_00046_40180_8668.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091106_021053_000011242084_00046_40180_8685.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091106_024943_000002852084_00046_40180_8731.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091106_030958_000001942084_00047_40181_8745.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091106_035146_000009142084_00047_40181_8742.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091106_040645_000001652084_00047_40181_8823.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091106_043028_000012442084_00047_40181_8838.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091106_053141_000005092084_00048_40182_8849.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091106_054220_000000442084_00048_40182_8843.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091106_054427_000002702084_00048_40182_8846.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091106_202725_000019342084_00057_40191_9185.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091106_211625_000002252084_00057_40191_9180.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091106_211910_000000902084_00057_40191_9225.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091106_220910_000018592084_00058_40192_9230.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091106_225815_000002852084_00058_40192_9233.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091106_230200_000008692084_00058_40192_9297.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091106_231838_000006742084_00059_40193_9302.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091106_235005_000007492084_00059_40193_9307.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091106_054827_000001502084_00048_40182_0337.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091106_055304_000000752084_00048_40182_9969.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091106_061104_000019492084_00048_40182_9974.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091106_073048_000001502084_00049_40183_9998.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091106_075140_000018742084_00049_40183_0005.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091106_090041_000008092084_00050_40184_0043.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091106_093216_000020092084_00050_40184_0052.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091106_103841_000010492084_00051_40185_0082.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091106_111252_000001952084_00051_40185_0085.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091106_111832_000016342084_00051_40185_0092.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091106_120326_000003002084_00052_40186_0116.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091106_120958_000005992084_00052_40186_0119.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091106_122920_000004352084_00052_40186_0126.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091106_125328_000003152084_00052_40186_0131.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091106_130610_000005692084_00052_40186_0136.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091106_131642_000001642084_00053_40187_0139.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091106_134532_000007192084_00053_40187_0175.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091106_141300_000002552084_00053_40187_0184.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091106_143404_000003902084_00053_40187_0187.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091106_144507_000004792084_00053_40187_0194.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091106_153420_000001342084_00054_40188_0230.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091106_153845_000011392084_00054_40188_0237.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091106_161802_000010342084_00054_40188_0242.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091106_171533_000013792084_00055_40189_0271.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091106_175748_000011092084_00055_40189_0280.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091106_184920_000017842084_00056_40190_0302.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK



ASA_WVS_1PNPDK20091106_193920_000003902084_00056_40190_0309.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

Analysing GM1 products...

Writing file ./RESULTS/DAILY/091106/AUXILIARY/Check_ADFs_GM1.xls...

Writing file ./RESULTS/DAILY/091106/AUXILIARY/Check_ADFs_GM1.txt...

ASA_GM1_1PNPDE20091106_000857_000006402084_00045_40179_8584.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091106_003929_000003622084_00045_40179_8597.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091106_005142_000001022084_00045_40179_8595.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091106_005606_000004712084_00045_40179_8605.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091106_012040_000003382084_00045_40179_8654.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091106_014031_000012452084_00046_40180_8689.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091106_020339_000001202084_00046_40180_8659.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091106_020642_000000962084_00046_40180_8665.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091106_020923_000000722084_00046_40180_8682.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091106_023801_000004162084_00046_40180_8728.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091106_025507_000001202084_00046_40180_8739.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091106_025711_000002772084_00046_40180_8737.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091106_030235_000001322084_00046_40180_8733.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091106_030816_000001022084_00047_40181_8726.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091106_031357_000008152084_00047_40181_8735.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091106_032822_000008392084_00047_40181_8749.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091106_034548_000003562084_00047_40181_8747.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091106_041723_000004772084_00047_40181_8831.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091106_042902_000000842084_00047_40181_8829.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091106_045159_000001082084_00048_40182_8827.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091106_045716_000003442084_00048_40182_8825.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091106_050415_000013712084_00048_40182_8872.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091106_051945_000004412084_00048_40182_8835.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091106_052825_000001932084_00048_40182_8851.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091106_200630_000000782084_00057_40191_9177.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091106_201220_000007062084_00057_40191_9182.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091106_210323_000004892084_00057_40191_9187.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091106_212451_000011232084_00057_40191_9237.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091106_214021_000001932084_00057_40191_9222.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091106_215133_000002112084_00058_40192_9218.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091106_215752_000003622084_00058_40192_9227.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091106_224413_000006282084_00058_40192_9235.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091106_231707_000000902084_00059_40193_9339.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091106_233607_000007312084_00059_40193_9304.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091106_055914_000007062084_00048_40182_9971.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091106_064849_000004712084_00049_40183_9976.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091106_065820_000005252084_00049_40183_9991.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091106_071226_000000962084_00049_40183_9993.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091106_071643_000005732084_00049_40183_9995.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091106_073736_0000108392084_00049_40183_0000.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091106_082501_000007312084_00050_40184_0002.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091106_083556_000002592084_00050_40184_0034.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091106_084238_000000722084_00050_40184_0036.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091106_085054_000001872084_00050_40184_0038.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091106_085913_000000842084_00050_40184_0040.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091106_091834_000008212084_00050_40184_0045.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091106_100625_000002592084_00051_40185_0047.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091106_101252_000001812084_00051_40185_0049.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091106_101437_000001022084_00051_40185_0075.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091106_101848_000001082084_00051_40185_0073.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091106_102543_000001082084_00051_40185_0077.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091106_103216_000001022084_00051_40185_0079.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091106_110041_000007312084_00051_40185_0087.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091106_114626_000002472084_00052_40186_0089.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091106_115407_000001022084_00052_40186_0121.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091106_123723_000000782084_00052_40186_0123.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091106_124222_000006642084_00052_40186_0128.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091106_125923_000004042084_00052_40186_0133.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

ASA_GM1_1PNPDK20091106_132012_000007062084_00053_40187_0141.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091106_133754_000003442084_00053_40187_0172.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091106_135812_000002472084_00053_40187_0170.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091106_140400_000003742084_00053_40187_0177.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091106_141023_000001572084_00053_40187_0179.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091106_141759_000001572084_00053_40187_0181.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091106_142323_000006402084_00053_40187_0189.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091106_144111_000002352084_00053_40187_0191.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091106_145354_000010622084_00054_40188_0200.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091106_152140_000007552084_00054_40188_0227.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091106_153712_000000902084_00054_40188_0232.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091106_155835_000000842084_00054_40188_0234.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091106_160340_000006582084_00054_40188_0239.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091106_163601_000008632084_00055_40189_0244.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091106_170137_000008332084_00055_40189_0266.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091106_174404_000001202084_00055_40189_0268.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091106_174706_000002652084_00055_40189_0273.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091106_181944_000002112084_00056_40190_0275.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091106_182550_000001872084_00056_40190_0277.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091106_182729_000002232084_00056_40190_0297.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091106_183607_000006222084_00056_40190_0299.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091106_192412_000006942084_00056_40190_0306.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091106_195028_000006762084_00056_40190_0304.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091106_200539_000001262084_00057_40191_0311.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

Analysing APM products...

Writing file ./RESULTS/DAILY/091106/AUXILIARY/Check_ADFs_APM.xls...

Writing file ./RESULTS/DAILY/091106/AUXILIARY/Check_ADFs_APM.txt...

ASA_APM_1PNPDE20091106_020820_000000412084_00046_40180_8687.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20091106_174603_000000402084_00055_40189_9103.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

Analysing IMM products...

Writing file ./RESULTS/DAILY/091106/AUXILIARY/Check_ADFs_IMM.xls...

Writing file ./RESULTS/DAILY/091106/AUXILIARY/Check_ADFs_IMM.txt...

ASA_IMM_1PNPDE20091106_000457_000000632084_00045_40179_8623.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091106_000457_000002292084_00045_40179_8697.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091106_000700_000001062084_00045_40179_8674.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091106_020115_000001332084_00046_40180_8695.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091106_020539_000000532084_00046_40180_8691.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091106_030147_000000372084_00046_40180_8751.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091106_030710_000000562084_00047_40181_8755.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091106_032732_000000372084_00047_40181_8753.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091106_045346_000001992084_00048_40182_8908.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091106_050257_000000622084_00048_40182_8810.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091106_052707_000000682084_00048_40182_8878.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091106_054344_000000372084_00048_40182_8840.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091106_070707_000001312084_00049_40183_8898.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091106_071403_000001502084_00049_40183_8914.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091106_111646_000000992084_00051_40185_9006.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091106_120900_000000532084_00052_40186_9004.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091106_184630_000001632084_00056_40190_9147.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091106_202408_000001912084_00057_40191_9216.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091106_214525_000000372084_00058_40192_9192.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091106_215500_000001602084_00058_40192_9276.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091106_234815_000000422084_00059_40193_9333.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20091106_064432_000002422084_00049_40183_9989.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20091106_082333_000000592084_00050_40184_0013.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20091106_084351_000001792084_00050_40184_0028.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK



ASA_IMM_1PNPDK20091106_102455_00000372084_00051_40185_0058.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

Analysing WSM products...

Writing file ./RESULTS/DAILY/091106/AUXILIARY/Check_ADFs_WSM.xls...

Writing file ./RESULTS/DAILY/091106/AUXILIARY/Check_ADFs_WSM.txt...

ASA_WSM_1PNPDE20091106_000209_000001342084_00045_40179_8702.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_001954_000000922084_00045_40179_8652.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_002108_000000182084_00045_40179_8633.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_005331_000001522084_00045_40179_8693.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_010403_000002752084_00045_40179_8800.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_010906_000000732084_00045_40179_8635.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_010906_000000912084_00045_40179_8672.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_023018_000001342084_00046_40180_8761.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_023018_000004582084_00046_40180_8853.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_023327_000002692084_00046_40180_8762.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_024501_000002752084_00046_40180_8859.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_034226_000001892084_00047_40181_8788.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_041348_000002132084_00047_40181_8910.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_041602_000000792084_00047_40181_8812.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_042526_000002132084_00047_40181_8870.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_054051_000000732084_00048_40182_8818.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_054051_000000912084_00048_40182_8912.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_055135_000000912084_00048_40182_8874.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_055630_000001582084_00048_40182_8876.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_065646_000000912084_00049_40183_8906.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_072618_000002682084_00049_40183_8926.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_073401_000002132084_00049_40183_8990.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_073514_000001392084_00049_40183_8946.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_085404_000003062084_00050_40184_8948.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_091459_000002142084_00050_40184_8974.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_101047_000001212084_00051_40185_8986.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_102042_000000922084_00051_40185_8972.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_103401_000002812084_00051_40185_9002.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_105731_000001822084_00051_40185_8988.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_115040_000001892084_00052_40186_9008.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_122037_000005252084_00052_40186_9028.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_134341_000001092084_00053_40187_9077.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_140225_000000912084_00053_40187_9095.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_142039_000001582084_00053_40187_9101.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_151929_000001292084_00054_40188_9079.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_160005_000001352084_00054_40188_9087.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_160005_000001902084_00054_40188_9105.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_161531_000001532084_00054_40188_9075.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_165032_000000912084_00055_40189_9081.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_165758_000001212084_00055_40189_9133.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_173928_000002692084_00055_40189_9143.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_175133_000001902084_00055_40189_9131.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_181655_000001652084_00056_40190_9141.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_182316_000000732084_00056_40190_9119.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_182316_000001532084_00056_40190_9145.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_182531_000000182084_00056_40190_9123.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_192037_000002082084_00056_40190_9173.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_193648_000001532084_00056_40190_9171.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_194632_000002322084_00056_40190_9175.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_210048_000001532084_00057_40191_9241.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_211136_000001352084_00057_40191_9343.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_211136_000002872084_00057_40191_9379.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_211446_000000962084_00057_40191_9344.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_212116_000002132084_00057_40191_9239.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_220358_000001342084_00058_40192_9280.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_220358_000003112084_00058_40192_9381.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_224138_000001472084_00058_40192_9337.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091106_225444_000002142084_00058_40192_9278.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

```
ASA_WSM_1PNPDE20091106_233032_000001712084_00059_40193_9456.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20091106_070932_000001702084_00049_40183_0030.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20091106_084018_000001342084_00050_40184_0032.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20091106_101621_000001342084_00051_40185_0069.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20091106_102042_000001902084_00051_40185_0071.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20091106_115553_000004522084_00052_40186_0113.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20091106_123846_000002142084_00052_40186_0168.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20091106_133204_000003482084_00053_40187_0166.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20091106_151138_000002142084_00054_40188_0223.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20091106_151556_000003062084_00054_40188_0225.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20091106_165233_000003602084_00055_40189_0264.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20091106_183117_000002872084_00056_40190_0295.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20091106_200750_000001222084_00057_40191_0324.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20091106_201026_000001092084_00057_40191_0326.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20091106_233311_000001712084_00059_40193_0334.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```

AUXILIARY FILES ANALYSIS completed

#####

MODULE STEPPING ANALYSIS

#####

Analysis will be performed from 2009-11-06 00:00:00 to 2009-11-06 23:59:59

Results will be exported to the directory: ./RESULTS/DAILY/091106/MODULE_STEPPING

Creating directory ./RESULTS/DAILY/091106/MODULE_STEPPING...

Creating directory ./RESULTS/DAILY/091106/MODULE_STEPPING/FIRST_REFERENCE...

Creating directory ./RESULTS/DAILY/091106/MODULE_STEPPING/SECOND_REFERENCE...

Creating directory ./RESULTS/DAILY/091106/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE...

Deleting old files...

Creating images comparing with second reference...

Exporting results to the directory ../../RESULTS/DAILY/091106/MODULE_STEPPING/SECOND_REFERENCE...

Polarization: H

Reference product: ASA_MS_0PNPDK20050922_062651_00000152041_00034_18625_0041.N1

Test product: ASA_MS_0PNPDK20091105_062635_00000162084_00034_40168_0909.N1

H

H

../../RESULTS/DAILY/091106/MODULE_STEPPING/SECOND_REFERENCE/TGH_20091105_062635-20050922_062651.png

../../RESULTS/DAILY/091106/MODULE_STEPPING/SECOND_REFERENCE/TPH_20091105_062635-20050922_062651.png

../../RESULTS/DAILY/091106/MODULE_STEPPING/SECOND_REFERENCE/RGH_20091105_062635-20050922_062651.png

../../RESULTS/DAILY/091106/MODULE_STEPPING/SECOND_REFERENCE/RPH_20091105_062635-20050922_062651.png

Polarization: V

Reference product: ASA_MS_0PNPDK20050923_055514_00000152041_00048_18639_0042.N1

Test product: ASA_MS_0PNPDK20091106_055458_00000162084_00048_40182_0910.N1

V

V

../../RESULTS/DAILY/091106/MODULE_STEPPING/SECOND_REFERENCE/TGV_20091106_055458-20050923_055514.png

../../RESULTS/DAILY/091106/MODULE_STEPPING/SECOND_REFERENCE/TPV_20091106_055458-20050923_055514.png

../../RESULTS/DAILY/091106/MODULE_STEPPING/SECOND_REFERENCE/RGV_20091106_055458-20050923_055514.png

../../RESULTS/DAILY/091106/MODULE_STEPPING/SECOND_REFERENCE/RPV_20091106_055458-20050923_055514.png

Creating images comparing with previous product reference...

Exporting results to the directory ../../RESULTS/DAILY/091106/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE...

Polarization: H

Reference product: ASA_MS_0PNPDK20091103_173325_00000162084_00012_40146_0907.N1

Test product: ASA_MS__0PNPDK20091105_062635_000000162084_00034_40168_0909.N1

H
H

../../../../RESULTS/DAILY/091106/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TGH_20091105_062635-20091103_173325.png
../../../../RESULTS/DAILY/091106/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TPH_20091105_062635-20091103_173325.png
../../../../RESULTS/DAILY/091106/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RGH_20091105_062635-20091103_173325.png
../../../../RESULTS/DAILY/091106/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RPH_20091105_062635-20091103_173325.png

Polarization: V

Reference product: ASA_MS__0PNPDK20091104_170147_000000162084_00026_40160_0908.N1

Test product: ASA_MS__0PNPDK20091106_055458_000000162084_00048_40182_0910.N1

V
V

../../../../RESULTS/DAILY/091106/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TGV_20091106_055458-20091104_170147.png
../../../../RESULTS/DAILY/091106/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TPV_20091106_055458-20091104_170147.png
../../../../RESULTS/DAILY/091106/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RGV_20091106_055458-20091104_170147.png
../../../../RESULTS/DAILY/091106/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RPV_20091106_055458-20091104_170147.png

MODULE_STEPPING ANALYSIS completed

#####

CALIBRATION PULSES ANALYSIS

#####

Creating directory ./RESULTS/DAILY/091106/CALIBRATION_PULSES...

ALL ROWS Analysis will be performed from 2009-11-06 00:00:00 to 2009-11-06 23:59:59

Analysing products WVS IS2 V/V

Writing image ../../RESULTS/DAILY/091106//CALIBRATION_PULSES/Calibration_pulses_all_rows_WVS_IS2_VV.png...

Analysing products GM1 SS3 H/H

Writing image ../../RESULTS/DAILY/091106//CALIBRATION_PULSES/Calibration_pulses_all_rows_GM1_SS3_HH.png...

TEMPORAL EVOLUTION Analysis will be performed from 2009-11-06 00:00:00 to 2009-11-06 23:59:59

Analysing products WVS IS2 V/V

Getting calibration pulses data for WVS IS2 V/V from 2009-11-06 00:00:00 to 2009-11-06 23:59:59. Rows: 1/5/9/13/17/21/25/29

Writing file ./RESULTS/DAILY/091106/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2009-11-06_1.dat...

Writing ../../RESULTS/DAILY/091106//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_1.png...

Writing ../../RESULTS/DAILY/091106//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_1.png...

Getting calibration pulses data for WVS IS2 V/V from 2009-11-06 00:00:00 to 2009-11-06 23:59:59. Rows: 2/6/10/14/18/22/26/30

Writing file ./RESULTS/DAILY/091106/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2009-11-06_2.dat...

Writing ../../RESULTS/DAILY/091106//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_2.png...

Writing ../../RESULTS/DAILY/091106//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_2.png...

Getting calibration pulses data for WVS IS2 V/V from 2009-11-06 00:00:00 to 2009-11-06 23:59:59. Rows: 3/7/11/15/19/23/27/31

Writing file ./RESULTS/DAILY/091106/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2009-11-06_3.dat...

Writing ../../RESULTS/DAILY/091106//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_3.png...

Writing ../../RESULTS/DAILY/091106//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_3.png...

Getting calibration pulses data for WVS IS2 V/V from 2009-11-06 00:00:00 to 2009-11-06 23:59:59. Rows: 4/8/12/16/20/24/28/32

Writing file ./RESULTS/DAILY/091106/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2009-11-06_4.dat...

Writing ../../RESULTS/DAILY/091106//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_4.png...

Writing ../../RESULTS/DAILY/091106//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_4.png...

Analysing products GM1 SS3 H/H
Getting calibration pulses data for GM1 SS3 H/H from 2009-11-06 00:00:00 to 2009-11-06 23:59:59. Rows: 1/5/9/13/17/21/25/29
Writing file ./RESULTS/DAILY/091106/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2009-11-06_1.dat...
Writing ../../RESULTS/DAILY/091106//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_1.png...
Writing ../../RESULTS/DAILY/091106//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_1.png...

Getting calibration pulses data for GM1 SS3 H/H from 2009-11-06 00:00:00 to 2009-11-06 23:59:59. Rows: 2/6/10/14/18/22/26/30
Writing file ./RESULTS/DAILY/091106/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2009-11-06_2.dat...
Writing ../../RESULTS/DAILY/091106//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_2.png...
Writing ../../RESULTS/DAILY/091106//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_2.png...

Getting calibration pulses data for GM1 SS3 H/H from 2009-11-06 00:00:00 to 2009-11-06 23:59:59. Rows: 3/7/11/15/19/23/27/31
Writing file ./RESULTS/DAILY/091106/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2009-11-06_3.dat...
Writing ../../RESULTS/DAILY/091106//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_3.png...
Writing ../../RESULTS/DAILY/091106//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_3.png...

Getting calibration pulses data for GM1 SS3 H/H from 2009-11-06 00:00:00 to 2009-11-06 23:59:59. Rows: 4/8/12/16/20/24/28/32
Writing file ./RESULTS/DAILY/091106/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2009-11-06_4.dat...
Writing ../../RESULTS/DAILY/091106//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_4.png...
Writing ../../RESULTS/DAILY/091106//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_4.png...

CALIBRATION PULSES ANALYSIS completed
#####

DOPPLER ANALYSIS

Creating directory ./RESULTS/DAILY/091106/DOPPLER...

DOPPLER ANX Analysis will be performed from 2009-11-06 00:00:00 to 2009-11-06 23:59:59

Analysing products WVS IS2 V/V
Getting doppler data for WVS IS2 V/V from 2009-11-06 00:00:00 to 2009-11-06 23:59:59...
Writing file ./RESULTS/DAILY/091106/DOPPLER/Doppler_data_WVS_IS2_VV_2009-11-06.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/091106/DOPPLER/DOPPLER_ANX_WVS_IS2_VV.png...

Analysing products GM1 SS1 H/H
Getting doppler data for GM1 SS1 H/H from 2009-11-06 00:00:00 to 2009-11-06 23:59:59...
Writing file ./RESULTS/DAILY/091106/DOPPLER/Doppler_data_GM1_SS1_HH_2009-11-06.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/091106/DOPPLER/DOPPLER_ANX_GM1_SS1_HH.png...

DOPPLER JUMPS Analysis will be performed on WSM products from 2009-11-06 00:00:00 to 2009-11-06 23:59:59

Analysing by default products WSM
Getting doppler jumps data for WSM from 2009-11-06 00:00:00 to 2009-11-06 23:59:59...
Writing file ./RESULTS/DAILY/091106/DOPPLER/Doppler_Jumps_data_WSM_2009-11-06.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/091106/DOPPLER/DOPPLER_JUMPS_ANX_WSM.png...
Writing file ../../RESULTS/DAILY/091106/DOPPLER/DOPPLER_JUMPS_Date_WSM.png...



DOPPLER MAP Analysis will be performed from 2009-11-06 00:00:00 to 2009-11-06 23:59:59

Analysing products WVS IS2 V/V
Loading predicted doppler values....
Phase: descending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -30.109485 Hz
Writing file ../RESULTS/DAILY/091106//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_WVS_IS2_VV_desc.jpg...
Writing file ../RESULTS/DAILY/091106//DOPPLER/DOPPLER_Absolute_WVS_IS2_VV_desc.jpg...

Loading predicted doppler values....
Phase: ascending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -30.093689 Hz
Writing file ../RESULTS/DAILY/091106//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_WVS_IS2_VV_asc.jpg...
Writing file ../RESULTS/DAILY/091106//DOPPLER/DOPPLER_Absolute_WVS_IS2_VV_asc.jpg...

Analysing products GM1 SS1 H/H
Loading predicted doppler values....
Phase: descending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -18.888965 Hz
Writing file ../RESULTS/DAILY/091106//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_GM1_SS1_HH_desc.jpg...
Writing file ../RESULTS/DAILY/091106//DOPPLER/DOPPLER_Absolute_GM1_SS1_HH_desc.jpg...

Loading predicted doppler values....
Phase: ascending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -25.097481 Hz
Writing file ../RESULTS/DAILY/091106//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_GM1_SS1_HH_asc.jpg...
Writing file ../RESULTS/DAILY/091106//DOPPLER/DOPPLER_Absolute_GM1_SS1_HH_asc.jpg...

DOPPLER ANALYSIS completed
#####

CHIRP ANALYSIS
#####
Creating directory ./RESULTS/DAILY/091106/CHIRP...

CHIRP Analysis will be performed from 2009-11-06 00:00:00 to 2009-11-06 23:59:59

Analysing products WSM SS1 H/H

Getting ScaleFactor data for WSM SS1 H/H from 2009-11-06 00:00:00 to 2009-11-06 23:59:59...
Writing file ./RESULTS/DAILY/091106/CHIRP/ScaleFactor_data_WSM_SS1_HH_2009-11-06.dat...
Running IDL program...
Writing file ../RESULTS/DAILY/091106/CHIRP/ScaleFactor_ANX_WSM_SS1_HH.png...
Writing file ../RESULTS/DAILY/091106/CHIRP/ScaleFactor_DATE_WSM_SS1_HH.png...

Analysing products WSM SS1 V/V

Getting ScaleFactor data for WSM SS1 V/V from 2009-11-06 00:00:00 to 2009-11-06 23:59:59...
Writing file ./RESULTS/DAILY/091106/CHIRP/ScaleFactor_data_WSM_SS1_VV_2009-11-06.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/091106/CHIRP/ScaleFactor_ANX_WSM_SS1_VV.png...
Writing file ../../RESULTS/DAILY/091106/CHIRP/ScaleFactor_DATE_WSM_SS1_VV.png...

CHIRP ANALYSIS completed

#####

RAW DATA ANALYSIS

Analysis will be performed from 2009-11-06 00:00:00 to 2009-11-06 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/091106/RAW_DATA

Creating directory ./RESULTS/DAILY/091106/RAW_DATA...

Getting raw data for WVS from 2009-11-06 00:00:00 to 2009-11-06 23:59:59...
Writing file ./RESULTS/DAILY/091106/RAW_DATA/Raw_data_WVS_2009-11-06.dat...
Running IDL program to create graphs...

Creating image ../../RESULTS/DAILY/091106/RAW_DATA/Raw_data_WVS_input_mean.png...
Creating image ../../RESULTS/DAILY/091106/RAW_DATA/Raw_data_WVS_input_stdev.png...
Creating image ../../RESULTS/DAILY/091106/RAW_DATA/Raw_data_WVS_gain_imbalance.png...

Getting raw data for IMM from 2009-11-06 00:00:00 to 2009-11-06 23:59:59...
Writing file ./RESULTS/DAILY/091106/RAW_DATA/Raw_data_IMM_2009-11-06.dat...
Running IDL program to create graphs...

Creating image ../../RESULTS/DAILY/091106/RAW_DATA/Raw_data_IMM_input_mean.png...
Creating image ../../RESULTS/DAILY/091106/RAW_DATA/Raw_data_IMM_input_stdev.png...
Creating image ../../RESULTS/DAILY/091106/RAW_DATA/Raw_data_IMM_gain_imbalance.png...

RAW DATA ANALYSIS completed

#####

TELEMETRY ANALYSIS

Analysis will be performed from 2009-11-06 00:00:00 to 2009-11-06 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/091106/TELEMETRY

Creating directory ./RESULTS/DAILY/091106/TELEMETRY...

Looking for gaps and missing lines in WVS products...

Checking 23 products from PDE...
Checking 27 products from PDK...

Looking for gaps and missing lines in GM1 products...

Checking 34 products from PDE...
Checking 48 products from PDK...

Looking for gaps and missing lines in APM products...

Checking 2 products from PDE...
No products from PDK...



Looking for gaps and missing lines in IMM products...

Checking 21 products from PDE...

Found product...ASA_IMM_1PNPDE20091106_054344_00000372084_00048_40182_8840.N1 / 1 gaps / 0 missing lines

Checking 4 products from PDK...

Looking for gaps and missing lines in WSM products...

Checking 59 products from PDE...

Found product...ASA_WSM_1PNPDE20091106_181655_000001652084_00056_40190_9141.N1 / 0 gaps / 29 missing lines

Checking 14 products from PDK...

Creating graph of missing lines and gaps...

Creating image: ./RESULTS/DAILY/091106/TELEMETRY/TELEMETRY_Missing_lines.png...

Creating image: ./RESULTS/DAILY/091106/TELEMETRY/TELEMETRY_Gaps.png...

TELEMETRY ANALYSIS completed

#####

BROWSE PRODUCTS ANALYSIS

#####

Analysis will be performed on 2009-11-06

Scanning directory /nfs-store/ASAR_Data//ASA_GM_BP...

Results will be exported to the directory: /nfs-store/ASAR_Data//ASA_GM_BP/JPG/20091106/

Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091106_000857_000006402084_00045_40179_8585.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091106_003929_000003622084_00045_40179_8598.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091106_005142_000001022084_00045_40179_8596.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091106_005606_000004712084_00045_40179_8606.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091106_012040_000003382084_00045_40179_8655.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091106_014031_000012452084_00046_40180_8690.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091106_020339_000001202084_00046_40180_8660.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091106_020642_000000962084_00046_40180_8666.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091106_020923_000000722084_00046_40180_8683.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091106_023801_000004162084_00046_40180_8729.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091106_025507_000001202084_00046_40180_8740.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091106_025711_000002772084_00046_40180_8738.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091106_030235_000001322084_00046_40180_8734.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091106_030816_000001022084_00047_40181_8727.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091106_031357_000008152084_00047_40181_8736.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091106_032822_000008392084_00047_40181_8750.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091106_034548_000003562084_00047_40181_8748.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091106_041723_000004772084_00047_40181_8832.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091106_042902_000000842084_00047_40181_8830.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091106_045159_000001082084_00048_40182_8828.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091106_045716_000003442084_00048_40182_8826.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091106_050415_000013712084_00048_40182_8873.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091106_051945_000004412084_00048_40182_8836.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091106_052825_000001932084_00048_40182_8852.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_055914_000007062084_00048_40182_9972.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_064849_000004712084_00049_40183_9977.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_065820_000005252084_00049_40183_9992.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_071226_000000962084_00049_40183_9994.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_071643_000005732084_00049_40183_9996.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_073736_000008392084_00049_40183_0001.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_082501_000007312084_00050_40184_0003.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_083556_000002592084_00050_40184_0035.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_084238_000000722084_00050_40184_0037.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_085054_000001872084_00050_40184_0039.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_085913_000000842084_00050_40184_0041.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_091834_000008212084_00050_40184_0046.N1 ...

Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_100625_000002592084_00051_40185_0048.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_101252_000001812084_00051_40185_0050.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_101437_000001022084_00051_40185_0076.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_101848_000001082084_00051_40185_0074.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_102543_000001082084_00051_40185_0078.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_103216_000001022084_00051_40185_0080.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_110041_000007312084_00051_40185_0088.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_114626_000002472084_00052_40186_0090.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_115407_000001022084_00052_40186_0122.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_123723_000000782084_00052_40186_0124.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_124222_000006642084_00052_40186_0129.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_125923_000004042084_00052_40186_0134.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_132012_000007062084_00053_40187_0142.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_133754_000003442084_00053_40187_0173.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_135812_000002472084_00053_40187_0171.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_140400_000003742084_00053_40187_0178.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_141023_000001572084_00053_40187_0180.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_141759_000001572084_00053_40187_0182.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_142323_000006402084_00053_40187_0190.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_144111_000002352084_00053_40187_0192.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_145354_000010622084_00054_40188_0201.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_152140_000007552084_00054_40188_0228.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_153712_000000902084_00054_40188_0233.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_155835_000000842084_00054_40188_0235.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_160340_000006582084_00054_40188_0240.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_163601_000008632084_00055_40189_0245.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_170137_000008332084_00055_40189_0267.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_174404_000001202084_00055_40189_0269.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_174706_000002652084_00055_40189_0274.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_181944_000002112084_00056_40190_0276.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_182550_000001872084_00056_40190_0278.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_182729_000002232084_00056_40190_0298.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_183607_000006222084_00056_40190_0300.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_192412_000006942084_00056_40190_0307.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_195028_000006762084_00056_40190_0305.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20091106_200539_000001262084_00057_40191_0312.N1 ...

ANALYSIS COMPLETED: 72 GM browse products to see...

Scanning directory /nfs-store/ASAR_Data//ASA_AP_BP...

Results will be exported to the directory: /nfs-store/ASAR_Data//ASA_AP_BP/JPG/20091106/

Stripping browse product /nfs-store/ASAR_Data//ASA_AP_BP/ASA_AP_BPZPDE20091106_020820_000000412084_00046_40180_8688.N1 ...

ANALYSIS COMPLETED: 1 AP browse products to see...

Scanning directory /nfs-store/ASAR_Data//ASA_IM_BP...

Results will be exported to the directory: /nfs-store/ASAR_Data//ASA_IM_BP/JPG/20091106/

Stripping browse product /nfs-store/ASAR_Data//ASA_IM_BP/ASA_IM_BPZPDK20091106_064432_000002422084_00049_40183_9990.N1 ...

Stripping browse product /nfs-store/ASAR_Data//ASA_IM_BP/ASA_IM_BPZPDK20091106_082333_000000592084_00050_40184_0014.N1 ...

Stripping browse product /nfs-store/ASAR_Data//ASA_IM_BP/ASA_IM_BPZPDK20091106_084351_000001792084_00050_40184_0029.N1 ...

Stripping browse product /nfs-store/ASAR_Data//ASA_IM_BP/ASA_IM_BPZPDK20091106_102455_000000372084_00051_40185_0059.N1 ...

ANALYSIS COMPLETED: 4 IM browse products to see...

Scanning directory /nfs-store/ASAR_Data//ASA_WS_BP...

Results will be exported to the directory: /nfs-store/ASAR_Data//ASA_WS_BP/JPG/20091106/

Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091106_000209_000001342084_00045_40179_8703.N1 ...

Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091106_001954_000000922084_00045_40179_8653.N1 ...

Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091106_002108_000000182084_00045_40179_8634.N1 ...



Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091106_005331_000001522084_00045_40179_8694.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091106_010403_000002752084_00045_40179_8801.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091106_010906_000000732084_00045_40179_8636.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091106_010906_000000912084_00045_40179_8673.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091106_023018_000001342084_00046_40180_8763.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091106_023018_000004582084_00046_40180_8854.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091106_023327_000002692084_00046_40180_8764.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091106_024501_000002752084_00046_40180_8860.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091106_034226_000001892084_00047_40181_8789.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091106_041348_000002132084_00047_40181_8911.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091106_041602_000000792084_00047_40181_8813.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091106_042526_000002132084_00047_40181_8871.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091106_054051_000000732084_00048_40182_8819.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091106_054051_000000912084_00048_40182_8913.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091106_055135_000000912084_00048_40182_8875.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091106_055630_000001582084_00048_40182_8877.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091106_065646_000000912084_00049_40183_8907.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091106_072618_000002682084_00049_40183_8927.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDK20091106_070932_000001702084_00049_40183_0031.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDK20091106_084018_000001342084_00050_40184_0033.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDK20091106_101621_000001342084_00051_40185_0070.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDK20091106_102042_000001902084_00051_40185_0072.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDK20091106_115553_000004522084_00052_40186_0114.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDK20091106_123846_000002142084_00052_40186_0169.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDK20091106_133204_000003482084_00053_40187_0167.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDK20091106_151138_000002142084_00054_40188_0224.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDK20091106_151556_000003062084_00054_40188_0226.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDK20091106_165233_000003602084_00055_40189_0265.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDK20091106_183117_000002872084_00056_40190_0296.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDK20091106_200750_000001222084_00057_40191_0325.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDK20091106_201026_000001092084_00057_40191_0327.N1 ...

ANALYSIS COMPLETED: 34 WS browse products to see...

BROWSE PRODUCTS ANALYSIS completed

#####

HTML REPORT generation

#####

Building file ./RESULTS/DAILY/091106/asarReport.html...

Building DATA SUMMARY section...

Building AUXILIARY FILES ANALYSIS section...

Building MODULE STEPPING ANALYSIS section...

Building CALIBRATION PULSES ANALYSIS section...

Building DOPPLER ANALYSIS section...

Building CHIRP ANALYSIS section...

Building RAW DATA ANALYSIS section...

Building TELEMETRY ANALYSIS section...

HTML REPORT generation completed

#####



ADFs disseminated for ASAR

ASA_CON_AXVIEC20081215_141339_20070204_165113_20091231_000000

ASA_INS_AXVIEC20090525_114808_20090428_100000_20091231_235959

ASA_XCH_AXVIEC20081215_143642_20020301_000000_20091231_000000

ASA_XCA_AXVIEC20090311_104501_20080801_000000_20091231_235959

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
WVS	0	0	0	0
GM1	0	0	0	0
APM	0	0	0	0
IMM	0	0	0	0
WSM	0	0	0	0

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
ASA_APM_1PNPDE20091106_020820_000000412084_00046_40180_8687.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20091106_174603_000000402084_00055_40189_9103.N1	OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_GM1_1PNPDE20091106_000857_000006402084_00045_40179_8584.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091106_003929_000003622084_00045_40179_8597.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091106_005142_000001022084_00045_40179_8595.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091106_005606_000004712084_00045_40179_8605.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091106_012040_000003382084_00045_40179_8654.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091106_014031_000012452084_00046_40180_8689.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091106_020339_000001202084_00046_40180_8659.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091106_020642_000000962084_00046_40180_8665.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091106_020923_000000722084_00046_40180_8682.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091106_023801_000004162084_00046_40180_8728.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091106_025507_000001202084_00046_40180_8739.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091106_025711_000002772084_00046_40180_8737.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091106_030235_000001322084_00046_40180_8733.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091106_030816_000001022084_00047_40181_8726.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091106_031357_000008152084_00047_40181_8735.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091106_032822_000008392084_00047_40181_8749.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091106_034548_000003562084_00047_40181_8747.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091106_041723_000004772084_00047_40181_8831.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091106_042902_000000842084_00047_40181_8829.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091106_045159_000001082084_00048_40182_8827.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091106_045716_000003442084_00048_40182_8825.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091106_050415_000013712084_00048_40182_8872.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091106_051945_000004412084_00048_40182_8835.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091106_052825_000001932084_00048_40182_8851.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091106_200630_000000782084_00057_40191_9177.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091106_201220_000007062084_00057_40191_9182.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091106_210323_000004892084_00057_40191_9187.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091106_212451_000011232084_00057_40191_9237.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091106_214021_000001932084_00057_40191_9222.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091106_215133_000002112084_00058_40192_9218.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091106_215752_000003622084_00058_40192_9227.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091106_224413_000006282084_00058_40192_9235.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091106_231707_000000902084_00059_40193_9339.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091106_233607_000007312084_00059_40193_9304.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091106_055914_000007062084_00048_40182_9971.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091106_064849_000004712084_00049_40183_9976.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091106_065820_000005252084_00049_40183_9991.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091106_071226_000000962084_00049_40183_9993.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091106_071643_000005732084_00049_40183_9995.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091106_073736_000008392084_00049_40183_0000.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091106_082501_000007312084_00050_40184_0002.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091106_083556_000002592084_00050_40184_0034.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091106_084238_000000722084_00050_40184_0036.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091106_085054_000001872084_00050_40184_0038.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091106_085913_000000842084_00050_40184_0040.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091106_091834_000008212084_00050_40184_0045.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091106_100625_000002592084_00051_40185_0047.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091106_101252_000001812084_00051_40185_0049.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091106_101437_000001022084_00051_40185_0075.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091106_101848_000001082084_00051_40185_0073.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091106_102543_000001082084_00051_40185_0077.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091106_103216_000001022084_00051_40185_0079.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091106_110041_000007312084_00051_40185_0087.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091106_114626_000002472084_00052_40186_0089.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091106_115407_000001022084_00052_40186_0121.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091106_123723_000000782084_00052_40186_0123.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091106_124222_000006642084_00052_40186_0128.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091106_125923_000004042084_00052_40186_0133.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091106_132012_000007062084_00053_40187_0141.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091106_133754_000003442084_00053_40187_0172.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091106_135812_000002472084_00053_40187_0170.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091106_140400_000003742084_00053_40187_0177.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091106_141023_000001572084_00053_40187_0179.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091106_141759_000001572084_00053_40187_0181.N1					OK	OK	OK	OK

ASA_GM1_1PNPDK20091106_142323_000006402084_00053_40187_0189.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091106_144111_000002352084_00053_40187_0191.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091106_145354_000010622084_00054_40188_0200.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091106_152140_000007552084_00054_40188_0227.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091106_153712_000000902084_00054_40188_0232.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091106_155835_000000842084_00054_40188_0234.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091106_160340_000006582084_00054_40188_0239.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091106_163601_000008632084_00055_40189_0244.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091106_170137_000008332084_00055_40189_0266.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091106_174404_000001202084_00055_40189_0268.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091106_174706_000002652084_00055_40189_0273.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091106_181944_000002112084_00056_40190_0275.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091106_182550_000001872084_00056_40190_0277.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091106_182729_000002232084_00056_40190_0297.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091106_183607_000006222084_00056_40190_0299.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091106_192412_000006942084_00056_40190_0306.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091106_195028_000006762084_00056_40190_0304.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091106_200539_000001262084_00057_40191_0311.N1	OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_IMM_1PNPDE20091106_000457_000000632084_00045_40179_8623.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091106_000457_000002292084_00045_40179_8697.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091106_000700_000001062084_00045_40179_8674.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091106_020115_000001332084_00046_40180_8695.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091106_020539_000000532084_00046_40180_8691.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091106_030147_000000372084_00046_40180_8751.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091106_030710_000000562084_00047_40181_8755.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091106_032732_000000372084_00047_40181_8753.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091106_045346_000001992084_00048_40182_8908.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091106_050257_000000622084_00048_40182_8810.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091106_052707_000000682084_00048_40182_8878.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091106_054344_000000372084_00048_40182_8840.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091106_070707_000001312084_00049_40183_8898.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091106_071403_000001502084_00049_40183_8914.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091106_111646_000000992084_00051_40185_9006.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091106_120900_000000532084_00052_40186_9004.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091106_184630_000001632084_00056_40190_9147.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091106_202408_000001912084_00057_40191_9216.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091106_214525_000000372084_00058_40192_9192.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091106_215500_000001602084_00058_40192_9276.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091106_234815_000000422084_00059_40193_9333.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20091106_064432_000002422084_00049_40183_9989.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20091106_082333_000000592084_00050_40184_0013.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20091106_084351_000001792084_00050_40184_0028.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20091106_102455_000000372084_00051_40185_0058.N1					OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.


Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WSM_1PNPDE20091106_000209_000001342084_00045_40179_8702.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_001954_000000922084_00045_40179_8652.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_002108_000000182084_00045_40179_8633.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_005331_000001522084_00045_40179_8693.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_010403_000002752084_00045_40179_8800.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_010906_000000732084_00045_40179_8635.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_010906_000000912084_00045_40179_8672.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_023018_000001342084_00046_40180_8761.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_023018_000004582084_00046_40180_8853.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_023327_000002692084_00046_40180_8762.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_024501_000002752084_00046_40180_8859.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_034226_000001892084_00047_40181_8788.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_041348_000002132084_00047_40181_8910.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_041602_000000792084_00047_40181_8812.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_042526_000002132084_00047_40181_8870.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_054051_000000732084_00048_40182_8818.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_054051_000000912084_00048_40182_8912.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_055135_000000912084_00048_40182_8874.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_055630_000001582084_00048_40182_8876.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_065646_000000912084_00049_40183_8906.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_072618_000002682084_00049_40183_8926.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_073401_000002132084_00049_40183_8990.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_073514_000001392084_00049_40183_8946.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_085404_000003062084_00050_40184_8948.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_091459_000002142084_00050_40184_8974.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_101047_000001212084_00051_40185_8986.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_102042_000000922084_00051_40185_8972.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_103401_000002812084_00051_40185_9002.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_105731_000001822084_00051_40185_8988.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_115040_000001892084_00052_40186_9008.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_122037_000005252084_00052_40186_9028.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_134341_000001092084_00053_40187_9077.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_140225_000000912084_00053_40187_9095.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_142039_000001582084_00053_40187_9101.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_151929_000001292084_00054_40188_9079.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_160005_000001352084_00054_40188_9087.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_160005_000001902084_00054_40188_9105.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_161531_000001532084_00054_40188_9075.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_165032_000000912084_00055_40189_9081.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_165758_000001212084_00055_40189_9133.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_173928_000002692084_00055_40189_9143.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_175133_000001902084_00055_40189_9131.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_181655_000001652084_00056_40190_9141.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_182316_000000732084_00056_40190_9119.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_182316_000001532084_00056_40190_9145.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_182531_000001822084_00056_40190_9123.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_192037_000002082084_00056_40190_9173.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_193648_000001532084_00056_40190_9171.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_194632_000002322084_00056_40190_9175.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_210048_000001532084_00057_40191_9241.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_211136_000001352084_00057_40191_9343.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_211136_000002872084_00057_40191_9379.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_211446_000000962084_00057_40191_9344.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_212116_000002132084_00057_40191_9239.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_220358_000001342084_00058_40192_9280.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_220358_000003112084_00058_40192_9381.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_224138_000001472084_00058_40192_9337.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_225444_000002142084_00058_40192_9278.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091106_233032_000001712084_00059_40193_9456.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20091106_070932_000001702084_00049_40183_0030.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20091106_084018_000001342084_00050_40184_0032.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20091106_101621_000001342084_00051_40185_0069.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20091106_102042_000001902084_00051_40185_0071.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20091106_115553_000004522084_00052_40186_0113.N1					OK	OK	OK	OK

ASA_WSM_1PNPDK20091106_123846_000002142084_00052_40186_0168.N1	OK	OK	OK	OK
ASA_WSM_1PNPDK20091106_133204_000003482084_00053_40187_0166.N1	OK	OK	OK	OK
ASA_WSM_1PNPDK20091106_151138_000002142084_00054_40188_0223.N1	OK	OK	OK	OK
ASA_WSM_1PNPDK20091106_151556_000003062084_00054_40188_0225.N1	OK	OK	OK	OK
ASA_WSM_1PNPDK20091106_165233_000003602084_00055_40189_0264.N1	OK	OK	OK	OK
ASA_WSM_1PNPDK20091106_183117_000002872084_00056_40190_0295.N1	OK	OK	OK	OK
ASA_WSM_1PNPDK20091106_200750_000001222084_00057_40191_0324.N1	OK	OK	OK	OK
ASA_WSM_1PNPDK20091106_201026_000001092084_00057_40191_0326.N1	OK	OK	OK	OK
ASA_WSM_1PNPDK20091106_233311_000001712084_00059_40193_0334.N1	OK	OK	OK	OK


Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WVS_1PNPDE20091106_002125_000010412084_00045_40179_8593.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091106_004535_000003302084_00045_40179_8600.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091106_011037_000001192084_00045_40179_8603.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091106_011137_000004052084_00045_40179_8657.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091106_012639_000007942084_00046_40180_8668.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091106_021053_000011242084_00046_40180_8685.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091106_024943_000002852084_00046_40180_8731.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091106_030958_000001942084_00047_40181_8745.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091106_035146_000009142084_00047_40181_8742.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091106_040645_000001652084_00047_40181_8823.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091106_043028_000012442084_00047_40181_8838.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091106_053141_000005092084_00048_40182_8849.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091106_054220_000000442084_00048_40182_8843.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091106_054427_000002702084_00048_40182_8846.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091106_202725_000019342084_00057_40191_9185.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091106_211625_000002252084_00057_40191_9180.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091106_211910_000000902084_00057_40191_9225.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091106_220910_000018592084_00058_40192_9230.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091106_225815_000002852084_00058_40192_9233.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091106_230200_000008692084_00058_40192_9297.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091106_231838_000006742084_00059_40193_9302.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091106_235005_000007492084_00059_40193_9307.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091106_054827_000001502084_00048_40182_0337.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091106_055304_000000752084_00048_40182_9969.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091106_061104_000019492084_00048_40182_9974.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091106_073048_000001502084_00049_40183_9998.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091106_075140_000018742084_00049_40183_0005.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091106_090041_000008092084_00050_40184_0043.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091106_093216_000020092084_00050_40184_0052.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091106_103841_000010492084_00051_40185_0082.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091106_111252_000001952084_00051_40185_0085.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091106_111832_000016342084_00051_40185_0092.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091106_120326_000003002084_00052_40186_0116.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091106_120958_000005992084_00052_40186_0119.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091106_122920_000004352084_00052_40186_0126.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091106_125328_000003152084_00052_40186_0131.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091106_130610_000005692084_00052_40186_0136.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091106_131642_000001642084_00053_40187_0139.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091106_134532_000007192084_00053_40187_0175.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091106_141300_000002552084_00053_40187_0184.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091106_143404_000003902084_00053_40187_0187.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091106_144507_000004792084_00053_40187_0194.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091106_153420_000001342084_00054_40188_0230.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091106_153845_000011392084_00054_40188_0237.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091106_161802_000010342084_00054_40188_0242.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091106_171533_000013792084_00055_40189_0271.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091106_175748_000011092084_00055_40189_0280.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091106_184920_000017842084_00056_40190_0302.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091106_193920_000003902084_00056_40190_0309.N1					OK	OK	OK	OK


Calibration pulses for GM1 SS3 H/H




Calibration pulses for GM1 SS3 H/H




Calibration pulses for GM1 SS3 H/H




06-Nov



06-Nov







06-Nov




06-Nov

rows: _ 3 _ 7 _ 11 _ 15 _ 19 _ 23 _ 27 _ 31


Calibration pulses for GM1 SS3 H/H




Calibration pulses for WVS IS2 V/V







Calibration pulses for WVS IS2 V/V




Calibration pulses for WVS IS2 V/V






Calibration pulses for WVS IS2 V/V







rows: _ 4 _ 8 _ 12 _ 16 _ 20 _ 24 _ 28 _ 32











































WVS			
Center	Beam	Pol	#
PDE	IS1	V/V	2
PDE	IS2	V/V	23
PDK	IS2	V/V	27

GM1			
Center	Beam	Pol	#
PDE	WS	H/H	34
PDK	WS	H/H	48

APM			
Center	Beam	Pol	#
PDE	IS3	V/H	1
PDE	IS7	H/H	1

IMM			
Center	Beam	Pol	#
PDE	IS2	H/H	3
PDE	IS2	V/V	14
PDE	IS3	V/V	1
PDE	IS4	V/V	1
PDE	IS5	H/H	1
PDE	IS5	V/V	1
PDK	IS2	V/V	4

WSM			
Center	Beam	Pol	#
PDE	WS	H/H	48
PDE	WS	V/V	11
PDK	WS	H/H	11
PDK	WS	V/V	3

MS			
Center	Time	Pol	Modules
PDK	2009-11-06 05:54:58	V	320

Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_APM_1PNPDE20091106_020820_000000412084_00046_40180_8687.N1						IS7	H/H	84	40180	46	4.07
ASA_APM_1PNPDE20091106_174603_000000402084_00055_40189_9103.N1						IS3	V/H	84	40189	55	4.07

ASA_GM1_1PNPDK20091106_182729_000002232084_00056_40190_0297.N1	SS1	H/H	84	40190	56	4.07
ASA_GM1_1PNPDK20091106_183607_000006222084_00056_40190_0299.N1	SS1	H/H	84	40190	56	4.07
ASA_GM1_1PNPDK20091106_192412_000006942084_00056_40190_0306.N1	SS1	H/H	84	40190	56	4.07
ASA_GM1_1PNPDK20091106_195028_000006762084_00056_40190_0304.N1	SS1	H/H	84	40190	56	4.07
ASA_GM1_1PNPDK20091106_200539_000001262084_00057_40191_0311.N1	SS1	H/H	84	40191	57	4.07
ASA_GM1_1PNPDE20091106_200630_000000782084_00057_40191_9177.N1	SS1	H/H	84	40191	57	4.07
ASA_GM1_1PNPDE20091106_201220_000007062084_00057_40191_9182.N1	SS1	H/H	84	40191	57	4.07
ASA_GM1_1PNPDE20091106_210323_000004892084_00057_40191_9187.N1	SS1	H/H	84	40191	57	4.07
ASA_GM1_1PNPDE20091106_212451_000011232084_00057_40191_9237.N1	SS1	H/H	84	40191	57	4.07
ASA_GM1_1PNPDE20091106_214021_000001932084_00057_40191_9222.N1	SS1	H/H	84	40191	57	4.07
ASA_GM1_1PNPDE20091106_215133_000002112084_00058_40192_9218.N1	SS1	H/H	84	40192	58	4.07
ASA_GM1_1PNPDE20091106_215752_000003622084_00058_40192_9227.N1	SS1	H/H	84	40192	58	4.07
ASA_GM1_1PNPDE20091106_224413_000006282084_00058_40192_9235.N1	SS1	H/H	84	40192	58	4.07
ASA_GM1_1PNPDE20091106_231707_000000902084_00059_40193_9339.N1	SS1	H/H	84	40193	59	4.07
ASA_GM1_1PNPDE20091106_233607_000007312084_00059_40193_9304.N1	SS1	H/H	84	40193	59	4.07


Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_IMM_1PNPDE20091106_000457_000000632084_00045_40179_8623.N1						IS2	H/H	84	40179	45	4.07
ASA_IMM_1PNPDE20091106_000457_000002292084_00045_40179_8697.N1						IS2	H/H	84	40179	45	4.07
ASA_IMM_1PNPDE20091106_000700_000001062084_00045_40179_8674.N1						IS2	H/H	84	40179	45	4.07
ASA_IMM_1PNPDE20091106_020115_000001332084_00046_40180_8695.N1						IS2	V/V	84	40180	46	4.07
ASA_IMM_1PNPDE20091106_020539_000000532084_00046_40180_8691.N1						IS3	V/V	84	40180	46	4.07
ASA_IMM_1PNPDE20091106_030147_000000372084_00046_40180_8751.N1						IS2	V/V	84	40180	46	4.07
ASA_IMM_1PNPDE20091106_030710_000000562084_00047_40181_8755.N1						IS2	V/V	84	40181	47	4.07
ASA_IMM_1PNPDE20091106_032732_000000372084_00047_40181_8753.N1						IS5	H/H	84	40181	47	4.07
ASA_IMM_1PNPDE20091106_045346_000001992084_00048_40182_8908.N1						IS2	V/V	84	40182	48	4.07
ASA_IMM_1PNPDE20091106_050257_000000622084_00048_40182_8810.N1						IS4	V/V	84	40182	48	4.07
ASA_IMM_1PNPDE20091106_052707_000000682084_00048_40182_8878.N1						IS2	V/V	84	40182	48	4.07
ASA_IMM_1PNPDE20091106_054344_000000372084_00048_40182_8840.N1						IS5	V/V	84	40182	48	4.07
ASA_IMM_1PNPDK20091106_064432_000002422084_00049_40183_9989.N1						IS2	V/V	84	40183	49	4.07
ASA_IMM_1PNPDE20091106_070707_000001312084_00049_40183_8898.N1						IS2	V/V	84	40183	49	4.07
ASA_IMM_1PNPDE20091106_071403_000001502084_00049_40183_8914.N1						IS2	V/V	84	40183	49	4.07
ASA_IMM_1PNPDK20091106_082333_000000592084_00050_40184_0013.N1						IS2	V/V	84	40184	50	4.07
ASA_IMM_1PNPDK20091106_084351_000001792084_00050_40184_0028.N1						IS2	V/V	84	40184	50	4.07
ASA_IMM_1PNPDK20091106_102455_000000372084_00051_40185_0058.N1						IS2	V/V	84	40185	51	4.07
ASA_IMM_1PNPDE20091106_111646_000000992084_00051_40185_9006.N1						IS2	V/V	84	40185	51	4.07
ASA_IMM_1PNPDE20091106_120900_000000532084_00052_40186_9004.N1						IS2	V/V	84	40186	52	4.07
ASA_IMM_1PNPDE20091106_184630_000001632084_00056_40190_9147.N1						IS2	V/V	84	40190	56	4.07
ASA_IMM_1PNPDE20091106_202408_000001912084_00057_40191_9216.N1						IS2	V/V	84	40191	57	4.07
ASA_IMM_1PNPDE20091106_214525_000000372084_00058_40192_9192.N1						IS2	V/V	84	40192	58	4.07
ASA_IMM_1PNPDE20091106_215500_000001602084_00058_40192_9276.N1						IS2	V/V	84	40192	58	4.07
ASA_IMM_1PNPDE20091106_234815_000000422084_00059_40193_9333.N1						IS2	V/V	84	40193	59	4.07


Filename	Pol	Timestamp	count(Module)
ASA_MS__0PNPDK20091106_055458_000000162084_00048_40182_0910.N1	V	2009-11-06 05:54:58	320





ASA_WSM_1PNPDE20091106_220358_000003112084_00058_40192_9381.N1	SS1	H/H	84	40192	58	4.07
ASA_WSM_1PNPDE20091106_220358_000001342084_00058_40192_9280.N1	SS1	H/H	84	40192	58	4.07
ASA_WSM_1PNPDE20091106_224138_000001472084_00058_40192_9337.N1	SS1	H/H	84	40192	58	4.07
ASA_WSM_1PNPDE20091106_225444_000002142084_00058_40192_9278.N1	SS1	H/H	84	40192	58	4.07
ASA_WSM_1PNPDE20091106_233032_000001712084_00059_40193_9456.N1	SS1	H/H	84	40193	59	4.07
ASA_WSM_1PNPDK20091106_233311_000001712084_00059_40193_0334.N1	SS1	H/H	84	40193	59	4.07




Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WVS_1PNPDE20091105_233344_000016642084_00044_40178_8582.N1						IS2	V/V	84	40178	44	4.07
ASA_WVS_1PNPDE20091106_002125_000010412084_00045_40179_8593.N1						IS2	V/V	84	40179	45	4.07
ASA_WVS_1PNPDE20091106_004535_000003302084_00045_40179_8600.N1						IS2	V/V	84	40179	45	4.07
ASA_WVS_1PNPDE20091106_011037_000001192084_00045_40179_8603.N1						IS2	V/V	84	40179	45	4.07
ASA_WVS_1PNPDE20091106_011137_000004052084_00045_40179_8657.N1						IS2	V/V	84	40179	45	4.07
ASA_WVS_1PNPDE20091106_011037_000001192084_00045_40179_8603.N1						IS1	V/V	84	40179	45	4.07
ASA_WVS_1PNPDE20091106_012639_000007942084_00046_40180_8668.N1						IS2	V/V	84	40180	46	4.07
ASA_WVS_1PNPDE20091106_021053_000011242084_00046_40180_8685.N1						IS2	V/V	84	40180	46	4.07
ASA_WVS_1PNPDE20091106_024943_000002852084_00046_40180_8731.N1						IS2	V/V	84	40180	46	4.07
ASA_WVS_1PNPDE20091106_030958_000001942084_00047_40181_8745.N1						IS2	V/V	84	40181	47	4.07
ASA_WVS_1PNPDE20091106_035146_000009142084_00047_40181_8742.N1						IS2	V/V	84	40181	47	4.07
ASA_WVS_1PNPDE20091106_040645_000001652084_00047_40181_8823.N1						IS2	V/V	84	40181	47	4.07
ASA_WVS_1PNPDE20091106_043028_000012442084_00047_40181_8838.N1						IS2	V/V	84	40181	47	4.07
ASA_WVS_1PNPDE20091106_053141_000005092084_00048_40182_8849.N1						IS2	V/V	84	40182	48	4.07
ASA_WVS_1PNPDE20091106_054220_000000442084_00048_40182_8843.N1						IS2	V/V	84	40182	48	4.07
ASA_WVS_1PNPDE20091106_054427_000002702084_00048_40182_8846.N1						IS2	V/V	84	40182	48	4.07
ASA_WVS_1PNPDK20091106_054827_000001502084_00048_40182_0337.N1						IS2	V/V	84	40182	48	4.07
ASA_WVS_1PNPDE20091106_054427_000002702084_00048_40182_8846.N1						IS1	V/V	84	40182	48	4.07
ASA_WVS_1PNPDK20091106_055304_000000752084_00048_40182_9969.N1						IS2	V/V	84	40182	48	4.07
ASA_WVS_1PNPDK20091106_061104_000019492084_00048_40182_9974.N1						IS2	V/V	84	40182	48	4.07
ASA_WVS_1PNPDK20091106_073048_000001502084_00049_40183_9998.N1						IS2	V/V	84	40183	49	4.07
ASA_WVS_1PNPDK20091106_075140_000018742084_00049_40183_0005.N1						IS2	V/V	84	40183	49	4.07
ASA_WVS_1PNPDK20091106_090041_000008092084_00050_40184_0043.N1						IS2	V/V	84	40184	50	4.07
ASA_WVS_1PNPDK20091106_093216_000020092084_00050_40184_0052.N1						IS2	V/V	84	40184	50	4.07
ASA_WVS_1PNPDK20091106_103841_000010492084_00051_40185_0082.N1						IS2	V/V	84	40185	51	4.07
ASA_WVS_1PNPDK20091106_111252_000001952084_00051_40185_0085.N1						IS2	V/V	84	40185	51	4.07
ASA_WVS_1PNPDK20091106_111832_000016342084_00051_40185_0092.N1						IS2	V/V	84	40185	51	4.07
ASA_WVS_1PNPDK20091106_120326_000003002084_00052_40186_0116.N1						IS2	V/V	84	40186	52	4.07
ASA_WVS_1PNPDK20091106_120958_000005992084_00052_40186_0119.N1						IS2	V/V	84	40186	52	4.07
ASA_WVS_1PNPDK20091106_122920_000004352084_00052_40186_0126.N1						IS2	V/V	84	40186	52	4.07
ASA_WVS_1PNPDK20091106_125328_000003152084_00052_40186_0131.N1						IS2	V/V	84	40186	52	4.07
ASA_WVS_1PNPDK20091106_130610_000005692084_00052_40186_0136.N1						IS2	V/V	84	40186	52	4.07
ASA_WVS_1PNPDK20091106_131642_000001642084_00053_40187_0139.N1						IS2	V/V	84	40187	53	4.07
ASA_WVS_1PNPDK20091106_134532_000007192084_00053_40187_0175.N1						IS2	V/V	84	40187	53	4.07
ASA_WVS_1PNPDK20091106_141300_000002552084_00053_40187_0184.N1						IS2	V/V	84	40187	53	4.07
ASA_WVS_1PNPDK20091106_143404_000003902084_00053_40187_0187.N1						IS2	V/V	84	40187	53	4.07
ASA_WVS_1PNPDK20091106_144507_000004792084_00053_40187_0194.N1						IS2	V/V	84	40187	53	4.07
ASA_WVS_1PNPDK20091106_153420_000001342084_00054_40188_0230.N1						IS2	V/V	84	40188	54	4.07
ASA_WVS_1PNPDK20091106_153845_000011392084_00054_40188_0237.N1						IS2	V/V	84	40188	54	4.07
ASA_WVS_1PNPDK20091106_161802_000010342084_00054_40188_0242.N1						IS2	V/V	84	40188	54	4.07
ASA_WVS_1PNPDK20091106_171533_000013792084_00055_40189_0271.N1						IS2	V/V	84	40189	55	4.07
ASA_WVS_1PNPDK20091106_175748_000011092084_00055_40189_0280.N1						IS2	V/V	84	40189	55	4.07
ASA_WVS_1PNPDK20091106_184920_000017842084_00056_40190_0302.N1						IS2	V/V	84	40190	56	4.07
ASA_WVS_1PNPDK20091106_193920_000003902084_00056_40190_0309.N1						IS2	V/V	84	40190	56	4.07
ASA_WVS_1PNPDE20091106_202725_000019342084_00057_40191_9185.N1						IS2	V/V	84	40191	57	4.07
ASA_WVS_1PNPDE20091106_211625_000002252084_00057_40191_9180.N1						IS2	V/V	84	40191	57	4.07
ASA_WVS_1PNPDE20091106_211910_000000902084_00057_40191_9225.N1						IS2	V/V	84	40191	57	4.07
ASA_WVS_1PNPDE20091106_220910_000018592084_00058_40192_9230.N1						IS2	V/V	84	40192	58	4.07
ASA_WVS_1PNPDE20091106_225815_000002852084_00058_40192_9233.N1						IS2	V/V	84	40192	58	4.07
ASA_WVS_1PNPDE20091106_230200_000008692084_00058_40192_9297.N1						IS2	V/V	84	40192	58	4.07
ASA_WVS_1PNPDE20091106_231838_000006742084_00059_40193_9302.N1						IS2	V/V	84	40193	59	4.07
ASA_WVS_1PNPDE20091106_235005_000007492084_00059_40193_9307.N1						IS2	V/V	84	40193	59	4.07

















































06-Nov




06-Nov




06-Nov




06-Nov




06-Nov




06-Nov







06-Nov




06-Nov




06-Nov




06-Nov





06-Nov




06-Nov









Processing Center	Product	Gaps
Missing lines		
PDE	ASA_IMM_1PNPDE20091106_054344_000000372084_00048_40182_8840.N1	1
PDE	ASA_WSM_1PNPDE20091106_181655_000001652084_00056_40190_9141.N1	0

