



Analysis from 29-DEC-2009 00:00:00 to 29-DEC-2009 23:59:59. Page generated on 04-JAN-2010 16:44:33.
View log file: ASAR_Daily_Report_20100104_1640.log. For any anomalies please contact emma.griffiths@vega.co.uk, kajal.haria@vega.co.uk.

This report is automatically generated every day, every 2 hours. No comments are provided on the results.

SUMMARY

1. DATA SUMMARY
 - 1.1 Summary tables
 - 1.2 Lists of products used
2. AUXILIARY FILES ANALYSIS
 - 2.1 IECF operational ADFs list
 - 2.2 Products with wrong ADFs
3. MODULE STEPPING PRODUCTS ANALYSIS
 - 3.1 V/V polarisation
 - 3.2 H/H polarisation
4. CALIBRATION PULSES ANALYSIS
 - 4.1 Analysis for WVS IS2 V/V
 - 4.1.1 Temporal Evolution Analysis for WVS IS2 V/V
 - 4.1.2 All Rows Analysis for WVS IS2 V/V
 - 4.2 Analysis for GM1 SS3 H/H
 - 4.2.1 Temporal Evolution Analysis for GM1 SS3 H/H
 - 4.2.2 All Rows Analysis for GM1 SS3 H/H
5. DOPPLER ANALYSIS
 - 5.1 Analysis for WVS IS2 V/V
 - 5.1.1 Doppler MAP Analysis for WVS IS2 V/V
 - 5.1.2 Doppler ANX Analysis for WVS IS2 V/V
 - 5.2 Analysis for GM1 SS1 H/H
 - 5.2.1 Doppler MAP Analysis for GM1 SS1 H/H
 - 5.2.2 Doppler ANX Analysis for GM1 SS1 H/H
 - 5.3 Doppler JUMPS Analysis for WSM
6. CHIRP ANALYSIS
 - 6.1 Analysis for WSM SS1 H/H
 - 6.1.1 ScaleFactor
 - 6.2 Analysis for WSM SS1 V/V
 - 6.2.1 ScaleFactor
7. RAW DATA ANALYSIS
 - 7.1 Analysis for WVS
 - 7.2 Analysis for IMM
8. TELEMETRY ANALYSIS
 - 8.1 Number of Missing Lines
 - 8.2 Number of Gaps

1 - DATA SUMMARY

1.1 - Summary tables

[[BACK TO MENU](#)]

WVS				GM1				APM				IMM				WSM				MS			
Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Time	Pol	Modules
PDE	IS1	V/V	1	PDE	WS	H/H	29	PDE	IS3	H/H	1	PDE	IS1	V/V	1	PDE	WS	H/H	26	PDK	2009-12-29 08:10:02	H	320
PDE	IS2	V/V	25	PDK	WS	H/H	47	PDE	IS6	V/H	1	PDE	IS2	H/H	12	PDE	WS	V/V	5				
PDK	IS2	V/V	23									PDE	IS2	V/V	10	PDK	WS	H/H	13				
												PDE	IS4	H/H	1	PDK	WS	V/V	2				
												PDE	IS6	V/V	1								
												PDE	IS7	V/V	1								
												PDK	IS2	H/H	3								
												PDK	IS2	V/V	2								

1.2 - Lists of products used

[[BACK TO MENU](#)]

[TXT] [XLS] [List_WVS_products_used](#)
 [TXT] [XLS] [List_GM1_products_used](#)
 [TXT] [XLS] [List_APM_products_used](#)
 [TXT] [XLS] [List_IMM_products_used](#)
 [TXT] [XLS] [List_WSM_products_used](#)
 [TXT] [XLS] [List_MS_products_used](#)

2 - AUXILIARY FILES ANALYSIS

2.1 - IECF operational ADFs list

[[BACK TO MENU](#)]

ADFs disseminated for ASAR
ASA_CON_AXVIEC20091217_101713_20070204_165113_20101231_000000
ASA_INS_AXVIEC20091217_114637_20090428_100000_20101231_235959
ASA_XCH_AXVIEC20091217_113006_20020301_000000_20101231_000000
ASA_XCA_AXVIEC20091217_114112_20080801_000000_20101231_235959

2.2 - Products with wrong ADFs

[[BACK TO MENU](#)]

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
WVS	0	0	0	0
GM1	0	0	0	0
APM	0	0	0	0
IMM	0	0	0	0
WSM	0	0	0	0

[TXT] [XLS] [Check_ADFs_WVS](#)
 [TXT] [XLS] [Check_ADFs_GM1](#)
 [TXT] [XLS] [Check_ADFs_APM](#)
 [TXT] [XLS] [Check_ADFs_IMM](#)

3 - MODULE STEPPING PRODUCTS ANALYSIS





3.2 - H/H polarisation


[[BACK TO MENU](#)]

SECOND FIXED REFERENCE	PREVIOUS PRODUCT REFERENCE
After antenna maintenance (2005-09-22/23)	Previous product in the same polarisation

Reference: 2005-09-22 06:26:51 H RxGain
 Test : 2009-12-29 08:10:02 H






Reference: 2009-12-28 01:59:15 H RxGain
 Test : 2009-12-29 08:10:02 H






Reference: 2005-09-22 06:26:51 H RxPhase
 Test : 2009-12-29 08:10:02 H



Reference: 2009-12-28 01:59:15 H RxPhase
 Test : 2009-12-29 08:10:02 H





4 - CALIBRATION PULSES ANALYSIS

4.1 - Analysis for WVS IS2 V/V


4.1.1 - Temporal Evolution Analysis for WVS IS2 V/V

[BACK TO MENU]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Calibration pulses for WVS IS2 V/V




Transmit power (P1 - P1a) for WVS IS2 V/V



4.1.2 - All Rows Analysis for WVS IS2 V/V

[BACK TO MENU]





4.2 - Analysis for GM1 SS3 H/H


4.2.1 - Temporal Evolution Analysis for GM1 SS3 H/H

[BACK TO MENU]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Calibration pulses for GM1 SS3 H/H




Transmit power (P1 - P1a) for GM1 SS3 H/H



4.2.2 - All Rows Analysis for GM1 SS3 H/H

[BACK TO MENU]






5 - DOPPLER ANALYSIS

5.1 - Analysis for WVS IS2 V/V

5.1.1 - Doppler MAP Analysis for WVS IS2 V/V

[[BACK TO MENU](#)]






5.1.2 - Doppler ANX Analysis for WVS IS2 V/V

[[BACK TO MENU](#)]






5.2 - Analysis for GM1 SS1 H/H

5.2.1 - Doppler MAP Analysis for GM1 SS1 H/H

[[BACK TO MENU](#)]






5.2.2 - Doppler ANX Analysis for GM1 SS1 H/H

[[BACK TO MENU](#)]






5.3 - Doppler JUMPS Analysis for WSM

[BACK TO MENU]







6 - CHIRP ANALYSIS

6.1 - Analysis for WSM SS1 H/H

6.1.1 - ScaleFactor

[BACK TO MENU]







6.2 - Analysis for WSM SS1 V/V

6.2.1 - ScaleFactor

[[BACK TO MENU](#)]






7 - RAW DATA ANALYSIS

7.1 - Analysis for WVS

[[BACK TO MENU](#)]

--	--	--




Channel	Statistics	DSS-B
MEAN I	mean	0.000496809
	stdev	2.18545e-07
MEAN Q	mean	0.000512365
	stdev	2.30150e-07
Channel	Statistics	DSS-B
STDEV I	mean	0.132163
	stdev	0.000943997
STDEV Q	mean	0.132490
	stdev	0.000959510

7.2 - Analysis for IMM

[[BACK TO MENU](#)]






8 - TELEMETRY ANALYSIS

Processing Center	Product	Gaps	Missing lines
PDE	ASA_WSM_1PNPDE20091229_154046_00002202085_00312_40947_2142.N1	4	1024

8.1 - Number of Missing lines


[[BACK TO MENU](#)]





8.2 - Number of Gaps

[\[BACK TO MENU \]](#)



ASAR Daily Report V1.00

Document Reference: OSME-DPOC-SEDA-RP-06-0348/0349

Contract Reference: ESA/Esrin 19049/05/I-OL

All rights reserved to Serco S.p.A., Via XX Settembre, 1 - 00187 Roma - Italy.

In particular, but not limited to:

(a) Modification, reverse engineering or distribution is not permitted in any form.

(b) Usage is restricted to Serco S.p.A. employee belonging to the above Contract Reference.

Any deviation from above rules requires an explicit prior written authorisation of Serco S.p.A.

ASAR DAILY REPORT for 091229
#####

MODE: DAILY
ANALYSIS: ALL
DATE: 2009-12-29

Analysis will be performed from 2009-12-29 00:00:00 to 2009-12-29 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_091229/

DATA SUMMARY

Summary will be performed from 2009-12-29 00:00:00 to 2009-12-29 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_091229/DATA_SUMMARY

Creating directory ./RESULTS/DAILY/_091229/DATA_SUMMARY...
Writing file ./RESULTS/DAILY/_091229/DATA_SUMMARY/Data_summary.html...

Getting WVS products list from 2009-12-29 00:00:00 to 2009-12-29 23:59:59...
Writing file ./RESULTS/DAILY/_091229/DATA_SUMMARY/List_WVS_products_used.xls...
Writing file ./RESULTS/DAILY/_091229/DATA_SUMMARY/List_WVS_products_used.txt...

Getting GM1 products list from 2009-12-29 00:00:00 to 2009-12-29 23:59:59...
Writing file ./RESULTS/DAILY/_091229/DATA_SUMMARY/List_GM1_products_used.xls...
Writing file ./RESULTS/DAILY/_091229/DATA_SUMMARY/List_GM1_products_used.txt...

Getting APM products list from 2009-12-29 00:00:00 to 2009-12-29 23:59:59...
Writing file ./RESULTS/DAILY/_091229/DATA_SUMMARY/List_APM_products_used.xls...
Writing file ./RESULTS/DAILY/_091229/DATA_SUMMARY/List_APM_products_used.txt...

Getting IMM products list from 2009-12-29 00:00:00 to 2009-12-29 23:59:59...
Writing file ./RESULTS/DAILY/_091229/DATA_SUMMARY/List_IMM_products_used.xls...
Writing file ./RESULTS/DAILY/_091229/DATA_SUMMARY/List_IMM_products_used.txt...

Getting WSM products list from 2009-12-29 00:00:00 to 2009-12-29 23:59:59...
Writing file ./RESULTS/DAILY/_091229/DATA_SUMMARY/List_WSM_products_used.xls...
Writing file ./RESULTS/DAILY/_091229/DATA_SUMMARY/List_WSM_products_used.txt...

Getting MS products list from 2009-12-29 00:00:00 to 2009-12-29 23:59:59...
Writing file ./RESULTS/DAILY/_091229/DATA_SUMMARY/List_MS_products_used.xls...
Writing file ./RESULTS/DAILY/_091229/DATA_SUMMARY/List_MS_products_used.txt...

DATA SUMMARY completed
#####

AUXILIARY FILES ANALYSIS

Analysis will be performed from 2009-12-29 00:00:00 to 2009-12-29 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_091229/AUXILIARY

Creating directory ./RESULTS/DAILY/_091229/AUXILIARY...

Looking for the IECF operational ADFs list...



ADF filter 20091229*current_3_IECF_ADFs.txt
 Found list 20091229_030001_current_3_IECF_ADFs.txt...
 Extracting ADFs...

ASA_CON_AXVIEC20091217_101713_20070204_165113_20101231_000000
 ASA_INS_AXVIEC20091217_114637_20090428_100000_20101231_235959
 ASA_XCH_AXVIEC20091217_113006_20020301_000000_20101231_000000
 ASA_XCA_AXVIEC20091217_114112_20080801_000000_20101231_235959

Writing file ./RESULTS/DAILY/_091229/AUXILIARY/ASAR_ADFs_IECF_List3.html...
 Writing file ./RESULTS/DAILY/_091229/AUXILIARY/Auxiliary_files_summary.html...

Analysing WVS products...

Writing file ./RESULTS/DAILY/_091229/AUXILIARY/Check_ADFs_WVS.xls...
 Writing file ./RESULTS/DAILY/_091229/AUXILIARY/Check_ADFs_WVS.txt...

ASA_WVS_1PNPDE20091229_000337_000002842085_00302_40937_1992.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091229_000737_000017092085_00302_40937_2005.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091229_005750_000009552085_00303_40938_2008.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091229_012046_000003752085_00303_40938_2007.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091229_014342_000002402085_00303_40938_2009.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091229_014657_000002552085_00303_40938_2022.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091229_020309_000004642085_00304_40939_2025.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091229_024841_000010192085_00304_40939_2024.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091229_030526_000000302085_00304_40939_2044.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091229_032412_000001202085_00304_40939_2043.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091229_033227_000002692085_00304_40939_2051.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091229_034120_000001192085_00304_40939_2050.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091229_034538_000001942085_00305_40940_2048.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091229_043006_000007342085_00305_40940_2047.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091229_044206_000003602085_00305_40940_2066.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091229_050457_000014242085_00305_40940_2074.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091229_060752_000009292085_00306_40941_2073.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091229_210128_000019642085_00315_40950_2161.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091229_215123_000002552085_00315_40950_2162.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091229_215454_000008242085_00315_40950_2173.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091229_222007_000002402085_00316_40951_2175.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091229_224213_000013942085_00316_40951_2178.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091229_230927_000003152085_00316_40951_2180.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091229_233157_000003002085_00316_40951_2181.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091229_233627_000016642085_00316_40951_2195.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091229_062306_000003452085_00306_40941_2855.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091229_064533_000019792085_00306_40941_2858.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091229_080307_000003752085_00307_40942_2878.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091229_082609_000020542085_00307_40942_2881.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091229_093222_000010492085_00308_40943_2899.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091229_100645_000018592085_00308_40943_2902.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091229_110202_000001642085_00309_40944_2914.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091229_110704_000014092085_00309_40944_2915.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091229_114720_000017842085_00309_40944_2918.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091229_123843_000009292085_00310_40945_2928.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091229_130611_000003002085_00310_40945_2933.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091229_132756_000003752085_00310_40945_2934.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091229_134124_000003742085_00310_40945_2936.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091229_134901_000000592085_00311_40946_2939.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091229_142434_000004192085_00311_40946_2951.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091229_143956_000007042085_00311_40946_2954.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091229_150823_000011842085_00311_40946_2957.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091229_160800_000014542085_00312_40947_2971.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091229_164859_000011092085_00312_40947_2973.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091229_174807_000014842085_00313_40948_2988.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091229_183347_000008542085_00313_40948_2991.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091229_192141_000019042085_00314_40949_3006.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091229_201011_000003302085_00314_40949_3013.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

Analysing GM1 products...

Writing file ./RESULTS/DAILY/_091229/AUXILIARY/Check_ADFs_GM1.xls...

Writing file ./RESULTS/DAILY/_091229/AUXILIARY/Check_ADFs_GM1.txt...

ASA_GM1_1PNPDE20091229_003650_00000842085_00303_40938_2003.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091229_004012_000008822085_00303_40938_2004.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091229_005545_000001202085_00303_40938_2006.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091229_011427_000003742085_00303_40938_2010.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091229_015202_000006282085_00303_40938_2021.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091229_021318_000002052085_00304_40939_2027.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091229_022312_000012332085_00304_40939_2026.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091229_024629_00000842085_00304_40939_2023.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091229_032702_000003202085_00304_40939_2045.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091229_033737_000002232085_00304_40939_2052.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091229_034934_000003982085_00305_40940_2053.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091229_035750_000014382085_00305_40940_2049.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091229_042416_000002772085_00305_40940_2046.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091229_044852_000000722085_00305_40940_2064.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091229_045301_000001022085_00305_40940_2065.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091229_050256_000001142085_00305_40940_2070.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091229_053413_000000662085_00306_40941_2076.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091229_053707_000014682085_00306_40941_2075.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091229_060317_000002712085_00306_40941_2071.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091229_204238_000001262085_00315_40950_2158.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091229_204625_000000722085_00315_40950_2159.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091229_205630_000002952085_00315_40950_2160.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091229_213452_000005672085_00315_40950_2163.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091229_221127_000003382085_00316_40951_2172.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091229_221834_000000842085_00316_40951_2174.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091229_223203_000001752085_00316_40951_2177.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091229_230609_000000902085_00316_40951_2176.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091229_230752_000000902085_00316_40951_2179.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091229_231528_000005672085_00316_40951_2182.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091229_062931_000001142085_00306_40941_2856.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091229_064334_000001142085_00306_40941_2857.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091229_071920_000007612085_00307_40942_2859.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091229_073056_000001082085_00307_40942_2873.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091229_073614_000002472085_00307_40942_2874.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091229_074912_000001692085_00307_40942_2875.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091229_075403_000001022085_00307_40942_2876.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091229_075904_000000962085_00307_40942_2877.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091229_081121_000005552085_00307_40942_2879.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091229_082451_000000722085_00307_40942_2880.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091229_090117_000006042085_00308_40943_2882.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091229_092547_000003922085_00308_40943_2897.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091229_095042_000000902085_00308_40943_2898.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091229_100530_000000662085_00308_40943_2900.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091229_104013_000002832085_00309_40944_2901.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091229_104637_000002352085_00309_40944_2903.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091229_113726_000001812085_00309_40944_2916.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091229_114549_000000842085_00309_40944_2917.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091229_121751_000006652085_00310_40945_2919.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091229_125500_000005492085_00310_40945_2929.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091229_130418_000001082085_00310_40945_2930.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091229_131155_000003682085_00310_40945_2931.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091229_132640_000000662085_00310_40945_2932.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091229_133449_000003922085_00310_40945_2935.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091229_135340_00000842085_00311_40946_2937.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091229_135612_000008702085_00311_40946_2938.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091229_140933_000004162085_00311_40946_2950.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091229_143214_000004592085_00311_40946_2952.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091229_145229_000004652085_00311_40946_2953.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091229_150255_000001322085_00311_40946_2955.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK


```
ASA_GM1_1PNPDK20091229_152855_000002052085_00312_40947_2956.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091229_153453_000003322085_00312_40947_2958.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091229_155549_000007312085_00312_40947_2970.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091229_163305_000005672085_00312_40947_2972.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091229_170808_000010942085_00313_40948_2974.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091229_172509_000000722085_00313_40948_2985.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091229_173056_000005432085_00313_40948_2986.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091229_174228_000001202085_00313_40948_2987.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091229_181339_000005372085_00313_40948_2989.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091229_184838_000008702085_00314_40949_2990.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091229_190453_000001572085_00314_40949_3003.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091229_191248_000005312085_00314_40949_3004.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091229_195418_000004712085_00314_40949_3009.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091229_202049_000003322085_00314_40949_3008.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091229_202709_000005492085_00314_40949_3010.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091229_204030_000000662085_00315_40950_3007.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091229_204235_000000662085_00315_40950_3012.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```

Analysing APM products...

Writing file ./RESULTS/DAILY/_091229/AUXILIARY/Check_ADFs_APM.xls...

Writing file ./RESULTS/DAILY/_091229/AUXILIARY/Check_ADFs_APM.txt...

```
ASA_APM_1PNPDE20091229_174123_000000432085_00313_40948_2153.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20091229_221023_000000442085_00316_40951_2189.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```

Analysing IMM products...

Writing file ./RESULTS/DAILY/_091229/AUXILIARY/Check_ADFs_IMM.xls...

Writing file ./RESULTS/DAILY/_091229/AUXILIARY/Check_ADFs_IMM.txt...

```
ASA_IMM_1PNPDE20091229_003818_000001032085_00303_40938_2002.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091229_012827_000005842085_00303_40938_2016.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091229_024354_000000372085_00304_40939_2018.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091229_024756_000000372085_00304_40939_2019.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091229_030915_000003032085_00304_40939_2036.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091229_031505_000001622085_00304_40939_2037.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091229_034413_000000392085_00305_40940_2040.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091229_042145_000001422085_00305_40940_2041.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091229_042854_000000622085_00305_40940_2042.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091229_045007_000001622085_00305_40940_2060.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091229_045447_000000922085_00305_40940_2061.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091229_053023_000002182085_00306_40941_2067.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091229_053524_000000912085_00306_40941_2068.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091229_060136_000000922085_00306_40941_2069.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091229_063129_000001622085_00306_40941_2072.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091229_074607_000001762085_00307_40942_2084.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091229_075200_000001112085_00307_40942_2085.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091229_095217_000004432085_00308_40943_2114.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091229_113134_000003432085_00309_40944_2129.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091229_114023_000000922085_00309_40944_2138.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091229_153219_000001422085_00312_40947_2148.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091229_164231_000001622085_00312_40947_2143.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091229_173958_000000672085_00313_40948_2152.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091229_174431_000001142085_00313_40948_2154.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091229_182236_000002332085_00313_40948_2150.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091229_202618_000000402085_00314_40949_2170.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20091229_063459_000002332085_00306_40941_2864.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20091229_105748_000001682085_00309_40944_2911.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20091229_131801_000001622085_00310_40945_2945.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20091229_134815_000000392085_00311_40946_2947.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20091229_222830_000002032085_00316_40951_3027.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```

Analysing WSM products...

Writing file ./RESULTS/DAILY/_091229/AUXILIARY/Check_ADFs_WSM.xls...

Writing file ./RESULTS/DAILY/_091229/AUXILIARY/Check_ADFs_WSM.txt...

ASA_WSM_1PNPDE20091229_013904_000002812085_00303_40938_2017.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091229_021142_000000922085_00304_40939_2020.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091229_021652_000003672085_00304_40939_2034.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091229_031833_000002942085_00304_40939_2038.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091229_035617_000000862085_00305_40940_2039.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091229_045735_000002022085_00305_40940_2062.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091229_050117_000000922085_00305_40940_2063.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091229_073253_000001842085_00307_40942_2083.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091229_075555_000001842085_00307_40942_2086.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091229_080048_000000862085_00307_40942_2087.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091229_091129_000001712085_00308_40943_2105.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091229_092014_000001532085_00308_40943_2106.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091229_100048_000002812085_00308_40943_2122.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091229_103832_000000982085_00309_40944_2123.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091229_104502_000000862085_00309_40944_2124.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091229_114229_000001842085_00309_40944_2139.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091229_141633_000001472085_00311_40946_2145.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091229_150019_000001532085_00311_40946_2146.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091229_150519_000001282085_00311_40946_2147.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091229_154046_000002202085_00312_40947_2142.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091229_155352_000001102085_00312_40947_2149.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091229_164622_000001282085_00312_40947_2144.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091229_174639_000000862085_00313_40948_2155.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091229_182651_000001162085_00313_40948_2151.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091229_200218_000004282085_00314_40949_2156.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091229_201623_000002632085_00314_40949_2157.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091229_205142_000002882085_00315_40950_2171.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091229_214427_000004162085_00315_40950_2169.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091229_223504_000004282085_00316_40951_2190.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091229_232502_000004162085_00316_40951_2188.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20091229_064005_000002022085_00306_40941_2866.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20091229_082045_000002452085_00307_40942_2888.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20091229_091916_000001042085_00308_40943_2892.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20091229_105039_000002392085_00309_40944_2909.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20091229_105521_000001162085_00309_40944_2910.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20091229_122903_000005812085_00310_40945_2925.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20091229_132104_000003302085_00310_40945_2946.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20091229_154357_000001532085_00312_40947_2964.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20091229_154659_000004712085_00312_40947_2965.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20091229_172635_000002452085_00313_40948_2980.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20091229_190315_000000982085_00314_40949_2997.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20091229_190734_000003062085_00314_40949_2998.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20091229_204452_000000862085_00315_40950_3019.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20091229_204751_000002632085_00315_40950_3020.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20091229_222452_000001842085_00316_40951_3026.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

AUXILIARY FILES ANALYSIS completed

#####

MODULE STEPPING ANALYSIS

#####

Analysis will be performed from 2009-12-29 00:00:00 to 2009-12-29 23:59:59

Results will be exported to the directory: ./RESULTS/DAILY/_091229/MODULE_STEPPING

Creating directory ./RESULTS/DAILY/_091229/MODULE_STEPPING...


```
Creating directory ./RESULTS/DAILY/_091229/MODULE_STEPPING/FIRST_REFERENCE...
Creating directory ./RESULTS/DAILY/_091229/MODULE_STEPPING/SECOND_REFERENCE...
Creating directory ./RESULTS/DAILY/_091229/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE...
Deleting old files...
```

```
*****
*****
Creating images comparing with second reference...
```

```
Exporting results to the directory ../../RESULTS/DAILY/_091229/MODULE_STEPPING/SECOND_REFERENCE...
```

```
Polarization: H
Reference product: ASA_MS__0PNPDK20050922_062651_000000152041_00034_18625_0041.N1
Test product: ASA_MS__0PNPDK20091229_081002_000000162085_00307_40942_0948.N1
  H
  H
../../RESULTS/DAILY/_091229/MODULE_STEPPING/SECOND_REFERENCE/TGH_20091229_081002-20050922_062651.png
../../RESULTS/DAILY/_091229/MODULE_STEPPING/SECOND_REFERENCE/TPH_20091229_081002-20050922_062651.png
../../RESULTS/DAILY/_091229/MODULE_STEPPING/SECOND_REFERENCE/RGH_20091229_081002-20050922_062651.png
../../RESULTS/DAILY/_091229/MODULE_STEPPING/SECOND_REFERENCE/RPH_20091229_081002-20050922_062651.png
```

```
Polarization: V
Reference product: ASA_MS__0PNPDK20050923_055514_000000152041_00048_18639_0042.N1
Test product: ASA_MS__0PNPDK20091228_084139_000000162085_00293_40928_0947.N1
  V
  V
../../RESULTS/DAILY/_091229/MODULE_STEPPING/SECOND_REFERENCE/TGV_20091228_084139-20050923_055514.png
../../RESULTS/DAILY/_091229/MODULE_STEPPING/SECOND_REFERENCE/TPV_20091228_084139-20050923_055514.png
../../RESULTS/DAILY/_091229/MODULE_STEPPING/SECOND_REFERENCE/RGV_20091228_084139-20050923_055514.png
../../RESULTS/DAILY/_091229/MODULE_STEPPING/SECOND_REFERENCE/RPV_20091228_084139-20050923_055514.png
```

```
*****
*****
Creating images comparing with previous product reference...
```

```
Exporting results to the directory ../../RESULTS/DAILY/_091229/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE...
```

```
Polarization: H
Reference product: ASA_MS__0PNPDE20091228_015915_000000162085_00289_40924_0489.N1
Test product: ASA_MS__0PNPDK20091229_081002_000000162085_00307_40942_0948.N1
  H
  H
../../RESULTS/DAILY/_091229/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TGH_20091229_081002-20091228_015915.png
../../RESULTS/DAILY/_091229/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TPH_20091229_081002-20091228_015915.png
../../RESULTS/DAILY/_091229/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RGH_20091229_081002-20091228_015915.png
../../RESULTS/DAILY/_091229/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RPH_20091229_081002-20091228_015915.png
```

```
Polarization: V
Reference product: ASA_MS__0PNPDE20091227_023052_000000162085_00275_40910_0488.N1
Test product: ASA_MS__0PNPDK20091228_084139_000000162085_00293_40928_0947.N1
  V
  V
../../RESULTS/DAILY/_091229/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TGV_20091228_084139-20091227_023052.png
../../RESULTS/DAILY/_091229/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TPV_20091228_084139-20091227_023052.png
../../RESULTS/DAILY/_091229/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RGV_20091228_084139-20091227_023052.png
../../RESULTS/DAILY/_091229/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RPV_20091228_084139-20091227_023052.png
```

```
MODULE_STEPPING ANALYSIS completed
#####
```

```
CALIBRATION PULSES ANALYSIS
#####
Creating directory ./RESULTS/DAILY/_091229/CALIBRATION_PULSES...
```


ALL ROWS Analysis will be performed from 2009-12-29 00:00:00 to 2009-12-29 23:59:59

Analysing products WVS IS2 V/V
Writing image ../../RESULTS/DAILY/_091229//CALIBRATION_PULSES/Calibration_pulses_all_rows_WVS_IS2_VV.png...
Analysing products GM1 SS3 H/H
Writing image ../../RESULTS/DAILY/_091229//CALIBRATION_PULSES/Calibration_pulses_all_rows_GM1_SS3_HH.png...

TEMPORAL EVOLUTION Analysis will be performed from 2009-12-29 00:00:00 to 2009-12-29 23:59:59

Analysing products WVS IS2 V/V
Getting calibration pulses data for WVS IS2 V/V from 2009-12-29 00:00:00 to 2009-12-29 23:59:59. Rows: 1/5/9/13/17/21/25/29
Writing file ./RESULTS/DAILY/_091229/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2009-12-29_1.dat...
Writing ../../RESULTS/DAILY/_091229//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_1.png...
Writing ../../RESULTS/DAILY/_091229//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_1.png...

Getting calibration pulses data for WVS IS2 V/V from 2009-12-29 00:00:00 to 2009-12-29 23:59:59. Rows: 2/6/10/14/18/22/26/30
Writing file ./RESULTS/DAILY/_091229/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2009-12-29_2.dat...
Writing ../../RESULTS/DAILY/_091229//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_2.png...
Writing ../../RESULTS/DAILY/_091229//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_2.png...

Getting calibration pulses data for WVS IS2 V/V from 2009-12-29 00:00:00 to 2009-12-29 23:59:59. Rows: 3/7/11/15/19/23/27/31
Writing file ./RESULTS/DAILY/_091229/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2009-12-29_3.dat...
Writing ../../RESULTS/DAILY/_091229//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_3.png...
Writing ../../RESULTS/DAILY/_091229//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_3.png...

Getting calibration pulses data for WVS IS2 V/V from 2009-12-29 00:00:00 to 2009-12-29 23:59:59. Rows: 4/8/12/16/20/24/28/32
Writing file ./RESULTS/DAILY/_091229/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2009-12-29_4.dat...
Writing ../../RESULTS/DAILY/_091229//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_4.png...
Writing ../../RESULTS/DAILY/_091229//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_4.png...

Analysing products GM1 SS3 H/H
Getting calibration pulses data for GM1 SS3 H/H from 2009-12-29 00:00:00 to 2009-12-29 23:59:59. Rows: 1/5/9/13/17/21/25/29
Writing file ./RESULTS/DAILY/_091229/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2009-12-29_1.dat...
Writing ../../RESULTS/DAILY/_091229//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_1.png...
Writing ../../RESULTS/DAILY/_091229//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_1.png...

Getting calibration pulses data for GM1 SS3 H/H from 2009-12-29 00:00:00 to 2009-12-29 23:59:59. Rows: 2/6/10/14/18/22/26/30
Writing file ./RESULTS/DAILY/_091229/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2009-12-29_2.dat...
Writing ../../RESULTS/DAILY/_091229//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_2.png...
Writing ../../RESULTS/DAILY/_091229//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_2.png...

Getting calibration pulses data for GM1 SS3 H/H from 2009-12-29 00:00:00 to 2009-12-29 23:59:59. Rows: 3/7/11/15/19/23/27/31
Writing file ./RESULTS/DAILY/_091229/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2009-12-29_3.dat...
Writing ../../RESULTS/DAILY/_091229//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_3.png...
Writing ../../RESULTS/DAILY/_091229//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_3.png...

Getting calibration pulses data for GM1 SS3 H/H from 2009-12-29 00:00:00 to 2009-12-29 23:59:59. Rows: 4/8/12/16/20/24/28/32
Writing file ./RESULTS/DAILY/_091229/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2009-12-29_4.dat...
Writing ../../RESULTS/DAILY/_091229//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_4.png...
Writing ../../RESULTS/DAILY/_091229//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_4.png...

CALIBRATION PULSES ANALYSIS completed
#####

DOPPLER ANALYSIS

Creating directory ./RESULTS/DAILY/_091229/DOPPLER...

DOPPLER ANX Analysis will be performed from 2009-12-29 00:00:00 to 2009-12-29 23:59:59

Analysing products WVS IS2 V/V
Getting doppler data for WVS IS2 V/V from 2009-12-29 00:00:00 to 2009-12-29 23:59:59...
Writing file ./RESULTS/DAILY/_091229/DOPPLER/Doppler_data_WVS_IS2_VV_2009-12-29.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/_091229/DOPPLER/DOPPLER_ANX_WVS_IS2_VV.png...

Analysing products GM1 SS1 H/H
Getting doppler data for GM1 SS1 H/H from 2009-12-29 00:00:00 to 2009-12-29 23:59:59...
Writing file ./RESULTS/DAILY/_091229/DOPPLER/Doppler_data_GM1_SS1_HH_2009-12-29.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/_091229/DOPPLER/DOPPLER_ANX_GM1_SS1_HH.png...

DOPPLER JUMPS Analysis will be performed on WSM products from 2009-12-29 00:00:00 to 2009-12-29 23:59:59

Analysing by default products WSM
Getting doppler jumps data for WSM from 2009-12-29 00:00:00 to 2009-12-29 23:59:59...
Writing file ./RESULTS/DAILY/_091229/DOPPLER/Doppler_Jumps_data_WSM_2009-12-29.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/_091229/DOPPLER/DOPPLER_JUMPS_ANX_WSM.png...
Writing file ../../RESULTS/DAILY/_091229/DOPPLER/DOPPLER_JUMPS_Date_WSM.png...

DOPPLER MAP Analysis will be performed from 2009-12-29 00:00:00 to 2009-12-29 23:59:59

Analysing products WVS IS2 V/V
Loading predicted doppler values....
Phase: descending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -32.684269 Hz
Writing file ../../RESULTS/DAILY/_091229//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_WVS_IS2_VV_desc.jpg...
Writing file ../../RESULTS/DAILY/_091229//DOPPLER/DOPPLER_Absolute_WVS_IS2_VV_desc.jpg...

Loading predicted doppler values....
Phase: ascending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -28.830262 Hz
Writing file ../../RESULTS/DAILY/_091229//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_WVS_IS2_VV_asc.jpg...
Writing file ../../RESULTS/DAILY/_091229//DOPPLER/DOPPLER_Absolute_WVS_IS2_VV_asc.jpg...

Analysing products GM1 SS1 H/H
Loading predicted doppler values....
Phase: descending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -22.975435 Hz

Writing file ../../RESULTS/DAILY/_091229//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_GM1_SS1_HH_desc.jpg...
Writing file ../../RESULTS/DAILY/_091229//DOPPLER/DOPPLER_Absolute_GM1_SS1_HH_desc.jpg...

Loading predicted doppler values...
Phase: ascending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -22.951818 Hz
Writing file ../../RESULTS/DAILY/_091229//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_GM1_SS1_HH_asc.jpg...
Writing file ../../RESULTS/DAILY/_091229//DOPPLER/DOPPLER_Absolute_GM1_SS1_HH_asc.jpg...

DOPPLER ANALYSIS completed
#####

CHIRP ANALYSIS

Creating directory ./RESULTS/DAILY/_091229/CHIRP...

CHIRP Analysis will be performed from 2009-12-29 00:00:00 to 2009-12-29 23:59:59

Analysing products WSM SS1 H/H

Getting ScaleFactor data for WSM SS1 H/H from 2009-12-29 00:00:00 to 2009-12-29 23:59:59...
Writing file ./RESULTS/DAILY/_091229/CHIRP/ScaleFactor_data_WSM_SS1_HH_2009-12-29.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/_091229/CHIRP/ScaleFactor_ANX_WSM_SS1_HH.png...
Writing file ../../RESULTS/DAILY/_091229/CHIRP/ScaleFactor_DATE_WSM_SS1_HH.png...

Analysing products WSM SS1 V/V

Getting ScaleFactor data for WSM SS1 V/V from 2009-12-29 00:00:00 to 2009-12-29 23:59:59...
Writing file ./RESULTS/DAILY/_091229/CHIRP/ScaleFactor_data_WSM_SS1_VV_2009-12-29.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/_091229/CHIRP/ScaleFactor_ANX_WSM_SS1_VV.png...
Writing file ../../RESULTS/DAILY/_091229/CHIRP/ScaleFactor_DATE_WSM_SS1_VV.png...

CHIRP ANALYSIS completed
#####

RAW DATA ANALYSIS

Analysis will be performed from 2009-12-29 00:00:00 to 2009-12-29 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_091229/RAW_DATA

Creating directory ./RESULTS/DAILY/_091229/RAW_DATA...

Getting raw data for WVS from 2009-12-29 00:00:00 to 2009-12-29 23:59:59...
Writing file ./RESULTS/DAILY/_091229/RAW_DATA/Raw_data_WVS_2009-12-29.dat...
Running IDL program to create graphs...

Creating image ../../RESULTS/DAILY/_091229/RAW_DATA/Raw_data_WVS_input_mean.png...
Creating image ../../RESULTS/DAILY/_091229/RAW_DATA/Raw_data_WVS_input_stdev.png...

Creating image ../../RESULTS/DAILY/_091229/RAW_DATA/Raw_data_WVS_gain_imbalance.png...

Getting raw data for IMM from 2009-12-29 00:00:00 to 2009-12-29 23:59:59...
Writing file ./RESULTS/DAILY/_091229/RAW_DATA/Raw_data_IMM_2009-12-29.dat...
Running IDL program to create graphs...

Creating image ../../RESULTS/DAILY/_091229/RAW_DATA/Raw_data_IMM_input_mean.png...
Creating image ../../RESULTS/DAILY/_091229/RAW_DATA/Raw_data_IMM_input_stdev.png...
Creating image ../../RESULTS/DAILY/_091229/RAW_DATA/Raw_data_IMM_gain_imbalance.png...

RAW DATA ANALYSIS completed
#####

TELEMETRY ANALYSIS

Analysis will be performed from 2009-12-29 00:00:00 to 2009-12-29 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_091229/TELEMETRY

Creating directory ./RESULTS/DAILY/_091229/TELEMETRY...

Looking for gaps and missing lines in WVS products...

Checking 25 products from PDE...
Checking 23 products from PDK...

Looking for gaps and missing lines in GM1 products...

Checking 29 products from PDE...
Checking 47 products from PDK...

Looking for gaps and missing lines in APM products...

Checking 2 products from PDE...
No products from PDK...

Looking for gaps and missing lines in IMM products...

Checking 26 products from PDE...
Checking 5 products from PDK...

Looking for gaps and missing lines in WSM products...

Checking 31 products from PDE...
Found product..ASA_WSM_1PNPDE20091229_154046_000002202085_00312_40947_2142.N1 / 4 gaps / 1024 missing lines
Checking 15 products from PDK...

Creating graph of missing lines and gaps...

Creating image: ./RESULTS/DAILY/_091229/TELEMETRY/TELEMETRY_Missing_lines.png...
Creating image: ./RESULTS/DAILY/_091229/TELEMETRY/TELEMETRY_Gaps.png...

TELEMETRY ANALYSIS completed
#####

BROWSE PRODUCTS ANALYSIS

Analysis will be performed on 2009-12-29

Scanning directory /nfs-store/ASAR_Data//ASA_GM_BP...

Results will be exported to the directory: /nfs-store/ASAR_Data//ASA_GM_BP/JPG/20091229/

Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091229_003650_000000842085_00303_40938_2003.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091229_004012_000008822085_00303_40938_2004.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091229_005545_000001202085_00303_40938_2006.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091229_011427_000003742085_00303_40938_2010.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091229_015202_000006282085_00303_40938_2021.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091229_021318_000002052085_00304_40939_2027.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091229_022312_000012322085_00304_40939_2026.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091229_024629_000000842085_00304_40939_2023.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091229_032702_000003202085_00304_40939_2045.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091229_033737_000002232085_00304_40939_2052.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091229_034934_000003982085_00305_40940_2053.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091229_035750_000014382085_00305_40940_2049.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091229_042416_000002772085_00305_40940_2046.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091229_044852_000000722085_00305_40940_2064.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091229_045301_000001022085_00305_40940_2065.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091229_050256_000001142085_00305_40940_2070.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091229_053413_000000662085_00306_40941_2076.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091229_053707_000014682085_00306_40941_2075.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091229_060317_000002712085_00306_40941_2071.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091229_204238_000001262085_00315_40950_2158.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091229_204625_000000722085_00315_40950_2159.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091229_205630_000002952085_00315_40950_2160.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091229_213452_000005672085_00315_40950_2163.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091229_221127_000003382085_00316_40951_2172.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091229_221834_000000842085_00316_40951_2174.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091229_223203_000001752085_00316_40951_2177.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091229_230609_000000902085_00316_40951_2176.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091229_230752_000000902085_00316_40951_2179.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091229_231528_000005672085_00316_40951_2182.N1 ...

ANALYSIS COMPLETED: 29 GM browse products to see...

Scanning directory /nfs-store/ASAR_Data//ASA_AP_BP...

Results will be exported to the directory: /nfs-store/ASAR_Data//ASA_AP_BP/JPG/20091229/

Stripping browse product /nfs-store/ASAR_Data//ASA_AP_BP/ASA_AP_BPZPDE20091229_174123_000000432085_00313_40948_2153.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_AP_BP/ASA_AP_BPZPDE20091229_221023_000000442085_00316_40951_2189.N1 ...

ANALYSIS COMPLETED: 2 AP browse products to see...

Scanning directory /nfs-store/ASAR_Data//ASA_IM_BP...

Results will be exported to the directory: /nfs-store/ASAR_Data//ASA_IM_BP/JPG/20091229/

Stripping browse product /nfs-store/ASAR_Data//ASA_IM_BP/ASA_IM_BPZPDE20091229_003818_000001032085_00303_40938_2002.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_IM_BP/ASA_IM_BPZPDE20091229_012827_000005842085_00303_40938_2016.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_IM_BP/ASA_IM_BPZPDE20091229_024354_000000372085_00304_40939_2018.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_IM_BP/ASA_IM_BPZPDE20091229_024756_000000372085_00304_40939_2019.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_IM_BP/ASA_IM_BPZPDE20091229_030915_000003032085_00304_40939_2036.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_IM_BP/ASA_IM_BPZPDE20091229_031505_000001622085_00304_40939_2037.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_IM_BP/ASA_IM_BPZPDE20091229_034413_000000392085_00305_40940_2040.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_IM_BP/ASA_IM_BPZPDE20091229_042145_000001422085_00305_40940_2041.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_IM_BP/ASA_IM_BPZPDE20091229_042854_000000622085_00305_40940_2042.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_IM_BP/ASA_IM_BPZPDE20091229_045007_000001622085_00305_40940_2060.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_IM_BP/ASA_IM_BPZPDE20091229_045447_000000922085_00305_40940_2061.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_IM_BP/ASA_IM_BPZPDE20091229_053023_000002182085_00306_40941_2067.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_IM_BP/ASA_IM_BPZPDE20091229_053524_000000912085_00306_40941_2068.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_IM_BP/ASA_IM_BPZPDE20091229_060136_000000922085_00306_40941_2069.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_IM_BP/ASA_IM_BPZPDE20091229_063129_000001622085_00306_40941_2072.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_IM_BP/ASA_IM_BPZPDE20091229_074607_000001762085_00307_40942_2084.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_IM_BP/ASA_IM_BPZPDE20091229_075200_000001112085_00307_40942_2085.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_IM_BP/ASA_IM_BPZPDE20091229_095217_000004432085_00308_40943_2114.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_IM_BP/ASA_IM_BPZPDE20091229_113134_000003432085_00309_40944_2129.N1 ...



Stripping browse product /nfs-store/ASAR_Data//ASA_IM_BP/ASA_IM_BPZPDE20091229_114023_00000922085_00309_40944_2138.N1 ...
 Stripping browse product /nfs-store/ASAR_Data//ASA_IM_BP/ASA_IM_BPZPDE20091229_153219_000001422085_00312_40947_2148.N1 ...
 Stripping browse product /nfs-store/ASAR_Data//ASA_IM_BP/ASA_IM_BPZPDE20091229_164231_000001622085_00312_40947_2143.N1 ...
 Stripping browse product /nfs-store/ASAR_Data//ASA_IM_BP/ASA_IM_BPZPDE20091229_173958_00000672085_00313_40948_2152.N1 ...
 Stripping browse product /nfs-store/ASAR_Data//ASA_IM_BP/ASA_IM_BPZPDE20091229_174431_000001142085_00313_40948_2154.N1 ...
 Stripping browse product /nfs-store/ASAR_Data//ASA_IM_BP/ASA_IM_BPZPDE20091229_182236_000002332085_00313_40948_2150.N1 ...
 Stripping browse product /nfs-store/ASAR_Data//ASA_IM_BP/ASA_IM_BPZPDE20091229_202618_00000402085_00314_40949_2170.N1 ...

ANALYSIS COMPLETED: 26 IM browse products to see...

Scanning directory /nfs-store/ASAR_Data//ASA_WS_BP...

Results will be exported to the directory: /nfs-store/ASAR_Data//ASA_WS_BP/JPG/20091229/

Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091229_013904_000002812085_00303_40938_2017.N1 ...
 Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091229_021142_00000922085_00304_40939_2020.N1 ...
 Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091229_021652_000003672085_00304_40939_2034.N1 ...
 Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091229_031833_000002942085_00304_40939_2038.N1 ...
 Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091229_035617_000000862085_00305_40940_2039.N1 ...
 Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091229_045735_000002022085_00305_40940_2062.N1 ...
 Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091229_050117_00000922085_00305_40940_2063.N1 ...
 Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091229_073253_000001832085_00307_40942_2083.N1 ...
 Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091229_075555_000001832085_00307_40942_2086.N1 ...
 Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091229_080048_000000862085_00307_40942_2087.N1 ...
 Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091229_091129_000001712085_00308_40943_2105.N1 ...
 Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091229_092014_000001532085_00308_40943_2106.N1 ...
 Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091229_100048_000002812085_00308_40943_2122.N1 ...
 Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091229_103832_000000982085_00309_40944_2123.N1 ...
 Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091229_104502_000000862085_00309_40944_2124.N1 ...
 Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091229_114229_000001832085_00309_40944_2139.N1 ...
 Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091229_141633_000001472085_00311_40946_2145.N1 ...
 Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091229_150019_000001532085_00311_40946_2146.N1 ...
 Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091229_150519_000001282085_00311_40946_2147.N1 ...
 Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091229_154046_000002202085_00312_40947_2142.N1 ...
 Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091229_155352_000001102085_00312_40947_2149.N1 ...
 Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091229_164622_000001282085_00312_40947_2144.N1 ...
 Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091229_174639_000000862085_00313_40948_2155.N1 ...
 Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091229_182651_000001162085_00313_40948_2151.N1 ...
 Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091229_200218_000004282085_00314_40949_2156.N1 ...
 Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091229_201623_000002632085_00314_40949_2157.N1 ...
 Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091229_205142_000002872085_00315_40950_2171.N1 ...
 Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091229_214427_000004162085_00315_40950_2169.N1 ...
 Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091229_223504_000004282085_00316_40951_2190.N1 ...
 Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091229_232502_000004162085_00316_40951_2188.N1 ...

ANALYSIS COMPLETED: 30 WS browse products to see...

BROWSE PRODUCTS ANALYSIS completed

#####

HTML REPORT generation

#####

Building file ./RESULTS/DAILY/_091229/asarReport.html...

Building DATA SUMMARY section...

Building AUXILIARY FILES ANALYSIS section...

Building MODULE STEPPING ANALYSIS section...

Building CALIBRATION PULSES ANALYSIS section...

Building DOPPLER ANALYSIS section...

Building CHIRP ANALYSIS section...

Building RAW DATA ANALYSIS section...

Building TELEMETRY ANALYSIS section...

HTML REPORT generation completed

#####



Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
ASA_APM_1PNPDE20091229_174123_000000432085_00313_40948_2153.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20091229_221023_000000442085_00316_40951_2189.N1	OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_GM1_1PNPDE20091229_003650_000000842085_00303_40938_2003.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091229_004012_000008822085_00303_40938_2004.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091229_005545_000001202085_00303_40938_2006.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091229_011427_000003742085_00303_40938_2010.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091229_015202_000006282085_00303_40938_2021.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091229_021318_000002052085_00304_40939_2027.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091229_022312_000012332085_00304_40939_2026.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091229_024629_000008842085_00304_40939_2023.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091229_032702_000003202085_00304_40939_2045.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091229_033737_000002232085_00304_40939_2052.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091229_034934_000003982085_00305_40940_2053.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091229_035750_000014382085_00305_40940_2049.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091229_042416_000002772085_00305_40940_2046.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091229_044852_000000722085_00305_40940_2064.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091229_045301_000001022085_00305_40940_2065.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091229_050256_000001142085_00305_40940_2070.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091229_053413_000000662085_00306_40941_2076.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091229_053707_000014682085_00306_40941_2075.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091229_060317_000002712085_00306_40941_2071.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091229_204238_000001262085_00315_40950_2158.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091229_204625_000000722085_00315_40950_2159.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091229_205630_000002952085_00315_40950_2160.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091229_213452_000005672085_00315_40950_2163.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091229_221127_000003382085_00316_40951_2172.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091229_221834_000008842085_00316_40951_2174.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091229_223203_000001752085_00316_40951_2177.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091229_230609_000000902085_00316_40951_2176.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091229_230752_000000902085_00316_40951_2179.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091229_231528_000005672085_00316_40951_2182.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091229_062931_000001142085_00306_40941_2856.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091229_064334_000001142085_00306_40941_2857.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091229_071920_000007612085_00307_40942_2859.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091229_073056_000001082085_00307_40942_2873.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091229_073614_000002472085_00307_40942_2874.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091229_074912_000001692085_00307_40942_2875.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091229_075403_000001022085_00307_40942_2876.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091229_075904_000000962085_00307_40942_2877.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091229_081121_000005552085_00307_40942_2879.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091229_082451_000000722085_00307_40942_2880.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091229_090117_000006042085_00308_40943_2882.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091229_092547_000003922085_00308_40943_2897.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091229_095042_000000902085_00308_40943_2898.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091229_100530_000000662085_00308_40943_2900.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091229_104013_000002832085_00309_40944_2901.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091229_104637_000002352085_00309_40944_2903.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091229_113726_000001812085_00309_40944_2916.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091229_114549_000000842085_00309_40944_2917.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091229_121751_000006652085_00310_40945_2919.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091229_125500_000005492085_00310_40945_2929.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091229_130418_000001082085_00310_40945_2930.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091229_131155_000003682085_00310_40945_2931.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091229_132640_000000662085_00310_40945_2932.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091229_133449_000003922085_00310_40945_2935.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091229_135340_000008842085_00311_40946_2937.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091229_135612_000008702085_00311_40946_2938.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091229_140933_000004162085_00311_40946_2950.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091229_143214_000004592085_00311_40946_2952.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091229_145229_000004652085_00311_40946_2953.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091229_150255_000001322085_00311_40946_2955.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091229_152855_000002052085_00312_40947_2956.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091229_153453_000003322085_00312_40947_2958.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091229_155549_000007312085_00312_40947_2970.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091229_163305_000005672085_00312_40947_2972.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091229_170808_000010942085_00313_40948_2974.N1					OK	OK	OK	OK

ASA_GM1_1PNPDK20091229_172509_000000722085_00313_40948_2985.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091229_173056_000005432085_00313_40948_2986.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091229_174228_000001202085_00313_40948_2987.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091229_181339_000005372085_00313_40948_2989.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091229_184838_000008702085_00314_40949_2990.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091229_190453_000001572085_00314_40949_3003.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091229_191248_000005312085_00314_40949_3004.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091229_195418_000004712085_00314_40949_3009.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091229_202049_000003322085_00314_40949_3008.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091229_202709_000005492085_00314_40949_3010.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091229_204030_000000662085_00315_40950_3007.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091229_204235_000000662085_00315_40950_3012.N1	OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_IMM_1PNPDE20091229_003818_000001032085_00303_40938_2002.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091229_012827_000005842085_00303_40938_2016.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091229_024354_000000372085_00304_40939_2018.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091229_024756_000000372085_00304_40939_2019.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091229_030915_000003032085_00304_40939_2036.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091229_031505_000001622085_00304_40939_2037.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091229_034413_000000392085_00305_40940_2040.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091229_042145_000001422085_00305_40940_2041.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091229_042854_000000622085_00305_40940_2042.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091229_045007_000001622085_00305_40940_2060.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091229_045447_000000922085_00305_40940_2061.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091229_053023_000002182085_00306_40941_2067.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091229_053524_000000912085_00306_40941_2068.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091229_060136_000000922085_00306_40941_2069.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091229_063129_000001622085_00306_40941_2072.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091229_074607_000001762085_00307_40942_2084.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091229_075200_000001112085_00307_40942_2085.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091229_095217_000004432085_00308_40943_2114.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091229_113134_000003432085_00309_40944_2129.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091229_114023_000000922085_00309_40944_2138.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091229_153219_000001422085_00312_40947_2148.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091229_164231_000001622085_00312_40947_2143.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091229_173958_000000672085_00313_40948_2152.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091229_174431_000001142085_00313_40948_2154.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091229_182236_000002332085_00313_40948_2150.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091229_202618_000000402085_00314_40949_2170.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20091229_063459_000002332085_00306_40941_2864.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20091229_105748_000001682085_00309_40944_2911.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20091229_131801_000001622085_00310_40945_2945.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20091229_134815_000000392085_00311_40946_2947.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20091229_222830_000002032085_00316_40951_3027.N1					OK	OK	OK	OK


Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WSM_1PNPDE20091229_013904_000002812085_00303_40938_2017.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091229_021142_00000922085_00304_40939_2020.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091229_021652_000003672085_00304_40939_2034.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091229_031833_000002942085_00304_40939_2038.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091229_035617_000000862085_00305_40940_2039.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091229_045735_000002022085_00305_40940_2062.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091229_050117_000000922085_00305_40940_2063.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091229_073253_000001842085_00307_40942_2083.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091229_075555_000001842085_00307_40942_2086.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091229_080048_000000862085_00307_40942_2087.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091229_091129_000001712085_00308_40943_2105.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091229_092014_000001532085_00308_40943_2106.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091229_100048_000002812085_00308_40943_2122.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091229_103832_000000982085_00309_40944_2123.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091229_104502_000000862085_00309_40944_2124.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091229_114229_000001842085_00309_40944_2139.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091229_141633_000001472085_00311_40946_2145.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091229_150019_000001532085_00311_40946_2146.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091229_150519_000001282085_00311_40946_2147.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091229_154046_000002202085_00312_40947_2142.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091229_155352_000001102085_00312_40947_2149.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091229_164622_000001282085_00312_40947_2144.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091229_174639_000000862085_00313_40948_2155.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091229_182651_000001162085_00313_40948_2151.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091229_200218_000004282085_00314_40949_2156.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091229_201623_000002632085_00314_40949_2157.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091229_205142_000002882085_00315_40950_2171.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091229_214427_000004162085_00315_40950_2169.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091229_223504_000004282085_00316_40951_2190.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091229_232502_000004162085_00316_40951_2188.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20091229_064005_000002022085_00306_40941_2866.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20091229_082045_000002452085_00307_40942_2888.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20091229_091916_000001042085_00308_40943_2892.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20091229_105039_000002392085_00309_40944_2909.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20091229_105521_000001162085_00309_40944_2910.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20091229_122903_000005812085_00310_40945_2925.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20091229_132104_000003302085_00310_40945_2946.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20091229_154357_000001532085_00312_40947_2964.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20091229_154659_000004712085_00312_40947_2965.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20091229_172635_000002452085_00313_40948_2980.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20091229_190315_000000982085_00314_40949_2997.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20091229_190734_000003062085_00314_40949_2998.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20091229_204452_000000862085_00315_40950_3019.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20091229_204751_000002632085_00315_40950_3020.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20091229_222452_000001842085_00316_40951_3026.N1					OK	OK	OK	OK


Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WVS_1PNPDE20091229_000337_000002842085_00302_40937_1992.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091229_000737_000017092085_00302_40937_2005.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091229_005750_000009552085_00303_40938_2008.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091229_012046_000003752085_00303_40938_2007.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091229_014342_000002402085_00303_40938_2009.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091229_014657_000002552085_00303_40938_2022.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091229_020309_000004642085_00304_40939_2025.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091229_024841_000010192085_00304_40939_2024.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091229_030526_00000302085_00304_40939_2044.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091229_032412_000001202085_00304_40939_2043.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091229_033227_000002692085_00304_40939_2051.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091229_034120_000001192085_00304_40939_2050.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091229_034538_000001942085_00305_40940_2048.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091229_043006_000007342085_00305_40940_2047.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091229_044206_000003602085_00305_40940_2066.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091229_050457_000014242085_00305_40940_2074.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091229_060752_000009292085_00306_40941_2073.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091229_210128_000019642085_00315_40950_2161.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091229_215123_000002552085_00315_40950_2162.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091229_215454_000008242085_00315_40950_2173.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091229_222007_000002402085_00316_40951_2175.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091229_224213_000013942085_00316_40951_2178.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091229_230927_000003152085_00316_40951_2180.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091229_233157_000003002085_00316_40951_2181.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091229_233627_000016642085_00316_40951_2195.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091229_062306_000003452085_00306_40941_2855.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091229_064533_000019792085_00306_40941_2858.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091229_080307_000003752085_00307_40942_2878.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091229_082609_000020542085_00307_40942_2881.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091229_093222_000010492085_00308_40943_2899.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091229_100645_000018592085_00308_40943_2902.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091229_110202_000001642085_00309_40944_2914.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091229_110704_000014092085_00309_40944_2915.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091229_114720_000017842085_00309_40944_2918.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091229_123843_000009292085_00310_40945_2928.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091229_130611_000003002085_00310_40945_2933.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091229_132756_000003752085_00310_40945_2934.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091229_134124_000003742085_00310_40945_2936.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091229_134901_000000592085_00311_40946_2939.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091229_142434_000004192085_00311_40946_2951.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091229_143956_000007042085_00311_40946_2954.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091229_150823_000011842085_00311_40946_2957.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091229_160800_000014542085_00312_40947_2971.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091229_164859_000011092085_00312_40947_2973.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091229_174807_000014842085_00313_40948_2988.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091229_183347_000008542085_00313_40948_2991.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091229_192141_000019042085_00314_40949_3006.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091229_201011_000003302085_00314_40949_3013.N1					OK	OK	OK	OK





Calibration pulses for GM1 SS3 H/H



Calibration pulses for GM1 SS3 H/H




Calibration pulses for GM1 SS3 H/H




rows: _ 3 _ 7 _ 11 _ 15 _ 19 _ 23 _ 27 _ 31


Calibration pulses for GM1 SS3 H/H




29-Dec



29-Dec




29-Dec




29-Dec

rows: _ 4 _ 8 _ 12 _ 16 _ 20 _ 24 _ 28 _ 32


Calibration pulses for WVS IS2 V/V







Calibration pulses for WVS IS2 V/V




Calibration pulses for WVS IS2 V/V






Calibration pulses for WVS IS2 V/V





rows: — 4 — 8 — 12 — 16 — 20 — 24 — 28 — 32













^{29-Dec}
rows: _ 1 _ 5 _ 9 _ 13 _ 17 _ 21 _ 25 _ 29















rows: _ 1 _ 5 _ 9 _ 13 _ 17 _ 21 _ 25 _ 29




rows: _ 2 _ 6 _ 10 _ 14 _ 18 _ 22 _ 26 _ 30





rows: _ 3 _ 7 _ 11 _ 15 _ 19 _ 23 _ 27 _ 31




rows: _ 4 _ 8 _ 12 _ 16 _ 20 _ 24 _ 28 _ 32









Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion			
ASA_APM_1PNPDE20091229_174123_000000432085_00313_40948_2153.N1						IS6	V/H	85	40948 313 5.03
ASA_APM_1PNPDE20091229_221023_000000442085_00316_40951_2189.N1						IS3	H/H	85	40951 316 5.03

Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_GM1_1PNPDE20091229_003650_000000842085_00303_40938_2003.N1						SS1	H/H	85	40938	303	5.03
ASA_GM1_1PNPDE20091229_004012_000008822085_00303_40938_2004.N1						SS1	H/H	85	40938	303	5.03
ASA_GM1_1PNPDE20091229_005545_000001202085_00303_40938_2006.N1						SS1	H/H	85	40938	303	5.03
ASA_GM1_1PNPDE20091229_011427_000003742085_00303_40938_2010.N1						SS1	H/H	85	40938	303	5.03
ASA_GM1_1PNPDE20091229_015202_000006282085_00303_40938_2021.N1						SS1	H/H	85	40938	303	5.03
ASA_GM1_1PNPDE20091229_021318_000002052085_00304_40939_2027.N1						SS1	H/H	85	40939	304	5.03
ASA_GM1_1PNPDE20091229_022312_000012332085_00304_40939_2026.N1						SS1	H/H	85	40939	304	5.03
ASA_GM1_1PNPDE20091229_024629_000000842085_00304_40939_2023.N1						SS1	H/H	85	40939	304	5.03
ASA_GM1_1PNPDE20091229_032702_000003202085_00304_40939_2045.N1						SS1	H/H	85	40939	304	5.03
ASA_GM1_1PNPDE20091229_033737_000002232085_00304_40939_2052.N1						SS1	H/H	85	40939	304	5.03
ASA_GM1_1PNPDE20091229_034934_000003982085_00305_40940_2053.N1						SS1	H/H	85	40940	305	5.03
ASA_GM1_1PNPDE20091229_035750_000014382085_00305_40940_2049.N1						SS1	H/H	85	40940	305	5.03
ASA_GM1_1PNPDE20091229_042416_000002772085_00305_40940_2046.N1						SS1	H/H	85	40940	305	5.03
ASA_GM1_1PNPDE20091229_044852_000000722085_00305_40940_2064.N1						SS1	H/H	85	40940	305	5.03
ASA_GM1_1PNPDE20091229_045301_000001022085_00305_40940_2065.N1						SS1	H/H	85	40940	305	5.03
ASA_GM1_1PNPDE20091229_050256_000001142085_00305_40940_2070.N1						SS1	H/H	85	40940	305	5.03
ASA_GM1_1PNPDE20091229_053413_000000662085_00306_40941_2076.N1						SS1	H/H	85	40941	306	5.03
ASA_GM1_1PNPDE20091229_053707_000014682085_00306_40941_2075.N1						SS1	H/H	85	40941	306	5.03
ASA_GM1_1PNPDE20091229_060317_000002712085_00306_40941_2071.N1						SS1	H/H	85	40941	306	5.03
ASA_GM1_1PNPDK20091229_062931_000001142085_00306_40941_2856.N1						SS1	H/H	85	40941	306	5.03
ASA_GM1_1PNPDK20091229_064334_000001142085_00306_40941_2857.N1						SS1	H/H	85	40941	306	5.03
ASA_GM1_1PNPDK20091229_071920_000007612085_00307_40942_2859.N1						SS1	H/H	85	40942	307	5.03
ASA_GM1_1PNPDK20091229_073056_000001082085_00307_40942_2873.N1						SS1	H/H	85	40942	307	5.03
ASA_GM1_1PNPDK20091229_073614_000002472085_00307_40942_2874.N1						SS1	H/H	85	40942	307	5.03
ASA_GM1_1PNPDK20091229_074912_000001692085_00307_40942_2875.N1						SS1	H/H	85	40942	307	5.03
ASA_GM1_1PNPDK20091229_075403_000001022085_00307_40942_2876.N1						SS1	H/H	85	40942	307	5.03
ASA_GM1_1PNPDK20091229_075904_000000962085_00307_40942_2877.N1						SS1	H/H	85	40942	307	5.03
ASA_GM1_1PNPDK20091229_081121_000005552085_00307_40942_2879.N1						SS1	H/H	85	40942	307	5.03
ASA_GM1_1PNPDK20091229_082451_000000722085_00307_40942_2880.N1						SS1	H/H	85	40942	307	5.03
ASA_GM1_1PNPDK20091229_090117_000006042085_00308_40943_2882.N1						SS1	H/H	85	40943	308	5.03
ASA_GM1_1PNPDK20091229_092547_000003922085_00308_40943_2897.N1						SS1	H/H	85	40943	308	5.03
ASA_GM1_1PNPDK20091229_095042_000000902085_00308_40943_2898.N1						SS1	H/H	85	40943	308	5.03
ASA_GM1_1PNPDK20091229_100530_000000662085_00308_40943_2900.N1						SS1	H/H	85	40943	308	5.03
ASA_GM1_1PNPDK20091229_104013_000002832085_00309_40944_2901.N1						SS1	H/H	85	40944	309	5.03
ASA_GM1_1PNPDK20091229_104637_000002352085_00309_40944_2903.N1						SS1	H/H	85	40944	309	5.03
ASA_GM1_1PNPDK20091229_113726_000001812085_00309_40944_2916.N1						SS1	H/H	85	40944	309	5.03
ASA_GM1_1PNPDK20091229_114549_000000842085_00309_40944_2917.N1						SS1	H/H	85	40944	309	5.03
ASA_GM1_1PNPDK20091229_121751_000006652085_00310_40945_2919.N1						SS1	H/H	85	40945	310	5.03
ASA_GM1_1PNPDK20091229_125500_000005492085_00310_40945_2929.N1						SS1	H/H	85	40945	310	5.03
ASA_GM1_1PNPDK20091229_130418_000001082085_00310_40945_2930.N1						SS1	H/H	85	40945	310	5.03
ASA_GM1_1PNPDK20091229_131155_000003682085_00310_40945_2931.N1						SS1	H/H	85	40945	310	5.03
ASA_GM1_1PNPDK20091229_132640_000000662085_00310_40945_2932.N1						SS1	H/H	85	40945	310	5.03
ASA_GM1_1PNPDK20091229_133449_000003922085_00310_40945_2935.N1						SS1	H/H	85	40945	310	5.03
ASA_GM1_1PNPDK20091229_135340_000000842085_00311_40946_2937.N1						SS1	H/H	85	40946	311	5.03
ASA_GM1_1PNPDK20091229_135612_000008702085_00311_40946_2938.N1						SS1	H/H	85	40946	311	5.03
ASA_GM1_1PNPDK20091229_140933_000004162085_00311_40946_2950.N1						SS1	H/H	85	40946	311	5.03
ASA_GM1_1PNPDK20091229_143214_000004592085_00311_40946_2952.N1						SS1	H/H	85	40946	311	5.03
ASA_GM1_1PNPDK20091229_145229_000004652085_00311_40946_2953.N1						SS1	H/H	85	40946	311	5.03
ASA_GM1_1PNPDK20091229_150255_000001322085_00311_40946_2955.N1						SS1	H/H	85	40946	311	5.03
ASA_GM1_1PNPDK20091229_152855_000002052085_00312_40947_2956.N1						SS1	H/H	85	40947	312	5.03
ASA_GM1_1PNPDK20091229_153453_000003322085_00312_40947_2958.N1						SS1	H/H	85	40947	312	5.03
ASA_GM1_1PNPDK20091229_155549_000007312085_00312_40947_2970.N1						SS1	H/H	85	40947	312	5.03
ASA_GM1_1PNPDK20091229_163305_000005672085_00312_40947_2972.N1						SS1	H/H	85	40947	312	5.03
ASA_GM1_1PNPDK20091229_170808_000010942085_00313_40948_2974.N1						SS1	H/H	85	40948	313	5.03
ASA_GM1_1PNPDK20091229_172509_000000722085_00313_40948_2985.N1						SS1	H/H	85	40948	313	5.03
ASA_GM1_1PNPDK20091229_173056_000005432085_00313_40948_2986.N1						SS1	H/H	85	40948	313	5.03
ASA_GM1_1PNPDK20091229_174228_000001202085_00313_40948_2987.N1						SS1	H/H	85	40948	313	5.03
ASA_GM1_1PNPDK20091229_181339_000005372085_00313_40948_2989.N1						SS1	H/H	85	40948	313	5.03
ASA_GM1_1PNPDK20091229_184838_000008702085_00314_40949_2990.N1						SS1	H/H	85	40949	314	5.03
ASA_GM1_1PNPDK20091229_190453_000001572085_00314_40949_3003.N1						SS1	H/H	85	40949	314	5.03
ASA_GM1_1PNPDK20091229_191248_000005312085_00314_40949_3004.N1						SS1	H/H	85	40949	314	5.03
ASA_GM1_1PNPDK20091229_195418_000004712085_00314_40949_3009.N1						SS1	H/H	85	40949	314	5.03
ASA_GM1_1PNPDK20091229_202049_000003322085_00314_40949_3008.N1						SS1	H/H	85	40949	314	5.03
ASA_GM1_1PNPDK20091229_202709_000005492085_00314_40949_3010.N1						SS1	H/H	85	40949	314	5.03
ASA_GM1_1PNPDK20091229_204030_000000662085_00315_40950_3007.N1						SS1	H/H	85	40950	315	5.03
ASA_GM1_1PNPDK20091229_204235_000000662085_00315_40950_3012.N1						SS1	H/H	85	40950	315	5.03
ASA_GM1_1PNPDE20091229_204238_000001262085_00315_40950_2158.N1						SS1	H/H	85	40950	315	5.03

ASA_GM1_1PNPDE20091229_204625_00000722085_00315_40950_2159.N1	SS1	H/H	85	40950	315	5.03
ASA_GM1_1PNPDE20091229_205630_000002952085_00315_40950_2160.N1	SS1	H/H	85	40950	315	5.03
ASA_GM1_1PNPDE20091229_213452_000005672085_00315_40950_2163.N1	SS1	H/H	85	40950	315	5.03
ASA_GM1_1PNPDE20091229_221127_000003382085_00316_40951_2172.N1	SS1	H/H	85	40951	316	5.03
ASA_GM1_1PNPDE20091229_221834_000000842085_00316_40951_2174.N1	SS1	H/H	85	40951	316	5.03
ASA_GM1_1PNPDE20091229_223203_000001752085_00316_40951_2177.N1	SS1	H/H	85	40951	316	5.03
ASA_GM1_1PNPDE20091229_230609_000000902085_00316_40951_2176.N1	SS1	H/H	85	40951	316	5.03
ASA_GM1_1PNPDE20091229_230752_000000902085_00316_40951_2179.N1	SS1	H/H	85	40951	316	5.03
ASA_GM1_1PNPDE20091229_231528_000005672085_00316_40951_2182.N1	SS1	H/H	85	40951	316	5.03


Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_IMM_1PNPDE20091229_003818_000001032085_00303_40938_2002.N1						IS2	H/H	85	40938	303	5.03
ASA_IMM_1PNPDE20091229_012827_000005842085_00303_40938_2016.N1						IS2	H/H	85	40938	303	5.03
ASA_IMM_1PNPDE20091229_024354_000000372085_00304_40939_2018.N1						IS1	V/V	85	40939	304	5.03
ASA_IMM_1PNPDE20091229_024756_000000372085_00304_40939_2019.N1						IS2	V/V	85	40939	304	5.03
ASA_IMM_1PNPDE20091229_030915_000003032085_00304_40939_2036.N1						IS2	H/H	85	40939	304	5.03
ASA_IMM_1PNPDE20091229_031505_000001622085_00304_40939_2037.N1						IS2	H/H	85	40939	304	5.03
ASA_IMM_1PNPDE20091229_034413_000000392085_00305_40940_2040.N1						IS2	V/V	85	40940	305	5.03
ASA_IMM_1PNPDE20091229_042145_000001422085_00305_40940_2041.N1						IS2	V/V	85	40940	305	5.03
ASA_IMM_1PNPDE20091229_042854_000000622085_00305_40940_2042.N1						IS4	H/H	85	40940	305	5.03
ASA_IMM_1PNPDE20091229_045007_000001622085_00305_40940_2060.N1						IS2	H/H	85	40940	305	5.03
ASA_IMM_1PNPDE20091229_045447_000000922085_00305_40940_2061.N1						IS2	H/H	85	40940	305	5.03
ASA_IMM_1PNPDE20091229_053023_000002182085_00306_40941_2067.N1						IS2	V/V	85	40941	306	5.03
ASA_IMM_1PNPDE20091229_053524_000000912085_00306_40941_2068.N1						IS2	V/V	85	40941	306	5.03
ASA_IMM_1PNPDE20091229_060136_000000922085_00306_40941_2069.N1						IS2	V/V	85	40941	306	5.03
ASA_IMM_1PNPDE20091229_063129_000001622085_00306_40941_2072.N1						IS2	H/H	85	40941	306	5.03
ASA_IMM_1PNPDK20091229_063459_000002332085_00306_40941_2864.N1						IS2	H/H	85	40941	306	5.03
ASA_IMM_1PNPDE20091229_074607_000001762085_00307_40942_2084.N1						IS2	V/V	85	40942	307	5.03
ASA_IMM_1PNPDE20091229_075200_000001112085_00307_40942_2085.N1						IS2	V/V	85	40942	307	5.03
ASA_IMM_1PNPDE20091229_095217_000004432085_00308_40943_2114.N1						IS2	H/H	85	40943	308	5.03
ASA_IMM_1PNPDK20091229_105748_000001682085_00309_40944_2911.N1						IS2	V/V	85	40944	309	5.03
ASA_IMM_1PNPDE20091229_113134_000003432085_00309_40944_2129.N1						IS2	H/H	85	40944	309	5.03
ASA_IMM_1PNPDE20091229_114023_000000922085_00309_40944_2138.N1						IS2	H/H	85	40944	309	5.03
ASA_IMM_1PNPDK20091229_131801_000001622085_00310_40945_2945.N1						IS2	H/H	85	40945	310	5.03
ASA_IMM_1PNPDK20091229_134815_000000392085_00311_40946_2947.N1						IS2	V/V	85	40946	311	5.03
ASA_IMM_1PNPDE20091229_153219_000001422085_00312_40947_2148.N1						IS2	V/V	85	40947	312	5.03
ASA_IMM_1PNPDE20091229_164231_000001622085_00312_40947_2143.N1						IS2	H/H	85	40947	312	5.03
ASA_IMM_1PNPDE20091229_173958_000000672085_00313_40948_2152.N1						IS6	V/V	85	40948	313	5.03
ASA_IMM_1PNPDE20091229_174431_000001142085_00313_40948_2154.N1						IS2	V/V	85	40948	313	5.03
ASA_IMM_1PNPDE20091229_182236_000002332085_00313_40948_2150.N1						IS2	H/H	85	40948	313	5.03
ASA_IMM_1PNPDE20091229_202618_000000402085_00314_40949_2170.N1						IS7	V/V	85	40949	314	5.03
ASA_IMM_1PNPDK20091229_222830_000002032085_00316_40951_3027.N1						IS2	H/H	85	40951	316	5.03


Filename	Pol	Timestamp	count(Module)
ASA_MS__0PNPDK20091229_081002_000000162085_00307_40942_0948.N1	H	2009-12-29 08:10:02	320





Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WSM_1PNPDE20091228_235848_000002942085_00302_40937_2000.N1						SS1	H/H	85	40937	302	5.03
ASA_WSM_1PNPDE20091229_013904_000002812085_00303_40938_2017.N1						SS1	H/H	85	40938	303	5.03
ASA_WSM_1PNPDE20091229_021142_000000922085_00304_40939_2020.N1						SS1	H/H	85	40939	304	5.03
ASA_WSM_1PNPDE20091229_021652_000003672085_00304_40939_2034.N1						SS1	H/H	85	40939	304	5.03
ASA_WSM_1PNPDE20091229_031833_000002942085_00304_40939_2038.N1						SS1	H/H	85	40939	304	5.03
ASA_WSM_1PNPDE20091229_035617_000000862085_00305_40940_2039.N1						SS1	V/V	85	40940	305	5.03
ASA_WSM_1PNPDE20091229_045735_000002022085_00305_40940_2062.N1						SS1	H/H	85	40940	305	5.03
ASA_WSM_1PNPDE20091229_050117_000000922085_00305_40940_2063.N1						SS1	H/H	85	40940	305	5.03
ASA_WSM_1PNPDK20091229_064005_000002022085_00306_40941_2866.N1						SS1	H/H	85	40941	306	5.03
ASA_WSM_1PNPDE20091229_073253_000001842085_00307_40942_2083.N1						SS1	H/H	85	40942	307	5.03
ASA_WSM_1PNPDE20091229_075555_000001842085_00307_40942_2086.N1						SS1	H/H	85	40942	307	5.03
ASA_WSM_1PNPDE20091229_080048_000000862085_00307_40942_2087.N1						SS1	V/V	85	40942	307	5.03
ASA_WSM_1PNPDK20091229_082045_000002452085_00307_40942_2888.N1						SS1	H/H	85	40942	307	5.03
ASA_WSM_1PNPDE20091229_091129_000001712085_00308_40943_2105.N1						SS1	H/H	85	40943	308	5.03
ASA_WSM_1PNPDK20091229_091916_000001042085_00308_40943_2892.N1						SS1	V/V	85	40943	308	5.03
ASA_WSM_1PNPDE20091229_092014_000001532085_00308_40943_2106.N1						SS1	V/V	85	40943	308	5.03
ASA_WSM_1PNPDE20091229_100048_000002812085_00308_40943_2122.N1						SS1	H/H	85	40943	308	5.03
ASA_WSM_1PNPDE20091229_103832_000000982085_00309_40944_2123.N1						SS1	H/H	85	40944	309	5.03
ASA_WSM_1PNPDE20091229_104502_000000862085_00309_40944_2124.N1						SS1	H/H	85	40944	309	5.03
ASA_WSM_1PNPDK20091229_105039_000002392085_00309_40944_2909.N1						SS1	H/H	85	40944	309	5.03
ASA_WSM_1PNPDK20091229_105521_000001162085_00309_40944_2910.N1						SS1	H/H	85	40944	309	5.03
ASA_WSM_1PNPDE20091229_114229_000001842085_00309_40944_2139.N1						SS1	H/H	85	40944	309	5.03
ASA_WSM_1PNPDK20091229_122903_000005812085_00310_40945_2925.N1						SS1	H/H	85	40945	310	5.03
ASA_WSM_1PNPDK20091229_132104_000003302085_00310_40945_2946.N1						SS1	H/H	85	40945	310	5.03
ASA_WSM_1PNPDE20091229_141633_000001472085_00311_40946_2145.N1						SS1	H/H	85	40946	311	5.03
ASA_WSM_1PNPDE20091229_150019_000001532085_00311_40946_2146.N1						SS1	H/H	85	40946	311	5.03
ASA_WSM_1PNPDE20091229_150519_000001282085_00311_40946_2147.N1						SS1	H/H	85	40946	311	5.03
ASA_WSM_1PNPDE20091229_154046_000002202085_00312_40947_2142.N1						SS1	H/H	85	40947	312	5.03
ASA_WSM_1PNPDK20091229_154357_000001532085_00312_40947_2964.N1						SS1	H/H	85	40947	312	5.03
ASA_WSM_1PNPDK20091229_154659_000004712085_00312_40947_2965.N1						SS1	H/H	85	40947	312	5.03
ASA_WSM_1PNPDE20091229_155352_000001102085_00312_40947_2149.N1						SS1	H/H	85	40947	312	5.03
ASA_WSM_1PNPDE20091229_164622_000001282085_00312_40947_2144.N1						SS1	H/H	85	40947	312	5.03
ASA_WSM_1PNPDK20091229_172635_000002452085_00313_40948_2980.N1						SS1	H/H	85	40948	313	5.03
ASA_WSM_1PNPDE20091229_174639_000000862085_00313_40948_2155.N1						SS1	V/V	85	40948	313	5.03
ASA_WSM_1PNPDE20091229_182651_000001162085_00313_40948_2151.N1						SS1	H/H	85	40948	313	5.03
ASA_WSM_1PNPDK20091229_190315_000000982085_00314_40949_2997.N1						SS1	H/H	85	40949	314	5.03
ASA_WSM_1PNPDK20091229_190734_000003062085_00314_40949_2998.N1						SS1	H/H	85	40949	314	5.03
ASA_WSM_1PNPDE20091229_200218_000004282085_00314_40949_2156.N1						SS1	H/H	85	40949	314	5.03
ASA_WSM_1PNPDE20091229_201623_000002632085_00314_40949_2157.N1						SS1	V/V	85	40949	314	5.03
ASA_WSM_1PNPDK20091229_204452_000000862085_00315_40950_3019.N1						SS1	V/V	85	40950	315	5.03
ASA_WSM_1PNPDK20091229_204751_000002632085_00315_40950_3020.N1						SS1	H/H	85	40950	315	5.03
ASA_WSM_1PNPDE20091229_205142_000002882085_00315_40950_2171.N1						SS1	H/H	85	40950	315	5.03
ASA_WSM_1PNPDE20091229_214427_000004162085_00315_40950_2169.N1						SS1	H/H	85	40950	315	5.03
ASA_WSM_1PNPDK20091229_222452_000001842085_00316_40951_3026.N1						SS1	H/H	85	40951	316	5.03
ASA_WSM_1PNPDE20091229_223504_000004282085_00316_40951_2190.N1						SS1	H/H	85	40951	316	5.03
ASA_WSM_1PNPDE20091229_232502_000004162085_00316_40951_2188.N1						SS1	H/H	85	40951	316	5.03




Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WVS_1PNPDE20091229_000337_000002842085_00302_40937_1992.N1						IS2	V/V	85	40937	302	5.03
ASA_WVS_1PNPDE20091229_000737_000017092085_00302_40937_2005.N1						IS2	V/V	85	40937	302	5.03
ASA_WVS_1PNPDE20091229_000337_000002842085_00302_40937_1992.N1						IS1	V/V	85	40937	302	5.03
ASA_WVS_1PNPDE20091229_005750_000009552085_00303_40938_2008.N1						IS2	V/V	85	40938	303	5.03
ASA_WVS_1PNPDE20091229_012046_000003752085_00303_40938_2007.N1						IS2	V/V	85	40938	303	5.03
ASA_WVS_1PNPDE20091229_014342_000002402085_00303_40938_2009.N1						IS2	V/V	85	40938	303	5.03
ASA_WVS_1PNPDE20091229_014657_000002552085_00303_40938_2022.N1						IS2	V/V	85	40938	303	5.03
ASA_WVS_1PNPDE20091229_020309_000004642085_00304_40939_2025.N1						IS2	V/V	85	40939	304	5.03
ASA_WVS_1PNPDE20091229_024841_000010192085_00304_40939_2024.N1						IS2	V/V	85	40939	304	5.03
ASA_WVS_1PNPDE20091229_030526_000000302085_00304_40939_2044.N1						IS2	V/V	85	40939	304	5.03
ASA_WVS_1PNPDE20091229_032412_000001202085_00304_40939_2043.N1						IS2	V/V	85	40939	304	5.03
ASA_WVS_1PNPDE20091229_033227_000002692085_00304_40939_2051.N1						IS2	V/V	85	40939	304	5.03
ASA_WVS_1PNPDE20091229_034120_000001192085_00304_40939_2050.N1						IS2	V/V	85	40939	304	5.03
ASA_WVS_1PNPDE20091229_034538_000001942085_00305_40940_2048.N1						IS2	V/V	85	40940	305	5.03
ASA_WVS_1PNPDE20091229_043006_000007342085_00305_40940_2047.N1						IS2	V/V	85	40940	305	5.03
ASA_WVS_1PNPDE20091229_044206_000003602085_00305_40940_2066.N1						IS2	V/V	85	40940	305	5.03
ASA_WVS_1PNPDE20091229_050457_000014242085_00305_40940_2074.N1						IS2	V/V	85	40940	305	5.03
ASA_WVS_1PNPDE20091229_060752_000009292085_00306_40941_2073.N1						IS2	V/V	85	40941	306	5.03
ASA_WVS_1PNPDK20091229_062306_000003452085_00306_40941_2855.N1						IS2	V/V	85	40941	306	5.03
ASA_WVS_1PNPDK20091229_064533_000019792085_00306_40941_2858.N1						IS2	V/V	85	40941	306	5.03
ASA_WVS_1PNPDK20091229_080307_000003752085_00307_40942_2878.N1						IS2	V/V	85	40942	307	5.03
ASA_WVS_1PNPDK20091229_082609_000020542085_00307_40942_2881.N1						IS2	V/V	85	40942	307	5.03
ASA_WVS_1PNPDK20091229_093222_000010492085_00308_40943_2899.N1						IS2	V/V	85	40943	308	5.03
ASA_WVS_1PNPDK20091229_100645_000018592085_00308_40943_2902.N1						IS2	V/V	85	40943	308	5.03
ASA_WVS_1PNPDK20091229_110202_000001642085_00309_40944_2914.N1						IS2	V/V	85	40944	309	5.03
ASA_WVS_1PNPDK20091229_110704_000014092085_00309_40944_2915.N1						IS2	V/V	85	40944	309	5.03
ASA_WVS_1PNPDK20091229_114720_000017842085_00309_40944_2918.N1						IS2	V/V	85	40944	309	5.03
ASA_WVS_1PNPDK20091229_123843_000009292085_00310_40945_2928.N1						IS2	V/V	85	40945	310	5.03
ASA_WVS_1PNPDK20091229_130611_000003002085_00310_40945_2933.N1						IS2	V/V	85	40945	310	5.03
ASA_WVS_1PNPDK20091229_132756_000003752085_00310_40945_2934.N1						IS2	V/V	85	40945	310	5.03
ASA_WVS_1PNPDK20091229_134124_000003742085_00310_40945_2936.N1						IS2	V/V	85	40945	310	5.03
ASA_WVS_1PNPDK20091229_134901_000000592085_00311_40946_2939.N1						IS2	V/V	85	40946	311	5.03
ASA_WVS_1PNPDK20091229_142434_000004192085_00311_40946_2951.N1						IS2	V/V	85	40946	311	5.03
ASA_WVS_1PNPDK20091229_143956_000007042085_00311_40946_2954.N1						IS2	V/V	85	40946	311	5.03
ASA_WVS_1PNPDK20091229_150823_000011842085_00311_40946_2957.N1						IS2	V/V	85	40946	311	5.03
ASA_WVS_1PNPDK20091229_160800_000014542085_00312_40947_2971.N1						IS2	V/V	85	40947	312	5.03
ASA_WVS_1PNPDK20091229_164859_000011092085_00312_40947_2973.N1						IS2	V/V	85	40947	312	5.03
ASA_WVS_1PNPDK20091229_174807_000014842085_00313_40948_2988.N1						IS2	V/V	85	40948	313	5.03
ASA_WVS_1PNPDK20091229_183347_000008542085_00313_40948_2991.N1						IS2	V/V	85	40948	313	5.03
ASA_WVS_1PNPDK20091229_192141_000019042085_00314_40949_3006.N1						IS2	V/V	85	40949	314	5.03
ASA_WVS_1PNPDK20091229_201011_000003302085_00314_40949_3013.N1						IS2	V/V	85	40949	314	5.03
ASA_WVS_1PNPDE20091229_210128_000019642085_00315_40950_2161.N1						IS2	V/V	85	40950	315	5.03
ASA_WVS_1PNPDE20091229_215123_000002552085_00315_40950_2162.N1						IS2	V/V	85	40950	315	5.03
ASA_WVS_1PNPDE20091229_215454_000008242085_00315_40950_2173.N1						IS2	V/V	85	40950	315	5.03
ASA_WVS_1PNPDE20091229_222007_000002402085_00316_40951_2175.N1						IS2	V/V	85	40951	316	5.03
ASA_WVS_1PNPDE20091229_224213_000013942085_00316_40951_2178.N1						IS2	V/V	85	40951	316	5.03
ASA_WVS_1PNPDE20091229_230927_000003152085_00316_40951_2180.N1						IS2	V/V	85	40951	316	5.03
ASA_WVS_1PNPDE20091229_233157_000003002085_00316_40951_2181.N1						IS2	V/V	85	40951	316	5.03
ASA_WVS_1PNPDE20091229_233627_000016642085_00316_40951_2195.N1						IS2	V/V	85	40951	316	5.03








































29-Dec



29-Dec





29-Dec




29-Dec

Date







29-Dec




29-Dec




29-Dec



29-Dec



29-Dec



29-Dec

