



Analysis from 01-JAN-2010 00:00:00 to 01-JAN-2010 23:59:59. Page generated on 05-JAN-2010 10:14:41.
View log file: ASAR_Daily_Report_20100105_1010.log. For any anomalies please contact emma.griffiths@vega.co.uk, kajal.haria@vega.co.uk.

This report is automatically generated every day, every 2 hours. No comments are provided on the results.

SUMMARY

1. DATA SUMMARY
 - 1.1 Summary tables
 - 1.2 Lists of products used
2. AUXILIARY FILES ANALYSIS
 - 2.1 IECF operational ADFs list
 - 2.2 Products with wrong ADFs
3. MODULE STEPPING PRODUCTS ANALYSIS
 - 3.1 V/V polarisation
 - 3.2 H/H polarisation
4. CALIBRATION PULSES ANALYSIS
 - 4.1 Analysis for WVS IS2 V/V
 - 4.1.1 Temporal Evolution Analysis for WVS IS2 V/V
 - 4.1.2 All Rows Analysis for WVS IS2 V/V
 - 4.2 Analysis for GM1 SS3 H/H
 - 4.2.1 Temporal Evolution Analysis for GM1 SS3 H/H
 - 4.2.2 All Rows Analysis for GM1 SS3 H/H
5. DOPPLER ANALYSIS
 - 5.1 Analysis for WVS IS2 V/V
 - 5.1.1 Doppler MAP Analysis for WVS IS2 V/V
 - 5.1.2 Doppler ANX Analysis for WVS IS2 V/V
 - 5.2 Analysis for GM1 SS1 H/H
 - 5.2.1 Doppler MAP Analysis for GM1 SS1 H/H
 - 5.2.2 Doppler ANX Analysis for GM1 SS1 H/H
 - 5.3 Doppler JUMPS Analysis for WSM
6. CHIRP ANALYSIS
 - 6.1 Analysis for WSM SS1 H/H
 - 6.1.1 ScaleFactor
 - 6.2 Analysis for WSM SS1 V/V
 - 6.2.1 ScaleFactor
7. RAW DATA ANALYSIS
 - 7.1 Analysis for WVS
 - 7.2 Analysis for IMM
8. TELEMETRY ANALYSIS
 - 8.1 Number of Missing Lines
 - 8.2 Number of Gaps

1 - DATA SUMMARY

1.1 - Summary tables

[[BACK TO MENU](#)]

WVS				GM1				APM				IMM				WSM				MS			
Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Time	Pol	Modules
PDE	IS1	V/V	4	PDE	WS	H/H	25	PDE	IS2	H/H	1	PDE	IS1	V/V	1	PDE	WS	H/H	27	PDK	2010-01-01 06:35:12	V	320
PDE	IS2	V/V	27	PDK	WS	H/H	44	PDE	IS5	H/H	1	PDE	IS2	H/H	8	PDE	WS	V/V	5				
PDK	IS2	V/V	25					PDK	IS1	H/H	1	PDE	IS2	V/V	15	PDK	WS	H/H	17				
												PDE	IS3	V/V	1	PDK	WS	V/V	3				
												PDE	IS4	V/V	1								
												PDE	IS5	V/V	1								
												PDK	IS2	H/H	1								
												PDK	IS2	V/V	1								

1.2 - Lists of products used

[[BACK TO MENU](#)]

[TXT] [XLS] [List_WVS_products_used](#)
 [TXT] [XLS] [List_GM1_products_used](#)
 [TXT] [XLS] [List_APM_products_used](#)
 [TXT] [XLS] [List_IMM_products_used](#)
 [TXT] [XLS] [List_WSM_products_used](#)
 [TXT] [XLS] [List_MS_products_used](#)

2 - AUXILIARY FILES ANALYSIS

2.1 - IECF operational ADFs list

[[BACK TO MENU](#)]

ADFs disseminated for ASAR
ASA_CON_AXVIEC20091217_101713_20070204_165113_20101231_000000
ASA_INS_AXVIEC20091217_114637_20090428_100000_20101231_235959
ASA_XCH_AXVIEC20091217_113006_20020301_000000_20101231_000000
ASA_XCA_AXVIEC20091217_114112_20080801_000000_20101231_235959

2.2 - Products with wrong ADFs

[[BACK TO MENU](#)]

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
WVS	0	0	0	0
GM1	0	0	0	0
APM	0	0	0	0
IMM	0	0	0	0
WSM	0	0	0	0

[TXT] [XLS] [Check_ADFs_WVS](#)
 [TXT] [XLS] [Check_ADFs_GM1](#)
 [TXT] [XLS] [Check_ADFs_APM](#)
 [TXT] [XLS] [Check_ADFs_IMM](#)

3 - MODULE STEPPING PRODUCTS ANALYSIS





3.2 - H/H polarisation

[[BACK TO MENU](#)]

SECOND FIXED REFERENCE	PREVIOUS PRODUCT REFERENCE
After antenna maintenance (2005-09-22/23)	Previous product in the same polarisation


Reference: 2005-09-22 06:26:51 H RxGain

Test : 2009-12-31 07:06:49 H



Reference: 2009-12-29 08:10:02 H RxGain

Test : 2009-12-31 07:06:49 H




Reference: 2005-09-22 06:26:51 H RxPhase




Test : 2009-12-31 07:06:49 H



Reference: 2009-12-29 08:10:02 H RxPhase

Test : 2009-12-31 07:06:49 H





4 - CALIBRATION PULSES ANALYSIS

4.1 - Analysis for WVS IS2 V/V


4.1.1 - Temporal Evolution Analysis for WVS IS2 V/V

[BACK TO MENU]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Calibration pulses for WVS IS2 V/V




Transmit power (P1 - P1a) for WVS IS2 V/V



4.1.2 - All Rows Analysis for WVS IS2 V/V

[[BACK TO MENU](#)]





4.2 - Analysis for GM1 SS3 H/H


4.2.1 - Temporal Evolution Analysis for GM1 SS3 H/H

[BACK TO MENU]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Calibration pulses for GM1 SS3 H/H




Transmit power (P1 - P1a) for GM1 SS3 H/H



4.2.2 - All Rows Analysis for GM1 SS3 H/H

[[BACK TO MENU](#)]







5 - DOPPLER ANALYSIS

5.1 - Analysis for WVS IS2 V/V

5.1.1 - Doppler MAP Analysis for WVS IS2 V/V

[[BACK TO MENU](#)]






5.1.2 - Doppler ANX Analysis for WVS IS2 V/V

[[BACK TO MENU](#)]






5.2 - Analysis for GM1 SS1 H/H

5.2.1 - Doppler MAP Analysis for GM1 SS1 H/H

[[BACK TO MENU](#)]






5.2.2 - Doppler ANX Analysis for GM1 SS1 H/H

[[BACK TO MENU](#)]






5.3 - Doppler JUMPS Analysis for WSM

[[BACK TO MENU](#)]

--	--





6 - CHIRP ANALYSIS

6.1 - Analysis for WSM SS1 H/H

6.1.1 - ScaleFactor

[[BACK TO MENU](#)]







6.2 - Analysis for WSM SS1 V/V

6.2.1 - ScaleFactor

[[BACK TO MENU](#)]






7 - RAW DATA ANALYSIS

7.1 - Analysis for WVS

[[BACK TO MENU](#)]

--	--	--




Channel	Statistics	DSS-B
MEAN I	mean	0.000534862
	stdev	1.82867e-07
MEAN Q	mean	0.000540439
	stdev	2.21883e-07
Channel	Statistics	DSS-B
STDEV I	mean	0.136933
	stdev	0.00101745
STDEV Q	mean	0.137301
	stdev	0.00103603

7.2 - Analysis for IMM

[[BACK TO MENU](#)]







8 - TELEMETRY ANALYSIS

Processing Center	Product	Gaps	Missing lines
PDE	ASA_WSM_1PNPDE20100101_092559_00000922085_00351_40986_2703.N1	0	1
PDK	ASA_WSM_1PNPDK20100101_191211_000003792085_00357_40992_3517.N1	0	101

8.1 - Number of Missing lines


[[BACK TO MENU](#)]





8.2 - Number of Gaps

[\[BACK TO MENU \]](#)



ASAR DAILY REPORT for 100101
#####

MODE: DAILY
ANALYSIS: ALL
DATE: 2010-01-01

Analysis will be performed from 2010-01-01 00:00:00 to 2010-01-01 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_100101/

DATA SUMMARY

Summary will be performed from 2010-01-01 00:00:00 to 2010-01-01 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_100101/DATA_SUMMARY

Creating directory ./RESULTS/DAILY/_100101/DATA_SUMMARY...
Writing file ./RESULTS/DAILY/_100101/DATA_SUMMARY/Data_summary.html...

Getting WVS products list from 2010-01-01 00:00:00 to 2010-01-01 23:59:59...
Writing file ./RESULTS/DAILY/_100101/DATA_SUMMARY/List_WVS_products_used.xls...
Writing file ./RESULTS/DAILY/_100101/DATA_SUMMARY/List_WVS_products_used.txt...

Getting GM1 products list from 2010-01-01 00:00:00 to 2010-01-01 23:59:59...
Writing file ./RESULTS/DAILY/_100101/DATA_SUMMARY/List_GM1_products_used.xls...
Writing file ./RESULTS/DAILY/_100101/DATA_SUMMARY/List_GM1_products_used.txt...

Getting APM products list from 2010-01-01 00:00:00 to 2010-01-01 23:59:59...
Writing file ./RESULTS/DAILY/_100101/DATA_SUMMARY/List_APM_products_used.xls...
Writing file ./RESULTS/DAILY/_100101/DATA_SUMMARY/List_APM_products_used.txt...

Getting IMM products list from 2010-01-01 00:00:00 to 2010-01-01 23:59:59...
Writing file ./RESULTS/DAILY/_100101/DATA_SUMMARY/List_IMM_products_used.xls...
Writing file ./RESULTS/DAILY/_100101/DATA_SUMMARY/List_IMM_products_used.txt...

Getting WSM products list from 2010-01-01 00:00:00 to 2010-01-01 23:59:59...
Writing file ./RESULTS/DAILY/_100101/DATA_SUMMARY/List_WSM_products_used.xls...
Writing file ./RESULTS/DAILY/_100101/DATA_SUMMARY/List_WSM_products_used.txt...

Getting MS products list from 2010-01-01 00:00:00 to 2010-01-01 23:59:59...
Writing file ./RESULTS/DAILY/_100101/DATA_SUMMARY/List_MS_products_used.xls...
Writing file ./RESULTS/DAILY/_100101/DATA_SUMMARY/List_MS_products_used.txt...

DATA SUMMARY completed
#####

AUXILIARY FILES ANALYSIS

Analysis will be performed from 2010-01-01 00:00:00 to 2010-01-01 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_100101/AUXILIARY

Creating directory ./RESULTS/DAILY/_100101/AUXILIARY...

Looking for the IECF operational ADFs list...



ADF filter 20100101*current_3_IECF_ADFs.txt
 Found list 20100101_030001_current_3_IECF_ADFs.txt...
 Extracting ADFs...

ASA_CON_AXVIEC20091217_101713_20070204_165113_20101231_000000
 ASA_INS_AXVIEC20091217_114637_20090428_100000_20101231_235959
 ASA_XCH_AXVIEC20091217_113006_20020301_000000_20101231_000000
 ASA_XCA_AXVIEC20091217_114112_20080801_000000_20101231_235959

Writing file ./RESULTS/DAILY/_100101/AUXILIARY/ASAR_ADFs_IECF_List3.html...
 Writing file ./RESULTS/DAILY/_100101/AUXILIARY/Auxiliary_files_summary.html...

Analysing WVS products...

Writing file ./RESULTS/DAILY/_100101/AUXILIARY/Check_ADFs_WVS.xls...
 Writing file ./RESULTS/DAILY/_100101/AUXILIARY/Check_ADFs_WVS.txt...

ASA_WVS_1PNPDE20100101_000919_000002852085_00345_40980_2586.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100101_001319_000016642085_00345_40980_2599.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100101_010355_000009502085_00346_40981_2601.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100101_012626_000004652085_00346_40981_2603.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100101_014924_000002392085_00346_40981_2604.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100101_015239_000002402085_00346_40981_2623.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100101_020909_00000592085_00347_40982_2622.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100101_021137_000002542085_00347_40982_2618.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100101_025428_000009892085_00347_40982_2617.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100101_031043_00000302085_00347_40982_2636.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100101_032904_000001502085_00347_40982_2648.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100101_033727_000003892085_00347_40982_2646.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100101_034630_000001492085_00347_40982_2643.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100101_035311_00000592085_00348_40983_2640.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100101_043551_000007792085_00348_40983_2638.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100101_044836_000004052085_00348_40983_2663.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100101_050901_000015742085_00348_40983_2674.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100101_061342_000009142085_00349_40984_2673.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100101_210710_000020542085_00358_40993_2757.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100101_215707_000003152085_00358_40993_2758.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100101_220122_00000902085_00358_40993_2769.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100101_220511_000005542085_00358_40993_2770.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100101_222549_000002402085_00359_40994_2772.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100101_224659_000014092085_00359_40994_2774.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100101_231513_000003902085_00359_40994_2775.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100101_233745_000002852085_00359_40994_2776.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100101_234145_000016642085_00359_40994_2789.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100101_062827_000003602085_00349_40984_3373.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100101_064937_000020392085_00349_40984_3376.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100101_080828_000004952085_00350_40985_3395.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100101_083031_000021442085_00350_40985_3398.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100101_093754_000011542085_00351_40986_3414.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100101_101109_000019792085_00351_40986_3417.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100101_110831_000001192085_00352_40987_3426.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100101_111236_000015142085_00352_40987_3427.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100101_115133_000002402085_00352_40987_3428.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100101_115726_000015142085_00352_40987_3431.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100101_124427_000009142085_00353_40988_3446.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100101_131235_000003452085_00353_40988_3448.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100101_133219_000004652085_00353_40988_3450.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100101_134703_000004192085_00353_40988_3454.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100101_142852_000004942085_00354_40989_3468.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100101_144522_000008252085_00354_40989_3470.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100101_151319_000012592085_00354_40989_3474.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100101_161348_00000892085_00355_40990_3487.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100101_161738_000013192085_00355_40990_3489.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100101_165343_000012742085_00355_40990_3491.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100101_175350_000015742085_00356_40991_3506.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

```
ASA_WVS_1PNPDK20100101_183932_000003602085_00356_40991_3508.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100101_184646_000003892085_00356_40991_3509.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100101_192710_000020242085_00357_40992_3524.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100101_201504_000005402085_00357_40992_3528.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```

Analysing GM1 products...

Writing file ./RESULTS/DAILY/_100101/AUXILIARY/Check_ADFs_GM1.xls...

Writing file ./RESULTS/DAILY/_100101/AUXILIARY/Check_ADFs_GM1.txt...

```
ASA_GM1_1PNPDE20100101_005053_000005072085_00346_40981_2598.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100101_010105_000001692085_00346_40981_2600.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100101_012032_000003502085_00346_40981_2602.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100101_013458_000005792085_00346_40981_2605.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100101_015728_000007012085_00346_40981_2621.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100101_021924_000001872085_00347_40982_2620.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100101_023015_000008342085_00347_40982_2619.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100101_024845_000003442085_00347_40982_2616.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100101_031531_000005192085_00347_40982_2637.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100101_033219_000003082085_00347_40982_2649.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100101_034439_000001022085_00347_40982_2647.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100101_035112_000001142085_00348_40983_2645.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100101_035903_000001812085_00348_40983_2644.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100101_040304_0000011962085_00348_40983_2642.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100101_042445_000001572085_00348_40983_2641.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100101_043012_000002472085_00348_40983_2639.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100101_045608_000004222085_00348_40983_2671.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100101_053958_000000662085_00349_40984_2670.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100101_054251_000001692085_00349_40984_2669.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100101_054730_000013172085_00349_40984_2672.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100101_205208_000000782085_00358_40993_2756.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100101_205632_000006282085_00358_40993_2759.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100101_221705_000005192085_00359_40994_2771.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100101_223746_000005492085_00359_40994_2773.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100101_231117_000001382085_00359_40994_2777.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100101_063644_000005312085_00349_40984_3374.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100101_073046_000004282085_00350_40985_3375.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100101_073650_000000782085_00350_40985_3391.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100101_074156_000001872085_00350_40985_3392.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100101_075455_000003922085_00350_40985_3393.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100101_080434_000002292085_00350_40985_3394.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100101_081720_000005372085_00350_40985_3396.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100101_090702_000004892085_00351_40986_3397.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100101_093428_000001502085_00351_40986_3413.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100101_095754_000005072085_00351_40986_3415.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100101_105212_000001752085_00352_40987_3416.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100101_113833_000005672085_00352_40987_3429.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100101_122319_000003802085_00353_40988_3430.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100101_123302_000002412085_00353_40988_3432.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100101_123553_000003022085_00353_40988_3444.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100101_130019_000005732085_00353_40988_3445.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100101_130959_000001502085_00353_40988_3447.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100101_131909_000004532085_00353_40988_3449.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100101_134041_000003802085_00353_40988_3451.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100101_135829_000001442085_00354_40989_3452.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100101_140157_000005612085_00354_40989_3453.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100101_141349_000001812085_00354_40989_3455.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100101_141536_000003862085_00354_40989_3466.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100101_142658_000001082085_00354_40989_3467.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100101_143755_000004472085_00354_40989_3469.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100101_145944_000007132085_00354_40989_3471.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100101_153509_000001752085_00355_40990_3472.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100101_154513_000004042085_00355_40990_3473.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100101_155422_000001632085_00355_40990_3485.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100101_160028_000007982085_00355_40990_3486.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```

ASA_GM1_1PNPDK20100101_161605_00000842085_00355_40990_3488.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100101_164020_000006952085_00355_40990_3490.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100101_171546_000008882085_00356_40991_3492.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100101_172923_000001692085_00356_40991_3504.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100101_173925_00000782085_00356_40991_3503.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100101_174140_000002472085_00356_40991_3502.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100101_174659_000002712085_00356_40991_3505.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100101_182056_000006952085_00356_40991_3507.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100101_185400_000008942085_00357_40992_3510.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100101_191041_00000782085_00357_40992_3520.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100101_191835_000002052085_00357_40992_3521.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100101_192504_000001202085_00357_40992_3525.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100101_202440_000010392085_00357_40992_3526.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100101_204638_00000722085_00358_40993_3527.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

Analysing APM products...

Writing file ./RESULTS/DAILY/_100101/AUXILIARY/Check_ADFs_APM.xls...

Writing file ./RESULTS/DAILY/_100101/AUXILIARY/Check_ADFs_APM.txt...

ASA_APM_1PNPDE20100101_040201_00000402085_00348_40983_2659.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20100101_221604_00000432085_00359_40994_2787.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDK20100101_135449_00000422085_00354_40989_3463.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

Analysing IMM products...

Writing file ./RESULTS/DAILY/_100101/AUXILIARY/Check_ADFs_IMM.xls...

Writing file ./RESULTS/DAILY/_100101/AUXILIARY/Check_ADFs_IMM.txt...

ASA_IMM_1PNPDE20100101_021049_00000422085_00347_40982_2615.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100101_024407_000002672085_00347_40982_2614.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100101_035017_00000422085_00348_40983_2652.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100101_042723_000001562085_00348_40983_2634.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100101_043420_000000862085_00348_40983_2635.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100101_053633_00000512085_00349_40984_2662.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100101_053739_000001292085_00349_40984_2664.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100101_054110_00000922085_00349_40984_2665.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100101_060927_000001062085_00349_40984_2667.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100101_074504_000001592085_00350_40985_2683.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100101_075055_000002332085_00350_40985_2684.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100101_091511_00000532085_00351_40986_2696.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100101_093657_00000512085_00351_40986_2704.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100101_111102_00000882085_00352_40987_2723.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100101_153804_000003802085_00355_40990_2744.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100101_154225_000001612085_00355_40990_2739.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100101_174047_00000392085_00356_40991_2745.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100101_174543_00000672085_00356_40991_2746.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100101_175131_00000372085_00356_40991_2747.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100101_184602_00000372085_00356_40991_2750.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100101_200235_000003022085_00357_40992_2755.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100101_200825_000002332085_00357_40992_2752.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100101_214227_000002322085_00358_40993_2767.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100101_214710_000003002085_00358_40993_2763.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100101_231337_00000382085_00359_40994_2786.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100101_232215_000001612085_00359_40994_2785.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100101_232545_000003732085_00359_40994_2781.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20100101_072411_000002432085_00350_40985_3383.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20100101_155702_000001962085_00355_40990_3481.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

Analysing WSM products...



Writing file ./RESULTS/DAILY/_100101/AUXILIARY/Check_ADFs_WSM.xls...

Writing file ./RESULTS/DAILY/_100101/AUXILIARY/Check_ADFs_WSM.txt...

ASA_WSM_1PNPDE20100101_000432_000002882085_00345_40980_2594.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100101_004154_000001162085_00346_40981_2597.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100101_004449_000003612085_00346_40981_2611.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100101_005925_000000982085_00346_40981_2612.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100101_014446_000002812085_00346_40981_2613.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100101_021634_000001652085_00347_40982_2624.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100101_022239_000004532085_00347_40982_2630.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100101_032415_000002942085_00347_40982_2655.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100101_035501_000002392085_00348_40983_2658.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100101_042306_000000982085_00348_40983_2633.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100101_050653_000000982085_00348_40983_2661.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100101_054547_000000982085_00349_40984_2666.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100101_061122_000000982085_00349_40984_2668.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100101_073819_000002142085_00350_40985_2682.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100101_080136_000001712085_00350_40985_2685.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100101_091617_000002882085_00351_40986_2702.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100101_092559_000000922085_00351_40986_2703.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100101_100630_000002812085_00351_40986_2724.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100101_104518_000002452085_00352_40987_2725.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100101_105017_000001102085_00352_40987_2726.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100101_142208_000001592085_00354_40989_2742.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100101_151141_000000982085_00354_40989_2743.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100101_165202_000001042085_00355_40990_2741.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100101_175223_000000862085_00356_40991_2748.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100101_183238_000001162085_00356_40991_2749.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100101_191211_000000862085_00357_40992_2751.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100101_192208_000001712085_00357_40992_2754.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100101_201250_000001282085_00357_40992_2753.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100101_215332_000002142085_00358_40993_2766.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100101_220333_000000982085_00358_40993_2768.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100101_233252_000002942085_00359_40994_2784.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100101_064545_000002082085_00349_40984_3382.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100101_072826_000001282085_00350_40985_3384.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100101_082624_000002452085_00350_40985_3404.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100101_092021_000002632085_00351_40986_3405.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100101_092501_000001162085_00351_40986_3406.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100101_105512_000004712085_00352_40987_3423.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100101_114804_000002082085_00352_40987_3438.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100101_115612_000000672085_00352_40987_3439.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100101_122947_000001842085_00353_40988_3440.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100101_124100_000002082085_00353_40988_3441.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100101_132645_000003362085_00353_40988_3462.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100101_141126_000001282085_00354_40989_3456.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100101_155203_000001282085_00355_40990_3480.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100101_173215_000004222085_00356_40991_3498.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100101_190857_000000982085_00357_40992_3516.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100101_191211_000003792085_00357_40992_3517.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100101_204811_000001222085_00358_40993_3530.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100101_205035_000000862085_00358_40993_3534.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100101_205336_000001712085_00358_40993_3536.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100101_223037_000004222085_00359_40994_3539.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

AUXILIARY FILES ANALYSIS completed

#####

MODULE STEPPING ANALYSIS

#####

Analysis will be performed from 2010-01-01 00:00:00 to 2010-01-01 23:59:59

Results will be exported to the directory: ./RESULTS/DAILY/_100101/MODULE_STEPPING


```
Creating directory ./RESULTS/DAILY/_100101/MODULE_STEPPING...
Creating directory ./RESULTS/DAILY/_100101/MODULE_STEPPING/FIRST_REFERENCE...
Creating directory ./RESULTS/DAILY/_100101/MODULE_STEPPING/SECOND_REFERENCE...
Creating directory ./RESULTS/DAILY/_100101/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE...
Deleting old files...
```

```
*****
*****
```

```
Creating images comparing with second reference...
```

```
Exporting results to the directory ../../RESULTS/DAILY/_100101/MODULE_STEPPING/SECOND_REFERENCE...
```

```
Polarization: H
Reference product: ASA_MS__0PNPDK20050922_062651_000000152041_00034_18625_0041.N1
Test product: ASA_MS__0PNPDK20091231_070649_000000162085_00335_40970_0950.N1
  H
  H
../../RESULTS/DAILY/_100101/MODULE_STEPPING/SECOND_REFERENCE/TGH_20091231_070649-20050922_062651.png
../../RESULTS/DAILY/_100101/MODULE_STEPPING/SECOND_REFERENCE/TPH_20091231_070649-20050922_062651.png
../../RESULTS/DAILY/_100101/MODULE_STEPPING/SECOND_REFERENCE/RGH_20091231_070649-20050922_062651.png
../../RESULTS/DAILY/_100101/MODULE_STEPPING/SECOND_REFERENCE/RPH_20091231_070649-20050922_062651.png
```

```
Polarization: V
Reference product: ASA_MS__0PNPDK20050923_055514_000000152041_00048_18639_0042.N1
Test product: ASA_MS__0PNPDK20100101_063512_000000162085_00349_40984_0951.N1
  V
  V
../../RESULTS/DAILY/_100101/MODULE_STEPPING/SECOND_REFERENCE/TGV_20100101_063512-20050923_055514.png
../../RESULTS/DAILY/_100101/MODULE_STEPPING/SECOND_REFERENCE/TPV_20100101_063512-20050923_055514.png
../../RESULTS/DAILY/_100101/MODULE_STEPPING/SECOND_REFERENCE/RGV_20100101_063512-20050923_055514.png
../../RESULTS/DAILY/_100101/MODULE_STEPPING/SECOND_REFERENCE/RPV_20100101_063512-20050923_055514.png
```

```
*****
*****
```

```
Creating images comparing with previous product reference...
```

```
Exporting results to the directory ../../RESULTS/DAILY/_100101/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE...
```

```
Polarization: H
Reference product: ASA_MS__0PNPDK20091229_081002_000000162085_00307_40942_0948.N1
Test product: ASA_MS__0PNPDK20091231_070649_000000162085_00335_40970_0950.N1
  H
  H
../../RESULTS/DAILY/_100101/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TGH_20091231_070649-20091229_081002.png
../../RESULTS/DAILY/_100101/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TPH_20091231_070649-20091229_081002.png
../../RESULTS/DAILY/_100101/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RGH_20091231_070649-20091229_081002.png
../../RESULTS/DAILY/_100101/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RPH_20091231_070649-20091229_081002.png
```

```
Polarization: V
Reference product: ASA_MS__0PNPDK20091230_073826_000000162085_00321_40956_0949.N1
Test product: ASA_MS__0PNPDK20100101_063512_000000162085_00349_40984_0951.N1
  V
  V
../../RESULTS/DAILY/_100101/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TGV_20100101_063512-20091230_073826.png
../../RESULTS/DAILY/_100101/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TPV_20100101_063512-20091230_073826.png
../../RESULTS/DAILY/_100101/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RGV_20100101_063512-20091230_073826.png
../../RESULTS/DAILY/_100101/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RPV_20100101_063512-20091230_073826.png
```

```
MODULE_STEPPING ANALYSIS completed
#####
```

```
CALIBRATION PULSES ANALYSIS
#####
Creating directory ./RESULTS/DAILY/_100101/CALIBRATION_PULSES...
```


ALL ROWS Analysis will be performed from 2010-01-01 00:00:00 to 2010-01-01 23:59:59

Analysing products WVS IS2 V/V

Writing image ../../RESULTS/DAILY/_100101//CALIBRATION_PULSES/Calibration_pulses_all_rows_WVS_IS2_VV.png...

Analysing products GM1 SS3 H/H

Writing image ../../RESULTS/DAILY/_100101//CALIBRATION_PULSES/Calibration_pulses_all_rows_GM1_SS3_HH.png...

TEMPORAL EVOLUTION Analysis will be performed from 2010-01-01 00:00:00 to 2010-01-01 23:59:59

Analysing products WVS IS2 V/V

Getting calibration pulses data for WVS IS2 V/V from 2010-01-01 00:00:00 to 2010-01-01 23:59:59. Rows: 1/5/9/13/17/21/25/29

Writing file ./RESULTS/DAILY/_100101/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2010-01-01_1.dat...

Writing ../../RESULTS/DAILY/_100101//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_1.png...

Writing ../../RESULTS/DAILY/_100101//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_1.png...

Getting calibration pulses data for WVS IS2 V/V from 2010-01-01 00:00:00 to 2010-01-01 23:59:59. Rows: 2/6/10/14/18/22/26/30

Writing file ./RESULTS/DAILY/_100101/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2010-01-01_2.dat...

Writing ../../RESULTS/DAILY/_100101//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_2.png...

Writing ../../RESULTS/DAILY/_100101//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_2.png...

Getting calibration pulses data for WVS IS2 V/V from 2010-01-01 00:00:00 to 2010-01-01 23:59:59. Rows: 3/7/11/15/19/23/27/31

Writing file ./RESULTS/DAILY/_100101/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2010-01-01_3.dat...

Writing ../../RESULTS/DAILY/_100101//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_3.png...

Writing ../../RESULTS/DAILY/_100101//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_3.png...

Getting calibration pulses data for WVS IS2 V/V from 2010-01-01 00:00:00 to 2010-01-01 23:59:59. Rows: 4/8/12/16/20/24/28/32

Writing file ./RESULTS/DAILY/_100101/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2010-01-01_4.dat...

Writing ../../RESULTS/DAILY/_100101//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_4.png...

Writing ../../RESULTS/DAILY/_100101//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_4.png...

Analysing products GM1 SS3 H/H

Getting calibration pulses data for GM1 SS3 H/H from 2010-01-01 00:00:00 to 2010-01-01 23:59:59. Rows: 1/5/9/13/17/21/25/29

Writing file ./RESULTS/DAILY/_100101/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2010-01-01_1.dat...

Writing ../../RESULTS/DAILY/_100101//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_1.png...

Writing ../../RESULTS/DAILY/_100101//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_1.png...

Getting calibration pulses data for GM1 SS3 H/H from 2010-01-01 00:00:00 to 2010-01-01 23:59:59. Rows: 2/6/10/14/18/22/26/30

Writing file ./RESULTS/DAILY/_100101/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2010-01-01_2.dat...

Writing ../../RESULTS/DAILY/_100101//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_2.png...

Writing ../../RESULTS/DAILY/_100101//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_2.png...

Getting calibration pulses data for GM1 SS3 H/H from 2010-01-01 00:00:00 to 2010-01-01 23:59:59. Rows: 3/7/11/15/19/23/27/31

Writing file ./RESULTS/DAILY/_100101/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2010-01-01_3.dat...

Writing ../../RESULTS/DAILY/_100101//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_3.png...

Writing ../../RESULTS/DAILY/_100101//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_3.png...

Getting calibration pulses data for GM1 SS3 H/H from 2010-01-01 00:00:00 to 2010-01-01 23:59:59. Rows: 4/8/12/16/20/24/28/32

Writing file ./RESULTS/DAILY/_100101/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2010-01-01_4.dat...

Writing ../../RESULTS/DAILY/_100101//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_4.png...

Writing ../../RESULTS/DAILY/_100101//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_4.png...

CALIBRATION PULSES ANALYSIS completed

#####

DOPPLER ANALYSIS

#####

Creating directory ./RESULTS/DAILY/_100101/DOPPLER...

DOPPLER ANX Analysis will be performed from 2010-01-01 00:00:00 to 2010-01-01 23:59:59

Analysing products WVS IS2 V/V

Getting doppler data for WVS IS2 V/V from 2010-01-01 00:00:00 to 2010-01-01 23:59:59...

Writing file ./RESULTS/DAILY/_100101/DOPPLER/Doppler_data_WVS_IS2_VV_2010-01-01.dat...

Running IDL program...

Writing file ../../RESULTS/DAILY/_100101/DOPPLER/DOPPLER_ANX_WVS_IS2_VV.png...

Analysing products GM1 SS1 H/H

Getting doppler data for GM1 SS1 H/H from 2010-01-01 00:00:00 to 2010-01-01 23:59:59...

Writing file ./RESULTS/DAILY/_100101/DOPPLER/Doppler_data_GM1_SS1_HH_2010-01-01.dat...

Running IDL program...

Writing file ../../RESULTS/DAILY/_100101/DOPPLER/DOPPLER_ANX_GM1_SS1_HH.png...

DOPPLER JUMPS Analysis will be performed on WSM products from 2010-01-01 00:00:00 to 2010-01-01 23:59:59

Analysing by default products WSM

Getting doppler jumps data for WSM from 2010-01-01 00:00:00 to 2010-01-01 23:59:59...

Writing file ./RESULTS/DAILY/_100101/DOPPLER/Doppler_Jumps_data_WSM_2010-01-01.dat...

Running IDL program...

Writing file ../../RESULTS/DAILY/_100101/DOPPLER/DOPPLER_JUMPS_ANX_WSM.png...

Writing file ../../RESULTS/DAILY/_100101/DOPPLER/DOPPLER_JUMPS_Date_WSM.png...

DOPPLER MAP Analysis will be performed from 2010-01-01 00:00:00 to 2010-01-01 23:59:59

Analysing products WVS IS2 V/V

Loading predicted doppler values....

Phase: descending

Found data...

Computing mean error doppler estimated-predicted...

Mean error = -32.164925 Hz

Writing file ../../RESULTS/DAILY/_100101//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_WVS_IS2_VV_desc.jpg...

Writing file ../../RESULTS/DAILY/_100101//DOPPLER/DOPPLER_Absolute_WVS_IS2_VV_desc.jpg...

Loading predicted doppler values....

Phase: ascending

Found data...

Computing mean error doppler estimated-predicted...

Mean error = -28.773269 Hz

Writing file ../../RESULTS/DAILY/_100101//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_WVS_IS2_VV_asc.jpg...

Writing file ../../RESULTS/DAILY/_100101//DOPPLER/DOPPLER_Absolute_WVS_IS2_VV_asc.jpg...

Analysing products GM1 SS1 H/H

Loading predicted doppler values....

Phase: descending

Found data...

```
Computing mean error doppler estimated-predicted...
Mean error = -25.154824 Hz
Writing file ../../RESULTS/DAILY/_100101//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_GM1_SS1_HH_desc.jpg...
Writing file ../../RESULTS/DAILY/_100101//DOPPLER/DOPPLER_Absolute_GM1_SS1_HH_desc.jpg...
```

```
*****
Loading predicted doppler values....
Phase: ascending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -24.451609 Hz
Writing file ../../RESULTS/DAILY/_100101//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_GM1_SS1_HH_asc.jpg...
Writing file ../../RESULTS/DAILY/_100101//DOPPLER/DOPPLER_Absolute_GM1_SS1_HH_asc.jpg...
```

```
DOPPLER ANALYSIS completed
#####
```

```
CHIRP ANALYSIS
#####
Creating directory ./RESULTS/DAILY/_100101/CHIRP...
```

```
*****
*****
CHIRP Analysis will be performed from 2010-01-01 00:00:00 to 2010-01-01 23:59:59
```

```
Analysing products WSM SS1 H/H
*****
Getting ScaleFactor data for WSM SS1 H/H from 2010-01-01 00:00:00 to 2010-01-01 23:59:59...
Writing file ./RESULTS/DAILY/_100101/CHIRP/ScaleFactor_data_WSM_SS1_HH_2010-01-01.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/_100101/CHIRP/ScaleFactor_ANX_WSM_SS1_HH.png...
Writing file ../../RESULTS/DAILY/_100101/CHIRP/ScaleFactor_DATE_WSM_SS1_HH.png...
```

```
Analysing products WSM SS1 V/V
*****
Getting ScaleFactor data for WSM SS1 V/V from 2010-01-01 00:00:00 to 2010-01-01 23:59:59...
Writing file ./RESULTS/DAILY/_100101/CHIRP/ScaleFactor_data_WSM_SS1_VV_2010-01-01.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/_100101/CHIRP/ScaleFactor_ANX_WSM_SS1_VV.png...
Writing file ../../RESULTS/DAILY/_100101/CHIRP/ScaleFactor_DATE_WSM_SS1_VV.png...
```

```
CHIRP ANALYSIS completed
#####
```

```
RAW DATA ANALYSIS
#####
Analysis will be performed from 2010-01-01 00:00:00 to 2010-01-01 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_100101/RAW_DATA
```

```
Creating directory ./RESULTS/DAILY/_100101/RAW_DATA...
```

```
*****
Getting raw data for WVS from 2010-01-01 00:00:00 to 2010-01-01 23:59:59...
Writing file ./RESULTS/DAILY/_100101/RAW_DATA/Raw_data_WVS_2010-01-01.dat...
Running IDL program to create graphs...
```

Creating image ../../RESULTS/DAILY/_100101/RAW_DATA/Raw_data_WVS_input_mean.png...
Creating image ../../RESULTS/DAILY/_100101/RAW_DATA/Raw_data_WVS_input_stdev.png...
Creating image ../../RESULTS/DAILY/_100101/RAW_DATA/Raw_data_WVS_gain_imbalance.png...

Getting raw data for IMM from 2010-01-01 00:00:00 to 2010-01-01 23:59:59...
Writing file ./RESULTS/DAILY/_100101/RAW_DATA/Raw_data_IMM_2010-01-01.dat...
Running IDL program to create graphs...

Creating image ../../RESULTS/DAILY/_100101/RAW_DATA/Raw_data_IMM_input_mean.png...
Creating image ../../RESULTS/DAILY/_100101/RAW_DATA/Raw_data_IMM_input_stdev.png...
Creating image ../../RESULTS/DAILY/_100101/RAW_DATA/Raw_data_IMM_gain_imbalance.png...

RAW DATA ANALYSIS completed
#####

TELEMETRY ANALYSIS

Analysis will be performed from 2010-01-01 00:00:00 to 2010-01-01 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_100101/TELEMETRY

Creating directory ./RESULTS/DAILY/_100101/TELEMETRY...

Looking for gaps and missing lines in WVS products...

Checking 27 products from PDE...
Checking 25 products from PDK...

Looking for gaps and missing lines in GM1 products...

Checking 25 products from PDE...
Checking 44 products from PDK...

Looking for gaps and missing lines in APM products...

Checking 2 products from PDE...
Checking 1 products from PDK...

Looking for gaps and missing lines in IMM products...

Checking 27 products from PDE...
Checking 2 products from PDK...

Looking for gaps and missing lines in WSM products...

Checking 32 products from PDE...
Found product...ASA_WSM_1PNPDE20100101_092559_00000922085_00351_40986_2703.N1 / 0 gaps / 1 missing lines
Checking 20 products from PDK...
Found product...ASA_WSM_1PNPDK20100101_191211_000003792085_00357_40992_3517.N1 / 0 gaps / 101 missing lines

Creating graph of missing lines and gaps...

Creating image: ./RESULTS/DAILY/_100101/TELEMETRY/TELEMETRY_Missing_lines.png...
Creating image: ./RESULTS/DAILY/_100101/TELEMETRY/TELEMETRY_Gaps.png...

TELEMETRY ANALYSIS completed
#####

BROWSE PRODUCTS ANALYSIS

Analysis will be performed on 2010-01-01

Scanning directory /nfs-store/ASAR_Data//ASA_GM_BP...
Results will be exported to the directory: /nfs-store/ASAR_Data//ASA_GM_BP/JPG/20100101/

Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20100101_063644_000005312085_00349_40984_3374.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20100101_073046_000004282085_00350_40985_3375.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20100101_073650_000000782085_00350_40985_3391.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20100101_074156_000001872085_00350_40985_3392.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20100101_075455_000003922085_00350_40985_3393.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20100101_080434_000002292085_00350_40985_3394.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20100101_081720_000005372085_00350_40985_3396.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20100101_090702_000004892085_00351_40986_3397.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20100101_093428_000001502085_00351_40986_3413.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20100101_095754_000005072085_00351_40986_3415.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20100101_105212_000001752085_00352_40987_3416.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20100101_113833_000005672085_00352_40987_3429.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20100101_122319_000003802085_00353_40988_3430.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20100101_123302_000002412085_00353_40988_3432.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20100101_123553_000003022085_00353_40988_3444.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20100101_130019_000005732085_00353_40988_3445.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20100101_130959_000001502085_00353_40988_3447.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20100101_131909_000004532085_00353_40988_3449.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20100101_134041_000003802085_00353_40988_3451.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20100101_135829_000001442085_00354_40989_3452.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20100101_140157_000005612085_00354_40989_3453.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20100101_141349_000001812085_00354_40989_3455.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20100101_141536_000003862085_00354_40989_3466.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20100101_142658_000001082085_00354_40989_3467.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20100101_143755_000004472085_00354_40989_3469.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20100101_145944_000007132085_00354_40989_3471.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20100101_153509_000001752085_00355_40990_3472.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20100101_154513_000004042085_00355_40990_3473.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20100101_155422_000001632085_00355_40990_3485.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20100101_160028_000007972085_00355_40990_3486.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20100101_161605_000000842085_00355_40990_3488.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20100101_164020_000006952085_00355_40990_3490.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20100101_171546_000008882085_00356_40991_3492.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20100101_172923_000001692085_00356_40991_3504.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20100101_173925_000000782085_00356_40991_3503.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20100101_174140_000002472085_00356_40991_3502.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20100101_174659_000002712085_00356_40991_3505.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20100101_182056_000006952085_00356_40991_3507.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20100101_185400_000008942085_00357_40992_3510.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20100101_191041_000000782085_00357_40992_3520.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20100101_191835_000002052085_00357_40992_3521.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20100101_192504_000001202085_00357_40992_3525.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20100101_202440_000010392085_00357_40992_3526.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDK20100101_204638_000000722085_00358_40993_3527.N1 ...

ANALYSIS COMPLETED: 44 GM browse products to see...

Scanning directory /nfs-store/ASAR_Data//ASA_AP_BP...
Results will be exported to the directory: /nfs-store/ASAR_Data//ASA_AP_BP/JPG/20100101/

Stripping browse product /nfs-store/ASAR_Data//ASA_AP_BP/ASA_AP_BPZPDK20100101_135449_000000422085_00354_40989_3463.N1 ...

ANALYSIS COMPLETED: 1 AP browse products to see...

Scanning directory /nfs-store/ASAR_Data//ASA_IM_BP...
Results will be exported to the directory: /nfs-store/ASAR_Data//ASA_IM_BP/JPG/20100101/

Stripping browse product /nfs-store/ASAR_Data//ASA_IM_BP/ASA_IM_BPZPDK20100101_072411_000002422085_00350_40985_3383.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_IM_BP/ASA_IM_BPZPDK20100101_155702_000001962085_00355_40990_3481.N1 ...

ANALYSIS COMPLETED: 2 IM browse products to see...

Scanning directory /nfs-store/ASAR_Data//ASA_WS_BP...

Results will be exported to the directory: /nfs-store/ASAR_Data//ASA_WS_BP/JPG/20100101/

Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDK20100101_064545_000002082085_00349_40984_3382.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDK20100101_072826_000001282085_00350_40985_3384.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDK20100101_082624_000002452085_00350_40985_3404.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDK20100101_092021_000002632085_00351_40986_3405.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDK20100101_092501_000001162085_00351_40986_3406.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDK20100101_105512_000004712085_00352_40987_3423.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDK20100101_114804_000002082085_00352_40987_3438.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDK20100101_115612_000000672085_00352_40987_3439.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDK20100101_122947_000001832085_00353_40988_3440.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDK20100101_124100_000002082085_00353_40988_3441.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDK20100101_132645_000003362085_00353_40988_3462.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDK20100101_141126_000001282085_00354_40989_3456.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDK20100101_155203_000001282085_00355_40990_3480.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDK20100101_173215_000004222085_00356_40991_3498.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDK20100101_190857_000000982085_00357_40992_3516.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDK20100101_191211_000003792085_00357_40992_3517.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDK20100101_204811_000001222085_00358_40993_3530.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDK20100101_205035_000000862085_00358_40993_3534.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDK20100101_205336_000001712085_00358_40993_3536.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDK20100101_223037_000004222085_00359_40994_3539.N1 ...

ANALYSIS COMPLETED: 20 WS browse products to see...

BROWSE PRODUCTS ANALYSIS completed

#####

HTML REPORT generation

#####

Building file ./RESULTS/DAILY/_100101/asarReport.html...

Building DATA SUMMARY section...

Building AUXILIARY FILES ANALYSIS section...

Building MODULE STEPPING ANALYSIS section...

Building CALIBRATION PULSES ANALYSIS section...

Building DOPPLER ANALYSIS section...

Building CHIRP ANALYSIS section...

Building RAW DATA ANALYSIS section...

Building TELEMETRY ANALYSIS section...

HTML REPORT generation completed

#####



Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
ASA_APM_1PNPDE20100101_040201_000000402085_00348_40983_2659.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20100101_221604_000000432085_00359_40994_2787.N1	OK	OK	OK	OK
ASA_APM_1PNPDK20100101_135449_000000422085_00354_40989_3463.N1	OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_GM1_1PNPDE20100101_005053_000005072085_00346_40981_2598.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100101_010105_000001692085_00346_40981_2600.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100101_012032_000003502085_00346_40981_2602.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100101_013458_000005792085_00346_40981_2605.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100101_015728_000007012085_00346_40981_2621.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100101_021924_000001872085_00347_40982_2620.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100101_023015_000008342085_00347_40982_2619.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100101_024845_000003442085_00347_40982_2616.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100101_031531_000005192085_00347_40982_2637.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100101_033219_000003082085_00347_40982_2649.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100101_034439_000001022085_00347_40982_2647.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100101_035112_000001142085_00348_40983_2645.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100101_035903_000001812085_00348_40983_2644.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100101_040304_000011962085_00348_40983_2642.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100101_042445_000001572085_00348_40983_2641.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100101_043012_000002472085_00348_40983_2639.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100101_045608_000004222085_00348_40983_2671.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100101_053958_000000662085_00349_40984_2670.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100101_054251_000001692085_00349_40984_2669.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100101_054730_000013172085_00349_40984_2672.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100101_205208_000000782085_00358_40993_2756.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100101_205632_000006282085_00358_40993_2759.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100101_221705_000005192085_00359_40994_2771.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100101_223746_000005492085_00359_40994_2773.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100101_231117_000001382085_00359_40994_2777.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100101_063644_000005312085_00349_40984_3374.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100101_073046_000004282085_00350_40985_3375.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100101_073650_000000782085_00350_40985_3391.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100101_074156_000001872085_00350_40985_3392.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100101_075455_000003922085_00350_40985_3393.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100101_080434_000002292085_00350_40985_3394.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100101_081720_000005372085_00350_40985_3396.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100101_090702_000004892085_00351_40986_3397.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100101_093428_000001502085_00351_40986_3413.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100101_095754_000005072085_00351_40986_3415.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100101_105212_000001752085_00352_40987_3416.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100101_113833_000005672085_00352_40987_3429.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100101_122319_000003802085_00353_40988_3430.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100101_123302_000002412085_00353_40988_3432.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100101_123553_000003022085_00353_40988_3444.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100101_130019_000005732085_00353_40988_3445.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100101_130959_000001502085_00353_40988_3447.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100101_131909_000004532085_00353_40988_3449.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100101_134041_000003802085_00353_40988_3451.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100101_135829_000001442085_00354_40989_3452.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100101_140157_000005612085_00354_40989_3453.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100101_141349_000001812085_00354_40989_3455.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100101_141536_000003862085_00354_40989_3466.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100101_142658_000001082085_00354_40989_3467.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100101_143755_000004472085_00354_40989_3469.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100101_145944_000007132085_00354_40989_3471.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100101_153509_000001752085_00355_40990_3472.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100101_154513_000004042085_00355_40990_3473.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100101_155422_000001632085_00355_40990_3485.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100101_160028_000007982085_00355_40990_3486.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100101_161605_000000842085_00355_40990_3488.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100101_164020_000006952085_00355_40990_3490.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100101_171546_000008882085_00356_40991_3492.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100101_172923_000001692085_00356_40991_3504.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100101_173925_000000782085_00356_40991_3503.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100101_174140_000002472085_00356_40991_3502.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100101_174659_000002712085_00356_40991_3505.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100101_182056_000006952085_00356_40991_3507.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100101_185400_000008942085_00357_40992_3510.N1					OK	OK	OK	OK

ASA_GM1_1PNPDK20100101_191041_000000782085_00357_40992_3520.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100101_191835_000002052085_00357_40992_3521.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100101_192504_000001202085_00357_40992_3525.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100101_202440_000010392085_00357_40992_3526.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100101_204638_000000722085_00358_40993_3527.N1	OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
ASA_IMM_1PNPDE20100101_021049_000000422085_00347_40982_2615.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20100101_024407_000002672085_00347_40982_2614.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20100101_035017_000000422085_00348_40983_2652.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20100101_042723_000001562085_00348_40983_2634.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20100101_043420_000000862085_00348_40983_2635.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20100101_053633_000000512085_00349_40984_2662.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20100101_053739_000001292085_00349_40984_2664.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20100101_054110_000000922085_00349_40984_2665.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20100101_060927_000001062085_00349_40984_2667.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20100101_074504_000001592085_00350_40985_2683.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20100101_075055_000002332085_00350_40985_2684.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20100101_091511_000000532085_00351_40986_2696.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20100101_093657_000000512085_00351_40986_2704.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20100101_111102_000000882085_00352_40987_2723.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20100101_153804_000003802085_00355_40990_2744.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20100101_154225_000001612085_00355_40990_2739.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20100101_174047_000000392085_00356_40991_2745.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20100101_174543_000000672085_00356_40991_2746.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20100101_175131_000000372085_00356_40991_2747.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20100101_184602_000000372085_00356_40991_2750.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20100101_200235_000003022085_00357_40992_2755.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20100101_200825_000002332085_00357_40992_2752.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20100101_214227_000002322085_00358_40993_2767.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20100101_214710_000003002085_00358_40993_2763.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20100101_231337_000000382085_00359_40994_2786.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20100101_232215_000001612085_00359_40994_2785.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20100101_232545_000003732085_00359_40994_2781.N1	OK	OK	OK	OK
ASA_IMM_1PNPDK20100101_072411_000002432085_00350_40985_3383.N1	OK	OK	OK	OK
ASA_IMM_1PNPDK20100101_155702_000001962085_00355_40990_3481.N1	OK	OK	OK	OK


Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WSM_1PNPDE20100101_000432_000002882085_00345_40980_2594.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100101_004154_000001162085_00346_40981_2597.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100101_004449_000003612085_00346_40981_2611.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100101_005925_000000982085_00346_40981_2612.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100101_014446_000002812085_00346_40981_2613.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100101_021634_000001652085_00347_40982_2624.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100101_022239_000004532085_00347_40982_2630.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100101_032415_000002942085_00347_40982_2655.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100101_035501_000002392085_00348_40983_2658.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100101_042306_000000982085_00348_40983_2633.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100101_050653_000000982085_00348_40983_2661.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100101_054547_000000982085_00349_40984_2666.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100101_061122_000000982085_00349_40984_2668.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100101_073819_000002142085_00350_40985_2682.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100101_080136_000001712085_00350_40985_2685.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100101_091617_000002882085_00351_40986_2702.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100101_092559_000000922085_00351_40986_2703.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100101_100630_000002812085_00351_40986_2724.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100101_104518_000002452085_00352_40987_2725.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100101_105017_000001102085_00352_40987_2726.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100101_142208_000001592085_00354_40989_2742.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100101_151141_000000982085_00354_40989_2743.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100101_165202_000001042085_00355_40990_2741.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100101_175223_000000862085_00356_40991_2748.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100101_183238_000001162085_00356_40991_2749.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100101_191211_000000862085_00357_40992_2751.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100101_192208_000001712085_00357_40992_2754.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100101_201250_000001282085_00357_40992_2753.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100101_215332_000002142085_00358_40993_2766.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100101_220333_000000982085_00358_40993_2768.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100101_233252_000002942085_00359_40994_2784.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100101_064545_000002082085_00349_40984_3382.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100101_072826_000001282085_00350_40985_3384.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100101_082624_000002452085_00350_40985_3404.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100101_092021_000002632085_00351_40986_3405.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100101_092501_000001162085_00351_40986_3406.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100101_105512_000004712085_00352_40987_3423.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100101_114804_000002082085_00352_40987_3438.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100101_115612_000000672085_00352_40987_3439.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100101_122947_000001842085_00353_40988_3440.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100101_124100_000002082085_00353_40988_3441.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100101_132645_000003362085_00353_40988_3462.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100101_141126_000001282085_00354_40989_3456.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100101_155203_000001282085_00355_40990_3480.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100101_173215_000004222085_00356_40991_3498.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100101_190857_000000982085_00357_40992_3516.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100101_191211_000003792085_00357_40992_3517.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100101_204811_000001222085_00358_40993_3530.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100101_205035_000000862085_00358_40993_3534.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100101_205336_000001712085_00358_40993_3536.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100101_223037_000004222085_00359_40994_3539.N1					OK	OK	OK	OK


Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WVS_1PNPDE20100101_000919_000002852085_00345_40980_2586.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100101_001319_000016642085_00345_40980_2599.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100101_010355_000009502085_00346_40981_2601.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100101_012626_000004652085_00346_40981_2603.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100101_014924_000002392085_00346_40981_2604.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100101_015239_000002402085_00346_40981_2623.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100101_020909_000000592085_00347_40982_2622.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100101_021137_000002542085_00347_40982_2618.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100101_025428_000009892085_00347_40982_2617.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100101_031043_000000302085_00347_40982_2636.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100101_032904_000001502085_00347_40982_2648.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100101_033727_000003892085_00347_40982_2646.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100101_034630_000001492085_00347_40982_2643.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100101_035311_000000592085_00348_40983_2640.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100101_043551_000007792085_00348_40983_2638.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100101_044836_000004052085_00348_40983_2663.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100101_050901_000015742085_00348_40983_2674.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100101_061342_000009142085_00349_40984_2673.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100101_210710_000020542085_00358_40993_2757.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100101_215707_000003152085_00358_40993_2758.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100101_220122_000000902085_00358_40993_2769.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100101_220511_000005542085_00358_40993_2770.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100101_222549_000002402085_00359_40994_2772.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100101_224659_000014092085_00359_40994_2774.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100101_231513_000003902085_00359_40994_2775.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100101_233745_000002852085_00359_40994_2776.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100101_234145_000016642085_00359_40994_2789.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100101_062827_000003602085_00349_40984_3373.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100101_064937_000020392085_00349_40984_3376.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100101_080828_000004952085_00350_40985_3395.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100101_083031_000021442085_00350_40985_3398.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100101_093754_000011542085_00351_40986_3414.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100101_101109_000019792085_00351_40986_3417.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100101_110831_000001192085_00352_40987_3426.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100101_111236_000015142085_00352_40987_3427.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100101_115133_000002402085_00352_40987_3428.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100101_115726_000015142085_00352_40987_3431.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100101_124427_000009142085_00353_40988_3446.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100101_131235_000003452085_00353_40988_3448.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100101_133219_000004652085_00353_40988_3450.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100101_134703_000004192085_00353_40988_3454.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100101_142852_000004942085_00354_40989_3468.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100101_144522_000008252085_00354_40989_3470.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100101_151319_000012592085_00354_40989_3474.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100101_161348_000000892085_00355_40990_3487.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100101_161738_000013192085_00355_40990_3489.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100101_165343_000012742085_00355_40990_3491.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100101_175350_000015742085_00356_40991_3506.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100101_183932_000003602085_00356_40991_3508.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100101_184646_000003892085_00356_40991_3509.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100101_192710_000020242085_00357_40992_3524.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100101_201504_000005402085_00357_40992_3528.N1					OK	OK	OK	OK


Calibration pulses for GM1 SS3 H/H




Calibration pulses for GM1 SS3 H/H




Calibration pulses for GM1 SS3 H/H




01-Jan



01-Jan







01-Jan



01-Jan


rows: _ 3 _ 7 _ 11 _ 15 _ 19 _ 23 _ 27 _ 31

Calibration pulses for GM1 SS3 H/H




rows: 4 8 12 16 20 24 28 32


Calibration pulses for WVS IS2 V/V




Calibration pulses for WVS IS2 V/V





Calibration pulses for WVS IS2 V/V







Calibration pulses for WVS IS2 V/V















































Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_APM_1PNPDE20100101_040201_000000402085_00348_40983_2659.N1						IS2	H/H	85	40983	348	5.03
ASA_APM_1PNPDK20100101_135449_000000422085_00354_40989_3463.N1						IS1	H/H	85	40989	354	5.03
ASA_APM_1PNPDE20100101_221604_000000432085_00359_40994_2787.N1						IS5	H/H	85	40994	359	5.03

Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_GM1_1PNPDE20100101_005053_000005072085_00346_40981_2598.N1						SS1	H/H	85	40981	346	5.03
ASA_GM1_1PNPDE20100101_010105_000001692085_00346_40981_2600.N1						SS1	H/H	85	40981	346	5.03
ASA_GM1_1PNPDE20100101_012032_000003502085_00346_40981_2602.N1						SS1	H/H	85	40981	346	5.03
ASA_GM1_1PNPDE20100101_013458_000005792085_00346_40981_2605.N1						SS1	H/H	85	40981	346	5.03
ASA_GM1_1PNPDE20100101_015728_000007012085_00346_40981_2621.N1						SS1	H/H	85	40981	346	5.03
ASA_GM1_1PNPDE20100101_021924_000001872085_00347_40982_2620.N1						SS1	H/H	85	40982	347	5.03
ASA_GM1_1PNPDE20100101_023015_000008342085_00347_40982_2619.N1						SS1	H/H	85	40982	347	5.03
ASA_GM1_1PNPDE20100101_024845_000003442085_00347_40982_2616.N1						SS1	H/H	85	40982	347	5.03
ASA_GM1_1PNPDE20100101_031531_000005192085_00347_40982_2637.N1						SS1	H/H	85	40982	347	5.03
ASA_GM1_1PNPDE20100101_033219_000003082085_00347_40982_2649.N1						SS1	H/H	85	40982	347	5.03
ASA_GM1_1PNPDE20100101_034439_000001022085_00347_40982_2647.N1						SS1	H/H	85	40982	347	5.03
ASA_GM1_1PNPDE20100101_035112_000001142085_00348_40983_2645.N1						SS1	H/H	85	40983	348	5.03
ASA_GM1_1PNPDE20100101_035903_000001812085_00348_40983_2644.N1						SS1	H/H	85	40983	348	5.03
ASA_GM1_1PNPDE20100101_040304_0000011962085_00348_40983_2642.N1						SS1	H/H	85	40983	348	5.03
ASA_GM1_1PNPDE20100101_042445_000001572085_00348_40983_2641.N1						SS1	H/H	85	40983	348	5.03
ASA_GM1_1PNPDE20100101_043012_000002472085_00348_40983_2639.N1						SS1	H/H	85	40983	348	5.03
ASA_GM1_1PNPDE20100101_045608_000004222085_00348_40983_2671.N1						SS1	H/H	85	40983	348	5.03
ASA_GM1_1PNPDE20100101_053958_000000662085_00349_40984_2670.N1						SS1	H/H	85	40984	349	5.03
ASA_GM1_1PNPDE20100101_054251_000001692085_00349_40984_2669.N1						SS1	H/H	85	40984	349	5.03
ASA_GM1_1PNPDE20100101_054730_0000013172085_00349_40984_2672.N1						SS1	H/H	85	40984	349	5.03
ASA_GM1_1PNPDK20100101_063644_000005312085_00349_40984_3374.N1						SS1	H/H	85	40984	349	5.03
ASA_GM1_1PNPDK20100101_073046_000004282085_00350_40985_3375.N1						SS1	H/H	85	40985	350	5.03
ASA_GM1_1PNPDK20100101_073650_000000782085_00350_40985_3391.N1						SS1	H/H	85	40985	350	5.03
ASA_GM1_1PNPDK20100101_074156_000001872085_00350_40985_3392.N1						SS1	H/H	85	40985	350	5.03
ASA_GM1_1PNPDK20100101_075455_000003922085_00350_40985_3393.N1						SS1	H/H	85	40985	350	5.03
ASA_GM1_1PNPDK20100101_080434_000002292085_00350_40985_3394.N1						SS1	H/H	85	40985	350	5.03
ASA_GM1_1PNPDK20100101_081720_000005372085_00350_40985_3396.N1						SS1	H/H	85	40985	350	5.03
ASA_GM1_1PNPDK20100101_090702_000004892085_00351_40986_3397.N1						SS1	H/H	85	40986	351	5.03
ASA_GM1_1PNPDK20100101_093428_000001502085_00351_40986_3413.N1						SS1	H/H	85	40986	351	5.03
ASA_GM1_1PNPDK20100101_095754_000005072085_00351_40986_3415.N1						SS1	H/H	85	40986	351	5.03
ASA_GM1_1PNPDK20100101_105212_000001752085_00352_40987_3416.N1						SS1	H/H	85	40987	352	5.03
ASA_GM1_1PNPDK20100101_113833_000005672085_00352_40987_3429.N1						SS1	H/H	85	40987	352	5.03
ASA_GM1_1PNPDK20100101_122319_000003802085_00353_40988_3430.N1						SS1	H/H	85	40988	353	5.03
ASA_GM1_1PNPDK20100101_123302_000002412085_00353_40988_3432.N1						SS1	H/H	85	40988	353	5.03
ASA_GM1_1PNPDK20100101_123553_000003022085_00353_40988_3444.N1						SS1	H/H	85	40988	353	5.03
ASA_GM1_1PNPDK20100101_130019_000005732085_00353_40988_3445.N1						SS1	H/H	85	40988	353	5.03
ASA_GM1_1PNPDK20100101_130959_000001502085_00353_40988_3447.N1						SS1	H/H	85	40988	353	5.03
ASA_GM1_1PNPDK20100101_131909_000004532085_00353_40988_3449.N1						SS1	H/H	85	40988	353	5.03
ASA_GM1_1PNPDK20100101_134041_000003802085_00353_40988_3451.N1						SS1	H/H	85	40988	353	5.03
ASA_GM1_1PNPDK20100101_135829_000001442085_00354_40989_3452.N1						SS1	H/H	85	40989	354	5.03
ASA_GM1_1PNPDK20100101_140157_000005612085_00354_40989_3453.N1						SS1	H/H	85	40989	354	5.03
ASA_GM1_1PNPDK20100101_141349_000001812085_00354_40989_3455.N1						SS1	H/H	85	40989	354	5.03
ASA_GM1_1PNPDK20100101_141536_000003862085_00354_40989_3466.N1						SS1	H/H	85	40989	354	5.03
ASA_GM1_1PNPDK20100101_142658_000001082085_00354_40989_3467.N1						SS1	H/H	85	40989	354	5.03
ASA_GM1_1PNPDK20100101_143755_000004472085_00354_40989_3469.N1						SS1	H/H	85	40989	354	5.03
ASA_GM1_1PNPDK20100101_145944_000007132085_00354_40989_3471.N1						SS1	H/H	85	40989	354	5.03
ASA_GM1_1PNPDK20100101_153509_000001752085_00355_40990_3472.N1						SS1	H/H	85	40990	355	5.03
ASA_GM1_1PNPDK20100101_154513_000004042085_00355_40990_3473.N1						SS1	H/H	85	40990	355	5.03
ASA_GM1_1PNPDK20100101_155422_000001632085_00355_40990_3485.N1						SS1	H/H	85	40990	355	5.03
ASA_GM1_1PNPDK20100101_160028_000007982085_00355_40990_3486.N1						SS1	H/H	85	40990	355	5.03
ASA_GM1_1PNPDK20100101_161605_000000842085_00355_40990_3488.N1						SS1	H/H	85	40990	355	5.03
ASA_GM1_1PNPDK20100101_164020_000006952085_00355_40990_3490.N1						SS1	H/H	85	40990	355	5.03
ASA_GM1_1PNPDK20100101_171546_000008882085_00356_40991_3492.N1						SS1	H/H	85	40991	356	5.03
ASA_GM1_1PNPDK20100101_172923_000001692085_00356_40991_3504.N1						SS1	H/H	85	40991	356	5.03
ASA_GM1_1PNPDK20100101_173925_000000782085_00356_40991_3503.N1						SS1	H/H	85	40991	356	5.03
ASA_GM1_1PNPDK20100101_174140_000002472085_00356_40991_3502.N1						SS1	H/H	85	40991	356	5.03
ASA_GM1_1PNPDK20100101_174659_000002712085_00356_40991_3505.N1						SS1	H/H	85	40991	356	5.03
ASA_GM1_1PNPDK20100101_182056_000006952085_00356_40991_3507.N1						SS1	H/H	85	40991	356	5.03
ASA_GM1_1PNPDK20100101_185400_000008942085_00357_40992_3510.N1						SS1	H/H	85	40992	357	5.03
ASA_GM1_1PNPDK20100101_191041_000000782085_00357_40992_3520.N1						SS1	H/H	85	40992	357	5.03
ASA_GM1_1PNPDK20100101_191835_000002052085_00357_40992_3521.N1						SS1	H/H	85	40992	357	5.03
ASA_GM1_1PNPDK20100101_192504_000001202085_00357_40992_3525.N1						SS1	H/H	85	40992	357	5.03
ASA_GM1_1PNPDK20100101_202440_0000010392085_00357_40992_3526.N1						SS1	H/H	85	40992	357	5.03
ASA_GM1_1PNPDK20100101_204638_000000722085_00358_40993_3527.N1						SS1	H/H	85	40993	358	5.03
ASA_GM1_1PNPDE20100101_205208_000000782085_00358_40993_2756.N1						SS1	H/H	85	40993	358	5.03
ASA_GM1_1PNPDE20100101_205632_000006282085_00358_40993_2759.N1						SS1	H/H	85	40993	358	5.03
ASA_GM1_1PNPDE20100101_221705_000005192085_00359_40994_2771.N1						SS1	H/H	85	40994	359	5.03

ASA_GM1_1PNPDE20100101_223746_000005492085_00359_40994_2773.N1	SS1	H/H	85	40994	359	5.03
ASA_GM1_1PNPDE20100101_231117_000001382085_00359_40994_2777.N1	SS1	H/H	85	40994	359	5.03



Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_IMM_1PNPDE20100101_021049_000000422085_00347_40982_2615.N1						IS2	V/V	85	40982	347	5.03
ASA_IMM_1PNPDE20100101_024407_000002672085_00347_40982_2614.N1						IS2	V/V	85	40982	347	5.03
ASA_IMM_1PNPDE20100101_035017_000000422085_00348_40983_2652.N1						IS2	V/V	85	40983	348	5.03
ASA_IMM_1PNPDE20100101_042723_000001562085_00348_40983_2634.N1						IS2	V/V	85	40983	348	5.03
ASA_IMM_1PNPDE20100101_043420_000000862085_00348_40983_2635.N1						IS2	V/V	85	40983	348	5.03
ASA_IMM_1PNPDE20100101_053633_000000512085_00349_40984_2662.N1						IS1	V/V	85	40984	349	5.03
ASA_IMM_1PNPDE20100101_053739_000001292085_00349_40984_2664.N1						IS2	V/V	85	40984	349	5.03
ASA_IMM_1PNPDE20100101_054110_000000922085_00349_40984_2665.N1						IS2	V/V	85	40984	349	5.03
ASA_IMM_1PNPDE20100101_060927_000001062085_00349_40984_2667.N1						IS2	V/V	85	40984	349	5.03
ASA_IMM_1PNPDK20100101_072411_000002432085_00350_40985_3383.N1						IS2	V/V	85	40985	350	5.03
ASA_IMM_1PNPDE20100101_074504_000001592085_00350_40985_2683.N1						IS2	V/V	85	40985	350	5.03
ASA_IMM_1PNPDE20100101_075055_000002332085_00350_40985_2684.N1						IS2	V/V	85	40985	350	5.03
ASA_IMM_1PNPDE20100101_091511_000000532085_00351_40986_2696.N1						IS2	H/H	85	40986	351	5.03
ASA_IMM_1PNPDE20100101_093657_000000512085_00351_40986_2704.N1						IS2	V/V	85	40986	351	5.03
ASA_IMM_1PNPDE20100101_111102_000000882085_00352_40987_2723.N1						IS2	V/V	85	40987	352	5.03
ASA_IMM_1PNPDE20100101_153804_000003802085_00355_40990_2744.N1						IS2	V/V	85	40990	355	5.03
ASA_IMM_1PNPDE20100101_154225_000001612085_00355_40990_2739.N1						IS2	V/V	85	40990	355	5.03
ASA_IMM_1PNPDK20100101_155702_000001962085_00355_40990_3481.N1						IS2	H/H	85	40990	355	5.03
ASA_IMM_1PNPDE20100101_174047_000000392085_00356_40991_2745.N1						IS2	H/H	85	40991	356	5.03
ASA_IMM_1PNPDE20100101_174543_000000672085_00356_40991_2746.N1						IS5	V/V	85	40991	356	5.03
ASA_IMM_1PNPDE20100101_175131_000000372085_00356_40991_2747.N1						IS2	V/V	85	40991	356	5.03
ASA_IMM_1PNPDE20100101_184602_000000372085_00356_40991_2750.N1						IS3	V/V	85	40991	356	5.03
ASA_IMM_1PNPDE20100101_200235_000003022085_00357_40992_2755.N1						IS2	H/H	85	40992	357	5.03
ASA_IMM_1PNPDE20100101_200825_000002332085_00357_40992_2752.N1						IS2	H/H	85	40992	357	5.03
ASA_IMM_1PNPDE20100101_214227_000002322085_00358_40993_2767.N1						IS2	H/H	85	40993	358	5.03
ASA_IMM_1PNPDE20100101_214710_000003002085_00358_40993_2763.N1						IS2	H/H	85	40993	358	5.03
ASA_IMM_1PNPDE20100101_231337_000000382085_00359_40994_2786.N1						IS4	V/V	85	40994	359	5.03
ASA_IMM_1PNPDE20100101_232215_000001612085_00359_40994_2785.N1						IS2	H/H	85	40994	359	5.03
ASA_IMM_1PNPDE20100101_232545_000003732085_00359_40994_2781.N1						IS2	H/H	85	40994	359	5.03

Filename	Pol	Timestamp	count(Module)
ASA_MS__0PNPDK20100101_063512_000000162085_00349_40984_0951.N1	V	2010-01-01 06:35:12	320



Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WSM_1PNPDE20091231_235728_000003612085_00345_40980_2593.N1						SS1	H/H	85	40980	345	5.03
ASA_WSM_1PNPDE20100101_000432_000002882085_00345_40980_2594.N1						SS1	H/H	85	40980	345	5.03
ASA_WSM_1PNPDE20100101_004154_000001162085_00346_40981_2597.N1						SS1	H/H	85	40981	346	5.03
ASA_WSM_1PNPDE20100101_004449_000003612085_00346_40981_2611.N1						SS1	H/H	85	40981	346	5.03
ASA_WSM_1PNPDE20100101_005925_000000982085_00346_40981_2612.N1						SS1	H/H	85	40981	346	5.03
ASA_WSM_1PNPDE20100101_014446_000002812085_00346_40981_2613.N1						SS1	H/H	85	40981	346	5.03
ASA_WSM_1PNPDE20100101_021634_000001652085_00347_40982_2624.N1						SS1	V/V	85	40982	347	5.03
ASA_WSM_1PNPDE20100101_022239_000004532085_00347_40982_2630.N1						SS1	H/H	85	40982	347	5.03
ASA_WSM_1PNPDE20100101_032415_000002942085_00347_40982_2655.N1						SS1	H/H	85	40982	347	5.03
ASA_WSM_1PNPDE20100101_035501_000002392085_00348_40983_2658.N1						SS1	H/H	85	40983	348	5.03
ASA_WSM_1PNPDE20100101_042306_000000982085_00348_40983_2633.N1						SS1	H/H	85	40983	348	5.03
ASA_WSM_1PNPDE20100101_050653_000000982085_00348_40983_2661.N1						SS1	H/H	85	40983	348	5.03
ASA_WSM_1PNPDE20100101_054547_000000982085_00349_40984_2666.N1						SS1	H/H	85	40984	349	5.03
ASA_WSM_1PNPDE20100101_061122_000000982085_00349_40984_2668.N1						SS1	V/V	85	40984	349	5.03
ASA_WSM_1PNPDK20100101_064545_000002082085_00349_40984_3382.N1						SS1	H/H	85	40984	349	5.03
ASA_WSM_1PNPDK20100101_072826_000001282085_00350_40985_3384.N1						SS1	H/H	85	40985	350	5.03
ASA_WSM_1PNPDE20100101_073819_000002142085_00350_40985_2682.N1						SS1	H/H	85	40985	350	5.03
ASA_WSM_1PNPDE20100101_080136_000001712085_00350_40985_2685.N1						SS1	H/H	85	40985	350	5.03
ASA_WSM_1PNPDK20100101_082624_000002452085_00350_40985_3404.N1						SS1	H/H	85	40985	350	5.03
ASA_WSM_1PNPDE20100101_091617_000002882085_00351_40986_2702.N1						SS1	H/H	85	40986	351	5.03
ASA_WSM_1PNPDK20100101_092021_000002632085_00351_40986_3405.N1						SS1	H/H	85	40986	351	5.03
ASA_WSM_1PNPDK20100101_092501_000001162085_00351_40986_3406.N1						SS1	V/V	85	40986	351	5.03
ASA_WSM_1PNPDE20100101_092559_000000922085_00351_40986_2703.N1						SS1	V/V	85	40986	351	5.03
ASA_WSM_1PNPDE20100101_100630_000002812085_00351_40986_2724.N1						SS1	H/H	85	40986	351	5.03
ASA_WSM_1PNPDE20100101_104518_000002452085_00352_40987_2725.N1						SS1	H/H	85	40987	352	5.03
ASA_WSM_1PNPDE20100101_105017_000001102085_00352_40987_2726.N1						SS1	H/H	85	40987	352	5.03
ASA_WSM_1PNPDK20100101_105512_000004712085_00352_40987_3423.N1						SS1	H/H	85	40987	352	5.03
ASA_WSM_1PNPDK20100101_114804_000002082085_00352_40987_3438.N1						SS1	H/H	85	40987	352	5.03
ASA_WSM_1PNPDK20100101_115612_000000672085_00352_40987_3439.N1						SS1	V/V	85	40987	352	5.03
ASA_WSM_1PNPDK20100101_122947_000001842085_00353_40988_3440.N1						SS1	H/H	85	40988	353	5.03
ASA_WSM_1PNPDK20100101_124100_000002082085_00353_40988_3441.N1						SS1	H/H	85	40988	353	5.03
ASA_WSM_1PNPDK20100101_132645_000003362085_00353_40988_3462.N1						SS1	H/H	85	40988	353	5.03
ASA_WSM_1PNPDK20100101_141126_000001282085_00354_40989_3456.N1						SS1	H/H	85	40989	354	5.03
ASA_WSM_1PNPDE20100101_142208_000001592085_00354_40989_2742.N1						SS1	H/H	85	40989	354	5.03
ASA_WSM_1PNPDE20100101_151141_000000982085_00354_40989_2743.N1						SS1	H/H	85	40989	354	5.03
ASA_WSM_1PNPDK20100101_155203_000001282085_00355_40990_3480.N1						SS1	H/H	85	40990	355	5.03
ASA_WSM_1PNPDE20100101_165202_000001042085_00355_40990_2741.N1						SS1	H/H	85	40990	355	5.03
ASA_WSM_1PNPDK20100101_173215_000004222085_00356_40991_3498.N1						SS1	H/H	85	40991	356	5.03
ASA_WSM_1PNPDE20100101_175223_000000862085_00356_40991_2748.N1						SS1	V/V	85	40991	356	5.03
ASA_WSM_1PNPDE20100101_183238_000001162085_00356_40991_2749.N1						SS1	H/H	85	40991	356	5.03
ASA_WSM_1PNPDK20100101_190857_000000982085_00357_40992_3516.N1						SS1	H/H	85	40992	357	5.03
ASA_WSM_1PNPDE20100101_191211_000000862085_00357_40992_2751.N1						SS1	H/H	85	40992	357	5.03
ASA_WSM_1PNPDK20100101_191211_000003792085_00357_40992_3517.N1						SS1	H/H	85	40992	357	5.03
ASA_WSM_1PNPDE20100101_192208_000001712085_00357_40992_2754.N1						SS1	H/H	85	40992	357	5.03
ASA_WSM_1PNPDE20100101_201250_000001282085_00357_40992_2753.N1						SS1	H/H	85	40992	357	5.03
ASA_WSM_1PNPDK20100101_204811_000001222085_00358_40993_3530.N1						SS1	H/H	85	40993	358	5.03
ASA_WSM_1PNPDK20100101_205035_000000862085_00358_40993_3534.N1						SS1	V/V	85	40993	358	5.03
ASA_WSM_1PNPDK20100101_205336_000001712085_00358_40993_3536.N1						SS1	H/H	85	40993	358	5.03
ASA_WSM_1PNPDE20100101_215332_000002142085_00358_40993_2766.N1						SS1	H/H	85	40993	358	5.03
ASA_WSM_1PNPDE20100101_220333_000000982085_00358_40993_2768.N1						SS1	V/V	85	40993	358	5.03
ASA_WSM_1PNPDK20100101_223037_000004222085_00359_40994_3539.N1						SS1	H/H	85	40994	359	5.03
ASA_WSM_1PNPDE20100101_233252_000002942085_00359_40994_2784.N1						SS1	H/H	85	40994	359	5.03

Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WVS_1PNPDE20100101_000919_000002852085_00345_40980_2586.N1						IS2	V/V	85	40980	345	5.03
ASA_WVS_1PNPDE20100101_001319_000016642085_00345_40980_2599.N1						IS2	V/V	85	40980	345	5.03
ASA_WVS_1PNPDE20100101_010355_000009502085_00346_40981_2601.N1						IS2	V/V	85	40981	346	5.03
ASA_WVS_1PNPDE20100101_012626_000004652085_00346_40981_2603.N1						IS2	V/V	85	40981	346	5.03
ASA_WVS_1PNPDE20100101_014924_000002392085_00346_40981_2604.N1						IS2	V/V	85	40981	346	5.03
ASA_WVS_1PNPDE20100101_015239_000002402085_00346_40981_2623.N1						IS2	V/V	85	40981	346	5.03
ASA_WVS_1PNPDE20100101_014924_000002392085_00346_40981_2604.N1						IS1	V/V	85	40981	346	5.03
ASA_WVS_1PNPDE20100101_020909_000000592085_00347_40982_2622.N1						IS2	V/V	85	40982	347	5.03
ASA_WVS_1PNPDE20100101_021137_000002542085_00347_40982_2618.N1						IS2	V/V	85	40982	347	5.03
ASA_WVS_1PNPDE20100101_025428_000009892085_00347_40982_2617.N1						IS2	V/V	85	40982	347	5.03
ASA_WVS_1PNPDE20100101_031043_000000302085_00347_40982_2636.N1						IS2	V/V	85	40982	347	5.03
ASA_WVS_1PNPDE20100101_025428_000009892085_00347_40982_2617.N1						IS1	V/V	85	40982	347	5.03
ASA_WVS_1PNPDE20100101_032904_000001502085_00347_40982_2648.N1						IS2	V/V	85	40982	347	5.03
ASA_WVS_1PNPDE20100101_033727_000003892085_00347_40982_2646.N1						IS2	V/V	85	40982	347	5.03
ASA_WVS_1PNPDE20100101_034630_000001492085_00347_40982_2643.N1						IS2	V/V	85	40982	347	5.03
ASA_WVS_1PNPDE20100101_035311_000000592085_00348_40983_2640.N1						IS2	V/V	85	40983	348	5.03
ASA_WVS_1PNPDE20100101_043551_000007792085_00348_40983_2638.N1						IS2	V/V	85	40983	348	5.03
ASA_WVS_1PNPDE20100101_044836_000004052085_00348_40983_2663.N1						IS2	V/V	85	40983	348	5.03
ASA_WVS_1PNPDE20100101_043551_000007792085_00348_40983_2638.N1						IS1	V/V	85	40983	348	5.03
ASA_WVS_1PNPDE20100101_050901_000015742085_00348_40983_2674.N1						IS2	V/V	85	40983	348	5.03
ASA_WVS_1PNPDE20100101_061342_000009142085_00349_40984_2673.N1						IS2	V/V	85	40984	349	5.03
ASA_WVS_1PNPDK20100101_062827_000003602085_00349_40984_3373.N1						IS2	V/V	85	40984	349	5.03
ASA_WVS_1PNPDE20100101_061342_000009142085_00349_40984_2673.N1						IS1	V/V	85	40984	349	5.03
ASA_WVS_1PNPDK20100101_064937_000020392085_00349_40984_3376.N1						IS2	V/V	85	40984	349	5.03
ASA_WVS_1PNPDK20100101_080828_000004952085_00350_40985_3395.N1						IS2	V/V	85	40985	350	5.03
ASA_WVS_1PNPDK20100101_083031_000021442085_00350_40985_3398.N1						IS2	V/V	85	40985	350	5.03
ASA_WVS_1PNPDK20100101_093754_000011542085_00351_40986_3414.N1						IS2	V/V	85	40986	351	5.03
ASA_WVS_1PNPDK20100101_101109_000019792085_00351_40986_3417.N1						IS2	V/V	85	40986	351	5.03
ASA_WVS_1PNPDK20100101_110831_000001192085_00352_40987_3426.N1						IS2	V/V	85	40987	352	5.03
ASA_WVS_1PNPDK20100101_111236_000015142085_00352_40987_3427.N1						IS2	V/V	85	40987	352	5.03
ASA_WVS_1PNPDK20100101_115133_000002402085_00352_40987_3428.N1						IS2	V/V	85	40987	352	5.03
ASA_WVS_1PNPDK20100101_115726_000015142085_00352_40987_3431.N1						IS2	V/V	85	40987	352	5.03
ASA_WVS_1PNPDK20100101_124427_000009142085_00353_40988_3446.N1						IS2	V/V	85	40988	353	5.03
ASA_WVS_1PNPDK20100101_131235_000003452085_00353_40988_3448.N1						IS2	V/V	85	40988	353	5.03
ASA_WVS_1PNPDK20100101_133219_000004652085_00353_40988_3450.N1						IS2	V/V	85	40988	353	5.03
ASA_WVS_1PNPDK20100101_134703_000004192085_00353_40988_3454.N1						IS2	V/V	85	40988	353	5.03
ASA_WVS_1PNPDK20100101_142852_000004942085_00354_40989_3468.N1						IS2	V/V	85	40989	354	5.03
ASA_WVS_1PNPDK20100101_144522_000008252085_00354_40989_3470.N1						IS2	V/V	85	40989	354	5.03
ASA_WVS_1PNPDK20100101_151319_000012592085_00354_40989_3474.N1						IS2	V/V	85	40989	354	5.03
ASA_WVS_1PNPDK20100101_161348_00000892085_00355_40990_3487.N1						IS2	V/V	85	40990	355	5.03
ASA_WVS_1PNPDK20100101_161738_000013192085_00355_40990_3489.N1						IS2	V/V	85	40990	355	5.03
ASA_WVS_1PNPDK20100101_165343_000012742085_00355_40990_3491.N1						IS2	V/V	85	40990	355	5.03
ASA_WVS_1PNPDK20100101_175350_000015742085_00356_40991_3506.N1						IS2	V/V	85	40991	356	5.03
ASA_WVS_1PNPDK20100101_183932_000003602085_00356_40991_3508.N1						IS2	V/V	85	40991	356	5.03
ASA_WVS_1PNPDK20100101_184646_000003892085_00356_40991_3509.N1						IS2	V/V	85	40991	356	5.03
ASA_WVS_1PNPDK20100101_192710_000020242085_00357_40992_3524.N1						IS2	V/V	85	40992	357	5.03
ASA_WVS_1PNPDK20100101_201504_000005402085_00357_40992_3528.N1						IS2	V/V	85	40992	357	5.03
ASA_WVS_1PNPDE20100101_210710_000020542085_00358_40993_2757.N1						IS2	V/V	85	40993	358	5.03
ASA_WVS_1PNPDE20100101_215707_000003152085_00358_40993_2758.N1						IS2	V/V	85	40993	358	5.03
ASA_WVS_1PNPDE20100101_220122_000000902085_00358_40993_2769.N1						IS2	V/V	85	40993	358	5.03
ASA_WVS_1PNPDE20100101_220511_000005542085_00358_40993_2770.N1						IS2	V/V	85	40993	358	5.03
ASA_WVS_1PNPDE20100101_222549_000002402085_00359_40994_2772.N1						IS2	V/V	85	40994	359	5.03
ASA_WVS_1PNPDE20100101_224659_000014092085_00359_40994_2774.N1						IS2	V/V	85	40994	359	5.03
ASA_WVS_1PNPDE20100101_231513_000003902085_00359_40994_2775.N1						IS2	V/V	85	40994	359	5.03
ASA_WVS_1PNPDE20100101_233745_000002852085_00359_40994_2776.N1						IS2	V/V	85	40994	359	5.03
ASA_WVS_1PNPDE20100101_234145_000016642085_00359_40994_2789.N1						IS2	V/V	85	40994	359	5.03

