



Analysis from 21-JUN-2010 00:00:00 to 21-JUN-2010 23:59:59. Page generated on 22-JUN-2010 07:32:19.
View log file: ASAR_Daily_Report_20100622_0731.log. For any anomalies please contact emma.griffiths@vega.co.uk, kajal.haria@vega.co.uk.

This report is automatically generated every day, every 2 hours. No comments are provided on the results.

SUMMARY

1. DATA SUMMARY
 - 1.1 Summary tables
 - 1.2 Lists of products used
2. AUXILIARY FILES ANALYSIS
 - 2.1 IECF operational ADFs list
 - 2.2 Products with wrong ADFs
3. MODULE STEPPING PRODUCTS ANALYSIS
 - 3.1 V/V polarisation
 - 3.2 H/H polarisation
4. CALIBRATION PULSES ANALYSIS
 - 4.1 Analysis for WVS IS2 V/V
 - 4.1.1 Temporal Evolution Analysis for WVS IS2 V/V
 - 4.1.2 All Rows Analysis for WVS IS2 V/V
 - 4.2 Analysis for GM1 SS3 H/H
 - 4.2.1 Temporal Evolution Analysis for GM1 SS3 H/H
 - 4.2.2 All Rows Analysis for GM1 SS3 H/H
5. DOPPLER ANALYSIS
 - 5.1 Analysis for WVS IS2 V/V
 - 5.1.1 Doppler MAP Analysis for WVS IS2 V/V
 - 5.1.2 Doppler ANX Analysis for WVS IS2 V/V
 - 5.2 Analysis for GM1 SS1 H/H
 - 5.2.1 Doppler MAP Analysis for GM1 SS1 H/H
 - 5.2.2 Doppler ANX Analysis for GM1 SS1 H/H
 - 5.3 Doppler JUMPS Analysis for WSM
6. CHIRP ANALYSIS
 - 6.1 Analysis for WSM SS1 H/H
 - 6.1.1 ScaleFactor
 - 6.2 Analysis for WSM SS1 V/V
 - 6.2.1 ScaleFactor
7. RAW DATA ANALYSIS
 - 7.1 Analysis for WVS
 - 7.2 Analysis for IMM
8. TELEMETRY ANALYSIS
 - 8.1 Number of Missing Lines
 - 8.2 Number of Gaps

1 - DATA SUMMARY

1.1 - Summary tables

[[BACK TO MENU](#)]

WVS				GM1				APM				IMM				WSM				MS			
Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Time	Pol	Modules
PDE	IS1	V/V	4	PDE	WS	H/H	36	PDE	IS4	V/H	1	PDE	IS2	H/H	20	PDE	WS	H/H	22	PDE	2010-06-21 01:59:13	H	320
PDE	IS2	V/V	31	PDK	WS	H/H	33	PDE	IS4	V/V	1	PDE	IS2	V/V	14	PDE	WS	V/V	7	PDK	2010-06-21 08:41:36	V	320
PDK	IS2	V/V	23									PDE	IS7	V/V	1	PDK	WS	H/H	11				
												PDK	IS2	H/H	3								
												PDK	IS2	V/V	1								

1.2 - Lists of products used

[[BACK TO MENU](#)]

[\[TXT\]](#) [\[XLS\]](#) List_WVS_products_used
[\[TXT\]](#) [\[XLS\]](#) List_GM1_products_used
[\[TXT\]](#) [\[XLS\]](#) List_APM_products_used
[\[TXT\]](#) [\[XLS\]](#) List_IMM_products_used
[\[TXT\]](#) [\[XLS\]](#) List_WSM_products_used
[\[TXT\]](#) [\[XLS\]](#) List_MS_products_used

2 - AUXILIARY FILES ANALYSIS

2.1 - IECF operational ADFs list

[[BACK TO MENU](#)]

ADFs disseminated for ASAR
ASA_CON_AXVIEC20100608_125449_20100317_120410_20101231_000000
ASA_INS_AXVIEC20091217_114637_20090428_100000_20101231_235959
ASA_XCH_AXVIEC20091217_113006_20020301_000000_20101231_000000
ASA_XCA_AXVIEC20100608_123419_20100317_120410_20110101_000000

2.2 - Products with wrong ADFs

[[BACK TO MENU](#)]

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
WVS	0	0	0	0
GM1	0	0	0	0
APM	0	0	0	0
IMM	0	0	0	0
WSM	0	0	0	0

[\[TXT\]](#) [\[XLS\]](#) Check_ADFs_WVS
[\[TXT\]](#) [\[XLS\]](#) Check_ADFs_GM1
[\[TXT\]](#) [\[XLS\]](#) Check_ADFs_APM
[\[TXT\]](#) [\[XLS\]](#) Check_ADFs_IMM
[\[TXT\]](#) [\[XLS\]](#) Check_ADFs_WSM

3 - MODULE STEPPING PRODUCTS ANALYSIS

SECOND FIXED REFERENCE

Pre-launch reference (2001-02-09)


Reference: 2001-02-09 14:08:23 V RxGain
 Test : 2010-06-21 08:41:36 V



PREVIOUS PRODUCT REFERENCE

Previous product in the same polarisation


Reference: 2010-06-20 02:30:50 V RxGain
 Test : 2010-06-21 08:41:36 V



Reference: 2001-02-09 14:08:23 V RxPhase
 Test : 2010-06-21 08:41:36 V



Reference: 2010-06-20 02:30:50 V RxPhase
 Test : 2010-06-21 08:41:36 V






3.2 - H/H polarisation


[[BACK TO MENU](#)]

SECOND FIXED REFERENCE	PREVIOUS PRODUCT REFERENCE
Pre-launch reference (2001-02-09)	Previous product in the same polarisation


Reference: 2001-02-09 13:50:42 H RxGain
 Test : 2010-06-21 01:59:13 H




Reference: 2010-06-19 03:02:27 H RxGain
 Test : 2010-06-21 01:59:13 H







Reference: 2001-02-09 13:50:42 H RxPhase
 Test : 2010-06-21 01:59:13 H



Reference: 2010-06-19 03:02:27 H RxPhase
 Test : 2010-06-21 01:59:13 H





4 - CALIBRATION PULSES ANALYSIS

4.1 - Analysis for WVS IS2 V/V


4.1.1 - Temporal Evolution Analysis for WVS IS2 V/V

[BACK TO MENU]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Calibration pulses for WVS IS2 V/V




Transmit power (P1 - P1a) for WVS IS2 V/V



4.1.2 - All Rows Analysis for WVS IS2 V/V

[[BACK TO MENU](#)]





4.2 - Analysis for GM1 SS3 H/H


4.2.1 - Temporal Evolution Analysis for GM1 SS3 H/H

[BACK TO MENU]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Calibration pulses for GM1 SS3 H/H




Transmit power (P1 - P1a) for GM1 SS3 H/H



4.2.2 - All Rows Analysis for GM1 SS3 H/H

[[BACK TO MENU](#)]






5 - DOPPLER ANALYSIS

5.1 - Analysis for WVS IS2 V/V

5.1.1 - Doppler MAP Analysis for WVS IS2 V/V

[[BACK TO MENU](#)]






5.1.2 - Doppler ANX Analysis for WVS IS2 V/V

[[BACK TO MENU](#)]






5.2 - Analysis for GM1 SS1 H/H

5.2.1 - Doppler MAP Analysis for GM1 SS1 H/H

[[BACK TO MENU](#)]






5.2.2 - Doppler ANX Analysis for GM1 SS1 H/H

[[BACK TO MENU](#)]






5.3 - Doppler JUMPS Analysis for WSM

[[BACK TO MENU](#)]








6 - CHIRP ANALYSIS

6.1 - Analysis for WSM SS1 H/H

6.1.1 - ScaleFactor

[[BACK TO MENU](#)]







6.2 - Analysis for WSM SS1 V/V

6.2.1 - ScaleFactor

[[BACK TO MENU](#)]






7 - RAW DATA ANALYSIS

7.1 - Analysis for WVS

[[BACK TO MENU](#)]

--	--	--




Channel	Statistics	DSS-B
MEAN I	mean	0.000625091
	stdev	1.09865e-07
MEAN Q	mean	0.000479150
	stdev	1.98692e-07
Channel	Statistics	DSS-B
STDEV I	mean	0.153376
	stdev	0.00125105
STDEV Q	mean	0.153962
	stdev	0.00127657

7.2 - Analysis for IMM

[[BACK TO MENU](#)]







8 - TELEMETRY ANALYSIS

Processing Center	Product	Gaps	Missing lines
PDE	ASA_IMM_1PNPDE20100621_160224_000000372090_00298_43438_0731.N1	0	2
PDE	ASA_WSM_1PNPDE20100621_063029_000000922090_00292_43432_0544.N1	0	1

8.1 - Number of Missing lines


[[BACK TO MENU](#)]





8.2 - Number of Gaps

[\[BACK TO MENU \]](#)



ASAR DAILY REPORT for 100621
#####

MODE: DAILY
ANALYSIS: ALL
DATE: YESTERDAY

Analysis will be performed from 2010-06-21 00:00:00 to 2010-06-21 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_100621/

DATA SUMMARY

Summary will be performed from 2010-06-21 00:00:00 to 2010-06-21 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_100621/DATA_SUMMARY

Creating directory ./RESULTS/DAILY/_100621/DATA_SUMMARY...
Writing file ./RESULTS/DAILY/_100621/DATA_SUMMARY/Data_summary.html...

Getting WVS products list from 2010-06-21 00:00:00 to 2010-06-21 23:59:59...
Writing file ./RESULTS/DAILY/_100621/DATA_SUMMARY/List_WVS_products_used.xls...
Writing file ./RESULTS/DAILY/_100621/DATA_SUMMARY/List_WVS_products_used.txt...

Getting GM1 products list from 2010-06-21 00:00:00 to 2010-06-21 23:59:59...
Writing file ./RESULTS/DAILY/_100621/DATA_SUMMARY/List_GM1_products_used.xls...
Writing file ./RESULTS/DAILY/_100621/DATA_SUMMARY/List_GM1_products_used.txt...

Getting APM products list from 2010-06-21 00:00:00 to 2010-06-21 23:59:59...
Writing file ./RESULTS/DAILY/_100621/DATA_SUMMARY/List_APM_products_used.xls...
Writing file ./RESULTS/DAILY/_100621/DATA_SUMMARY/List_APM_products_used.txt...

Getting IMM products list from 2010-06-21 00:00:00 to 2010-06-21 23:59:59...
Writing file ./RESULTS/DAILY/_100621/DATA_SUMMARY/List_IMM_products_used.xls...
Writing file ./RESULTS/DAILY/_100621/DATA_SUMMARY/List_IMM_products_used.txt...

Getting WSM products list from 2010-06-21 00:00:00 to 2010-06-21 23:59:59...
Writing file ./RESULTS/DAILY/_100621/DATA_SUMMARY/List_WSM_products_used.xls...
Writing file ./RESULTS/DAILY/_100621/DATA_SUMMARY/List_WSM_products_used.txt...

Getting MS products list from 2010-06-21 00:00:00 to 2010-06-21 23:59:59...
Writing file ./RESULTS/DAILY/_100621/DATA_SUMMARY/List_MS_products_used.xls...
Writing file ./RESULTS/DAILY/_100621/DATA_SUMMARY/List_MS_products_used.txt...

DATA SUMMARY completed
#####

AUXILIARY FILES ANALYSIS

Analysis will be performed from 2010-06-21 00:00:00 to 2010-06-21 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_100621/AUXILIARY

Creating directory ./RESULTS/DAILY/_100621/AUXILIARY...

Looking for the IECF operational ADFs list...



ADF filter 20100621*current_3_IECF_ADFs.txt
 Found list 20100621_030003_current_3_IECF_ADFs.txt...
 Extracting ADFs...

ASA_CON_AXVIEC20100608_125449_20100317_120410_20101231_000000
 ASA_INS_AXVIEC20091217_114637_20090428_100000_20101231_235959
 ASA_XCH_AXVIEC20091217_113006_20020301_000000_20101231_000000
 ASA_XCA_AXVIEC20100608_123419_20100317_120410_20110101_000000

Writing file ./RESULTS/DAILY/_100621/AUXILIARY/ASAR_ADFs_IECF_List3.html...
 Writing file ./RESULTS/DAILY/_100621/AUXILIARY/Auxiliary_files_summary.html...

Analysing WVS products...

Writing file ./RESULTS/DAILY/_100621/AUXILIARY/Check_ADFs_WVS.xls...
 Writing file ./RESULTS/DAILY/_100621/AUXILIARY/Check_ADFs_WVS.txt...

ASA_WVS_1PNPDE20100621_001137_000003742090_00288_43428_0441.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100621_003457_000003902090_00288_43428_0446.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100621_004042_000003742090_00288_43428_0465.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100621_005101_000009592090_00288_43428_0469.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100621_014503_000001342090_00289_43429_0468.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100621_015046_000004652090_00289_43429_0473.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100621_021510_00000592090_00289_43429_0471.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100621_021510_000003902090_00289_43429_0487.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100621_023528_000001942090_00290_43430_0490.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100621_023528_000001942090_00290_43430_0493.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100621_032220_000006592090_00290_43430_0488.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100621_032220_000006592090_00290_43430_0491.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100621_033250_000002252090_00290_43430_0522.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100621_040021_000008992090_00290_43430_0520.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100621_045948_000008542090_00291_43431_0518.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100621_051333_000001052090_00291_43431_0560.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100621_051755_000001052090_00291_43431_0559.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100621_053631_000015442090_00291_43431_0555.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100621_064401_000001342090_00292_43432_0554.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100621_064741_000004342090_00292_43432_0553.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100621_195214_000019792090_00300_43440_0746.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100621_204145_000001802090_00300_43440_0747.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100621_204400_000001202090_00300_43440_0761.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100621_213242_000019792090_00301_43441_0764.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100621_222248_000003452090_00301_43441_0765.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100621_222748_000007192090_00301_43441_0781.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100621_224809_000005252090_00302_43442_0783.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100621_231311_000010192090_00302_43442_0784.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100621_233410_00000442090_00302_43442_0785.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100621_234108_000003152090_00302_43442_0789.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100621_065440_000003452090_00292_43432_5592.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100621_071707_000019042090_00292_43432_5597.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100621_083218_000005252090_00293_43433_5611.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100621_085743_000020242090_00293_43433_5614.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100621_100406_000010492090_00294_43434_5630.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100621_103819_000018442090_00294_43434_5635.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100621_112756_000007192090_00295_43435_5648.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100621_114126_000012442090_00295_43435_5649.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100621_121845_000004202090_00295_43435_5650.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100621_123027_000001042090_00295_43435_5652.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100621_123457_000007522090_00295_43435_5657.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100621_130937_000008692090_00296_43436_5673.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100621_135921_000004352090_00296_43436_5676.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100621_141937_000001342090_00297_43437_5678.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100621_145553_000005842090_00297_43437_5690.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100621_150854_000008692090_00297_43437_5692.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100621_153957_000013042090_00297_43437_5700.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100621_164303_000012442090_00298_43438_5709.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK



ASA_WVS_1PNPDK20100621_172033_000014092090_00298_43438_5711.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100621_181834_000015592090_00299_43439_5725.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100621_190109_000000452090_00299_43439_5724.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100621_190405_000004202090_00299_43439_5726.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100621_191521_000001342090_00299_43439_5727.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

Analysing GM1 products...

Writing file ./RESULTS/DAILY/_100621/AUXILIARY/Check_ADFs_GM1.xls...

Writing file ./RESULTS/DAILY/_100621/AUXILIARY/Check_ADFs_GM1.txt...

ASA_GM1_1PNPDE20100621_000235_000005372090_00288_43428_0442.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100621_001841_000001202090_00288_43428_0447.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100621_004910_000001022090_00288_43428_0466.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100621_011505_000010452090_00289_43429_0467.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100621_013721_000004592090_00289_43429_0470.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100621_014756_000001692090_00289_43429_0474.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100621_020031_000003202090_00289_43429_0472.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100621_022218_000007912090_00289_43429_0496.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100621_024530_000004652090_00290_43430_0495.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100621_025401_000010092090_00290_43430_0494.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100621_031635_000003442090_00290_43430_0489.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100621_031635_000003442090_00290_43430_0492.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100621_034330_000004222090_00290_43430_0525.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100621_035433_000000722090_00290_43430_0524.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100621_035648_000002112090_00290_43430_0523.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100621_042022_000018312090_00291_43431_0521.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100621_045538_000002472090_00291_43431_0519.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100621_052027_000000842090_00291_43431_0562.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100621_053422_000001202090_00291_43431_0561.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100621_060306_000006222090_00292_43432_0558.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100621_061507_000003322090_00292_43432_0557.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100621_062710_000001932090_00292_43432_0556.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100621_063201_000007192090_00292_43432_0552.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100621_193429_000001812090_00300_43440_0744.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100621_194330_000005192090_00300_43440_0745.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100621_202548_000001502090_00300_43440_0748.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100621_205018_000011302090_00300_43440_0759.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100621_212322_000002112090_00301_43441_0760.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100621_212932_000001872090_00301_43441_0763.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100621_220627_000000902090_00301_43441_0762.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100621_221206_000000782090_00301_43441_0766.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100621_224034_000003982090_00302_43442_0782.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100621_230111_000007192090_00302_43442_0788.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100621_233541_000002172090_00302_43442_0787.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100621_233927_000000962090_00302_43442_0786.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100621_234945_000001022090_00302_43442_0791.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100621_070100_000001382090_00292_43432_5594.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100621_070722_000001022090_00292_43432_5593.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100621_071514_000001082090_00292_43432_5595.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100621_075546_000002652090_00293_43433_5598.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100621_081805_000008522090_00293_43433_5610.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100621_084256_000005862090_00293_43433_5612.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100621_093218_000005432090_00294_43434_5615.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100621_120736_000001812090_00295_43435_5651.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100621_122625_000002412090_00295_43435_5653.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100621_124809_000005612090_00296_43436_5656.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100621_130010_000001992090_00296_43436_5658.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100621_130244_000002772090_00296_43436_5669.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100621_132449_000001812090_00296_43436_5670.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100621_132922_000003802090_00296_43436_5671.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100621_133552_000003682090_00296_43436_5672.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100621_134326_000006282090_00296_43436_5674.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100621_140714_000002892090_00296_43436_5675.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100621_141318_000003802090_00296_43436_5677.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

ASA_GM1_1PNPDK20100621_142527_000006832090_00297_43437_5679.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100621_144901_000004102090_00297_43437_5689.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100621_150614_000001572090_00297_43437_5691.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100621_152402_000007792090_00297_43437_5693.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100621_160311_000002832090_00298_43438_5694.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100621_161025_000002772090_00298_43438_5701.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100621_162423_000001142090_00298_43438_5707.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100621_162921_000007372090_00298_43438_5708.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100621_170439_000002112090_00298_43438_5710.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100621_174439_000006712090_00299_43439_5712.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100621_175446_000001142090_00299_43439_5721.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100621_180428_000007012090_00299_43439_5722.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100621_184513_000001812090_00299_43439_5723.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100621_191147_000001142090_00299_43439_5729.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100621_191813_000010452090_00299_43439_5728.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

Analysing APM products...

Writing file ./RESULTS/DAILY/_100621/AUXILIARY/Check_ADFs_APM.xls...

Writing file ./RESULTS/DAILY/_100621/AUXILIARY/Check_ADFs_APM.txt...

ASA_APM_1PNPDE20100621_041603_000001752090_00291_43431_0516.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20100621_132749_00000762090_00296_43436_0727.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

Analysing IMM products...

Writing file ./RESULTS/DAILY/_100621/AUXILIARY/Check_ADFs_IMM.xls...

Writing file ./RESULTS/DAILY/_100621/AUXILIARY/Check_ADFs_IMM.txt...

ASA_IMM_1PNPDE20100621_002044_000005122090_00288_43428_0456.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100621_020553_000002332090_00289_43429_0482.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100621_024439_00000372090_00290_43430_0503.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100621_025311_00000372090_00290_43430_0504.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100621_031051_000002152090_00290_43430_0484.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100621_031445_00000992090_00290_43430_0486.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100621_034055_000001462090_00290_43430_0509.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100621_045115_000002502090_00291_43431_0517.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100621_052155_000001362090_00291_43431_0533.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100621_052525_000003732090_00291_43431_0545.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100621_064706_00000282090_00292_43432_0550.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100621_070318_000002322090_00292_43432_0567.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100621_095221_00000372090_00294_43434_0634.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100621_095642_00000372090_00294_43434_0635.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100621_102338_000004432090_00294_43434_0657.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100621_114027_00000532090_00295_43435_0679.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100621_120334_000002322090_00295_43435_0686.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100621_160224_00000372090_00298_43438_0731.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100621_160754_000001422090_00298_43438_0732.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100621_164135_00000832090_00298_43438_0736.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100621_170806_000003022090_00298_43438_0737.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100621_170806_000003022090_00298_43438_0741.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100621_171356_000002332090_00298_43438_0733.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100621_181605_000001442090_00299_43439_0740.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100621_184811_000003022090_00299_43439_0742.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100621_185411_000002112090_00299_43439_0738.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100621_202817_000003022090_00300_43440_0757.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100621_203407_000002332090_00300_43440_0755.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100621_211137_00000372090_00301_43441_0775.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100621_220803_000002302090_00301_43441_0779.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100621_220803_000002302090_00301_43441_0780.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100621_221332_000002642090_00301_43441_0774.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100621_224710_00000532090_00302_43442_0777.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK



```

ASA_IMM_1PNPDE20100621_234801_000000912090_00302_43442_0837.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100621_235131_000003732090_00302_43442_0797.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20100621_070908_000001622090_00292_43432_5602.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20100621_074928_000001832090_00293_43433_5607.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20100621_121034_000000922090_00295_43435_5664.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20100621_193731_000000512090_00300_43440_5731.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

```

Analysing WSM products...

Writing file ./RESULTS/DAILY/_100621/AUXILIARY/Check_ADFs_WSM.xls...

Writing file ./RESULTS/DAILY/_100621/AUXILIARY/Check_ADFs_WSM.txt...

```

ASA_WSM_1PNPDE20100621_003027_000002692090_00288_43428_0457.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100621_010812_000004102090_00289_43429_0481.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100621_021017_000002882090_00289_43429_0483.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100621_023932_000002452090_00290_43430_0497.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100621_035040_000002262090_00290_43430_0515.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100621_053205_000001282090_00291_43431_0546.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100621_061333_000000862090_00292_43432_0551.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100621_063029_000000922090_00292_43432_0544.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100621_080019_000004222090_00293_43433_0675.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100621_081106_000002392090_00293_43433_0714.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100621_081106_000002392090_00293_43433_0717.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100621_094130_000001842090_00294_43434_0625.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100621_094508_000001472090_00294_43434_0632.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100621_094829_000000922090_00294_43434_0633.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100621_103307_000002202090_00294_43434_0677.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100621_135412_000002452090_00296_43436_0728.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100621_142354_000000862090_00297_43437_0729.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100621_144519_000002202090_00297_43437_0730.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100621_153706_000001282090_00297_43437_0726.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100621_162629_000001712090_00298_43438_0735.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100621_171804_000001162090_00298_43438_0734.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100621_185806_000001282090_00299_43439_0739.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100621_191353_000000922090_00299_43439_0743.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100621_203905_000001222090_00300_43440_0756.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100621_204643_000002142090_00300_43440_0758.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100621_212700_000001472090_00301_43441_0778.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100621_221856_000002322090_00301_43441_0776.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100621_233052_000002022090_00302_43442_0800.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100621_235844_000002942090_00302_43442_0799.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100621_075322_000001412090_00293_43433_5608.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100621_121316_000002692090_00295_43435_5667.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100621_125738_000001472090_00296_43436_5660.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100621_130729_000001282090_00296_43436_5668.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100621_143656_000002322090_00297_43437_5684.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100621_144124_000003062090_00297_43437_5683.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100621_161512_000003062090_00298_43438_5705.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100621_162129_000001652090_00298_43438_5706.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100621_175652_000002142090_00299_43439_5719.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100621_180132_000001712090_00299_43439_5720.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100621_193846_000002812090_00300_43440_5736.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

```

AUXILIARY FILES ANALYSIS completed

#####

MODULE STEPPING ANALYSIS

#####

Analysis will be performed from 2010-06-21 00:00:00 to 2010-06-21 23:59:59

Results will be exported to the directory: ./RESULTS/DAILY/_100621/MODULE_STEPPING


```
Creating directory ./RESULTS/DAILY/_100621/MODULE_STEPPING...
Creating directory ./RESULTS/DAILY/_100621/MODULE_STEPPING/FIRST_REFERENCE...
Creating directory ./RESULTS/DAILY/_100621/MODULE_STEPPING/SECOND_REFERENCE...
Creating directory ./RESULTS/DAILY/_100621/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE...
Deleting old files...
```

```
*****
*****
Creating images comparing with second reference...
```

```
Exporting results to the directory ../../RESULTS/DAILY/_100621/MODULE_STEPPING/SECOND_REFERENCE...
```

```
Polarization: H
Reference product: ASA_MS__0PNPDK20010209_135042_0000009A024_00180_11700_0052.N1
Test product: ASA_MS__0PNPDE20100621_015913_000000162090_00289_43429_0554.N1
  H
  H
../../RESULTS/DAILY/_100621/MODULE_STEPPING/SECOND_REFERENCE/TGH_20100621_015913-20010209_135042.png
../../RESULTS/DAILY/_100621/MODULE_STEPPING/SECOND_REFERENCE/TPH_20100621_015913-20010209_135042.png
../../RESULTS/DAILY/_100621/MODULE_STEPPING/SECOND_REFERENCE/RGH_20100621_015913-20010209_135042.png
../../RESULTS/DAILY/_100621/MODULE_STEPPING/SECOND_REFERENCE/RPH_20100621_015913-20010209_135042.png
```

```
Polarization: V
Reference product: ASA_MS__0PNPDK20010209_140823_0000009A024_00180_11700_0054.N1
Test product: ASA_MS__0PNPDK20100621_084136_000000162090_00293_43433_0144.N1
  V
  V
../../RESULTS/DAILY/_100621/MODULE_STEPPING/SECOND_REFERENCE/TGV_20100621_084136-20010209_140823.png
../../RESULTS/DAILY/_100621/MODULE_STEPPING/SECOND_REFERENCE/TPV_20100621_084136-20010209_140823.png
../../RESULTS/DAILY/_100621/MODULE_STEPPING/SECOND_REFERENCE/RGV_20100621_084136-20010209_140823.png
../../RESULTS/DAILY/_100621/MODULE_STEPPING/SECOND_REFERENCE/RPV_20100621_084136-20010209_140823.png
```

```
*****
*****
Creating images comparing with previous product reference...
```

```
Exporting results to the directory ../../RESULTS/DAILY/_100621/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE...
```

```
Polarization: H
Reference product: ASA_MS__0PNPDE20100619_030227_000000162090_00261_43401_0552.N1
Test product: ASA_MS__0PNPDE20100621_015913_000000162090_00289_43429_0554.N1
  H
  H
../../RESULTS/DAILY/_100621/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TGH_20100621_015913-20100619_030227.png
../../RESULTS/DAILY/_100621/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TPH_20100621_015913-20100619_030227.png
../../RESULTS/DAILY/_100621/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RGH_20100621_015913-20100619_030227.png
../../RESULTS/DAILY/_100621/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RPH_20100621_015913-20100619_030227.png
```

```
Polarization: V
Reference product: ASA_MS__0PNPDE20100620_023050_000000162090_00275_43415_0553.N1
Test product: ASA_MS__0PNPDK20100621_084136_000000162090_00293_43433_0144.N1
  V
  V
../../RESULTS/DAILY/_100621/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TGV_20100621_084136-20100620_023050.png
../../RESULTS/DAILY/_100621/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TPV_20100621_084136-20100620_023050.png
../../RESULTS/DAILY/_100621/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RGV_20100621_084136-20100620_023050.png
../../RESULTS/DAILY/_100621/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RPV_20100621_084136-20100620_023050.png
```

```
MODULE_STEPPING ANALYSIS completed
#####
```

```
CALIBRATION PULSES ANALYSIS
#####
Creating directory ./RESULTS/DAILY/_100621/CALIBRATION_PULSES...
```


ALL ROWS Analysis will be performed from 2010-06-21 00:00:00 to 2010-06-21 23:59:59

Analysing products WVS IS2 V/V

Writing image ../../RESULTS/DAILY/_100621//CALIBRATION_PULSES/Calibration_pulses_all_rows_WVS_IS2_VV.png...

Analysing products GM1 SS3 H/H

Writing image ../../RESULTS/DAILY/_100621//CALIBRATION_PULSES/Calibration_pulses_all_rows_GM1_SS3_HH.png...

TEMPORAL EVOLUTION Analysis will be performed from 2010-06-21 00:00:00 to 2010-06-21 23:59:59

Analysing products WVS IS2 V/V

Getting calibration pulses data for WVS IS2 V/V from 2010-06-21 00:00:00 to 2010-06-21 23:59:59. Rows: 1/5/9/13/17/21/25/29

Writing file ./RESULTS/DAILY/_100621/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2010-06-21_1.dat...

Writing ../../RESULTS/DAILY/_100621//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_1.png...

Writing ../../RESULTS/DAILY/_100621//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_1.png...

Getting calibration pulses data for WVS IS2 V/V from 2010-06-21 00:00:00 to 2010-06-21 23:59:59. Rows: 2/6/10/14/18/22/26/30

Writing file ./RESULTS/DAILY/_100621/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2010-06-21_2.dat...

Writing ../../RESULTS/DAILY/_100621//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_2.png...

Writing ../../RESULTS/DAILY/_100621//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_2.png...

Getting calibration pulses data for WVS IS2 V/V from 2010-06-21 00:00:00 to 2010-06-21 23:59:59. Rows: 3/7/11/15/19/23/27/31

Writing file ./RESULTS/DAILY/_100621/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2010-06-21_3.dat...

Writing ../../RESULTS/DAILY/_100621//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_3.png...

Writing ../../RESULTS/DAILY/_100621//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_3.png...

Getting calibration pulses data for WVS IS2 V/V from 2010-06-21 00:00:00 to 2010-06-21 23:59:59. Rows: 4/8/12/16/20/24/28/32

Writing file ./RESULTS/DAILY/_100621/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2010-06-21_4.dat...

Writing ../../RESULTS/DAILY/_100621//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_4.png...

Writing ../../RESULTS/DAILY/_100621//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_4.png...

Analysing products GM1 SS3 H/H

Getting calibration pulses data for GM1 SS3 H/H from 2010-06-21 00:00:00 to 2010-06-21 23:59:59. Rows: 1/5/9/13/17/21/25/29

Writing file ./RESULTS/DAILY/_100621/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2010-06-21_1.dat...

Writing ../../RESULTS/DAILY/_100621//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_1.png...

Writing ../../RESULTS/DAILY/_100621//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_1.png...

Getting calibration pulses data for GM1 SS3 H/H from 2010-06-21 00:00:00 to 2010-06-21 23:59:59. Rows: 2/6/10/14/18/22/26/30

Writing file ./RESULTS/DAILY/_100621/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2010-06-21_2.dat...

Writing ../../RESULTS/DAILY/_100621//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_2.png...

Writing ../../RESULTS/DAILY/_100621//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_2.png...

Getting calibration pulses data for GM1 SS3 H/H from 2010-06-21 00:00:00 to 2010-06-21 23:59:59. Rows: 3/7/11/15/19/23/27/31

Writing file ./RESULTS/DAILY/_100621/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2010-06-21_3.dat...

Writing ../../RESULTS/DAILY/_100621//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_3.png...

Writing ../../RESULTS/DAILY/_100621//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_3.png...

Getting calibration pulses data for GM1 SS3 H/H from 2010-06-21 00:00:00 to 2010-06-21 23:59:59. Rows: 4/8/12/16/20/24/28/32

Writing file ./RESULTS/DAILY/_100621/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2010-06-21_4.dat...

Writing ../../RESULTS/DAILY/_100621//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_4.png...

Writing ../../RESULTS/DAILY/_100621//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_4.png...

CALIBRATION PULSES ANALYSIS completed

#####

DOPPLER ANALYSIS

#####

Creating directory ./RESULTS/DAILY/_100621/DOPPLER...

DOPPLER ANX Analysis will be performed from 2010-06-21 00:00:00 to 2010-06-21 23:59:59

Analysing products WVS IS2 V/V
Getting doppler data for WVS IS2 V/V from 2010-06-21 00:00:00 to 2010-06-21 23:59:59...
Writing file ./RESULTS/DAILY/_100621/DOPPLER/Doppler_data_WVS_IS2_VV_2010-06-21.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/_100621/DOPPLER/DOPPLER_ANX_WVS_IS2_VV.png...

Analysing products GM1 SS1 H/H
Getting doppler data for GM1 SS1 H/H from 2010-06-21 00:00:00 to 2010-06-21 23:59:59...
Writing file ./RESULTS/DAILY/_100621/DOPPLER/Doppler_data_GM1_SS1_HH_2010-06-21.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/_100621/DOPPLER/DOPPLER_ANX_GM1_SS1_HH.png...

DOPPLER JUMPS Analysis will be performed on WSM products from 2010-06-21 00:00:00 to 2010-06-21 23:59:59

Analysing by default products WSM
Getting doppler jumps data for WSM from 2010-06-21 00:00:00 to 2010-06-21 23:59:59...
Writing file ./RESULTS/DAILY/_100621/DOPPLER/Doppler_Jumps_data_WSM_2010-06-21.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/_100621/DOPPLER/DOPPLER_JUMPS_ANX_WSM.png...
Writing file ../../RESULTS/DAILY/_100621/DOPPLER/DOPPLER_JUMPS_Date_WSM.png...

DOPPLER MAP Analysis will be performed from 2010-06-21 00:00:00 to 2010-06-21 23:59:59

Analysing products WVS IS2 V/V
Loading predicted doppler values....
Phase: descending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -34.070132 Hz
Writing file ../../RESULTS/DAILY/_100621//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_WVS_IS2_VV_desc.jpg...
Writing file ../../RESULTS/DAILY/_100621//DOPPLER/DOPPLER_Absolute_WVS_IS2_VV_desc.jpg...

Loading predicted doppler values....
Phase: ascending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -32.268825 Hz
Writing file ../../RESULTS/DAILY/_100621//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_WVS_IS2_VV_asc.jpg...
Writing file ../../RESULTS/DAILY/_100621//DOPPLER/DOPPLER_Absolute_WVS_IS2_VV_asc.jpg...

Analysing products GM1 SS1 H/H
Loading predicted doppler values....
Phase: descending
Found data...
Computing mean error doppler estimated-predicted...

Mean error = -3.6427093 Hz
Writing file ../../RESULTS/DAILY/_100621//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_GM1_SS1_HH_desc.jpg...
Writing file ../../RESULTS/DAILY/_100621//DOPPLER/DOPPLER_Absolute_GM1_SS1_HH_desc.jpg...

Loading predicted doppler values....
Phase: ascending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -14.298548 Hz
Writing file ../../RESULTS/DAILY/_100621//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_GM1_SS1_HH_asc.jpg...
Writing file ../../RESULTS/DAILY/_100621//DOPPLER/DOPPLER_Absolute_GM1_SS1_HH_asc.jpg...

DOPPLER ANALYSIS completed
#####

CHIRP ANALYSIS

Creating directory ./RESULTS/DAILY/_100621/CHIRP...

CHIRP Analysis will be performed from 2010-06-21 00:00:00 to 2010-06-21 23:59:59

Analysing products WSM SS1 H/H

Getting ScaleFactor data for WSM SS1 H/H from 2010-06-21 00:00:00 to 2010-06-21 23:59:59...
Writing file ./RESULTS/DAILY/_100621/CHIRP/ScaleFactor_data_WSM_SS1_HH_2010-06-21.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/_100621/CHIRP/ScaleFactor_ANX_WSM_SS1_HH.png...
Writing file ../../RESULTS/DAILY/_100621/CHIRP/ScaleFactor_DATE_WSM_SS1_HH.png...

Analysing products WSM SS1 V/V

Getting ScaleFactor data for WSM SS1 V/V from 2010-06-21 00:00:00 to 2010-06-21 23:59:59...
Writing file ./RESULTS/DAILY/_100621/CHIRP/ScaleFactor_data_WSM_SS1_VV_2010-06-21.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/_100621/CHIRP/ScaleFactor_ANX_WSM_SS1_VV.png...
Writing file ../../RESULTS/DAILY/_100621/CHIRP/ScaleFactor_DATE_WSM_SS1_VV.png...

CHIRP ANALYSIS completed
#####

RAW DATA ANALYSIS

Analysis will be performed from 2010-06-21 00:00:00 to 2010-06-21 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_100621/RAW_DATA

Creating directory ./RESULTS/DAILY/_100621/RAW_DATA...

Getting raw data for WVS from 2010-06-21 00:00:00 to 2010-06-21 23:59:59...
Writing file ./RESULTS/DAILY/_100621/RAW_DATA/Raw_data_WVS_2010-06-21.dat...
Running IDL program to create graphs...

Creating image ../../RESULTS/DAILY/_100621/RAW_DATA/Raw_data_WVS_input_mean.png...

Creating image ../../RESULTS/DAILY/_100621/RAW_DATA/Raw_data_WVS_input_stdev.png...
Creating image ../../RESULTS/DAILY/_100621/RAW_DATA/Raw_data_WVS_gain_imbalance.png...

Getting raw data for IMM from 2010-06-21 00:00:00 to 2010-06-21 23:59:59...
Writing file ./RESULTS/DAILY/_100621/RAW_DATA/Raw_data_IMM_2010-06-21.dat...
Running IDL program to create graphs...

Creating image ../../RESULTS/DAILY/_100621/RAW_DATA/Raw_data_IMM_input_mean.png...
Creating image ../../RESULTS/DAILY/_100621/RAW_DATA/Raw_data_IMM_input_stdev.png...
Creating image ../../RESULTS/DAILY/_100621/RAW_DATA/Raw_data_IMM_gain_imbalance.png...

RAW DATA ANALYSIS completed
#####

TELEMETRY ANALYSIS

Analysis will be performed from 2010-06-21 00:00:00 to 2010-06-21 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_100621/TELEMETRY

Creating directory ./RESULTS/DAILY/_100621/TELEMETRY...

Looking for gaps and missing lines in WVS products...

Checking 31 products from PDE...
Checking 23 products from PDK...

Looking for gaps and missing lines in GM1 products...

Checking 36 products from PDE...
Checking 33 products from PDK...

Looking for gaps and missing lines in APM products...

Checking 2 products from PDE...
No products from PDK...

Looking for gaps and missing lines in IMM products...

Checking 35 products from PDE...
Found product...ASA_IMM_1PNPDE20100621_160224_00000372090_00298_43438_0731.N1 / 0 gaps / 2 missing lines
Checking 4 products from PDK...

Looking for gaps and missing lines in WSM products...

Checking 29 products from PDE...
Found product...ASA_WSM_1PNPDE20100621_063029_00000922090_00292_43432_0544.N1 / 0 gaps / 1 missing lines
Checking 11 products from PDK...

Creating graph of missing lines and gaps...

Creating image: ./RESULTS/DAILY/_100621/TELEMETRY/TELEMETRY_Missing_lines.png...
Creating image: ./RESULTS/DAILY/_100621/TELEMETRY/TELEMETRY_Gaps.png...

TELEMETRY ANALYSIS completed
#####

HTML REPORT generation
#####

Building file ./RESULTS/DAILY/_100621/asarReport.html...
Building DATA SUMMARY section...

Building AUXILIARY FILES ANALYSIS section...
Building MODULE STEPPING ANALYSIS section...
Building CALIBRATION PULSES ANALYSIS section...
Building DOPPLER ANALYSIS section...
Building CHIRP ANALYSIS section...
Building RAW DATA ANALYSIS section...
Building TELEMETRY ANALYSIS section...

HTML REPORT generation completed

#####



Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_APM_1PNPDE20100621_041603_000001752090_00291_43431_0516.N1					OK	OK	OK	OK
ASA_APM_1PNPDE20100621_132749_000000762090_00296_43436_0727.N1					OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_GM1_1PNPDE20100621_000235_000005372090_00288_43428_0442.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100621_001841_000001202090_00288_43428_0447.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100621_004910_000001022090_00288_43428_0466.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100621_011505_000010452090_00289_43429_0467.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100621_013721_000004592090_00289_43429_0470.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100621_014756_000001692090_00289_43429_0474.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100621_020031_000003202090_00289_43429_0472.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100621_022218_000007912090_00289_43429_0496.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100621_024530_000004652090_00290_43430_0495.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100621_025401_000010092090_00290_43430_0494.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100621_031635_000003442090_00290_43430_0489.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100621_031635_000003442090_00290_43430_0492.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100621_034330_000004222090_00290_43430_0525.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100621_035433_000000722090_00290_43430_0524.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100621_035648_000002112090_00290_43430_0523.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100621_042022_000018312090_00291_43431_0521.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100621_045538_000002472090_00291_43431_0519.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100621_052027_000000842090_00291_43431_0562.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100621_053422_000001202090_00291_43431_0561.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100621_060306_000006222090_00292_43432_0558.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100621_061507_000003322090_00292_43432_0557.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100621_062710_000001932090_00292_43432_0556.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100621_063201_000007192090_00292_43432_0552.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100621_193429_000001812090_00300_43440_0744.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100621_194330_000005192090_00300_43440_0745.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100621_202548_000001502090_00300_43440_0748.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100621_205018_000011302090_00300_43440_0759.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100621_212322_000002112090_00301_43441_0760.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100621_212932_000001872090_00301_43441_0763.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100621_220627_000000902090_00301_43441_0762.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100621_221206_000000782090_00301_43441_0766.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100621_224034_000003982090_00302_43442_0782.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100621_230111_000007192090_00302_43442_0788.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100621_233541_000002172090_00302_43442_0787.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100621_233927_000000962090_00302_43442_0786.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100621_234945_000001022090_00302_43442_0791.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100621_070100_000001382090_00292_43432_5594.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100621_070722_000001022090_00292_43432_5593.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100621_071514_000001082090_00292_43432_5595.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100621_075546_000002652090_00293_43433_5598.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100621_081805_000008522090_00293_43433_5610.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100621_084256_000005862090_00293_43433_5612.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100621_093218_000005432090_00294_43434_5615.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100621_120736_000001812090_00295_43435_5651.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100621_122625_000002412090_00295_43435_5653.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100621_124809_000005612090_00296_43436_5656.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100621_130010_000001992090_00296_43436_5658.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100621_130244_000002772090_00296_43436_5669.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100621_132449_000001812090_00296_43436_5670.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100621_132922_000003802090_00296_43436_5671.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100621_133552_000003682090_00296_43436_5672.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100621_134326_000006282090_00296_43436_5674.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100621_140714_000002892090_00296_43436_5675.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100621_141318_000003802090_00296_43436_5677.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100621_142527_000006832090_00297_43437_5679.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100621_144901_000004102090_00297_43437_5689.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100621_150614_000001572090_00297_43437_5691.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100621_152402_000007792090_00297_43437_5693.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100621_160311_000002832090_00298_43438_5694.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100621_161025_000002772090_00298_43438_5701.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100621_162423_000001142090_00298_43438_5707.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100621_162921_000007372090_00298_43438_5708.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100621_170439_000002112090_00298_43438_5710.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100621_174439_000006712090_00299_43439_5712.N1					OK	OK	OK	OK

ASA_GM1_1PNPDK20100621_175446_000001142090_00299_43439_5721.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100621_180428_000007012090_00299_43439_5722.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100621_184513_000001812090_00299_43439_5723.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100621_191147_000001142090_00299_43439_5729.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100621_191813_000010452090_00299_43439_5728.N1	OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_IMM_1PNPDE20100621_002044_000005122090_00288_43428_0456.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100621_020553_000002332090_00289_43429_0482.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100621_024439_000000372090_00290_43430_0503.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100621_025311_000000372090_00290_43430_0504.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100621_031051_000002152090_00290_43430_0484.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100621_031445_000000992090_00290_43430_0486.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100621_034055_000001462090_00290_43430_0509.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100621_045115_000002502090_00291_43431_0517.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100621_052155_000001362090_00291_43431_0533.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100621_052525_000003732090_00291_43431_0545.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100621_064706_000000282090_00292_43432_0550.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100621_070318_000002322090_00292_43432_0567.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100621_095221_000000372090_00294_43434_0634.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100621_095642_000000372090_00294_43434_0635.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100621_102338_000004432090_00294_43434_0657.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100621_114027_000000532090_00295_43435_0679.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100621_120334_000002322090_00295_43435_0686.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100621_160224_000000372090_00298_43438_0731.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100621_160754_000001422090_00298_43438_0732.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100621_164135_000000832090_00298_43438_0736.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100621_170806_000003022090_00298_43438_0737.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100621_170806_000003022090_00298_43438_0741.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100621_171356_000002332090_00298_43438_0733.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100621_181605_000001442090_00299_43439_0740.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100621_184811_000003022090_00299_43439_0742.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100621_185411_000002112090_00299_43439_0738.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100621_202817_000003022090_00300_43440_0757.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100621_203407_000002332090_00300_43440_0755.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100621_211137_000000372090_00301_43441_0775.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100621_220803_000002302090_00301_43441_0779.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100621_220803_000002302090_00301_43441_0780.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100621_221332_000002642090_00301_43441_0774.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100621_224710_000000532090_00302_43442_0777.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100621_234801_000000912090_00302_43442_0837.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100621_235131_000003732090_00302_43442_0797.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20100621_070908_000001622090_00292_43432_5602.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20100621_074928_000001832090_00293_43433_5607.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20100621_121034_000000922090_00295_43435_5664.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20100621_193731_000000512090_00300_43440_5731.N1					OK	OK	OK	OK


Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WSM_1PNPDE20100621_003027_000002692090_00288_43428_0457.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100621_010812_000004102090_00289_43429_0481.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100621_021017_000002882090_00289_43429_0483.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100621_023932_000002452090_00290_43430_0497.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100621_035040_000002262090_00290_43430_0515.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100621_053205_000001282090_00291_43431_0546.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100621_061333_000000862090_00292_43432_0551.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100621_063029_000000922090_00292_43432_0544.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100621_080019_000004222090_00293_43433_0675.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100621_081106_000002392090_00293_43433_0714.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100621_081106_000002392090_00293_43433_0717.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100621_094130_000001842090_00294_43434_0625.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100621_094508_000001472090_00294_43434_0632.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100621_094829_000000922090_00294_43434_0633.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100621_103307_000002202090_00294_43434_0677.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100621_135412_000002452090_00296_43436_0728.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100621_142354_000000862090_00297_43437_0729.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100621_144519_000002202090_00297_43437_0730.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100621_153706_000001282090_00297_43437_0726.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100621_162629_000001712090_00298_43438_0735.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100621_171804_000001162090_00298_43438_0734.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100621_185806_000001282090_00299_43439_0739.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100621_191353_000000922090_00299_43439_0743.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100621_203905_000001222090_00300_43440_0756.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100621_204643_000002142090_00300_43440_0758.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100621_212700_000001472090_00301_43441_0778.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100621_221856_000002322090_00301_43441_0776.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100621_233052_000002022090_00302_43442_0800.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100621_235844_000002942090_00302_43442_0799.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100621_075322_000001412090_00293_43433_5608.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100621_121316_000002692090_00295_43435_5667.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100621_125738_000001472090_00296_43436_5660.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100621_130729_000001282090_00296_43436_5668.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100621_143656_000002322090_00297_43437_5684.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100621_144124_000003062090_00297_43437_5683.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100621_161512_000003062090_00298_43438_5705.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100621_162129_000001652090_00298_43438_5706.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100621_175652_000002142090_00299_43439_5719.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100621_180132_000001712090_00299_43439_5720.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100621_193846_000002812090_00300_43440_5736.N1					OK	OK	OK	OK





Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WVS_1PNPDE20100621_001137_000003742090_00288_43428_0441.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100621_003457_000003902090_00288_43428_0446.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100621_004042_000003742090_00288_43428_0465.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100621_005101_000009592090_00288_43428_0469.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100621_014503_000001342090_00289_43429_0468.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100621_015046_000004652090_00289_43429_0473.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100621_021510_000005592090_00289_43429_0471.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100621_021510_000003902090_00289_43429_0487.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100621_023528_000001942090_00290_43430_0490.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100621_023528_000001942090_00290_43430_0493.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100621_032220_000006592090_00290_43430_0488.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100621_032220_000006592090_00290_43430_0491.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100621_033250_000002252090_00290_43430_0522.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100621_040021_000008992090_00290_43430_0520.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100621_045948_000008542090_00291_43431_0518.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100621_051333_000001052090_00291_43431_0560.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100621_051755_000001052090_00291_43431_0559.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100621_053631_000015442090_00291_43431_0555.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100621_064401_000001342090_00292_43432_0554.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100621_064741_000004342090_00292_43432_0553.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100621_195214_000019792090_00300_43440_0746.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100621_204145_000001802090_00300_43440_0747.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100621_204400_000001202090_00300_43440_0761.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100621_213242_000019792090_00301_43441_0764.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100621_222248_000003452090_00301_43441_0765.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100621_222748_000007192090_00301_43441_0781.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100621_224809_000005252090_00302_43442_0783.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100621_231311_000010192090_00302_43442_0784.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100621_233410_000000442090_00302_43442_0785.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100621_234108_000003152090_00302_43442_0789.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100621_065440_000003452090_00292_43432_5592.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100621_071707_000019042090_00292_43432_5597.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100621_083218_000005252090_00293_43433_5611.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100621_085743_000020242090_00293_43433_5614.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100621_100406_000010492090_00294_43434_5630.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100621_103819_000018442090_00294_43434_5635.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100621_112756_000007192090_00295_43435_5648.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100621_114126_000012442090_00295_43435_5649.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100621_121845_000004202090_00295_43435_5650.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100621_123027_000001042090_00295_43435_5652.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100621_123457_000007522090_00295_43435_5657.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100621_130937_000008692090_00296_43436_5673.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100621_135921_000004352090_00296_43436_5676.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100621_141937_000001342090_00297_43437_5678.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100621_145553_000005842090_00297_43437_5690.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100621_150854_000008692090_00297_43437_5692.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100621_153957_000013042090_00297_43437_5700.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100621_164303_000012442090_00298_43438_5709.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100621_172033_000014092090_00298_43438_5711.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100621_181834_000015592090_00299_43439_5725.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100621_190109_000000452090_00299_43439_5724.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100621_190405_000004202090_00299_43439_5726.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100621_191521_000001342090_00299_43439_5727.N1					OK	OK	OK	OK

Calibration pulses for GM1 SS3 H/H







Calibration pulses for GM1 SS3 H/H







rows: — 2 — 6 — 10 — 14 — 18 — 22 — 26 — 30

Calibration pulses for GM1 SS3 H/H




rows: _ 3 _ 7 _ 11 _ 15 _ 19 _ 23 _ 27 _ 31


Calibration pulses for GM1 SS3 H/H




Calibration pulses for WVS IS2 V/V







Calibration pulses for WVS IS2 V/V




Calibration pulses for WVS IS2 V/V






Calibration pulses for WVS IS2 V/V







rows: _ 4 _ 8 _ 12 _ 16 _ 20 _ 24 _ 28 _ 32











































Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion				
ASA_APM_1PNPDE20100621_041603_000001752090_00291_43431_0516.N1						IS4 V/V 90	43431	291	5.03	
ASA_APM_1PNPDE20100621_132749_000000762090_00296_43436_0727.N1						IS4 V/H 90	43436	296	5.03	

Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_GM1_1PNPDE20100621_000235_000005372090_00288_43428_0442.N1						SS1	H/H	90	43428	288	5.03
ASA_GM1_1PNPDE20100621_001841_000001202090_00288_43428_0447.N1						SS1	H/H	90	43428	288	5.03
ASA_GM1_1PNPDE20100621_004910_000001022090_00288_43428_0466.N1						SS1	H/H	90	43428	288	5.03
ASA_GM1_1PNPDE20100621_011505_000010452090_00289_43429_0467.N1						SS1	H/H	90	43429	289	5.03
ASA_GM1_1PNPDE20100621_013721_000004592090_00289_43429_0470.N1						SS1	H/H	90	43429	289	5.03
ASA_GM1_1PNPDE20100621_014756_000001692090_00289_43429_0474.N1						SS1	H/H	90	43429	289	5.03
ASA_GM1_1PNPDE20100621_020031_000003202090_00289_43429_0472.N1						SS1	H/H	90	43429	289	5.03
ASA_GM1_1PNPDE20100621_022218_000007912090_00289_43429_0496.N1						SS1	H/H	90	43429	289	5.03
ASA_GM1_1PNPDE20100621_024530_000004652090_00290_43430_0495.N1						SS1	H/H	90	43430	290	5.03
ASA_GM1_1PNPDE20100621_025401_000010092090_00290_43430_0494.N1						SS1	H/H	90	43430	290	5.03
ASA_GM1_1PNPDE20100621_031635_000003442090_00290_43430_0489.N1						SS1	H/H	90	43430	290	5.03
ASA_GM1_1PNPDE20100621_031635_000003442090_00290_43430_0492.N1						SS1	H/H	90	43430	290	5.03
ASA_GM1_1PNPDE20100621_034330_000004222090_00290_43430_0525.N1						SS1	H/H	90	43430	290	5.03
ASA_GM1_1PNPDE20100621_035433_000000722090_00290_43430_0524.N1						SS1	H/H	90	43430	290	5.03
ASA_GM1_1PNPDE20100621_035648_000002112090_00290_43430_0523.N1						SS1	H/H	90	43430	290	5.03
ASA_GM1_1PNPDE20100621_042022_000018312090_00291_43431_0521.N1						SS1	H/H	90	43431	291	5.03
ASA_GM1_1PNPDE20100621_045538_000002472090_00291_43431_0519.N1						SS1	H/H	90	43431	291	5.03
ASA_GM1_1PNPDE20100621_052027_000000842090_00291_43431_0562.N1						SS1	H/H	90	43431	291	5.03
ASA_GM1_1PNPDE20100621_053422_000001202090_00291_43431_0561.N1						SS1	H/H	90	43431	291	5.03
ASA_GM1_1PNPDE20100621_060306_000006222090_00292_43432_0558.N1						SS1	H/H	90	43432	292	5.03
ASA_GM1_1PNPDE20100621_061507_000003322090_00292_43432_0557.N1						SS1	H/H	90	43432	292	5.03
ASA_GM1_1PNPDE20100621_062710_000001932090_00292_43432_0556.N1						SS1	H/H	90	43432	292	5.03
ASA_GM1_1PNPDE20100621_063201_000007192090_00292_43432_0552.N1						SS1	H/H	90	43432	292	5.03
ASA_GM1_1PNPDK20100621_070100_000001382090_00292_43432_5594.N1						SS1	H/H	90	43432	292	5.03
ASA_GM1_1PNPDK20100621_070722_000001022090_00292_43432_5593.N1						SS1	H/H	90	43432	292	5.03
ASA_GM1_1PNPDK20100621_071514_000001082090_00292_43432_5595.N1						SS1	H/H	90	43432	292	5.03
ASA_GM1_1PNPDK20100621_075546_000002652090_00293_43433_5598.N1						SS1	H/H	90	43433	293	5.03
ASA_GM1_1PNPDK20100621_081805_000008522090_00293_43433_5610.N1						SS1	H/H	90	43433	293	5.03
ASA_GM1_1PNPDK20100621_084256_000005862090_00293_43433_5612.N1						SS1	H/H	90	43433	293	5.03
ASA_GM1_1PNPDK20100621_093218_000005432090_00294_43434_5615.N1						SS1	H/H	90	43434	294	5.03
ASA_GM1_1PNPDK20100621_120736_000001812090_00295_43435_5651.N1						SS1	H/H	90	43435	295	5.03
ASA_GM1_1PNPDK20100621_122625_000002412090_00295_43435_5653.N1						SS1	H/H	90	43435	295	5.03
ASA_GM1_1PNPDK20100621_124809_000005612090_00296_43436_5656.N1						SS1	H/H	90	43436	296	5.03
ASA_GM1_1PNPDK20100621_130010_000001992090_00296_43436_5658.N1						SS1	H/H	90	43436	296	5.03
ASA_GM1_1PNPDK20100621_130244_000002772090_00296_43436_5669.N1						SS1	H/H	90	43436	296	5.03
ASA_GM1_1PNPDK20100621_132449_000001812090_00296_43436_5670.N1						SS1	H/H	90	43436	296	5.03
ASA_GM1_1PNPDK20100621_132922_000003802090_00296_43436_5671.N1						SS1	H/H	90	43436	296	5.03
ASA_GM1_1PNPDK20100621_133552_000003682090_00296_43436_5672.N1						SS1	H/H	90	43436	296	5.03
ASA_GM1_1PNPDK20100621_134326_000006282090_00296_43436_5674.N1						SS1	H/H	90	43436	296	5.03
ASA_GM1_1PNPDK20100621_140714_000002892090_00296_43436_5675.N1						SS1	H/H	90	43436	296	5.03
ASA_GM1_1PNPDK20100621_141318_000003802090_00296_43436_5677.N1						SS1	H/H	90	43436	296	5.03
ASA_GM1_1PNPDK20100621_142527_000006832090_00297_43437_5679.N1						SS1	H/H	90	43437	297	5.03
ASA_GM1_1PNPDK20100621_144901_000004102090_00297_43437_5689.N1						SS1	H/H	90	43437	297	5.03
ASA_GM1_1PNPDK20100621_150614_000001572090_00297_43437_5691.N1						SS1	H/H	90	43437	297	5.03
ASA_GM1_1PNPDK20100621_152402_000007792090_00297_43437_5693.N1						SS1	H/H	90	43437	297	5.03
ASA_GM1_1PNPDK20100621_160311_000002832090_00298_43438_5694.N1						SS1	H/H	90	43438	298	5.03
ASA_GM1_1PNPDK20100621_161025_000002772090_00298_43438_5701.N1						SS1	H/H	90	43438	298	5.03
ASA_GM1_1PNPDK20100621_162423_000001142090_00298_43438_5707.N1						SS1	H/H	90	43438	298	5.03
ASA_GM1_1PNPDK20100621_162921_000007372090_00298_43438_5708.N1						SS1	H/H	90	43438	298	5.03
ASA_GM1_1PNPDK20100621_170439_000002112090_00298_43438_5710.N1						SS1	H/H	90	43438	298	5.03
ASA_GM1_1PNPDK20100621_174439_000006712090_00299_43439_5712.N1						SS1	H/H	90	43439	299	5.03
ASA_GM1_1PNPDK20100621_175446_000001142090_00299_43439_5721.N1						SS1	H/H	90	43439	299	5.03
ASA_GM1_1PNPDK20100621_180428_000007012090_00299_43439_5722.N1						SS1	H/H	90	43439	299	5.03
ASA_GM1_1PNPDK20100621_184513_000001812090_00299_43439_5723.N1						SS1	H/H	90	43439	299	5.03
ASA_GM1_1PNPDK20100621_191147_000001142090_00299_43439_5729.N1						SS1	H/H	90	43439	299	5.03
ASA_GM1_1PNPDK20100621_191813_000010452090_00299_43439_5728.N1						SS1	H/H	90	43439	299	5.03
ASA_GM1_1PNPDE20100621_193429_000001812090_00300_43440_0744.N1						SS1	H/H	90	43440	300	5.03
ASA_GM1_1PNPDE20100621_194330_000005192090_00300_43440_0745.N1						SS1	H/H	90	43440	300	5.03
ASA_GM1_1PNPDE20100621_202548_000001502090_00300_43440_0748.N1						SS1	H/H	90	43440	300	5.03
ASA_GM1_1PNPDE20100621_205018_000011302090_00300_43440_0759.N1						SS1	H/H	90	43440	300	5.03
ASA_GM1_1PNPDE20100621_212322_000002112090_00301_43441_0760.N1						SS1	H/H	90	43441	301	5.03
ASA_GM1_1PNPDE20100621_212932_000001872090_00301_43441_0763.N1						SS1	H/H	90	43441	301	5.03
ASA_GM1_1PNPDE20100621_220627_000000902090_00301_43441_0762.N1						SS1	H/H	90	43441	301	5.03
ASA_GM1_1PNPDE20100621_221206_000000782090_00301_43441_0766.N1						SS1	H/H	90	43441	301	5.03
ASA_GM1_1PNPDE20100621_224034_000003982090_00302_43442_0782.N1						SS1	H/H	90	43442	302	5.03
ASA_GM1_1PNPDE20100621_230111_000007192090_00302_43442_0788.N1						SS1	H/H	90	43442	302	5.03
ASA_GM1_1PNPDE20100621_233541_000002172090_00302_43442_0787.N1						SS1	H/H	90	43442	302	5.03

ASA_GM1_1PNPDE20100621_233927_00000962090_00302_43442_0786.N1	SS1	H/H	90	43442	302	5.03
ASA_GM1_1PNPDE20100621_234945_000001022090_00302_43442_0791.N1	SS1	H/H	90	43442	302	5.03





Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_IMM_1PNPDE20100621_002044_000005122090_00288_43428_0456.N1						IS2	H/H	90	43428	288	5.03
ASA_IMM_1PNPDE20100621_020553_000002332090_00289_43429_0482.N1						IS2	H/H	90	43429	289	5.03
ASA_IMM_1PNPDE20100621_024439_000000372090_00290_43430_0503.N1						IS2	V/V	90	43430	290	5.03
ASA_IMM_1PNPDE20100621_025311_000000372090_00290_43430_0504.N1						IS2	V/V	90	43430	290	5.03
ASA_IMM_1PNPDE20100621_031051_000002152090_00290_43430_0484.N1						IS2	V/V	90	43430	290	5.03
ASA_IMM_1PNPDE20100621_031445_000000992090_00290_43430_0486.N1						IS2	V/V	90	43430	290	5.03
ASA_IMM_1PNPDE20100621_034055_000001462090_00290_43430_0509.N1						IS2	H/H	90	43430	290	5.03
ASA_IMM_1PNPDE20100621_045115_000002502090_00291_43431_0517.N1						IS2	V/V	90	43431	291	5.03
ASA_IMM_1PNPDE20100621_052155_000001362090_00291_43431_0533.N1						IS2	H/H	90	43431	291	5.03
ASA_IMM_1PNPDE20100621_052525_000003732090_00291_43431_0545.N1						IS2	H/H	90	43431	291	5.03
ASA_IMM_1PNPDE20100621_064706_000002822090_00292_43432_0550.N1						IS2	V/V	90	43432	292	5.03
ASA_IMM_1PNPDE20100621_070318_000002322090_00292_43432_0567.N1						IS2	H/H	90	43432	292	5.03
ASA_IMM_1PNPDK20100621_070908_000001622090_00292_43432_5602.N1						IS2	H/H	90	43432	292	5.03
ASA_IMM_1PNPDK20100621_074928_000001832090_00293_43433_5607.N1						IS2	V/V	90	43433	293	5.03
ASA_IMM_1PNPDE20100621_095221_000000372090_00294_43434_0634.N1						IS2	V/V	90	43434	294	5.03
ASA_IMM_1PNPDE20100621_095642_000000372090_00294_43434_0635.N1						IS2	V/V	90	43434	294	5.03
ASA_IMM_1PNPDE20100621_102338_000004432090_00294_43434_0657.N1						IS2	H/H	90	43434	294	5.03
ASA_IMM_1PNPDE20100621_114027_000000532090_00295_43435_0679.N1						IS2	V/V	90	43435	295	5.03
ASA_IMM_1PNPDE20100621_120334_000002322090_00295_43435_0686.N1						IS2	H/H	90	43435	295	5.03
ASA_IMM_1PNPDK20100621_121034_000000922090_00295_43435_5664.N1						IS2	H/H	90	43435	295	5.03
ASA_IMM_1PNPDE20100621_160224_000000372090_00298_43438_0731.N1						IS7	V/V	90	43438	298	5.03
ASA_IMM_1PNPDE20100621_160754_000001422090_00298_43438_0732.N1						IS2	V/V	90	43438	298	5.03
ASA_IMM_1PNPDE20100621_164135_000000832090_00298_43438_0736.N1						IS2	V/V	90	43438	298	5.03
ASA_IMM_1PNPDE20100621_170806_000003022090_00298_43438_0741.N1						IS2	H/H	90	43438	298	5.03
ASA_IMM_1PNPDE20100621_170806_000003022090_00298_43438_0737.N1						IS2	H/H	90	43438	298	5.03
ASA_IMM_1PNPDE20100621_171356_000002332090_00298_43438_0733.N1						IS2	H/H	90	43438	298	5.03
ASA_IMM_1PNPDE20100621_181605_000001442090_00299_43439_0740.N1						IS2	V/V	90	43439	299	5.03
ASA_IMM_1PNPDE20100621_184811_000003022090_00299_43439_0742.N1						IS2	H/H	90	43439	299	5.03
ASA_IMM_1PNPDE20100621_185411_000002112090_00299_43439_0738.N1						IS2	H/H	90	43439	299	5.03
ASA_IMM_1PNPDK20100621_193731_000000512090_00300_43440_5731.N1						IS2	H/H	90	43440	300	5.03
ASA_IMM_1PNPDE20100621_202817_000003022090_00300_43440_0757.N1						IS2	H/H	90	43440	300	5.03
ASA_IMM_1PNPDE20100621_203407_000002332090_00300_43440_0755.N1						IS2	H/H	90	43440	300	5.03
ASA_IMM_1PNPDE20100621_211137_000000372090_00301_43441_0775.N1						IS2	V/V	90	43441	301	5.03
ASA_IMM_1PNPDE20100621_220803_000002302090_00301_43441_0779.N1						IS2	H/H	90	43441	301	5.03
ASA_IMM_1PNPDE20100621_220803_000002302090_00301_43441_0780.N1						IS2	H/H	90	43441	301	5.03
ASA_IMM_1PNPDE20100621_221332_000002642090_00301_43441_0774.N1						IS2	H/H	90	43441	301	5.03
ASA_IMM_1PNPDE20100621_224710_000000532090_00302_43442_0777.N1						IS2	V/V	90	43442	302	5.03
ASA_IMM_1PNPDE20100621_234801_000000912090_00302_43442_0837.N1						IS2	H/H	90	43442	302	5.03
ASA_IMM_1PNPDE20100621_235131_000003732090_00302_43442_0797.N1						IS2	H/H	90	43442	302	5.03


Filename	Pol	Timestamp	count(Module)				
ASA_MS__0PNPDE20100621_015913_000000162090_00289_43429_0554.N1	H			2010-06-21	01:59:13	320	
ASA_MS__0PNPDK20100621_084136_000000162090_00293_43433_0144.N1	V			2010-06-21	08:41:36	320	


Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WSM_1PNPDE20100621_003027_000002692090_00288_43428_0457.N1						SS1	H/H	90	43428	288	5.03
ASA_WSM_1PNPDE20100621_010812_000004102090_00289_43429_0481.N1						SS1	H/H	90	43429	289	5.03
ASA_WSM_1PNPDE20100621_021017_000002882090_00289_43429_0483.N1						SS1	H/H	90	43429	289	5.03
ASA_WSM_1PNPDE20100621_023932_000002452090_00290_43430_0497.N1						SS1	V/V	90	43430	290	5.03
ASA_WSM_1PNPDE20100621_035040_000002262090_00290_43430_0515.N1						SS1	H/H	90	43430	290	5.03
ASA_WSM_1PNPDE20100621_053205_000001282090_00291_43431_0546.N1						SS1	H/H	90	43431	291	5.03
ASA_WSM_1PNPDE20100621_061333_000000862090_00292_43432_0551.N1						SS1	H/H	90	43432	292	5.03
ASA_WSM_1PNPDE20100621_063029_000000922090_00292_43432_0544.N1						SS1	H/H	90	43432	292	5.03
ASA_WSM_1PNPDK20100621_075322_000001412090_00293_43433_5608.N1						SS1	H/H	90	43433	293	5.03
ASA_WSM_1PNPDE20100621_080019_000004222090_00293_43433_0675.N1						SS1	H/H	90	43433	293	5.03
ASA_WSM_1PNPDE20100621_081106_000002392090_00293_43433_0714.N1						SS1	V/V	90	43433	293	5.03
ASA_WSM_1PNPDE20100621_081106_000002392090_00293_43433_0717.N1						SS1	V/V	90	43433	293	5.03
ASA_WSM_1PNPDE20100621_094130_000001842090_00294_43434_0625.N1						SS1	H/H	90	43434	294	5.03
ASA_WSM_1PNPDE20100621_094508_000001472090_00294_43434_0632.N1						SS1	V/V	90	43434	294	5.03
ASA_WSM_1PNPDE20100621_094829_000000922090_00294_43434_0633.N1						SS1	V/V	90	43434	294	5.03
ASA_WSM_1PNPDE20100621_103307_000002202090_00294_43434_0677.N1						SS1	H/H	90	43434	294	5.03
ASA_WSM_1PNPDK20100621_121316_000002692090_00295_43435_5667.N1						SS1	H/H	90	43435	295	5.03
ASA_WSM_1PNPDK20100621_125738_000001472090_00296_43436_5660.N1						SS1	H/H	90	43436	296	5.03
ASA_WSM_1PNPDK20100621_130729_000001282090_00296_43436_5668.N1						SS1	H/H	90	43436	296	5.03
ASA_WSM_1PNPDE20100621_135412_000002452090_00296_43436_0728.N1						SS1	H/H	90	43436	296	5.03
ASA_WSM_1PNPDE20100621_142354_000000862090_00297_43437_0729.N1						SS1	H/H	90	43437	297	5.03
ASA_WSM_1PNPDK20100621_143656_000002322090_00297_43437_5684.N1						SS1	H/H	90	43437	297	5.03
ASA_WSM_1PNPDK20100621_144124_000003062090_00297_43437_5683.N1						SS1	H/H	90	43437	297	5.03
ASA_WSM_1PNPDE20100621_144519_000002202090_00297_43437_0730.N1						SS1	H/H	90	43437	297	5.03
ASA_WSM_1PNPDE20100621_153706_000001282090_00297_43437_0726.N1						SS1	H/H	90	43437	297	5.03
ASA_WSM_1PNPDK20100621_161512_000003062090_00298_43438_5705.N1						SS1	H/H	90	43438	298	5.03
ASA_WSM_1PNPDK20100621_162129_000001652090_00298_43438_5706.N1						SS1	H/H	90	43438	298	5.03
ASA_WSM_1PNPDE20100621_162629_000001712090_00298_43438_0735.N1						SS1	H/H	90	43438	298	5.03
ASA_WSM_1PNPDE20100621_171804_000001162090_00298_43438_0734.N1						SS1	H/H	90	43438	298	5.03
ASA_WSM_1PNPDK20100621_175652_000002142090_00299_43439_5719.N1						SS1	H/H	90	43439	299	5.03
ASA_WSM_1PNPDK20100621_180132_000001712090_00299_43439_5720.N1						SS1	H/H	90	43439	299	5.03
ASA_WSM_1PNPDE20100621_185806_000001282090_00299_43439_0739.N1						SS1	H/H	90	43439	299	5.03
ASA_WSM_1PNPDE20100621_191353_000000922090_00299_43439_0743.N1						SS1	H/H	90	43439	299	5.03
ASA_WSM_1PNPDK20100621_193846_000002812090_00300_43440_5736.N1						SS1	H/H	90	43440	300	5.03
ASA_WSM_1PNPDE20100621_203905_000001222090_00300_43440_0756.N1						SS1	H/H	90	43440	300	5.03
ASA_WSM_1PNPDE20100621_204643_000002142090_00300_43440_0758.N1						SS1	V/V	90	43440	300	5.03
ASA_WSM_1PNPDE20100621_212700_000001472090_00301_43441_0778.N1						SS1	H/H	90	43441	301	5.03
ASA_WSM_1PNPDE20100621_221856_000002322090_00301_43441_0776.N1						SS1	H/H	90	43441	301	5.03
ASA_WSM_1PNPDE20100621_233052_000002022090_00302_43442_0800.N1						SS1	V/V	90	43442	302	5.03
ASA_WSM_1PNPDE20100621_235844_000002942090_00302_43442_0799.N1						SS1	H/H	90	43442	302	5.03




Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WVS_1PNPDE20100620_234710_000008842090_00288_43428_0440.N1						IS2	V/V	90	43428	288	5.03
ASA_WVS_1PNPDE20100621_001137_000003742090_00288_43428_0441.N1						IS2	V/V	90	43428	288	5.03
ASA_WVS_1PNPDE20100621_003457_000003902090_00288_43428_0446.N1						IS2	V/V	90	43428	288	5.03
ASA_WVS_1PNPDE20100621_004042_000003742090_00288_43428_0465.N1						IS2	V/V	90	43428	288	5.03
ASA_WVS_1PNPDE20100621_005101_000009592090_00288_43428_0469.N1						IS2	V/V	90	43428	288	5.03
ASA_WVS_1PNPDE20100621_014503_000001342090_00289_43429_0468.N1						IS2	V/V	90	43429	289	5.03
ASA_WVS_1PNPDE20100621_015046_000004652090_00289_43429_0473.N1						IS2	V/V	90	43429	289	5.03
ASA_WVS_1PNPDE20100621_021510_000003902090_00289_43429_0487.N1						IS2	V/V	90	43429	289	5.03
ASA_WVS_1PNPDE20100621_021510_000000592090_00289_43429_0471.N1						IS2	V/V	90	43429	289	5.03
ASA_WVS_1PNPDE20100621_021510_000000592090_00289_43429_0471.N1						IS1	V/V	90	43429	289	5.03
ASA_WVS_1PNPDE20100621_023528_000001942090_00290_43430_0493.N1						IS2	V/V	90	43430	290	5.03
ASA_WVS_1PNPDE20100621_023528_000001942090_00290_43430_0490.N1						IS2	V/V	90	43430	290	5.03
ASA_WVS_1PNPDE20100621_032220_000006592090_00290_43430_0491.N1						IS2	V/V	90	43430	290	5.03
ASA_WVS_1PNPDE20100621_032220_000006592090_00290_43430_0488.N1						IS2	V/V	90	43430	290	5.03
ASA_WVS_1PNPDE20100621_033250_000002252090_00290_43430_0522.N1						IS2	V/V	90	43430	290	5.03
ASA_WVS_1PNPDE20100621_032220_000006592090_00290_43430_0488.N1						IS1	V/V	90	43430	290	5.03
ASA_WVS_1PNPDE20100621_032220_000006592090_00290_43430_0491.N1						IS1	V/V	90	43430	290	5.03
ASA_WVS_1PNPDE20100621_040021_000008992090_00290_43430_0520.N1						IS2	V/V	90	43430	290	5.03
ASA_WVS_1PNPDE20100621_045948_000008542090_00291_43431_0518.N1						IS2	V/V	90	43431	291	5.03
ASA_WVS_1PNPDE20100621_051333_000001052090_00291_43431_0560.N1						IS2	V/V	90	43431	291	5.03
ASA_WVS_1PNPDE20100621_045948_000008542090_00291_43431_0518.N1						IS1	V/V	90	43431	291	5.03
ASA_WVS_1PNPDE20100621_051755_000001052090_00291_43431_0559.N1						IS2	V/V	90	43431	291	5.03
ASA_WVS_1PNPDE20100621_053631_000015442090_00291_43431_0555.N1						IS2	V/V	90	43431	291	5.03
ASA_WVS_1PNPDE20100621_064401_000001342090_00292_43432_0554.N1						IS2	V/V	90	43432	292	5.03
ASA_WVS_1PNPDE20100621_064741_000004342090_00292_43432_0553.N1						IS2	V/V	90	43432	292	5.03
ASA_WVS_1PNPDE20100621_065440_000003452090_00292_43432_5592.N1						IS2	V/V	90	43432	292	5.03
ASA_WVS_1PNPDK20100621_071707_000019042090_00292_43432_5597.N1						IS2	V/V	90	43432	292	5.03
ASA_WVS_1PNPDK20100621_083218_000005252090_00293_43433_5611.N1						IS2	V/V	90	43433	293	5.03
ASA_WVS_1PNPDK20100621_085743_000020242090_00293_43433_5614.N1						IS2	V/V	90	43433	293	5.03
ASA_WVS_1PNPDK20100621_100406_000010492090_00294_43434_5630.N1						IS2	V/V	90	43434	294	5.03
ASA_WVS_1PNPDK20100621_103819_000018442090_00294_43434_5635.N1						IS2	V/V	90	43434	294	5.03
ASA_WVS_1PNPDK20100621_112756_000007192090_00295_43435_5648.N1						IS2	V/V	90	43435	295	5.03
ASA_WVS_1PNPDK20100621_114126_000012442090_00295_43435_5649.N1						IS2	V/V	90	43435	295	5.03
ASA_WVS_1PNPDK20100621_121845_000004202090_00295_43435_5650.N1						IS2	V/V	90	43435	295	5.03
ASA_WVS_1PNPDK20100621_123027_000001042090_00295_43435_5652.N1						IS2	V/V	90	43435	295	5.03
ASA_WVS_1PNPDK20100621_123457_000007522090_00295_43435_5657.N1						IS2	V/V	90	43435	295	5.03
ASA_WVS_1PNPDK20100621_130937_000008692090_00296_43436_5673.N1						IS2	V/V	90	43436	296	5.03
ASA_WVS_1PNPDK20100621_135921_000004352090_00296_43436_5676.N1						IS2	V/V	90	43436	296	5.03
ASA_WVS_1PNPDK20100621_141937_000001342090_00297_43437_5678.N1						IS2	V/V	90	43437	297	5.03
ASA_WVS_1PNPDK20100621_145553_000005842090_00297_43437_5690.N1						IS2	V/V	90	43437	297	5.03
ASA_WVS_1PNPDK20100621_150854_000008692090_00297_43437_5692.N1						IS2	V/V	90	43437	297	5.03
ASA_WVS_1PNPDK20100621_153957_000013042090_00297_43437_5700.N1						IS2	V/V	90	43437	297	5.03
ASA_WVS_1PNPDK20100621_164303_000012442090_00298_43438_5709.N1						IS2	V/V	90	43438	298	5.03
ASA_WVS_1PNPDK20100621_172033_000014092090_00298_43438_5711.N1						IS2	V/V	90	43438	298	5.03
ASA_WVS_1PNPDK20100621_181834_000015592090_00299_43439_5725.N1						IS2	V/V	90	43439	299	5.03
ASA_WVS_1PNPDK20100621_190109_000000452090_00299_43439_5724.N1						IS2	V/V	90	43439	299	5.03
ASA_WVS_1PNPDK20100621_190405_000004202090_00299_43439_5726.N1						IS2	V/V	90	43439	299	5.03
ASA_WVS_1PNPDK20100621_191521_000001342090_00299_43439_5727.N1						IS2	V/V	90	43439	299	5.03
ASA_WVS_1PNPDE20100621_195214_000019792090_00300_43440_0746.N1						IS2	V/V	90	43440	300	5.03
ASA_WVS_1PNPDE20100621_204145_000001802090_00300_43440_0747.N1						IS2	V/V	90	43440	300	5.03
ASA_WVS_1PNPDE20100621_204400_000001202090_00300_43440_0761.N1						IS2	V/V	90	43440	300	5.03
ASA_WVS_1PNPDE20100621_213242_000019792090_00301_43441_0764.N1						IS2	V/V	90	43441	301	5.03
ASA_WVS_1PNPDE20100621_222248_000003452090_00301_43441_0765.N1						IS2	V/V	90	43441	301	5.03
ASA_WVS_1PNPDE20100621_222748_000007192090_00301_43441_0781.N1						IS2	V/V	90	43441	301	5.03
ASA_WVS_1PNPDE20100621_224809_000005252090_00302_43442_0783.N1						IS2	V/V	90	43442	302	5.03
ASA_WVS_1PNPDE20100621_231311_000010192090_00302_43442_0784.N1						IS2	V/V	90	43442	302	5.03
ASA_WVS_1PNPDE20100621_233410_000000442090_00302_43442_0785.N1						IS2	V/V	90	43442	302	5.03
ASA_WVS_1PNPDE20100621_234108_000003152090_00302_43442_0789.N1						IS2	V/V	90	43442	302	5.03














































21-Jun




21-Jun




21-Jun




21-Jun





21-Jun




21-Jun








21-Jun



21-Jun



21-Jun

