



Analysis from 03-NOV-2010 00:00:00 to 03-NOV-2010 23:59:59. Page generated on 04-NOV-2010 07:32:06.
View log file: ASAR_Daily_Report_20101104_0731.log. For any anomalies please contact emma.griffiths@vega.co.uk, kajal.haria@vega.co.uk.

This report is automatically generated every day, every 2 hours. No comments are provided on the results.

SUMMARY

1. DATA SUMMARY
 - 1.1 Summary tables
 - 1.2 Lists of products used
2. AUXILIARY FILES ANALYSIS
 - 2.1 IECF operational ADFs list
 - 2.2 Products with wrong ADFs
3. MODULE STEPPING PRODUCTS ANALYSIS
 - 3.1 V/V polarisation
 - 3.2 H/H polarisation
4. CALIBRATION PULSES ANALYSIS
 - 4.1 Analysis for WVS IS2 V/V
 - 4.1.1 Temporal Evolution Analysis for WVS IS2 V/V
 - 4.1.2 All Rows Analysis for WVS IS2 V/V
 - 4.2 Analysis for GM1 SS3 H/H
 - 4.2.1 Temporal Evolution Analysis for GM1 SS3 H/H
 - 4.2.2 All Rows Analysis for GM1 SS3 H/H
5. DOPPLER ANALYSIS
 - 5.1 Analysis for WVS IS2 V/V
 - 5.1.1 Doppler MAP Analysis for WVS IS2 V/V
 - 5.1.2 Doppler ANX Analysis for WVS IS2 V/V
 - 5.2 Analysis for GM1 SS1 H/H
 - 5.2.1 Doppler MAP Analysis for GM1 SS1 H/H
 - 5.2.2 Doppler ANX Analysis for GM1 SS1 H/H
 - 5.3 Doppler JUMPS Analysis for WSM
6. CHIRP ANALYSIS
 - 6.1 Analysis for WSM SS1 H/H
 - 6.1.1 ScaleFactor
 - 6.2 Analysis for WSM SS1 V/V
 - 6.2.1 ScaleFactor
7. RAW DATA ANALYSIS
 - 7.1 Analysis for WVS
 - 7.2 Analysis for IMM
8. TELEMETRY ANALYSIS
 - 8.1 Number of Missing Lines
 - 8.2 Number of Gaps

1 - DATA SUMMARY

1.1 - Summary tables

[BACK TO MENU]

WVS				GM1				APM				IMM				WSM				MS			
Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Time	Pol	Modules
PDE	IS1	V/V	1	PDE	WS	H/H	43					PDE	IS1	H/H	1	PDE	WS	H/H	21	PDE	2010-11-03 00:25:07	V	320
PDE	IS2	V/V	27	PDK	WS	H/H	46					PDE	IS2	V/V	1	PDE	WS	V/V	6	PDE	2010-11-03 05:25:50	H	320
PDK	IS2	V/V	26									PDE	IS4	H/H	2	PDK	WS	H/H	8	PDE	2010-11-03 20:27:57	V	320
												PDE	IS6	H/H	4	PDK	WS	V/V	2	PDK	2010-11-03 10:26:32	V	320
												PDK	IS3	V/V	1					PDK	2010-11-03 15:27:14	H	320
												PDK	IS6	H/H	1								

1.2 - Lists of products used

[BACK TO MENU]

[TXT] [XLS] List_WVS_products_used
 [TXT] [XLS] List_GM1_products_used
 [TXT] [XLS] List_IMM_products_used
 [TXT] [XLS] List_WSM_products_used
 [TXT] [XLS] List_MS_products_used

2 - AUXILIARY FILES ANALYSIS

2.1 - IECF operational ADFs list

[BACK TO MENU]

ADFs disseminated for ASAR
ASA_CON_AXVIEC20100608_125449_20100317_120410_20101231_000000
ASA_INS_AXVIEC20101028_095209_20101022_000000_20101231_235959
ASA_XCH_AXVIEC20091217_113006_20020301_000000_20101231_000000
ASA_XCA_AXVIEC20100608_123419_20100317_120410_20110101_000000

2.2 - Products with wrong ADFs

[BACK TO MENU]

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
WVS	0	0	0	0
GM1	0	0	0	0
IMM	0	0	0	0
WSM	0	0	0	0

[TXT] [XLS] Check_ADFs_WVS
 [TXT] [XLS] Check_ADFs_GM1
 [TXT] [XLS] Check_ADFs_IMM
 [TXT] [XLS] Check_ADFs_WSM

3 - MODULE STEPPING PRODUCTS ANALYSIS



SECOND FIXED REFERENCE	PREVIOUS PRODUCT REFERENCE
------------------------	----------------------------

Pre-launch reference (2001-02-09)

Previous product in the same polarisation

Reference: 2001-02-09 14:08:23 V RxGain
 Test : 2010-11-03 20:27:57 V





Reference: 2010-11-03 10:26:32 V RxGain
 Test : 2010-11-03 20:27:57 V



Reference: 2001-02-09 14:08:23 V RxPhase
 Test : 2010-11-03 20:27:57 V

Reference: 2010-11-03 10:26:32 V RxPhase
 Test : 2010-11-03 20:27:57 V






3.2 - H/H polarisation

[[BACK TO MENU](#)]

SECOND FIXED REFERENCE	PREVIOUS PRODUCT REFERENCE
Pre-launch reference (2001-02-09)	Previous product in the same polarisation

Reference: 2001-02-09 13:50:42 H RxGain
 Test : 2010-11-03 15:27:14 H




Reference: 2010-11-03 05:25:50 H RxGain
 Test : 2010-11-03 15:27:14 H







Reference: 2001-02-09 13:50:42 H RxPhase
 Test : 2010-11-03 15:27:14 H



Reference: 2010-11-03 05:25:50 H RxPhase
 Test : 2010-11-03 15:27:14 H





4 - CALIBRATION PULSES ANALYSIS

4.1 - Analysis for WVS IS2 V/V


4.1.1 - Temporal Evolution Analysis for WVS IS2 V/V

[BACK TO MENU]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Calibration pulses for WVS IS2 V/V




Transmit power (P1 - P1a) for WVS IS2 V/V



4.1.2 - All Rows Analysis for WVS IS2 V/V

[BACK TO MENU]





4.2 - Analysis for GM1 SS3 H/H


4.2.1 - Temporal Evolution Analysis for GM1 SS3 H/H

[BACK TO MENU]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Calibration pulses for GM1 SS3 H/H




Transmit power (P1 - P1a) for GM1 SS3 H/H



4.2.2 - All Rows Analysis for GM1 SS3 H/H

[BACK TO MENU]






5 - DOPPLER ANALYSIS

5.1 - Analysis for WVS IS2 V/V

5.1.1 - Doppler MAP Analysis for WVS IS2 V/V

[[BACK TO MENU](#)]






5.1.2 - Doppler ANX Analysis for WVS IS2 V/V

[[BACK TO MENU](#)]






5.2 - Analysis for GM1 SS1 H/H

5.2.1 - Doppler MAP Analysis for GM1 SS1 H/H

[BACK TO MENU]






5.2.2 - Doppler ANX Analysis for GM1 SS1 H/H


[[BACK TO MENU](#)]






5.3 - Doppler JUMPS Analysis for WSM

[[BACK TO MENU](#)]






6 - CHIRP ANALYSIS

6.1 - Analysis for WSM SS1 H/H

6.1.1 - ScaleFactor

[[BACK TO MENU](#)]






6.2 - Analysis for WSM SS1 V/V

6.2.1 - ScaleFactor


[BACK TO MENU]






7 - RAW DATA ANALYSIS

7.1 - Analysis for WVS

[BACK TO MENU]






Channel	Statistics	DSS-B
MEAN I	mean	0.000640302
	stdev	1.17963e-07
MEAN Q	mean	0.000555853
	stdev	2.07937e-07
Channel	Statistics	DSS-B
STDEV I	mean	0.147470
	stdev	0.00117241
STDEV Q	mean	0.147984
	stdev	0.00119436

7.2 - Analysis for IMM

[[BACK TO MENU](#)]






8 - TELEMETRY ANALYSIS

Processing Center	Product	Gaps	Missing lines
PDK	ASA_IMM_1PNPDK20101103_124823_00001363096_00096_45369_7029.N1	0	2

8.1 - Number of Missing lines


[[BACK TO MENU](#)]





8.2 - Number of Gaps

[[BACK TO MENU](#)]



ASAR DAILY REPORT for 101103
#####

MODE: DAILY
ANALYSIS: ALL
DATE: 2010-11-03 00:00:00

Analysis will be performed from 2010-11-03 00:00:00 to 2010-11-03 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_101103/

DATA SUMMARY

Summary will be performed from 2010-11-03 00:00:00 to 2010-11-03 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_101103/DATA_SUMMARY

Creating directory ./RESULTS/DAILY/_101103/DATA_SUMMARY...
Writing file ./RESULTS/DAILY/_101103/DATA_SUMMARY/Data_summary.html...

Getting WVS products list from 2010-11-03 00:00:00 to 2010-11-03 23:59:59...
Writing file ./RESULTS/DAILY/_101103/DATA_SUMMARY/List_WVS_products_used.xls...
Writing file ./RESULTS/DAILY/_101103/DATA_SUMMARY/List_WVS_products_used.txt...

Getting GM1 products list from 2010-11-03 00:00:00 to 2010-11-03 23:59:59...
Writing file ./RESULTS/DAILY/_101103/DATA_SUMMARY/List_GM1_products_used.xls...
Writing file ./RESULTS/DAILY/_101103/DATA_SUMMARY/List_GM1_products_used.txt...

Getting APM products list from 2010-11-03 00:00:00 to 2010-11-03 23:59:59...
Writing file ./RESULTS/DAILY/_101103/DATA_SUMMARY/List_APM_products_used.xls...
Writing file ./RESULTS/DAILY/_101103/DATA_SUMMARY/List_APM_products_used.txt...

Getting IMM products list from 2010-11-03 00:00:00 to 2010-11-03 23:59:59...
Writing file ./RESULTS/DAILY/_101103/DATA_SUMMARY/List_IMM_products_used.xls...
Writing file ./RESULTS/DAILY/_101103/DATA_SUMMARY/List_IMM_products_used.txt...

Getting WSM products list from 2010-11-03 00:00:00 to 2010-11-03 23:59:59...
Writing file ./RESULTS/DAILY/_101103/DATA_SUMMARY/List_WSM_products_used.xls...
Writing file ./RESULTS/DAILY/_101103/DATA_SUMMARY/List_WSM_products_used.txt...

Getting MS products list from 2010-11-03 00:00:00 to 2010-11-03 23:59:59...
Writing file ./RESULTS/DAILY/_101103/DATA_SUMMARY/List_MS_products_used.xls...
Writing file ./RESULTS/DAILY/_101103/DATA_SUMMARY/List_MS_products_used.txt...

DATA SUMMARY completed
#####

AUXILIARY FILES ANALYSIS

Analysis will be performed from 2010-11-03 00:00:00 to 2010-11-03 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_101103/AUXILIARY

Creating directory ./RESULTS/DAILY/_101103/AUXILIARY...

Looking for the IECF operational ADFs list...

ADF filter 20101103*current_3_IECF_ADFs.txt
Found list 20101103_030002_current_3_IECF_ADFs.txt...
Extracting ADFs...

ASA_CON_AXVIEC20100608_125449_20100317_120410_20101231_000000
ASA_INS_AXVIEC20101028_095209_20101022_000000_20101231_235959
ASA_XCH_AXVIEC20091217_113006_20020301_000000_20101231_000000
ASA_XCA_AXVIEC20100608_123419_20100317_120410_20110101_000000

Writing file ./RESULTS/DAILY/_101103/AUXILIARY/ASAR_ADFs_IECF_List3.html...
Writing file ./RESULTS/DAILY/_101103/AUXILIARY/Auxiliary_files_summary.html...

Analysing WVS products...

Writing file ./RESULTS/DAILY/_101103/AUXILIARY/Check_ADFs_WVS.xls...
Writing file ./RESULTS/DAILY/_101103/AUXILIARY/Check_ADFs_WVS.txt...

ASA_WVS_1PNPDE20101103_001803_000003003096_00088_45361_3323.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101103_004239_000002253096_00088_45361_3325.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101103_004539_000003143096_00088_45361_3363.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101103_005828_000008843096_00089_45362_3367.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101103_013845_000001643096_00089_45362_3372.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101103_015111_000001343096_00089_45362_3370.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101103_015620_000004053096_00089_45362_3375.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101103_022253_000000453096_00089_45362_3374.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101103_022253_000002403096_00089_45362_3411.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101103_032615_000007043096_00090_45363_3422.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101103_033745_000003453096_00090_45363_3429.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101103_040519_000010043096_00090_45363_3434.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101103_050441_000009143096_00091_45364_3435.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101103_051940_000002403096_00091_45364_3449.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101103_054322_000014243096_00091_45364_3457.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101103_064930_000001343096_00092_45365_3456.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101103_065409_000003443096_00092_45365_3461.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101103_195428_000018743096_00100_45373_3541.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101103_195428_000018743096_00100_45373_3545.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101103_204529_000003153096_00100_45373_3552.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101103_213436_000018893096_00101_45374_3554.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101103_222543_000003443096_00101_45374_3555.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101103_223028_000006593096_00101_45374_3568.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101103_225604_00000603096_00102_45375_3570.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101103_231444_000013043096_00102_45375_3573.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101103_234234_000002253096_00102_45375_3576.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101103_065939_000002553096_00092_45365_7088.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101103_072336_000018593096_00092_45365_7093.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101103_083631_000004503096_00093_45366_7092.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101103_090350_000019343096_00093_45366_7091.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101103_100914_000008993096_00094_45367_7090.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101103_104404_000017393096_00094_45367_7089.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101103_113150_000003153096_00095_45368_7094.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101103_114119_000007793096_00095_45368_7095.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101103_115728_000004203096_00095_45368_7028.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101103_122418_000003003096_00095_45368_7027.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101103_123430_000001043096_00095_45368_7026.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101103_123854_000005363096_00095_45368_7096.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101103_131328_000008543096_00096_45369_7041.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101103_140432_000003303096_00096_45369_7044.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101103_141520_000000443096_00096_45369_7048.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101103_142243_000001493096_00097_45370_7049.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101103_150826_000000443096_00097_45370_7112.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101103_151156_000007793096_00097_45370_7116.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101103_154447_000012293096_00097_45370_7120.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101103_164545_000011693096_00098_45371_7154.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101103_172501_000013043096_00098_45371_7157.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101103_172501_000013043096_00098_45371_7158.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

```
ASA_WVS_1PNPDK20101103_172501_000013043096_00098_45371_7159.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101103_182039_000014993096_00099_45372_7233.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101103_190515_000004803096_00099_45372_7231.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101103_191658_000001643096_00099_45372_7237.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```

Analysing GM1 products...

Writing file ./RESULTS/DAILY/_101103/AUXILIARY/Check_ADFs_GM1.xls...

Writing file ./RESULTS/DAILY/_101103/AUXILIARY/Check_ADFs_GM1.txt...

```
ASA_GM1_1PNPDE20101103_000914_000004653096_00088_45361_3320.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101103_002341_000000783096_00088_45361_3322.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101103_002622_000005013096_00088_45361_3324.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101103_003922_000001933096_00088_45361_3326.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101103_005345_000002593096_00088_45361_3368.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101103_012035_000010883096_00089_45362_3369.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101103_014228_000005193096_00089_45362_3373.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101103_015419_000001143096_00089_45362_3371.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101103_020356_000000963096_00089_45362_3383.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101103_021001_000002293096_00089_45362_3382.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101103_021853_000002353096_00089_45362_3376.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101103_022731_000000783096_00089_45362_3416.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101103_022901_000004223096_00089_45362_3415.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101103_023650_000008283096_00089_45362_3414.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101103_025125_000001383096_00090_45363_3413.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101103_030022_000009123096_00090_45363_3412.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101103_032124_000002893096_00090_45363_3423.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101103_034406_000005193096_00090_45363_3430.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101103_040124_000002293096_00090_45363_3432.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101103_042242_000008223096_00091_45364_3431.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101103_043922_000010573096_00091_45364_3433.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101103_050056_000002233096_00091_45364_3436.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101103_052423_000000783096_00091_45364_3447.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101103_052706_000002773096_00091_45364_3448.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101103_054022_000001753096_00091_45364_3450.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101103_061224_000008583096_00092_45365_3462.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101103_063201_000002473096_00092_45365_3460.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101103_063752_000006953096_00092_45365_3459.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101103_065225_000000963096_00092_45365_3458.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101103_193723_000000723096_00100_45373_3536.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101103_194357_000006283096_00100_45373_3538.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101103_202631_000000783096_00100_45373_3539.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101103_203505_000006223096_00100_45373_3540.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101103_203505_000006223096_00100_45373_3544.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101103_205355_000009913096_00100_45373_3551.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101103_211903_000009303096_00101_45374_3553.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101103_220644_000011363096_00101_45374_3558.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101103_224216_000003323096_00102_45375_3567.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101103_225922_000001813096_00102_45375_3569.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101103_230359_000006283096_00102_45375_3571.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101103_233707_000002173096_00102_45375_3572.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101103_234052_000000963096_00102_45375_3574.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101103_234700_000006043096_00102_45375_3575.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101103_070437_000003263096_00092_45365_7058.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101103_071823_000003143096_00092_45365_7057.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101103_075525_000005983096_00093_45366_7061.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101103_081140_000001933096_00093_45366_7064.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101103_082543_000006283096_00093_45366_7063.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101103_084451_000001993096_00093_45366_7062.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101103_085623_000004473096_00093_45366_7060.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101103_093646_000006833096_00094_45367_7059.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101103_093646_000006833096_00094_45367_7076.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101103_100103_000001573096_00094_45367_7077.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101103_102506_000000783096_00094_45367_7078.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101103_102750_000009733096_00094_45367_7079.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```


ASA_GM1_1PNPDK20101103_111352_000007613096_00095_45368_7080.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101103_112809_000002173096_00095_45368_7081.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101103_120520_000000843096_00095_45368_7019.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101103_121506_000005493096_00095_45368_7025.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101103_123043_000002233096_00095_45368_7024.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101103_123656_000001143096_00095_45368_7023.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101103_125148_000009493096_00096_45369_7082.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101103_130625_000004223096_00096_45369_7037.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101103_132827_000006283096_00096_45369_7039.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101103_133926_000006893096_00096_45369_7040.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101103_135518_000001503096_00096_45369_7042.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101103_140109_000001993096_00096_45369_7045.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101103_141045_000002713096_00096_45369_7046.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101103_141653_000002953096_00096_45369_7047.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101103_142607_000011303096_00097_45370_7050.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101103_142607_000011303096_00097_45370_7051.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101103_144343_000014803096_00097_45370_7111.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101103_150958_000001143096_00097_45370_7113.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101103_152548_000000783096_00097_45370_7114.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101103_152832_000009733096_00097_45370_7118.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101103_160606_000009433096_00098_45371_7119.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101103_162102_000001633096_00098_45371_7150.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101103_162523_000012203096_00098_45371_7151.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101103_170558_000002533096_00098_45371_7153.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101103_171651_000001143096_00098_45371_7152.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101103_172255_000001203096_00098_45371_7155.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101103_174724_000007193096_00099_45372_7156.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101103_175810_000013473096_00099_45372_7229.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101103_184618_000002473096_00099_45372_7230.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101103_185458_000001933096_00099_45372_7232.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101103_190253_000001383096_00099_45372_7234.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101103_191352_000001813096_00099_45372_7235.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101103_192026_000005013096_00099_45372_7236.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101103_193320_000001443096_00100_45373_7238.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

Analysing APM products...

No APM products available for the selected period...

Analysing IMM products...

Writing file ./RESULTS/DAILY/_101103/AUXILIARY/Check_ADFs_IMM.xls...

Writing file ./RESULTS/DAILY/_101103/AUXILIARY/Check_ADFs_IMM.txt...

ASA_IMM_1PNPDE20101103_023601_000000393096_00089_45362_3409.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20101103_025038_000000383096_00090_45363_3410.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20101103_031531_000003453096_00090_45363_3408.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20101103_045659_000002263096_00091_45364_3427.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20101103_060750_000001423096_00092_45365_3446.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20101103_063609_000000933096_00092_45365_3444.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20101103_082130_000002433096_00093_45366_3483.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20101103_142144_000000513096_00097_45370_3529.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20101103_124823_000001363096_00096_45369_7029.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20101103_211518_000000373096_00101_45374_7275.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

Analysing WSM products...

Writing file ./RESULTS/DAILY/_101103/AUXILIARY/Check_ADFs_WSM.xls...

Writing file ./RESULTS/DAILY/_101103/AUXILIARY/Check_ADFs_WSM.txt...

```
ASA_WSM_1PNPDE20101103_003447_000002693096_00088_45361_3314.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101103_005136_000000923096_00088_45361_3327.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101103_011447_000003433096_00089_45362_3386.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101103_020540_000002513096_00089_45362_3362.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101103_021355_000002943096_00089_45362_3366.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101103_025347_000003923096_00090_45363_3424.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101103_035247_000005143096_00090_45363_3426.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101103_043627_000001713096_00091_45364_3428.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101103_053148_000005143096_00091_45364_3445.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101103_071005_000001533096_00092_45365_3465.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101103_080526_000003733096_00093_45366_3482.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101103_094813_000003363096_00094_45367_3496.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101103_100347_000003123096_00094_45367_3497.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101103_113748_000002143096_00095_45368_3510.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101103_115458_000001533096_00095_45368_3511.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101103_120649_000002693096_00095_45368_3515.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101103_135056_000002513096_00096_45369_3527.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101103_135755_000001903096_00096_45369_3528.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101103_171018_000003733096_00098_45371_3533.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101103_171850_000002393096_00098_45371_3532.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101103_185027_000002513096_00099_45372_3535.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101103_185812_000002813096_00099_45372_3534.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101103_202956_000003063096_00100_45373_3537.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101103_205153_000001163096_00100_45373_3550.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101103_224748_000002083096_00102_45375_3564.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101103_225234_000002083096_00102_45375_3565.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101103_235706_000003123096_00102_45375_3566.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20101103_062646_000003063096_00092_45365_7083.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20101103_071258_000003123096_00092_45365_7085.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20101103_084812_000004893096_00093_45366_7084.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20101103_095409_000000923096_00094_45367_7086.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20101103_112633_000000923096_00095_45368_7087.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20101103_121159_000001843096_00095_45368_7022.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20101103_162348_000000923096_00098_45371_7123.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20101103_193548_000000923096_00100_45373_7240.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20101103_193842_000003123096_00100_45373_7246.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20101103_211628_000001533096_00101_45374_7285.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```

AUXILIARY FILES ANALYSIS completed

#####

MODULE STEPPING ANALYSIS

#####

Analysis will be performed from 2010-11-03 00:00:00 to 2010-11-03 23:59:59

Results will be exported to the directory: ./RESULTS/DAILY/_101103/MODULE_STEPPING

Creating directory ./RESULTS/DAILY/_101103/MODULE_STEPPING...

Creating directory ./RESULTS/DAILY/_101103/MODULE_STEPPING/FIRST_REFERENCE...

Creating directory ./RESULTS/DAILY/_101103/MODULE_STEPPING/SECOND_REFERENCE...

Creating directory ./RESULTS/DAILY/_101103/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE...

Deleting old files...

Creating images comparing with second reference...

Exporting results to the directory ../../RESULTS/DAILY/_101103/MODULE_STEPPING/SECOND_REFERENCE...

Polarization: H

Reference product: ASA_MS__0PNPDK20010209_135042_00000009A024_00180_11700_0052.N1

Test product: ASA_MS__0PNPDK20101103_152714_000000163096_00097_45370_0260.N1

H

H

../../RESULTS/DAILY/_101103/MODULE_STEPPING/SECOND_REFERENCE/TGH_20101103_152714-20010209_135042.png

../../RESULTS/DAILY/_101103/MODULE_STEPPING/SECOND_REFERENCE/TPH_20101103_152714-20010209_135042.png
../../RESULTS/DAILY/_101103/MODULE_STEPPING/SECOND_REFERENCE/RGH_20101103_152714-20010209_135042.png
../../RESULTS/DAILY/_101103/MODULE_STEPPING/SECOND_REFERENCE/RPH_20101103_152714-20010209_135042.png

Polarization: V

Reference product: ASA_MS_0PNPK20010209_140823_0000009A024_00180_11700_0054.N1

Test product: ASA_MS_0PNPDE20101103_202757_000000163096_00100_45373_0043.N1

V
V

../../RESULTS/DAILY/_101103/MODULE_STEPPING/SECOND_REFERENCE/TGV_20101103_202757-20010209_140823.png
../../RESULTS/DAILY/_101103/MODULE_STEPPING/SECOND_REFERENCE/TPV_20101103_202757-20010209_140823.png
../../RESULTS/DAILY/_101103/MODULE_STEPPING/SECOND_REFERENCE/RGV_20101103_202757-20010209_140823.png
../../RESULTS/DAILY/_101103/MODULE_STEPPING/SECOND_REFERENCE/RPV_20101103_202757-20010209_140823.png

Creating images comparing with previous product reference...

Exporting results to the directory ../../RESULTS/DAILY/_101103/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE...

Polarization: H

Reference product: ASA_MS_0PNPDE20101103_052550_000000163096_00091_45364_0042.N1

Test product: ASA_MS_0PNPK20101103_152714_000000163096_00097_45370_0260.N1

H
H

../../RESULTS/DAILY/_101103/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TGH_20101103_152714-20101103_052550.png
../../RESULTS/DAILY/_101103/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TPH_20101103_152714-20101103_052550.png
../../RESULTS/DAILY/_101103/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RGH_20101103_152714-20101103_052550.png
../../RESULTS/DAILY/_101103/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RPH_20101103_152714-20101103_052550.png

Polarization: V

Reference product: ASA_MS_0PNPK20101103_102632_000000163096_00094_45367_0259.N1

Test product: ASA_MS_0PNPDE20101103_202757_000000163096_00100_45373_0043.N1

V
V

../../RESULTS/DAILY/_101103/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TGV_20101103_202757-20101103_102632.png
../../RESULTS/DAILY/_101103/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TPV_20101103_202757-20101103_102632.png
../../RESULTS/DAILY/_101103/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RGV_20101103_202757-20101103_102632.png
../../RESULTS/DAILY/_101103/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RPV_20101103_202757-20101103_102632.png

MODULE_STEPPING ANALYSIS completed

#####

CALIBRATION PULSES ANALYSIS

#####

Creating directory ./RESULTS/DAILY/_101103/CALIBRATION_PULSES...

ALL ROWS Analysis will be performed from 2010-11-03 00:00:00 to 2010-11-03 23:59:59

Analysing products WVS IS2 V/V

Writing image ../../RESULTS/DAILY/_101103//CALIBRATION_PULSES/Calibration_pulses_all_rows_WVS_IS2_VV.png...

Analysing products GM1 SS3 H/H

Writing image ../../RESULTS/DAILY/_101103//CALIBRATION_PULSES/Calibration_pulses_all_rows_GM1_SS3_HH.png...

TEMPORAL EVOLUTION Analysis will be performed from 2010-11-03 00:00:00 to 2010-11-03 23:59:59

Analysing products WVS IS2 V/V

Getting calibration pulses data for WVS IS2 V/V from 2010-11-03 00:00:00 to 2010-11-03 23:59:59. Rows: 1/5/9/13/17/21/25/29

Writing file ./RESULTS/DAILY/_101103/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2010-11-03_1.dat...



Writing ../../RESULTS/DAILY/_101103//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_1.png...
Writing ../../RESULTS/DAILY/_101103//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_1.png...

Getting calibration pulses data for WVS IS2 V/V from 2010-11-03 00:00:00 to 2010-11-03 23:59:59. Rows: 2/6/10/14/18/22/26/30
Writing file ./RESULTS/DAILY/_101103/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2010-11-03_2.dat...
Writing ../../RESULTS/DAILY/_101103//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_2.png...
Writing ../../RESULTS/DAILY/_101103//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_2.png...

Getting calibration pulses data for WVS IS2 V/V from 2010-11-03 00:00:00 to 2010-11-03 23:59:59. Rows: 3/7/11/15/19/23/27/31
Writing file ./RESULTS/DAILY/_101103/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2010-11-03_3.dat...
Writing ../../RESULTS/DAILY/_101103//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_3.png...
Writing ../../RESULTS/DAILY/_101103//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_3.png...

Getting calibration pulses data for WVS IS2 V/V from 2010-11-03 00:00:00 to 2010-11-03 23:59:59. Rows: 4/8/12/16/20/24/28/32
Writing file ./RESULTS/DAILY/_101103/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2010-11-03_4.dat...
Writing ../../RESULTS/DAILY/_101103//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_4.png...
Writing ../../RESULTS/DAILY/_101103//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_4.png...

Analysing products GM1 SS3 H/H
Getting calibration pulses data for GM1 SS3 H/H from 2010-11-03 00:00:00 to 2010-11-03 23:59:59. Rows: 1/5/9/13/17/21/25/29
Writing file ./RESULTS/DAILY/_101103/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2010-11-03_1.dat...
Writing ../../RESULTS/DAILY/_101103//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_1.png...
Writing ../../RESULTS/DAILY/_101103//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_1.png...

Getting calibration pulses data for GM1 SS3 H/H from 2010-11-03 00:00:00 to 2010-11-03 23:59:59. Rows: 2/6/10/14/18/22/26/30
Writing file ./RESULTS/DAILY/_101103/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2010-11-03_2.dat...
Writing ../../RESULTS/DAILY/_101103//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_2.png...
Writing ../../RESULTS/DAILY/_101103//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_2.png...

Getting calibration pulses data for GM1 SS3 H/H from 2010-11-03 00:00:00 to 2010-11-03 23:59:59. Rows: 3/7/11/15/19/23/27/31
Writing file ./RESULTS/DAILY/_101103/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2010-11-03_3.dat...
Writing ../../RESULTS/DAILY/_101103//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_3.png...
Writing ../../RESULTS/DAILY/_101103//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_3.png...

Getting calibration pulses data for GM1 SS3 H/H from 2010-11-03 00:00:00 to 2010-11-03 23:59:59. Rows: 4/8/12/16/20/24/28/32
Writing file ./RESULTS/DAILY/_101103/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2010-11-03_4.dat...
Writing ../../RESULTS/DAILY/_101103//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_4.png...
Writing ../../RESULTS/DAILY/_101103//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_4.png...

CALIBRATION PULSES ANALYSIS completed
#####

DOPPLER ANALYSIS

Creating directory ./RESULTS/DAILY/_101103/DOPPLER...

DOPPLER ANX Analysis will be performed from 2010-11-03 00:00:00 to 2010-11-03 23:59:59

Analysing products WVS IS2 V/V
Getting doppler data for WVS IS2 V/V from 2010-11-03 00:00:00 to 2010-11-03 23:59:59...
Writing file ./RESULTS/DAILY/_101103/DOPPLER/Doppler_data_WVS_IS2_VV_2010-11-03.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/_101103/DOPPLER/DOPPLER_ANX_WVS_IS2_VV.png...

Analysing products GM1 SS1 H/H
Getting doppler data for GM1 SS1 H/H from 2010-11-03 00:00:00 to 2010-11-03 23:59:59...
Writing file ./RESULTS/DAILY/_101103/DOPPLER/Doppler_data_GM1_SS1_HH_2010-11-03.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/_101103/DOPPLER/DOPPLER_ANX_GM1_SS1_HH.png...

DOPPLER JUMPS Analysis will be performed on WSM products from 2010-11-03 00:00:00 to 2010-11-03 23:59:59

Analysing by default products WSM
Getting doppler jumps data for WSM from 2010-11-03 00:00:00 to 2010-11-03 23:59:59...
Writing file ./RESULTS/DAILY/_101103/DOPPLER/Doppler_Jumps_data_WSM_2010-11-03.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/_101103/DOPPLER/DOPPLER_JUMPS_ANX_WSM.png...
Writing file ../../RESULTS/DAILY/_101103/DOPPLER/DOPPLER_JUMPS_Date_WSM.png...

DOPPLER MAP Analysis will be performed from 2010-11-03 00:00:00 to 2010-11-03 23:59:59

Analysing products WVS IS2 V/V
Loading predicted doppler values....
Phase: descending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -74.354690 Hz
Writing file ../../RESULTS/DAILY/_101103//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_WVS_IS2_VV_desc.jpg...
Writing file ../../RESULTS/DAILY/_101103//DOPPLER/DOPPLER_Absolute_WVS_IS2_VV_desc.jpg...

Loading predicted doppler values....
Phase: ascending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -69.096741 Hz
Writing file ../../RESULTS/DAILY/_101103//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_WVS_IS2_VV_asc.jpg...
Writing file ../../RESULTS/DAILY/_101103//DOPPLER/DOPPLER_Absolute_WVS_IS2_VV_asc.jpg...

Analysing products GM1 SS1 H/H
Loading predicted doppler values....
Phase: descending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -55.366966 Hz
Writing file ../../RESULTS/DAILY/_101103//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_GM1_SS1_HH_desc.jpg...
Writing file ../../RESULTS/DAILY/_101103//DOPPLER/DOPPLER_Absolute_GM1_SS1_HH_desc.jpg...

Loading predicted doppler values....
Phase: ascending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -63.673322 Hz
Writing file ../../RESULTS/DAILY/_101103//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_GM1_SS1_HH_asc.jpg...
Writing file ../../RESULTS/DAILY/_101103//DOPPLER/DOPPLER_Absolute_GM1_SS1_HH_asc.jpg...

DOPPLER ANALYSIS completed
#####

CHIRP ANALYSIS

Creating directory ./RESULTS/DAILY/_101103/CHIRP...

CHIRP Analysis will be performed from 2010-11-03 00:00:00 to 2010-11-03 23:59:59

Analysing products WSM SS1 H/H

Getting ScaleFactor data for WSM SS1 H/H from 2010-11-03 00:00:00 to 2010-11-03 23:59:59...
Writing file ./RESULTS/DAILY/_101103/CHIRP/ScaleFactor_data_WSM_SS1_HH_2010-11-03.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/_101103/CHIRP/ScaleFactor_ANX_WSM_SS1_HH.png...
Writing file ../../RESULTS/DAILY/_101103/CHIRP/ScaleFactor_DATE_WSM_SS1_HH.png...

Analysing products WSM SS1 V/V

Getting ScaleFactor data for WSM SS1 V/V from 2010-11-03 00:00:00 to 2010-11-03 23:59:59...
Writing file ./RESULTS/DAILY/_101103/CHIRP/ScaleFactor_data_WSM_SS1_VV_2010-11-03.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/_101103/CHIRP/ScaleFactor_ANX_WSM_SS1_VV.png...
Writing file ../../RESULTS/DAILY/_101103/CHIRP/ScaleFactor_DATE_WSM_SS1_VV.png...

CHIRP ANALYSIS completed
#####

RAW DATA ANALYSIS

Analysis will be performed from 2010-11-03 00:00:00 to 2010-11-03 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_101103/RAW_DATA

Creating directory ./RESULTS/DAILY/_101103/RAW_DATA...

Getting raw data for WVS from 2010-11-03 00:00:00 to 2010-11-03 23:59:59...
Writing file ./RESULTS/DAILY/_101103/RAW_DATA/Raw_data_WVS_2010-11-03.dat...
Running IDL program to create graphs...

Creating image ../../RESULTS/DAILY/_101103/RAW_DATA/Raw_data_WVS_input_mean.png...
Creating image ../../RESULTS/DAILY/_101103/RAW_DATA/Raw_data_WVS_input_stdev.png...
Creating image ../../RESULTS/DAILY/_101103/RAW_DATA/Raw_data_WVS_gain_imbalance.png...

Getting raw data for IMM from 2010-11-03 00:00:00 to 2010-11-03 23:59:59...
Writing file ./RESULTS/DAILY/_101103/RAW_DATA/Raw_data_IMM_2010-11-03.dat...
Running IDL program to create graphs...

Creating image ../../RESULTS/DAILY/_101103/RAW_DATA/Raw_data_IMM_input_mean.png...
Creating image ../../RESULTS/DAILY/_101103/RAW_DATA/Raw_data_IMM_input_stdev.png...
Creating image ../../RESULTS/DAILY/_101103/RAW_DATA/Raw_data_IMM_gain_imbalance.png...

RAW DATA ANALYSIS completed
#####

TELEMETRY ANALYSIS

Analysis will be performed from 2010-11-03 00:00:00 to 2010-11-03 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_101103/TELEMETRY

Creating directory ./RESULTS/DAILY/_101103/TELEMETRY...

Looking for gaps and missing lines in WVS products...

Checking 27 products from PDE...
Checking 26 products from PDK...

Looking for gaps and missing lines in GM1 products...

Checking 43 products from PDE...
Checking 46 products from PDK...

Looking for gaps and missing lines in APM products...

No products from PDE...
No products from PDK...

Looking for gaps and missing lines in IMM products...

Checking 8 products from PDE...
Checking 2 products from PDK...
Found product...ASA_IMM_1PNPDK20101103_124823_000001363096_00096_45369_7029.N1 / 0 gaps / 2 missing lines

Looking for gaps and missing lines in WSM products...

Checking 27 products from PDE...
Checking 10 products from PDK...

Creating graph of missing lines and gaps...

Creating image: ./RESULTS/DAILY/_101103/TELEMETRY/TELEMETRY_Missing_lines.png...
Creating image: ./RESULTS/DAILY/_101103/TELEMETRY/TELEMETRY_Gaps.png...

TELEMETRY ANALYSIS completed

#####

HTML REPORT generation

#####

Building file ./RESULTS/DAILY/_101103/asarReport.html...

- Building DATA SUMMARY section...
- Building AUXILIARY FILES ANALYSIS section...
- Building MODULE STEPPING ANALYSIS section...
- Building CALIBRATION PULSES ANALYSIS section...
- Building DOPPLER ANALYSIS section...
- Building CHIRP ANALYSIS section...
- Building RAW DATA ANALYSIS section...
- Building TELEMETRY ANALYSIS section...

HTML REPORT generation completed

#####



Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_GM1_1PNPDE20101103_000914_000004653096_00088_45361_3320.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101103_002341_000000783096_00088_45361_3322.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101103_002622_000005013096_00088_45361_3324.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101103_003922_000001933096_00088_45361_3326.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101103_005345_000002593096_00088_45361_3368.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101103_012035_000010883096_00089_45362_3369.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101103_014228_000005193096_00089_45362_3373.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101103_015419_000001143096_00089_45362_3371.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101103_020356_000000963096_00089_45362_3383.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101103_021001_000002293096_00089_45362_3382.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101103_021853_000002353096_00089_45362_3376.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101103_022731_000000783096_00089_45362_3416.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101103_022901_000004223096_00089_45362_3415.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101103_023650_000008283096_00089_45362_3414.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101103_025125_000001383096_00090_45363_3413.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101103_030022_000009123096_00090_45363_3412.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101103_032124_000002893096_00090_45363_3423.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101103_034406_000005193096_00090_45363_3430.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101103_040124_000002293096_00090_45363_3432.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101103_042242_000008223096_00091_45364_3431.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101103_043922_000010573096_00091_45364_3433.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101103_050056_000002233096_00091_45364_3436.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101103_052423_000000783096_00091_45364_3447.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101103_052706_000002773096_00091_45364_3448.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101103_054022_000001753096_00091_45364_3450.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101103_061224_000008583096_00092_45365_3462.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101103_063201_000002473096_00092_45365_3460.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101103_063752_000006953096_00092_45365_3459.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101103_065225_000000963096_00092_45365_3458.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101103_193723_000000723096_00100_45373_3536.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101103_194357_000006283096_00100_45373_3538.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101103_202631_000000783096_00100_45373_3539.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101103_203505_000006223096_00100_45373_3540.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101103_203505_000006223096_00100_45373_3544.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101103_205355_000009913096_00100_45373_3551.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101103_211903_000009303096_00101_45374_3553.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101103_220644_000011363096_00101_45374_3558.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101103_224216_000003323096_00102_45375_3567.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101103_225922_000001813096_00102_45375_3569.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101103_230359_000006283096_00102_45375_3571.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101103_233707_000002173096_00102_45375_3572.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101103_234052_000000963096_00102_45375_3574.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101103_234700_000006043096_00102_45375_3575.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101103_070437_000003263096_00092_45365_7058.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101103_071823_000003143096_00092_45365_7057.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101103_075525_000005983096_00093_45366_7061.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101103_081140_000001933096_00093_45366_7064.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101103_082543_000006283096_00093_45366_7063.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101103_084451_000001993096_00093_45366_7062.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101103_085623_000004473096_00093_45366_7060.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101103_093646_000006833096_00094_45367_7059.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101103_093646_000006833096_00094_45367_7076.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101103_100103_000001573096_00094_45367_7077.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101103_102506_000000783096_00094_45367_7078.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101103_102750_000009733096_00094_45367_7079.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101103_111352_000007613096_00095_45368_7080.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101103_112809_000002173096_00095_45368_7081.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101103_120520_000000843096_00095_45368_7019.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101103_121506_000005493096_00095_45368_7025.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101103_123043_000002233096_00095_45368_7024.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101103_123656_000001143096_00095_45368_7023.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101103_125148_000009493096_00096_45369_7082.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101103_130625_000004223096_00096_45369_7037.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101103_132827_000006283096_00096_45369_7039.N1					OK	OK	OK	OK

ASA_GM1_1PNPDK20101103_133926_000006893096_00096_45369_7040.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101103_135518_000001503096_00096_45369_7042.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101103_140109_000001993096_00096_45369_7045.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101103_141045_000002713096_00096_45369_7046.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101103_141653_000002953096_00096_45369_7047.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101103_142607_000011303096_00097_45370_7050.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101103_142607_000011303096_00097_45370_7051.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101103_144343_000014803096_00097_45370_7111.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101103_150958_000001143096_00097_45370_7113.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101103_152548_000000783096_00097_45370_7114.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101103_152832_000009733096_00097_45370_7118.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101103_160606_000009433096_00098_45371_7119.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101103_162102_000001633096_00098_45371_7150.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101103_162523_000012203096_00098_45371_7151.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101103_170558_000002533096_00098_45371_7153.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101103_171651_000001143096_00098_45371_7152.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101103_172255_000001203096_00098_45371_7155.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101103_174724_000007193096_00099_45372_7156.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101103_175810_000013473096_00099_45372_7229.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101103_184618_000002473096_00099_45372_7230.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101103_185458_000001933096_00099_45372_7232.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101103_190253_000001383096_00099_45372_7234.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101103_191352_000001813096_00099_45372_7235.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101103_192026_000005013096_00099_45372_7236.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101103_193320_000001443096_00100_45373_7238.N1	OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
ASA_IMM_1PNPDE20101103_023601_000000393096_00089_45362_3409.N1				
ASA_IMM_1PNPDE20101103_025038_000000383096_00090_45363_3410.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20101103_031531_0000003453096_00090_45363_3408.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20101103_045659_000002263096_00091_45364_3427.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20101103_060750_000001423096_00092_45365_3446.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20101103_063609_000000933096_00092_45365_3444.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20101103_082130_000002433096_00093_45366_3483.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20101103_142144_000000513096_00097_45370_3529.N1	OK	OK	OK	OK
ASA_IMM_1PNPDK20101103_124823_000001363096_00096_45369_7029.N1	OK	OK	OK	OK
ASA_IMM_1PNPDK20101103_211518_000000373096_00101_45374_7275.N1	OK	OK	OK	OK


Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WSM_1PNPDE20101103_003447_000002693096_00088_45361_3314.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101103_005136_000000923096_00088_45361_3327.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101103_011447_000003433096_00089_45362_3386.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101103_020540_000002513096_00089_45362_3362.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101103_021355_000002943096_00089_45362_3366.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101103_025347_000003923096_00090_45363_3424.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101103_035247_000005143096_00090_45363_3426.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101103_043627_000001713096_00091_45364_3428.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101103_053148_000005143096_00091_45364_3445.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101103_071005_000001533096_00092_45365_3465.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101103_080526_000003733096_00093_45366_3482.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101103_094813_000003363096_00094_45367_3496.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101103_100347_000003123096_00094_45367_3497.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101103_113748_000002143096_00095_45368_3510.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101103_115458_000001533096_00095_45368_3511.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101103_120649_000002693096_00095_45368_3515.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101103_135056_000002513096_00096_45369_3527.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101103_135755_000001903096_00096_45369_3528.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101103_171018_000003733096_00098_45371_3533.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101103_171850_000002393096_00098_45371_3532.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101103_185027_000002513096_00099_45372_3535.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101103_185812_000002813096_00099_45372_3534.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101103_202956_000003063096_00100_45373_3537.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101103_205153_000001163096_00100_45373_3550.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101103_224748_000002083096_00102_45375_3564.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101103_225234_000002083096_00102_45375_3565.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101103_235706_000003123096_00102_45375_3566.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20101103_062646_000003063096_00092_45365_7083.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20101103_071258_000003123096_00092_45365_7085.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20101103_084812_000004893096_00093_45366_7084.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20101103_095409_000000923096_00094_45367_7086.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20101103_112633_000000923096_00095_45368_7087.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20101103_121159_000001843096_00095_45368_7022.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20101103_162348_000000923096_00098_45371_7123.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20101103_193548_000000923096_00100_45373_7240.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20101103_193842_000003123096_00100_45373_7246.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20101103_211628_000001533096_00101_45374_7285.N1					OK	OK	OK	OK





Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WVS_1PNPDE20101103_001803_000003003096_00088_45361_3323.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101103_004239_000002253096_00088_45361_3325.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101103_004539_000003143096_00088_45361_3363.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101103_005828_000008843096_00089_45362_3367.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101103_013845_000001643096_00089_45362_3372.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101103_015111_000001343096_00089_45362_3370.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101103_015620_000004053096_00089_45362_3375.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101103_022253_000000453096_00089_45362_3374.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101103_022253_000002403096_00089_45362_3411.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101103_032615_000007043096_00090_45363_3422.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101103_033745_000003453096_00090_45363_3429.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101103_040519_000010043096_00090_45363_3434.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101103_050441_000009143096_00091_45364_3435.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101103_051940_000002403096_00091_45364_3449.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101103_054322_000014243096_00091_45364_3457.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101103_064930_000001343096_00092_45365_3456.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101103_065409_000003443096_00092_45365_3461.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101103_195428_000018743096_00100_45373_3541.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101103_195428_000018743096_00100_45373_3545.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101103_204529_000003153096_00100_45373_3552.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101103_213436_000018893096_00101_45374_3554.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101103_222543_000003443096_00101_45374_3555.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101103_223028_000006593096_00101_45374_3568.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101103_225604_000000603096_00102_45375_3570.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101103_231444_000013043096_00102_45375_3573.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101103_234234_000002253096_00102_45375_3576.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101103_065939_000002553096_00092_45365_7088.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101103_072336_000018593096_00092_45365_7093.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101103_083631_000004503096_00093_45366_7092.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101103_090350_000019343096_00093_45366_7091.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101103_100914_000008993096_00094_45367_7090.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101103_104404_000017393096_00094_45367_7089.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101103_113150_000003153096_00095_45368_7094.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101103_114119_000007793096_00095_45368_7095.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101103_115728_000004203096_00095_45368_7028.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101103_122418_000003003096_00095_45368_7027.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101103_123430_000001043096_00095_45368_7026.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101103_123854_000005363096_00095_45368_7096.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101103_131328_000008543096_00096_45369_7041.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101103_140432_000003303096_00096_45369_7044.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101103_141520_000000443096_00096_45369_7048.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101103_142243_000001493096_00097_45370_7049.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101103_150826_000000443096_00097_45370_7112.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101103_151156_000007793096_00097_45370_7116.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101103_154447_000012293096_00097_45370_7120.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101103_164545_000011693096_00098_45371_7154.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101103_172501_000013043096_00098_45371_7157.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101103_172501_000013043096_00098_45371_7158.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101103_172501_000013043096_00098_45371_7159.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101103_182039_000014993096_00099_45372_7233.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101103_190515_000004803096_00099_45372_7231.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101103_191658_000001643096_00099_45372_7237.N1					OK	OK	OK	OK


Calibration pulses for GM1 SS3 H/H







Calibration pulses for GM1 SS3 H/H



Calibration pulses for GM1 SS3 H/H




Calibration pulses for GM1 SS3 H/H




rows: 4 8 12 16 20 24 28 32


Calibration pulses for WVS IS2 V/V




Calibration pulses for WVS IS2 V/V





Calibration pulses for WVS IS2 V/V







Calibration pulses for WVS IS2 V/V































03-Nov
rows: _ 1 _ 5 _ 9 _ 13 _ 17 _ 21 _ 25 _ 29

















Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_GM1_1PNPDE20101103_000914_000004653096_00088_45361_3320.N1						SS1	H/H	96	45361	88	5.04
ASA_GM1_1PNPDE20101103_002341_000000783096_00088_45361_3322.N1						SS1	H/H	96	45361	88	5.04
ASA_GM1_1PNPDE20101103_002622_000005013096_00088_45361_3324.N1						SS1	H/H	96	45361	88	5.04
ASA_GM1_1PNPDE20101103_003922_000001933096_00088_45361_3326.N1						SS1	H/H	96	45361	88	5.04
ASA_GM1_1PNPDE20101103_005345_000002593096_00088_45361_3368.N1						SS1	H/H	96	45361	88	5.04
ASA_GM1_1PNPDE20101103_012035_000010883096_00089_45362_3369.N1						SS1	H/H	96	45362	89	5.04
ASA_GM1_1PNPDE20101103_014228_000005193096_00089_45362_3373.N1						SS1	H/H	96	45362	89	5.04
ASA_GM1_1PNPDE20101103_015419_000001143096_00089_45362_3371.N1						SS1	H/H	96	45362	89	5.04
ASA_GM1_1PNPDE20101103_020356_000000963096_00089_45362_3383.N1						SS1	H/H	96	45362	89	5.04
ASA_GM1_1PNPDE20101103_021001_000002293096_00089_45362_3382.N1						SS1	H/H	96	45362	89	5.04
ASA_GM1_1PNPDE20101103_021853_000002353096_00089_45362_3376.N1						SS1	H/H	96	45362	89	5.04
ASA_GM1_1PNPDE20101103_022731_000000783096_00089_45362_3416.N1						SS1	H/H	96	45362	89	5.04
ASA_GM1_1PNPDE20101103_022901_000004223096_00089_45362_3415.N1						SS1	H/H	96	45362	89	5.04
ASA_GM1_1PNPDE20101103_023650_000008283096_00089_45362_3414.N1						SS1	H/H	96	45362	89	5.04
ASA_GM1_1PNPDE20101103_025125_000001383096_00090_45363_3413.N1						SS1	H/H	96	45363	90	5.04
ASA_GM1_1PNPDE20101103_030022_000009123096_00090_45363_3412.N1						SS1	H/H	96	45363	90	5.04
ASA_GM1_1PNPDE20101103_032124_000002893096_00090_45363_3423.N1						SS1	H/H	96	45363	90	5.04
ASA_GM1_1PNPDE20101103_034406_000005193096_00090_45363_3430.N1						SS1	H/H	96	45363	90	5.04
ASA_GM1_1PNPDE20101103_040124_000002293096_00090_45363_3432.N1						SS1	H/H	96	45363	90	5.04
ASA_GM1_1PNPDE20101103_042242_000008223096_00091_45364_3431.N1						SS1	H/H	96	45364	91	5.04
ASA_GM1_1PNPDE20101103_043922_000010573096_00091_45364_3433.N1						SS1	H/H	96	45364	91	5.04
ASA_GM1_1PNPDE20101103_050056_000002233096_00091_45364_3436.N1						SS1	H/H	96	45364	91	5.04
ASA_GM1_1PNPDE20101103_052423_000000783096_00091_45364_3447.N1						SS1	H/H	96	45364	91	5.04
ASA_GM1_1PNPDE20101103_052706_000002773096_00091_45364_3448.N1						SS1	H/H	96	45364	91	5.04
ASA_GM1_1PNPDE20101103_054022_000001753096_00091_45364_3450.N1						SS1	H/H	96	45364	91	5.04
ASA_GM1_1PNPDE20101103_061224_000008583096_00092_45365_3462.N1						SS1	H/H	96	45365	92	5.04
ASA_GM1_1PNPDE20101103_063201_000002473096_00092_45365_3460.N1						SS1	H/H	96	45365	92	5.04
ASA_GM1_1PNPDE20101103_063752_000006953096_00092_45365_3459.N1						SS1	H/H	96	45365	92	5.04
ASA_GM1_1PNPDE20101103_065225_000000963096_00092_45365_3458.N1						SS1	H/H	96	45365	92	5.04
ASA_GM1_1PNPDK20101103_070437_000003263096_00092_45365_7058.N1						SS1	H/H	96	45365	92	5.04
ASA_GM1_1PNPDK20101103_071823_000003143096_00092_45365_7057.N1						SS1	H/H	96	45365	92	5.04
ASA_GM1_1PNPDK20101103_075525_000005983096_00093_45366_7061.N1						SS1	H/H	96	45366	93	5.04
ASA_GM1_1PNPDK20101103_081140_000001933096_00093_45366_7064.N1						SS1	H/H	96	45366	93	5.04
ASA_GM1_1PNPDK20101103_082543_000006283096_00093_45366_7063.N1						SS1	H/H	96	45366	93	5.04
ASA_GM1_1PNPDK20101103_084451_000001993096_00093_45366_7062.N1						SS1	H/H	96	45366	93	5.04
ASA_GM1_1PNPDK20101103_085623_000004473096_00093_45366_7060.N1						SS1	H/H	96	45366	93	5.04
ASA_GM1_1PNPDK20101103_093646_000006833096_00094_45367_7059.N1						SS1	H/H	96	45367	94	5.04
ASA_GM1_1PNPDK20101103_093646_000006833096_00094_45367_7076.N1						SS1	H/H	96	45367	94	5.04
ASA_GM1_1PNPDK20101103_100103_000001573096_00094_45367_7077.N1						SS1	H/H	96	45367	94	5.04
ASA_GM1_1PNPDK20101103_102506_000000783096_00094_45367_7078.N1						SS1	H/H	96	45367	94	5.04
ASA_GM1_1PNPDK20101103_102750_000009733096_00094_45367_7079.N1						SS1	H/H	96	45367	94	5.04
ASA_GM1_1PNPDK20101103_111352_000007613096_00095_45368_7080.N1						SS1	H/H	96	45368	95	5.04
ASA_GM1_1PNPDK20101103_112809_000002173096_00095_45368_7081.N1						SS1	H/H	96	45368	95	5.04
ASA_GM1_1PNPDK20101103_120520_000000843096_00095_45368_7019.N1						SS1	H/H	96	45368	95	5.04
ASA_GM1_1PNPDK20101103_121506_000005493096_00095_45368_7025.N1						SS1	H/H	96	45368	95	5.04
ASA_GM1_1PNPDK20101103_123043_000002233096_00095_45368_7024.N1						SS1	H/H	96	45368	95	5.04
ASA_GM1_1PNPDK20101103_123656_000001143096_00095_45368_7023.N1						SS1	H/H	96	45368	95	5.04
ASA_GM1_1PNPDK20101103_125148_000009493096_00096_45369_7082.N1						SS1	H/H	96	45369	96	5.04
ASA_GM1_1PNPDK20101103_130625_000004223096_00096_45369_7037.N1						SS1	H/H	96	45369	96	5.04
ASA_GM1_1PNPDK20101103_132827_000006283096_00096_45369_7039.N1						SS1	H/H	96	45369	96	5.04
ASA_GM1_1PNPDK20101103_133926_000006893096_00096_45369_7040.N1						SS1	H/H	96	45369	96	5.04
ASA_GM1_1PNPDK20101103_135518_000001503096_00096_45369_7042.N1						SS1	H/H	96	45369	96	5.04
ASA_GM1_1PNPDK20101103_140109_000001993096_00096_45369_7045.N1						SS1	H/H	96	45369	96	5.04
ASA_GM1_1PNPDK20101103_141045_000002713096_00096_45369_7046.N1						SS1	H/H	96	45369	96	5.04
ASA_GM1_1PNPDK20101103_141653_000002953096_00096_45369_7047.N1						SS1	H/H	96	45369	96	5.04
ASA_GM1_1PNPDK20101103_142607_000011303096_00097_45370_7051.N1						SS1	H/H	96	45370	97	5.04
ASA_GM1_1PNPDK20101103_142607_000011303096_00097_45370_7050.N1						SS1	H/H	96	45370	97	5.04
ASA_GM1_1PNPDK20101103_144343_000014803096_00097_45370_7111.N1						SS1	H/H	96	45370	97	5.04
ASA_GM1_1PNPDK20101103_150958_000001143096_00097_45370_7113.N1						SS1	H/H	96	45370	97	5.04
ASA_GM1_1PNPDK20101103_152548_000000783096_00097_45370_7114.N1						SS1	H/H	96	45370	97	5.04
ASA_GM1_1PNPDK20101103_152832_000009733096_00097_45370_7118.N1						SS1	H/H	96	45370	97	5.04
ASA_GM1_1PNPDK20101103_160606_000009433096_00098_45371_7119.N1						SS1	H/H	96	45371	98	5.04
ASA_GM1_1PNPDK20101103_162102_000001633096_00098_45371_7150.N1						SS1	H/H	96	45371	98	5.04
ASA_GM1_1PNPDK20101103_162523_000012203096_00098_45371_7151.N1						SS1	H/H	96	45371	98	5.04
ASA_GM1_1PNPDK20101103_170558_000002533096_00098_45371_7153.N1						SS1	H/H	96	45371	98	5.04
ASA_GM1_1PNPDK20101103_171651_000001143096_00098_45371_7152.N1						SS1	H/H	96	45371	98	5.04
ASA_GM1_1PNPDK20101103_172255_000001203096_00098_45371_7155.N1						SS1	H/H	96	45371	98	5.04


ASA_GM1_1PNPDK20101103_174724_000007193096_00099_45372_7156.N1	SS1	H/H	96	45372	99	5.04
ASA_GM1_1PNPDK20101103_175810_000013473096_00099_45372_7229.N1	SS1	H/H	96	45372	99	5.04
ASA_GM1_1PNPDK20101103_184618_000002473096_00099_45372_7230.N1	SS1	H/H	96	45372	99	5.04
ASA_GM1_1PNPDK20101103_185458_000001933096_00099_45372_7232.N1	SS1	H/H	96	45372	99	5.04
ASA_GM1_1PNPDK20101103_190253_000001383096_00099_45372_7234.N1	SS1	H/H	96	45372	99	5.04
ASA_GM1_1PNPDK20101103_191352_000001813096_00099_45372_7235.N1	SS1	H/H	96	45372	99	5.04
ASA_GM1_1PNPDK20101103_192026_000005013096_00099_45372_7236.N1	SS1	H/H	96	45372	99	5.04
ASA_GM1_1PNPDK20101103_193320_000001443096_00100_45373_7238.N1	SS1	H/H	96	45373	100	5.04
ASA_GM1_1PNPDE20101103_193723_000000723096_00100_45373_3536.N1	SS1	H/H	96	45373	100	5.04
ASA_GM1_1PNPDE20101103_194357_000006283096_00100_45373_3538.N1	SS1	H/H	96	45373	100	5.04
ASA_GM1_1PNPDE20101103_202631_000000783096_00100_45373_3539.N1	SS1	H/H	96	45373	100	5.04
ASA_GM1_1PNPDE20101103_203505_000006223096_00100_45373_3544.N1	SS1	H/H	96	45373	100	5.04
ASA_GM1_1PNPDE20101103_203505_000006223096_00100_45373_3540.N1	SS1	H/H	96	45373	100	5.04
ASA_GM1_1PNPDE20101103_205355_000009913096_00100_45373_3551.N1	SS1	H/H	96	45373	100	5.04
ASA_GM1_1PNPDE20101103_211903_000009303096_00101_45374_3553.N1	SS1	H/H	96	45374	101	5.04
ASA_GM1_1PNPDE20101103_220644_000011363096_00101_45374_3558.N1	SS1	H/H	96	45374	101	5.04
ASA_GM1_1PNPDE20101103_224216_000003323096_00102_45375_3567.N1	SS1	H/H	96	45375	102	5.04
ASA_GM1_1PNPDE20101103_225922_000001813096_00102_45375_3569.N1	SS1	H/H	96	45375	102	5.04
ASA_GM1_1PNPDE20101103_230359_000006283096_00102_45375_3571.N1	SS1	H/H	96	45375	102	5.04
ASA_GM1_1PNPDE20101103_233707_000002173096_00102_45375_3572.N1	SS1	H/H	96	45375	102	5.04
ASA_GM1_1PNPDE20101103_234052_000000963096_00102_45375_3574.N1	SS1	H/H	96	45375	102	5.04
ASA_GM1_1PNPDE20101103_234700_000006043096_00102_45375_3575.N1	SS1	H/H	96	45375	102	5.04


Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_IMM_1PNPDE20101103_023601_000000393096_00089_45362_3409.N1						IS1	H/H	96	45362	89	5.04
ASA_IMM_1PNPDE20101103_025038_000000383096_00090_45363_3410.N1						IS4	H/H	96	45363	90	5.04
ASA_IMM_1PNPDE20101103_031531_0000003453096_00090_45363_3408.N1						IS6	H/H	96	45363	90	5.04
ASA_IMM_1PNPDE20101103_045659_0000002263096_00091_45364_3427.N1						IS6	H/H	96	45364	91	5.04
ASA_IMM_1PNPDE20101103_060750_0000001423096_00092_45365_3446.N1						IS6	H/H	96	45365	92	5.04
ASA_IMM_1PNPDE20101103_063609_000000933096_00092_45365_3444.N1						IS6	H/H	96	45365	92	5.04
ASA_IMM_1PNPDE20101103_082130_0000002433096_00093_45366_3483.N1						IS2	V/V	96	45366	93	5.04
ASA_IMM_1PNPDK20101103_124823_0000001363096_00096_45369_7029.N1						IS6	H/H	96	45369	96	5.04
ASA_IMM_1PNPDE20101103_142144_000000513096_00097_45370_3529.N1						IS4	H/H	96	45370	97	5.04
ASA_IMM_1PNPDK20101103_211518_000000373096_00101_45374_7275.N1						IS3	V/V	96	45374	101	5.04


Filename	Pol	Timestamp	count(Module)				
ASA_MS__0PNPDE20101103_002507_000000163096_00088_45361_0041.N1	V			2010-11-03	00:25:07	320	
ASA_MS__0PNPDE20101103_052550_000000163096_00091_45364_0042.N1	H			2010-11-03	05:25:50	320	
ASA_MS__0PNPDK20101103_102632_000000163096_00094_45367_0259.N1	V			2010-11-03	10:26:32	320	
ASA_MS__0PNPDK20101103_152714_000000163096_00097_45370_0260.N1	H			2010-11-03	15:27:14	320	
ASA_MS__0PNPDE20101103_202757_000000163096_00100_45373_0043.N1	V			2010-11-03	20:27:57	320	


Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WSM_1PNPDE20101103_003447_000002693096_00088_45361_3314.N1						SS1	H/H	96	45361	88	5.04
ASA_WSM_1PNPDE20101103_005136_000000923096_00088_45361_3327.N1						SS1	V/V	96	45361	88	5.04
ASA_WSM_1PNPDE20101103_011447_000003433096_00089_45362_3386.N1						SS1	H/H	96	45362	89	5.04
ASA_WSM_1PNPDE20101103_020540_000002513096_00089_45362_3362.N1						SS1	H/H	96	45362	89	5.04
ASA_WSM_1PNPDE20101103_021355_000002943096_00089_45362_3366.N1						SS1	H/H	96	45362	89	5.04
ASA_WSM_1PNPDE20101103_025347_000003923096_00090_45363_3424.N1						SS1	H/H	96	45363	90	5.04
ASA_WSM_1PNPDE20101103_035247_000005143096_00090_45363_3426.N1						SS1	H/H	96	45363	90	5.04
ASA_WSM_1PNPDE20101103_043627_000001713096_00091_45364_3428.N1						SS1	H/H	96	45364	91	5.04
ASA_WSM_1PNPDE20101103_053148_000005143096_00091_45364_3445.N1						SS1	H/H	96	45364	91	5.04
ASA_WSM_1PNPDK20101103_062646_000003063096_00092_45365_7083.N1						SS1	H/H	96	45365	92	5.04
ASA_WSM_1PNPDE20101103_071005_000001533096_00092_45365_3465.N1						SS1	H/H	96	45365	92	5.04
ASA_WSM_1PNPDK20101103_071258_000003123096_00092_45365_7085.N1						SS1	H/H	96	45365	92	5.04
ASA_WSM_1PNPDE20101103_080526_000003733096_00093_45366_3482.N1						SS1	H/H	96	45366	93	5.04
ASA_WSM_1PNPDK20101103_084812_000004893096_00093_45366_7084.N1						SS1	H/H	96	45366	93	5.04
ASA_WSM_1PNPDE20101103_094813_000003363096_00094_45367_3496.N1						SS1	H/H	96	45367	94	5.04
ASA_WSM_1PNPDK20101103_095409_000000923096_00094_45367_7086.N1						SS1	V/V	96	45367	94	5.04
ASA_WSM_1PNPDE20101103_100347_000003123096_00094_45367_3497.N1						SS1	H/H	96	45367	94	5.04
ASA_WSM_1PNPDK20101103_112633_000000923096_00095_45368_7087.N1						SS1	H/H	96	45368	95	5.04
ASA_WSM_1PNPDE20101103_113748_000002143096_00095_45368_3510.N1						SS1	V/V	96	45368	95	5.04
ASA_WSM_1PNPDE20101103_115458_000001533096_00095_45368_3511.N1						SS1	V/V	96	45368	95	5.04
ASA_WSM_1PNPDE20101103_120649_000002693096_00095_45368_3515.N1						SS1	H/H	96	45368	95	5.04
ASA_WSM_1PNPDK20101103_121159_000001843096_00095_45368_7022.N1						SS1	H/H	96	45368	95	5.04
ASA_WSM_1PNPDE20101103_135056_000002513096_00096_45369_3527.N1						SS1	H/H	96	45369	96	5.04
ASA_WSM_1PNPDE20101103_135755_000001903096_00096_45369_3528.N1						SS1	H/H	96	45369	96	5.04
ASA_WSM_1PNPDK20101103_162348_000000923096_00098_45371_7123.N1						SS1	H/H	96	45371	98	5.04
ASA_WSM_1PNPDE20101103_171018_000003733096_00098_45371_3533.N1						SS1	H/H	96	45371	98	5.04
ASA_WSM_1PNPDE20101103_171850_000002393096_00098_45371_3532.N1						SS1	H/H	96	45371	98	5.04
ASA_WSM_1PNPDE20101103_185027_000002513096_00099_45372_3535.N1						SS1	H/H	96	45372	99	5.04
ASA_WSM_1PNPDE20101103_185812_000002813096_00099_45372_3534.N1						SS1	H/H	96	45372	99	5.04
ASA_WSM_1PNPDK20101103_193548_000000923096_00100_45373_7240.N1						SS1	V/V	96	45373	100	5.04
ASA_WSM_1PNPDK20101103_193842_000003123096_00100_45373_7246.N1						SS1	H/H	96	45373	100	5.04
ASA_WSM_1PNPDE20101103_202956_000003063096_00100_45373_3537.N1						SS1	H/H	96	45373	100	5.04
ASA_WSM_1PNPDE20101103_205153_000001163096_00100_45373_3550.N1						SS1	V/V	96	45373	100	5.04
ASA_WSM_1PNPDK20101103_211628_000001533096_00101_45374_7285.N1						SS1	H/H	96	45374	101	5.04
ASA_WSM_1PNPDE20101103_224748_000002083096_00102_45375_3564.N1						SS1	V/V	96	45375	102	5.04
ASA_WSM_1PNPDE20101103_225234_000002083096_00102_45375_3565.N1						SS1	V/V	96	45375	102	5.04
ASA_WSM_1PNPDE20101103_235706_000003123096_00102_45375_3566.N1						SS1	H/H	96	45375	102	5.04




Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WVS_1PNPDE20101102_235353_000008693096_00088_45361_3321.N1						IS2	V/V	96	45361	88	5.04
ASA_WVS_1PNPDE20101103_001803_000003003096_00088_45361_3323.N1						IS2	V/V	96	45361	88	5.04
ASA_WVS_1PNPDE20101103_004239_000002253096_00088_45361_3325.N1						IS2	V/V	96	45361	88	5.04
ASA_WVS_1PNPDE20101103_004539_000003143096_00088_45361_3363.N1						IS2	V/V	96	45361	88	5.04
ASA_WVS_1PNPDE20101103_005828_000008843096_00089_45362_3367.N1						IS2	V/V	96	45362	89	5.04
ASA_WVS_1PNPDE20101103_013845_000001643096_00089_45362_3372.N1						IS2	V/V	96	45362	89	5.04
ASA_WVS_1PNPDE20101103_015111_000001343096_00089_45362_3370.N1						IS2	V/V	96	45362	89	5.04
ASA_WVS_1PNPDE20101103_015620_000004053096_00089_45362_3375.N1						IS2	V/V	96	45362	89	5.04
ASA_WVS_1PNPDE20101103_022253_00000453096_00089_45362_3374.N1						IS2	V/V	96	45362	89	5.04
ASA_WVS_1PNPDE20101103_022253_000002403096_00089_45362_3411.N1						IS2	V/V	96	45362	89	5.04
ASA_WVS_1PNPDE20101103_032615_000007043096_00090_45363_3422.N1						IS2	V/V	96	45363	90	5.04
ASA_WVS_1PNPDE20101103_033745_000003453096_00090_45363_3429.N1						IS2	V/V	96	45363	90	5.04
ASA_WVS_1PNPDE20101103_040519_000010043096_00090_45363_3434.N1						IS2	V/V	96	45363	90	5.04
ASA_WVS_1PNPDE20101103_050441_000009143096_00091_45364_3435.N1						IS2	V/V	96	45364	91	5.04
ASA_WVS_1PNPDE20101103_051940_000002403096_00091_45364_3449.N1						IS2	V/V	96	45364	91	5.04
ASA_WVS_1PNPDE20101103_054322_000014243096_00091_45364_3457.N1						IS2	V/V	96	45364	91	5.04
ASA_WVS_1PNPDE20101103_064930_000001343096_00092_45365_3456.N1						IS2	V/V	96	45365	92	5.04
ASA_WVS_1PNPDE20101103_065409_000003443096_00092_45365_3461.N1						IS2	V/V	96	45365	92	5.04
ASA_WVS_1PNPDK20101103_065939_000002553096_00092_45365_7088.N1						IS2	V/V	96	45365	92	5.04
ASA_WVS_1PNPDK20101103_072336_000018593096_00092_45365_7093.N1						IS2	V/V	96	45365	92	5.04
ASA_WVS_1PNPDK20101103_083631_000004503096_00093_45366_7092.N1						IS2	V/V	96	45366	93	5.04
ASA_WVS_1PNPDK20101103_090350_000019343096_00093_45366_7091.N1						IS2	V/V	96	45366	93	5.04
ASA_WVS_1PNPDK20101103_100914_000008993096_00094_45367_7090.N1						IS2	V/V	96	45367	94	5.04
ASA_WVS_1PNPDK20101103_104404_000017393096_00094_45367_7089.N1						IS2	V/V	96	45367	94	5.04
ASA_WVS_1PNPDK20101103_113150_000003153096_00095_45368_7094.N1						IS2	V/V	96	45368	95	5.04
ASA_WVS_1PNPDK20101103_114119_000007793096_00095_45368_7095.N1						IS2	V/V	96	45368	95	5.04
ASA_WVS_1PNPDK20101103_115728_000004203096_00095_45368_7028.N1						IS2	V/V	96	45368	95	5.04
ASA_WVS_1PNPDK20101103_122418_000003003096_00095_45368_7027.N1						IS2	V/V	96	45368	95	5.04
ASA_WVS_1PNPDK20101103_123430_000001043096_00095_45368_7026.N1						IS2	V/V	96	45368	95	5.04
ASA_WVS_1PNPDK20101103_123854_000005363096_00095_45368_7096.N1						IS2	V/V	96	45368	95	5.04
ASA_WVS_1PNPDK20101103_131328_000008543096_00096_45369_7041.N1						IS2	V/V	96	45369	96	5.04
ASA_WVS_1PNPDK20101103_140432_000003303096_00096_45369_7044.N1						IS2	V/V	96	45369	96	5.04
ASA_WVS_1PNPDK20101103_141520_000000443096_00096_45369_7048.N1						IS2	V/V	96	45369	96	5.04
ASA_WVS_1PNPDK20101103_142243_000001493096_00097_45370_7049.N1						IS2	V/V	96	45370	97	5.04
ASA_WVS_1PNPDK20101103_150826_000000443096_00097_45370_7112.N1						IS2	V/V	96	45370	97	5.04
ASA_WVS_1PNPDK20101103_151156_000007793096_00097_45370_7116.N1						IS2	V/V	96	45370	97	5.04
ASA_WVS_1PNPDK20101103_154447_000012293096_00097_45370_7120.N1						IS2	V/V	96	45370	97	5.04
ASA_WVS_1PNPDK20101103_164545_000011693096_00098_45371_7154.N1						IS2	V/V	96	45371	98	5.04
ASA_WVS_1PNPDK20101103_172501_000013043096_00098_45371_7157.N1						IS2	V/V	96	45371	98	5.04
ASA_WVS_1PNPDK20101103_172501_000013043096_00098_45371_7158.N1						IS2	V/V	96	45371	98	5.04
ASA_WVS_1PNPDK20101103_172501_000013043096_00098_45371_7159.N1						IS2	V/V	96	45371	98	5.04
ASA_WVS_1PNPDK20101103_182039_000014993096_00099_45372_7233.N1						IS2	V/V	96	45372	99	5.04
ASA_WVS_1PNPDK20101103_190515_000004803096_00099_45372_7231.N1						IS2	V/V	96	45372	99	5.04
ASA_WVS_1PNPDK20101103_191658_000001643096_00099_45372_7237.N1						IS2	V/V	96	45372	99	5.04
ASA_WVS_1PNPDE20101103_195428_000018743096_00100_45373_3541.N1						IS2	V/V	96	45373	100	5.04
ASA_WVS_1PNPDE20101103_195428_000018743096_00100_45373_3545.N1						IS2	V/V	96	45373	100	5.04
ASA_WVS_1PNPDE20101103_204529_000003153096_00100_45373_3552.N1						IS2	V/V	96	45373	100	5.04
ASA_WVS_1PNPDE20101103_213436_000018893096_00101_45374_3554.N1						IS2	V/V	96	45374	101	5.04
ASA_WVS_1PNPDE20101103_222543_000003443096_00101_45374_3555.N1						IS2	V/V	96	45374	101	5.04
ASA_WVS_1PNPDE20101103_223028_000006593096_00101_45374_3568.N1						IS2	V/V	96	45374	101	5.04
ASA_WVS_1PNPDE20101103_222543_000003443096_00101_45374_3555.N1						IS1	V/V	96	45374	101	5.04
ASA_WVS_1PNPDE20101103_225604_000000603096_00102_45375_3570.N1						IS2	V/V	96	45375	102	5.04
ASA_WVS_1PNPDE20101103_231444_000013043096_00102_45375_3573.N1						IS2	V/V	96	45375	102	5.04
ASA_WVS_1PNPDE20101103_234234_000002253096_00102_45375_3576.N1						IS2	V/V	96	45375	102	5.04
















































03-Nov





03-Nov






03-Nov









03-Nov

Reference: 2001-02-09 14:08:23 V RxGain
 Test : 2010-11-03 20:27:57 V

