



Analysis from 04-NOV-2010 00:00:00 to 04-NOV-2010 23:59:59. Page generated on 05-NOV-2010 07:32:11.
View log file: ASAR_Daily_Report_20101105_0731.log. For any anomalies please contact emma.griffiths@vega.co.uk, kajal.haria@vega.co.uk.

This report is automatically generated every day, every 2 hours. No comments are provided on the results.

SUMMARY

1. DATA SUMMARY
 - 1.1 Summary tables
 - 1.2 Lists of products used
2. AUXILIARY FILES ANALYSIS
 - 2.1 IECF operational ADFs list
 - 2.2 Products with wrong ADFs
3. MODULE STEPPING PRODUCTS ANALYSIS
 - 3.1 V/V polarisation
 - 3.2 H/H polarisation
4. CALIBRATION PULSES ANALYSIS
 - 4.1 Analysis for WVS IS2 V/V
 - 4.1.1 Temporal Evolution Analysis for WVS IS2 V/V
 - 4.1.2 All Rows Analysis for WVS IS2 V/V
 - 4.2 Analysis for GM1 SS3 H/H
 - 4.2.1 Temporal Evolution Analysis for GM1 SS3 H/H
 - 4.2.2 All Rows Analysis for GM1 SS3 H/H
5. DOPPLER ANALYSIS
 - 5.1 Analysis for WVS IS2 V/V
 - 5.1.1 Doppler MAP Analysis for WVS IS2 V/V
 - 5.1.2 Doppler ANX Analysis for WVS IS2 V/V
 - 5.2 Analysis for GM1 SS1 H/H
 - 5.2.1 Doppler MAP Analysis for GM1 SS1 H/H
 - 5.2.2 Doppler ANX Analysis for GM1 SS1 H/H
 - 5.3 Doppler JUMPS Analysis for WSM
6. CHIRP ANALYSIS
 - 6.1 Analysis for WSM SS1 H/H
 - 6.1.1 ScaleFactor
 - 6.2 Analysis for WSM SS1 V/V
 - 6.2.1 ScaleFactor
7. RAW DATA ANALYSIS
 - 7.1 Analysis for WVS
 - 7.2 Analysis for IMM
8. TELEMETRY ANALYSIS
 - 8.1 Number of Missing Lines
 - 8.2 Number of Gaps

1 - DATA SUMMARY

1.1 - Summary tables

[[BACK TO MENU](#)]

WVS				GM1				APM				IMM				WSM				MS			
Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Time	Pol	Modules
PDE	IS1	V/V	2	PDE	WS	H/H	32	PDE	IS4	V/H	1	PDE	IS6	H/H	8	PDE	WS	H/H	23	PDE	2010-11-04 01:28:39	H	320
PDE	IS2	V/V	26	PDK	WS	H/H	55					PDK	IS2	H/H	1	PDE	WS	V/V	5	PDE	2010-11-04 21:31:29	H	320
PDK	IS2	V/V	22													PDK	WS	H/H	13	PDK	2010-11-04 06:29:22	V	320
																PDK	WS	V/V	1	PDK	2010-11-04 11:30:04	H	320
																				PDK	2010-11-04 16:30:46	V	320

1.2 - Lists of products used

[[BACK TO MENU](#)]

[TXT] [XLS] [List_WVS_products_used](#)
 [TXT] [XLS] [List_GM1_products_used](#)
 [TXT] [XLS] [List_APM_products_used](#)
 [TXT] [XLS] [List_IMM_products_used](#)
 [TXT] [XLS] [List_WSM_products_used](#)
 [TXT] [XLS] [List_MS_products_used](#)

2 - AUXILIARY FILES ANALYSIS

2.1 - IECF operational ADFs list

[[BACK TO MENU](#)]

ADFs disseminated for ASAR
ASA_CON_AXVIEC20100608_125449_20100317_120410_20101231_000000
ASA_INS_AXVIEC20101028_095209_20101022_000000_20101231_235959
ASA_XCH_AXVIEC20091217_113006_20020301_000000_20101231_000000
ASA_XCA_AXVIEC20100608_123419_20100317_120410_20110101_000000

2.2 - Products with wrong ADFs

[[BACK TO MENU](#)]

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
WVS	0	0	0	0
GM1	0	0	0	0
APM	0	0	0	0
IMM	0	0	0	0
WSM	0	0	0	0


[TXT] [XLS] [Check_ADFs_WVS](#)
 [TXT] [XLS] [Check_ADFs_GM1](#)
 [TXT] [XLS] [Check_ADFs_APM](#)
 [TXT] [XLS] [Check_ADFs_IMM](#)
 [TXT] [XLS] [Check_ADFs_WSM](#)

3 - MODULE STEPPING PRODUCTS ANALYSIS

SECOND FIXED REFERENCE

Pre-launch reference (2001-02-09)


Reference: 2001-02-09 14:08:23 V RxGain
 Test : 2010-11-04 16:30:46 V



PREVIOUS PRODUCT REFERENCE

Previous product in the same polarisation


Reference: 2010-11-04 06:29:22 V RxGain
 Test : 2010-11-04 16:30:46 V







Reference: 2001-02-09 14:08:23 V RxPhase
 Test : 2010-11-04 16:30:46 V



Reference: 2010-11-04 06:29:22 V RxPhase
 Test : 2010-11-04 16:30:46 V













3.2 - H/H polarisation

[[BACK TO MENU](#)]

SECOND FIXED REFERENCE	PREVIOUS PRODUCT REFERENCE
Pre-launch reference (2001-02-09)	Previous product in the same polarisation





4 - CALIBRATION PULSES ANALYSIS

4.1 - Analysis for WVS IS2 V/V


4.1.1 - Temporal Evolution Analysis for WVS IS2 V/V

[BACK TO MENU]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Calibration pulses for WVS IS2 V/V




Transmit power (P1 - P1a) for WVS IS2 V/V



4.1.2 - All Rows Analysis for WVS IS2 V/V

[BACK TO MENU]





4.2 - Analysis for GM1 SS3 H/H


4.2.1 - Temporal Evolution Analysis for GM1 SS3 H/H

[BACK TO MENU]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Calibration pulses for GM1 SS3 H/H




Transmit power (P1 - P1a) for GM1 SS3 H/H



4.2.2 - All Rows Analysis for GM1 SS3 H/H

[[BACK TO MENU](#)]






5 - DOPPLER ANALYSIS

5.1 - Analysis for WVS IS2 V/V

5.1.1 - Doppler MAP Analysis for WVS IS2 V/V

[[BACK TO MENU](#)]






5.1.2 - Doppler ANX Analysis for WVS IS2 V/V

[[BACK TO MENU](#)]






5.2 - Analysis for GM1 SS1 H/H

5.2.1 - Doppler MAP Analysis for GM1 SS1 H/H

[BACK TO MENU]






5.2.2 - Doppler ANX Analysis for GM1 SS1 H/H


[[BACK TO MENU](#)]






5.3 - Doppler JUMPS Analysis for WSM

[[BACK TO MENU](#)]







6 - CHIRP ANALYSIS

6.1 - Analysis for WSM SS1 H/H

6.1.1 - ScaleFactor

[BACK TO MENU]







6.2 - Analysis for WSM SS1 V/V

6.2.1 - ScaleFactor

[[BACK TO MENU](#)]






7 - RAW DATA ANALYSIS

7.1 - Analysis for WVS

[[BACK TO MENU](#)]


--	--	--



7.2 - Analysis for IMM

[[BACK TO MENU](#)]

--	--	--





8 - TELEMETRY ANALYSIS

Processing Center	Product	Gaps	Missing lines
PDE	ASA_WSM_1PNPDE20101104_145340_00000673096_00111_45384_3716.N1	1	737
PDK	ASA_WSM_1PNPDK20101104_081131_000001593096_00107_45380_7600.N1	0	1

8.1 - Number of Missing lines


[[BACK TO MENU](#)]





8.2 - Number of Gaps

[\[BACK TO MENU \]](#)



ASAR DAILY REPORT for 101104
#####

MODE: DAILY
ANALYSIS: ALL
DATE: 2010-11-04 00:00:00

Analysis will be performed from 2010-11-04 00:00:00 to 2010-11-04 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_101104/

DATA SUMMARY

Summary will be performed from 2010-11-04 00:00:00 to 2010-11-04 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_101104/DATA_SUMMARY

Creating directory ./RESULTS/DAILY/_101104/DATA_SUMMARY...
Writing file ./RESULTS/DAILY/_101104/DATA_SUMMARY/Data_summary.html...

Getting WVS products list from 2010-11-04 00:00:00 to 2010-11-04 23:59:59...
Writing file ./RESULTS/DAILY/_101104/DATA_SUMMARY/List_WVS_products_used.xls...
Writing file ./RESULTS/DAILY/_101104/DATA_SUMMARY/List_WVS_products_used.txt...

Getting GM1 products list from 2010-11-04 00:00:00 to 2010-11-04 23:59:59...
Writing file ./RESULTS/DAILY/_101104/DATA_SUMMARY/List_GM1_products_used.xls...
Writing file ./RESULTS/DAILY/_101104/DATA_SUMMARY/List_GM1_products_used.txt...

Getting APM products list from 2010-11-04 00:00:00 to 2010-11-04 23:59:59...
Writing file ./RESULTS/DAILY/_101104/DATA_SUMMARY/List_APM_products_used.xls...
Writing file ./RESULTS/DAILY/_101104/DATA_SUMMARY/List_APM_products_used.txt...

Getting IMM products list from 2010-11-04 00:00:00 to 2010-11-04 23:59:59...
Writing file ./RESULTS/DAILY/_101104/DATA_SUMMARY/List_IMM_products_used.xls...
Writing file ./RESULTS/DAILY/_101104/DATA_SUMMARY/List_IMM_products_used.txt...

Getting WSM products list from 2010-11-04 00:00:00 to 2010-11-04 23:59:59...
Writing file ./RESULTS/DAILY/_101104/DATA_SUMMARY/List_WSM_products_used.xls...
Writing file ./RESULTS/DAILY/_101104/DATA_SUMMARY/List_WSM_products_used.txt...

Getting MS products list from 2010-11-04 00:00:00 to 2010-11-04 23:59:59...
Writing file ./RESULTS/DAILY/_101104/DATA_SUMMARY/List_MS_products_used.xls...
Writing file ./RESULTS/DAILY/_101104/DATA_SUMMARY/List_MS_products_used.txt...

DATA SUMMARY completed
#####

AUXILIARY FILES ANALYSIS

Analysis will be performed from 2010-11-04 00:00:00 to 2010-11-04 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_101104/AUXILIARY

Creating directory ./RESULTS/DAILY/_101104/AUXILIARY...

Looking for the IECF operational ADFs list...



ADF filter 20101104*current_3_IECF_ADFs.txt
 Found list 20101104_030002_current_3_IECF_ADFs.txt...
 Extracting ADFs...

ASA_CON_AXVIEC20100608_125449_20100317_120410_20101231_000000
 ASA_INS_AXVIEC20101028_095209_20101022_000000_20101231_235959
 ASA_XCH_AXVIEC20091217_113006_20020301_000000_20101231_000000
 ASA_XCA_AXVIEC20100608_123419_20100317_120410_20110101_000000

Writing file ./RESULTS/DAILY/_101104/AUXILIARY/ASAR_ADFs_IECF_List3.html...
 Writing file ./RESULTS/DAILY/_101104/AUXILIARY/Auxiliary_files_summary.html...

Analysing WVS products...

Writing file ./RESULTS/DAILY/_101104/AUXILIARY/Check_ADFs_WVS.xls...
 Writing file ./RESULTS/DAILY/_101104/AUXILIARY/Check_ADFs_WVS.txt...

ASA_WVS_1PNPDE20101104_000557_000003303096_00102_45375_3577.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101104_001042_000015893096_00102_45375_3594.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101104_005858_000000743096_00103_45376_3595.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101104_010219_000004523096_00103_45376_3598.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101104_012147_000002853096_00103_45376_3601.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101104_014602_000001653096_00103_45376_3602.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101104_014802_000001653096_00103_45376_3613.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101104_025328_000004943096_00104_45377_3625.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101104_030127_000003153096_00104_45377_3636.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101104_033251_000002843096_00104_45377_3639.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101104_034148_000001193096_00104_45377_3643.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101104_042956_000008393096_00105_45378_3644.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101104_042956_000008393096_00105_45378_3646.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101104_044341_000001953096_00105_45378_3659.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101104_050640_000013343096_00105_45378_3663.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101104_061118_000002243096_00106_45379_3664.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101104_061955_000001643096_00106_45379_3667.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101104_205816_000018593096_00115_45388_3732.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101104_214901_000002393096_00115_45388_3738.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101104_215201_000007943096_00115_45388_3743.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101104_222039_000000593096_00116_45389_3745.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101104_223852_000014093096_00116_45389_3746.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101104_230422_000003153096_00116_45389_3749.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101104_232915_000002393096_00116_45389_3755.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101104_233215_000011993096_00116_45389_3759.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101104_235620_000003003096_00117_45390_3760.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101104_062225_000002853096_00106_45379_7553.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101104_064654_000018893096_00106_45379_7556.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101104_080250_000002703096_00107_45380_7594.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101104_082708_000019643096_00107_45380_7599.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101104_093143_000009593096_00108_45381_7644.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101104_100722_000018143096_00108_45381_7646.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101104_110220_000000893096_00109_45382_7722.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101104_110909_000011243096_00109_45382_7725.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101104_114736_000016943096_00109_45382_7727.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101104_123522_000010493096_00110_45383_7774.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101104_130438_000002103096_00110_45383_7779.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101104_132750_000002553096_00110_45383_7783.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101104_141940_000000593096_00111_45384_7877.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101104_143801_000006153096_00111_45384_7881.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101104_150805_000007493096_00111_45384_7884.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101104_161004_000011093096_00112_45385_7900.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101104_164819_000010043096_00112_45385_7903.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101104_174520_000014093096_00113_45386_7931.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101104_182833_000011243096_00113_45386_7935.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101104_191858_000017993096_00114_45387_7962.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101104_200847_000004353096_00114_45387_7965.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101104_200847_000004353096_00114_45387_7966.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

Analysing GM1 products...

Writing file ./RESULTS/DAILY/_101104/AUXILIARY/Check_ADFs_GM1.xls...

Writing file ./RESULTS/DAILY/_101104/AUXILIARY/Check_ADFs_GM1.txt...

ASA_GM1_1PNPDE20101104_000220_000002173096_00102_45375_3578.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101104_003802_000000783096_00103_45376_3593.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101104_004305_000009493096_00103_45376_3596.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101104_011044_000005863096_00103_45376_3597.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101104_012035_000000663096_00103_45376_3600.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101104_012713_000000783096_00103_45376_3599.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101104_012959_000004653096_00103_45376_3603.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101104_015443_000013233096_00103_45376_3616.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101104_022355_000009913096_00104_45377_3615.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101104_024606_000002053096_00104_45377_3614.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101104_025026_000001813096_00104_45377_3624.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101104_030726_000005613096_00104_45377_3635.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101104_032420_000001323096_00104_45377_3634.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101104_032737_000001143096_00104_45377_3637.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101104_033123_000000783096_00104_45377_3638.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101104_033823_000002053096_00104_45377_3640.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101104_034429_000007983096_00105_45378_3641.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101104_035923_000012333096_00105_45378_3642.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101104_042409_000003443096_00105_45378_3647.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101104_044743_000004833096_00105_45378_3658.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101104_050421_000001323096_00105_45378_3660.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101104_052944_000012333096_00106_45379_3661.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101104_055415_000003803096_00106_45379_3662.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101104_060318_000001633096_00106_45379_3665.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101104_061552_000002413096_00106_45379_3668.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101104_204327_000008883096_00115_45388_3730.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101104_213003_000000783096_00115_45388_3731.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101104_213720_000007013096_00115_45388_3734.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101104_220603_000004833096_00116_45389_3744.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101104_222230_000006283096_00116_45389_3747.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101104_230302_000000723096_00116_45389_3748.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101104_231016_000011363096_00116_45389_3751.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_062755_000000783096_00106_45379_7551.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_063037_000002713096_00106_45379_7552.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_064221_000002713096_00106_45379_7554.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_071904_000004043096_00107_45380_7555.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_072726_000001083096_00107_45380_7557.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_073528_000003203096_00107_45380_7590.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_080132_000000723096_00107_45380_7593.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_080809_000001993096_00107_45380_7592.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_081413_000001323096_00107_45380_7595.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_082103_000003623096_00107_45380_7596.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_090040_000006043096_00108_45381_7601.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_090929_000001083096_00108_45381_7640.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_092407_000001143096_00108_45381_7641.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_092920_000001383096_00108_45381_7642.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_095823_000005373096_00108_45381_7645.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_103821_000006043096_00109_45382_7647.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_105230_000001503096_00109_45382_7723.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_112838_000000783096_00109_45382_7724.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_113122_000009733096_00109_45382_7726.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_121634_000007433096_00110_45383_7728.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_122740_000004593096_00110_45383_7773.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_125334_000005433096_00110_45383_7775.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_130246_000001083096_00110_45383_7776.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_130845_000001693096_00110_45383_7777.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_131710_000006283096_00110_45383_7778.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_133254_000000663096_00110_45383_7780.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_133415_000003323096_00110_45383_7781.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK


```
ASA_GM1_1PNPDK20101104_134046_000002173096_00110_45383_7782.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_135051_000009973096_00111_45384_7784.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_140613_000008043096_00111_45384_7876.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_142122_000008283096_00111_45384_7878.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_144905_000001873096_00111_45384_7879.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_145451_000000783096_00111_45384_7880.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_145955_000004893096_00111_45384_7883.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_152111_000003023096_00111_45384_7882.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_152851_000009853096_00112_45385_7885.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_154401_000002233096_00112_45385_7897.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_154924_000011063096_00112_45385_7899.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_162920_000000783096_00112_45385_7898.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_163204_000009733096_00112_45385_7901.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_170547_000010943096_00113_45386_7902.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_172239_000002713096_00113_45386_7922.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_173002_000001263096_00113_45386_7921.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_173350_000004833096_00113_45386_7923.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_180935_000002233096_00113_45386_7930.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_181856_000001573096_00113_45386_7932.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_182628_000001203096_00113_45386_7933.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_184756_000004103096_00114_45387_7934.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_185622_000002593096_00114_45387_7936.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_185925_000001993096_00114_45387_7952.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_190926_000005673096_00114_45387_7953.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_194950_000002413096_00114_45387_7959.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_195728_000001503096_00114_45387_7958.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_200522_000002053096_00114_45387_7963.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101104_201646_000010213096_00114_45387_7964.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```

Analysing APM products...

Writing file ./RESULTS/DAILY/_101104/AUXILIARY/Check_ADFs_APM.xls...

Writing file ./RESULTS/DAILY/_101104/AUXILIARY/Check_ADFs_APM.txt...

```
ASA_APM_1PNPDE20101104_160750_000001283096_00112_45385_3719.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```

Analysing IMM products...

Writing file ./RESULTS/DAILY/_101104/AUXILIARY/Check_ADFs_IMM.xls...

Writing file ./RESULTS/DAILY/_101104/AUXILIARY/Check_ADFs_IMM.txt...

```
ASA_IMM_1PNPDE20101104_010050_000000823096_00103_45376_3591.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20101104_024026_000003303096_00104_45377_3612.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20101104_032931_000001023096_00104_45377_3633.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20101104_042023_000002153096_00105_45378_3631.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20101104_060032_000001583096_00106_45379_3655.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20101104_060600_000000373096_00106_45379_3656.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20101104_073425_000000523096_00107_45380_3681.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20101104_174152_000001423096_00113_45386_3721.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20101104_134423_000002023096_00111_45384_7790.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```

Analysing WSM products...

Writing file ./RESULTS/DAILY/_101104/AUXILIARY/Check_ADFs_WSM.xls...

Writing file ./RESULTS/DAILY/_101104/AUXILIARY/Check_ADFs_WSM.txt...

```
ASA_WSM_1PNPDE20101104_003929_000002143096_00103_45376_3590.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101104_013748_000004533096_00103_45376_3610.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101104_015126_000001903096_00103_45376_3611.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```

ASA_WSM_1PNPDE20101104_021648_000004223096_00104_45377_3617.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101104_021648_000004223096_00104_45377_3619.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101104_031649_000004533096_00104_45377_3630.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101104_035749_000000923096_00105_45378_3632.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101104_045549_000005143096_00105_45378_3669.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101104_060733_000002263096_00106_45379_3657.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101104_072922_000002943096_00107_45380_3680.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101104_091124_000003613096_00108_45381_3695.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101104_092606_000001903096_00108_45381_3696.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101104_095549_000001533096_00108_45381_3702.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101104_104826_000002453096_00109_45382_3706.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101104_105516_000002943096_00109_45382_3707.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101104_110425_000002323096_00109_45382_3708.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101104_145340_000000673096_00111_45384_3716.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101104_145615_000002143096_00111_45384_3717.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101104_152616_000001473096_00112_45385_3718.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101104_181321_000003303096_00113_45386_3723.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101104_182137_000002883096_00113_45386_3720.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101104_195353_000002143096_00114_45387_3726.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101104_200003_000003123096_00114_45387_3725.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101104_213333_000002203096_00115_45388_3729.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101104_221706_000001533096_00116_45389_3740.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101104_223317_000003363096_00116_45389_3742.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101104_235250_000002083096_00117_45390_3757.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20101104_055043_000002083096_00106_45379_7550.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20101104_063512_000004283096_00106_45379_7563.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20101104_072549_000000923096_00107_45380_7564.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20101104_081131_000001593096_00107_45380_7600.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20101104_081634_000002513096_00107_45380_7602.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20101104_091751_000001653096_00108_45381_7607.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20101104_131134_000003303096_00110_45383_7789.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20101104_154750_000000923096_00112_45385_7886.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20101104_172711_000001653096_00113_45386_7908.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20101104_190250_000001533096_00114_45387_7941.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20101104_190550_000000923096_00114_45387_7942.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20101104_190750_000000923096_00114_45387_7943.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20101104_203609_000004343096_00115_45388_7970.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20101104_221906_000000923096_00116_45389_7979.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

AUXILIARY FILES ANALYSIS completed

#####

MODULE STEPPING ANALYSIS

#####

Analysis will be performed from 2010-11-04 00:00:00 to 2010-11-04 23:59:59

Results will be exported to the directory: ./RESULTS/DAILY/_101104/MODULE_STEPPING

Creating directory ./RESULTS/DAILY/_101104/MODULE_STEPPING...

Creating directory ./RESULTS/DAILY/_101104/MODULE_STEPPING/FIRST_REFERENCE...

Creating directory ./RESULTS/DAILY/_101104/MODULE_STEPPING/SECOND_REFERENCE...

Creating directory ./RESULTS/DAILY/_101104/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE...

Deleting old files...

Creating images comparing with second reference...

Exporting results to the directory ../../RESULTS/DAILY/_101104/MODULE_STEPPING/SECOND_REFERENCE...

Polarization: H

Reference product: ASA_MS_0PNPDK20010209_135042_0000009A024_00180_11700_0052.N1

Test product: ASA_MS_0PNPDE20101104_213129_000000163096_00115_45388_0045.N1

H

H

../../../../RESULTS/DAILY/_101104/MODULE_STEPPING/SECOND_REFERENCE/TGH_20101104_213129-20010209_135042.png
../../../../RESULTS/DAILY/_101104/MODULE_STEPPING/SECOND_REFERENCE/TPH_20101104_213129-20010209_135042.png
../../../../RESULTS/DAILY/_101104/MODULE_STEPPING/SECOND_REFERENCE/RGH_20101104_213129-20010209_135042.png
../../../../RESULTS/DAILY/_101104/MODULE_STEPPING/SECOND_REFERENCE/RPH_20101104_213129-20010209_135042.png

Polarization: V
Reference product: ASA_MS__0PNPK20010209_140823_00000009A024_00180_11700_0054.N1
Test product: ASA_MS__0PNPK20101104_163046_000000163096_00112_45385_0263.N1

V
V
../../../../RESULTS/DAILY/_101104/MODULE_STEPPING/SECOND_REFERENCE/TGV_20101104_163046-20010209_140823.png
../../../../RESULTS/DAILY/_101104/MODULE_STEPPING/SECOND_REFERENCE/TPV_20101104_163046-20010209_140823.png
../../../../RESULTS/DAILY/_101104/MODULE_STEPPING/SECOND_REFERENCE/RGV_20101104_163046-20010209_140823.png
../../../../RESULTS/DAILY/_101104/MODULE_STEPPING/SECOND_REFERENCE/RPV_20101104_163046-20010209_140823.png

Creating images comparing with previous product reference...

Exporting results to the directory ../../RESULTS/DAILY/_101104/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE...

Polarization: H
Reference product: ASA_MS__0PNPK20101104_113004_000000163096_00109_45382_0262.N1
Test product: ASA_MS__0PNPDE20101104_213129_000000163096_00115_45388_0045.N1

H
H
../../../../RESULTS/DAILY/_101104/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TGH_20101104_213129-20101104_113004.png
../../../../RESULTS/DAILY/_101104/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TPH_20101104_213129-20101104_113004.png
../../../../RESULTS/DAILY/_101104/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RGH_20101104_213129-20101104_113004.png
../../../../RESULTS/DAILY/_101104/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RPH_20101104_213129-20101104_113004.png

Polarization: V
Reference product: ASA_MS__0PNPK20101104_062922_000000163096_00106_45379_0261.N1
Test product: ASA_MS__0PNPK20101104_163046_000000163096_00112_45385_0263.N1

V
V
../../../../RESULTS/DAILY/_101104/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TGV_20101104_163046-20101104_062922.png
../../../../RESULTS/DAILY/_101104/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TPV_20101104_163046-20101104_062922.png
../../../../RESULTS/DAILY/_101104/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RGV_20101104_163046-20101104_062922.png
../../../../RESULTS/DAILY/_101104/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RPV_20101104_163046-20101104_062922.png

MODULE_STEPPING ANALYSIS completed
#####

CALIBRATION PULSES ANALYSIS

Creating directory ./RESULTS/DAILY/_101104/CALIBRATION_PULSES...

ALL ROWS Analysis will be performed from 2010-11-04 00:00:00 to 2010-11-04 23:59:59

Analysing products WVS IS2 V/V
Writing image ../../RESULTS/DAILY/_101104//CALIBRATION_PULSES/Calibration_pulses_all_rows_WVS_IS2_VV.png...
Analysing products GM1 SS3 H/H
Writing image ../../RESULTS/DAILY/_101104//CALIBRATION_PULSES/Calibration_pulses_all_rows_GM1_SS3_HH.png...

TEMPORAL EVOLUTION Analysis will be performed from 2010-11-04 00:00:00 to 2010-11-04 23:59:59

Analysing products WVS IS2 V/V
Getting calibration pulses data for WVS IS2 V/V from 2010-11-04 00:00:00 to 2010-11-04 23:59:59. Rows: 1/5/9/13/17/21/25/29



Writing file ./RESULTS/DAILY/_101104/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2010-11-04_1.dat...
Writing ../../RESULTS/DAILY/_101104//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_1.png...
Writing ../../RESULTS/DAILY/_101104//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_1.png...

Getting calibration pulses data for WVS IS2 V/V from 2010-11-04 00:00:00 to 2010-11-04 23:59:59. Rows: 2/6/10/14/18/22/26/30
Writing file ./RESULTS/DAILY/_101104/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2010-11-04_2.dat...
Writing ../../RESULTS/DAILY/_101104//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_2.png...
Writing ../../RESULTS/DAILY/_101104//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_2.png...

Getting calibration pulses data for WVS IS2 V/V from 2010-11-04 00:00:00 to 2010-11-04 23:59:59. Rows: 3/7/11/15/19/23/27/31
Writing file ./RESULTS/DAILY/_101104/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2010-11-04_3.dat...
Writing ../../RESULTS/DAILY/_101104//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_3.png...
Writing ../../RESULTS/DAILY/_101104//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_3.png...

Getting calibration pulses data for WVS IS2 V/V from 2010-11-04 00:00:00 to 2010-11-04 23:59:59. Rows: 4/8/12/16/20/24/28/32
Writing file ./RESULTS/DAILY/_101104/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2010-11-04_4.dat...
Writing ../../RESULTS/DAILY/_101104//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_4.png...
Writing ../../RESULTS/DAILY/_101104//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_4.png...

Analysing products GM1 SS3 H/H
Getting calibration pulses data for GM1 SS3 H/H from 2010-11-04 00:00:00 to 2010-11-04 23:59:59. Rows: 1/5/9/13/17/21/25/29
Writing file ./RESULTS/DAILY/_101104/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2010-11-04_1.dat...
Writing ../../RESULTS/DAILY/_101104//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_1.png...
Writing ../../RESULTS/DAILY/_101104//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_1.png...

Getting calibration pulses data for GM1 SS3 H/H from 2010-11-04 00:00:00 to 2010-11-04 23:59:59. Rows: 2/6/10/14/18/22/26/30
Writing file ./RESULTS/DAILY/_101104/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2010-11-04_2.dat...
Writing ../../RESULTS/DAILY/_101104//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_2.png...
Writing ../../RESULTS/DAILY/_101104//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_2.png...

Getting calibration pulses data for GM1 SS3 H/H from 2010-11-04 00:00:00 to 2010-11-04 23:59:59. Rows: 3/7/11/15/19/23/27/31
Writing file ./RESULTS/DAILY/_101104/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2010-11-04_3.dat...
Writing ../../RESULTS/DAILY/_101104//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_3.png...
Writing ../../RESULTS/DAILY/_101104//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_3.png...

Getting calibration pulses data for GM1 SS3 H/H from 2010-11-04 00:00:00 to 2010-11-04 23:59:59. Rows: 4/8/12/16/20/24/28/32
Writing file ./RESULTS/DAILY/_101104/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2010-11-04_4.dat...
Writing ../../RESULTS/DAILY/_101104//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_4.png...
Writing ../../RESULTS/DAILY/_101104//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_4.png...

CALIBRATION PULSES ANALYSIS completed
#####

DOPPLER ANALYSIS

Creating directory ./RESULTS/DAILY/_101104/DOPPLER...

DOPPLER ANX Analysis will be performed from 2010-11-04 00:00:00 to 2010-11-04 23:59:59

Analysing products WVS IS2 V/V
Getting doppler data for WVS IS2 V/V from 2010-11-04 00:00:00 to 2010-11-04 23:59:59...
Writing file ./RESULTS/DAILY/_101104/DOPPLER/Doppler_data_WVS_IS2_VV_2010-11-04.dat...
Running IDL program...

Writing file ../../RESULTS/DAILY/_101104/DOPPLER/DOPPLER_ANX_WVS_IS2_VV.png...

Analysing products GM1 SS1 H/H
Getting doppler data for GM1 SS1 H/H from 2010-11-04 00:00:00 to 2010-11-04 23:59:59...
Writing file ./RESULTS/DAILY/_101104/DOPPLER/Doppler_data_GM1_SS1_HH_2010-11-04.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/_101104/DOPPLER/DOPPLER_ANX_GM1_SS1_HH.png...

DOPPLER JUMPS Analysis will be performed on WSM products from 2010-11-04 00:00:00 to 2010-11-04 23:59:59

Analysing by default products WSM
Getting doppler jumps data for WSM from 2010-11-04 00:00:00 to 2010-11-04 23:59:59...
Writing file ./RESULTS/DAILY/_101104/DOPPLER/Doppler_Jumps_data_WSM_2010-11-04.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/_101104/DOPPLER/DOPPLER_JUMPS_ANX_WSM.png...
Writing file ../../RESULTS/DAILY/_101104/DOPPLER/DOPPLER_JUMPS_Date_WSM.png...

DOPPLER MAP Analysis will be performed from 2010-11-04 00:00:00 to 2010-11-04 23:59:59

Analysing products WVS IS2 V/V
Loading predicted doppler values....
Phase: descending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -63.719298 Hz
Writing file ../../RESULTS/DAILY/_101104//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_WVS_IS2_VV_desc.jpg...
Writing file ../../RESULTS/DAILY/_101104//DOPPLER/DOPPLER_Absolute_WVS_IS2_VV_desc.jpg...

Loading predicted doppler values....
Phase: ascending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -61.084002 Hz
Writing file ../../RESULTS/DAILY/_101104//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_WVS_IS2_VV_asc.jpg...
Writing file ../../RESULTS/DAILY/_101104//DOPPLER/DOPPLER_Absolute_WVS_IS2_VV_asc.jpg...

Analysing products GM1 SS1 H/H
Loading predicted doppler values....
Phase: descending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -48.998373 Hz
Writing file ../../RESULTS/DAILY/_101104//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_GM1_SS1_HH_desc.jpg...
Writing file ../../RESULTS/DAILY/_101104//DOPPLER/DOPPLER_Absolute_GM1_SS1_HH_desc.jpg...

Loading predicted doppler values....
Phase: ascending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -54.248805 Hz
Writing file ../../RESULTS/DAILY/_101104//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_GM1_SS1_HH_asc.jpg...
Writing file ../../RESULTS/DAILY/_101104//DOPPLER/DOPPLER_Absolute_GM1_SS1_HH_asc.jpg...

DOPPLER ANALYSIS completed

#####

CHIRP ANALYSIS

#####

Creating directory ./RESULTS/DAILY/_101104/CHIRP...

CHIRP Analysis will be performed from 2010-11-04 00:00:00 to 2010-11-04 23:59:59

Analysing products WSM SS1 H/H

Getting ScaleFactor data for WSM SS1 H/H from 2010-11-04 00:00:00 to 2010-11-04 23:59:59...

Writing file ./RESULTS/DAILY/_101104/CHIRP/ScaleFactor_data_WSM_SS1_HH_2010-11-04.dat...

Running IDL program...

Writing file ../../RESULTS/DAILY/_101104/CHIRP/ScaleFactor_ANX_WSM_SS1_HH.png...

Writing file ../../RESULTS/DAILY/_101104/CHIRP/ScaleFactor_DATE_WSM_SS1_HH.png...

Analysing products WSM SS1 V/V

Getting ScaleFactor data for WSM SS1 V/V from 2010-11-04 00:00:00 to 2010-11-04 23:59:59...

Writing file ./RESULTS/DAILY/_101104/CHIRP/ScaleFactor_data_WSM_SS1_VV_2010-11-04.dat...

Running IDL program...

Writing file ../../RESULTS/DAILY/_101104/CHIRP/ScaleFactor_ANX_WSM_SS1_VV.png...

Writing file ../../RESULTS/DAILY/_101104/CHIRP/ScaleFactor_DATE_WSM_SS1_VV.png...

CHIRP ANALYSIS completed

#####

RAW DATA ANALYSIS

#####

Analysis will be performed from 2010-11-04 00:00:00 to 2010-11-04 23:59:59

Results will be exported to the directory: ./RESULTS/DAILY/_101104/RAW_DATA

Creating directory ./RESULTS/DAILY/_101104/RAW_DATA...

Getting raw data for WVS from 2010-11-04 00:00:00 to 2010-11-04 23:59:59...

Writing file ./RESULTS/DAILY/_101104/RAW_DATA/Raw_data_WVS_2010-11-04.dat...

Running IDL program to create graphs...

Creating image ../../RESULTS/DAILY/_101104/RAW_DATA/Raw_data_WVS_input_mean.png...

Creating image ../../RESULTS/DAILY/_101104/RAW_DATA/Raw_data_WVS_input_stdev.png...

Creating image ../../RESULTS/DAILY/_101104/RAW_DATA/Raw_data_WVS_gain_imbalance.png...

Getting raw data for IMM from 2010-11-04 00:00:00 to 2010-11-04 23:59:59...

Writing file ./RESULTS/DAILY/_101104/RAW_DATA/Raw_data_IMM_2010-11-04.dat...

Running IDL program to create graphs...

Creating image ../../RESULTS/DAILY/_101104/RAW_DATA/Raw_data_IMM_input_mean.png...

Creating image ../../RESULTS/DAILY/_101104/RAW_DATA/Raw_data_IMM_input_stdev.png...

Creating image ../../RESULTS/DAILY/_101104/RAW_DATA/Raw_data_IMM_gain_imbalance.png...

RAW DATA ANALYSIS completed

#####

TELEMETRY ANALYSIS

Analysis will be performed from 2010-11-04 00:00:00 to 2010-11-04 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_101104/TELEMETRY

Creating directory ./RESULTS/DAILY/_101104/TELEMETRY...

Looking for gaps and missing lines in WVS products...

Checking 26 products from PDE...
Checking 22 products from PDK...

Looking for gaps and missing lines in GM1 products...

Checking 32 products from PDE...
Checking 55 products from PDK...

Looking for gaps and missing lines in APM products...

Checking 1 products from PDE...
No products from PDK...

Looking for gaps and missing lines in IMM products...

Checking 8 products from PDE...
Checking 1 products from PDK...

Looking for gaps and missing lines in WSM products...

Checking 28 products from PDE...
Found product...ASA_WSM_1PNPDE20101104_145340_00000673096_00111_45384_3716.N1 / 1 gaps / 737 missing lines
Checking 14 products from PDK...
Found product...ASA_WSM_1PNPDK20101104_081131_000001593096_00107_45380_7600.N1 / 0 gaps / 1 missing lines

Creating graph of missing lines and gaps...

Creating image: ./RESULTS/DAILY/_101104/TELEMETRY/TELEMETRY_Missing_lines.png...
Creating image: ./RESULTS/DAILY/_101104/TELEMETRY/TELEMETRY_Gaps.png...

TELEMETRY ANALYSIS completed

#####

HTML REPORT generation

#####

Building file ./RESULTS/DAILY/_101104/asarReport.html...

Building DATA SUMMARY section...
Building AUXILIARY FILES ANALYSIS section...
Building MODULE STEPPING ANALYSIS section...
Building CALIBRATION PULSES ANALYSIS section...
Building DOPPLER ANALYSIS section...
Building CHIRP ANALYSIS section...
Building RAW DATA ANALYSIS section...
Building TELEMETRY ANALYSIS section...

HTML REPORT generation completed

#####



Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
ASA_APM_1PNPDE20101104_160750_000001283096_00112_45385_3719.N1	OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_GM1_1PNPDE20101104_000220_000002173096_00102_45375_3578.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101104_003802_000000783096_00103_45376_3593.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101104_004305_000009493096_00103_45376_3596.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101104_011044_000005863096_00103_45376_3597.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101104_012035_000000663096_00103_45376_3600.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101104_012713_000000783096_00103_45376_3599.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101104_012959_000004653096_00103_45376_3603.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101104_015443_000013233096_00103_45376_3616.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101104_022355_000009913096_00104_45377_3615.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101104_024606_000002053096_00104_45377_3614.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101104_025026_000001813096_00104_45377_3624.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101104_030726_000005613096_00104_45377_3635.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101104_032420_000001323096_00104_45377_3634.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101104_032737_000001143096_00104_45377_3637.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101104_033123_000000783096_00104_45377_3638.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101104_033823_000002053096_00104_45377_3640.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101104_034429_000007983096_00105_45378_3641.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101104_035923_000012333096_00105_45378_3642.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101104_042409_000003443096_00105_45378_3647.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101104_044743_000004833096_00105_45378_3658.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101104_050421_000001323096_00105_45378_3660.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101104_052944_000012333096_00106_45379_3661.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101104_055415_000003803096_00106_45379_3662.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101104_060318_000001633096_00106_45379_3665.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101104_061552_000002413096_00106_45379_3668.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101104_204327_000008883096_00115_45388_3730.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101104_213003_000000783096_00115_45388_3731.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101104_213720_000007013096_00115_45388_3734.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101104_220603_000004833096_00116_45389_3744.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101104_222230_000006283096_00116_45389_3747.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101104_230302_000000723096_00116_45389_3748.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101104_231016_000011363096_00116_45389_3751.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_062755_000000783096_00106_45379_7551.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_063037_000002713096_00106_45379_7552.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_064221_000002713096_00106_45379_7554.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_071904_000004043096_00107_45380_7555.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_072726_000001083096_00107_45380_7557.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_073528_000003203096_00107_45380_7590.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_080132_000000723096_00107_45380_7593.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_080809_000001993096_00107_45380_7592.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_081413_000001323096_00107_45380_7595.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_082103_000003623096_00107_45380_7596.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_090040_000006043096_00108_45381_7601.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_090929_000001083096_00108_45381_7640.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_092407_000001143096_00108_45381_7641.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_092920_000001383096_00108_45381_7642.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_095823_000005373096_00108_45381_7645.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_103821_000006043096_00109_45382_7647.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_105230_000001503096_00109_45382_7723.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_112838_000000783096_00109_45382_7724.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_113122_000009733096_00109_45382_7726.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_121634_000007433096_00110_45383_7728.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_122740_000004593096_00110_45383_7773.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_125334_000005433096_00110_45383_7775.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_130246_000001083096_00110_45383_7776.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_130845_000001693096_00110_45383_7777.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_131710_000006283096_00110_45383_7778.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_133254_000000663096_00110_45383_7780.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_133415_000003323096_00110_45383_7781.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_134046_000002173096_00110_45383_7782.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_135051_000009973096_00111_45384_7784.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_140613_000008043096_00111_45384_7876.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_142122_000008283096_00111_45384_7878.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_144905_000001873096_00111_45384_7879.N1					OK	OK	OK	OK

ASA_GM1_1PNPDK20101104_145451_000000783096_00111_45384_7880.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_145955_000004893096_00111_45384_7883.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_152111_000003023096_00111_45384_7882.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_152851_000009853096_00112_45385_7885.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_154401_000002233096_00112_45385_7897.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_154924_000011063096_00112_45385_7899.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_162920_000000783096_00112_45385_7898.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_163204_000009733096_00112_45385_7901.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_170547_000010943096_00113_45386_7902.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_172239_000002713096_00113_45386_7922.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_173002_000001263096_00113_45386_7921.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_173350_000004833096_00113_45386_7923.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_180935_000002233096_00113_45386_7930.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_181856_000001573096_00113_45386_7932.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_182628_000001203096_00113_45386_7933.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_184756_000004103096_00114_45387_7934.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_185622_000002593096_00114_45387_7936.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_185925_000001993096_00114_45387_7952.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_190926_000005673096_00114_45387_7953.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_194950_000002413096_00114_45387_7959.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_195728_000001503096_00114_45387_7958.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_200522_000002053096_00114_45387_7963.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101104_201646_000010213096_00114_45387_7964.N1	OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
ASA_IMM_1PNPDE20101104_010050_000000823096_00103_45376_3591.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20101104_024026_000003303096_00104_45377_3612.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20101104_032931_000001023096_00104_45377_3633.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20101104_042023_000002153096_00105_45378_3631.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20101104_060032_000001583096_00106_45379_3655.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20101104_060600_000000373096_00106_45379_3656.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20101104_073425_000000523096_00107_45380_3681.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20101104_174152_000001423096_00113_45386_3721.N1	OK	OK	OK	OK
ASA_IMM_1PNPDK20101104_134423_000002023096_00111_45384_7790.N1	OK	OK	OK	OK


Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WSM_1PNPDE20101104_003929_000002143096_00103_45376_3590.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101104_013748_000004533096_00103_45376_3610.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101104_015126_000001903096_00103_45376_3611.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101104_021648_000004223096_00104_45377_3617.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101104_021648_000004223096_00104_45377_3619.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101104_031649_000004533096_00104_45377_3630.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101104_035749_000000923096_00105_45378_3632.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101104_045549_000005143096_00105_45378_3669.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101104_060733_000002263096_00106_45379_3657.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101104_072922_000002943096_00107_45380_3680.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101104_091124_000003613096_00108_45381_3695.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101104_092606_000001903096_00108_45381_3696.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101104_095549_000001533096_00108_45381_3702.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101104_104826_000002453096_00109_45382_3706.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101104_105516_000002943096_00109_45382_3707.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101104_110425_000002323096_00109_45382_3708.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101104_145340_000000673096_00111_45384_3716.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101104_145615_000002143096_00111_45384_3717.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101104_152616_000001473096_00112_45385_3718.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101104_181321_000003303096_00113_45386_3723.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101104_182137_000002883096_00113_45386_3720.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101104_195353_000002143096_00114_45387_3726.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101104_200003_000003123096_00114_45387_3725.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101104_213333_000002203096_00115_45388_3729.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101104_221706_000001533096_00116_45389_3740.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101104_223317_000003363096_00116_45389_3742.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101104_235250_000002083096_00117_45390_3757.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20101104_055043_000002083096_00106_45379_7550.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20101104_063512_000004283096_00106_45379_7563.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20101104_072549_000000923096_00107_45380_7564.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20101104_081131_000001593096_00107_45380_7600.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20101104_081634_000002513096_00107_45380_7602.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20101104_091751_000001653096_00108_45381_7607.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20101104_131134_000003303096_00110_45383_7789.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20101104_154750_000000923096_00112_45385_7886.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20101104_172711_000001653096_00113_45386_7908.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20101104_190250_000001533096_00114_45387_7941.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20101104_190550_000000923096_00114_45387_7942.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20101104_190750_000000923096_00114_45387_7943.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20101104_203609_000004343096_00115_45388_7970.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20101104_221906_000000923096_00116_45389_7979.N1					OK	OK	OK	OK





Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WVS_1PNPDE20101104_000557_000003303096_00102_45375_3577.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101104_001042_000015893096_00102_45375_3594.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101104_005858_000000743096_00103_45376_3595.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101104_010219_000004523096_00103_45376_3598.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101104_012147_000002853096_00103_45376_3601.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101104_014602_000001653096_00103_45376_3602.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101104_014802_000001653096_00103_45376_3613.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101104_025328_000004943096_00104_45377_3625.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101104_030127_000003153096_00104_45377_3636.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101104_033251_000002843096_00104_45377_3639.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101104_034148_000001193096_00104_45377_3643.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101104_042956_000008393096_00105_45378_3644.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101104_042956_000008393096_00105_45378_3646.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101104_044341_000001953096_00105_45378_3659.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101104_050640_000013343096_00105_45378_3663.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101104_061118_000002243096_00106_45379_3664.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101104_061955_000001643096_00106_45379_3667.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101104_205816_000018593096_00115_45388_3732.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101104_214901_000002393096_00115_45388_3738.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101104_215201_000007943096_00115_45388_3743.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101104_222039_000000593096_00116_45389_3745.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101104_223852_000014093096_00116_45389_3746.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101104_230422_000003153096_00116_45389_3749.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101104_232915_000002393096_00116_45389_3755.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101104_233215_000011993096_00116_45389_3759.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101104_235620_000003003096_00117_45390_3760.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101104_062225_000002853096_00106_45379_7553.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101104_064654_000018893096_00106_45379_7556.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101104_080250_000002703096_00107_45380_7594.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101104_082708_000019643096_00107_45380_7599.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101104_093143_000009593096_00108_45381_7644.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101104_100722_000018143096_00108_45381_7646.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101104_110220_000000893096_00109_45382_7722.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101104_110909_000011243096_00109_45382_7725.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101104_114736_000016943096_00109_45382_7727.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101104_123522_000010493096_00110_45383_7774.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101104_130438_000002103096_00110_45383_7779.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101104_132750_000002553096_00110_45383_7783.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101104_141940_000000593096_00111_45384_7877.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101104_143801_000006153096_00111_45384_7881.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101104_150805_000007493096_00111_45384_7884.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101104_161004_000011093096_00112_45385_7900.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101104_164819_000010043096_00112_45385_7903.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101104_174520_000014093096_00113_45386_7931.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101104_182833_000011243096_00113_45386_7935.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101104_191858_000017993096_00114_45387_7962.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101104_200847_000004353096_00114_45387_7965.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101104_200847_000004353096_00114_45387_7966.N1					OK	OK	OK	OK


Calibration pulses for GM1 SS3 H/H







Calibration pulses for GM1 SS3 H/H




Calibration pulses for GM1 SS3 H/H




Calibration pulses for GM1 SS3 H/H




Calibration pulses for WVS IS2 V/V




Calibration pulses for WVS IS2 V/V




Calibration pulses for WVS IS2 V/V




04-Nov



04-Nov




04-Nov




04-Nov

rows: _ 3 _ 7 _ 11 _ 15 _ 19 _ 23 _ 27 _ 31


Calibration pulses for WVS IS2 V/V




04-Nov



04-Nov





04-Nov







04-Nov



rows: _ 4 _ 8 _ 12 _ 16 _ 20 _ 24 _ 28 _ 32











































Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion			
ASA_APM_1PNPDE20101104_160750_000001283096_00112_45385_3719.N1						IS4	V/H	96	45385 112 5.04



Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_GM1_1PNPDE20101104_000220_000002173096_00102_45375_3578.N1						SS1	H/H	96	45375	102	5.04
ASA_GM1_1PNPDE20101104_003802_000000783096_00103_45376_3593.N1						SS1	H/H	96	45376	103	5.04
ASA_GM1_1PNPDE20101104_004305_000009493096_00103_45376_3596.N1						SS1	H/H	96	45376	103	5.04
ASA_GM1_1PNPDE20101104_011044_000005863096_00103_45376_3597.N1						SS1	H/H	96	45376	103	5.04
ASA_GM1_1PNPDE20101104_012035_000000663096_00103_45376_3600.N1						SS1	H/H	96	45376	103	5.04
ASA_GM1_1PNPDE20101104_012713_000000783096_00103_45376_3599.N1						SS1	H/H	96	45376	103	5.04
ASA_GM1_1PNPDE20101104_012959_000004653096_00103_45376_3603.N1						SS1	H/H	96	45376	103	5.04
ASA_GM1_1PNPDE20101104_015443_000013233096_00103_45376_3616.N1						SS1	H/H	96	45376	103	5.04
ASA_GM1_1PNPDE20101104_022355_000009913096_00104_45377_3615.N1						SS1	H/H	96	45377	104	5.04
ASA_GM1_1PNPDE20101104_024606_000002053096_00104_45377_3614.N1						SS1	H/H	96	45377	104	5.04
ASA_GM1_1PNPDE20101104_025026_000001813096_00104_45377_3624.N1						SS1	H/H	96	45377	104	5.04
ASA_GM1_1PNPDE20101104_030726_000005613096_00104_45377_3635.N1						SS1	H/H	96	45377	104	5.04
ASA_GM1_1PNPDE20101104_032420_000001323096_00104_45377_3634.N1						SS1	H/H	96	45377	104	5.04
ASA_GM1_1PNPDE20101104_032737_000001143096_00104_45377_3637.N1						SS1	H/H	96	45377	104	5.04
ASA_GM1_1PNPDE20101104_033123_000000783096_00104_45377_3638.N1						SS1	H/H	96	45377	104	5.04
ASA_GM1_1PNPDE20101104_033823_000002053096_00104_45377_3640.N1						SS1	H/H	96	45377	104	5.04
ASA_GM1_1PNPDE20101104_034429_000007983096_00105_45378_3641.N1						SS1	H/H	96	45378	105	5.04
ASA_GM1_1PNPDE20101104_035923_000012333096_00105_45378_3642.N1						SS1	H/H	96	45378	105	5.04
ASA_GM1_1PNPDE20101104_042409_000003443096_00105_45378_3647.N1						SS1	H/H	96	45378	105	5.04
ASA_GM1_1PNPDE20101104_044743_000004833096_00105_45378_3658.N1						SS1	H/H	96	45378	105	5.04
ASA_GM1_1PNPDE20101104_050421_000001323096_00105_45378_3660.N1						SS1	H/H	96	45378	105	5.04
ASA_GM1_1PNPDE20101104_052944_000012333096_00106_45379_3661.N1						SS1	H/H	96	45379	106	5.04
ASA_GM1_1PNPDE20101104_055415_000003803096_00106_45379_3662.N1						SS1	H/H	96	45379	106	5.04
ASA_GM1_1PNPDE20101104_060318_000001633096_00106_45379_3665.N1						SS1	H/H	96	45379	106	5.04
ASA_GM1_1PNPDE20101104_061552_000002413096_00106_45379_3668.N1						SS1	H/H	96	45379	106	5.04
ASA_GM1_1PNPDK20101104_062755_000000783096_00106_45379_7551.N1						SS1	H/H	96	45379	106	5.04
ASA_GM1_1PNPDK20101104_063037_000002713096_00106_45379_7552.N1						SS1	H/H	96	45379	106	5.04
ASA_GM1_1PNPDK20101104_064221_000002713096_00106_45379_7554.N1						SS1	H/H	96	45379	106	5.04
ASA_GM1_1PNPDK20101104_071904_000004043096_00107_45380_7555.N1						SS1	H/H	96	45380	107	5.04
ASA_GM1_1PNPDK20101104_072726_000001083096_00107_45380_7557.N1						SS1	H/H	96	45380	107	5.04
ASA_GM1_1PNPDK20101104_073528_000003203096_00107_45380_7590.N1						SS1	H/H	96	45380	107	5.04
ASA_GM1_1PNPDK20101104_080132_000000723096_00107_45380_7593.N1						SS1	H/H	96	45380	107	5.04
ASA_GM1_1PNPDK20101104_080809_000001993096_00107_45380_7592.N1						SS1	H/H	96	45380	107	5.04
ASA_GM1_1PNPDK20101104_081413_000001323096_00107_45380_7595.N1						SS1	H/H	96	45380	107	5.04
ASA_GM1_1PNPDK20101104_082103_000003623096_00107_45380_7596.N1						SS1	H/H	96	45380	107	5.04
ASA_GM1_1PNPDK20101104_090040_000006043096_00108_45381_7601.N1						SS1	H/H	96	45381	108	5.04
ASA_GM1_1PNPDK20101104_090929_000001083096_00108_45381_7640.N1						SS1	H/H	96	45381	108	5.04
ASA_GM1_1PNPDK20101104_092407_000001143096_00108_45381_7641.N1						SS1	H/H	96	45381	108	5.04
ASA_GM1_1PNPDK20101104_092920_000001383096_00108_45381_7642.N1						SS1	H/H	96	45381	108	5.04
ASA_GM1_1PNPDK20101104_095823_000005373096_00108_45381_7645.N1						SS1	H/H	96	45381	108	5.04
ASA_GM1_1PNPDK20101104_103821_000006043096_00109_45382_7647.N1						SS1	H/H	96	45382	109	5.04
ASA_GM1_1PNPDK20101104_105230_000001503096_00109_45382_7723.N1						SS1	H/H	96	45382	109	5.04
ASA_GM1_1PNPDK20101104_112838_000000783096_00109_45382_7724.N1						SS1	H/H	96	45382	109	5.04
ASA_GM1_1PNPDK20101104_113122_000009733096_00109_45382_7726.N1						SS1	H/H	96	45382	109	5.04
ASA_GM1_1PNPDK20101104_121634_000007433096_00110_45383_7728.N1						SS1	H/H	96	45383	110	5.04
ASA_GM1_1PNPDK20101104_122740_000004593096_00110_45383_7773.N1						SS1	H/H	96	45383	110	5.04
ASA_GM1_1PNPDK20101104_125334_000005433096_00110_45383_7775.N1						SS1	H/H	96	45383	110	5.04
ASA_GM1_1PNPDK20101104_130246_000001083096_00110_45383_7776.N1						SS1	H/H	96	45383	110	5.04
ASA_GM1_1PNPDK20101104_130845_000001693096_00110_45383_7777.N1						SS1	H/H	96	45383	110	5.04
ASA_GM1_1PNPDK20101104_131710_000006283096_00110_45383_7778.N1						SS1	H/H	96	45383	110	5.04
ASA_GM1_1PNPDK20101104_133254_000000663096_00110_45383_7780.N1						SS1	H/H	96	45383	110	5.04
ASA_GM1_1PNPDK20101104_133415_000003323096_00110_45383_7781.N1						SS1	H/H	96	45383	110	5.04
ASA_GM1_1PNPDK20101104_134046_000002173096_00110_45383_7782.N1						SS1	H/H	96	45383	110	5.04
ASA_GM1_1PNPDK20101104_135051_000009973096_00111_45384_7784.N1						SS1	H/H	96	45384	111	5.04
ASA_GM1_1PNPDK20101104_140613_000008043096_00111_45384_7876.N1						SS1	H/H	96	45384	111	5.04
ASA_GM1_1PNPDK20101104_142122_000008283096_00111_45384_7878.N1						SS1	H/H	96	45384	111	5.04
ASA_GM1_1PNPDK20101104_144905_000001873096_00111_45384_7879.N1						SS1	H/H	96	45384	111	5.04
ASA_GM1_1PNPDK20101104_145451_000000783096_00111_45384_7880.N1						SS1	H/H	96	45384	111	5.04
ASA_GM1_1PNPDK20101104_145955_000004893096_00111_45384_7883.N1						SS1	H/H	96	45384	111	5.04
ASA_GM1_1PNPDK20101104_152111_000003023096_00111_45384_7882.N1						SS1	H/H	96	45384	111	5.04
ASA_GM1_1PNPDK20101104_152851_000009853096_00112_45385_7885.N1						SS1	H/H	96	45385	112	5.04
ASA_GM1_1PNPDK20101104_154401_000002233096_00112_45385_7897.N1						SS1	H/H	96	45385	112	5.04
ASA_GM1_1PNPDK20101104_154924_000011063096_00112_45385_7899.N1						SS1	H/H	96	45385	112	5.04
ASA_GM1_1PNPDK20101104_162920_000000783096_00112_45385_7898.N1						SS1	H/H	96	45385	112	5.04
ASA_GM1_1PNPDK20101104_163204_000009733096_00112_45385_7901.N1						SS1	H/H	96	45385	112	5.04
ASA_GM1_1PNPDK20101104_170547_000010943096_00113_45386_7902.N1						SS1	H/H	96	45386	113	5.04
ASA_GM1_1PNPDK20101104_172239_000002713096_00113_45386_7922.N1						SS1	H/H	96	45386	113	5.04


ASA_GM1_1PNPDK20101104_173002_000001263096_00113_45386_7921.N1	SS1	H/H	96	45386	113	5.04
ASA_GM1_1PNPDK20101104_173350_000004833096_00113_45386_7923.N1	SS1	H/H	96	45386	113	5.04
ASA_GM1_1PNPDK20101104_180935_000002233096_00113_45386_7930.N1	SS1	H/H	96	45386	113	5.04
ASA_GM1_1PNPDK20101104_181856_000001573096_00113_45386_7932.N1	SS1	H/H	96	45386	113	5.04
ASA_GM1_1PNPDK20101104_182628_000001203096_00113_45386_7933.N1	SS1	H/H	96	45386	113	5.04
ASA_GM1_1PNPDK20101104_184756_000004103096_00114_45387_7934.N1	SS1	H/H	96	45387	114	5.04
ASA_GM1_1PNPDK20101104_185622_000002593096_00114_45387_7936.N1	SS1	H/H	96	45387	114	5.04
ASA_GM1_1PNPDK20101104_185925_000001993096_00114_45387_7952.N1	SS1	H/H	96	45387	114	5.04
ASA_GM1_1PNPDK20101104_190926_000005673096_00114_45387_7953.N1	SS1	H/H	96	45387	114	5.04
ASA_GM1_1PNPDK20101104_194950_000002413096_00114_45387_7959.N1	SS1	H/H	96	45387	114	5.04
ASA_GM1_1PNPDK20101104_195728_000001503096_00114_45387_7958.N1	SS1	H/H	96	45387	114	5.04
ASA_GM1_1PNPDK20101104_200522_000002053096_00114_45387_7963.N1	SS1	H/H	96	45387	114	5.04
ASA_GM1_1PNPDK20101104_201646_000010213096_00114_45387_7964.N1	SS1	H/H	96	45387	114	5.04
ASA_GM1_1PNPDE20101104_204327_000008883096_00115_45388_3730.N1	SS1	H/H	96	45388	115	5.04
ASA_GM1_1PNPDE20101104_213003_000000783096_00115_45388_3731.N1	SS1	H/H	96	45388	115	5.04
ASA_GM1_1PNPDE20101104_213720_000007013096_00115_45388_3734.N1	SS1	H/H	96	45388	115	5.04
ASA_GM1_1PNPDE20101104_220603_000004833096_00116_45389_3744.N1	SS1	H/H	96	45389	116	5.04
ASA_GM1_1PNPDE20101104_222230_000006283096_00116_45389_3747.N1	SS1	H/H	96	45389	116	5.04
ASA_GM1_1PNPDE20101104_230302_000000723096_00116_45389_3748.N1	SS1	H/H	96	45389	116	5.04
ASA_GM1_1PNPDE20101104_231016_000011363096_00116_45389_3751.N1	SS1	H/H	96	45389	116	5.04


Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_IMM_1PNPDE20101104_010050_000000823096_00103_45376_3591.N1						IS6	H/H	96	45376	103	5.04
ASA_IMM_1PNPDE20101104_024026_000003303096_00104_45377_3612.N1						IS6	H/H	96	45377	104	5.04
ASA_IMM_1PNPDE20101104_032931_000001023096_00104_45377_3633.N1						IS6	H/H	96	45377	104	5.04
ASA_IMM_1PNPDE20101104_042023_000002153096_00105_45378_3631.N1						IS6	H/H	96	45378	105	5.04
ASA_IMM_1PNPDE20101104_060032_000001583096_00106_45379_3655.N1						IS6	H/H	96	45379	106	5.04
ASA_IMM_1PNPDE20101104_060600_000000373096_00106_45379_3656.N1						IS6	H/H	96	45379	106	5.04
ASA_IMM_1PNPDE20101104_073425_000000523096_00107_45380_3681.N1						IS6	H/H	96	45380	107	5.04
ASA_IMM_1PNPDK20101104_134423_000002023096_00111_45384_7790.N1						IS2	H/H	96	45384	111	5.04
ASA_IMM_1PNPDE20101104_174152_000001423096_00113_45386_3721.N1						IS6	H/H	96	45386	113	5.04


Filename	Pol	Timestamp	count(Module)				
ASA_MS__0PNPDE20101104_012839_000000163096_00103_45376_0044.N1				H	2010-11-04	01:28:39	320
ASA_MS__0PNPDK20101104_062922_000000163096_00106_45379_0261.N1				V	2010-11-04	06:29:22	320
ASA_MS__0PNPDK20101104_113004_000000163096_00109_45382_0262.N1				H	2010-11-04	11:30:04	320
ASA_MS__0PNPDK20101104_163046_000000163096_00112_45385_0263.N1				V	2010-11-04	16:30:46	320
ASA_MS__0PNPDE20101104_213129_000000163096_00115_45388_0045.N1				H	2010-11-04	21:31:29	320


Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WSM_1PNPDE20101103_235706_000003123096_00102_45375_3566.N1						SS1	H/H	96	45375	102	5.04
ASA_WSM_1PNPDE20101104_003929_000002143096_00103_45376_3590.N1						SS1	H/H	96	45376	103	5.04
ASA_WSM_1PNPDE20101104_013748_000004533096_00103_45376_3610.N1						SS1	H/H	96	45376	103	5.04
ASA_WSM_1PNPDE20101104_015126_000001903096_00103_45376_3611.N1						SS1	V/V	96	45376	103	5.04
ASA_WSM_1PNPDE20101104_021648_000004223096_00104_45377_3619.N1						SS1	H/H	96	45377	104	5.04
ASA_WSM_1PNPDE20101104_021648_000004223096_00104_45377_3617.N1						SS1	H/H	96	45377	104	5.04
ASA_WSM_1PNPDE20101104_031649_000004533096_00104_45377_3630.N1						SS1	H/H	96	45377	104	5.04
ASA_WSM_1PNPDE20101104_035749_00000923096_00105_45378_3632.N1						SS1	H/H	96	45378	105	5.04
ASA_WSM_1PNPDE20101104_045549_000005143096_00105_45378_3669.N1						SS1	H/H	96	45378	105	5.04
ASA_WSM_1PNPDK20101104_055043_000002083096_00106_45379_7550.N1						SS1	H/H	96	45379	106	5.04
ASA_WSM_1PNPDE20101104_060733_000002263096_00106_45379_3657.N1						SS1	H/H	96	45379	106	5.04
ASA_WSM_1PNPDK20101104_063512_000004283096_00106_45379_7563.N1						SS1	H/H	96	45379	106	5.04
ASA_WSM_1PNPDK20101104_072549_00000923096_00107_45380_7564.N1						SS1	H/H	96	45380	107	5.04
ASA_WSM_1PNPDE20101104_072922_000002943096_00107_45380_3680.N1						SS1	H/H	96	45380	107	5.04
ASA_WSM_1PNPDK20101104_081131_000001593096_00107_45380_7600.N1						SS1	H/H	96	45380	107	5.04
ASA_WSM_1PNPDK20101104_081634_000002513096_00107_45380_7602.N1						SS1	H/H	96	45380	107	5.04
ASA_WSM_1PNPDE20101104_091124_000003613096_00108_45381_3695.N1						SS1	H/H	96	45381	108	5.04
ASA_WSM_1PNPDK20101104_091751_000001653096_00108_45381_7607.N1						SS1	H/H	96	45381	108	5.04
ASA_WSM_1PNPDE20101104_092606_000001903096_00108_45381_3696.N1						SS1	H/H	96	45381	108	5.04
ASA_WSM_1PNPDE20101104_095549_000001533096_00108_45381_3702.N1						SS1	H/H	96	45381	108	5.04
ASA_WSM_1PNPDE20101104_104826_000002453096_00109_45382_3706.N1						SS1	H/H	96	45382	109	5.04
ASA_WSM_1PNPDE20101104_105516_000002943096_00109_45382_3707.N1						SS1	V/V	96	45382	109	5.04
ASA_WSM_1PNPDE20101104_110425_000002323096_00109_45382_3708.N1						SS1	V/V	96	45382	109	5.04
ASA_WSM_1PNPDK20101104_131134_000003303096_00110_45383_7789.N1						SS1	H/H	96	45383	110	5.04
ASA_WSM_1PNPDE20101104_145340_00000673096_00111_45384_3716.N1						SS1	H/H	96	45384	111	5.04
ASA_WSM_1PNPDE20101104_145615_000002143096_00111_45384_3717.N1						SS1	H/H	96	45384	111	5.04
ASA_WSM_1PNPDE20101104_152616_000001473096_00112_45385_3718.N1						SS1	V/V	96	45385	112	5.04
ASA_WSM_1PNPDK20101104_154750_00000923096_00112_45385_7886.N1						SS1	H/H	96	45385	112	5.04
ASA_WSM_1PNPDK20101104_172711_000001653096_00113_45386_7908.N1						SS1	H/H	96	45386	113	5.04
ASA_WSM_1PNPDE20101104_181321_000003303096_00113_45386_3723.N1						SS1	H/H	96	45386	113	5.04
ASA_WSM_1PNPDE20101104_182137_000002883096_00113_45386_3720.N1						SS1	H/H	96	45386	113	5.04
ASA_WSM_1PNPDK20101104_190250_000001533096_00114_45387_7941.N1						SS1	V/V	96	45387	114	5.04
ASA_WSM_1PNPDK20101104_190550_00000923096_00114_45387_7942.N1						SS1	H/H	96	45387	114	5.04
ASA_WSM_1PNPDK20101104_190750_00000923096_00114_45387_7943.N1						SS1	H/H	96	45387	114	5.04
ASA_WSM_1PNPDE20101104_195353_000002143096_00114_45387_3726.N1						SS1	H/H	96	45387	114	5.04
ASA_WSM_1PNPDE20101104_200003_000003123096_00114_45387_3725.N1						SS1	H/H	96	45387	114	5.04
ASA_WSM_1PNPDK20101104_203609_000004343096_00115_45388_7970.N1						SS1	H/H	96	45388	115	5.04
ASA_WSM_1PNPDE20101104_213333_000002203096_00115_45388_3729.N1						SS1	H/H	96	45388	115	5.04
ASA_WSM_1PNPDE20101104_221706_000001533096_00116_45389_3740.N1						SS1	H/H	96	45389	116	5.04
ASA_WSM_1PNPDK20101104_221906_00000923096_00116_45389_7979.N1						SS1	H/H	96	45389	116	5.04
ASA_WSM_1PNPDE20101104_223317_000003363096_00116_45389_3742.N1						SS1	H/H	96	45389	116	5.04
ASA_WSM_1PNPDE20101104_235250_000002083096_00117_45390_3757.N1						SS1	V/V	96	45390	117	5.04




Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WVS_1PNPDE20101104_000557_000003303096_00102_45375_3577.N1						IS2	V/V	96	45375	102	5.04
ASA_WVS_1PNPDE20101104_001042_000015893096_00102_45375_3594.N1						IS2	V/V	96	45375	102	5.04
ASA_WVS_1PNPDE20101104_005858_000000743096_00103_45376_3595.N1						IS2	V/V	96	45376	103	5.04
ASA_WVS_1PNPDE20101104_010219_000004523096_00103_45376_3598.N1						IS2	V/V	96	45376	103	5.04
ASA_WVS_1PNPDE20101104_012147_000002853096_00103_45376_3601.N1						IS2	V/V	96	45376	103	5.04
ASA_WVS_1PNPDE20101104_014602_000001653096_00103_45376_3602.N1						IS2	V/V	96	45376	103	5.04
ASA_WVS_1PNPDE20101104_014802_000001653096_00103_45376_3613.N1						IS2	V/V	96	45376	103	5.04
ASA_WVS_1PNPDE20101104_025328_000004943096_00104_45377_3625.N1						IS2	V/V	96	45377	104	5.04
ASA_WVS_1PNPDE20101104_030127_000003153096_00104_45377_3636.N1						IS2	V/V	96	45377	104	5.04
ASA_WVS_1PNPDE20101104_033251_000002843096_00104_45377_3639.N1						IS2	V/V	96	45377	104	5.04
ASA_WVS_1PNPDE20101104_034148_000001193096_00104_45377_3643.N1						IS2	V/V	96	45377	104	5.04
ASA_WVS_1PNPDE20101104_042956_000008393096_00105_45378_3644.N1						IS2	V/V	96	45378	105	5.04
ASA_WVS_1PNPDE20101104_042956_000008393096_00105_45378_3646.N1						IS2	V/V	96	45378	105	5.04
ASA_WVS_1PNPDE20101104_044341_000001953096_00105_45378_3659.N1						IS2	V/V	96	45378	105	5.04
ASA_WVS_1PNPDE20101104_050640_000013343096_00105_45378_3663.N1						IS2	V/V	96	45378	105	5.04
ASA_WVS_1PNPDE20101104_061118_000002243096_00106_45379_3664.N1						IS2	V/V	96	45379	106	5.04
ASA_WVS_1PNPDE20101104_061955_000001643096_00106_45379_3667.N1						IS2	V/V	96	45379	106	5.04
ASA_WVS_1PNPDK20101104_062225_000002853096_00106_45379_7553.N1						IS2	V/V	96	45379	106	5.04
ASA_WVS_1PNPDK20101104_064654_000018893096_00106_45379_7556.N1						IS2	V/V	96	45379	106	5.04
ASA_WVS_1PNPDK20101104_080250_000002703096_00107_45380_7594.N1						IS2	V/V	96	45380	107	5.04
ASA_WVS_1PNPDK20101104_082708_000019643096_00107_45380_7599.N1						IS2	V/V	96	45380	107	5.04
ASA_WVS_1PNPDK20101104_093143_000009593096_00108_45381_7644.N1						IS2	V/V	96	45381	108	5.04
ASA_WVS_1PNPDK20101104_100722_000018143096_00108_45381_7646.N1						IS2	V/V	96	45381	108	5.04
ASA_WVS_1PNPDK20101104_110220_000000893096_00109_45382_7722.N1						IS2	V/V	96	45382	109	5.04
ASA_WVS_1PNPDK20101104_110909_000011243096_00109_45382_7725.N1						IS2	V/V	96	45382	109	5.04
ASA_WVS_1PNPDK20101104_114736_000016943096_00109_45382_7727.N1						IS2	V/V	96	45382	109	5.04
ASA_WVS_1PNPDK20101104_123522_000010493096_00110_45383_7774.N1						IS2	V/V	96	45383	110	5.04
ASA_WVS_1PNPDK20101104_130438_000002103096_00110_45383_7779.N1						IS2	V/V	96	45383	110	5.04
ASA_WVS_1PNPDK20101104_132750_000002553096_00110_45383_7783.N1						IS2	V/V	96	45383	110	5.04
ASA_WVS_1PNPDK20101104_141940_000000593096_00111_45384_7877.N1						IS2	V/V	96	45384	111	5.04
ASA_WVS_1PNPDK20101104_143801_000006153096_00111_45384_7881.N1						IS2	V/V	96	45384	111	5.04
ASA_WVS_1PNPDK20101104_150805_000007493096_00111_45384_7884.N1						IS2	V/V	96	45384	111	5.04
ASA_WVS_1PNPDK20101104_161004_000011093096_00112_45385_7900.N1						IS2	V/V	96	45385	112	5.04
ASA_WVS_1PNPDK20101104_164819_000010043096_00112_45385_7903.N1						IS2	V/V	96	45385	112	5.04
ASA_WVS_1PNPDK20101104_174520_000014093096_00113_45386_7931.N1						IS2	V/V	96	45386	113	5.04
ASA_WVS_1PNPDK20101104_182833_000011243096_00113_45386_7935.N1						IS2	V/V	96	45386	113	5.04
ASA_WVS_1PNPDK20101104_191858_000017993096_00114_45387_7962.N1						IS2	V/V	96	45387	114	5.04
ASA_WVS_1PNPDK20101104_200847_000004353096_00114_45387_7965.N1						IS2	V/V	96	45387	114	5.04
ASA_WVS_1PNPDK20101104_200847_000004353096_00114_45387_7966.N1						IS2	V/V	96	45387	114	5.04
ASA_WVS_1PNPDE20101104_205816_000018593096_00115_45388_3732.N1						IS2	V/V	96	45388	115	5.04
ASA_WVS_1PNPDE20101104_214901_000002393096_00115_45388_3738.N1						IS2	V/V	96	45388	115	5.04
ASA_WVS_1PNPDE20101104_215201_000007943096_00115_45388_3743.N1						IS2	V/V	96	45388	115	5.04
ASA_WVS_1PNPDE20101104_214901_000002393096_00115_45388_3738.N1						IS1	V/V	96	45388	115	5.04
ASA_WVS_1PNPDE20101104_222039_000000593096_00116_45389_3745.N1						IS2	V/V	96	45389	116	5.04
ASA_WVS_1PNPDE20101104_223852_000014093096_00116_45389_3746.N1						IS2	V/V	96	45389	116	5.04
ASA_WVS_1PNPDE20101104_230422_000003153096_00116_45389_3749.N1						IS2	V/V	96	45389	116	5.04
ASA_WVS_1PNPDE20101104_232915_000002393096_00116_45389_3755.N1						IS2	V/V	96	45389	116	5.04
ASA_WVS_1PNPDE20101104_233215_000011993096_00116_45389_3759.N1						IS2	V/V	96	45389	116	5.04
ASA_WVS_1PNPDE20101104_232915_000002393096_00116_45389_3755.N1						IS1	V/V	96	45389	116	5.04
ASA_WVS_1PNPDE20101104_235620_000003003096_00117_45390_3760.N1						IS2	V/V	96	45390	117	5.04













































04-Nov



04-Nov



04-Nov

