



Analysis from 02-FEB-2011 00:00:00 to 02-FEB-2011 23:59:59. Page generated on 03-FEB-2011 07:32:33.
View log file: ASAR_Daily_Report_20110203_0731.log. For any anomalies please contact emma.griffiths@vega.co.uk, kajal.haria@vega.co.uk.

This report is automatically generated every day, every 2 hours. No comments are provided on the results.

SUMMARY

1. DATA SUMMARY
 - 1.1 Summary tables
 - 1.2 Lists of products used
2. AUXILIARY FILES ANALYSIS
 - 2.1 IECF operational ADFs list
 - 2.2 Products with wrong ADFs
3. MODULE STEPPING PRODUCTS ANALYSIS
 - 3.1 V/V polarisation
 - 3.2 H/H polarisation
4. CALIBRATION PULSES ANALYSIS
 - 4.1 Analysis for WVS IS2 V/V
 - 4.1.1 Temporal Evolution Analysis for WVS IS2 V/V
 - 4.1.2 All Rows Analysis for WVS IS2 V/V
 - 4.2 Analysis for GM1 SS3 H/H
 - 4.2.1 Temporal Evolution Analysis for GM1 SS3 H/H
 - 4.2.2 All Rows Analysis for GM1 SS3 H/H
5. DOPPLER ANALYSIS
 - 5.1 Analysis for WVS IS2 V/V
 - 5.1.1 Doppler MAP Analysis for WVS IS2 V/V
 - 5.1.2 Doppler ANX Analysis for WVS IS2 V/V
 - 5.2 Analysis for GM1 SS1 H/H
 - 5.2.1 Doppler MAP Analysis for GM1 SS1 H/H
 - 5.2.2 Doppler ANX Analysis for GM1 SS1 H/H
 - 5.3 Doppler JUMPS Analysis for WSM
6. CHIRP ANALYSIS
 - 6.1 Analysis for WSM SS1 H/H
 - 6.1.1 ScaleFactor
 - 6.2 Analysis for WSM SS1 V/V
 - 6.2.1 ScaleFactor
7. RAW DATA ANALYSIS
 - 7.1 Analysis for WVS
 - 7.2 Analysis for IMM
8. TELEMETRY ANALYSIS
 - 8.1 Number of Missing Lines
 - 8.2 Number of Gaps

1 - DATA SUMMARY

1.1 - Summary tables

[[BACK TO MENU](#)]

WVS				GM1				APM				IMM				WSM				MS			
Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Time	Pol	Modules
PDE	IS1	V/V	5	PDE	WS	H/H	23	PDE	IS3	H/H	1	PDE	IS1	H/H	1	PDE	WS	H/H	26	PDK	2011-02-02 18:13:17	H	320
PDE	IS2	V/V	29	PDK	WS	H/H	43	PDE	IS4	V/H	2	PDE	IS3	H/H	1	PDE	WS	V/V	5	PDK	2011-02-02 19:53:31	V	320
PDK	IS2	V/V	25									PDE	IS3	V/V	1	PDK	WS	H/H	15				
												PDE	IS4	V/V	1	PDK	WS	V/V	2				
												PDE	IS6	H/H	10								
												PDE	IS7	H/H	2								

1.2 - Lists of products used

[[BACK TO MENU](#)]

[\[TXT\]](#) [\[XLS\]](#) List_WVS_products_used
[\[TXT\]](#) [\[XLS\]](#) List_GM1_products_used
[\[TXT\]](#) [\[XLS\]](#) List_APM_products_used
[\[TXT\]](#) [\[XLS\]](#) List_IMM_products_used
[\[TXT\]](#) [\[XLS\]](#) List_WSM_products_used
[\[TXT\]](#) [\[XLS\]](#) List_MS_products_used

2 - AUXILIARY FILES ANALYSIS

2.1 - IECF operational ADFs list

[[BACK TO MENU](#)]

ADFs disseminated for ASAR
ASA_CON_AXVIEC20101222_141422_20100317_120410_20141231_000000
ASA_INS_AXVIEC20110124_114858_20101228_112000_20141231_235959
ASA_XCH_AXVIEC20101222_143057_20020301_000000_20141231_000000
ASA_XCA_AXVIEC20101111_113830_20100601_000000_20141231_000000

2.2 - Products with wrong ADFs

[[BACK TO MENU](#)]

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
WVS	0	0	0	0
GM1	0	0	0	0
APM	0	0	0	0
IMM	0	0	0	0
WSM	0	0	0	0

[\[TXT\]](#) [\[XLS\]](#) Check_ADFs_WVS
[\[TXT\]](#) [\[XLS\]](#) Check_ADFs_GM1
[\[TXT\]](#) [\[XLS\]](#) Check_ADFs_APM
[\[TXT\]](#) [\[XLS\]](#) Check_ADFs_IMM
[\[TXT\]](#) [\[XLS\]](#) Check_ADFs_WSM

3 - MODULE STEPPING PRODUCTS ANALYSIS











3.2 - H/H polarisation

[[BACK TO MENU](#)]

SECOND FIXED REFERENCE	PREVIOUS PRODUCT REFERENCE
Pre-launch reference (2001-02-09)	Previous product in the same polarisation





4 - CALIBRATION PULSES ANALYSIS

4.1 - Analysis for WVS IS2 V/V


4.1.1 - Temporal Evolution Analysis for WVS IS2 V/V

[BACK TO MENU]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Calibration pulses for WVS IS2 V/V




Transmit power (P1 - P1a) for WVS IS2 V/V



4.1.2 - All Rows Analysis for WVS IS2 V/V

[[BACK TO MENU](#)]



4.2 - Analysis for GM1 SS3 H/H


4.2.1 - Temporal Evolution Analysis for GM1 SS3 H/H

[BACK TO MENU]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Calibration pulses for GM1 SS3 H/H




Transmit power (P1 - P1a) for GM1 SS3 H/H



4.2.2 - All Rows Analysis for GM1 SS3 H/H

[BACK TO MENU]






5 - DOPPLER ANALYSIS

5.1 - Analysis for WVS IS2 V/V

5.1.1 - Doppler MAP Analysis for WVS IS2 V/V

[[BACK TO MENU](#)]






5.1.2 - Doppler ANX Analysis for WVS IS2 V/V

[[BACK TO MENU](#)]






5.2 - Analysis for GM1 SS1 H/H

5.2.1 - Doppler MAP Analysis for GM1 SS1 H/H

[[BACK TO MENU](#)]






5.2.2 - Doppler ANX Analysis for GM1 SS1 H/H

[[BACK TO MENU](#)]






5.3 - Doppler JUMPS Analysis for WSM

[[BACK TO MENU](#)]

--	--





6 - CHIRP ANALYSIS

6.1 - Analysis for WSM SS1 H/H

6.1.1 - ScaleFactor

[[BACK TO MENU](#)]







6.2 - Analysis for WSM SS1 V/V

6.2.1 - ScaleFactor

[[BACK TO MENU](#)]






7 - RAW DATA ANALYSIS

7.1 - Analysis for WVS

[[BACK TO MENU](#)]




--	--	--



7.2 - Analysis for IMM

[[BACK TO MENU](#)]

--	--	--




Channel	Statistics	DSS-B
MEAN I	mean	0.000279962
	stdev	6.88366e-09
MEAN Q	mean	0.000541542
	stdev	7.38925e-09
Channel	Statistics	DSS-B
STDEV I	mean	0.0758390
	stdev	0.000596206
STDEV Q	mean	0.0761590
	stdev	0.000604580

8 - TELEMETRY ANALYSIS

8.1 - Number of Missing lines


[BACK TO MENU]





8.2 - Number of Gaps

[[BACK TO MENU](#)]



ASAR DAILY REPORT for 110202
#####

MODE: DAILY
ANALYSIS: ALL
DATE: 2011-02-02 00:00:00

Analysis will be performed from 2011-02-02 00:00:00 to 2011-02-02 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_110202/

DATA SUMMARY

Summary will be performed from 2011-02-02 00:00:00 to 2011-02-02 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_110202/DATA_SUMMARY

Creating directory ./RESULTS/DAILY/_110202/DATA_SUMMARY...
Writing file ./RESULTS/DAILY/_110202/DATA_SUMMARY/Data_summary.html...

Getting WVS products list from 2011-02-02 00:00:00 to 2011-02-02 23:59:59...
Writing file ./RESULTS/DAILY/_110202/DATA_SUMMARY/List_WVS_products_used.xls...
Writing file ./RESULTS/DAILY/_110202/DATA_SUMMARY/List_WVS_products_used.txt...

Getting GM1 products list from 2011-02-02 00:00:00 to 2011-02-02 23:59:59...
Writing file ./RESULTS/DAILY/_110202/DATA_SUMMARY/List_GM1_products_used.xls...
Writing file ./RESULTS/DAILY/_110202/DATA_SUMMARY/List_GM1_products_used.txt...

Getting APM products list from 2011-02-02 00:00:00 to 2011-02-02 23:59:59...
Writing file ./RESULTS/DAILY/_110202/DATA_SUMMARY/List_APM_products_used.xls...
Writing file ./RESULTS/DAILY/_110202/DATA_SUMMARY/List_APM_products_used.txt...

Getting IMM products list from 2011-02-02 00:00:00 to 2011-02-02 23:59:59...
Writing file ./RESULTS/DAILY/_110202/DATA_SUMMARY/List_IMM_products_used.xls...
Writing file ./RESULTS/DAILY/_110202/DATA_SUMMARY/List_IMM_products_used.txt...

Getting WSM products list from 2011-02-02 00:00:00 to 2011-02-02 23:59:59...
Writing file ./RESULTS/DAILY/_110202/DATA_SUMMARY/List_WSM_products_used.xls...
Writing file ./RESULTS/DAILY/_110202/DATA_SUMMARY/List_WSM_products_used.txt...

Getting MS products list from 2011-02-02 00:00:00 to 2011-02-02 23:59:59...
Writing file ./RESULTS/DAILY/_110202/DATA_SUMMARY/List_MS_products_used.xls...
Writing file ./RESULTS/DAILY/_110202/DATA_SUMMARY/List_MS_products_used.txt...

DATA SUMMARY completed
#####

AUXILIARY FILES ANALYSIS

Analysis will be performed from 2011-02-02 00:00:00 to 2011-02-02 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_110202/AUXILIARY

Creating directory ./RESULTS/DAILY/_110202/AUXILIARY...

Looking for the IECF operational ADFs list...



ADF filter 20110202*current_3_IECF_ADFs.txt
 Found list 20110202_030001_current_3_IECF_ADFs.txt...
 Extracting ADFs...

ASA_CON_AXVIEC20101222_141422_20100317_120410_20141231_000000
 ASA_INS_AXVIEC20110124_114858_20101228_112000_20141231_235959
 ASA_XCH_AXVIEC20101222_143057_20020301_000000_20141231_000000
 ASA_XCA_AXVIEC20101111_113830_20100601_000000_20141231_000000

Writing file ./RESULTS/DAILY/_110202/AUXILIARY/ASAR_ADFs_IECF_List3.html...
 Writing file ./RESULTS/DAILY/_110202/AUXILIARY/Auxiliary_files_summary.html...

Analysing WVS products...

Writing file ./RESULTS/DAILY/_110202/AUXILIARY/Check_ADFs_WVS.xls...
 Writing file ./RESULTS/DAILY/_110202/AUXILIARY/Check_ADFs_WVS.txt...

ASA_WVS_1PNPDE20110202_000506_000004503099_00102_46668_6190.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110202_001151_000015893099_00102_46668_6210.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110202_010135_000001043099_00103_46669_6209.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110202_010507_000004213099_00103_46669_6207.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110202_012404_000003003099_00103_46669_6205.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110202_014529_000003293099_00103_46669_6212.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110202_015014_000002553099_00103_46669_6229.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110202_020621_000001943099_00104_46670_6225.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110202_021340_000001053099_00104_46670_6222.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110202_025545_000004643099_00104_46670_6235.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110202_030315_000005253099_00104_46670_6248.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110202_032543_000002103099_00104_46670_6249.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110202_033459_000002993099_00104_46670_6251.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110202_034405_000001193099_00104_46670_6254.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110202_034835_000001793099_00105_46671_6255.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110202_043227_000007793099_00105_46671_6260.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110202_044456_000004353099_00105_46671_6268.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110202_050557_000015143099_00105_46671_6272.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110202_061047_000003893099_00106_46672_6271.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110202_062231_000002253099_00106_46672_6273.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110202_210032_000015293099_00115_46681_6401.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110202_212953_000002853099_00115_46681_6399.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110202_215003_000002843099_00115_46681_6398.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110202_215348_000008243099_00115_46681_6409.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110202_221855_000003003099_00116_46682_6412.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110202_224036_000014393099_00116_46682_6413.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110202_230659_000004653099_00116_46682_6415.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110202_232921_000004043099_00116_46682_6426.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110202_233506_000016193099_00116_46682_6435.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110202_062601_000003903099_00106_46672_5445.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110202_064611_0000020243099_00106_46672_5450.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110202_080441_000004803099_00107_46673_5481.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110202_082625_000021443099_00107_46673_5484.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110202_093423_000011093099_00108_46674_5507.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110202_100639_000019943099_00108_46674_5509.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110202_110141_000002243099_00109_46675_5547.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110202_111135_000012143099_00109_46675_5549.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110202_114653_000018743099_00109_46675_5553.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110202_114653_000018743099_00109_46675_5555.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110202_123753_000010343099_00110_46676_5579.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110202_130655_000003903099_00110_46676_5581.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110202_132707_000004353099_00110_46676_5584.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110202_142147_000002843099_00111_46677_5598.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110202_142937_000001343099_00111_46677_5599.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110202_144017_000007953099_00111_46677_5601.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110202_150721_000009303099_00111_46677_5603.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110202_160805_000001343099_00112_46678_5640.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110202_161151_000013193099_00112_46678_5642.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

```
ASA_WVS_1PNPDK20110202_164735_000011843099_00112_46678_5644.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110202_174739_000014993099_00113_46679_5669.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110202_182749_000001353099_00113_46679_5668.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110202_183214_000010343099_00113_46679_5671.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110202_192105_000019043099_00114_46680_5696.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110202_200829_000005853099_00114_46680_5699.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```

Analysing GM1 products...

Writing file ./RESULTS/DAILY/_110202/AUXILIARY/Check_ADFs_GM1.xls...

Writing file ./RESULTS/DAILY/_110202/AUXILIARY/Check_ADFs_GM1.txt...

```
ASA_GM1_1PNPDE20110202_004842_000006283099_00103_46669_6208.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110202_011259_000006283099_00103_46669_6206.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110202_013508_000006163099_00103_46669_6211.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110202_015511_000006713099_00103_46669_6224.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110202_021603_000009433099_00104_46670_6227.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110202_023427_000004833099_00104_46670_6223.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110202_025244_000001813099_00104_46670_6238.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110202_031243_000007793099_00104_46670_6247.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110202_032951_000001753099_00104_46670_6246.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110202_034040_000002053099_00104_46670_6252.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110202_034648_000001023099_00105_46671_6253.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110202_035223_000011783099_00105_46671_6250.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110202_041417_000003803099_00105_46671_6261.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110202_045257_000007793099_00105_46671_6269.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110202_053200_000017583099_00106_46672_6278.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110202_204537_00000963099_00115_46681_6391.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110202_205256_000004533099_00115_46681_6400.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110202_213518_000005673099_00115_46681_6397.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110202_220816_000006283099_00116_46682_6411.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110202_222830_00000783099_00116_46682_6410.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110202_223228_000003923099_00116_46682_6414.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110202_231810_000003563099_00116_46682_6428.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110202_063311_000007793099_00106_46672_5448.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110202_072209_000003863099_00107_46673_5449.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110202_073028_000001753099_00107_46673_5451.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110202_073216_000001753099_00107_46673_5477.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110202_073844_000002113099_00107_46673_5478.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110202_075134_000005373099_00107_46673_5480.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110202_080315_00000783099_00107_46673_5479.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110202_081325_000007793099_00107_46673_5482.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110202_090253_000002893099_00108_46674_5485.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110202_092044_000000663099_00108_46674_5504.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110202_092242_00000723099_00108_46674_5505.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110202_092623_000003503099_00108_46674_5506.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110202_095339_000007793099_00108_46674_5508.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110202_104037_000004713099_00109_46675_5510.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110202_105444_000001573099_00109_46675_5546.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110202_110834_000001813099_00109_46675_5548.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110202_113646_000006043099_00109_46675_5550.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110202_121850_000005493099_00110_46676_5552.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110202_121850_000005493099_00110_46676_5554.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110202_125551_000005433099_00110_46676_5578.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110202_130502_000001083099_00110_46676_5580.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110202_131407_000007793099_00110_46676_5583.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110202_133509_000004103099_00110_46676_5582.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110202_134304_000004893099_00110_46676_5586.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110202_135306_000001443099_00111_46677_5585.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110202_135714_000006283099_00111_46677_5587.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110202_141331_000002053099_00111_46677_5597.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110202_143239_000002653099_00111_46677_5600.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110202_145421_000007793099_00111_46677_5602.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110202_152328_000013533099_00111_46677_5604.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110202_155611_000007133099_00112_46678_5641.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```



```
ASA_GM1_1PNPDK20110202_163435_000007793099_00112_46678_5643.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110202_170803_000010813099_00113_46679_5645.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110202_170803_000010813099_00113_46679_5646.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110202_173602_000005253099_00113_46679_5667.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110202_181449_000007793099_00113_46679_5670.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110202_185013_000007133099_00114_46680_5672.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110202_190046_000000783099_00114_46680_5693.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110202_190450_000000963099_00114_46680_5694.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110202_191326_000003203099_00114_46680_5695.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110202_195935_000002893099_00114_46680_5697.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110202_202006_000009613099_00114_46680_5698.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110202_203855_000001203099_00115_46681_5700.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```

Analysing APM products...

```
Writing file ./RESULTS/DAILY/_110202/AUXILIARY/Check_ADFs_APM.xls...
Writing file ./RESULTS/DAILY/_110202/AUXILIARY/Check_ADFs_APM.txt...
```

```
ASA_APM_1PNPDE20110202_142021_000000443099_00111_46677_6377.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20110202_143835_000000413099_00111_46677_6380.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20110202_161102_000000423099_00112_46678_6382.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```

Analysing IMM products...

```
Writing file ./RESULTS/DAILY/_110202/AUXILIARY/Check_ADFs_IMM.xls...
Writing file ./RESULTS/DAILY/_110202/AUXILIARY/Check_ADFs_IMM.txt...
```

```
ASA_IMM_1PNPDE20110202_010353_000000623099_00103_46669_6213.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20110202_024230_000005003099_00104_46670_6221.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20110202_033245_000001123099_00104_46670_6243.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20110202_042035_000004703099_00105_46671_6244.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20110202_042928_000001723099_00105_46671_6245.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20110202_060115_000003543099_00106_46672_6266.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20110202_060743_000001783099_00106_46672_6267.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20110202_073513_000002003099_00107_46673_6297.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20110202_074213_000000383099_00107_46673_6298.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20110202_092154_000000373099_00108_46674_6328.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20110202_143706_000000793099_00111_46677_6379.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20110202_174447_000001663099_00113_46679_6385.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20110202_191847_000001223099_00114_46680_6388.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20110202_201906_000000513099_00114_46680_6390.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20110202_230616_000000373099_00116_46682_6417.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20110202_230616_000000373099_00116_46682_6418.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```

Analysing WSM products...

```
Writing file ./RESULTS/DAILY/_110202/AUXILIARY/Check_ADFs_WSM.xls...
Writing file ./RESULTS/DAILY/_110202/AUXILIARY/Check_ADFs_WSM.txt...
```

```
ASA_WSM_1PNPDE20110202_000148_000001533099_00102_46668_6180.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110202_003908_000005693099_00103_46669_6204.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110202_012951_000003123099_00103_46669_6203.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110202_021023_000001903099_00104_46670_6228.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110202_023149_000001533099_00104_46670_6226.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110202_025102_000000923099_00104_46670_6230.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110202_041205_000001283099_00105_46671_6242.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110202_061834_000002393099_00106_46672_6270.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110202_074526_000003673099_00107_46673_6299.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110202_080032_000001593099_00107_46673_6300.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```

ASA_WSM_1PNPDE20110202_091428_000003733099_00108_46674_6327.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110202_093214_000001283099_00108_46674_6329.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110202_104831_000001773099_00109_46675_6354.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110202_105806_000000923099_00109_46675_6357.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110202_110646_000000923099_00109_46675_6358.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110202_113232_000002453099_00109_46675_6359.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110202_141702_000001593099_00111_46677_6376.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110202_142712_000001353099_00111_46677_6378.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110202_155029_000003363099_00112_46678_6381.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110202_172947_000002513099_00113_46679_6383.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110202_173429_000000923099_00113_46679_6384.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110202_190848_000002753099_00114_46680_6386.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110202_195603_000001903099_00114_46680_6389.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110202_200430_000002393099_00114_46680_6387.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110202_204720_000003303099_00115_46681_6396.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110202_212641_000001903099_00115_46681_6405.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110202_214446_000003123099_00115_46681_6392.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110202_222955_000001533099_00116_46682_6427.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110202_223905_000000923099_00116_46682_6419.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110202_231526_000001593099_00116_46682_6429.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110202_232410_000003123099_00116_46682_6416.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20110202_072035_000000923099_00107_46673_5446.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20110202_072840_000001043099_00107_46673_5447.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20110202_090747_000001103099_00108_46674_5494.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20110202_090939_000000923099_00108_46674_5483.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20110202_091135_000005383099_00108_46674_5489.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20110202_105109_000002143099_00109_46675_5518.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20110202_105806_000000923099_00109_46675_5517.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20110202_105950_000001103099_00109_46675_5519.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20110202_122801_000005933099_00110_46676_5563.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20110202_135538_000000923099_00111_46677_5594.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20110202_140800_000003123099_00111_46677_5593.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20110202_154606_000003303099_00112_46678_5621.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20110202_172611_000003303099_00113_46679_5654.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20110202_190214_000001533099_00114_46680_5678.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20110202_190635_000002083099_00114_46680_5679.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20110202_204101_000002693099_00115_46681_5706.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20110202_222455_000002083099_00116_46682_5726.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

AUXILIARY FILES ANALYSIS completed

#####

MODULE STEPPING ANALYSIS

#####

Analysis will be performed from 2011-02-02 00:00:00 to 2011-02-02 23:59:59

Results will be exported to the directory: ./RESULTS/DAILY/_110202/MODULE_STEPPING

Creating directory ./RESULTS/DAILY/_110202/MODULE_STEPPING...

Creating directory ./RESULTS/DAILY/_110202/MODULE_STEPPING/FIRST_REFERENCE...

Creating directory ./RESULTS/DAILY/_110202/MODULE_STEPPING/SECOND_REFERENCE...

Creating directory ./RESULTS/DAILY/_110202/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE...

Deleting old files...

Creating images comparing with second reference...

Exporting results to the directory ../RESULTS/DAILY/_110202/MODULE_STEPPING/SECOND_REFERENCE...

Polarization: H

Reference product: ASA_MS_0PNPDK20010209_135042_0000009A024_00180_11700_0052.N1

Test product: ASA_MS_0PNPDK20110202_181317_000000163099_00113_46679_0424.N1

H

H

../../../../RESULTS/DAILY/_110202/MODULE_STEPPING/SECOND_REFERENCE/TGH_20110202_181317-20010209_135042.png
../../../../RESULTS/DAILY/_110202/MODULE_STEPPING/SECOND_REFERENCE/TPH_20110202_181317-20010209_135042.png
../../../../RESULTS/DAILY/_110202/MODULE_STEPPING/SECOND_REFERENCE/RGH_20110202_181317-20010209_135042.png
../../../../RESULTS/DAILY/_110202/MODULE_STEPPING/SECOND_REFERENCE/RPH_20110202_181317-20010209_135042.png

Polarization: V
Reference product: ASA_MS__0PNPK20010209_140823_00000009A024_00180_11700_0054.N1
Test product: ASA_MS__0PNPK20110202_195331_000000163099_00114_46680_0425.N1

V
V
../../../../RESULTS/DAILY/_110202/MODULE_STEPPING/SECOND_REFERENCE/TGV_20110202_195331-20010209_140823.png
../../../../RESULTS/DAILY/_110202/MODULE_STEPPING/SECOND_REFERENCE/TPV_20110202_195331-20010209_140823.png
../../../../RESULTS/DAILY/_110202/MODULE_STEPPING/SECOND_REFERENCE/RGV_20110202_195331-20010209_140823.png
../../../../RESULTS/DAILY/_110202/MODULE_STEPPING/SECOND_REFERENCE/RPV_20110202_195331-20010209_140823.png

Creating images comparing with previous product reference...

Exporting results to the directory ../../RESULTS/DAILY/_110202/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE...

Polarization: H
Reference product: ASA_MS__0PNPK20110201_185000_000000163099_00099_46665_0423.N1
Test product: ASA_MS__0PNPK20110202_181317_000000163099_00113_46679_0424.N1

H
H
../../../../RESULTS/DAILY/_110202/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TGH_20110202_181317-20110201_185000.png
../../../../RESULTS/DAILY/_110202/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TPH_20110202_181317-20110201_185000.png
../../../../RESULTS/DAILY/_110202/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RGH_20110202_181317-20110201_185000.png
../../../../RESULTS/DAILY/_110202/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RPH_20110202_181317-20110201_185000.png

Polarization: V
Reference product: ASA_MS__0PNPDE20110201_203014_000000163099_00100_46666_0131.N1
Test product: ASA_MS__0PNPK20110202_195331_000000163099_00114_46680_0425.N1

V
V
../../../../RESULTS/DAILY/_110202/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TGV_20110202_195331-20110201_203014.png
../../../../RESULTS/DAILY/_110202/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TPV_20110202_195331-20110201_203014.png
../../../../RESULTS/DAILY/_110202/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RGV_20110202_195331-20110201_203014.png
../../../../RESULTS/DAILY/_110202/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RPV_20110202_195331-20110201_203014.png

MODULE_STEPPING ANALYSIS completed
#####

CALIBRATION PULSES ANALYSIS

Creating directory ./RESULTS/DAILY/_110202/CALIBRATION_PULSES...

ALL ROWS Analysis will be performed from 2011-02-02 00:00:00 to 2011-02-02 23:59:59

Analysing products WVS IS2 V/V
Writing image ../../RESULTS/DAILY/_110202//CALIBRATION_PULSES/Calibration_pulses_all_rows_WVS_IS2_VV.png...
Analysing products GM1 SS3 H/H
Writing image ../../RESULTS/DAILY/_110202//CALIBRATION_PULSES/Calibration_pulses_all_rows_GM1_SS3_HH.png...

TEMPORAL EVOLUTION Analysis will be performed from 2011-02-02 00:00:00 to 2011-02-02 23:59:59

Analysing products WVS IS2 V/V
Getting calibration pulses data for WVS IS2 V/V from 2011-02-02 00:00:00 to 2011-02-02 23:59:59. Rows: 1/5/9/13/17/21/25/29



Writing file ./RESULTS/DAILY/_110202/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2011-02-02_1.dat...
Writing ../../RESULTS/DAILY/_110202//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_1.png...
Writing ../../RESULTS/DAILY/_110202//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_1.png...

Getting calibration pulses data for WVS IS2 V/V from 2011-02-02 00:00:00 to 2011-02-02 23:59:59. Rows: 2/6/10/14/18/22/26/30
Writing file ./RESULTS/DAILY/_110202/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2011-02-02_2.dat...
Writing ../../RESULTS/DAILY/_110202//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_2.png...
Writing ../../RESULTS/DAILY/_110202//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_2.png...

Getting calibration pulses data for WVS IS2 V/V from 2011-02-02 00:00:00 to 2011-02-02 23:59:59. Rows: 3/7/11/15/19/23/27/31
Writing file ./RESULTS/DAILY/_110202/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2011-02-02_3.dat...
Writing ../../RESULTS/DAILY/_110202//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_3.png...
Writing ../../RESULTS/DAILY/_110202//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_3.png...

Getting calibration pulses data for WVS IS2 V/V from 2011-02-02 00:00:00 to 2011-02-02 23:59:59. Rows: 4/8/12/16/20/24/28/32
Writing file ./RESULTS/DAILY/_110202/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2011-02-02_4.dat...
Writing ../../RESULTS/DAILY/_110202//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_4.png...
Writing ../../RESULTS/DAILY/_110202//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_4.png...

Analysing products GM1 SS3 H/H
Getting calibration pulses data for GM1 SS3 H/H from 2011-02-02 00:00:00 to 2011-02-02 23:59:59. Rows: 1/5/9/13/17/21/25/29
Writing file ./RESULTS/DAILY/_110202/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2011-02-02_1.dat...
Writing ../../RESULTS/DAILY/_110202//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_1.png...
Writing ../../RESULTS/DAILY/_110202//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_1.png...

Getting calibration pulses data for GM1 SS3 H/H from 2011-02-02 00:00:00 to 2011-02-02 23:59:59. Rows: 2/6/10/14/18/22/26/30
Writing file ./RESULTS/DAILY/_110202/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2011-02-02_2.dat...
Writing ../../RESULTS/DAILY/_110202//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_2.png...
Writing ../../RESULTS/DAILY/_110202//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_2.png...

Getting calibration pulses data for GM1 SS3 H/H from 2011-02-02 00:00:00 to 2011-02-02 23:59:59. Rows: 3/7/11/15/19/23/27/31
Writing file ./RESULTS/DAILY/_110202/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2011-02-02_3.dat...
Writing ../../RESULTS/DAILY/_110202//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_3.png...
Writing ../../RESULTS/DAILY/_110202//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_3.png...

Getting calibration pulses data for GM1 SS3 H/H from 2011-02-02 00:00:00 to 2011-02-02 23:59:59. Rows: 4/8/12/16/20/24/28/32
Writing file ./RESULTS/DAILY/_110202/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2011-02-02_4.dat...
Writing ../../RESULTS/DAILY/_110202//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_4.png...
Writing ../../RESULTS/DAILY/_110202//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_4.png...

CALIBRATION PULSES ANALYSIS completed
#####

DOPPLER ANALYSIS

Creating directory ./RESULTS/DAILY/_110202/DOPPLER...

DOPPLER ANX Analysis will be performed from 2011-02-02 00:00:00 to 2011-02-02 23:59:59

Analysing products WVS IS2 V/V
Getting doppler data for WVS IS2 V/V from 2011-02-02 00:00:00 to 2011-02-02 23:59:59...
Writing file ./RESULTS/DAILY/_110202/DOPPLER/Doppler_data_WVS_IS2_VV_2011-02-02.dat...
Running IDL program...

Writing file ../../RESULTS/DAILY/_110202/DOPPLER/DOPPLER_ANX_WVS_IS2_VV.png...

Analysing products GM1 SS1 H/H
Getting doppler data for GM1 SS1 H/H from 2011-02-02 00:00:00 to 2011-02-02 23:59:59...
Writing file ./RESULTS/DAILY/_110202/DOPPLER/Doppler_data_GM1_SS1_HH_2011-02-02.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/_110202/DOPPLER/DOPPLER_ANX_GM1_SS1_HH.png...

DOPPLER JUMPS Analysis will be performed on WSM products from 2011-02-02 00:00:00 to 2011-02-02 23:59:59

Analysing by default products WSM
Getting doppler jumps data for WSM from 2011-02-02 00:00:00 to 2011-02-02 23:59:59...
Writing file ./RESULTS/DAILY/_110202/DOPPLER/Doppler_Jumps_data_WSM_2011-02-02.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/_110202/DOPPLER/DOPPLER_JUMPS_ANX_WSM.png...
Writing file ../../RESULTS/DAILY/_110202/DOPPLER/DOPPLER_JUMPS_Date_WSM.png...

DOPPLER MAP Analysis will be performed from 2011-02-02 00:00:00 to 2011-02-02 23:59:59

Analysing products WVS IS2 V/V
Loading predicted doppler values....
Phase: descending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -61.919682 Hz
Writing file ../../RESULTS/DAILY/_110202//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_WVS_IS2_VV_desc.jpg...
Writing file ../../RESULTS/DAILY/_110202//DOPPLER/DOPPLER_Absolute_WVS_IS2_VV_desc.jpg...

Loading predicted doppler values....
Phase: ascending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -63.845991 Hz
Writing file ../../RESULTS/DAILY/_110202//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_WVS_IS2_VV_asc.jpg...
Writing file ../../RESULTS/DAILY/_110202//DOPPLER/DOPPLER_Absolute_WVS_IS2_VV_asc.jpg...

Analysing products GM1 SS1 H/H
Loading predicted doppler values....
Phase: descending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -50.687364 Hz
Writing file ../../RESULTS/DAILY/_110202//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_GM1_SS1_HH_desc.jpg...
Writing file ../../RESULTS/DAILY/_110202//DOPPLER/DOPPLER_Absolute_GM1_SS1_HH_desc.jpg...

Loading predicted doppler values....
Phase: ascending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -54.007083 Hz
Writing file ../../RESULTS/DAILY/_110202//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_GM1_SS1_HH_asc.jpg...
Writing file ../../RESULTS/DAILY/_110202//DOPPLER/DOPPLER_Absolute_GM1_SS1_HH_asc.jpg...

DOPPLER ANALYSIS completed

#####

CHIRP ANALYSIS

#####

Creating directory ./RESULTS/DAILY/_110202/CHIRP...

CHIRP Analysis will be performed from 2011-02-02 00:00:00 to 2011-02-02 23:59:59

Analysing products WSM SS1 H/H

Getting ScaleFactor data for WSM SS1 H/H from 2011-02-02 00:00:00 to 2011-02-02 23:59:59...

Writing file ./RESULTS/DAILY/_110202/CHIRP/ScaleFactor_data_WSM_SS1_HH_2011-02-02.dat...

Running IDL program...

Writing file ../../RESULTS/DAILY/_110202/CHIRP/ScaleFactor_ANX_WSM_SS1_HH.png...

Writing file ../../RESULTS/DAILY/_110202/CHIRP/ScaleFactor_DATE_WSM_SS1_HH.png...

Analysing products WSM SS1 V/V

Getting ScaleFactor data for WSM SS1 V/V from 2011-02-02 00:00:00 to 2011-02-02 23:59:59...

Writing file ./RESULTS/DAILY/_110202/CHIRP/ScaleFactor_data_WSM_SS1_VV_2011-02-02.dat...

Running IDL program...

Writing file ../../RESULTS/DAILY/_110202/CHIRP/ScaleFactor_ANX_WSM_SS1_VV.png...

Writing file ../../RESULTS/DAILY/_110202/CHIRP/ScaleFactor_DATE_WSM_SS1_VV.png...

CHIRP ANALYSIS completed

#####

RAW DATA ANALYSIS

#####

Analysis will be performed from 2011-02-02 00:00:00 to 2011-02-02 23:59:59

Results will be exported to the directory: ./RESULTS/DAILY/_110202/RAW_DATA

Creating directory ./RESULTS/DAILY/_110202/RAW_DATA...

Getting raw data for WVS from 2011-02-02 00:00:00 to 2011-02-02 23:59:59...

Writing file ./RESULTS/DAILY/_110202/RAW_DATA/Raw_data_WVS_2011-02-02.dat...

Running IDL program to create graphs...

Creating image ../../RESULTS/DAILY/_110202/RAW_DATA/Raw_data_WVS_input_mean.png...

Creating image ../../RESULTS/DAILY/_110202/RAW_DATA/Raw_data_WVS_input_stdev.png...

Creating image ../../RESULTS/DAILY/_110202/RAW_DATA/Raw_data_WVS_gain_imbalance.png...

Getting raw data for IMM from 2011-02-02 00:00:00 to 2011-02-02 23:59:59...

Writing file ./RESULTS/DAILY/_110202/RAW_DATA/Raw_data_IMM_2011-02-02.dat...

Running IDL program to create graphs...

Creating image ../../RESULTS/DAILY/_110202/RAW_DATA/Raw_data_IMM_input_mean.png...

Creating image ../../RESULTS/DAILY/_110202/RAW_DATA/Raw_data_IMM_input_stdev.png...

Creating image ../../RESULTS/DAILY/_110202/RAW_DATA/Raw_data_IMM_gain_imbalance.png...

RAW DATA ANALYSIS completed

#####

TELEMETRY ANALYSIS

Analysis will be performed from 2011-02-02 00:00:00 to 2011-02-02 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_110202/TELEMETRY

Creating directory ./RESULTS/DAILY/_110202/TELEMETRY...

Looking for gaps and missing lines in WVS products...

Checking 29 products from PDE...
Checking 25 products from PDK...

Looking for gaps and missing lines in GM1 products...

Checking 23 products from PDE...
Checking 43 products from PDK...

Looking for gaps and missing lines in APM products...

Checking 3 products from PDE...
No products from PDK...

Looking for gaps and missing lines in IMM products...

Checking 16 products from PDE...
No products from PDK...

Looking for gaps and missing lines in WSM products...

Checking 31 products from PDE...
Checking 17 products from PDK...

Creating graph of missing lines and gaps...

Creating image: ./RESULTS/DAILY/_110202/TELEMETRY/TELEMETRY_Missing_lines.png...
Creating image: ./RESULTS/DAILY/_110202/TELEMETRY/TELEMETRY_Gaps.png...

TELEMETRY ANALYSIS completed

#####

HTML REPORT generation

#####

Building file ./RESULTS/DAILY/_110202/asarReport.html...

Building DATA SUMMARY section...
Building AUXILIARY FILES ANALYSIS section...
Building MODULE STEPPING ANALYSIS section...
Building CALIBRATION PULSES ANALYSIS section...
Building DOPPLER ANALYSIS section...
Building CHIRP ANALYSIS section...
Building RAW DATA ANALYSIS section...
Building TELEMETRY ANALYSIS section...

HTML REPORT generation completed

#####



Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
ASA_APM_1PNPDE20110202_142021_000000443099_00111_46677_6377.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20110202_143835_000000413099_00111_46677_6380.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20110202_161102_000000423099_00112_46678_6382.N1	OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_GM1_1PNPDE20110202_004842_000006283099_00103_46669_6208.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110202_011259_000006283099_00103_46669_6206.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110202_013508_000006163099_00103_46669_6211.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110202_015511_000006713099_00103_46669_6224.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110202_021603_000009433099_00104_46670_6227.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110202_023427_000004833099_00104_46670_6223.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110202_025244_000001813099_00104_46670_6238.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110202_031243_000007793099_00104_46670_6247.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110202_032951_000001753099_00104_46670_6246.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110202_034040_000002053099_00104_46670_6252.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110202_034648_000001023099_00105_46671_6253.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110202_035223_000011783099_00105_46671_6250.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110202_041417_000003803099_00105_46671_6261.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110202_045257_000007793099_00105_46671_6269.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110202_053200_000017583099_00106_46672_6278.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110202_204537_000000963099_00115_46681_6391.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110202_205256_000004533099_00115_46681_6400.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110202_213518_000005673099_00115_46681_6397.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110202_220816_000006283099_00116_46682_6411.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110202_222830_000000783099_00116_46682_6410.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110202_223228_000003923099_00116_46682_6414.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110202_231810_000003563099_00116_46682_6428.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110202_063311_000007793099_00106_46672_5448.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110202_072209_000003863099_00107_46673_5449.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110202_073028_000001753099_00107_46673_5451.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110202_073216_000001753099_00107_46673_5477.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110202_073844_000002113099_00107_46673_5478.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110202_075134_000005373099_00107_46673_5480.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110202_080315_000000783099_00107_46673_5479.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110202_081325_000007793099_00107_46673_5482.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110202_090253_000002893099_00108_46674_5485.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110202_092044_000000663099_00108_46674_5504.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110202_092242_000000723099_00108_46674_5505.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110202_092623_000003503099_00108_46674_5506.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110202_095339_000007793099_00108_46674_5508.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110202_104037_000004713099_00109_46675_5510.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110202_105444_000001573099_00109_46675_5546.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110202_110834_000001813099_00109_46675_5548.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110202_113646_000006043099_00109_46675_5550.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110202_121850_000005493099_00110_46676_5552.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110202_121850_000005493099_00110_46676_5554.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110202_125551_000005433099_00110_46676_5578.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110202_130502_000001083099_00110_46676_5580.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110202_131407_000007793099_00110_46676_5583.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110202_133509_000004103099_00110_46676_5582.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110202_134304_000004893099_00110_46676_5586.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110202_135306_000001443099_00111_46677_5585.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110202_135714_000006283099_00111_46677_5587.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110202_141331_000002053099_00111_46677_5597.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110202_143239_000002653099_00111_46677_5600.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110202_145421_000007793099_00111_46677_5602.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110202_152328_000013533099_00111_46677_5604.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110202_155611_000007133099_00112_46678_5641.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110202_163435_000007793099_00112_46678_5643.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110202_170803_000010813099_00113_46679_5645.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110202_170803_000010813099_00113_46679_5646.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110202_173602_000005253099_00113_46679_5667.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110202_181449_000007793099_00113_46679_5670.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110202_185013_000007133099_00114_46680_5672.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110202_190046_000000783099_00114_46680_5693.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110202_190450_000000963099_00114_46680_5694.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110202_191326_000003203099_00114_46680_5695.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110202_195935_000002893099_00114_46680_5697.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110202_202006_000009613099_00114_46680_5698.N1					OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
ASA_IMM_1PNPDE20110202_010353_000000623099_00103_46669_6213.N1		OK	OK	OK
ASA_IMM_1PNPDE20110202_024230_000005003099_00104_46670_6221.N1		OK	OK	OK
ASA_IMM_1PNPDE20110202_033245_000001123099_00104_46670_6243.N1		OK	OK	OK
ASA_IMM_1PNPDE20110202_042035_000004703099_00105_46671_6244.N1		OK	OK	OK
ASA_IMM_1PNPDE20110202_042928_000001723099_00105_46671_6245.N1		OK	OK	OK
ASA_IMM_1PNPDE20110202_060115_000003543099_00106_46672_6266.N1		OK	OK	OK
ASA_IMM_1PNPDE20110202_060743_000001783099_00106_46672_6267.N1		OK	OK	OK
ASA_IMM_1PNPDE20110202_073513_000002003099_00107_46673_6297.N1		OK	OK	OK
ASA_IMM_1PNPDE20110202_074213_000000383099_00107_46673_6298.N1		OK	OK	OK
ASA_IMM_1PNPDE20110202_092154_000000373099_00108_46674_6328.N1		OK	OK	OK
ASA_IMM_1PNPDE20110202_143706_000000793099_00111_46677_6379.N1		OK	OK	OK
ASA_IMM_1PNPDE20110202_174447_000001663099_00113_46679_6385.N1		OK	OK	OK
ASA_IMM_1PNPDE20110202_191847_000001223099_00114_46680_6388.N1		OK	OK	OK
ASA_IMM_1PNPDE20110202_201906_000000513099_00114_46680_6390.N1		OK	OK	OK
ASA_IMM_1PNPDE20110202_230616_000000373099_00116_46682_6417.N1		OK	OK	OK
ASA_IMM_1PNPDE20110202_230616_000000373099_00116_46682_6418.N1		OK	OK	OK


Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WSM_1PNPDE20110202_000148_000001533099_00102_46668_6180.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110202_003908_000005693099_00103_46669_6204.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110202_012951_000003123099_00103_46669_6203.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110202_021023_000001903099_00104_46670_6228.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110202_023149_000001533099_00104_46670_6226.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110202_025102_000000923099_00104_46670_6230.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110202_041205_000001283099_00105_46671_6242.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110202_061834_000002393099_00106_46672_6270.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110202_074526_000003673099_00107_46673_6299.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110202_080032_000001593099_00107_46673_6300.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110202_091428_000003733099_00108_46674_6327.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110202_093214_000001283099_00108_46674_6329.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110202_104831_000001773099_00109_46675_6354.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110202_105806_000000923099_00109_46675_6357.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110202_110646_000000923099_00109_46675_6358.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110202_113232_000002453099_00109_46675_6359.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110202_141702_000001593099_00111_46677_6376.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110202_142712_000001353099_00111_46677_6378.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110202_155029_000003363099_00112_46678_6381.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110202_172947_000002513099_00113_46679_6383.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110202_173429_000000923099_00113_46679_6384.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110202_190848_000002753099_00114_46680_6386.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110202_195603_000001903099_00114_46680_6389.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110202_200430_000002393099_00114_46680_6387.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110202_204720_000003303099_00115_46681_6396.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110202_212641_000001903099_00115_46681_6405.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110202_214446_000003123099_00115_46681_6392.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110202_222955_000001533099_00116_46682_6427.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110202_223905_000000923099_00116_46682_6419.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110202_231526_000001593099_00116_46682_6429.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110202_232410_000003123099_00116_46682_6416.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20110202_072035_000000923099_00107_46673_5446.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20110202_072840_000001043099_00107_46673_5447.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20110202_090747_000001103099_00108_46674_5494.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20110202_090939_000000923099_00108_46674_5483.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20110202_091135_000005383099_00108_46674_5489.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20110202_105109_000002143099_00109_46675_5518.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20110202_105806_000000923099_00109_46675_5517.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20110202_105950_000001103099_00109_46675_5519.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20110202_122801_000005933099_00110_46676_5563.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20110202_135538_000000923099_00111_46677_5594.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20110202_140800_000003123099_00111_46677_5593.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20110202_154606_000003303099_00112_46678_5621.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20110202_172611_000003303099_00113_46679_5654.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20110202_190214_000001533099_00114_46680_5678.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20110202_190635_000002083099_00114_46680_5679.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20110202_204101_000002693099_00115_46681_5706.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20110202_222455_000002083099_00116_46682_5726.N1					OK	OK	OK	OK





Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WVS_1PNPDE20110202_000506_000004503099_00102_46668_6190.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110202_001151_000015893099_00102_46668_6210.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110202_010135_000001043099_00103_46669_6209.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110202_010507_000004213099_00103_46669_6207.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110202_012404_000003003099_00103_46669_6205.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110202_014529_000003293099_00103_46669_6212.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110202_015014_000002553099_00103_46669_6229.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110202_020621_000001943099_00104_46670_6225.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110202_021340_000001053099_00104_46670_6222.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110202_025545_000004643099_00104_46670_6235.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110202_030315_000005253099_00104_46670_6248.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110202_032543_000002103099_00104_46670_6249.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110202_033459_000002993099_00104_46670_6251.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110202_034405_000001193099_00104_46670_6254.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110202_034835_000001793099_00105_46671_6255.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110202_043227_000007793099_00105_46671_6260.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110202_044456_000004353099_00105_46671_6268.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110202_050557_000015143099_00105_46671_6272.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110202_061047_000003893099_00106_46672_6271.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110202_062231_000002253099_00106_46672_6273.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110202_210032_000015293099_00115_46681_6401.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110202_212953_000002853099_00115_46681_6399.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110202_215003_000002843099_00115_46681_6398.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110202_215348_000008243099_00115_46681_6409.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110202_221855_000003003099_00116_46682_6412.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110202_224036_000014393099_00116_46682_6413.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110202_230659_000004653099_00116_46682_6415.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110202_232921_000004043099_00116_46682_6426.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110202_233506_000016193099_00116_46682_6435.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110202_062601_000003903099_00106_46672_5445.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110202_064611_000020243099_00106_46672_5450.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110202_080441_000004803099_00107_46673_5481.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110202_082625_000021443099_00107_46673_5484.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110202_093423_000011093099_00108_46674_5507.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110202_100639_000019943099_00108_46674_5509.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110202_110141_000002243099_00109_46675_5547.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110202_111135_000012143099_00109_46675_5549.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110202_114653_000018743099_00109_46675_5553.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110202_114653_000018743099_00109_46675_5555.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110202_123753_000010343099_00110_46676_5579.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110202_130655_000003903099_00110_46676_5581.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110202_132707_000004353099_00110_46676_5584.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110202_142147_000002843099_00111_46677_5598.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110202_142937_000001343099_00111_46677_5599.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110202_144017_000007953099_00111_46677_5601.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110202_150721_000009303099_00111_46677_5603.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110202_160805_000001343099_00112_46678_5640.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110202_161151_000013193099_00112_46678_5642.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110202_164735_000011843099_00112_46678_5644.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110202_174739_000014993099_00113_46679_5669.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110202_182749_000001353099_00113_46679_5668.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110202_183214_000010343099_00113_46679_5671.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110202_192105_000019043099_00114_46680_5696.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110202_200829_000005853099_00114_46680_5699.N1					OK	OK	OK	OK

Calibration pulses for GM1 SS3 H/H




Calibration pulses for GM1 SS3 H/H







rows: _ 2 _ 6 _ 10 _ 14 _ 18 _ 22 _ 26 _ 30

Calibration pulses for GM1 SS3 H/H




Calibration pulses for GM1 SS3 H/H




rows: _ 4 _ 8 _ 12 _ 16 _ 20 _ 24 _ 28 _ 32


Calibration pulses for WVS IS2 V/V







Calibration pulses for WVS IS2 V/V




Calibration pulses for WVS IS2 V/V






Calibration pulses for WVS IS2 V/V







rows: 4 8 12 16 20 24 28 32



















02-Feb
rows: _ 3 _ 7 _ 11 _ 15 _ 19 _ 23 _ 27 _ 31















02-Feb
rows: _ 3 _ 7 _ 11 _ 15 _ 19 _ 23 _ 27 _ 31











Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_APM_1PNPDE20110202_142021_000000443099_00111_46677_6377.N1						IS3	H/H	99	46677	111	5.04
ASA_APM_1PNPDE20110202_143835_000000413099_00111_46677_6380.N1						IS4	V/H	99	46677	111	5.04
ASA_APM_1PNPDE20110202_161102_000000423099_00112_46678_6382.N1						IS4	V/H	99	46678	112	5.04

Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_GM1_1PNPDE20110201_235216_000005673099_00102_46668_6191.N1						SS1	H/H	99	46668	102	5.04
ASA_GM1_1PNPDE20110202_004842_000006283099_00103_46669_6208.N1						SS1	H/H	99	46669	103	5.04
ASA_GM1_1PNPDE20110202_011259_000006283099_00103_46669_6206.N1						SS1	H/H	99	46669	103	5.04
ASA_GM1_1PNPDE20110202_013508_000006163099_00103_46669_6211.N1						SS1	H/H	99	46669	103	5.04
ASA_GM1_1PNPDE20110202_015511_000006713099_00103_46669_6224.N1						SS1	H/H	99	46669	103	5.04
ASA_GM1_1PNPDE20110202_021603_000009433099_00104_46670_6227.N1						SS1	H/H	99	46670	104	5.04
ASA_GM1_1PNPDE20110202_023427_000004833099_00104_46670_6223.N1						SS1	H/H	99	46670	104	5.04
ASA_GM1_1PNPDE20110202_025244_000001813099_00104_46670_6238.N1						SS1	H/H	99	46670	104	5.04
ASA_GM1_1PNPDE20110202_031243_000007793099_00104_46670_6247.N1						SS1	H/H	99	46670	104	5.04
ASA_GM1_1PNPDE20110202_032951_000001753099_00104_46670_6246.N1						SS1	H/H	99	46670	104	5.04
ASA_GM1_1PNPDE20110202_034040_000002053099_00104_46670_6252.N1						SS1	H/H	99	46670	104	5.04
ASA_GM1_1PNPDE20110202_034648_000001023099_00105_46671_6253.N1						SS1	H/H	99	46671	105	5.04
ASA_GM1_1PNPDE20110202_035223_000011783099_00105_46671_6250.N1						SS1	H/H	99	46671	105	5.04
ASA_GM1_1PNPDE20110202_041417_000003803099_00105_46671_6261.N1						SS1	H/H	99	46671	105	5.04
ASA_GM1_1PNPDE20110202_045257_000007793099_00105_46671_6269.N1						SS1	H/H	99	46671	105	5.04
ASA_GM1_1PNPDE20110202_053200_000017583099_00106_46672_6278.N1						SS1	H/H	99	46672	106	5.04
ASA_GM1_1PNPDK20110202_063311_000007793099_00106_46672_5448.N1						SS1	H/H	99	46672	106	5.04
ASA_GM1_1PNPDK20110202_072209_000003863099_00107_46673_5449.N1						SS1	H/H	99	46673	107	5.04
ASA_GM1_1PNPDK20110202_073028_000001753099_00107_46673_5451.N1						SS1	H/H	99	46673	107	5.04
ASA_GM1_1PNPDK20110202_073216_000001753099_00107_46673_5477.N1						SS1	H/H	99	46673	107	5.04
ASA_GM1_1PNPDK20110202_073844_000002113099_00107_46673_5478.N1						SS1	H/H	99	46673	107	5.04
ASA_GM1_1PNPDK20110202_075134_000005373099_00107_46673_5480.N1						SS1	H/H	99	46673	107	5.04
ASA_GM1_1PNPDK20110202_080315_000000783099_00107_46673_5479.N1						SS1	H/H	99	46673	107	5.04
ASA_GM1_1PNPDK20110202_081325_000007793099_00107_46673_5482.N1						SS1	H/H	99	46673	107	5.04
ASA_GM1_1PNPDK20110202_090253_000002893099_00108_46674_5485.N1						SS1	H/H	99	46674	108	5.04
ASA_GM1_1PNPDK20110202_092044_000000663099_00108_46674_5504.N1						SS1	H/H	99	46674	108	5.04
ASA_GM1_1PNPDK20110202_092242_000000723099_00108_46674_5505.N1						SS1	H/H	99	46674	108	5.04
ASA_GM1_1PNPDK20110202_092623_000003503099_00108_46674_5506.N1						SS1	H/H	99	46674	108	5.04
ASA_GM1_1PNPDK20110202_095339_000007793099_00108_46674_5508.N1						SS1	H/H	99	46674	108	5.04
ASA_GM1_1PNPDK20110202_104037_000004713099_00109_46675_5510.N1						SS1	H/H	99	46675	109	5.04
ASA_GM1_1PNPDK20110202_105444_000001573099_00109_46675_5546.N1						SS1	H/H	99	46675	109	5.04
ASA_GM1_1PNPDK20110202_110834_000001813099_00109_46675_5548.N1						SS1	H/H	99	46675	109	5.04
ASA_GM1_1PNPDK20110202_113646_000006043099_00109_46675_5550.N1						SS1	H/H	99	46675	109	5.04
ASA_GM1_1PNPDK20110202_121850_000005493099_00110_46676_5552.N1						SS1	H/H	99	46676	110	5.04
ASA_GM1_1PNPDK20110202_121850_000005493099_00110_46676_5554.N1						SS1	H/H	99	46676	110	5.04
ASA_GM1_1PNPDK20110202_125551_000005433099_00110_46676_5578.N1						SS1	H/H	99	46676	110	5.04
ASA_GM1_1PNPDK20110202_130502_000001083099_00110_46676_5580.N1						SS1	H/H	99	46676	110	5.04
ASA_GM1_1PNPDK20110202_131407_000007793099_00110_46676_5583.N1						SS1	H/H	99	46676	110	5.04
ASA_GM1_1PNPDK20110202_133509_000004103099_00110_46676_5582.N1						SS1	H/H	99	46676	110	5.04
ASA_GM1_1PNPDK20110202_134304_000004893099_00110_46676_5586.N1						SS1	H/H	99	46676	110	5.04
ASA_GM1_1PNPDK20110202_135306_000001443099_00111_46677_5585.N1						SS1	H/H	99	46677	111	5.04
ASA_GM1_1PNPDK20110202_135714_000006283099_00111_46677_5587.N1						SS1	H/H	99	46677	111	5.04
ASA_GM1_1PNPDK20110202_141331_000002053099_00111_46677_5597.N1						SS1	H/H	99	46677	111	5.04
ASA_GM1_1PNPDK20110202_143239_000002653099_00111_46677_5600.N1						SS1	H/H	99	46677	111	5.04
ASA_GM1_1PNPDK20110202_145421_000007793099_00111_46677_5602.N1						SS1	H/H	99	46677	111	5.04
ASA_GM1_1PNPDK20110202_152328_000013533099_00111_46677_5604.N1						SS1	H/H	99	46677	111	5.04
ASA_GM1_1PNPDK20110202_155611_000007133099_00112_46678_5641.N1						SS1	H/H	99	46678	112	5.04
ASA_GM1_1PNPDK20110202_163435_000007793099_00112_46678_5643.N1						SS1	H/H	99	46678	112	5.04
ASA_GM1_1PNPDK20110202_170803_000010813099_00113_46679_5645.N1						SS1	H/H	99	46679	113	5.04
ASA_GM1_1PNPDK20110202_170803_000010813099_00113_46679_5646.N1						SS1	H/H	99	46679	113	5.04
ASA_GM1_1PNPDK20110202_173602_000005253099_00113_46679_5667.N1						SS1	H/H	99	46679	113	5.04
ASA_GM1_1PNPDK20110202_181449_000007793099_00113_46679_5670.N1						SS1	H/H	99	46679	113	5.04
ASA_GM1_1PNPDK20110202_185013_000007133099_00114_46680_5672.N1						SS1	H/H	99	46680	114	5.04
ASA_GM1_1PNPDK20110202_190046_000000783099_00114_46680_5693.N1						SS1	H/H	99	46680	114	5.04
ASA_GM1_1PNPDK20110202_190450_000000963099_00114_46680_5694.N1						SS1	H/H	99	46680	114	5.04
ASA_GM1_1PNPDK20110202_191326_000003203099_00114_46680_5695.N1						SS1	H/H	99	46680	114	5.04
ASA_GM1_1PNPDK20110202_195935_000002893099_00114_46680_5697.N1						SS1	H/H	99	46680	114	5.04
ASA_GM1_1PNPDK20110202_202006_000009613099_00114_46680_5698.N1						SS1	H/H	99	46680	114	5.04
ASA_GM1_1PNPDK20110202_203855_000001203099_00115_46681_5700.N1						SS1	H/H	99	46681	115	5.04
ASA_GM1_1PNPDE20110202_204537_000000963099_00115_46681_6391.N1						SS1	H/H	99	46681	115	5.04
ASA_GM1_1PNPDE20110202_205256_000004533099_00115_46681_6400.N1						SS1	H/H	99	46681	115	5.04
ASA_GM1_1PNPDE20110202_213518_000005673099_00115_46681_6397.N1						SS1	H/H	99	46681	115	5.04
ASA_GM1_1PNPDE20110202_220816_000006283099_00116_46682_6411.N1						SS1	H/H	99	46682	116	5.04
ASA_GM1_1PNPDE20110202_222830_000000783099_00116_46682_6410.N1						SS1	H/H	99	46682	116	5.04
ASA_GM1_1PNPDE20110202_223228_000003923099_00116_46682_6414.N1						SS1	H/H	99	46682	116	5.04
ASA_GM1_1PNPDE20110202_231810_000003563099_00116_46682_6428.N1						SS1	H/H	99	46682	116	5.04

Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_IMM_1PNPDE20110202_010353_000000623099_00103_46669_6213.N1						IS6	H/H	99	46669	103	5.04
ASA_IMM_1PNPDE20110202_024230_000005003099_00104_46670_6221.N1						IS6	H/H	99	46670	104	5.04
ASA_IMM_1PNPDE20110202_033245_000001123099_00104_46670_6243.N1						IS6	H/H	99	46670	104	5.04
ASA_IMM_1PNPDE20110202_042035_000004703099_00105_46671_6244.N1						IS6	H/H	99	46671	105	5.04
ASA_IMM_1PNPDE20110202_042928_000001723099_00105_46671_6245.N1						IS6	H/H	99	46671	105	5.04
ASA_IMM_1PNPDE20110202_060115_000003543099_00106_46672_6266.N1						IS6	H/H	99	46672	106	5.04
ASA_IMM_1PNPDE20110202_060743_000001783099_00106_46672_6267.N1						IS6	H/H	99	46672	106	5.04
ASA_IMM_1PNPDE20110202_073513_000002003099_00107_46673_6297.N1						IS6	H/H	99	46673	107	5.04
ASA_IMM_1PNPDE20110202_074213_000000383099_00107_46673_6298.N1						IS4	V/V	99	46673	107	5.04
ASA_IMM_1PNPDE20110202_092154_000000373099_00108_46674_6328.N1						IS3	V/V	99	46674	108	5.04
ASA_IMM_1PNPDE20110202_143706_000000793099_00111_46677_6379.N1						IS1	H/H	99	46677	111	5.04
ASA_IMM_1PNPDE20110202_174447_000001663099_00113_46679_6385.N1						IS6	H/H	99	46679	113	5.04
ASA_IMM_1PNPDE20110202_191847_000001223099_00114_46680_6388.N1						IS6	H/H	99	46680	114	5.04
ASA_IMM_1PNPDE20110202_201906_000000513099_00114_46680_6390.N1						IS3	H/H	99	46680	114	5.04
ASA_IMM_1PNPDE20110202_230616_000000373099_00116_46682_6417.N1						IS7	H/H	99	46682	116	5.04
ASA_IMM_1PNPDE20110202_230616_000000373099_00116_46682_6418.N1						IS7	H/H	99	46682	116	5.04

Filename	Pol	Timestamp	count(Module)					
ASA_MS__0PNPDK20110202_181317_000000163099_00113_46679_0424.N1	H				2011-02-02	18:13:17	320	
ASA_MS__0PNPDK20110202_195331_000000163099_00114_46680_0425.N1	V				2011-02-02	19:53:31	320	

Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WSM_1PNPDE20110202_000148_000001533099_00102_46668_6180.N1						SS1	H/H	99	46668	102	5.04
ASA_WSM_1PNPDE20110202_003908_000005693099_00103_46669_6204.N1						SS1	H/H	99	46669	103	5.04
ASA_WSM_1PNPDE20110202_012951_000003123099_00103_46669_6203.N1						SS1	H/H	99	46669	103	5.04
ASA_WSM_1PNPDE20110202_021023_000001903099_00104_46670_6228.N1						SS1	V/V	99	46670	104	5.04
ASA_WSM_1PNPDE20110202_023149_000001533099_00104_46670_6226.N1						SS1	V/V	99	46670	104	5.04
ASA_WSM_1PNPDE20110202_025102_000000923099_00104_46670_6230.N1						SS1	H/H	99	46670	104	5.04
ASA_WSM_1PNPDE20110202_041205_000001283099_00105_46671_6242.N1						SS1	H/H	99	46671	105	5.04
ASA_WSM_1PNPDE20110202_061834_000002393099_00106_46672_6270.N1						SS1	H/H	99	46672	106	5.04
ASA_WSM_1PNPDK20110202_072035_000000923099_00107_46673_5446.N1						SS1	H/H	99	46673	107	5.04
ASA_WSM_1PNPDK20110202_072840_000001043099_00107_46673_5447.N1						SS1	H/H	99	46673	107	5.04
ASA_WSM_1PNPDE20110202_074526_000003673099_00107_46673_6299.N1						SS1	H/H	99	46673	107	5.04
ASA_WSM_1PNPDE20110202_080032_000001593099_00107_46673_6300.N1						SS1	H/H	99	46673	107	5.04
ASA_WSM_1PNPDK20110202_090747_000001103099_00108_46674_5494.N1						SS1	H/H	99	46674	108	5.04
ASA_WSM_1PNPDK20110202_090939_000000923099_00108_46674_5483.N1						SS1	H/H	99	46674	108	5.04
ASA_WSM_1PNPDK20110202_091135_000005383099_00108_46674_5489.N1						SS1	H/H	99	46674	108	5.04
ASA_WSM_1PNPDE20110202_091428_000003733099_00108_46674_6327.N1						SS1	H/H	99	46674	108	5.04
ASA_WSM_1PNPDE20110202_093214_000001283099_00108_46674_6329.N1						SS1	H/H	99	46674	108	5.04
ASA_WSM_1PNPDE20110202_104831_000001773099_00109_46675_6354.N1						SS1	H/H	99	46675	109	5.04
ASA_WSM_1PNPDK20110202_105109_000002143099_00109_46675_5518.N1						SS1	H/H	99	46675	109	5.04
ASA_WSM_1PNPDK20110202_105806_000000923099_00109_46675_5517.N1						SS1	V/V	99	46675	109	5.04
ASA_WSM_1PNPDE20110202_105806_000000923099_00109_46675_6357.N1						SS1	V/V	99	46675	109	5.04
ASA_WSM_1PNPDK20110202_105950_000001103099_00109_46675_5519.N1						SS1	H/H	99	46675	109	5.04
ASA_WSM_1PNPDE20110202_110646_000000923099_00109_46675_6358.N1						SS1	V/V	99	46675	109	5.04
ASA_WSM_1PNPDE20110202_113232_000002453099_00109_46675_6359.N1						SS1	H/H	99	46675	109	5.04
ASA_WSM_1PNPDK20110202_122801_000005933099_00110_46676_5563.N1						SS1	H/H	99	46676	110	5.04
ASA_WSM_1PNPDK20110202_135538_000000923099_00111_46677_5594.N1						SS1	V/V	99	46677	111	5.04
ASA_WSM_1PNPDK20110202_140800_000003123099_00111_46677_5593.N1						SS1	H/H	99	46677	111	5.04
ASA_WSM_1PNPDE20110202_141702_000001593099_00111_46677_6376.N1						SS1	H/H	99	46677	111	5.04
ASA_WSM_1PNPDE20110202_142712_000001353099_00111_46677_6378.N1						SS1	V/V	99	46677	111	5.04
ASA_WSM_1PNPDK20110202_154606_000003303099_00112_46678_5621.N1						SS1	H/H	99	46678	112	5.04
ASA_WSM_1PNPDE20110202_155029_000003363099_00112_46678_6381.N1						SS1	H/H	99	46678	112	5.04
ASA_WSM_1PNPDK20110202_172611_000003303099_00113_46679_5654.N1						SS1	H/H	99	46679	113	5.04
ASA_WSM_1PNPDE20110202_172947_000002513099_00113_46679_6383.N1						SS1	H/H	99	46679	113	5.04
ASA_WSM_1PNPDE20110202_173429_000000923099_00113_46679_6384.N1						SS1	H/H	99	46679	113	5.04
ASA_WSM_1PNPDK20110202_190214_000001533099_00114_46680_5678.N1						SS1	H/H	99	46680	114	5.04
ASA_WSM_1PNPDK20110202_190635_000002083099_00114_46680_5679.N1						SS1	H/H	99	46680	114	5.04
ASA_WSM_1PNPDE20110202_190848_000002753099_00114_46680_6386.N1						SS1	H/H	99	46680	114	5.04
ASA_WSM_1PNPDE20110202_195603_000001903099_00114_46680_6389.N1						SS1	H/H	99	46680	114	5.04
ASA_WSM_1PNPDE20110202_200430_000002393099_00114_46680_6387.N1						SS1	H/H	99	46680	114	5.04
ASA_WSM_1PNPDK20110202_204101_000002693099_00115_46681_5706.N1						SS1	H/H	99	46681	115	5.04
ASA_WSM_1PNPDE20110202_204720_000003303099_00115_46681_6396.N1						SS1	H/H	99	46681	115	5.04
ASA_WSM_1PNPDE20110202_212641_000001903099_00115_46681_6405.N1						SS1	H/H	99	46681	115	5.04
ASA_WSM_1PNPDE20110202_214446_000003123099_00115_46681_6392.N1						SS1	H/H	99	46681	115	5.04
ASA_WSM_1PNPDK20110202_222455_000002083099_00116_46682_5726.N1						SS1	H/H	99	46682	116	5.04
ASA_WSM_1PNPDE20110202_222955_000001533099_00116_46682_6427.N1						SS1	H/H	99	46682	116	5.04
ASA_WSM_1PNPDE20110202_223905_000000923099_00116_46682_6419.N1						SS1	H/H	99	46682	116	5.04
ASA_WSM_1PNPDE20110202_231526_000001593099_00116_46682_6429.N1						SS1	H/H	99	46682	116	5.04
ASA_WSM_1PNPDE20110202_232410_000003123099_00116_46682_6416.N1						SS1	H/H	99	46682	116	5.04

Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WVS_1PNPDE20110202_000506_000004503099_00102_46668_6190.N1						IS2	V/V	99	46668	102	5.04
ASA_WVS_1PNPDE20110202_001151_000015893099_00102_46668_6210.N1						IS2	V/V	99	46668	102	5.04
ASA_WVS_1PNPDE20110202_010135_000001043099_00103_46669_6209.N1						IS2	V/V	99	46669	103	5.04
ASA_WVS_1PNPDE20110202_010507_000004213099_00103_46669_6207.N1						IS2	V/V	99	46669	103	5.04
ASA_WVS_1PNPDE20110202_012404_000003003099_00103_46669_6205.N1						IS2	V/V	99	46669	103	5.04
ASA_WVS_1PNPDE20110202_014529_000003293099_00103_46669_6212.N1						IS2	V/V	99	46669	103	5.04
ASA_WVS_1PNPDE20110202_015014_000002553099_00103_46669_6229.N1						IS2	V/V	99	46669	103	5.04
ASA_WVS_1PNPDE20110202_014529_000003293099_00103_46669_6212.N1						IS1	V/V	99	46669	103	5.04
ASA_WVS_1PNPDE20110202_020621_000001943099_00104_46670_6225.N1						IS2	V/V	99	46670	104	5.04
ASA_WVS_1PNPDE20110202_021340_000001053099_00104_46670_6222.N1						IS2	V/V	99	46670	104	5.04
ASA_WVS_1PNPDE20110202_025545_000004643099_00104_46670_6235.N1						IS2	V/V	99	46670	104	5.04
ASA_WVS_1PNPDE20110202_030315_000005253099_00104_46670_6248.N1						IS2	V/V	99	46670	104	5.04
ASA_WVS_1PNPDE20110202_032543_000002103099_00104_46670_6249.N1						IS2	V/V	99	46670	104	5.04
ASA_WVS_1PNPDE20110202_033459_000002993099_00104_46670_6251.N1						IS2	V/V	99	46670	104	5.04
ASA_WVS_1PNPDE20110202_034405_000001193099_00104_46670_6254.N1						IS2	V/V	99	46670	104	5.04
ASA_WVS_1PNPDE20110202_034835_000001793099_00105_46671_6255.N1						IS2	V/V	99	46671	105	5.04
ASA_WVS_1PNPDE20110202_043227_000007793099_00105_46671_6260.N1						IS2	V/V	99	46671	105	5.04
ASA_WVS_1PNPDE20110202_044456_000004353099_00105_46671_6268.N1						IS2	V/V	99	46671	105	5.04
ASA_WVS_1PNPDE20110202_043227_000007793099_00105_46671_6260.N1						IS1	V/V	99	46671	105	5.04
ASA_WVS_1PNPDE20110202_050557_000015143099_00105_46671_6272.N1						IS2	V/V	99	46671	105	5.04
ASA_WVS_1PNPDE20110202_061047_000003893099_00106_46672_6271.N1						IS2	V/V	99	46672	106	5.04
ASA_WVS_1PNPDE20110202_062231_000002253099_00106_46672_6273.N1						IS2	V/V	99	46672	106	5.04
ASA_WVS_1PNPDK20110202_062601_000003903099_00106_46672_5445.N1						IS2	V/V	99	46672	106	5.04
ASA_WVS_1PNPDE20110202_062231_000002253099_00106_46672_6273.N1						IS1	V/V	99	46672	106	5.04
ASA_WVS_1PNPDK20110202_064611_000020243099_00106_46672_5450.N1						IS2	V/V	99	46672	106	5.04
ASA_WVS_1PNPDK20110202_080441_000004803099_00107_46673_5481.N1						IS2	V/V	99	46673	107	5.04
ASA_WVS_1PNPDK20110202_082625_000021443099_00107_46673_5484.N1						IS2	V/V	99	46673	107	5.04
ASA_WVS_1PNPDK20110202_093423_000011093099_00108_46674_5507.N1						IS2	V/V	99	46674	108	5.04
ASA_WVS_1PNPDK20110202_100639_000019943099_00108_46674_5509.N1						IS2	V/V	99	46674	108	5.04
ASA_WVS_1PNPDK20110202_110141_000002243099_00109_46675_5547.N1						IS2	V/V	99	46675	109	5.04
ASA_WVS_1PNPDK20110202_111135_000012143099_00109_46675_5549.N1						IS2	V/V	99	46675	109	5.04
ASA_WVS_1PNPDK20110202_114653_000018743099_00109_46675_5555.N1						IS2	V/V	99	46675	109	5.04
ASA_WVS_1PNPDK20110202_114653_000018743099_00109_46675_5553.N1						IS2	V/V	99	46675	109	5.04
ASA_WVS_1PNPDK20110202_123753_000010343099_00110_46676_5579.N1						IS2	V/V	99	46676	110	5.04
ASA_WVS_1PNPDK20110202_130655_000003903099_00110_46676_5581.N1						IS2	V/V	99	46676	110	5.04
ASA_WVS_1PNPDK20110202_132707_000004353099_00110_46676_5584.N1						IS2	V/V	99	46676	110	5.04
ASA_WVS_1PNPDK20110202_142147_000002843099_00111_46677_5598.N1						IS2	V/V	99	46677	111	5.04
ASA_WVS_1PNPDK20110202_142937_000001343099_00111_46677_5599.N1						IS2	V/V	99	46677	111	5.04
ASA_WVS_1PNPDK20110202_144017_000007953099_00111_46677_5601.N1						IS2	V/V	99	46677	111	5.04
ASA_WVS_1PNPDK20110202_150721_000009303099_00111_46677_5603.N1						IS2	V/V	99	46677	111	5.04
ASA_WVS_1PNPDK20110202_160805_000001343099_00112_46678_5640.N1						IS2	V/V	99	46678	112	5.04
ASA_WVS_1PNPDK20110202_161151_000013193099_00112_46678_5642.N1						IS2	V/V	99	46678	112	5.04
ASA_WVS_1PNPDK20110202_164735_000011843099_00112_46678_5644.N1						IS2	V/V	99	46678	112	5.04
ASA_WVS_1PNPDK20110202_174739_000014993099_00113_46679_5669.N1						IS2	V/V	99	46679	113	5.04
ASA_WVS_1PNPDK20110202_182749_000001353099_00113_46679_5668.N1						IS2	V/V	99	46679	113	5.04
ASA_WVS_1PNPDK20110202_183214_000010343099_00113_46679_5671.N1						IS2	V/V	99	46679	113	5.04
ASA_WVS_1PNPDK20110202_192105_000019043099_00114_46680_5696.N1						IS2	V/V	99	46680	114	5.04
ASA_WVS_1PNPDK20110202_200829_000005853099_00114_46680_5699.N1						IS2	V/V	99	46680	114	5.04
ASA_WVS_1PNPDE20110202_210032_000015293099_00115_46681_6401.N1						IS2	V/V	99	46681	115	5.04
ASA_WVS_1PNPDE20110202_212953_000002853099_00115_46681_6399.N1						IS2	V/V	99	46681	115	5.04
ASA_WVS_1PNPDE20110202_215003_000002843099_00115_46681_6398.N1						IS2	V/V	99	46681	115	5.04
ASA_WVS_1PNPDE20110202_215348_000008243099_00115_46681_6409.N1						IS2	V/V	99	46681	115	5.04
ASA_WVS_1PNPDE20110202_215003_000002843099_00115_46681_6398.N1						IS1	V/V	99	46681	115	5.04
ASA_WVS_1PNPDE20110202_221855_000003003099_00116_46682_6412.N1						IS2	V/V	99	46682	116	5.04
ASA_WVS_1PNPDE20110202_224036_000014393099_00116_46682_6413.N1						IS2	V/V	99	46682	116	5.04
ASA_WVS_1PNPDE20110202_230659_000004653099_00116_46682_6415.N1						IS2	V/V	99	46682	116	5.04
ASA_WVS_1PNPDE20110202_232921_000004043099_00116_46682_6426.N1						IS2	V/V	99	46682	116	5.04
ASA_WVS_1PNPDE20110202_233506_000016193099_00116_46682_6435.N1						IS2	V/V	99	46682	116	5.04
ASA_WVS_1PNPDE20110202_232921_000004043099_00116_46682_6426.N1						IS1	V/V	99	46682	116	5.04

