



Analysis from 14-DEC-2011 00:00:00 to 14-DEC-2011 23:59:59. Page generated on 15-DEC-2011 06:31:43.
View log file: ASAR_Daily_Report_20111215_0631.log. For any anomalies please contact emma.hatton@vegaspaces.com, kajal.haria@vegaspaces.com.

This report is automatically generated every day, every 2 hours. No comments are provided on the results.

SUMMARY

1. DATA SUMMARY
 - 1.1 Summary tables
 - 1.2 Lists of products used
2. AUXILIARY FILES ANALYSIS
 - 2.1 IECF operational ADFs list
 - 2.2 Products with wrong ADFs
3. MODULE STEPPING PRODUCTS ANALYSIS
 - 3.1 V/V polarisation
 - 3.2 H/H polarisation
4. CALIBRATION PULSES ANALYSIS
 - 4.1 Analysis for WVS IS2 V/V
 - 4.1.1 Temporal Evolution Analysis for WVS IS2 V/V
 - 4.1.2 All Rows Analysis for WVS IS2 V/V
 - 4.2 Analysis for GM1 SS3 H/H
 - 4.2.1 Temporal Evolution Analysis for GM1 SS3 H/H
 - 4.2.2 All Rows Analysis for GM1 SS3 H/H
5. DOPPLER ANALYSIS
 - 5.1 Analysis for WVS IS2 V/V
 - 5.1.1 Doppler MAP Analysis for WVS IS2 V/V
 - 5.1.2 Doppler ANX Analysis for WVS IS2 V/V
 - 5.2 Analysis for GM1 SS1 H/H
 - 5.2.1 Doppler MAP Analysis for GM1 SS1 H/H
 - 5.2.2 Doppler ANX Analysis for GM1 SS1 H/H
 - 5.3 Doppler JUMPS Analysis for WSM
6. CHIRP ANALYSIS
 - 6.1 Analysis for WSM SS1 H/H
 - 6.1.1 ScaleFactor
 - 6.2 Analysis for WSM SS1 V/V
 - 6.2.1 ScaleFactor
7. RAW DATA ANALYSIS
 - 7.1 Analysis for WVS
 - 7.2 Analysis for IMM
8. TELEMETRY ANALYSIS
 - 8.1 Number of Missing Lines
 - 8.2 Number of Gaps

1 - DATA SUMMARY

1.1 - Summary tables

[[BACK TO MENU](#)]

WVS				GM1				APM				IMM				WSM				MS			
Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Time	Pol	Modules
PDE	IS1	V/V	3	PDE	WS	H/H	41	PDE	IS1	V/H	1	PDE	IS2	V/V	1	PDE	WS	H/H	34	PDK	2011-12-14 09:06:14	H	320
PDE	IS2	V/V	26	PDK	WS	H/H	42	PDE	IS4	H/H	2	PDE	IS3	H/H	1	PDE	WS	V/V	9	PDK	2011-12-14 10:46:28	V	320
PDK	IS2	V/V	25					PDK	IS6	V/H	1	PDE	IS5	H/H	1	PDK	WS	H/H	12				
												PDE	IS6	H/H	3	PDK	WS	V/V	2				
												PDE	IS6	V/V	2								

1.2 - Lists of products used

[[BACK TO MENU](#)]

[TXT] [XLS] [List_WVS_products_used](#)
 [TXT] [XLS] [List_GM1_products_used](#)
 [TXT] [XLS] [List_APM_products_used](#)
 [TXT] [XLS] [List_IMM_products_used](#)
 [TXT] [XLS] [List_WSM_products_used](#)
 [TXT] [XLS] [List_MS_products_used](#)

2 - AUXILIARY FILES ANALYSIS

2.1 - IECF operational ADFs list

[[BACK TO MENU](#)]

ADFs disseminated for ASAR
ASA_CON_AXVIEC20110526_075001_20101027_215740_20141231_000000
ASA_INS_AXVIEC20110124_114858_20101228_112000_20141231_235959
ASA_XCH_AXVIEC20101222_143057_20020301_000000_20141231_000000
ASA_XCA_AXVIEC20110526_075734_20101027_215740_20141231_000000

2.2 - Products with wrong ADFs

[[BACK TO MENU](#)]

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
WVS	0	0	0	0
GM1	0	0	0	0
APM	0	0	0	0
IMM	0	0	0	0
WSM	0	0	0	0

[TXT] [XLS] [Check_ADFs_WVS](#)
 [TXT] [XLS] [Check_ADFs_GM1](#)
 [TXT] [XLS] [Check_ADFs_APM](#)
 [TXT] [XLS] [Check_ADFs_IMM](#)
 [TXT] [XLS] [Check_ADFs_WSM](#)

3 - MODULE STEPPING PRODUCTS ANALYSIS

SECOND FIXED REFERENCE

Pre-launch reference (2001-02-09)


Reference: 2001-02-09 14:08:23 V RxGain
 Test : 2011-12-14 10:46:28 V



PREVIOUS PRODUCT REFERENCE

Previous product in the same polarisation


Reference: 2011-12-13 11:23:13 V RxGain
 Test : 2011-12-14 10:46:28 V







Reference: 2001-02-09 14:08:23 V RxPhase
 Test : 2011-12-14 10:46:28 V



Reference: 2011-12-13 11:23:13 V RxPhase
 Test : 2011-12-14 10:46:28 V















3.2 - H/H polarisation

[[BACK TO MENU](#)]

SECOND FIXED REFERENCE	PREVIOUS PRODUCT REFERENCE
Pre-launch reference (2001-02-09)	Previous product in the same polarisation





4 - CALIBRATION PULSES ANALYSIS

4.1 - Analysis for WVS IS2 V/V


4.1.1 - Temporal Evolution Analysis for WVS IS2 V/V

[BACK TO MENU]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Calibration pulses for WVS IS2 V/V




Transmit power (P1 - P1a) for WVS IS2 V/V



4.1.2 - All Rows Analysis for WVS IS2 V/V

[[BACK TO MENU](#)]





4.2 - Analysis for GM1 SS3 H/H


4.2.1 - Temporal Evolution Analysis for GM1 SS3 H/H

[BACK TO MENU]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Calibration pulses for GM1 SS3 H/H




Transmit power (P1 - P1a) for GM1 SS3 H/H



4.2.2 - All Rows Analysis for GM1 SS3 H/H

[[BACK TO MENU](#)]






5 - DOPPLER ANALYSIS

5.1 - Analysis for WVS IS2 V/V

5.1.1 - Doppler MAP Analysis for WVS IS2 V/V

[[BACK TO MENU](#)]






5.1.2 - Doppler ANX Analysis for WVS IS2 V/V

[[BACK TO MENU](#)]







5.2 - Analysis for GM1 SS1 H/H

5.2.1 - Doppler MAP Analysis for GM1 SS1 H/H

[[BACK TO MENU](#)]






5.2.2 - Doppler ANX Analysis for GM1 SS1 H/H

[[BACK TO MENU](#)]






5.3 - Doppler JUMPS Analysis for WSM

[[BACK TO MENU](#)]

--	--





6 - CHIRP ANALYSIS

6.1 - Analysis for WSM SS1 H/H

6.1.1 - ScaleFactor

[[BACK TO MENU](#)]







6.2 - Analysis for WSM SS1 V/V

6.2.1 - ScaleFactor

[[BACK TO MENU](#)]






7 - RAW DATA ANALYSIS

7.1 - Analysis for WVS

[[BACK TO MENU](#)]

--	--	--




Channel	Statistics	DSS-B
MEAN I	mean	0.000645179
	stdev	1.20728e-07
MEAN Q	mean	0.000507083
	stdev	2.05519e-07
Channel	Statistics	DSS-B
STDEV I	mean	0.151329
	stdev	0.00145480
STDEV Q	mean	0.151918
	stdev	0.00148553

7.2 - Analysis for IMM

[[BACK TO MENU](#)]







8 - TELEMETRY ANALYSIS

Processing Center	Product	Gaps	Missing lines
PDE	ASA_WVS_1PNPDE20111214_034417_000007493109_00320_51196_9314.N1	1	0
PDE	ASA_WVS_1PNPDE20111214_071715_000002103109_00322_51198_9410.N1	1	0
PDE	ASA_WVS_1PNPDE20111214_210409_000000153109_00330_51206_9535.N1	1	0
PDK	ASA_WVS_1PNPDK20111214_125908_000004913109_00325_51201_4653.N1	0	8
PDE	ASA_WSM_1PNPDE20111214_044204_000001533109_00321_51197_9353.N1	0	122

8.1 - Number of Missing lines


[[BACK TO MENU](#)]





8.2 - Number of Gaps

[\[BACK TO MENU \]](#)



ASAR DAILY REPORT for 111214
#####

MODE: DAILY
ANALYSIS: ALL
DATE: 2011-12-14 00:00:00

Analysis will be performed from 2011-12-14 00:00:00 to 2011-12-14 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_111214/

DATA SUMMARY

Summary will be performed from 2011-12-14 00:00:00 to 2011-12-14 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_111214/DATA_SUMMARY

Creating directory ./RESULTS/DAILY/_111214/DATA_SUMMARY...
Writing file ./RESULTS/DAILY/_111214/DATA_SUMMARY/Data_summary.html...

Getting WVS products list from 2011-12-14 00:00:00 to 2011-12-14 23:59:59...
Writing file ./RESULTS/DAILY/_111214/DATA_SUMMARY/List_WVS_products_used.xls...
Writing file ./RESULTS/DAILY/_111214/DATA_SUMMARY/List_WVS_products_used.txt...

Getting GM1 products list from 2011-12-14 00:00:00 to 2011-12-14 23:59:59...
Writing file ./RESULTS/DAILY/_111214/DATA_SUMMARY/List_GM1_products_used.xls...
Writing file ./RESULTS/DAILY/_111214/DATA_SUMMARY/List_GM1_products_used.txt...

Getting APM products list from 2011-12-14 00:00:00 to 2011-12-14 23:59:59...
Writing file ./RESULTS/DAILY/_111214/DATA_SUMMARY/List_APM_products_used.xls...
Writing file ./RESULTS/DAILY/_111214/DATA_SUMMARY/List_APM_products_used.txt...

Getting IMM products list from 2011-12-14 00:00:00 to 2011-12-14 23:59:59...
Writing file ./RESULTS/DAILY/_111214/DATA_SUMMARY/List_IMM_products_used.xls...
Writing file ./RESULTS/DAILY/_111214/DATA_SUMMARY/List_IMM_products_used.txt...

Getting WSM products list from 2011-12-14 00:00:00 to 2011-12-14 23:59:59...
Writing file ./RESULTS/DAILY/_111214/DATA_SUMMARY/List_WSM_products_used.xls...
Writing file ./RESULTS/DAILY/_111214/DATA_SUMMARY/List_WSM_products_used.txt...

Getting MS products list from 2011-12-14 00:00:00 to 2011-12-14 23:59:59...
Writing file ./RESULTS/DAILY/_111214/DATA_SUMMARY/List_MS_products_used.xls...
Writing file ./RESULTS/DAILY/_111214/DATA_SUMMARY/List_MS_products_used.txt...

DATA SUMMARY completed
#####

AUXILIARY FILES ANALYSIS

Analysis will be performed from 2011-12-14 00:00:00 to 2011-12-14 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_111214/AUXILIARY

Creating directory ./RESULTS/DAILY/_111214/AUXILIARY...

Looking for the IECF operational ADFs list...



ADF filter 20111214*current_3_IECF_ADFs.txt
 Found list 20111214_030001_current_3_IECF_ADFs.txt...
 Extracting ADFs...

ASA_CON_AXVIEC20110526_075001_20101027_215740_20141231_000000
 ASA_INS_AXVIEC20110124_114858_20101228_112000_20141231_235959
 ASA_XCH_AXVIEC20101222_143057_20020301_000000_20141231_000000
 ASA_XCA_AXVIEC20110526_075734_20101027_215740_20141231_000000

Writing file ./RESULTS/DAILY/_111214/AUXILIARY/ASAR_ADFs_IECF_List3.html...
 Writing file ./RESULTS/DAILY/_111214/AUXILIARY/Auxiliary_files_summary.html...

Analysing WVS products...

Writing file ./RESULTS/DAILY/_111214/AUXILIARY/Check_ADFs_WVS.xls...
 Writing file ./RESULTS/DAILY/_111214/AUXILIARY/Check_ADFs_WVS.txt...

ASA_WVS_1PNPDE20111214_001336_000008693109_00318_51194_9270.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20111214_003050_00000603109_00318_51194_9274.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20111214_003726_000004203109_00318_51194_9276.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20111214_010205_000002843109_00318_51194_9277.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20111214_010605_000003153109_00318_51194_9302.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20111214_011738_000007643109_00318_51194_9310.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20111214_015749_000000743109_00319_51195_9312.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20111214_021120_000007953109_00319_51195_9323.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20111214_024122_000003153109_00319_51195_9319.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20111214_030133_000003293109_00320_51196_9316.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20111214_034417_000007493109_00320_51196_9314.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20111214_035631_000002703109_00320_51196_9355.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20111214_042351_000010493109_00320_51196_9359.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20111214_052332_000009893109_00321_51197_9360.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20111214_053947_000003153109_00321_51197_9396.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20111214_060150_000016943109_00321_51197_9405.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20111214_071715_000002103109_00322_51198_9410.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20111214_201450_000017093109_00330_51206_9534.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20111214_210409_000000153109_00330_51206_9535.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20111214_210409_000003753109_00330_51206_9551.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20111214_215414_000004653109_00331_51207_9550.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20111214_220418_000013793109_00331_51207_9554.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20111214_224517_000002693109_00331_51207_9555.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20111214_224902_000007643109_00331_51207_9572.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20111214_230821_000005693109_00332_51208_9580.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20111214_233629_000008843109_00332_51208_9576.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20111214_072030_000002853109_00322_51198_4558.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20111214_074204_000019493109_00322_51198_4561.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20111214_085444_000006453109_00323_51199_4584.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20111214_092209_000020243109_00323_51199_4589.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20111214_102816_000010493109_00324_51200_4626.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20111214_110223_000002703109_00324_51200_4627.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20111214_110936_000015443109_00324_51200_4629.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20111214_115958_000005993109_00325_51201_4647.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20111214_121720_000005253109_00325_51201_4649.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20111214_124245_000003303109_00325_51201_4652.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20111214_125908_000004913109_00325_51201_4653.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20111214_130938_000000443109_00326_51202_4656.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20111214_133447_000007493109_00326_51202_4680.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20111214_140503_000000753109_00326_51202_4682.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20111214_142252_000004053109_00326_51202_4683.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20111214_143429_000001043109_00326_51202_4687.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20111214_152117_000002693109_00327_51203_4708.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20111214_152744_000011243109_00327_51203_4711.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20111214_160305_000013043109_00327_51203_4713.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20111214_170517_000010643109_00328_51204_4729.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20111214_172516_000000903109_00328_51204_4731.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20111214_174345_000013643109_00328_51204_4735.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

```
ASA_WVS_1PNPDK20111214_183940_000016343109_00329_51205_4756.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20111214_192332_000005403109_00329_51205_4758.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20111214_193607_000001493109_00329_51205_4761.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```

Analysing GM1 products...

Writing file ./RESULTS/DAILY/_111214/AUXILIARY/Check_ADFs_GM1.xls...

Writing file ./RESULTS/DAILY/_111214/AUXILIARY/Check_ADFs_GM1.txt...

```
ASA_GM1_1PNPDE20111214_000424_000005493109_00318_51194_9272.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20111214_002856_000001083109_00318_51194_9271.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20111214_003227_000002953109_00318_51194_9275.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20111214_004505_000006833109_00318_51194_9278.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20111214_011205_000001813109_00318_51194_9303.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20111214_013101_000001873109_00319_51195_9305.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20111214_014044_000010213109_00319_51195_9308.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20111214_015941_000000783109_00319_51195_9307.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20111214_020424_000003263109_00319_51195_9313.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20111214_022519_000009613109_00319_51195_9324.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20111214_024716_000000903109_00319_51195_9322.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20111214_024856_000003983109_00319_51195_9321.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20111214_025659_000002713109_00319_51195_9320.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20111214_030742_000001083109_00320_51196_9318.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20111214_031719_000010753109_00320_51196_9317.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20111214_033920_000002953109_00320_51196_9315.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20111214_040532_000005313109_00320_51196_9356.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20111214_042238_000000663109_00320_51196_9357.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20111214_044441_000005923109_00321_51197_9358.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20111214_045923_000010393109_00321_51197_9361.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20111214_054549_000004593109_00321_51197_9395.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20111214_060007_000000963109_00321_51197_9400.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20111214_063639_000005373109_00322_51198_9399.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20111214_064957_000003383109_00322_51198_9412.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20111214_065929_000003383109_00322_51198_9409.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20111214_070559_000001203109_00322_51198_9408.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20111214_071007_000000723109_00322_51198_9406.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20111214_071239_000002713109_00322_51198_9411.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20111214_200855_000002593109_00330_51206_9532.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20111214_204842_000007133109_00330_51206_9536.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20111214_211106_000004343109_00330_51206_9547.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20111214_212057_000006163109_00331_51207_9548.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20111214_213229_000001573109_00331_51207_9552.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20111214_214641_000003023109_00331_51207_9553.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20111214_222807_000006953109_00331_51207_9557.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20111214_230229_000003503109_00332_51208_9573.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20111214_232103_000001573109_00332_51208_9574.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20111214_233247_000001693109_00332_51208_9579.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20111214_235157_000001383109_00332_51208_9578.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20111214_235540_000003023109_00332_51208_9577.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20111214_072601_000006283109_00322_51198_4796.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20111214_074037_000000783109_00322_51198_4560.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20111214_081513_000007613109_00323_51199_4562.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20111214_082641_000001813109_00323_51199_4578.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20111214_084113_000008103109_00323_51199_4583.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20111214_090733_000004653109_00323_51199_4586.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20111214_095632_000005553109_00324_51200_4590.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20111214_100943_000000783109_00324_51200_4623.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20111214_101303_000000723109_00324_51200_4624.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20111214_102150_000000723109_00324_51200_4625.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20111214_104748_000004833109_00324_51200_4628.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20111214_113601_000003803109_00325_51201_4630.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20111214_122643_000005553109_00325_51201_4648.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20111214_123957_000001633109_00325_51201_4650.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20111214_124900_000000723109_00325_51201_4651.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20111214_125021_000005253109_00325_51201_4654.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```


ASA_GM1_1PNPDK20111214_131111_000006283109_00326_51202_4655.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20111214_132558_000003923109_00326_51202_4677.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20111214_132600_000006063109_00326_51202_4657.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20111214_134754_000006833109_00326_51202_4678.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20111214_135922_000003383109_00326_51202_4681.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20111214_140657_000007433109_00326_51202_4685.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20111214_143019_000002473109_00326_51202_4684.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20111214_143657_000002773109_00326_51202_4686.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20111214_144617_000008883109_00327_51203_4688.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20111214_151415_000001813109_00327_51203_4706.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20111214_151802_000001933109_00327_51203_4707.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20111214_152628_000006663109_00327_51203_4709.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20111214_154709_000003983109_00327_51203_4710.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20111214_155708_000001383109_00327_51203_4712.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20111214_162527_000008943109_00328_51204_4714.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20111214_165651_000005013109_00328_51204_4730.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20111214_172725_000006223109_00328_51204_4733.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20111214_180719_000003023109_00329_51205_4732.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20111214_181402_000003563109_00329_51205_4734.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20111214_181849_000000843109_00329_51205_4753.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20111214_182814_000002053109_00329_51205_4754.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20111214_183826_000006663109_00329_51205_4755.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20111214_190739_000006223109_00329_51205_4757.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20111214_193318_000001633109_00329_51205_4759.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20111214_193925_000005983109_00329_51205_4760.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20111214_195332_00000903109_00330_51206_4762.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

Analysing APM products...

Writing file ./RESULTS/DAILY/_111214/AUXILIARY/Check_ADFs_APM.xls...

Writing file ./RESULTS/DAILY/_111214/AUXILIARY/Check_ADFs_APM.txt...

ASA_APM_1PNPDE20111214_020105_000008843109_00319_51195_9306.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20111214_071123_00000573109_00322_51198_9393.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20111214_183440_00000423109_00329_51205_9524.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDK20111214_213504_00000433109_00331_51207_4783.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

Analysing IMM products...

Writing file ./RESULTS/DAILY/_111214/AUXILIARY/Check_ADFs_IMM.xls...

Writing file ./RESULTS/DAILY/_111214/AUXILIARY/Check_ADFs_IMM.txt...

ASA_IMM_1PNPDE20111214_020335_00000373109_00319_51195_9304.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20111214_025532_00000763109_00319_51195_9309.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20111214_033512_000002393109_00320_51196_9300.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20111214_065725_000001123109_00322_51198_9388.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20111214_070508_00000373109_00322_51198_9389.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20111214_070801_000001153109_00322_51198_9392.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20111214_110756_00000523109_00324_51200_9472.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20111214_233538_00000433109_00332_51208_9587.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

Analysing WSM products...

Writing file ./RESULTS/DAILY/_111214/AUXILIARY/Check_ADFs_WSM.xls...

Writing file ./RESULTS/DAILY/_111214/AUXILIARY/Check_ADFs_WSM.txt...

ASA_WSM_1PNPDE20111214_000014_000002453109_00318_51194_9267.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20111214_005633_000003303109_00318_51194_9268.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20111214_011509_000001223109_00318_51194_9285.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

ASA_WSM_1PNPDE20111214_013410_000003923109_00319_51195_9301.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20111214_020950_000000923109_00319_51195_9311.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20111214_041429_000003923109_00320_51196_9352.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20111214_044204_000001533109_00321_51197_9353.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20111214_051647_000004043109_00321_51197_9354.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20111214_055330_000001533109_00321_51197_9394.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20111214_055631_000002143109_00321_51197_9397.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20111214_063258_000002143109_00322_51198_9398.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20111214_065536_000000923109_00322_51198_9385.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20111214_082943_000004283109_00323_51199_9429.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20111214_083737_000002143109_00323_51199_9430.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20111214_100548_000002323109_00324_51200_9453.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20111214_102311_000002883109_00324_51200_9455.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20111214_105556_000003303109_00324_51200_9471.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20111214_115828_000000923109_00325_51201_9470.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20111214_121033_000003983109_00325_51201_9473.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20111214_133233_000001353109_00326_51202_9507.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20111214_141921_000002143109_00326_51202_9508.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20111214_150831_000001353109_00327_51203_9509.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20111214_155354_000001903109_00327_51203_9511.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20111214_155934_000002143109_00327_51203_9506.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20111214_164707_000001593109_00328_51204_9517.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20111214_172345_000000923109_00328_51204_9516.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20111214_173749_000003553109_00328_51204_9515.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20111214_181225_000000923109_00329_51205_9520.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20111214_182343_000002513109_00329_51205_9521.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20111214_191803_000003123109_00329_51205_9523.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20111214_194928_000000923109_00330_51206_9525.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20111214_195138_000001103109_00330_51206_9526.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20111214_200442_000002513109_00330_51206_9542.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20111214_201320_000000923109_00330_51206_9543.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20111214_204407_000002693109_00330_51206_9545.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20111214_210038_000002143109_00330_51206_9533.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20111214_211822_000001533109_00330_51206_9546.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20111214_214007_000003923109_00331_51207_9556.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20111214_215143_000001533109_00331_51207_9558.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20111214_220248_000000923109_00331_51207_9564.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20111214_223944_000003363109_00331_51207_9549.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20111214_232343_000001533109_00332_51208_9581.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20111214_232714_000003303109_00332_51208_9586.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20111214_064540_000002513109_00322_51198_4547.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20111214_073635_000002393109_00322_51198_4569.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20111214_091519_000003923109_00323_51199_4600.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20111214_114223_000006003109_00325_51201_4637.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20111214_123602_000002323109_00325_51201_4664.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20111214_130807_000000923109_00326_51202_4666.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20111214_132156_000002393109_00326_51202_4665.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20111214_150110_000003923109_00327_51203_4695.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20111214_164026_000004343109_00328_51204_4721.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20111214_182019_000002393109_00329_51205_4746.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20111214_195511_000003733109_00330_51206_4767.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20111214_200204_000001903109_00330_51206_4769.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20111214_213614_000001593109_00331_51207_4784.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20111214_231830_000001533109_00332_51208_4803.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

AUXILIARY FILES ANALYSIS completed

#####

MODULE STEPPING ANALYSIS

#####

Analysis will be performed from 2011-12-14 00:00:00 to 2011-12-14 23:59:59

Results will be exported to the directory: ./RESULTS/DAILY/_111214/MODULE_STEPPING

Creating directory ./RESULTS/DAILY/_111214/MODULE_STEPPING...


```
Creating directory ./RESULTS/DAILY/_111214/MODULE_STEPPING/FIRST_REFERENCE...
Creating directory ./RESULTS/DAILY/_111214/MODULE_STEPPING/SECOND_REFERENCE...
Creating directory ./RESULTS/DAILY/_111214/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE...
Deleting old files...
```

```
*****
*****
Creating images comparing with second reference...
```

```
Exporting results to the directory ../../RESULTS/DAILY/_111214/MODULE_STEPPING/SECOND_REFERENCE...
```

```
Polarization: H
Reference product: ASA_MS__0PNPDK20010209_135042_0000009A024_00180_11700_0052.N1
Test product: ASA_MS__0PNPDK20111214_090614_000000163109_00323_51199_0927.N1
  H
  H
../../RESULTS/DAILY/_111214/MODULE_STEPPING/SECOND_REFERENCE/TGH_20111214_090614-20010209_135042.png
../../RESULTS/DAILY/_111214/MODULE_STEPPING/SECOND_REFERENCE/TPH_20111214_090614-20010209_135042.png
../../RESULTS/DAILY/_111214/MODULE_STEPPING/SECOND_REFERENCE/RGH_20111214_090614-20010209_135042.png
../../RESULTS/DAILY/_111214/MODULE_STEPPING/SECOND_REFERENCE/RPH_20111214_090614-20010209_135042.png
```

```
Polarization: V
Reference product: ASA_MS__0PNPDK20010209_140823_0000009A024_00180_11700_0054.N1
Test product: ASA_MS__0PNPDK20111214_104628_000000163109_00324_51200_0928.N1
  V
  V
../../RESULTS/DAILY/_111214/MODULE_STEPPING/SECOND_REFERENCE/TGV_20111214_104628-20010209_140823.png
../../RESULTS/DAILY/_111214/MODULE_STEPPING/SECOND_REFERENCE/TPV_20111214_104628-20010209_140823.png
../../RESULTS/DAILY/_111214/MODULE_STEPPING/SECOND_REFERENCE/RGV_20111214_104628-20010209_140823.png
../../RESULTS/DAILY/_111214/MODULE_STEPPING/SECOND_REFERENCE/RPV_20111214_104628-20010209_140823.png
```

```
*****
*****
Creating images comparing with previous product reference...
```

```
Exporting results to the directory ../../RESULTS/DAILY/_111214/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE...
```

```
Polarization: H
Reference product: ASA_MS__0PNPDK20111213_094259_000000163109_00309_51185_0925.N1
Test product: ASA_MS__0PNPDK20111214_090614_000000163109_00323_51199_0927.N1
  H
  H
../../RESULTS/DAILY/_111214/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TGH_20111214_090614-20111213_094259.png
../../RESULTS/DAILY/_111214/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TPH_20111214_090614-20111213_094259.png
../../RESULTS/DAILY/_111214/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RGH_20111214_090614-20111213_094259.png
../../RESULTS/DAILY/_111214/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RPH_20111214_090614-20111213_094259.png
```

```
Polarization: V
Reference product: ASA_MS__0PNPDK20111213_112313_000000163109_00310_51186_0926.N1
Test product: ASA_MS__0PNPDK20111214_104628_000000163109_00324_51200_0928.N1
  V
  V
../../RESULTS/DAILY/_111214/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TGV_20111214_104628-20111213_112313.png
../../RESULTS/DAILY/_111214/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TPV_20111214_104628-20111213_112313.png
../../RESULTS/DAILY/_111214/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RGV_20111214_104628-20111213_112313.png
../../RESULTS/DAILY/_111214/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RPV_20111214_104628-20111213_112313.png
```

```
MODULE_STEPPING ANALYSIS completed
#####
```

```
CALIBRATION PULSES ANALYSIS
#####
Creating directory ./RESULTS/DAILY/_111214/CALIBRATION_PULSES...
```


ALL ROWS Analysis will be performed from 2011-12-14 00:00:00 to 2011-12-14 23:59:59

Analysing products WVS IS2 V/V

1 75233 7 75233
Writing image ../../RESULTS/DAILY/_111214//CALIBRATION_PULSES/Calibration_pulses_all_rows_WVS_IS2_VV.png...
Analysing products GM1 SS3 H/H
1 40417 7 40417
Writing image ../../RESULTS/DAILY/_111214//CALIBRATION_PULSES/Calibration_pulses_all_rows_GM1_SS3_HH.png...

TEMPORAL EVOLUTION Analysis will be performed from 2011-12-14 00:00:00 to 2011-12-14 23:59:59

Analysing products WVS IS2 V/V

Getting calibration pulses data for WVS IS2 V/V from 2011-12-14 00:00:00 to 2011-12-14 23:59:59. Rows: 1/5/9/13/17/21/25/29
Writing file ./RESULTS/DAILY/_111214/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2011-12-14_1.dat...
Writing ../../RESULTS/DAILY/_111214//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_1.png...
Writing ../../RESULTS/DAILY/_111214//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_1.png...

Getting calibration pulses data for WVS IS2 V/V from 2011-12-14 00:00:00 to 2011-12-14 23:59:59. Rows: 2/6/10/14/18/22/26/30
Writing file ./RESULTS/DAILY/_111214/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2011-12-14_2.dat...
Writing ../../RESULTS/DAILY/_111214//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_2.png...
Writing ../../RESULTS/DAILY/_111214//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_2.png...

Getting calibration pulses data for WVS IS2 V/V from 2011-12-14 00:00:00 to 2011-12-14 23:59:59. Rows: 3/7/11/15/19/23/27/31
Writing file ./RESULTS/DAILY/_111214/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2011-12-14_3.dat...
Writing ../../RESULTS/DAILY/_111214//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_3.png...
Writing ../../RESULTS/DAILY/_111214//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_3.png...

Getting calibration pulses data for WVS IS2 V/V from 2011-12-14 00:00:00 to 2011-12-14 23:59:59. Rows: 4/8/12/16/20/24/28/32
Writing file ./RESULTS/DAILY/_111214/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2011-12-14_4.dat...
Writing ../../RESULTS/DAILY/_111214//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_4.png...
Writing ../../RESULTS/DAILY/_111214//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_4.png...

Analysing products GM1 SS3 H/H

Getting calibration pulses data for GM1 SS3 H/H from 2011-12-14 00:00:00 to 2011-12-14 23:59:59. Rows: 1/5/9/13/17/21/25/29
Writing file ./RESULTS/DAILY/_111214/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2011-12-14_1.dat...
Writing ../../RESULTS/DAILY/_111214//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_1.png...
Writing ../../RESULTS/DAILY/_111214//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_1.png...

Getting calibration pulses data for GM1 SS3 H/H from 2011-12-14 00:00:00 to 2011-12-14 23:59:59. Rows: 2/6/10/14/18/22/26/30
Writing file ./RESULTS/DAILY/_111214/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2011-12-14_2.dat...
Writing ../../RESULTS/DAILY/_111214//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_2.png...
Writing ../../RESULTS/DAILY/_111214//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_2.png...

Getting calibration pulses data for GM1 SS3 H/H from 2011-12-14 00:00:00 to 2011-12-14 23:59:59. Rows: 3/7/11/15/19/23/27/31
Writing file ./RESULTS/DAILY/_111214/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2011-12-14_3.dat...
Writing ../../RESULTS/DAILY/_111214//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_3.png...
Writing ../../RESULTS/DAILY/_111214//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_3.png...

Getting calibration pulses data for GM1 SS3 H/H from 2011-12-14 00:00:00 to 2011-12-14 23:59:59. Rows: 4/8/12/16/20/24/28/32
Writing file ./RESULTS/DAILY/_111214/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2011-12-14_4.dat...
Writing ../../RESULTS/DAILY/_111214//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_4.png...
Writing ../../RESULTS/DAILY/_111214//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_4.png...

CALIBRATION PULSES ANALYSIS completed

#####

DOPPLER ANALYSIS

#####

Creating directory ./RESULTS/DAILY/_111214/DOPPLER...

DOPPLER ANX Analysis will be performed from 2011-12-14 00:00:00 to 2011-12-14 23:59:59

Analysing products WVS IS2 V/V

Getting doppler data for WVS IS2 V/V from 2011-12-14 00:00:00 to 2011-12-14 23:59:59...

Writing file ./RESULTS/DAILY/_111214/DOPPLER/Doppler_data_WVS_IS2_VV_2011-12-14.dat...

Running IDL program...

Writing file ../../RESULTS/DAILY/_111214/DOPPLER/DOPPLER_ANX_WVS_IS2_VV.png...

Analysing products GM1 SS1 H/H

Getting doppler data for GM1 SS1 H/H from 2011-12-14 00:00:00 to 2011-12-14 23:59:59...

Writing file ./RESULTS/DAILY/_111214/DOPPLER/Doppler_data_GM1_SS1_HH_2011-12-14.dat...

Running IDL program...

Writing file ../../RESULTS/DAILY/_111214/DOPPLER/DOPPLER_ANX_GM1_SS1_HH.png...

DOPPLER JUMPS Analysis will be performed on WSM products from 2011-12-14 00:00:00 to 2011-12-14 23:59:59

Analysing by default products WSM

Getting doppler jumps data for WSM from 2011-12-14 00:00:00 to 2011-12-14 23:59:59...

Writing file ./RESULTS/DAILY/_111214/DOPPLER/Doppler_Jumps_data_WSM_2011-12-14.dat...

Running IDL program...

Writing file ../../RESULTS/DAILY/_111214/DOPPLER/DOPPLER_JUMPS_ANX_WSM.png...

Writing file ../../RESULTS/DAILY/_111214/DOPPLER/DOPPLER_JUMPS_Date_WSM.png...

DOPPLER MAP Analysis will be performed from 2011-12-14 00:00:00 to 2011-12-14 23:59:59

Analysing products WVS IS2 V/V

1180

Loading predicted doppler values....

./PREDICTED_DOPPLER/doppler.WV_2

Phase: descending

Found data...

Computing mean error doppler estimated-predicted...

Mean error = -44.181851 Hz

Writing file ../../RESULTS/DAILY/_111214//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_WVS_IS2_VV_desc.jpg...

Writing file ../../RESULTS/DAILY/_111214//DOPPLER/DOPPLER_Absolute_WVS_IS2_VV_desc.jpg...

1173

Loading predicted doppler values....

./PREDICTED_DOPPLER/doppler.WV_2

Phase: ascending

Found data...

Computing mean error doppler estimated-predicted...

Mean error = -30.879350 Hz

Writing file ../../RESULTS/DAILY/_111214//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_WVS_IS2_VV_asc.jpg...

Writing file ../../RESULTS/DAILY/_111214//DOPPLER/DOPPLER_Absolute_WVS_IS2_VV_asc.jpg...

Analysing products GM1 SS1 H/H

2809

Loading predicted doppler values....
./PREDICTED_DOPPLER/doppler.GM_1
Phase: descending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -11.684686 Hz
Writing file ../../RESULTS/DAILY/_111214//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_GM1_SS1_HH_desc.jpg...
Writing file ../../RESULTS/DAILY/_111214//DOPPLER/DOPPLER_Absolute_GM1_SS1_HH_desc.jpg...

2323

Loading predicted doppler values....
./PREDICTED_DOPPLER/doppler.GM_1
Phase: ascending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -16.544395 Hz
Writing file ../../RESULTS/DAILY/_111214//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_GM1_SS1_HH_asc.jpg...
Writing file ../../RESULTS/DAILY/_111214//DOPPLER/DOPPLER_Absolute_GM1_SS1_HH_asc.jpg...

DOPPLER ANALYSIS completed

#####

CHIRP ANALYSIS

#####

Creating directory ./RESULTS/DAILY/_111214/CHIRP...

CHIRP Analysis will be performed from 2011-12-14 00:00:00 to 2011-12-14 23:59:59

Analysing products WSM SS1 H/H

Getting ScaleFactor data for WSM SS1 H/H from 2011-12-14 00:00:00 to 2011-12-14 23:59:59...
Writing file ./RESULTS/DAILY/_111214/CHIRP/ScaleFactor_data_WSM_SS1_HH_2011-12-14.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/_111214/CHIRP/ScaleFactor_ANX_WSM_SS1_HH.png...
Writing file ../../RESULTS/DAILY/_111214/CHIRP/ScaleFactor_DATE_WSM_SS1_HH.png...

Analysing products WSM SS1 V/V

Getting ScaleFactor data for WSM SS1 V/V from 2011-12-14 00:00:00 to 2011-12-14 23:59:59...
Writing file ./RESULTS/DAILY/_111214/CHIRP/ScaleFactor_data_WSM_SS1_VV_2011-12-14.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/_111214/CHIRP/ScaleFactor_ANX_WSM_SS1_VV.png...
Writing file ../../RESULTS/DAILY/_111214/CHIRP/ScaleFactor_DATE_WSM_SS1_VV.png...

CHIRP ANALYSIS completed

#####

RAW DATA ANALYSIS

#####

Analysis will be performed from 2011-12-14 00:00:00 to 2011-12-14 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_111214/RAW_DATA

Creating directory ./RESULTS/DAILY/_111214/RAW_DATA...

Getting raw data for WVS from 2011-12-14 00:00:00 to 2011-12-14 23:59:59...
Writing file ./RESULTS/DAILY/_111214/RAW_DATA/Raw_data_WVS_2011-12-14.dat...
Running IDL program to create graphs...

Creating image ../../RESULTS/DAILY/_111214/RAW_DATA/Raw_data_WVS_input_mean.png...
Creating image ../../RESULTS/DAILY/_111214/RAW_DATA/Raw_data_WVS_input_stdev.png...
Creating image ../../RESULTS/DAILY/_111214/RAW_DATA/Raw_data_WVS_gain_imbalance.png...

Getting raw data for IMM from 2011-12-14 00:00:00 to 2011-12-14 23:59:59...
Writing file ./RESULTS/DAILY/_111214/RAW_DATA/Raw_data_IMM_2011-12-14.dat...
Running IDL program to create graphs...

Creating image ../../RESULTS/DAILY/_111214/RAW_DATA/Raw_data_IMM_input_mean.png...
Creating image ../../RESULTS/DAILY/_111214/RAW_DATA/Raw_data_IMM_input_stdev.png...
Creating image ../../RESULTS/DAILY/_111214/RAW_DATA/Raw_data_IMM_gain_imbalance.png...

RAW DATA ANALYSIS completed

#####

TELEMETRY ANALYSIS

#####

Analysis will be performed from 2011-12-14 00:00:00 to 2011-12-14 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_111214/TELEMETRY

Creating directory ./RESULTS/DAILY/_111214/TELEMETRY...

Looking for gaps and missing lines in WVS products...

Checking 26 products from PDE...
Found product...ASA_WVS_1PNPDE20111214_034417_000007493109_00320_51196_9314.N1 / 1 gaps / 0 missing lines
Found product...ASA_WVS_1PNPDE20111214_071715_000002103109_00322_51198_9410.N1 / 1 gaps / 0 missing lines
Found product...ASA_WVS_1PNPDE20111214_210409_000000153109_00330_51206_9535.N1 / 1 gaps / 0 missing lines
Checking 25 products from PDK...
Found product...ASA_WVS_1PNPDK20111214_125908_000004913109_00325_51201_4653.N1 / 0 gaps / 8 missing lines

Looking for gaps and missing lines in GM1 products...

Checking 41 products from PDE...
Checking 42 products from PDK...

Looking for gaps and missing lines in APM products...

Checking 3 products from PDE...
Checking 1 products from PDK...

Looking for gaps and missing lines in IMM products...

Checking 8 products from PDE...
No products from PDK...

Looking for gaps and missing lines in WSM products...

Checking 43 products from PDE...
Found product...ASA_WSM_1PNPDE20111214_044204_000001533109_00321_51197_9353.N1 / 0 gaps / 122 missing lines
Checking 14 products from PDK...

Creating graph of missing lines and gaps...

Creating image: ./RESULTS/DAILY/_111214/TELEMETRY/TELEMETRY_Missing_lines.png...
Creating image: ./RESULTS/DAILY/_111214/TELEMETRY/TELEMETRY_Gaps.png...

TELEMETRY ANALYSIS completed
#####

HTML REPORT generation
#####

Building file ./RESULTS/DAILY/_111214/asarReport.html...
Building DATA SUMMARY section...
Building AUXILIARY FILES ANALYSIS section...
Building MODULE STEPPING ANALYSIS section...
Building CALIBRATION PULSES ANALYSIS section...
Building DOPPLER ANALYSIS section...
Building CHIRP ANALYSIS section...
Building RAW DATA ANALYSIS section...
Building TELEMETRY ANALYSIS section...

HTML REPORT generation completed
#####



Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
ASA_APM_1PNPDE20111214_020105_000000843109_00319_51195_9306.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20111214_071123_000000573109_00322_51198_9393.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20111214_183440_000000423109_00329_51205_9524.N1	OK	OK	OK	OK
ASA_APM_1PNPDK20111214_213504_000000433109_00331_51207_4783.N1	OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_GM1_1PNPDE20111214_000424_000005493109_00318_51194_9272.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20111214_002856_000001083109_00318_51194_9271.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20111214_003227_000002953109_00318_51194_9275.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20111214_004505_000006833109_00318_51194_9278.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20111214_011205_000001813109_00318_51194_9303.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20111214_013101_000001873109_00319_51195_9305.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20111214_014044_000010213109_00319_51195_9308.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20111214_015941_000000783109_00319_51195_9307.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20111214_020424_000003263109_00319_51195_9313.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20111214_022519_000009613109_00319_51195_9324.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20111214_024716_000000903109_00319_51195_9322.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20111214_024856_000003983109_00319_51195_9321.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20111214_025659_000002713109_00319_51195_9320.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20111214_030742_000001083109_00320_51196_9318.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20111214_031719_000010753109_00320_51196_9317.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20111214_033920_000002953109_00320_51196_9315.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20111214_040532_000005313109_00320_51196_9356.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20111214_042238_000000663109_00320_51196_9357.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20111214_044441_000005923109_00321_51197_9358.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20111214_045923_000010393109_00321_51197_9361.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20111214_054549_000004593109_00321_51197_9395.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20111214_060007_000000963109_00321_51197_9400.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20111214_063639_000005373109_00322_51198_9399.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20111214_064957_000003383109_00322_51198_9412.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20111214_065929_000003383109_00322_51198_9409.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20111214_070559_000001203109_00322_51198_9408.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20111214_071007_000000723109_00322_51198_9406.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20111214_071239_000002713109_00322_51198_9411.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20111214_200855_000002593109_00330_51206_9532.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20111214_204842_000007133109_00330_51206_9536.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20111214_211106_000004343109_00330_51206_9547.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20111214_212057_000006163109_00331_51207_9548.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20111214_213229_000001573109_00331_51207_9552.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20111214_214641_000003023109_00331_51207_9553.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20111214_222807_000006953109_00331_51207_9557.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20111214_230229_000003503109_00332_51208_9573.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20111214_232103_000001573109_00332_51208_9574.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20111214_233247_000001693109_00332_51208_9579.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20111214_235157_000001383109_00332_51208_9578.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20111214_235540_000003023109_00332_51208_9577.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20111214_072601_000006283109_00322_51198_4796.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20111214_074037_000000783109_00322_51198_4560.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20111214_081513_000007613109_00323_51199_4562.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20111214_082641_000001813109_00323_51199_4578.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20111214_084113_000008103109_00323_51199_4583.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20111214_090733_000004653109_00323_51199_4586.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20111214_095632_000005553109_00324_51200_4590.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20111214_100943_000000783109_00324_51200_4623.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20111214_101303_000000723109_00324_51200_4624.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20111214_102150_000000723109_00324_51200_4625.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20111214_104748_000004833109_00324_51200_4628.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20111214_113601_000003803109_00325_51201_4630.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20111214_122643_000005553109_00325_51201_4648.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20111214_123957_000001633109_00325_51201_4650.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20111214_124900_000000723109_00325_51201_4651.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20111214_125021_000005253109_00325_51201_4654.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20111214_131111_000006283109_00326_51202_4655.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20111214_132558_000003923109_00326_51202_4677.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20111214_132600_000000603109_00326_51202_4657.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20111214_134754_000006833109_00326_51202_4678.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20111214_135922_000003383109_00326_51202_4681.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20111214_140657_000007433109_00326_51202_4685.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20111214_143019_000002473109_00326_51202_4684.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20111214_143657_000002773109_00326_51202_4686.N1					OK	OK	OK	OK

ASA_GM1_1PNPDK20111214_144617_000008883109_00327_51203_4688.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20111214_151415_000001813109_00327_51203_4706.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20111214_151802_000001933109_00327_51203_4707.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20111214_152628_000000663109_00327_51203_4709.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20111214_154709_000003983109_00327_51203_4710.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20111214_155708_000001383109_00327_51203_4712.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20111214_162527_000008943109_00328_51204_4714.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20111214_165651_000005013109_00328_51204_4730.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20111214_172725_000006223109_00328_51204_4733.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20111214_180719_000003023109_00329_51205_4732.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20111214_181402_000003563109_00329_51205_4734.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20111214_181849_000000843109_00329_51205_4753.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20111214_182814_000002053109_00329_51205_4754.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20111214_183826_000000663109_00329_51205_4755.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20111214_190739_000006223109_00329_51205_4757.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20111214_193318_000001633109_00329_51205_4759.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20111214_193925_000005983109_00329_51205_4760.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20111214_195332_000000903109_00330_51206_4762.N1	OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
ASA_IMM_1PNPDE20111214_020335_000000373109_00319_51195_9304.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20111214_025532_000000763109_00319_51195_9309.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20111214_033512_000002393109_00320_51196_9300.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20111214_065725_000001123109_00322_51198_9388.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20111214_070508_000000373109_00322_51198_9389.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20111214_070801_000001153109_00322_51198_9392.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20111214_110756_000000523109_00324_51200_9472.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20111214_233538_000000433109_00332_51208_9587.N1	OK	OK	OK	OK





Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WSM_1PNPDE20111214_000014_000002453109_00318_51194_9267.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20111214_005633_000003303109_00318_51194_9268.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20111214_011509_000001223109_00318_51194_9285.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20111214_013410_000003923109_00319_51195_9301.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20111214_020950_000000923109_00319_51195_9311.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20111214_041429_000003923109_00320_51196_9352.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20111214_044204_000001533109_00321_51197_9353.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20111214_051647_000004043109_00321_51197_9354.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20111214_055330_000001533109_00321_51197_9394.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20111214_055631_000002143109_00321_51197_9397.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20111214_063258_000002143109_00322_51198_9398.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20111214_065536_000000923109_00322_51198_9385.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20111214_082943_000004283109_00323_51199_9429.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20111214_083737_000002143109_00323_51199_9430.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20111214_100548_000002323109_00324_51200_9453.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20111214_102311_000002883109_00324_51200_9455.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20111214_105556_000003303109_00324_51200_9471.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20111214_115828_000000923109_00325_51201_9470.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20111214_121033_000003983109_00325_51201_9473.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20111214_133233_000001353109_00326_51202_9507.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20111214_141921_000002143109_00326_51202_9508.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20111214_150831_000001353109_00327_51203_9509.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20111214_155354_000001903109_00327_51203_9511.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20111214_155934_000002143109_00327_51203_9506.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20111214_164707_000001593109_00328_51204_9517.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20111214_172345_000000923109_00328_51204_9516.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20111214_173749_000003553109_00328_51204_9515.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20111214_181225_000000923109_00329_51205_9520.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20111214_182343_000002513109_00329_51205_9521.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20111214_191803_000003123109_00329_51205_9523.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20111214_194928_000000923109_00330_51206_9525.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20111214_195138_000001103109_00330_51206_9526.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20111214_200442_000002513109_00330_51206_9542.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20111214_201320_000000923109_00330_51206_9543.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20111214_204407_000002693109_00330_51206_9545.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20111214_210038_000002143109_00330_51206_9533.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20111214_211822_000001533109_00330_51206_9546.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20111214_214007_000003923109_00331_51207_9556.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20111214_215143_000001533109_00331_51207_9558.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20111214_220248_000000923109_00331_51207_9564.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20111214_223944_000003363109_00331_51207_9549.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20111214_232343_000001533109_00332_51208_9581.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20111214_232714_000003303109_00332_51208_9586.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20111214_064540_000002513109_00322_51198_4547.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20111214_073635_000002393109_00322_51198_4569.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20111214_091519_000003923109_00323_51199_4600.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20111214_114223_000006003109_00325_51201_4637.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20111214_123602_000002323109_00325_51201_4664.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20111214_130807_000000923109_00326_51202_4666.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20111214_132156_000002393109_00326_51202_4665.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20111214_150110_000003923109_00327_51203_4695.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20111214_164026_000004343109_00328_51204_4721.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20111214_182019_000002393109_00329_51205_4746.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20111214_195511_000003733109_00330_51206_4767.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20111214_200204_000001903109_00330_51206_4769.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20111214_213614_000001593109_00331_51207_4784.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20111214_231830_000001533109_00332_51208_4803.N1					OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.


Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WVS_1PNPDE20111214_001336_000008693109_00318_51194_9270.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20111214_003050_00000603109_00318_51194_9274.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20111214_003726_000004203109_00318_51194_9276.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20111214_010205_000002843109_00318_51194_9277.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20111214_010605_000003153109_00318_51194_9302.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20111214_011738_000007643109_00318_51194_9310.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20111214_015749_000000743109_00319_51195_9312.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20111214_021120_000007953109_00319_51195_9323.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20111214_024122_000003153109_00319_51195_9319.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20111214_030133_000003293109_00320_51196_9316.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20111214_034417_000007493109_00320_51196_9314.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20111214_035631_000002703109_00320_51196_9355.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20111214_042351_000010493109_00320_51196_9359.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20111214_052332_000009893109_00321_51197_9360.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20111214_053947_000003153109_00321_51197_9396.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20111214_060150_000016943109_00321_51197_9405.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20111214_071715_000002103109_00322_51198_9410.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20111214_201450_000017093109_00330_51206_9534.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20111214_210409_000000153109_00330_51206_9535.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20111214_210409_000003753109_00330_51206_9551.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20111214_215414_000004653109_00331_51207_9550.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20111214_220418_000013793109_00331_51207_9554.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20111214_224517_000002693109_00331_51207_9555.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20111214_224902_000007643109_00331_51207_9572.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20111214_230821_000005693109_00332_51208_9580.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20111214_233629_000008843109_00332_51208_9576.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20111214_072030_000002853109_00322_51198_4558.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20111214_074204_000019493109_00322_51198_4561.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20111214_085444_000006453109_00323_51199_4584.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20111214_092209_000020243109_00323_51199_4589.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20111214_102816_000010493109_00324_51200_4626.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20111214_110223_000002703109_00324_51200_4627.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20111214_110936_000015443109_00324_51200_4629.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20111214_115958_000005993109_00325_51201_4647.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20111214_121720_000005253109_00325_51201_4649.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20111214_124245_000003303109_00325_51201_4652.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20111214_125908_000004913109_00325_51201_4653.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20111214_130938_000000443109_00326_51202_4656.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20111214_133447_000007493109_00326_51202_4680.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20111214_140503_000000753109_00326_51202_4682.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20111214_142252_000004053109_00326_51202_4683.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20111214_143429_000001043109_00326_51202_4687.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20111214_152117_000002693109_00327_51203_4708.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20111214_152744_000011243109_00327_51203_4711.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20111214_160305_000013043109_00327_51203_4713.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20111214_170517_000010643109_00328_51204_4729.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20111214_172516_000000903109_00328_51204_4731.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20111214_174345_000013643109_00328_51204_4735.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20111214_183940_000016343109_00329_51205_4756.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20111214_192332_000005403109_00329_51205_4758.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20111214_193607_000001493109_00329_51205_4761.N1					OK	OK	OK	OK

Calibration pulses for GM1 SS3 H/H




rows: _ 1 _ 13 _ 17 _ 21 _ 25 ^{14-Dec} _ 29 _ 5 _ 9


Calibration pulses for GM1 SS3 H/H




14-Dec



14-Dec




14-Dec




14-Dec

rows: _ 10 _ 14 _ 18 _ 2 _ 22 _ 26 _ 30 _ 6


Calibration pulses for GM1 SS3 H/H




Calibration pulses for GM1 SS3 H/H




Calibration pulses for WVS IS2 V/V




Calibration pulses for WVS IS2 V/V




Calibration pulses for WVS IS2 V/V




14-Dec



14-Dec




14-Dec




14-Dec

rows: _ 11 _ 15 _ 19 _ 23 _ 27 ^{14-Dec} _ 3 _ 31 _ 7


Calibration pulses for WVS IS2 V/V




14-Dec




14-Dec






14-Dec





rows: — 12 — 16 — 20 — 24 — 28 — 32 — 4 — 8











rows: _ 1 _ 13 _ 17 _ 21 _ 25 _ 29 _ 5 _ 9





rows: _ 10 _ 14 _ 18 _ 2 _ 22 _ 26 _ 30 _ 6





rows: _ 11 _ 15 _ 19 _ 23 _ 27 _ 31 _ 7





14-Dec
rows: _ 12 _ 16 _ 20 _ 24 _ 28 _ 32 _ 4 _ 8








14-Dec
rows: _ 10 _ 14 _ 18 _ 2 _ 22 _ 26 _ 30 _ 6





14-Dec
rows: _ 11 _ 15 _ 19 _ 23 _ 27 _ 3 _ 31 _ 7




14-Dec
rows: _ 12 _ 16 _ 20 _ 24 _ 28 _ 32 _ 4 _ 8









Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_APM_1PNPDE20111214_020105_000000843109_00319_51195_9306.N1						IS4	H/H	109	51195	319	5.04
ASA_APM_1PNPDE20111214_071123_000000573109_00322_51198_9393.N1						IS1	V/H	109	51198	322	5.04
ASA_APM_1PNPDE20111214_183440_000000423109_00329_51205_9524.N1						IS4	H/H	109	51205	329	5.04
ASA_APM_1PNPDK20111214_213504_000000433109_00331_51207_4783.N1						IS6	V/H	109	51207	331	5.04

Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_GM1_1PNPDE20111213_235732_000001573109_00318_51194_9269.N1						SS1	H/H	109	51194	318	5.04
ASA_GM1_1PNPDE20111214_000424_000005493109_00318_51194_9272.N1						SS1	H/H	109	51194	318	5.04
ASA_GM1_1PNPDE20111214_002856_000001083109_00318_51194_9271.N1						SS1	H/H	109	51194	318	5.04
ASA_GM1_1PNPDE20111214_003227_000002953109_00318_51194_9275.N1						SS1	H/H	109	51194	318	5.04
ASA_GM1_1PNPDE20111214_004505_000006833109_00318_51194_9278.N1						SS1	H/H	109	51194	318	5.04
ASA_GM1_1PNPDE20111214_011205_000001813109_00318_51194_9303.N1						SS1	H/H	109	51194	318	5.04
ASA_GM1_1PNPDE20111214_013101_000001873109_00319_51195_9305.N1						SS1	H/H	109	51195	319	5.04
ASA_GM1_1PNPDE20111214_014044_000010213109_00319_51195_9308.N1						SS1	H/H	109	51195	319	5.04
ASA_GM1_1PNPDE20111214_015941_000000783109_00319_51195_9307.N1						SS1	H/H	109	51195	319	5.04
ASA_GM1_1PNPDE20111214_020424_000003263109_00319_51195_9313.N1						SS1	H/H	109	51195	319	5.04
ASA_GM1_1PNPDE20111214_022519_000009613109_00319_51195_9324.N1						SS1	H/H	109	51195	319	5.04
ASA_GM1_1PNPDE20111214_024716_000000903109_00319_51195_9322.N1						SS1	H/H	109	51195	319	5.04
ASA_GM1_1PNPDE20111214_024856_000003983109_00319_51195_9321.N1						SS1	H/H	109	51195	319	5.04
ASA_GM1_1PNPDE20111214_025659_000002713109_00319_51195_9320.N1						SS1	H/H	109	51195	319	5.04
ASA_GM1_1PNPDE20111214_030742_000001083109_00320_51196_9318.N1						SS1	H/H	109	51196	320	5.04
ASA_GM1_1PNPDE20111214_031719_000010753109_00320_51196_9317.N1						SS1	H/H	109	51196	320	5.04
ASA_GM1_1PNPDE20111214_033920_000002953109_00320_51196_9315.N1						SS1	H/H	109	51196	320	5.04
ASA_GM1_1PNPDE20111214_040532_000005313109_00320_51196_9356.N1						SS1	H/H	109	51196	320	5.04
ASA_GM1_1PNPDE20111214_042238_000000663109_00320_51196_9357.N1						SS1	H/H	109	51196	320	5.04
ASA_GM1_1PNPDE20111214_044441_000005923109_00321_51197_9358.N1						SS1	H/H	109	51197	321	5.04
ASA_GM1_1PNPDE20111214_045923_000010393109_00321_51197_9361.N1						SS1	H/H	109	51197	321	5.04
ASA_GM1_1PNPDE20111214_054549_000004593109_00321_51197_9395.N1						SS1	H/H	109	51197	321	5.04
ASA_GM1_1PNPDE20111214_060007_000000963109_00321_51197_9400.N1						SS1	H/H	109	51197	321	5.04
ASA_GM1_1PNPDE20111214_063639_000005373109_00322_51198_9399.N1						SS1	H/H	109	51198	322	5.04
ASA_GM1_1PNPDE20111214_064957_000003383109_00322_51198_9412.N1						SS1	H/H	109	51198	322	5.04
ASA_GM1_1PNPDE20111214_065929_000003383109_00322_51198_9409.N1						SS1	H/H	109	51198	322	5.04
ASA_GM1_1PNPDE20111214_070559_000001203109_00322_51198_9408.N1						SS1	H/H	109	51198	322	5.04
ASA_GM1_1PNPDE20111214_071007_000000723109_00322_51198_9406.N1						SS1	H/H	109	51198	322	5.04
ASA_GM1_1PNPDE20111214_071239_000002713109_00322_51198_9411.N1						SS1	H/H	109	51198	322	5.04
ASA_GM1_1PNPDK20111214_072601_000006283109_00322_51198_4796.N1						SS1	H/H	109	51198	322	5.04
ASA_GM1_1PNPDK20111214_074037_000000783109_00322_51198_4560.N1						SS1	H/H	109	51198	322	5.04
ASA_GM1_1PNPDK20111214_081513_000007613109_00323_51199_4562.N1						SS1	H/H	109	51199	323	5.04
ASA_GM1_1PNPDK20111214_082641_000001813109_00323_51199_4578.N1						SS1	H/H	109	51199	323	5.04
ASA_GM1_1PNPDK20111214_084113_000008103109_00323_51199_4583.N1						SS1	H/H	109	51199	323	5.04
ASA_GM1_1PNPDK20111214_090733_000004653109_00323_51199_4586.N1						SS1	H/H	109	51199	323	5.04
ASA_GM1_1PNPDK20111214_095632_000005553109_00324_51200_4590.N1						SS1	H/H	109	51200	324	5.04
ASA_GM1_1PNPDK20111214_100943_000000783109_00324_51200_4623.N1						SS1	H/H	109	51200	324	5.04
ASA_GM1_1PNPDK20111214_101303_000000723109_00324_51200_4624.N1						SS1	H/H	109	51200	324	5.04
ASA_GM1_1PNPDK20111214_102150_000000723109_00324_51200_4625.N1						SS1	H/H	109	51200	324	5.04
ASA_GM1_1PNPDK20111214_104748_000004833109_00324_51200_4628.N1						SS1	H/H	109	51200	324	5.04
ASA_GM1_1PNPDK20111214_113601_000003803109_00325_51201_4630.N1						SS1	H/H	109	51201	325	5.04
ASA_GM1_1PNPDK20111214_122643_000005553109_00325_51201_4648.N1						SS1	H/H	109	51201	325	5.04
ASA_GM1_1PNPDK20111214_123957_000001633109_00325_51201_4650.N1						SS1	H/H	109	51201	325	5.04
ASA_GM1_1PNPDK20111214_124900_000000723109_00325_51201_4651.N1						SS1	H/H	109	51201	325	5.04
ASA_GM1_1PNPDK20111214_125021_000005253109_00325_51201_4654.N1						SS1	H/H	109	51201	325	5.04
ASA_GM1_1PNPDK20111214_131111_000006283109_00326_51202_4655.N1						SS1	H/H	109	51202	326	5.04
ASA_GM1_1PNPDK20111214_132558_000003923109_00326_51202_4677.N1						SS1	H/H	109	51202	326	5.04
ASA_GM1_1PNPDK20111214_132600_000000603109_00326_51202_4657.N1						SS1	H/H	109	51202	326	5.04
ASA_GM1_1PNPDK20111214_134754_000006833109_00326_51202_4678.N1						SS1	H/H	109	51202	326	5.04
ASA_GM1_1PNPDK20111214_135922_000003383109_00326_51202_4681.N1						SS1	H/H	109	51202	326	5.04
ASA_GM1_1PNPDK20111214_140657_000007433109_00326_51202_4685.N1						SS1	H/H	109	51202	326	5.04
ASA_GM1_1PNPDK20111214_143019_000002473109_00326_51202_4684.N1						SS1	H/H	109	51202	326	5.04
ASA_GM1_1PNPDK20111214_143657_000002773109_00326_51202_4686.N1						SS1	H/H	109	51202	326	5.04
ASA_GM1_1PNPDK20111214_144617_000008883109_00327_51203_4688.N1						SS1	H/H	109	51203	327	5.04
ASA_GM1_1PNPDK20111214_151415_000001813109_00327_51203_4706.N1						SS1	H/H	109	51203	327	5.04
ASA_GM1_1PNPDK20111214_151802_000001933109_00327_51203_4707.N1						SS1	H/H	109	51203	327	5.04
ASA_GM1_1PNPDK20111214_152628_000000663109_00327_51203_4709.N1						SS1	H/H	109	51203	327	5.04
ASA_GM1_1PNPDK20111214_154709_000003983109_00327_51203_4710.N1						SS1	H/H	109	51203	327	5.04
ASA_GM1_1PNPDK20111214_155708_000001383109_00327_51203_4712.N1						SS1	H/H	109	51203	327	5.04
ASA_GM1_1PNPDK20111214_162527_000008943109_00328_51204_4714.N1						SS1	H/H	109	51204	328	5.04
ASA_GM1_1PNPDK20111214_165651_000005013109_00328_51204_4730.N1						SS1	H/H	109	51204	328	5.04
ASA_GM1_1PNPDK20111214_172725_000006223109_00328_51204_4733.N1						SS1	H/H	109	51204	328	5.04
ASA_GM1_1PNPDK20111214_180719_000003023109_00329_51205_4732.N1						SS1	H/H	109	51205	329	5.04
ASA_GM1_1PNPDK20111214_181402_000003563109_00329_51205_4734.N1						SS1	H/H	109	51205	329	5.04
ASA_GM1_1PNPDK20111214_181849_000000843109_00329_51205_4753.N1						SS1	H/H	109	51205	329	5.04
ASA_GM1_1PNPDK20111214_182814_000002053109_00329_51205_4754.N1						SS1	H/H	109	51205	329	5.04
ASA_GM1_1PNPDK20111214_183826_000000663109_00329_51205_4755.N1						SS1	H/H	109	51205	329	5.04


ASA_GM1_1PNPDK20111214_190739_000006223109_00329_51205_4757.N1	SS1	H/H	109	51205	329	5.04
ASA_GM1_1PNPDK20111214_193318_000001633109_00329_51205_4759.N1	SS1	H/H	109	51205	329	5.04
ASA_GM1_1PNPDK20111214_193925_000005983109_00329_51205_4760.N1	SS1	H/H	109	51205	329	5.04
ASA_GM1_1PNPDK20111214_195332_000000903109_00330_51206_4762.N1	SS1	H/H	109	51206	330	5.04
ASA_GM1_1PNPDE20111214_200855_000002593109_00330_51206_9532.N1	SS1	H/H	109	51206	330	5.04
ASA_GM1_1PNPDE20111214_204842_000007133109_00330_51206_9536.N1	SS1	H/H	109	51206	330	5.04
ASA_GM1_1PNPDE20111214_211106_000004343109_00330_51206_9547.N1	SS1	H/H	109	51206	330	5.04
ASA_GM1_1PNPDE20111214_212057_000006163109_00331_51207_9548.N1	SS1	H/H	109	51207	331	5.04
ASA_GM1_1PNPDE20111214_213229_000001573109_00331_51207_9552.N1	SS1	H/H	109	51207	331	5.04
ASA_GM1_1PNPDE20111214_214641_000003023109_00331_51207_9553.N1	SS1	H/H	109	51207	331	5.04
ASA_GM1_1PNPDE20111214_222807_000006953109_00331_51207_9557.N1	SS1	H/H	109	51207	331	5.04
ASA_GM1_1PNPDE20111214_230229_000003503109_00332_51208_9573.N1	SS1	H/H	109	51208	332	5.04
ASA_GM1_1PNPDE20111214_232103_000001573109_00332_51208_9574.N1	SS1	H/H	109	51208	332	5.04
ASA_GM1_1PNPDE20111214_233247_000001693109_00332_51208_9579.N1	SS1	H/H	109	51208	332	5.04
ASA_GM1_1PNPDE20111214_235157_000001383109_00332_51208_9578.N1	SS1	H/H	109	51208	332	5.04
ASA_GM1_1PNPDE20111214_235540_000003023109_00332_51208_9577.N1	SS1	H/H	109	51208	332	5.04


Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_IMM_1PNPDE20111214_020335_000000373109_00319_51195_9304.N1						IS3	H/H	109	51195	319	5.04
ASA_IMM_1PNPDE20111214_025532_000000763109_00319_51195_9309.N1						IS5	H/H	109	51195	319	5.04
ASA_IMM_1PNPDE20111214_033512_000002393109_00320_51196_9300.N1						IS6	H/H	109	51196	320	5.04
ASA_IMM_1PNPDE20111214_065725_000001123109_00322_51198_9388.N1						IS6	H/H	109	51198	322	5.04
ASA_IMM_1PNPDE20111214_070508_000000373109_00322_51198_9389.N1						IS6	V/V	109	51198	322	5.04
ASA_IMM_1PNPDE20111214_070801_000001153109_00322_51198_9392.N1						IS2	V/V	109	51198	322	5.04
ASA_IMM_1PNPDE20111214_110756_000000523109_00324_51200_9472.N1						IS6	H/H	109	51200	324	5.04
ASA_IMM_1PNPDE20111214_233538_000000433109_00332_51208_9587.N1						IS6	V/V	109	51208	332	5.04


Filename	Pol	Timestamp	count(Module)
ASA_MS__0PNPDK20111214_090614_000000163109_00323_51199_0927.N1	H	2011-12-14 09:06:14	320
ASA_MS__0PNPDK20111214_104628_000000163109_00324_51200_0928.N1	V	2011-12-14 10:46:28	320


Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WSM_1PNPDE20111214_000014_000002453109_00318_51194_9267.N1						SS1	H/H	109	51194	318	5.04
ASA_WSM_1PNPDE20111214_005633_000003303109_00318_51194_9268.N1						SS1	H/H	109	51194	318	5.04
ASA_WSM_1PNPDE20111214_011509_000001223109_00318_51194_9285.N1						SS1	V/V	109	51194	318	5.04
ASA_WSM_1PNPDE20111214_013410_000003923109_00319_51195_9301.N1						SS1	H/H	109	51195	319	5.04
ASA_WSM_1PNPDE20111214_020950_000000923109_00319_51195_9311.N1						SS1	H/H	109	51195	319	5.04
ASA_WSM_1PNPDE20111214_041429_000003923109_00320_51196_9352.N1						SS1	H/H	109	51196	320	5.04
ASA_WSM_1PNPDE20111214_044204_000001533109_00321_51197_9353.N1						SS1	H/H	109	51197	321	5.04
ASA_WSM_1PNPDE20111214_051647_000004043109_00321_51197_9354.N1						SS1	H/H	109	51197	321	5.04
ASA_WSM_1PNPDE20111214_055330_000001533109_00321_51197_9394.N1						SS1	H/H	109	51197	321	5.04
ASA_WSM_1PNPDE20111214_055631_000002143109_00321_51197_9397.N1						SS1	H/H	109	51197	321	5.04
ASA_WSM_1PNPDE20111214_063258_000002143109_00322_51198_9398.N1						SS1	V/V	109	51198	322	5.04
ASA_WSM_1PNPDK20111214_064540_000002513109_00322_51198_4547.N1						SS1	H/H	109	51198	322	5.04
ASA_WSM_1PNPDE20111214_065536_000000923109_00322_51198_9385.N1						SS1	H/H	109	51198	322	5.04
ASA_WSM_1PNPDK20111214_073635_000002393109_00322_51198_4569.N1						SS1	H/H	109	51198	322	5.04
ASA_WSM_1PNPDE20111214_082943_000004283109_00323_51199_9429.N1						SS1	H/H	109	51199	323	5.04
ASA_WSM_1PNPDE20111214_083737_000002143109_00323_51199_9430.N1						SS1	V/V	109	51199	323	5.04
ASA_WSM_1PNPDK20111214_091519_000003923109_00323_51199_4600.N1						SS1	H/H	109	51199	323	5.04
ASA_WSM_1PNPDE20111214_100548_000002323109_00324_51200_9453.N1						SS1	H/H	109	51200	324	5.04
ASA_WSM_1PNPDE20111214_102311_000002883109_00324_51200_9455.N1						SS1	H/H	109	51200	324	5.04
ASA_WSM_1PNPDE20111214_105556_000003303109_00324_51200_9471.N1						SS1	H/H	109	51200	324	5.04
ASA_WSM_1PNPDK20111214_114223_000006003109_00325_51201_4637.N1						SS1	H/H	109	51201	325	5.04
ASA_WSM_1PNPDE20111214_115828_000000923109_00325_51201_9470.N1						SS1	V/V	109	51201	325	5.04
ASA_WSM_1PNPDE20111214_121033_000003983109_00325_51201_9473.N1						SS1	V/V	109	51201	325	5.04
ASA_WSM_1PNPDK20111214_123602_000002323109_00325_51201_4664.N1						SS1	H/H	109	51201	325	5.04
ASA_WSM_1PNPDK20111214_130807_000000923109_00326_51202_4666.N1						SS1	V/V	109	51202	326	5.04
ASA_WSM_1PNPDK20111214_132156_000002393109_00326_51202_4665.N1						SS1	H/H	109	51202	326	5.04
ASA_WSM_1PNPDE20111214_133233_000001353109_00326_51202_9507.N1						SS1	H/H	109	51202	326	5.04
ASA_WSM_1PNPDE20111214_141921_000002143109_00326_51202_9508.N1						SS1	H/H	109	51202	326	5.04
ASA_WSM_1PNPDK20111214_150110_000003923109_00327_51203_4695.N1						SS1	H/H	109	51203	327	5.04
ASA_WSM_1PNPDE20111214_150831_000001353109_00327_51203_9509.N1						SS1	H/H	109	51203	327	5.04
ASA_WSM_1PNPDE20111214_155354_000001903109_00327_51203_9511.N1						SS1	H/H	109	51203	327	5.04
ASA_WSM_1PNPDE20111214_155934_000002143109_00327_51203_9506.N1						SS1	H/H	109	51203	327	5.04
ASA_WSM_1PNPDK20111214_164026_000004343109_00328_51204_4721.N1						SS1	H/H	109	51204	328	5.04
ASA_WSM_1PNPDE20111214_164707_000001593109_00328_51204_9517.N1						SS1	H/H	109	51204	328	5.04
ASA_WSM_1PNPDE20111214_172345_000000923109_00328_51204_9516.N1						SS1	H/H	109	51204	328	5.04
ASA_WSM_1PNPDE20111214_173749_000003553109_00328_51204_9515.N1						SS1	H/H	109	51204	328	5.04
ASA_WSM_1PNPDE20111214_181225_000000923109_00329_51205_9520.N1						SS1	H/H	109	51205	329	5.04
ASA_WSM_1PNPDK20111214_182019_000002393109_00329_51205_4746.N1						SS1	H/H	109	51205	329	5.04
ASA_WSM_1PNPDE20111214_182343_000002513109_00329_51205_9521.N1						SS1	H/H	109	51205	329	5.04
ASA_WSM_1PNPDE20111214_191803_000003123109_00329_51205_9523.N1						SS1	H/H	109	51205	329	5.04
ASA_WSM_1PNPDE20111214_194928_000000923109_00330_51206_9525.N1						SS1	V/V	109	51206	330	5.04
ASA_WSM_1PNPDE20111214_195138_000001103109_00330_51206_9526.N1						SS1	V/V	109	51206	330	5.04
ASA_WSM_1PNPDK20111214_195511_000003733109_00330_51206_4767.N1						SS1	H/H	109	51206	330	5.04
ASA_WSM_1PNPDK20111214_200204_000001903109_00330_51206_4769.N1						SS1	H/H	109	51206	330	5.04
ASA_WSM_1PNPDE20111214_200442_000002513109_00330_51206_9542.N1						SS1	H/H	109	51206	330	5.04
ASA_WSM_1PNPDE20111214_201320_000000923109_00330_51206_9543.N1						SS1	V/V	109	51206	330	5.04
ASA_WSM_1PNPDE20111214_204407_000002693109_00330_51206_9545.N1						SS1	H/H	109	51206	330	5.04
ASA_WSM_1PNPDE20111214_210038_000002143109_00330_51206_9533.N1						SS1	H/H	109	51206	330	5.04
ASA_WSM_1PNPDE20111214_211822_000001533109_00330_51206_9546.N1						SS1	H/H	109	51206	330	5.04
ASA_WSM_1PNPDK20111214_213614_000001593109_00331_51207_4784.N1						SS1	V/V	109	51207	331	5.04
ASA_WSM_1PNPDE20111214_214007_000003923109_00331_51207_9556.N1						SS1	H/H	109	51207	331	5.04
ASA_WSM_1PNPDE20111214_215143_000001533109_00331_51207_9558.N1						SS1	H/H	109	51207	331	5.04
ASA_WSM_1PNPDE20111214_220248_000000923109_00331_51207_9564.N1						SS1	V/V	109	51207	331	5.04
ASA_WSM_1PNPDE20111214_223944_000003363109_00331_51207_9549.N1						SS1	H/H	109	51207	331	5.04
ASA_WSM_1PNPDK20111214_231830_000001533109_00332_51208_4803.N1						SS1	H/H	109	51208	332	5.04
ASA_WSM_1PNPDE20111214_232343_000001533109_00332_51208_9581.N1						SS1	H/H	109	51208	332	5.04
ASA_WSM_1PNPDE20111214_232714_000003303109_00332_51208_9586.N1						SS1	H/H	109	51208	332	5.04




Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WVS_1PNPDE20111214_001336_000008693109_00318_51194_9270.N1						IS2	V/V	109	51194	318	5.04
ASA_WVS_1PNPDE20111214_003050_00000603109_00318_51194_9274.N1						IS2	V/V	109	51194	318	5.04
ASA_WVS_1PNPDE20111214_003726_000004203109_00318_51194_9276.N1						IS2	V/V	109	51194	318	5.04
ASA_WVS_1PNPDE20111214_010205_000002843109_00318_51194_9277.N1						IS2	V/V	109	51194	318	5.04
ASA_WVS_1PNPDE20111214_010605_000003153109_00318_51194_9302.N1						IS2	V/V	109	51194	318	5.04
ASA_WVS_1PNPDE20111214_010205_000002843109_00318_51194_9277.N1						IS1	V/V	109	51194	318	5.04
ASA_WVS_1PNPDE20111214_011738_000007643109_00318_51194_9310.N1						IS2	V/V	109	51194	318	5.04
ASA_WVS_1PNPDE20111214_015749_000000743109_00319_51195_9312.N1						IS2	V/V	109	51195	319	5.04
ASA_WVS_1PNPDE20111214_021120_000007953109_00319_51195_9323.N1						IS2	V/V	109	51195	319	5.04
ASA_WVS_1PNPDE20111214_024122_000003153109_00319_51195_9319.N1						IS2	V/V	109	51195	319	5.04
ASA_WVS_1PNPDE20111214_030133_000003293109_00320_51196_9316.N1						IS2	V/V	109	51196	320	5.04
ASA_WVS_1PNPDE20111214_034417_000007493109_00320_51196_9314.N1						IS2	V/V	109	51196	320	5.04
ASA_WVS_1PNPDE20111214_035631_000002703109_00320_51196_9355.N1						IS2	V/V	109	51196	320	5.04
ASA_WVS_1PNPDE20111214_042351_000010493109_00320_51196_9359.N1						IS2	V/V	109	51196	320	5.04
ASA_WVS_1PNPDE20111214_052332_000009893109_00321_51197_9360.N1						IS2	V/V	109	51197	321	5.04
ASA_WVS_1PNPDE20111214_053947_000003153109_00321_51197_9396.N1						IS2	V/V	109	51197	321	5.04
ASA_WVS_1PNPDE20111214_052332_000009893109_00321_51197_9360.N1						IS1	V/V	109	51197	321	5.04
ASA_WVS_1PNPDE20111214_060150_000016943109_00321_51197_9405.N1						IS2	V/V	109	51197	321	5.04
ASA_WVS_1PNPDE20111214_071715_000002103109_00322_51198_9410.N1						IS2	V/V	109	51198	322	5.04
ASA_WVS_1PNPDK20111214_072030_000002853109_00322_51198_4558.N1						IS2	V/V	109	51198	322	5.04
ASA_WVS_1PNPDK20111214_074204_000019493109_00322_51198_4561.N1						IS2	V/V	109	51198	322	5.04
ASA_WVS_1PNPDK20111214_085444_000006453109_00323_51199_4584.N1						IS2	V/V	109	51199	323	5.04
ASA_WVS_1PNPDK20111214_092209_000020243109_00323_51199_4589.N1						IS2	V/V	109	51199	323	5.04
ASA_WVS_1PNPDK20111214_102816_000010493109_00324_51200_4626.N1						IS2	V/V	109	51200	324	5.04
ASA_WVS_1PNPDK20111214_110223_000002703109_00324_51200_4627.N1						IS2	V/V	109	51200	324	5.04
ASA_WVS_1PNPDK20111214_110936_000015443109_00324_51200_4629.N1						IS2	V/V	109	51200	324	5.04
ASA_WVS_1PNPDK20111214_115958_000005993109_00325_51201_4647.N1						IS2	V/V	109	51201	325	5.04
ASA_WVS_1PNPDK20111214_121720_000005253109_00325_51201_4649.N1						IS2	V/V	109	51201	325	5.04
ASA_WVS_1PNPDK20111214_124245_000003303109_00325_51201_4652.N1						IS2	V/V	109	51201	325	5.04
ASA_WVS_1PNPDK20111214_125908_000004913109_00325_51201_4653.N1						IS2	V/V	109	51201	325	5.04
ASA_WVS_1PNPDK20111214_130938_000000443109_00326_51202_4656.N1						IS2	V/V	109	51202	326	5.04
ASA_WVS_1PNPDK20111214_133447_000007493109_00326_51202_4680.N1						IS2	V/V	109	51202	326	5.04
ASA_WVS_1PNPDK20111214_140503_000000753109_00326_51202_4682.N1						IS2	V/V	109	51202	326	5.04
ASA_WVS_1PNPDK20111214_142252_000004053109_00326_51202_4683.N1						IS2	V/V	109	51202	326	5.04
ASA_WVS_1PNPDK20111214_143429_000001043109_00326_51202_4687.N1						IS2	V/V	109	51202	326	5.04
ASA_WVS_1PNPDK20111214_152117_000002693109_00327_51203_4708.N1						IS2	V/V	109	51203	327	5.04
ASA_WVS_1PNPDK20111214_152744_000011243109_00327_51203_4711.N1						IS2	V/V	109	51203	327	5.04
ASA_WVS_1PNPDK20111214_160305_000013043109_00327_51203_4713.N1						IS2	V/V	109	51203	327	5.04
ASA_WVS_1PNPDK20111214_170517_000010643109_00328_51204_4729.N1						IS2	V/V	109	51204	328	5.04
ASA_WVS_1PNPDK20111214_172516_000000903109_00328_51204_4731.N1						IS2	V/V	109	51204	328	5.04
ASA_WVS_1PNPDK20111214_174345_000013643109_00328_51204_4735.N1						IS2	V/V	109	51204	328	5.04
ASA_WVS_1PNPDK20111214_183940_000016343109_00329_51205_4756.N1						IS2	V/V	109	51205	329	5.04
ASA_WVS_1PNPDK20111214_192332_000005403109_00329_51205_4758.N1						IS2	V/V	109	51205	329	5.04
ASA_WVS_1PNPDK20111214_193607_000001493109_00329_51205_4761.N1						IS2	V/V	109	51205	329	5.04
ASA_WVS_1PNPDE20111214_201450_000017093109_00330_51206_9534.N1						IS2	V/V	109	51206	330	5.04
ASA_WVS_1PNPDE20111214_210409_000000153109_00330_51206_9535.N1						IS2	V/V	109	51206	330	5.04
ASA_WVS_1PNPDE20111214_210409_000003753109_00330_51206_9551.N1						IS2	V/V	109	51206	330	5.04
ASA_WVS_1PNPDE20111214_215414_000004653109_00331_51207_9550.N1						IS2	V/V	109	51207	331	5.04
ASA_WVS_1PNPDE20111214_220418_000013793109_00331_51207_9554.N1						IS2	V/V	109	51207	331	5.04
ASA_WVS_1PNPDE20111214_224517_000002693109_00331_51207_9555.N1						IS2	V/V	109	51207	331	5.04
ASA_WVS_1PNPDE20111214_224902_000007643109_00331_51207_9572.N1						IS2	V/V	109	51207	331	5.04
ASA_WVS_1PNPDE20111214_224517_000002693109_00331_51207_9555.N1						IS1	V/V	109	51207	331	5.04
ASA_WVS_1PNPDE20111214_230821_000005693109_00332_51208_9580.N1						IS2	V/V	109	51208	332	5.04
ASA_WVS_1PNPDE20111214_233629_000008843109_00332_51208_9576.N1						IS2	V/V	109	51208	332	5.04

















































14-Dec




14-Dec




14-Dec




14-Dec





14-Dec




14-Dec








14-Dec



14-Dec



14-Dec

