




document title/ titre du document

# ENVISAT CYCLIC ALTIMETRIC REPORT



# CYCLE 35 from 21-01-2005 to 28-03-2005

# Quality Assessment Report

prepared by/préparé par reference/réference issue/édition

revision/révision
date of issue/date d'édition

status/état

Document type/type de

document

Distribution/distribution

EOP-GOQ and PCF team ENVI-GSOP-EOPG-03-0011

1

04 May 2005

**Technical Note** 

European Space Agency Agence spatiale européenne



# TABLE OF CONTENTS

1	INTRODUCTION	1
2	DISTRIBUTION LIST	1
3	ACRONYMS	1
4	REFERENCE DOCUMENTS	2
5	GENERAL QUALITY ASSESSMENT	3
	5.1 Instruments status	
	5.2 Cycle quality	
	5.3 Orbit quality	
	5.4 Ground Segment Processing Chain Status	
	5.4.1 IPF Processing Chain	
	5.4.2 F-PAC Processing Chain	
	5.4.3 Auxiliary Data File	
	5.4.4 Planned upgrades	
6	ENVISAT PAYLOAD STATUS  6.1 Altimeter Events  6.1.1 RA-2 instrument planning  6.2 MWR Events  6.3 DORIS Events	6 7
7		
	7.1 RA-2 Performances	
	7.1.1 IF Filter MASK	
	7.1.2 USO	
	7.1.3 Tracking capability	
	7.1.4 Sigma0 Transponder	
	7.1.5 Datation	
	7.1.6 Mispointing	
	7.1.7 S-Band anomaly	
	7.1.8 In-Flight Internal Calibration	
	7.2 MWR Performances	
	7.3 DORIS Performances	15
8	PRODUCT PERFORMANCES	15






10

Envisat Cyclic Altimetric Report issue 1 revision 0 – 04 May 2005 ENVI-GSOP-EOPG-03-0011

ENVI-GSOP-EOPG-0	3-0011
page	iii of iii

8.1 A	Availability of data	15
8.2 F	RA-2 Altimeter Parameters	21
8.2.1	Altimeter range	21
8.2.2	Significant Wave Height	21
8.2.3	Backscatter coefficient – Wind Speed	
8.3 E	Edited measurements	
8.4 P	Product disclaimer	25
8.5 I	Data handling recommendations	26
8.5.1	Sea-Ice flag	26
8.5.2	Ocean S-Band anomalies detection	26
8.5.3	Warning on IPF 4.56 Version Identification field	26
8.5.4	S-Band Backscattering Coefficient	26
8.5.5	USO Range Correction	26
8.5.6	Ku-Band Backscattering Coefficient calibration	27
8.5.7	Abnormal RA-2 range behavior after anomaly recovery	27
0.5.7		
	Wind & Wave quality assessment	27
8.6 V <b>9 LON</b> O	G TERM MONITORING	27
8.6 V <b>9 LON</b> 0 9.1 F	G TERM MONITORING	<b>27</b>
8.6 V 9.1 F 9.1.1	G TERM MONITORING  RA-2 Instrument monitoring  IF Filter Mask	<b>27</b> 27
9.1 F 9.1.1 9.1.2	G TERM MONITORING	272727
8.6 V 9.1 F 9.1.1 9.1.2 9.1.3	G TERM MONITORING  RA-2 Instrument monitoring  IF Filter Mask  USO  Tracking Capability	<b>27</b> 272729
9.1 F 9.1.1 9.1.2 9.1.3 9.1.4	G TERM MONITORING  RA-2 Instrument monitoring  IF Filter Mask  USO  Tracking Capability  Sigma0 absolute calibration	
9.1 F 9.1.1 9.1.2 9.1.3 9.1.4 9.1.5	G TERM MONITORING  RA-2 Instrument monitoring  IF Filter Mask  USO  Tracking Capability  Sigma0 absolute calibration  Datation	
8.6 V 9.1 F 9.1.1 9.1.2 9.1.3 9.1.4 9.1.5 9.1.6	G TERM MONITORING  RA-2 Instrument monitoring  IF Filter Mask  USO  Tracking Capability  Sigma0 absolute calibration  Datation  Mispointing	
9.1 F 9.1.1 9.1.2 9.1.3 9.1.4 9.1.5 9.1.6 9.1.7	G TERM MONITORING  RA-2 Instrument monitoring  IF Filter Mask  USO  Tracking Capability  Sigma0 absolute calibration  Datation  Mispointing  S-Band Anomaly	
9.1 F 9.1.1 9.1.2 9.1.3 9.1.4 9.1.5 9.1.6 9.1.7 9.1.8	G TERM MONITORING RA-2 Instrument monitoring IF Filter Mask USO Tracking Capability Sigma0 absolute calibration Datation Mispointing S-Band Anomaly In-Flight Internal Calibration	
8.6 V 9.1 F 9.1.1 9.1.2 9.1.3 9.1.4 9.1.5 9.1.6 9.1.7 9.1.8 9.2 F	G TERM MONITORING  RA-2 Instrument monitoring  IF Filter Mask  USO  Tracking Capability  Sigma0 absolute calibration  Datation  Mispointing  S-Band Anomaly  In-Flight Internal Calibration	
9.1 F 9.1.1 9.1.2 9.1.3 9.1.4 9.1.5 9.1.6 9.1.7 9.1.8 9.2 F	G TERM MONITORING RA-2 Instrument monitoring IF Filter Mask USO Tracking Capability Sigma0 absolute calibration Datation Mispointing S-Band Anomaly In-Flight Internal Calibration Products Monitoring Availability of Data	
8.6 V 9.1 F 9.1.1 9.1.2 9.1.3 9.1.4 9.1.5 9.1.6 9.1.7 9.1.8 9.2 F 9.2.1 9.2.2	G TERM MONITORING RA-2 Instrument monitoring IF Filter Mask USO Tracking Capability Sigma0 absolute calibration Datation Mispointing S-Band Anomaly In-Flight Internal Calibration Products Monitoring Availability of Data RA-2 Altimeter Parameters	
8.6 V 9.1 F 9.1.1 9.1.2 9.1.3 9.1.4 9.1.5 9.1.6 9.1.7 9.1.8 9.2 F 9.2.1 9.2.2 9.2.2	G TERM MONITORING RA-2 Instrument monitoring IF Filter Mask USO Tracking Capability Sigma0 absolute calibration Datation Mispointing S-Band Anomaly In-Flight Internal Calibration Products Monitoring Availability of Data RA-2 Altimeter Parameters	

PARTICULAR INVESTIGATIONS......41





ENVI-GSOP-EOPG-03-0011 page 1 of 41

#### INTRODUCTION 1

This documents aims at reporting on the performances of the EnviSat Radar Altimeter, Microwave Radiometer and DORIS sensors, on the data quality of the corresponding Fast Delivery products as well as on the main events occurred during cycle 35.

This report covers the period from the 21st of February 2005 and the 28th of March 2005.

#### 2 **DISTRIBUTION LIST**

This report is available in PDF format at the internet address http://earth.esa.int/pcs/envisat/ra2/reports/pcs\_cyclic/

#### 3 **ACRONYMS**

**AGC** Automatic Gain Control

**DORIS** Doppler Orbitography and Radiopositioning Integrated by Satellite

Data Set Record **DSR** 

**EPC Electronic Power Converter** 

**ERS** European Remote Sensing satellite European Space Research Institute **ESRIN European Space Operations Centre ESOC** 

Fast Delivery products FD **Ground Segment** GS

Global Telecommunication System GTS

Height Tracking Loop HTL Instrument Control Unit **ICU** 

**IECF Instrument Engineering Calibration Facility** 

IF Intermediate Frequency Individual Echoes ΙE

**IPF Instrument Processing Facility** 

LUT Look Up Table MCMD MacroCommand Main Product Header **MPH MSS** Mean Sea Surface MicroWave Radiometer **MWR MPS** Mission Planning System

Near Real Time NRT On-Board Time **OBT** 

Orbit Control Mode/Manoeuvres OCM **PCS ERS Products Control Service EnviSat Product Control Facility PCF** 

PDHS-E ESRIN Processing and Data Handling Station





PDHS-K Kiruna Processing and Data Handling Station

PLSOL Payload Switch-Off Line PMC Payload Main Computer

PSO On-orbit Position PTR Point Target Response

RA-2 EnviSat Radar Altimeter bi-frequency

RSL Resolution Selection Logic SAD Static Auxiliary Files SBT Satellite Binary Time

SEU Single Event

SFCM Stellar Fine Control Mode SPH Specific Product header

SPSA Signal Processing Sub-Assembly

SYSM Stellar Yaw Steering Mode

S/W Software TM Telemetry TRP Transponder


TWT Traveling Wave Tube

UTC Coordinated Universal Time

YSM Yaw Stellar Mode

### 4 REFERENCE DOCUMENTS

- [R 1a] F-PAC MONTHLY REPORT, SALP-RP-M-OP-15379-CN, February 2005
- [R 1b] F-PAC MONTHLY REPORT, SALP-RP-M-OP-15387-CN, March 2005
- [R 2] ENVISAT Microwave Radiometer Assessment Report Cycle 035, CLS.DOS/05.032, <a href="http://earth.esa.int/pcs/envisat/mwr/reports/">http://earth.esa.int/pcs/envisat/mwr/reports/</a>
- [R 3] Envisat RA-2 IF Mask weird behavior: Investigation Report
- [R 4] Instrument Performance Evaluation and Analysis Summary, PO-TR-ALS-RA-0042
- [R 5] Instrument Corrections Applied on RA-2 Level 1b products, Paper presented at the ENVISAT Calibration Review in September 2002
- [R 6] ENVISAT Phase E Cal/Val Acquisition Plan, ENVI-SPPA-EOPG-TN-03-0008
- [R 7] RA-2 S-Band Anomaly Investigation, PO-TN-ESA-RA-1341, http://earth.esa.int/pcs/envisat/ra2/articles/
- [R-8] RA-2 Performance Results, Paper presented at the ENVISAT Calibration Review in September 2002
- [R 9a] ECMWF Report on ENVISAT RA- 2 for February 2005, Report on ENVISAT Radar Altimeter 2 (RA- 2), Wind/ Wave Product with Height Information (RA2 WWV 2P),
- [R 9b] ECMWF Report on ENVISAT RA- 2 for March 2005, Report on ENVISAT Radar Altimeter 2 (RA- 2), Wind/ Wave Product with Height Information (RA2\_ WWV\_ 2P), http://earth.esa.int/pcs/envisat/ra2/reports/ecmwf/
- [R 10] Envisat GDR Quality Assessment Report, SALP-RP-P2-EX-21121-CLS015
- [R 11] Envisat RA-2 Range Instrumental correction: USO clock period variations and associated auxiliary file, ENVI-GSEG-EOPG-TN-03-0009





[R – 12] Defining a Rain flag for the Envisat altimeter, G. Quartly, study presented to the final CCVT plenary meeting, <a href="http://earth.esa.int/pcs/envisat/ra2/articles/">http://earth.esa.int/pcs/envisat/ra2/articles/</a>

[R-13] ENVISAT Weekly Mission Operations Reports # 141-146, ENVI-ESOC-OPS-RP-1011-TOS-OF

[R – 14] Envisat validation and cross calibration activities during the verification phase. Synthesis Report ESTEC contract No. 16243/02/NL/FF WP6, <a href="http://earth.esa.int/pcs/envisat/ra2/articles/">http://earth.esa.int/pcs/envisat/ra2/articles/</a>

[R – 15] ENVISAT-1 Products Specifications - Vol. 14: RA-2 Products Specifications, PO-RS-MDA-GS-2009, Iss 3, Rev. K, 24/05/2004

[R – 16] Algorithm for Flag identification and waveforms reconstruction of RA-2 data affected by "S-Band anomaly", ENVI-GSEG-TN-04-0004, Issue 1.4

# 5 GENERAL QUALITY ASSESSMENT

### 5.1 Instruments status

The RA-2 instrument, during this cycle underwent one instrument anomalies as given in par. 6.1.

The two known causes of random on-board anomalies are still present. In particular we refer to the so-called S-Band anomaly and the IF mask weird behavior described respectively in [R-7] and [R-3]. Only the S-Band anomaly partially affects a low number of Envisat data products as given in par. 7.1.7.

MWR sensor assessment report: refer to [R-2].

DORIS sensor assessment report: refer to [R-1a] and [R-1b].

# 5.2 Cycle quality

The summary of the RA-2 data products availability for this cycle is given in Table 1 (one line per week).

Start orbit	Stop orbit	Time [sec] instrum. Unavail- ability	Time [sec] L0 gaps	Time [sec] L1b gaps	Time [sec] L2 (FGD) gaps	% instrum. avail.	% L0 avail.	% L1b avail.	% L2 (FGD) avail.
15586	15686.2	1974.426	13432.533	7176.351	7196.453	99.6735	97.4526	98.4870	98.4837
15686.2	15786.4	2121.037	7125.529	7114.547	1105.745	99.6493	98.4711	98.4730	99.4665
15786.4	15886.6	2115.158	6394.513	6391.199	6407.926	99.6503	98.5930	98.5935	98.5908
15886.6	15986.8	37981.867	12561.383	22510.034	22538.647	93.7199	91.6430	89.9980	89.9933
15986.8	16087	2152.523	1094.291	18734.952	18762.706	99.6441	99.4632	96.5464	96.5418

Table 1: RA-2 L0, L1b and L2 FGD Data products availability summary for cycle 35

esa

The summary of the MWR L0 data products availability for this cycle is given in Table 2 (one line per week).

Start orbit	Stop orbit	Time [sec] instrum. unavailability	Time [sec] L0 gaps	% instrum. avail.	% L0 avail.
15586	15686.2	0	12431.999	100	97.9444
15686.2	15786.4	0	0	100	100
15786.4	15886.6	0	5375.999	100	99.1111
15886.6	15986.8	5768.141	11586.999	99.0463	97.1304
15986.8	16087	0	48	100	99.9921

Table 2: MWR L0 Data products availability summary for cycle 35

The summary of the DORIS L0 data products availability for this cycle is given in Table 3 (one line per week).

Start orbit	Stop orbit	Time [sec] instrum. unavailability	Time [sec] L0 gaps	% instrum. avail.	% L0 avail.
15586	15686.2	0	12431.999	100	97.944
15686.2	15786.4	0	0	100	100
15786.4	15886.6	0	5375.999	100	99.111
15886.6	15986.8	5768.141	11586.999	99.046	97.130
15986.8	16087	0	48	100	99.992

Table 3: DORIS L0 Data products availability summary for cycle 35

# 5.3 Orbit quality

One manoeuvre over the period on 17<sup>th</sup> of March to correct orbit inclination:

- Planned delta V size: 2.0 m/s, increasing orbit inclination by approximately 0.015 degree
- Mid thrust time: 05:58:26 UTC at PSO 355.83 degrees
- Thrust duration: 905.7 seconds
- Measured delta V: 2.0153 m/s across track, 0.0099 along track (towards flight direction),
- 0.0164 m/s radial (towards downward vertical).

During cycle 35 the orbit was maintained within the +/- 1km to the reference ground track.



# 5.4 Ground Segment Processing Chain Status

### 5.4.1 IPF PROCESSING CHAIN

Current version of the IPF processing chain is V4.58, installed in both PDHS-E and PDHS-K on July the 16<sup>th</sup> 2004. This is equivalent to the previous version for what regards all the algorithms and auxiliary files, only a new parameter has been added in the SPH that is the pass number which, for NRT data is nominally set to 0. This was done in order to be compliant with the off-line products version that indeed includes the pass number.

Previous IPF version V4.57 was operational at the Envisat PDHS-K and PDHS-E since April 29<sup>th</sup> and 28<sup>th</sup> 2004 respectively.

### 5.4.2 F-PAC PROCESSING CHAIN

Current version of CMA is V6.3 operational since Apr. 29, 2004. Patches 1, 2 and 3 and 4 have been installed until now.

F-PAC CMA anomalies: anomalies are detailed in the F-PAC Monthly Report [R – 1a] and [R-1b].

### 5.4.3 AUXILIARY DATA FILE

Hereafter all the Auxiliary files used actually used by the IPF ground processing are listed:

```
RA2 CHD AXVIEC20030402 094243 20030407 000000 20200101 000000
RA2 CON AXVIEC20020606 164228 20020101 000000 20200101 000000
RA2 CST AXVIEC20020621 135858 20020101 000000 20200101 000000
RA2 DIP AXVIEC20020122 134206 20020101 000000 20200101 000000
RA2 GEO AXVIEC20020314 093428 20020101 000000 20200101 000000
RA2 ICT AXVIEC20031208 143628 20020101 000000 20200101 000000
RA2 IFA AXVIEC20050216 125529 20020101 000000 20200101 000000
RA2 IFB AXVIEC20050216 125738 20020101 000000 20200101 000000
RA2 IFF AXVIEC20031208 151817 20030602 215929 20100101 000000
RA2 IOC AXVIEC20020122 141121 20020101 000000 20200101 000000
RA2 MET AXVIEC20020204 073357 20020101 000000 20200101 000000
RA2 MSS AXVIEC20031208 145545 20020101 000000 20200101 000000
RA2 OT1 AXVIEC20040120 082051 20020101 000000 20200101 000000
RA2 OT2 AXVIEC20031208 150159 20020101 000000 20200101 000000
RA2 SET AXVIEC20020122 150917 20020101 000000 20200101 000000
RA2 SL1 AXVIEC20030131 100228 20020101 000000 20200101 000000
RA2 SL2 AXVIEC20030131 101757 20020101 000000 20200101 000000
RA2 SOI AXVIEC20031208 150608 20020101 000000 20200101 000000
RA2 SSB AXVIEC20031208 150749 20020101 000000 20200101 000000
RA2 TLD AXVIEC20031208 151137 20020101 000000 20200101 000000
RA2 USO AXVIEC20020122 162920 20020101 000000 20200101 000000
```





The RA2\_POL\_AX, the RA2\_SOL\_AX and the RA2\_PLA\_AX have been regularly updated every week without problems.

The RA-2 Auxiliary Data Files (ADF) are accessible from the Envisat Web pages under <a href="http://www.envisat.esa.int/services/auxiliary\_data/ra2mwr/">http://www.envisat.esa.int/services/auxiliary\_data/ra2mwr/</a>.

### 5.4.4 PLANNED UPGRADES

Evolution of the IPF Level 1B and Level 2 processing chain is intended to be operational by the end of 2005. The next IPF version release shall nominally contain the following:

- 1. USO instrumental correction within the RA-2 L1b processor.
- 2. New MWR Side Lobes correction algorithm within MWR L1b processor
- 3. Correction of the mispointing evaluation algorithm within the RA-2 L2 processor
- 4. Inclusion of the loading tide for the GOT2000.2 model.
- 5. Addition of the peakiness fields in Ku and S band to the RA-2 and MWR FD/I/MAR meteorological products
- 6. Inclusion of the square of the significant wave height in Ku and S band
- 7. Inclusion of an S-band anomaly flag, see [R-16]
- 8. Upgrade of the Level 1B and Level 2 processing for DORIS NRT orbital information computation
- 9. New ADF for Digital Elevation Model (DEM): AUX DEM AX
- 10. Adjustment of the S Band computation for rain flag
- 11. Inclusion of nadir location not corrected for slope model
- 12. Inclusion of GPS Ionospheric correction
- 13. Addition of a field for Level 1B SW ID in Level 2 products
- 14. Inclusion of MOG2D Inverse Barometer Geophysical Correction in Level 2 products

Evolutions 3, 5, 6, 11, 12, 13 and 14 shall be reflected too in the F-PAC CMA processing chain.

# **6** ENVISAT PAYLOAD STATUS

### 6.1 Altimeter Events

The Radar Altimeter 2, during cycle 35, was unavailable once in the following time frames:

Start: 18 Mar 2005 04:35:34, orbit = 15933 Stop: 18 Mar 2005 12:58:00, orbit = 15938

cause: RA-2 was switched to Suspend by the PMC following an 'Uncontrolled Software Action'. This anomaly is under investigation, and is tracked via AR ENV-774 (see [R-13]).



### 6.1.1 RA-2 INSTRUMENT PLANNING

The RA-2 instrument planning was performed as follows:

- IF Calibration Mode according the nominal operational acquisition scheme: 100 seconds of data twice per day over Himalayan region (ascending and descending passes).
- Preset Loop Output mode for GAVDOS Range transponders, located in Creta.
- Preset Loop Output acquisition over ESA transponders, located near Rome; for both ascending and descending passes. The PLO planning has been updated to the High Chirp Resolution for the ESA TRP overpasses, starting from orbit #14790.
- Individual Echoes background planning: the buffering of 20 Data Blocks of Individual Echoes (1.114 sec.) transmitted every 160 Data Blocks starts after flying over Himalayan region (both ascending and descending passes) and prosecutes for half day.
- Individual Echoes acquisitions during PLO activity over the 4 ESA transponders near Rome (1 second length acquisition, 1 repetition)
- Individual Echoes acquisitions over Uyuni Salar zone, relative orbits #139 and 146 (1 second length acquisition, 2 repetitions)

Hereafter the map is reported showing the acquisition sites for both the Range and Sigma\_0 transponders.




Figure 1: Transponder Acquisition sites for cycle 35

# 6.2 MWR Events

The MWR, during cycle 35 was never unavailable [R-13].

### 6.3 DORIS Events

The DORIS during cycle 35 was never unavailable [R-13].



7

esa

### INSTRUMENT PERFORMANCES

# 7.1 RA-2 Performances

### 7.1.1 IF FILTER MASK

In Figure 2 all valid IF masks retrieved by averaging the 100 seconds of data acquired daily during cycle 35 are plotted in the left panel. The on-ground measured IF mask (ref [R-4]) is also plotted in that panel with a solid line. In the right panel the difference of each of the calculated IF masks with respect to the on-ground measured one is reported. During cycle 35 the number of valid IF masks have been of 17, representing about the 32% of the total available IF masks. Only valid IF masks are used to generate the final IF mask used in the Level 1B ground processing; the method used for editing the data is based on the comparison between each of the single IF masks and the reference one (on-ground).




Figure 2: Valid IF masks retrieved daily during cycle 35 plotted together with the on-ground reference.

### 7.1.2 USO

In Figure 3 the USO clock period trend retrieved for cycle 35 is reported. The difference of the actual USO clock period with respect to the nominal one has been plotted in the upper panel. In the lower panel the Range error due to the USO clock variability has been reported taking a satellite altitude of 800 Km as a nominal value.



Currently the nominal USO clock period (12500 ps) is used within the processing; this means that the data are not corrected for the bias and the drift correlated to the actual USO clock period. A particular investigation has been performed regarding the USO clock trend and the associated auxiliary file; this is described in [R-11]. The conclusion can be summarized as follows: the precision of 1 ps available in the current USO auxiliary file is not enough to appreciate its trend

and it is too rough for any altimetric application. A suitable resolution is considered to be of 10<sup>-6</sup> ps. This problem will be corrected with the following upgrade of the IPF as described in par. 5.4.4.




Figure 3: USO clock period for cycle 35

#### 7.1.3 TRACKING CAPABILITY

The percentages of acquisition in the different resolutions subdivided by surface type are given in the Table bellow:



20MHz Surface type 320 MHz 80 MHz Open Ocean 99.99 0.01 0 Costal Water (ocean depth < 200 m) 98.34 1.47 0.19 81.13 13.59 5.28 Sea Ice 96.27 2.95 0.78 Ice Sheet Land 99.14 0.74 0.12 All world 95.15 3.55

Table 4: RA-2 Tracking capability: Chirp ID percentages discriminated by surface type

The figures given for the RA-2 tracking performances during this cycle are very much in line with the ones recorded at the end of the Commissioning Phase and presented in [R - 8]. The slight differences are in part due to the different algorithms used to discriminate the surface types.

The objectives of the Commissioning Phase "RSL and Tracking optimization" are hereafter reported:

- 320MHz over Ocean > 99%
- 320 MHz within 15km of Land/Ocean boundary (Costal Water) no specific requirement
- 320 MHz over Sea Ice > 95%
- 320/80 MHz Fixed resolution at Ice Sheet Crossovers > 95%
- 320MHz over Ice Shelves > 95%

### 7.1.4 SIGMA0 TRANSPONDER

The  $\sigma^{\circ}$  absolute calibration of the RA-2 is performed using a reference target given by a transponder that has been developed at ESTEC. This has been exploited during the 6 month Commissioning phase to generate early calibration results. In order to consolidate this calibration results and to monitor the RA-2 calibration of  $\sigma^{\circ}$  during the Envisat lifetime, a continuous monitoring is needed by operating the transponder as many as possible Envisat overpasses.

Three of the four planned Sigma\_0 Transponder acquisitions for the cycle 35 were performed. The operation planned on 24 February has not been done cause of meteorological condition. All the acquisitions were executed in High Resolution mode. The dates and times of the acquisitions are reported hereafter:

8-March-2005, Maccarese, 09:41:58

15-March-2005, Roma, 20:39:24

24-March-2005, Valmontone, 09:39:08

The results are reported in the following Table 5, including the tropospheric attenuation estimated from ECMWF data.

Orbit	Date	Location/Rel. Track	Coordinates	Resolution	Not Corrected Backscattering Bias [dB]	Tropospheric Correction (one way) [dB]
15793	8-mar-05	Maccarese / 208	41.8605, 12.2385	High	0.93	0.058
15900	15-mar-05	Rome / 315	41.8472, 12.4819	High	0.93	0.064
16022	24-mar-05	Valmontone / 437	41.7673, 12.9247	High	0.94	0.077

Table 5: Absolute backscattering calibration results obtained with Transponder measurements



Envisat Cyclic Altimetric Report issue 1 revision 0 – 18 March 2005

### 7.1.5 DATATION

A significant part of an eventual error in the RA-2 products datation could be given by the not perfect synchronism between the Satellite Binary Time and the UTC Time due to a drift of the ICU clock period. A correlation between those two times is performed at every Kiruna orbit dump and then extrapolated for the four non-Kiruna orbits. In the upper panel of Figure 6, the differences between the extrapolated UTC values and the corresponding real UTC values measured at the next Kiruna dump, are reported. The variability observed during the previous cycles is not present for the current one, because the problem has been fixed at the end of the cycle 34. In the lower panel the ICU clock step for the same period is shown.




Figure 6: UTC deviations and ICU clock period for cycle 35

### 7.1.6 MISPOINTING

In Figure 7 the trend of the mispointing squared (averaged every orbit) is reported in deg^2\*10e-4



The average squared mispointing value, as extracted from the RA2\_FGD\_2P data products, is around  $0.028 \, \text{deg}^2$ , is known to be higher than the one reported at platform level [R - 13]. This is due to a not perfect tuning of the algorithm currently used to retrieve the mispointing value from the RA-2 waveform data.

For this cycle one event of low mispointing value is present and visible in the plot of Figure 7. The event is in correspondence with the instrument anomaly occurred on 18 March 2005, as reported in par. 6.1. In Figure 7 is also visible a high mispointing occurrence related to the orbital manoeuvre performed on 17<sup>th</sup> of March.




Figure 7: Smoothed mispointing squared trend for cycle 35 (deg^2\*10^4)

### 7.1.7 S-BAND ANOMALY

The so-called "S-Band anomaly" affects the RA-2 data products quality. Hereafter, the table lists the products files affected by the S-band anomaly problem during cycle 35. This corresponds to a total percentage of about 2.2% of the acquired data.

Being the method used a statistical one working on ocean data, files containing less than 1000 seconds of data over ocean have not been considered. This choice is supported by the fact that the



"S-Band anomaly" is associated to a particular instrumental behavior that cannot appear and disappear within a short time frame. (ref. [R-7])

File name	Start date	Start time	Stop date	Stop time
RA2_FGD_2PNPDE20050227_215645_000061162035_00086_15671_2968.N1	27-feb-05	56:45.9	27-feb-05	38:41.7
RA2_FGD_2PNPDE20050227_233721_000061752035_00087_15672_2969.N1	27-feb-05	37:21.5	28-feb-05	20:16.4
RA2_FGD_2PNPDE20050228_011856_000043782035_00088_15673_2970.N1	28-feb-05	18:56.2	28-feb-05	31:54.2
RA2_FGD_2PNPDE20050228_023118_000049262035_00089_15674_2971.N1	28-feb-05	31:18.6	28-feb-05	53:24.7
RA2_FGD_2PNPDE20050313_225949_000061272035_00287_15872_3138.N1	13-mar-05	59:49.2	14-mar-05	41:56.2
RA2_FGD_2PNPDE20050314_004057_000058232035_00288_15873_3139.N1	14-mar-05	40:57.2	14-mar-05	18:00.0
RA2_FGD_2PNPDE20050314_021650_000045612035_00289_15874_3140.N1	14-mar-05	16:51.0	14-mar-05	32:51.6
RA2_FGD_2PNPDE20050314_033219_000048702035_00290_15875_3141.N1	14-mar-05	32:19.4	14-mar-05	53:29.7
RA2_FGD_2PNPDE20050315_025957_000048692035_00304_15889_3159.N1	15-mar-05	59:57.6	15-mar-05	21:06.9
RA2_FGD_2PNPDE20050327_020743_000045512035_00475_16060_3328.N1	27-mar-05	07:43.8	27-mar-05	23:34.5
RA2_FGD_2PNPDE20050327_032258_000048962035_00476_16061_3329.N1	27-mar-05	22:58.9	27-mar-05	44:34.9

Table 6: List of L2 FGD Files affected by S-Band anomaly during cycle 35

A valuable algorithm to detect the RA-2 DSRs affected by the S-Band anomaly within the L2 products can be found in [R-12]. Note that the algorithm is only valid for data acquired over openocean.

#### IN-FLIGHT INTERNAL CALIBRATION 7.1.8

The RA-2 Range and Sigma0 measurements are corrected to take into account the internal path delay and attenuation, respectively. This is done by measuring those two variables in relation to the internal Point Target Response. The two correction factors are calculated during the L1b processing and directly applied. They are also continuously monitored and the results for cycle 35 (averaged per day) are reported in Figure 8 and Figure 9. The time delay calibration factor shows a regular behaviour as observed on previous cycles and the Sigma0 calibration factor seems to be quite stable for this cycle.








Figure 8: Ku and S Band in-flight time delay calibration factor for cycle 35




Figure 9: Ku and S Band in-flight Sigma0 calibration factor for cycle 35





### 7.2 **MWR Performances**

For MWR performances please refer to the Reference CLS Cyclic Report of the type of [R-2].

### 7.3 **DORIS Performances**

For DORIS performances refer to the Reference F-PAC Monthly Report of the type of [R – 1a] and [R-1b].

### PRODUCT PERFORMANCES 8

### 8.1 Availability of data

In Figure 10 and Table 7 the summary of unavailable RA-2 L0 products is given. It is easy to notice that close to the Himalayan region two small gaps in the data are present. This is due to the daily instrument switch-offs (Heater 2 mode) performed to prevent the S-Band anomaly to last more than half a day when it occurs.




Figure 10: RA-2 L0 unavailable products for cycle 35





Envisat Cyclic Altimetric Report issue 1 revision 0 – 18 March 2005 ENVI-GSOP-EOPG-03-0011 page 16 of 41

Start date	Start time	Stop date	Stop time	Duration [sec]	Start orbit	Stop orbit	Reason
22-feb-05	05:23:53	22-feb-05	05:25:11	78	15590	15590	PDS_UNKNOWN_FAILURE
22-feb-05	16:36:40	22-feb-05	16:37:58	78	15597	15597	PDS_UNKNOWN_FAILURE
26-feb-05	16:10:20	26-feb-05	16:11:38	78	15654	15654	PDS_UNKNOWN_FAILURE
26-feb-05	20:46:07	26-feb-05	22:30:18	6251	15656	15657	PDS_UNKNOWN_FAILURE
27-feb-05	04:23:53	27-feb-05	04:23:55	2	15661	15661	PDS_UNKNOWN_FAILURE
27-feb-05	04:27:06	27-feb-05	04:28:24	78	15661	15661	PDS_UNKNOWN_FAILURE
27-feb-05	15:36:27	27-feb-05	15:36:30	3	15668	15668	PDS_UNKNOWN_FAILURE
27-feb-05	15:39:28	27-feb-05	15:40:46	78	15668	15668	PDS_UNKNOWN_FAILURE
23-feb-05	04:52:58	23-feb-05	04:54:16	78	15604	15604	PDS_UNKNOWN_FAILURE
23-feb-05	16:04:38	23-feb-05	16:05:55	77	15611	15611	PDS_UNKNOWN_FAILURE
24-feb-05	04:21:21	24-feb-05	04:22:39	78	15618	15618	PDS_UNKNOWN_FAILURE
24-feb-05	15:33:52	24-feb-05	15:35:10	78	15625	15625	PDS_UNKNOWN_FAILURE
25-feb-05	05:28:52	25-feb-05	05:30:10	78	15633	15633	PDS_UNKNOWN_FAILURE
25-feb-05	06:57:26	25-feb-05	08:38:55	6089	15634	15635	PDS_UNKNOWN_FAILURE
25-feb-05	16:42:05	25-feb-05	16:43:22	77	15640	15640	PDS_UNKNOWN_FAILURE
26-feb-05	04:58:37	26-feb-05	04:59:55	78	15647	15647	PDS_UNKNOWN_FAILURE
01-mar-05	05:04:14	01-mar-05	05:05:32	78	15690	15690	PDS_UNKNOWN_FAILURE
01-mar-05	16:16:15	01-mar-05	16:17:32	77	15697	15697	PDS_UNKNOWN_FAILURE
05-mar-05	15:47:50	05-mar-05	15:47:53	3	15754	15754	PDS_UNKNOWN_FAILURE
05-mar-05	15:50:39	05-mar-05	15:51:57	78	15754	15754	PDS_UNKNOWN_FAILURE
06-mar-05	04:06:45	06-mar-05	04:08:03	78	15761	15761	PDS_UNKNOWN_FAILURE
06-mar-05	07:14:48	06-mar-05	08:55:12	6024	15763	15764	PDS_UNKNOWN_FAILURE
06-mar-05	15:16:42	06-mar-05	15:16:44	2	15768	15768	PDS_UNKNOWN_FAILURE
06-mar-05	15:19:09	06-mar-05	15:20:27	78	15768	15768	PDS_UNKNOWN_FAILURE
07-mar-05	05:13:15	07-mar-05	05:13:18	3	15776	15776	PDS_UNKNOWN_FAILURE
07-mar-05	05:15:28	07-mar-05	05:16:46	78	15776	15776	PDS_UNKNOWN_FAILURE
07-mar-05	16:28:04	07-mar-05	16:29:22	78	15783	15783	PDS_UNKNOWN_FAILURE
02-mar-05	04:32:51	02-mar-05	04:34:09	78	15704	15704	PDS_UNKNOWN_FAILURE
02-mar-05	15:45:03	02-mar-05	15:46:21	78	15711	15711	PDS_UNKNOWN_FAILURE
03-mar-05	04:00:53	03-mar-05	04:02:11	78	15718	15718	PDS_UNKNOWN_FAILURE
03-mar-05	15:13:14	03-mar-05	15:14:32	78	15725	15725	PDS_UNKNOWN_FAILURE
04-mar-05	05:07:38	04-mar-05	05:07:41	3	15733	15733	PDS_UNKNOWN_FAILURE
04-mar-05	05:09:51	04-mar-05	05:11:09	78	15733	15733	PDS_UNKNOWN_FAILURE
04-mar-05	16:22:09	04-mar-05	16:23:27	78	15740	15740	PDS_UNKNOWN_FAILURE
05-mar-05	04:38:36	05-mar-05	04:39:54	78	15747	15747	PDS_UNKNOWN_FAILURE
12-mar-05	15:30:58	12-mar-05	15:32:16	78	15854	15854	PDS_UNKNOWN_FAILURE
13-mar-05	05:26:23	13-mar-05	05:27:40	77	15862	15862	PDS_UNKNOWN_FAILURE
13-mar-05	16:39:22	13-mar-05	16:40:40	78	15869	15869	PDS_UNKNOWN_FAILURE
14-mar-05	04:55:48	14-mar-05	04:57:06	78	15876	15876	PDS_UNKNOWN_FAILURE
14-mar-05	16:07:25	14-mar-05	16:08:42	77	15883	15883	PDS_UNKNOWN_FAILURE
15-mar-05	04:24:13	15-mar-05	04:25:31	78	15890	15890	PDS_UNKNOWN_FAILURE
15-mar-05	06:23:10	15-mar-05	06:25:10	120	15891	15891	PDS_UNKNOWN_FAILURE
15-mar-05	15:36:39	15-mar-05	15:37:57	78	15897	15897	PDS_UNKNOWN_FAILURE





Envisat Cyclic Altimetric Report issue 1 revision 0 – 18 March 2005 ENVI-GSOP-EOPG-03-0011 page 17 of 41

		I	1	Г	1	ı	
16-mar-05	03:52:04	16-mar-05	03:53:21	77	15904	15904	PDS_UNKNOWN_FAILURE
16-mar-05	16:44:46	16-mar-05	16:46:04	78	15912	15912	PDS_UNKNOWN_FAILURE
10-mar-05	05:21:05	10-mar-05	05:22:22	77	15819	15819	PDS_UNKNOWN_FAILURE
10-mar-05	16:33:58	10-mar-05	16:35:16	78	15826	15826	PDS_UNKNOWN_FAILURE
11-mar-05	04:50:06	11-mar-05	04:51:23	77	15833	15833	PDS_UNKNOWN_FAILURE
11-mar-05	12:57:07	11-mar-05	13:06:05	538	15838	15838	PDS_UNKNOWN_FAILURE
11-mar-05	13:13:46	11-mar-05	14:33:13	4767	15838	15839	PDS_UNKNOWN_FAILURE
11-mar-05	16:01:50	11-mar-05	16:03:07	77	15840	15840	PDS_UNKNOWN_FAILURE
12-mar-05	04:18:29	12-mar-05	04:19:46	77	15847	15847	PDS_UNKNOWN_FAILURE
12-mar-05	15:27:59	12-mar-05	15:28:01	2	15854	15854	PDS_UNKNOWN_FAILURE
17-mar-05	02:06:48	17-mar-05	02:12:30	342	15917	15917	PDS_UNKNOWN_FAILURE
17-mar-05	04:59:12	17-mar-05	04:59:14	2	15919	15919	PDS_UNKNOWN_FAILURE
18-mar-05	15:42:15	18-mar-05	15:43:32	77	15940	15940	PDS_UNKNOWN_FAILURE
19-mar-05	03:55:54	19-mar-05	03:55:56	2	15947	15947	PDS_UNKNOWN_FAILURE
19-mar-05	03:57:56	19-mar-05	03:59:13	77	15947	15947	PDS_UNKNOWN_FAILURE
19-mar-05	15:10:16	19-mar-05	15:11:33	77	15954	15954	PDS_UNKNOWN_FAILURE
19-mar-05	21:29:11	19-mar-05	21:31:11	120	15957	15957	PDS_UNKNOWN_FAILURE
19-mar-05	21:31:11	19-mar-05	22:21:17	3006	15957	15958	PDS_UNKNOWN_FAILURE
19-mar-05	22:34:35	19-mar-05	22:52:19	1064	15958	15958	PDS_UNKNOWN_FAILURE
20-mar-05	05:07:02	20-mar-05	05:08:20	78	15962	15962	PDS_UNKNOWN_FAILURE
20-mar-05	16:19:12	20-mar-05	16:20:29	77	15969	15969	PDS_UNKNOWN_FAILURE
21-mar-05	04:32:35	21-mar-05	04:32:38	3	15976	15976	PDS_UNKNOWN_FAILURE
17-mar-05	05:01:24	17-mar-05	05:02:42	78	15919	15919	PDS_UNKNOWN_FAILURE
21-mar-05	04:35:43	21-mar-05	04:37:01	78	15976	15976	PDS_UNKNOWN_FAILURE
21-mar-05	15:44:58	21-mar-05	15:45:00	2	15983	15983	PDS_UNKNOWN_FAILURE
21-mar-05	15:47:51	21-mar-05	15:49:09	78	15983	15983	PDS_UNKNOWN_FAILURE
22-mar-05	04:03:49	22-mar-05	04:05:06	77	15990	15990	PDS_UNKNOWN_FAILURE
22-mar-05	15:16:11	22-mar-05	15:17:29	78	15997	15997	PDS_UNKNOWN_FAILURE
17-mar-05	09:23:44	17-mar-05	09:39:14	930	15922	15922	PDS_UNKNOWN_FAILURE
17-mar-05	11:15:44	17-mar-05	11:18:52	188	15923	15923	PDS_UNKNOWN_FAILURE
17-mar-05	14:46:37	17-mar-05	16:10:52	5055	15925	15926	PDS_UNKNOWN_FAILURE
17-mar-05	16:13:16	17-mar-05	16:19:48	392	15926	15926	PDS_UNKNOWN_FAILURE
18-mar-05	04:26:41	18-mar-05	04:26:43	2	15933	15933	PDS_UNKNOWN_FAILURE
18-mar-05	04:29:58	18-mar-05	04:35:34	336	15933	15933	PDS_UNKNOWN_FAILURE
18-mar-05	12:58:00	18-mar-05	12:59:06	66	15938	15938	PDS_UNKNOWN_FAILURE
19-mar-05	22:52:19	19-mar-05	23:09:43	1044	15958	15958	UNAV_ARTEMIS
18-mar-05	04:35:34	18-mar-05	12:58:00	30146	15933	15938	UNAV_RA2
24-mar-05	15:50:43	24-mar-05	15:50:45	2	16026	16026	PDS_UNKNOWN_FAILURE
24-mar-05	15:53:27	24-mar-05	15:54:44	77	16026	16026	PDS_UNKNOWN_FAILURE
25-mar-05	04:09:41	25-mar-05	04:10:59	78	16033	16033	PDS_UNKNOWN_FAILURE
25-mar-05	15:19:31	25-mar-05	15:19:34	3	16040	16040	
25-mar-05	15:22:06	25-mar-05	15:23:24	78	16040	16040	
26-mar-05	05:18:16	26-mar-05	05:19:34	78	16048	16048	
26-mar-05	16:31:02	26-mar-05	16:32:19	77	16055	16055	PDS_UNKNOWN_FAILURE



27-mar-05	04:47:14	27-mar-05	04:48:31	77	16062	16062	PDS_UNKNOWN_FAILURE
27-mar-05	15:59:02	27-mar-05	16:00:20	78	16069	16069	PDS_UNKNOWN_FAILURE

Table 7: List of gaps for RA-2 L0 products during cycle 35

In Figure 11 and Table 8 the summary of unavailable MWR L0 products is given.



Figure 11: MWR L0 unavailable products for cycle 35

Start date	Start time	Stop date	Stop time	Duration [sec]	Start orbit	Stop orbit	Reason
25-feb-05	06:56:23	25-feb-05	08:38:47	6144	15634	15635	PDS_UNKNOWN_FAILURE
26-feb-05	20:45:14	26-feb-05	22:30:02	6288	15656	15657	PDS_UNKNOWN_FAILURE
11-mar-05	12:56:06	11-mar-05	13:05:42	576	15838	15838	PDS_UNKNOWN_FAILURE
11-mar-05	13:12:54	11-mar-05	14:32:54	4800	15838	15839	PDS_UNKNOWN_FAILURE
17-mar-05	02:05:54	17-mar-05	02:12:42	408	15917	15917	PDS_UNKNOWN_FAILURE
17-mar-05	09:22:43	17-mar-05	09:39:31	1008	15922	15922	PDS_UNKNOWN_FAILURE
17-mar-05	11:14:43	17-mar-05	11:19:07	264	15923	15923	PDS_UNKNOWN_FAILURE
17-mar-05	14:45:31	17-mar-05	16:19:31	5640	15925	15926	PDS_UNKNOWN_FAILURE
19-mar-05	21:28:24	19-mar-05	21:31:11	167	15957	15957	PDS_UNKNOWN_FAILURE
19-mar-05	21:31:11	19-mar-05	22:21:12	3001	15957	15958	PDS_UNKNOWN_FAILURE
19-mar-05	22:34:00	19-mar-05	22:52:19	1099	15958	15958	PDS_UNKNOWN_FAILURE
19-mar-05	22:52:19	19-mar-05	23:09:36	1037	15958	15958	UNAV_ARTEMIS
25-mar-05	12:15:24	25-mar-05	12:16:12	48	16038	16038	PDS_UNKNOWN_FAILURE

Table 8: List of gaps for MWR L0 products during cycle 35



In Figure 12 and Table 9 the summary of unavailable RA-2 L1b products is given. Please note that in this case, only the gaps due to problems with the PDS are reported.




Figure 12: RA-2 L1b unavailable products for cycle 35

Start date	Start time	Stop date	Stop time	Duratio n [sec]	Start orbit	Stop orbit	Reason
26-feb-05	04:58:37	26-feb-05	04:59:55	78	15647	15647	PDS_UNKNOWN_FAILURE
26-feb-05	16:10:20	26-feb-05	16:11:38	78	15654	15654	PDS_UNKNOWN_FAILURE
27-feb-05	04:27:06	27-feb-05	04:28:24	78	15661	15661	PDS_UNKNOWN_FAILURE
27-feb-05	15:39:28	27-feb-05	15:40:46	78	15668	15668	PDS_UNKNOWN_FAILURE
28-feb-05	03:55:01	28-feb-05	03:56:18	77	15675	15675	PDS_UNKNOWN_FAILURE
28-feb-05	15:07:20	28-feb-05	15:08:37	77	15682	15682	PDS_UNKNOWN_FAILURE
23-feb-05	04:52:58	23-feb-05	04:54:16	78	15604	15604	PDS_UNKNOWN_FAILURE
23-feb-05	16:04:38	23-feb-05	16:05:55	77	15611	15611	PDS_UNKNOWN_FAILURE
24-feb-05	04:21:21	24-feb-05	04:22:39	78	15618	15618	PDS_UNKNOWN_FAILURE
24-feb-05	15:33:52	24-feb-05	15:35:10	78	15625	15625	PDS_UNKNOWN_FAILURE
25-feb-05	05:28:52	25-feb-05	05:30:10	78	15633	15633	PDS_UNKNOWN_FAILURE
25-feb-05	06:57:27	25-feb-05	08:38:55	6088	15634	15635	PDS_UNKNOWN_FAILURE
25-feb-05	16:42:05	25-feb-05	16:43:22	77	15640	15640	PDS_UNKNOWN_FAILURE
25-feb-05	16:43:22	25-feb-05	16:43:23	1	15640	15640	PDS_UNKNOWN_FAILURE
01-mar-05	05:04:14	01-mar-05	05:05:32	78	15690	15690	PDS_UNKNOWN_FAILURE
01-mar-05	16:16:15	01-mar-05	16:17:32	77	15697	15697	PDS_UNKNOWN_FAILURE





Envisat Cyclic Altimetric Report issue 1 revision 0 – 18 March 2005 ENVI-GSOP-EOPG-03-0011 page 20 of 41

06-mar-05   04:06:45   06-mar-05   04:08:03   78   15761   15761   PDS_UNKNOWN_FAILURE   06-mar-05   07:14:50   06-mar-05   08:55:12   6022   15763   15764   PDS_UNKNOWN_FAILURE   07-mar-05   05:15:28   07-mar-05   05:16:46   78   15776   15776   PDS_UNKNOWN_FAILURE   07-mar-05   16:28:04   07-mar-05   06:22:22   78   15783   15783   PDS_UNKNOWN_FAILURE   02-mar-05   04:32:51   02-mar-05   04:00:53   03-mar-05   04:00:53   03-mar-05   04:00:53   03-mar-05   04:01:31   03-mar-05   04:00:53   03-mar-05   05:11:199   78   15733   15783   PDS_UNKNOWN_FAILURE   03-mar-05   05:09:51   04-mar-05   05:11:09   78   15733   15733   PDS_UNKNOWN_FAILURE   03-mar-05   05:09:51   04-mar-05   05:11:09   78   15733   15733   PDS_UNKNOWN_FAILURE   03-mar-05   04:30:53   04-mar-05   05:11:09   78   15733   15733   PDS_UNKNOWN_FAILURE   03-mar-05   04:30:53   05-mar-05   04:33:54   78   15747   15747   PDS_UNKNOWN_FAILURE   05-mar-05   04:33:56   05-mar-05   05:26:23   05-mar-05   04:33:56   05-mar-05   04:04:04   07   04:04   07   05-mar-05   04:04:04   07   05-mar-05   04:04:04   07   05-mar-05   04:04:04   07   05-mar-05   04:04:04   07   05-mar		T	T	ı		1	1	
06-mar-05   07:14:50   06-mar-05   08:55:12   6022   15763   15764   PDS_UNKNOWN_FAILURE   06-mar-05   15:19:09   06-mar-05   15:20:27   78   15768   15768   PDS_UNKNOWN_FAILURE   07-mar-05   05:15:28   07-mar-05   05:16:46   78   15776   15776   PDS_UNKNOWN_FAILURE   07-mar-05   16:28:04   07-mar-05   16:29:22   78   15783   15783   PDS_UNKNOWN_FAILURE   02-mar-05   04:32:51   02-mar-05   04:32:51   02-mar-05   04:32:51   02-mar-05   04:32:51   02-mar-05   04:32:51   02-mar-05   04:02:11   78   15714   15711   PDS_UNKNOWN_FAILURE   03-mar-05   04:00:53   03-mar-05   04:02:11   78   15718   15718   PDS_UNKNOWN_FAILURE   03-mar-05   04:00:53   03-mar-05   04:02:11   78   15718   15718   PDS_UNKNOWN_FAILURE   04-mar-05   16:22:09   04-mar-05   05:09:51   04-mar-05   05:09:51   04-mar-05   06:23:27   78   15740   15740   PDS_UNKNOWN_FAILURE   05-mar-05   04:38:36   05-mar-05   04:39:54   78   15747   15747   PDS_UNKNOWN_FAILURE   05-mar-05   04:38:36   05-mar-05   04:39:54   78   15747   15747   PDS_UNKNOWN_FAILURE   09-mar-05   04:12:37   09-mar-05   04:12:37   09-mar-05   04:12:37   09-mar-05   05:26:21   78   15801   15802   PDS_UNKNOWN_FAILURE   09-mar-05   05:26:23   13-mar-05   05:27:40   77   15862   15862   PDS_UNKNOWN_FAILURE   13-mar-05   05:26:23   13-mar-05   05:27:41   1   15862   15862   PDS_UNKNOWN_FAILURE   14-mar-05   04:45:48   14-mar-05   06:25:10   15-mar-05   06:25:10   119   15891   15891   PDS_UNKNOWN_FAILURE   15-mar-05   06:25:10   15-mar-05   06	05-mar-05	15:50:39	05-mar-05	15:51:57	78	15754	15754	PDS_UNKNOWN_FAILURE
06-mar-05   15:19:09   06-mar-05   15:20:27   78   15768   15768   PDS_UNKNOWN_FAILURE   07-mar-05   06:15:28   07-mar-05   05:16:46   78   15776   15776   PDS_UNKNOWN_FAILURE   07-mar-05   16:28:04   07-mar-05   04:32:51   02-mar-05   04:34:09   78   15704   15704   PDS_UNKNOWN_FAILURE   02-mar-05   15:45:03   02-mar-05   04:09:21   78   15714   15711   PDS_UNKNOWN_FAILURE   03-mar-05   04:00:53   03-mar-05   04:02:11   78   15718   15718   PDS_UNKNOWN_FAILURE   03-mar-05   05:09:51   04-mar-05   15:14:32   78   15725   15725   PDS_UNKNOWN_FAILURE   04-mar-05   05:09:51   04-mar-05   16:23:27   78   15740   15740   PDS_UNKNOWN_FAILURE   04-mar-05   04:09:53   04-mar-05   04:39:54   78   15740   15740   PDS_UNKNOWN_FAILURE   05-mar-05   04:38:36   05-mar-05   04:39:54   78   15740   15740   PDS_UNKNOWN_FAILURE   05-mar-05   04:38:36   05-mar-05   04:39:54   78   15740   15740   PDS_UNKNOWN_FAILURE   09-mar-05   15:26:03   09-mar-05   15:47:53   2   15754   15740   PDS_UNKNOWN_FAILURE   09-mar-05   15:26:03   09-mar-05   04:13:55   78   15804   15804   PDS_UNKNOWN_FAILURE   09-mar-05   15:26:03   09-mar-05   04:13:55   78   15804   15804   PDS_UNKNOWN_FAILURE   13-mar-05   05:26:23   13-mar-05   05:27:40   77   15862   15862   PDS_UNKNOWN_FAILURE   13-mar-05   05:27:40   13-mar-05   05:27:40   13-mar-05   05:27:40   13-mar-05   05:27:40   13-mar-05   05:27:40   13-mar-05   05:27:40   13-mar-05   06:25:10   14-mar-05   06:25:10   15-mar-05   04:55:31   78   15890   15890   PDS_UNKNOWN_FAILURE   15-mar-05   06:25:10   04:10:40   04:10:40	06-mar-05		06-mar-05		78	15761	15761	PDS_UNKNOWN_FAILURE
07-mar-05         05:15:28         07-mar-05         05:16:46         78         15776         PDS_UNKNOWN_FAILURE           07-mar-05         16:28:04         07-mar-05         04:32:09         78         15783         15783         PDS_UNKNOWN_FAILURE           02-mar-05         16:32:02         78         15704         15704         PDS_UNKNOWN_FAILURE           02-mar-05         15:45:03         02-mar-05         15:46:21         78         15711         15711         PDS_UNKNOWN_FAILURE           03-mar-05         04:00:33         03-mar-05         04:02:11         78         15718         15718         PDS_UNKNOWN_FAILURE           03-mar-05         05:13:13         03-mar-05         05:11:09         78         15733         15733         PDS_UNKNOWN_FAILURE           04-mar-05         16:22:09         04-mar-05         16:23:27         78         15740         15740         PDS_UNKNOWN_FAILURE           05-mar-05         16:34:751         05-mar-05         16:47:51         2         15754         15747         15747         PDS_UNKNOWN_FAILURE           09-mar-05         15:25:03         09-mar-05         16:23:07         78         15804         15804         PDS_UNKNOWN_FAILURE           13-mar-05         <	06-mar-05	07:14:50	06-mar-05	08:55:12	6022	15763	15764	PDS_UNKNOWN_FAILURE
07-mar-05	06-mar-05	15:19:09	06-mar-05	15:20:27	78	15768	15768	PDS_UNKNOWN_FAILURE
D2-mar-05	07-mar-05	05:15:28	07-mar-05	05:16:46	78	15776	15776	PDS_UNKNOWN_FAILURE
02-mar-05	07-mar-05	16:28:04	07-mar-05	16:29:22	78	15783	15783	PDS_UNKNOWN_FAILURE
03-mar-05   04:00:53   03-mar-05   04:02:11   78   15718   15718   PDS UNKNOWN FAILURE   03-mar-05   15:13:14   03-mar-05   15:14:32   78   15725   15725   PDS UNKNOWN FAILURE   04-mar-05   05:09:51   04-mar-05   06:23:27   78   15740   15740   PDS UNKNOWN FAILURE   05-mar-05   04:38:36   05-mar-05   04:39:54   78   15747   15747   PDS UNKNOWN FAILURE   05-mar-05   15:47:51   05-mar-05   04:39:54   78   15747   15747   PDS UNKNOWN FAILURE   09-mar-05   15:47:51   05-mar-05   04:13:55   78   15804   15804   PDS UNKNOWN FAILURE   09-mar-05   15:25:03   09-mar-05   04:13:55   78   15804   15804   PDS UNKNOWN FAILURE   09-mar-05   05:26:23   13-mar-05   05:27:40   77   15862   15862   PDS UNKNOWN FAILURE   13-mar-05   05:27:40   13-mar-05   05:27:41   1   15862   15862   PDS UNKNOWN FAILURE   13-mar-05   04:55:48   14-mar-05   04:55:48   14-mar-05   04:55:48   14-mar-05   04:55:48   14-mar-05   04:25:31   78   15890   PDS UNKNOWN FAILURE   15-mar-05   06:23:11   15-mar-05   06:25:10   15-mar-05   06:25:22   77   15819   15891   PDS UNKNOWN FAILURE   15-mar-05   06:25:10   15-mar-05   06:25:22   77   15819   15897   PDS UNKNOWN FAILURE   11-mar-05   16:33:58   10-mar-05   16:33:51   6   78   15897   PDS UNKNOWN FAILURE   11-mar-05   16:33:58   10-mar-05   16:33:63   15-mar-05   16:33:63   10-mar-05   16:33:63   10-mar-05   16:33:13   17   15891   15891   PDS UNKNOWN FAILURE   11-mar-05   16:31:31   17   16:31   15891   PDS UNKNOWN FAILURE   11-mar-05   16:31:31   11-mar-05   16:33:53   10-mar-05   16:33:51   16   16:33:13   16   16:33:	02-mar-05	04:32:51	02-mar-05	04:34:09	78	15704	15704	PDS_UNKNOWN_FAILURE
03-mar-05	02-mar-05	15:45:03	02-mar-05	15:46:21	78	15711	15711	PDS_UNKNOWN_FAILURE
04-mar-05 05:09:51 04-mar-05 05:11:09 78 15733 15733 PDS_UNKNOWN_FAILURE 04-mar-05 16:22:09 04-mar-05 16:23:27 78 15740 15740 PDS_UNKNOWN_FAILURE 05-mar-05 04:38:36 05-mar-05 04:39:54 78 15747 15747 PDS_UNKNOWN_FAILURE 05-mar-05 05:07:51 05-mar-05 15:47:53 2 15754 15754 PDS_UNKNOWN_FAILURE 09-mar-05 04:12:37 09-mar-05 04:13:55 78 15804 15804 PDS_UNKNOWN_FAILURE 09-mar-05 05:26:23 13-mar-05 05:27:40 77 15862 15862 PDS_UNKNOWN_FAILURE 13-mar-05 05:27:40 13-mar-05 05:27:41 1 15862 15862 PDS_UNKNOWN_FAILURE 13-mar-05 16:39:22 13-mar-05 16:40:40 78 15869 15869 PDS_UNKNOWN_FAILURE 14-mar-05 04:55:48 14-mar-05 16:842-40 78 15869 15869 PDS_UNKNOWN_FAILURE 15-mar-05 04:24:13 15-mar-05 04:25:31 78 15890 15890 PDS_UNKNOWN_FAILURE 15-mar-05 06:23:11 15-mar-05 04:25:31 78 15891 15891 PDS_UNKNOWN_FAILURE 15-mar-05 06:23:11 15-mar-05 06:25:10 119 15891 15891 PDS_UNKNOWN_FAILURE 15-mar-05 05:27:08 11-mar-05 05:21:22 77 15819 15819 PDS_UNKNOWN_FAILURE 10-mar-05 05:21:05 10-mar-05 05:22:22 77 15819 15890 PDS_UNKNOWN_FAILURE 11-mar-05 05:500 11-mar-05 05:22:22 77 15819 15890 PDS_UNKNOWN_FAILURE 11-mar-05 05:500 11-mar-05 05:22:22 77 15819 15890 PDS_UNKNOWN_FAILURE 11-mar-05 05:500 11-mar-05 05:23:17 78 15897 PDS_UNKNOWN_FAILURE 11-mar-05 05:500 11-mar-05 05:22:22 77 15819 15890 PDS_UNKNOWN_FAILURE 11-mar-05 05:500 11-mar-05 05:23:27 77 15833 15833 PDS_UNKNOWN_FAILURE 11-mar-05 05:500 11-mar-05 05:23:77 15839 15839 PDS_UNKNOWN_FAILURE 11-mar-05 05:500 11-mar-05 05:03:77 15840 15840 PDS_UNKNOWN_FAILURE 11-mar-05 05:500 11-mar-05 05:03:77 15840 15840 PDS_UNKNOWN_FAILURE 11-mar-05 05:510 15-mar-05 16:33:11 15-mar-05 16:30:58 10-mar-05 16:30:16 78 15840 PDS_UNKNOWN_FAILURE 11-mar-05 05:500 11-mar-05 05:03:77 15840 15840 PDS_UNKNOWN_FAILURE 11-mar-05 05:500 11-mar-05 05:03:77 15840 15840 PDS_UNKNOWN_FAILURE 11-mar-05 05:05:05 11-mar-05 05:03:05 537 15838 15839 PDS_UNKNOWN_FAILURE 11-mar-05 15:05:80 11-mar-05 16:03:07 77 15840 15840 PDS_UNKNOWN_FAILURE 11-mar-05 15:05:80 11-mar-05 05:03:05 77 15990 15990 PDS_UNKNOWN_FAILURE 11-mar-05 15	03-mar-05	04:00:53	03-mar-05	04:02:11	78	15718	15718	PDS_UNKNOWN_FAILURE
04-mar-05	03-mar-05	15:13:14	03-mar-05	15:14:32	78	15725	15725	PDS_UNKNOWN_FAILURE
05-mar-05         04:38:36         05-mar-05         04:39:54         78         15747         15747         PDS_UNKNOWN_FAILURE           09-mar-05         16:47:51         05-mar-05         15:47:53         2         15754         15754         PDS_UNKNOWN_FAILURE           09-mar-05         04:12:37         09-mar-05         15:26:21         78         15804         15804         PDS_UNKNOWN_FAILURE           13-mar-05         05:25:03         09-mar-05         05:27:40         77         15862         15802         PDS_UNKNOWN_FAILURE           13-mar-05         05:27:40         13-mar-05         05:27:41         1         15862         PDS_UNKNOWN_FAILURE           13-mar-05         06:27:40         13-mar-05         05:27:41         1         15869         PDS_UNKNOWN_FAILURE           14-mar-05         04:55:48         14-mar-05         16:40:40         78         15869         PDS_UNKNOWN_FAILURE           14-mar-05         04:24:13         15-mar-05         16:08:42         77         15883         15883         PDS_UNKNOWN_FAILURE           15-mar-05         06:23:11         15-mar-05         06:25:10         119         15891         15890         PDS_UNKNOWN_FAILURE           15-mar-05         06:25:10	04-mar-05	05:09:51	04-mar-05	05:11:09	78	15733	15733	PDS_UNKNOWN_FAILURE
05-mar-05	04-mar-05	16:22:09	04-mar-05	16:23:27	78	15740	15740	PDS_UNKNOWN_FAILURE
09-mar-05         04:12:37         09-mar-05         04:13:55         78         15804         15804         PDS_UNKNOWN_FAILURE           09-mar-05         15:25:03         09-mar-05         15:26:21         78         15811         15811         PDS_UNKNOWN_FAILURE           13-mar-05         05:26:23         13-mar-05         05:27:40         77         15862         15862         PDS_UNKNOWN_FAILURE           13-mar-05         05:27:40         13-mar-05         16:40:40         78         15862         15862         PDS_UNKNOWN_FAILURE           14-mar-05         16:39:22         13-mar-05         06:57:06         78         15869         15869         PDS_UNKNOWN_FAILURE           14-mar-05         04:55:48         14-mar-05         04:57:06         78         15876         15876         PDS_UNKNOWN_FAILURE           15-mar-05         04:24:13         15-mar-05         06:25:10         119         15890         15890         PDS_UNKNOWN_FAILURE           15-mar-05         06:23:11         15-mar-05         06:23:11         15-mar-05         19:12:07         10017         15891         15890         PDS_UNKNOWN_FAILURE           15-mar-05         06:25:10         15-mar-05         06:23:11         15         15891	05-mar-05	04:38:36	05-mar-05	04:39:54	78	15747	15747	PDS_UNKNOWN_FAILURE
09-mar-05	05-mar-05	15:47:51	05-mar-05	15:47:53	2	15754	15754	PDS_UNKNOWN_FAILURE
13-mar-05   05:26:23   13-mar-05   05:27:40   77   15862   15862   PDS_UNKNOWN_FAILURE   13-mar-05   05:27:40   13-mar-05   05:27:41   1   15862   15862   PDS_UNKNOWN_FAILURE   13-mar-05   16:39:22   13-mar-05   16:40:40   78   15869   15869   PDS_UNKNOWN_FAILURE   14-mar-05   04:55:48   14-mar-05   04:55:48   14-mar-05   04:55:48   14-mar-05   04:51:40   78   15876   PDS_UNKNOWN_FAILURE   14-mar-05   16:07:25   14-mar-05   16:08:42   77   15883   15883   PDS_UNKNOWN_FAILURE   15-mar-05   04:24:13   15-mar-05   04:25:31   78   15890   15880   PDS_UNKNOWN_FAILURE   15-mar-05   06:23:11   15-mar-05   06:25:10   119   15891   15891   PDS_UNKNOWN_FAILURE   15-mar-05   06:25:10   15-mar-05   06:25:10   119   15891   15893   PDS_UNKNOWN_FAILURE   15-mar-05   06:25:10   15-mar-05   05:21:07   10017   15891   15893   PDS_UNKNOWN_FAILURE   10-mar-05   05:21:05   10-mar-05   05:22:22   77   15819   15819   PDS_UNKNOWN_FAILURE   10-mar-05   16:33:58   10-mar-05   06:25:10   77   15819   15826   PDS_UNKNOWN_FAILURE   11-mar-05   16:33:58   10-mar-05   04:51:23   77   15833   15833   PDS_UNKNOWN_FAILURE   11-mar-05   12:57:08   11-mar-05   13:06:05   537   15838   15838   PDS_UNKNOWN_FAILURE   11-mar-05   16:01:50   11-mar-05   16:03:07   77   15840   15840   PDS_UNKNOWN_FAILURE   11-mar-05   16:01:50   11-mar-05   04:19:46   77   15847   15847   PDS_UNKNOWN_FAILURE   12-mar-05   15:10:16   19-mar-05   15:21:11   119   15957   15957   PDS_UNKNOWN_FAILURE   19-mar-05   21:231:11   19-mar-05   22:25:117   3006   15957   15958   PDS_UNKNOWN_FAILURE   19-mar-05   22:35:27   19-mar-05   05:08:20   78   15962   PDS_UNKNOWN_FAILURE   20-mar-05   06:07:02   20-mar-05   06:03:07   77   15869   15969   PDS_UNKNOWN_FAILURE   21-mar-05   04:32:36   21-mar-05   04:32:38   21-mar-05   04	09-mar-05	04:12:37	09-mar-05	04:13:55	78	15804	15804	PDS_UNKNOWN_FAILURE
13-mar-05   05:27:40   13-mar-05   05:27:41   1   15862   15862   PDS_UNKNOWN_FAILURE   13-mar-05   16:39:22   13-mar-05   16:40:40   78   15869   15869   PDS_UNKNOWN_FAILURE   14-mar-05   04:55:48   14-mar-05   04:57:06   78   15876   15876   PDS_UNKNOWN_FAILURE   15-mar-05   04:25:48   14-mar-05   16:08:42   77   15883   15883   PDS_UNKNOWN_FAILURE   15-mar-05   04:24:13   15-mar-05   04:25:10   119   15890   15890   PDS_UNKNOWN_FAILURE   15-mar-05   06:23:11   15-mar-05   06:25:10   119   15891   15891   PDS_UNKNOWN_FAILURE   15-mar-05   06:25:10   15-mar-05   06:25:10   119   15891   15891   PDS_UNKNOWN_FAILURE   15-mar-05   06:25:10   15-mar-05   09:12:07   10017   15891   15893   PDS_UNKNOWN_FAILURE   15-mar-05   05:21:05   10-mar-05   05:22:22   77   15819   15819   PDS_UNKNOWN_FAILURE   10-mar-05   05:21:05   10-mar-05   05:22:22   77   15819   15819   PDS_UNKNOWN_FAILURE   10-mar-05   04:50:06   11-mar-05   04:51:23   77   15833   15833   PDS_UNKNOWN_FAILURE   11-mar-05   12:57:08   11-mar-05   13:06:05   537   15838   15838   PDS_UNKNOWN_FAILURE   11-mar-05   16:01:50   11-mar-05   16:03:07   77   15840   15840   PDS_UNKNOWN_FAILURE   11-mar-05   04:18:29   12-mar-05   04:19:46   77   15840   15840   PDS_UNKNOWN_FAILURE   12-mar-05   15:30:58   12-mar-05   15:32:16   78   15854   15854   PDS_UNKNOWN_FAILURE   19-mar-05   15:10:16   19-mar-05   21:22:117   3006   15957   15958   PDS_UNKNOWN_FAILURE   19-mar-05   22:35:27   19-mar-05   22:25:19   1012   15958   15968   PDS_UNKNOWN_FAILURE   20-mar-05   04:32:38   21-mar-05   04:35:43   21-mar-05   04:32:38   21-mar-05   04:35:43   21-mar-05   04:32:38   21-mar-05   04:03:49   22-mar-05   04:03:49   22-mar-05   04:03:49   22-mar-05   04:03:49   22-mar-05   04	09-mar-05	15:25:03	09-mar-05	15:26:21	78	15811	15811	PDS_UNKNOWN_FAILURE
13-mar-05	13-mar-05	05:26:23	13-mar-05	05:27:40	77	15862	15862	PDS_UNKNOWN_FAILURE
14-mar-05         04:55:48         14-mar-05         04:57:06         78         15876         PDS_UNKNOWN_FAILURE           14-mar-05         16:07:25         14-mar-05         16:08:42         77         15883         15883         PDS_UNKNOWN_FAILURE           15-mar-05         04:24:13         15-mar-05         04:25:31         78         15890         PDS_UNKNOWN_FAILURE           15-mar-05         06:23:11         15-mar-05         06:25:10         119         15891         15891         PDS_UNKNOWN_FAILURE           15-mar-05         06:25:10         15-mar-05         09:12:07         10017         15891         15893         PDS_UNKNOWN_FAILURE           15-mar-05         15:36:39         15-mar-05         15:37:57         78         15897         PDS_UNKNOWN_FAILURE           10-mar-05         05:21:05         10-mar-05         05:22:22         77         15819         15819         PDS_UNKNOWN_FAILURE           11-mar-05         04:50:06         11-mar-05         05:22:22         77         15839         15826         PDS_UNKNOWN_FAILURE           11-mar-05         16:33:58         10-mar-05         16:35:16         78         15826         15826         PDS_UNKNOWN_FAILURE           11-mar-05         12:57:08<	13-mar-05	05:27:40	13-mar-05	05:27:41	1	15862	15862	PDS_UNKNOWN_FAILURE
14-mar-05         16:07:25         14-mar-05         16:08:42         77         15883         15883         PDS_UNKNOWN_FAILURE           15-mar-05         04:24:13         15-mar-05         04:25:31         78         15890         15890         PDS_UNKNOWN_FAILURE           15-mar-05         06:23:11         15-mar-05         06:25:10         119         15891         15891         PDS_UNKNOWN_FAILURE           15-mar-05         06:25:10         15-mar-05         09:12:07         10017         15891         15893         PDS_UNKNOWN_FAILURE           15-mar-05         15:36:39         15-mar-05         15:37:57         78         15897         PDS_UNKNOWN_FAILURE           10-mar-05         05:21:05         10-mar-05         05:22:22         77         15819         PDS_UNKNOWN_FAILURE           10-mar-05         16:33:58         10-mar-05         16:35:16         78         15826         15826         PDS_UNKNOWN_FAILURE           11-mar-05         04:50:06         11-mar-05         13:06:05         537         15833         15838         PDS_UNKNOWN_FAILURE           11-mar-05         13:13:47         11-mar-05         13:06:05         537         15838         15839         PDS_UNKNOWN_FAILURE           12-mar-05 </td <td>13-mar-05</td> <td>16:39:22</td> <td>13-mar-05</td> <td>16:40:40</td> <td>78</td> <td>15869</td> <td>15869</td> <td>PDS_UNKNOWN_FAILURE</td>	13-mar-05	16:39:22	13-mar-05	16:40:40	78	15869	15869	PDS_UNKNOWN_FAILURE
15-mar-05         04:24:13         15-mar-05         04:25:31         78         15890         PDS         UNKNOWN         FAILURE           15-mar-05         06:23:11         15-mar-05         06:25:10         119         15891         15891         PDS         UNKNOWN         FAILURE           15-mar-05         06:25:10         15-mar-05         09:12:07         10017         15891         15893         PDS         UNKNOWN         FAILURE           15-mar-05         15:36:39         15-mar-05         15:37:57         78         15897         15897         PDS         UNKNOWN         FAILURE           10-mar-05         05:21:05         10-mar-05         05:22:22         77         15819         15819         PDS         UNKNOWN         FAILURE           10-mar-05         16:33:58         10-mar-05         16:35:16         78         15826         15826         PDS         UNKNOWN         FAILURE           11-mar-05         16:33:58         11-mar-05         14:33:13         77         15833         15833         PDS         UNKNOWN         FAILURE           11-mar-05         16:31:31         4766         15838         15839         PDS         UNKNOWN         FAILURE           <	14-mar-05	04:55:48	14-mar-05	04:57:06	78	15876	15876	PDS_UNKNOWN_FAILURE
15-mar-05         06:23:11         15-mar-05         06:25:10         119         15891         15891         PDS UNKNOWN FAILURE           15-mar-05         06:25:10         15-mar-05         09:12:07         10017         15891         15893         PDS UNKNOWN FAILURE           15-mar-05         15:36:39         15-mar-05         15:37:57         78         15897         PDS UNKNOWN FAILURE           10-mar-05         05:21:05         10-mar-05         05:22:22         77         15819         15819         PDS UNKNOWN FAILURE           10-mar-05         16:33:58         10-mar-05         16:35:16         78         15826         15826         PDS UNKNOWN FAILURE           11-mar-05         04:50:06         11-mar-05         04:51:23         77         15833         15838         PDS UNKNOWN FAILURE           11-mar-05         12:57:08         11-mar-05         13:06:05         537         15838         15838         PDS UNKNOWN FAILURE           11-mar-05         16:01:50         11-mar-05         14:33:13         4766         15838         15839         PDS UNKNOWN FAILURE           12-mar-05         16:01:50         11-mar-05         16:03:07         77         15840         15840         PDS UNKNOWN FAILURE	14-mar-05	16:07:25	14-mar-05	16:08:42	77	15883	15883	PDS_UNKNOWN_FAILURE
15-mar-05         06:25:10         15-mar-05         09:12:07         10017         15891         15893         PDS_UNKNOWN_FAILURE           15-mar-05         15:36:39         15-mar-05         15:37:57         78         15897         15897         PDS_UNKNOWN_FAILURE           10-mar-05         05:21:05         10-mar-05         05:22:22         77         15819         PDS_UNKNOWN_FAILURE           10-mar-05         16:33:58         10-mar-05         16:35:16         78         15826         PDS_UNKNOWN_FAILURE           11-mar-05         04:50:06         11-mar-05         04:51:23         77         15833         PDS_UNKNOWN_FAILURE           11-mar-05         12:57:08         11-mar-05         13:06:05         537         15838         PDS_UNKNOWN_FAILURE           11-mar-05         13:13:47         11-mar-05         14:33:13         4766         15838         15839         PDS_UNKNOWN_FAILURE           12-mar-05         16:01:50         11-mar-05         16:03:07         77         15840         15840         PDS_UNKNOWN_FAILURE           12-mar-05         15:30:58         12-mar-05         04:19:46         77         15847         15847         PDS_UNKNOWN_FAILURE           19-mar-05         15:30:58         12-m	15-mar-05	04:24:13	15-mar-05	04:25:31	78	15890	15890	PDS_UNKNOWN_FAILURE
15-mar-05         15:36:39         15-mar-05         15:37:57         78         15897         PDS UNKNOWN FAILURE           10-mar-05         05:21:05         10-mar-05         05:22:22         77         15819         15819         PDS UNKNOWN FAILURE           10-mar-05         16:33:58         10-mar-05         16:35:16         78         15826         PDS UNKNOWN FAILURE           11-mar-05         04:50:06         11-mar-05         04:51:23         77         15833         15833         PDS UNKNOWN FAILURE           11-mar-05         12:57:08         11-mar-05         13:06:05         537         15838         15838         PDS UNKNOWN FAILURE           11-mar-05         13:13:47         11-mar-05         14:33:13         4766         15838         15839         PDS UNKNOWN FAILURE           11-mar-05         16:01:50         11-mar-05         16:03:07         77         15840         15840         PDS UNKNOWN FAILURE           12-mar-05         04:19:46         77         15847         15847         PDS UNKNOWN FAILURE           12-mar-05         15:30:58         12-mar-05         15:32:16         78         15854         PDS UNKNOWN FAILURE           19-mar-05         15:10:16         19-mar-05         15:31:33 </td <td>15-mar-05</td> <td>06:23:11</td> <td>15-mar-05</td> <td>06:25:10</td> <td>119</td> <td>15891</td> <td>15891</td> <td>PDS_UNKNOWN_FAILURE</td>	15-mar-05	06:23:11	15-mar-05	06:25:10	119	15891	15891	PDS_UNKNOWN_FAILURE
10-mar-05         05:21:05         10-mar-05         05:22:22         77         15819         15819         PDS_UNKNOWN_FAILURE           10-mar-05         16:33:58         10-mar-05         16:35:16         78         15826         15826         PDS_UNKNOWN_FAILURE           11-mar-05         04:50:06         11-mar-05         04:51:23         77         15833         15833         PDS_UNKNOWN_FAILURE           11-mar-05         12:57:08         11-mar-05         13:06:05         537         15838         15838         PDS_UNKNOWN_FAILURE           11-mar-05         13:13:47         11-mar-05         14:33:13         4766         15838         15839         PDS_UNKNOWN_FAILURE           11-mar-05         16:01:50         11-mar-05         16:03:07         77         15840         PDS_UNKNOWN_FAILURE           12-mar-05         04:18:29         12-mar-05         04:19:46         77         15847         15847         PDS_UNKNOWN_FAILURE           12-mar-05         15:30:58         12-mar-05         15:32:16         78         15854         15854         PDS_UNKNOWN_FAILURE           19-mar-05         15:10:16         19-mar-05         15:11:33         77         15954         15954         PDS_UNKNOWN_FAILURE	15-mar-05	06:25:10	15-mar-05	09:12:07	10017	15891	15893	PDS_UNKNOWN_FAILURE
10-mar-05         16:33:58         10-mar-05         16:35:16         78         15826         15826         PDS_UNKNOWN_FAILURE           11-mar-05         04:50:06         11-mar-05         04:51:23         77         15833         15833         PDS_UNKNOWN_FAILURE           11-mar-05         12:57:08         11-mar-05         13:06:05         537         15838         15838         PDS_UNKNOWN_FAILURE           11-mar-05         13:13:47         11-mar-05         14:33:13         4766         15838         15839         PDS_UNKNOWN_FAILURE           11-mar-05         16:01:50         11-mar-05         16:03:07         77         15840         15840         PDS_UNKNOWN_FAILURE           12-mar-05         04:18:29         12-mar-05         04:19:46         77         15847         15847         PDS_UNKNOWN_FAILURE           12-mar-05         15:30:58         12-mar-05         15:32:16         78         15854         15854         PDS_UNKNOWN_FAILURE           19-mar-05         15:10:16         19-mar-05         15:11:33         77         15954         15954         PDS_UNKNOWN_FAILURE           19-mar-05         21:31:11         119         15957         15958         PDS_UNKNOWN_FAILURE           19-mar-05	15-mar-05	15:36:39	15-mar-05	15:37:57	78	15897	15897	PDS_UNKNOWN_FAILURE
11-mar-05         04:50:06         11-mar-05         04:51:23         77         15833         15833         PDS_UNKNOWN_FAILURE           11-mar-05         12:57:08         11-mar-05         13:06:05         537         15838         15838         PDS_UNKNOWN_FAILURE           11-mar-05         13:13:47         11-mar-05         14:33:13         4766         15838         15839         PDS_UNKNOWN_FAILURE           11-mar-05         16:01:50         11-mar-05         16:03:07         77         15840         PDS_UNKNOWN_FAILURE           12-mar-05         04:18:29         12-mar-05         04:19:46         77         15847         PDS_UNKNOWN_FAILURE           12-mar-05         15:30:58         12-mar-05         15:32:16         78         15854         15854         PDS_UNKNOWN_FAILURE           19-mar-05         15:10:16         19-mar-05         15:11:33         77         15954         15954         PDS_UNKNOWN_FAILURE           19-mar-05         21:29:12         19-mar-05         21:31:11         119         15957         15958         PDS_UNKNOWN_FAILURE           19-mar-05         22:33:27         19-mar-05         22:52:19         1012         15958         15958         PDS_UNKNOWN_FAILURE           20-mar-05 </td <td>10-mar-05</td> <td>05:21:05</td> <td>10-mar-05</td> <td>05:22:22</td> <td>77</td> <td>15819</td> <td>15819</td> <td>PDS_UNKNOWN_FAILURE</td>	10-mar-05	05:21:05	10-mar-05	05:22:22	77	15819	15819	PDS_UNKNOWN_FAILURE
11-mar-05         12:57:08         11-mar-05         13:06:05         537         15838         15838         PDS_UNKNOWN_FAILURE           11-mar-05         13:13:47         11-mar-05         14:33:13         4766         15838         15839         PDS_UNKNOWN_FAILURE           11-mar-05         16:01:50         11-mar-05         16:03:07         77         15840         15840         PDS_UNKNOWN_FAILURE           12-mar-05         04:18:29         12-mar-05         04:19:46         77         15847         15847         PDS_UNKNOWN_FAILURE           12-mar-05         15:30:58         12-mar-05         15:32:16         78         15854         15854         PDS_UNKNOWN_FAILURE           19-mar-05         15:10:16         19-mar-05         15:11:33         77         15954         15954         PDS_UNKNOWN_FAILURE           19-mar-05         21:31:11         19-mar-05         21:31:11         119         15957         15958         PDS_UNKNOWN_FAILURE           19-mar-05         22:35:27         19-mar-05         22:52:19         1012         15958         15958         PDS_UNKNOWN_FAILURE           20-mar-05         05:07:02         20-mar-05         05:08:20         78         15962         PDS_UNKNOWN_FAILURE	10-mar-05	16:33:58	10-mar-05	16:35:16	78	15826	15826	PDS_UNKNOWN_FAILURE
11-mar-05         13:13:47         11-mar-05         14:33:13         4766         15838         15839         PDS_UNKNOWN_FAILURE           11-mar-05         16:01:50         11-mar-05         16:03:07         77         15840         15840         PDS_UNKNOWN_FAILURE           12-mar-05         04:18:29         12-mar-05         04:19:46         77         15847         15847         PDS_UNKNOWN_FAILURE           12-mar-05         15:30:58         12-mar-05         15:32:16         78         15854         15854         PDS_UNKNOWN_FAILURE           19-mar-05         15:10:16         19-mar-05         15:11:33         77         15954         15954         PDS_UNKNOWN_FAILURE           19-mar-05         21:29:12         19-mar-05         21:31:11         119         15957         15957         PDS_UNKNOWN_FAILURE           19-mar-05         22:33:27         19-mar-05         22:52:19         1012         15958         PDS_UNKNOWN_FAILURE           20-mar-05         05:07:02         20-mar-05         05:08:20         78         15962         PDS_UNKNOWN_FAILURE           21-mar-05         04:32:36         21-mar-05         04:32:38         2         15976         PDS_UNKNOWN_FAILURE           21-mar-05         04:35:43<	11-mar-05	04:50:06	11-mar-05	04:51:23	77	15833	15833	PDS_UNKNOWN_FAILURE
11-mar-05         16:01:50         11-mar-05         16:03:07         77         15840         15840         PDS_UNKNOWN_FAILURE           12-mar-05         04:18:29         12-mar-05         04:19:46         77         15847         15847         PDS_UNKNOWN_FAILURE           12-mar-05         15:30:58         12-mar-05         15:32:16         78         15854         15854         PDS_UNKNOWN_FAILURE           19-mar-05         15:10:16         19-mar-05         15:11:33         77         15954         15954         PDS_UNKNOWN_FAILURE           19-mar-05         21:29:12         19-mar-05         21:31:11         119         15957         15957         PDS_UNKNOWN_FAILURE           19-mar-05         22:31:17         3006         15957         15958         PDS_UNKNOWN_FAILURE           19-mar-05         22:35:27         19-mar-05         22:52:19         1012         15958         15958         PDS_UNKNOWN_FAILURE           20-mar-05         05:07:02         20-mar-05         05:08:20         78         15962         15962         PDS_UNKNOWN_FAILURE           21-mar-05         04:32:36         21-mar-05         04:32:38         2         15976         PDS_UNKNOWN_FAILURE           21-mar-05         04:35:43	11-mar-05	12:57:08	11-mar-05	13:06:05	537	15838	15838	PDS UNKNOWN FAILURE
12-mar-05         04:18:29         12-mar-05         04:19:46         77         15847         15847         PDS_UNKNOWN_FAILURE           12-mar-05         15:30:58         12-mar-05         15:32:16         78         15854         15854         PDS_UNKNOWN_FAILURE           19-mar-05         15:10:16         19-mar-05         15:11:33         77         15954         15954         PDS_UNKNOWN_FAILURE           19-mar-05         21:29:12         19-mar-05         21:31:11         119         15957         15957         PDS_UNKNOWN_FAILURE           19-mar-05         21:31:11         19-mar-05         22:21:17         3006         15957         15958         PDS_UNKNOWN_FAILURE           19-mar-05         22:35:27         19-mar-05         22:52:19         1012         15958         15958         PDS_UNKNOWN_FAILURE           20-mar-05         05:07:02         20-mar-05         05:08:20         78         15962         PDS_UNKNOWN_FAILURE           21-mar-05         04:32:36         21-mar-05         04:32:38         2         15976         PDS_UNKNOWN_FAILURE           21-mar-05         04:35:43         21-mar-05         04:37:01         78         15983         PDS_UNKNOWN_FAILURE           21-mar-05         04:03:49<	11-mar-05	13:13:47	11-mar-05	14:33:13	4766	15838	15839	PDS_UNKNOWN_FAILURE
12-mar-05         15:30:58         12-mar-05         15:32:16         78         15854         15854         PDS_UNKNOWN_FAILURE           19-mar-05         15:10:16         19-mar-05         15:11:33         77         15954         15954         PDS_UNKNOWN_FAILURE           19-mar-05         21:29:12         19-mar-05         21:31:11         119         15957         15957         PDS_UNKNOWN_FAILURE           19-mar-05         21:31:11         19-mar-05         22:21:17         3006         15957         15958         PDS_UNKNOWN_FAILURE           19-mar-05         22:35:27         19-mar-05         22:52:19         1012         15958         15958         PDS_UNKNOWN_FAILURE           20-mar-05         05:07:02         20-mar-05         05:08:20         78         15962         PDS_UNKNOWN_FAILURE           20-mar-05         16:19:12         20-mar-05         16:20:29         77         15969         PDS_UNKNOWN_FAILURE           21-mar-05         04:32:36         21-mar-05         04:32:38         2         15976         PDS_UNKNOWN_FAILURE           21-mar-05         04:35:43         21-mar-05         04:37:01         78         15983         15983         PDS_UNKNOWN_FAILURE           22-mar-05         04:03:49<	11-mar-05	16:01:50	11-mar-05	16:03:07	77	15840	15840	PDS UNKNOWN FAILURE
12-mar-05         15:30:58         12-mar-05         15:32:16         78         15854         15854         PDS_UNKNOWN_FAILURE           19-mar-05         15:10:16         19-mar-05         15:11:33         77         15954         15954         PDS_UNKNOWN_FAILURE           19-mar-05         21:29:12         19-mar-05         21:31:11         119         15957         15957         PDS_UNKNOWN_FAILURE           19-mar-05         21:31:11         19-mar-05         22:21:17         3006         15957         15958         PDS_UNKNOWN_FAILURE           19-mar-05         22:35:27         19-mar-05         22:52:19         1012         15958         15958         PDS_UNKNOWN_FAILURE           20-mar-05         05:07:02         20-mar-05         05:08:20         78         15962         PDS_UNKNOWN_FAILURE           20-mar-05         16:19:12         20-mar-05         16:20:29         77         15969         PDS_UNKNOWN_FAILURE           21-mar-05         04:32:36         21-mar-05         04:32:38         2         15976         PDS_UNKNOWN_FAILURE           21-mar-05         04:35:43         21-mar-05         04:37:01         78         15983         15983         PDS_UNKNOWN_FAILURE           22-mar-05         04:03:49<	12-mar-05	04:18:29	12-mar-05	04:19:46	77	15847	15847	PDS UNKNOWN FAILURE
19-mar-05         21:29:12         19-mar-05         21:31:11         119         15957         15957         PDS_UNKNOWN_FAILURE           19-mar-05         21:31:11         19-mar-05         22:21:17         3006         15957         15958         PDS_UNKNOWN_FAILURE           19-mar-05         22:35:27         19-mar-05         22:52:19         1012         15958         15958         PDS_UNKNOWN_FAILURE           20-mar-05         05:07:02         20-mar-05         05:08:20         78         15962         PDS_UNKNOWN_FAILURE           20-mar-05         16:19:12         20-mar-05         16:20:29         77         15969         PDS_UNKNOWN_FAILURE           21-mar-05         04:32:36         21-mar-05         04:32:38         2         15976         PDS_UNKNOWN_FAILURE           21-mar-05         04:35:43         21-mar-05         04:37:01         78         15976         PDS_UNKNOWN_FAILURE           21-mar-05         15:47:51         21-mar-05         15:49:09         78         15983         15983         PDS_UNKNOWN_FAILURE           22-mar-05         04:03:49         22-mar-05         04:05:06         77         15990         15990         PDS_UNKNOWN_FAILURE			12-mar-05	15:32:16	78	15854	15854	PDS_UNKNOWN_FAILURE
19-mar-05         21:29:12         19-mar-05         21:31:11         119         15957         15957         PDS_UNKNOWN_FAILURE           19-mar-05         21:31:11         19-mar-05         22:21:17         3006         15957         15958         PDS_UNKNOWN_FAILURE           19-mar-05         22:35:27         19-mar-05         22:52:19         1012         15958         15958         PDS_UNKNOWN_FAILURE           20-mar-05         05:07:02         20-mar-05         05:08:20         78         15962         PDS_UNKNOWN_FAILURE           20-mar-05         16:19:12         20-mar-05         16:20:29         77         15969         PDS_UNKNOWN_FAILURE           21-mar-05         04:32:36         21-mar-05         04:32:38         2         15976         PDS_UNKNOWN_FAILURE           21-mar-05         04:35:43         21-mar-05         04:37:01         78         15976         PDS_UNKNOWN_FAILURE           21-mar-05         15:47:51         21-mar-05         15:49:09         78         15983         15983         PDS_UNKNOWN_FAILURE           22-mar-05         04:03:49         22-mar-05         04:05:06         77         15990         PDS_UNKNOWN_FAILURE	19-mar-05	15:10:16	19-mar-05	15:11:33	77	15954	15954	PDS UNKNOWN FAILURE
19-mar-05         21:31:11         19-mar-05         22:21:17         3006         15957         15958         PDS_UNKNOWN_FAILURE           19-mar-05         22:35:27         19-mar-05         22:52:19         1012         15958         15958         PDS_UNKNOWN_FAILURE           20-mar-05         05:07:02         20-mar-05         05:08:20         78         15962         15962         PDS_UNKNOWN_FAILURE           20-mar-05         16:19:12         20-mar-05         16:20:29         77         15969         PDS_UNKNOWN_FAILURE           21-mar-05         04:32:36         21-mar-05         04:32:38         2         15976         PDS_UNKNOWN_FAILURE           21-mar-05         04:35:43         21-mar-05         04:37:01         78         15976         PDS_UNKNOWN_FAILURE           21-mar-05         15:47:51         21-mar-05         15:49:09         78         15983         15983         PDS_UNKNOWN_FAILURE           22-mar-05         04:03:49         22-mar-05         04:05:06         77         15990         15990         PDS_UNKNOWN_FAILURE		21:29:12	19-mar-05		119		1	PDS UNKNOWN FAILURE
20-mar-05         05:07:02         20-mar-05         05:08:20         78         15962         15962         PDS_UNKNOWN_FAILURE           20-mar-05         16:19:12         20-mar-05         16:20:29         77         15969         PDS_UNKNOWN_FAILURE           21-mar-05         04:32:36         21-mar-05         04:32:38         2         15976         15976         PDS_UNKNOWN_FAILURE           21-mar-05         04:35:43         21-mar-05         04:37:01         78         15976         15976         PDS_UNKNOWN_FAILURE           21-mar-05         15:47:51         21-mar-05         15:49:09         78         15983         15983         PDS_UNKNOWN_FAILURE           22-mar-05         04:03:49         22-mar-05         04:05:06         77         15990         15990         PDS_UNKNOWN_FAILURE	19-mar-05	21:31:11	19-mar-05	22:21:17	3006	15957	15958	PDS UNKNOWN FAILURE
20-mar-05         05:07:02         20-mar-05         05:08:20         78         15962         15962         PDS_UNKNOWN_FAILURE           20-mar-05         16:19:12         20-mar-05         16:20:29         77         15969         PDS_UNKNOWN_FAILURE           21-mar-05         04:32:36         21-mar-05         04:32:38         2         15976         15976         PDS_UNKNOWN_FAILURE           21-mar-05         04:35:43         21-mar-05         04:37:01         78         15976         15976         PDS_UNKNOWN_FAILURE           21-mar-05         15:47:51         21-mar-05         15:49:09         78         15983         15983         PDS_UNKNOWN_FAILURE           22-mar-05         04:03:49         22-mar-05         04:05:06         77         15990         15990         PDS_UNKNOWN_FAILURE	19-mar-05	22:35:27	19-mar-05	22:52:19	1012	15958	15958	PDS UNKNOWN FAILURE
20-mar-05         16:19:12         20-mar-05         16:20:29         77         15969         15969         PDS_UNKNOWN_FAILURE           21-mar-05         04:32:36         21-mar-05         04:32:38         2         15976         15976         PDS_UNKNOWN_FAILURE           21-mar-05         04:35:43         21-mar-05         04:37:01         78         15976         PDS_UNKNOWN_FAILURE           21-mar-05         15:47:51         21-mar-05         15:49:09         78         15983         PDS_UNKNOWN_FAILURE           22-mar-05         04:03:49         22-mar-05         04:05:06         77         15990         15990         PDS_UNKNOWN_FAILURE							1	
21-mar-05         04:32:36         21-mar-05         04:32:38         2         15976         15976         PDS_UNKNOWN_FAILURE           21-mar-05         04:35:43         21-mar-05         04:37:01         78         15976         15976         PDS_UNKNOWN_FAILURE           21-mar-05         15:47:51         21-mar-05         15:49:09         78         15983         15983         PDS_UNKNOWN_FAILURE           22-mar-05         04:03:49         22-mar-05         04:05:06         77         15990         15990         PDS_UNKNOWN_FAILURE								
21-mar-05       04:35:43       21-mar-05       04:37:01       78       15976       15976       PDS_UNKNOWN_FAILURE         21-mar-05       15:47:51       21-mar-05       15:49:09       78       15983       15983       PDS_UNKNOWN_FAILURE         22-mar-05       04:03:49       22-mar-05       04:05:06       77       15990       15990       PDS_UNKNOWN_FAILURE							1	
21-mar-05         15:47:51         21-mar-05         15:49:09         78         15983         15983         PDS_UNKNOWN_FAILURE           22-mar-05         04:03:49         22-mar-05         04:05:06         77         15990         15990         PDS_UNKNOWN_FAILURE							1	
22-mar-05 04:03:49 22-mar-05 04:05:06 77 15990 15990 PDS_UNKNOWN_FAILURE								
							1	
22-mai-uo   15:16:11   22-mai-u5   15:17:29   - 78 -   15997   15997   PDS UNKNOWN FAILURE	22-mar-05	15:16:11	22-mar-05	15:17:29	78	15997	15997	PDS_UNKNOWN_FAILURE



Envisat Cyclic Altimetric Report issue 1 revision 0 – 18 March 2005 ENVI-GSOP-EOPG-03-0011 page 21 of 41

23-mar-05	05:10:27	23-mar-05	05:10:29	2	16005	16005	PDS_UNKNOWN_FAILURE
23-mar-05	05:12:39	23-mar-05	05:13:57	78	16005	16005	PDS_UNKNOWN_FAILURE
23-mar-05	16:25:07	23-mar-05	16:26:24	77	16012	16012	PDS_UNKNOWN_FAILURE
18-mar-05	04:29:58	18-mar-05	04:35:34	336	15933	15933	PDS_UNKNOWN_FAILURE
18-mar-05	12:58:00	18-mar-05	12:59:06	66	15938	15938	PDS_UNKNOWN_FAILURE
18-mar-05	15:42:15	18-mar-05	15:43:32	77	15940	15940	PDS_UNKNOWN_FAILURE
19-mar-05	03:57:56	19-mar-05	03:59:13	77	15947	15947	PDS_UNKNOWN_FAILURE
24-mar-05	04:41:29	24-mar-05	04:42:46	77	16019	16019	PDS_UNKNOWN_FAILURE
24-mar-05	15:53:27	24-mar-05	15:54:44	77	16026	16026	PDS_UNKNOWN_FAILURE
25-mar-05	04:09:41	25-mar-05	04:10:59	78	16033	16033	PDS_UNKNOWN_FAILURE
25-mar-05	15:22:06	25-mar-05	15:23:24	78	16040	16040	PDS_UNKNOWN_FAILURE
25-mar-05	18:47:32	25-mar-05	20:28:15	6043	16042	16043	PDS_UNKNOWN_FAILURE
26-mar-05	05:18:16	26-mar-05	05:19:34	78	16048	16048	PDS_UNKNOWN_FAILURE
26-mar-05	11:46:09	26-mar-05	13:24:44	5915	16052	16053	PDS_UNKNOWN_FAILURE
26-mar-05	16:31:02	26-mar-05	16:32:19	77	16055	16055	PDS_UNKNOWN_FAILURE
26-mar-05	16:41:12	26-mar-05	18:16:01	5689	16055	16056	PDS_UNKNOWN_FAILURE
27-mar-05	04:47:14	27-mar-05	04:48:31	77	16062	16062	PDS_UNKNOWN_FAILURE

Table 9: List of gaps for RA-2 L1b products during cycle 35

### 8.2 RA-2 Altimeter Parameters

Hereafter a summary of the main Altimetric parameters performances is reported; these results have been obtained with the editing criteria mentioned in par. 8.3.

### 8.2.1 ALTIMETER RANGE

The monitoring of the RA-2 FD altimetric range shall be done once the NRT products shall be upgraded with the DORIS navigator NRT orbital information. For NRT products there are no current results for the time being.

### 8.2.2 SIGNIFICANT WAVE HEIGHT

The histogram of the SWH, reported in Figure 13, shows a nominal behavior for this cycle. The trend goes on following the behavior shown in the cycle 33 and 34, where the peaks of Ku and S bands SWH histograms are closer to each other.

Figure 14 shows the SWH daily mean. The possible high values, sometimes plotted outside the figure range, reported for the S-Band data are due to the so-called S-Band anomaly (ref. par.7.1.7).








Figure 13: Histogram of Ku and S Band SWH for cycle 35 (mm)




Figure 14: Ku and S SWH daily average for cycle 35 (mm)





### 8.2.3 BACKSCATTER COEFFICIENT – WIND SPEED

The Sigma\_0 histogram both in Ku and S Band shows secondary peaks. A small investigation on this problem, performed on the data of cycle 28, demonstrated that the backscattering distribution assumes a different behavior for different sea conditions. Indeed, for both bands, the majority of the data is concentrated on lower values for rough sea state (southern hemisphere, winter conditions) and on higher values for calm sea state (northern hemisphere, summer conditions).

In Figure 16, the backscattering coefficient daily average trend is reported. The trend shows a nominal behavior for both bands. The high daily means (sometimes plotted outside the figure range) reported for the S-Band Sigma 0 are due to the so-called S-Band anomaly (ref. par. 7.1.7).

The histogram of Wind Speed computed for the Ku-band and the time behavior during cycle 35 are reported in Figure 17 and Figure 18, respectively. They are similar to the previous cycle.




Figure 15: Histogram of Ku and S Band Backscattering Coefficient for cycle 35 (dB/100)






Figure 16: Ku and S Sigma\_0 daily average for cycle 35 (dB/100)




Figure 17: Histogram of Ku Wind Speed for cycle 35 (mm/s)








Figure 18: Ku Band Wind Speed daily average for cycle 35 (mm/s)

#### 8.3 Edited measurements

In order to produce the statistics reported in 8.2 the following editing criteria have been used before using RA2 FGD products:

Parameter	Surface type	Zone	Range
Ku SWH	Open Ocean	All world	[0, 10] (m)
Ku Backscattering Coeff.	Open ocean	All world	[7, 17] (dBs)
Ku Wind Speed	Open ocean	All world	[0, 20] (m/s)

Table 10: Editing criteria for RA-2 parameters statistics

#### 8.4 Product disclaimer

For the product disclaimers please refer to the following web link: http://envisat.esa.int/dataproducts/availability/



issue 1 revision 0 - 18 March 2005 ENVI-GSOP-EOPG-03-0011 page 26 of 41

### Data handling recommendations 8.5

#### 8.5.1 SEA-ICE FLAG

The following algorithm is proposed for the determination of a sea-ice flag, presently missing in the Level 2 Ra-2 and MWR data products. (See [R - 14]):

|Latitude (lat: field#4 of L2 data)| >50 deg

The number of 20Hz valid data (num 18hz ku ocean: field#23 of L2 data) < 17

MWR Wet Tropospheric Correction (mwr wet tropo corr: field#42 of L2 data)-ECMWF Wet Tropospheric Correction (mod wet tropo corr: field#41 of L2 data)| > 10 cm

Peakiness (Ku peak: field#139 of L2 data) >2

#### 8 5 2 OCEAN S-BAND ANOMALIES DETECTION

A valuable algorithm to detect the Level 2 DSR affected by the RA-2 S-Band anomaly is proposed in [R-12]. Note that its validity is limited to the data acquired over open-ocean.

#### 8.5.3 WARNING ON IPF 4.56 VERSION IDENTIFICATION FIELD

All RA-2 and MWR level 1B and NRT Level 2 products generated after November 26, 2003 report a software version as being 4.54 (available in MPH field 8).

Nevertheless those products have been generated with the IPF V4.56 operational since November 26, 2003. The first nominal generated product, using the new SW version, will be the one relevant to the absolute orbit number 9094.

The software version ID is correct since December 4, 2003.

#### S-BAND BACKSCATTERING COEFFICIENT 8.5.4

For the data processed with IPF version 4.56 on, the S-Band Backscattering coefficient has been demonstrated to be in average about 0.65 dBs higher than for the previous versions of the processor. This is due to the algorithm used for the retrieval of the AGC in S-Band, corrected in IPF version 4.56 to be more coherent with the real functioning of the instrument.

An average value of 0.65 dBs is suggested to be added to the old software versions S-Band Sigma0 in order to be in line with the new IPF V4.56 version.

#### USO RANGE CORRECTION 8.5.5

The actual data of cycle 35 have to be corrected to compensate for the Ultra Stable Oscillator drift shown in Figure 3. The measured Range shall be corrected considering a drift of -6.59 mm per



year. Eventually it could also be corrected for the cyclic average given bias of 25.32 mm that has to be added to the measured value.

#### 8.5.6 KU-BAND BACKSCATTERING COEFFICIENT CALIBRATION

The results of the Ku-Band Sigma0 absolute calibration performed with a transponder have been presented in par. 7.1.4. Those results are going to be consolidated and are summarized on chapter 9.1.4. In order to absolutely calibrate the backscattering coefficient given in the RA2 L2 products the following shall be used by the end user to get to the real Sigma0 measurement:

Sigma 0 true = Sigma 0 prod + G tx rx prod - G\_tx\_rx\_real - Bias [dB]

Where:

**Bias**: Bias retrieved from the Sigma OAbsolute Calibration (see 9.1.4)

G tx rx prod: Current effective Tx-Rx Gain value used in the operational ground processing chain (ADF file RA2 CHD AX). The value nominally used since IPF V4.54 is (for configuration RFSS=A and HPA=A) is 170.70 dB

G tx rx real: Pre-launch characterization value (configuration value RFSS=A and HPA=A is 167.46 dB)

### 8.5.7 ABNORMAL RA-2 RANGE BEHAVIOR AFTER ANOMALY **RECOVERY**

An un-expected behavior of the Envisat RA-2 sensor was observed in the period from 2004/09/27 at ~16:00 and ending on 2004/09/29 at ~12:00 AM. This directly happened after the recovery of a RA-2 on-board anomaly occurred on the 2004/09/26 at ~13:40. The altimetric range jumped by several meters w.r.t. the Mean Sea Surface; on the other hand everything came back to normal as from the 29th of September around noon. RA-2 data from the above period have to be considered with caution.

### 8.6 Wind & Wave quality assessment

Refer to the ECMWF report given in [R - 9a] and [R-9b].

#### 9 LONG TERM MONITORING

### 9.1 RA-2 Instrument monitoring

#### IF FILTER MASK 9.1.1

In Figure 19 the evolution of the IF mask quality parameters evaluated as in [R-4] is reported only for valid data. It can be observed that the difference with respect to the on-ground reference stays quite constant around 0.07 dBs but a small increase is visible on the plot for the last three cycles.



Three peaks are visible on the plot that correspond to the data acquired on September the 27<sup>th</sup> 2003 at 15:48, on October the 29<sup>th</sup> 2003 at 15:42 and on May the 10<sup>th</sup> 2004 at 15:45. The reason of this could be found in the instrument warming up considering that the IF Cal acquisition has been made, in all the cases, only a couple of hours after an anomaly recovery. The residual noise and the accuracy show a very constant behavior over the whole period.

A weird behavior has been observed during the validation of several newly created IF mask correction auxiliary files. After an investigation, it has been recently found out that the phenomenon was due to an error done by the operator while manually creating the auxiliary files. During cycle 35 the IF Calibration Mode still shows the weird behavior described in [R-3]. This problem, present since the beginning of the mission, is under investigation. The anomaly directly affects the number of valid RA-2 IF masks obtained per cycle, but does not refrain from the generation of the IF mask correction file, used in input to the Level 1B ground processing.




Figure 19: Evolution of the IF mask related parameters for valid IF masks retrieved up to cycle 35

In Figure 19A the percentages of valid IF masks from cycle 20 up to cycle 35 are reported.








Figure 19A: Percentages of valid IF Mask up to cycle 35

### 9.1.2 USO

In Figure 20 the USO clock period trend retrieved until the end of cycle 35 is reported. In order to make the variability visible, the difference of the actual USO clock period with respect to the nominal one has been plotted, in the upper panel. In the lower panel the Range error due to the USO clock variability has been reported taking a satellite altitude of 800 Km as a nominal value.

Currently the nominal USO clock period (12500 ps) is used within the processing, this means that the data are not corrected for the bias and the drift correlated to the actual USO clock period. Those values, translated into altimetric range figures, are respectively of 31.23 mm and –4.697 mm/year as calculated with data covering the period 13 June 2003 to 21 February 2005 (the data covering the anomalous period between 2004/09/27 at ~16:00 and 2004/09/29 at ~12:00 AM have not been used to evaluate these figures). The given bias and drift have to be added to the original altimetric range.








Figure 20: USO clock period until end of cycle 35

### 9.1.3 TRACKING CAPABILITY

In Figure 21, Figure 22 and Figure 23 the cyclic tracking percentages for the three RA-2 bandwidths are reported.

The worsening in performances noticeable for cycle 20 was due to the up-load of wrong on-board software parameters for the lasted for about three days.

In general, even if a tiny evolution can be observed, the tracking performances are well in line with the output figures and objectives of the Commissioning Phase as given in par. 7.1.3.






Figure 21: RA-2 Tracking percentage at 320MHz for different surfaces




Figure 22: RA-2 Tracking percentage at 80MHz for different surfaces








Figure 23: RA-2 Tracking percentage at 20MHz for different surfaces

#### 9.1.4 SIGMA0 ABSOLUTE CALIBRATION

Table 11 reports the transponder measurement from cycle 24 up to cycle 35. Since December 2004 all the acquisitions have been performed in High Resolution Mode (320 MHz). The mean value of the estimated bias at High Resolution is 0.955 dB with a standard deviation of 0.047 dB. It is possible to notice that the Low Resolution measurement are coherent among themselves but there is a bias with respect to the High Resolution ones. This is probably due to a processing problem with the internal calibration factor not taken into account in Low Resolution Mode. The problem shall be investigated.

Absolute Orbit nb	Date of Measurement	Location / Rel. track	RA-2 resolution	Transponder Bias [dB]	In flight cal.fact. [dB]	ECMWF Wet Tropo. Corr. [dB]
10389	24-feb-04	Rome / 315	Low	1.552	0.59	0.120
10511	04-mar-04	Valmontone / 437	Low	1.542	0.59	0.102
10618	11-mar-04	Fiuggi / 43	Low	1.447	0.58	0.135
10783	23-mar-04	Maccarese / 208	Low	1.540	0.62	0.141
10890	30-mar-04	Rome / 315	Low	1.442	0.58	0.152
11119	15-apr-04	Fiuggi / 43	High	0.963	0.56	0.122
11513	13-mag-04	Valmontone / 437	Low	1.353	0.56	0.133
11620	20-mag-04	Fiuggi / 43	Low	1.417	0.55	0.139
11892	08-giu-04	Rome / 315	Low	1.504	0.55	0.154
12014	17-giu-04	Valmontone / 437	Low	1.448	0.54	0.348
12121	24-giu-04	Fiuggi / 43	Low	1.576	0.54	0.149
14290	23-nov-04	Maccarese / 208	Low	1.43	0.45	0.164



**Envisat Cyclic Altimetric Report** 

14397	30-nov-04	Rome / 315	Low	1.11	0.44	0.142
14519	9-dic-04	Valmontone / 437	Low	1.26	0.44	0.248
14791	28-dic-04	Maccarese / 208	High	0.97	0.45	0.134
14898	4-gen-05	Rome / 315	High	0.95	0.47	0.114
15020	13-gen-05	Valmontone / 437	High	0.88	0.49	0.118
15127	20-gen-05	Fiuggi / 43	High	1.01	0.49	0.108
15292	1-feb-05	Maccarese / 208	High	0.95	0.49	0.132
15399	8-feb-05	Rome / 315	High	1.05	0.48	0.124
15521	17-feb-05	Valmontone / 437	High	0.94	0.51	0.115
15793	8-mar-05	Maccarese / 208	High	0.93	0.52	0.116
15900	15-mar-05	Rome / 315	High	0.93	0.49	0.128
16022	24-mar-05	Valmontone / 437	High	0.94	0.50	0.154

Table 11: Transponder measurement results up to cycle 35

In Figure 24 the time behavior of the bias is plotted for both Low and High Resolution. The green line represents the corrected bias for the internal calibration factor (only for the Low Resolution data) and the tropospheric attenuation. The latter is estimated by using the ECMWF meteorological data. The low value of the corrected bias for the orbit 14397 is due to the dew air condition and a probable underestimation of the tropo-attenuation.




Figure 24: Time behavior of the transponder bias

#### 9.1.5 **DATATION**

In Figure 25 (upper panel) the differences between the extrapolated UTC values and the corresponding real UTC values measured at the next Kiruna dump, are reported.



The plots are only related to the data collected up to cycle 32. The UTC deviation for the cycle 33 and cycle 35 have been not added. The datation plots and comments pertinent to the cylce 35 are reported in par. 7.1.5.

Only few anomalous events can be observed at the beginning of the period (cycles 16/17) for which the difference rises above the 20 microseconds warning threshold. However, starting from cycles 22/23, the number of small differences (10 microseconds plus or minus) has increased a lot. Furthermore, during the last ten days of the cycle 32 and for all cycle 33 and 34, the variability of the deviations has increased reporting many peaks just over the 20 microseconds threshold; this phenomenon is now fixed. In the lower panel the ICU clock step for the same period is shown where big variations are reported. This is however not a problem because the ICU clock period variations are included in the algorithm for the SBT/UTC correlation evaluation.




Figure 25: UTC deviations and ICU clock period up to cycle 32

#### 9.1.6 **MISPOINTING**

In Figure 26 the overall mispointing squared trend (averaged over each orbit) is plotted for cycles 16 to 32. The jump occurred on November the 26<sup>th</sup> 2003 is correlated to the upload of IPF version 4.56; the abrupt decreasing of the mispointing squared value is due to the usage of a new RA2 IFF AX IF mask auxiliary file. After the drop a very tiny increase of the mispointing squared could eventually be detectable. The most probable cause of this phenomenon could be a change in the Intermediate Frequency Filter slope due to ageing effects.

On the other hand, it can be noticed that the mispointing squared assumes lower values just after an instrument anomaly, showing an increasing trend until it reaches back a standard mispointing value. This particular behavior can be explained by the different shape that the over-ocean average waveform has before and after an anomalous event as visible in Figure 27. Observe, in particular,





the disappearance of the small dip in the waveforms acquired after the anomaly. This problem will be solved with the introduction of an updated mispointing retrieval algorithm with the next version of the processing software as described in par. 5.4.4.




Figure 26: Smoothed mispointing squared trend until end of cycle 35 (deg^2\*10e-4)




Figure 27: Open Ocean average waveforms before (left) and after an anomaly (right)





#### 9.1.7 S-BAND ANOMALY

In Figure 28 the percentage of data per cycle that are affected by the so-called "S-Band" anomaly is reported. The figures are quite stable between 0% and 8.1%.

The relatively high value recorded for cycle 27 is due to the fact that on the day 1<sup>st</sup> of June 2004, the S-band anomaly started at around 14:30 while the instrument didn't switch to mode Heater 2 when foreseen (at about 15:50). For this reason the S-Band anomaly continued for the next 24 hours until the next Heater 2 mode on June the 2<sup>nd</sup>.




Figure 28: Percentage of data affected by the "S-Band Anomaly" for cycles 16-35

#### 9.1.8 IN-FLIGHT INTERNAL CALIBRATION

Figure 29 and Figure 20 report Ku and S Band in-flight calibration factors for Time Delay and Sigma0 respectively, daily averaged, up to the current cycle. The Time Delay factor shows to be very stable for both the working frequencies. The Ku band Sigma0 factor reveals a decrease of about 0.2 dBs over the period starting from cycle 16, but a light increase is visible for the last three months. Being the factor instability quite small this is not being considered a problem, for the moment, since the calibration factor is indeed introduced especially to correct for eventual instrumental changes. However a special eye is kept on the monitoring of this parameter.






Figure 29: Ku and S Band in-flight time delay calibration factor up to cycle 35




Figure 30: Ku and S Band in-flight Sigma0 calibration factor up to cycle 35





### 9.2 **Products Monitoring**

#### **AVAILABILITY OF DATA** 9.2.1

Hereafter the percentage of the different levels of products availability is reported up to the cycle 35. Considering as reference the instrument unavailability, it is possible to notice that in the last three cycles the situation is slightly improved for all levels of products.




Figure 31: Percentage of Products unavailability up to cycle 35

#### **RA-2 ALTIMETER PARAMETERS** 9.2.2

Hereafter a summary of the main altimetric parameters performances is reported; these results have been obtained with the editing criteria mentioned in par. 8.3.

# 9.2.2.1 Altimeter range

The monitoring of the RA-2 FD altimetric range shall be done once the NRT products shall be upgraded with the DORIS navigator NRT orbital information. For NRT products there are no current results for the time being.





# 9.2.2.2 Significant Wave Height

The SWH in both bands shows a small drop, of about 10 cm, on the July the 2<sup>nd</sup> 2004. After a detailed analysis that drop can be now interpreted more like a smoother decrease which can be correlated to a seasonal variability as it could be observed during the year 2003.

On the other hand, the S-Band SWH shows a drop on April the 9<sup>th</sup> 2003 corresponding to the operational up-load of IPF version 4.54; furthermore the high daily means reported (sometimes plotted outside the figure range) are due to the so-called S-Band anomaly (ref. par.7.1.7).




Figure 32: Ku and S SWH daily average up to cycle 35 (mm)

# 9.2.2.3 Backscatter coefficient – Wind Speed

The Ku-Band Sigma\_0 trend, reported hereafter, is characterized by a jump of in average 3.24 dBs concomitant with the operational up-load of IPF version 4.54 occurred on the 9<sup>th</sup> of April 2003. To be said that this change is due to the upload of a new RA2\_CHD\_AX ADF file that artificially shifted the RA-2 real Sigma 0 in order to align it with ERS-2 Sigma 0 and make it coherent with



the Witter and Chelton empirical wind model. A similar change in trend, but in the opposite direction, is also visible in the Wind Speed trend reported afterwards.

Beyond the huge jump occurred in April 2003, the S-Band Sigma\_0 reports a smaller jump occurring on November the 26<sup>th</sup> 2003. Following the installation of the IPF processing chain V4.56, the average values of the RA-2 S-Band backscattering parameter, shows an increase of ~0.65 dBs, the new S-band sigma0 being higher with respect to the previous versions. See chapter 8.5.4.




Figure 33: Ku and S band Backscattering daily averages up to cycle 35 (dB/100)








Figure 34: Wind Speed daily averages up to cycle 35 (mm/s)

### 10 PARTICULAR INVESTIGATIONS

During cycle 35 no special investigation has been performed.