



# IDEAS+ Daily Report for OFFLINE data:

20/09/2018

1. Overview				
	10.0.1.0010	Check	Status	
Report Production Date:	19-Oct-2018	Server check: science-pds.cryosat.esa.int	Nominal	
Processor Used:	CryoSat Ice Processor	Server check: calval-pds.cryosat.esa.int	Nominal	
Processor Used.		Product Software Check	Nominal	
Data Used:	L1B and L2 OFFLINE Data	Product Format Check	Nominal	
Data Used:		Product Header Analysis	See Section 4.2 and 5.2	
•		Star Tracker Usage Check	Nominal	
		L1B Calibration Usage Check	Nominal	
		L1B & L2 Auxiliary Data File Usage Check	Nominal	
		L1B & L2 Auxiliary Correction Error Check	Nominal	
		L1B & L2 Measurement Confidence Data Check	See Section 4.7 and 5.5	
Mission / Instrument News				
19-Sep-2018 None				
20-Sep-2018 None				
21-Sep-2018 Nothing planned				





The SIRAL instrument configuration for the day of acquisition is provided below.

# 4. Level 1B Data Quality Check

#### 4.1 L1B Product Format Check

Each product, retrieved and unpacked from the science server, is checked to ensure it consists of both an XML header file (.HDR) and a product file (.DBL)

# Number of products with errors:

# 4.2 L1B Product Header Analysis

For all products, a series of pre-defined checks are carried out on the MPH and SPH in order to identify any inconsistencies and/or errors raised by the ground-segment processing chain. Number of products with errors: 1 Product Test Failed

CS\_OFFL\_SIR\_SAR\_1B\_20180920T141843\_20180920T141844\_C001 Percentage of processing errors detected greater than minimum acceptable threshold

#### 4.3 Star Tracker Usage Check

Each product is checked in order to ensure a valid star tracker file has been used in processing

Number of products with errors:

#### 4.4 L1B Calibration Usage Check

Each product is checked in order to ensure that the necessary calibration files have been used in processing Number of products with errors:

4.5 L1B Auxilary Data File Usage Check

Each product is checked for missing Data Set Descriptors with respect to a pre-determined baseline and also to check the validity of Auxiliary Data Files is correct.

Number of products with errors:

#### 4.6 L1B Auxiliary Correction Error Check

CryoSat L1B data includes a correction error flag (field 54) for each measurement record. The bit value of this flag indicates any problems when set.

Number of products with errors:

#### 4.7 L1B Measurement Confidence Data Check

CryoSat L1B data includes a measurement confidence flag (field 18) for each measurement record. The bit value of this flag indicates any problems when set

Currently, there are several common error flags raised in the Level 1B products which are expected due to operational mode or surface type. All common flags are summarised in the list below, followed by a table of any additional issues arising from this test.

Block Degraded Flag: This flag is currently set for a number of individual records generally at the start or end of products (all modes), but this is to be expected

Phase Perturbation Flag: This flag is currently set for all L1B SARIn products, indicating that the ADC correction application is deactivated, but this is in line with the current configuration.

Number of products with errors:

# 5. Level 2 Data Quality Check

#### 5.1 L2 Product Format Check

Each product, retrieved and unpacked from the science server, is checked to ensure it consists of both an XML header file (.HDR) and a product file (.DBL).

Number of products with errors:

#### 5.2 L2 Product Header Analysis

For all products, a series of pre-defined checks are carried out on the MPH and SPH in order to identify any inconsistencies and/or errors raised by the ground-segment processing chain. Number of products with errors: 1

Product	Test Failed
CS_OFFL_SIR_SAR_220180920T141843_20180920T141844_C001	Percentage of processing errors detected greater than minimum acceptable threshold.

### 5.3 L2 Auxiliary Data File Usage Check

Each product is checked for missing Data Set Descriptors with respect to a pre-determined baseline and also to check the validity of Auxiliary Data Files is correct. 0

Number of products with errors:

# 5.4 L2 Auxiliary Correction Error Check

CryoSat L2 data includes a correction error flag (field 30) for each measurement record. The bit value of this flag indicates any problems when set.

Number of products with errors:

## 5.5 L2 Measurement Quality Flag Check

CryoSat L2 data includes a quality flag (field 50) for each 20-Hz measurement record. The bit value of this flag indicates any problems when set.

Currently, there are several common error flags raised in the Level 2 products which are expected due to operational mode or surface type. All common flags are summarised in the list below, followed by a table of any additional issues arising from this test.

Freeboard error: This flag is correctly set in all L2 SAR products that are not discriminated as sea-ice, and for which freeboard cannot be calculated.

Height and Backscatter errors: These flags are currently set for products over land, but this is to be expected. Retracker 1 Height and Backscatter error flags are also set for products over sea-ice, but this is to be expected.

Peakiness error: This flag is currently set for products over sea-ice, but this is to be expected.

106

SARIN X-Track Angle Error: This flag is set when the difference between the computed surface elevation and the DEM is >50 m. The DEM is only available over Greenland and Antarctica and as a result this flag is set for L2 SARIn products in all other locations as expected.

SSHA interpolation error: This flag is currently set for a number of SAR products occurring at surface type boundaries, but this is to be expected.

Number of products with errors:

Product	Test Failed	Description
CS_OFFL_SIR_LRM_220180919T235922_20180920T001135_C001	Height Error (Retracker 2), Backscatter Error (Retracker 2)	There is a height and backscatter error for Retracker 2 for one or more records
CS_OFFL_SIR_LRM_220180920T001339_20180920T002818_C001	Height Error (Retracker 2), Backscatter Error (Retracker 2)	There is a height and backscatter error for Retracker 2 for one or more records
CS_OFFL_SIR_LRM_220180920T004538_20180920T005549_C001	Height Error (Retracker 2), Backscatter Error (Retracker 2)	There is a height and backscatter error for Retracker 2 for one or more records
CS_OFFL_SIR_LRM_2_20180920T010208_20180920T011816_C001	Height Error (Retracker 2), Height Error (Retracker 3), Backscatter Error (Retracker 2)	There is a height and backscatter error for Retracker 2 and a height error for Retracker 3 for one or more records
CS_OFFL_SIR_LRM_2_20180920T012114_20180920T012204_C001	Height Error (Retracker 2), Backscatter Error (Retracker 2)	There is a height and backscatter error for Retracker 2 for one or more records
CS_OFFL_SIR_LRM_220180920T014916_20180920T015054_C001	Height Error (Retracker 2), Height Error (Retracker 3), Backscatter Error (Retracker 2)	There is a height and backscatter error for Retracker 2 and a height error for Retracker 3 for one or more records
CS_OFFL_SIR_LRM_2_20180920T015337_20180920T020654_C001	Height Error (Retracker 2), Backscatter Error (Retracker 2)	There is a height and backscatter error for Retracker 2 for one or more records
CS_OFFL_SIR_LRM_2_20180920T022318_20180920T025846_C001	Height Error (Retracker 2), Height Error (Retracker 3), Backscatter Error (Retracker 2)	There is a height and backscatter error for Retracker 2 and a height error for Retracker 3 for one or more records
CS_OFFL_SIR_LRM_2_20180920T032337_20180920T034527_C001	Height Error (Retracker 2), Height Error (Retracker 3), Backscatter Error (Retracker 2)	There is a height and backscatter error for Retracker 2 and a height error for Retracker 3 for one or more records
CS_OFFL_SIR_LRM_2_20180920T040201_20180920T042959_C001	Height Error (Retracker 2), Height Error (Retracker 3), Backscatter Error (Retracker 2)	There is a height and backscatter error for Retracker 2 and a height error for Retracker 3 for one or more records
CS_OFFL_SIR_LRM_220180920T044758_20180920T045057_C001	Height Error (Retracker 2), Backscatter Error (Retracker 2)	There is a height and backscatter error for Retracker 2 for one or more records
CS_OFFL_SIR_LRM_220180920T045215_20180920T052515_C001	Height Error (Retracker 2), Backscatter Error (Retracker 2)	There is a height and backscatter error for Retracker 2 for one or more records
CS_OFFL_SIR_LRM_2_20180920T053357_20180920T053725_C001	Surface Model Unavailable	No DEM or Slope Model was used for the location of one or more records
CS_OFFL_SIR_LRM_2_20180920T055736_20180920T061511_C001	Height Error (Retracker 2), Backscatter Error (Retracker 2)	There is a height and backscatter error for Retracker 2 for one or more records
CS_OFFL_SIR_LRM_2_20180920T062654_20180920T063410_C001	Height Error (Retracker 2), Backscatter Error (Retracker 2)	There is a height and backscatter error for Retracker 2 for one or more records
CS_OFFL_SIR_LRM_2_20180920T063856_20180920T064744_C001	Height Error (Retracker 2), Backscatter Error (Retracker 2)	There is a height and backscatter error for Retracker 2 for one or more records
CS_OFFL_SIR_LRM_220180920T070847_20180920T071422_C001	Surface Model Unavailable	No DEM or Slope Model was used for the location of one or more records
CS_OFFL_SIR_LRM_2_20180920T072157_20180920T075431_C001	Height Error (Retracker 2), Height Error (Retracker 3), Backscatter Error (Retracker 2)	There is a height and backscatter error for Retracker 2 and a height error for Retracker 3 for one or more records
CS_OFFL_SIR_LRM_2_20180920T075450_20180920T075608_C001	Height Error (Retracker 2), Backscatter Error (Retracker 2)	There is a height and backscatter error for Retracker 2 for one or more records
CS_OFFL_SIR_LRM_2_20180920T075617_20180920T075643_C001	Height Error (Retracker 2), Backscatter Error (Retracker 2)	There is a height and backscatter error for Retracker 2 for one or more records
CS_OFFL_SIR_LRM_220180920T075649_20180920T075744_C001	Height Error (Retracker 2), Height Error (Retracker 3), Backscatter Error (Retracker 2)	There is a height and backscatter error for Retracker 2 and a height error for Retracker 3 for one or more records
CS_OFFL_SIR_LRM_2_20180920T082655_20180920T084237_C001	Height Error (Retracker 2), Backscatter Error (Retracker 2)	There is a height and backscatter error for Retracker 2 for one or more records
CS_OFFL_SIR_LRM_2_20180920T090018_20180920T093544_C001	Height Error (Retracker 2), Height Error (Retracker 3), Backscatter Error (Retracker 2)	There is a height and backscatter error for Retracker 2 and a height error for Retracker 3 for one or more records
CS_OFFL_SIR_LRM_2_20180920T095756_20180920T100217_C001	Height Error (Retracker 2), Height Error (Retracker 3), Backscatter Error (Retracker 2)	There is a height and backscatter error for Retracker 2 and a height error for Retracker 3 for one or more records
CS_OFFL_SIR_LRM_2_20180920T100313_20180920T102049_C001	Height Error (Retracker 2), Height Error (Retracker 3), Backscatter Error (Retracker 2)	There is a height and backscatter error for Retracker 2 and a height error for Retracker 3 for one or more records
CS_OFFL_SIR_LRM_2_20180920T103020_20180920T103220_C001	Surface Model Unavailable	No DEM or Slope Model was used for the location of one or more records
CS_OFFL_SIR_LRM_220180920T103958_20180920T105725_C001	Height Error (Retracker 2), Height Error (Retracker 3), Backscatter Error (Retracker 2)	There is a height and backscatter error for Retracker 2 and a height error for Retracker 3 for one or more records
CS_OFFL_SIR_LRM_220180920T110121_20180920T111542_C001	Height Error (Retracker 2), Height Error (Retracker 3), Backscatter Error (Retracker 2)	There is a height and backscatter error for Retracker 2 and a height error for Retracker 3 for one or more records
CS_OFFL_SIR_LRM_220180920T112752_20180920T114618_C001	Height Error (Retracker 2), Backscatter Error (Retracker 2)	There is a height and backscatter error for Retracker 2 for one or more records

CS_OFFL_SIR_LRM_220180920T114738_20180920T120130_C001	Height Error (Retracker 2), Height Error (Retracker 3), Backscatter Error (Retracker 2)	There is a height and backscatter error for Retracker 2 and a height error for Retracker 3 for one or more records
CS_OFFL_SIR_LRM_220180920T121858_20180920T123349_C001	Height Error (Retracker 2), Backscatter Error (Retracker 2)	There is a height and backscatter error for Retracker 2 for one or more records
CS_OFFL_SIR_LRM_220180920T123550_20180920T124514_C001	Height Error (Retracker 2), Height Error (Retracker 3), Backscatter Error (Retracker 2)	There is a height and backscatter error for Retracker 2 and a height error for Retracker 3 for one or more records
CS_OFFL_SIR_LRM_220180920T130615_20180920T132418_C001	Height Error (Retracker 2), Height Error (Retracker 3), Backscatter Error (Retracker 2)	There is a height and backscatter error for Retracker 2 and a height error for Retracker 3 for one or more records
CS_OFFL_SIR_LRM_220180920T134023_20180920T134235_C001	Height Error (Retracker 2), Backscatter Error (Retracker 2)	There is a height and backscatter error for Retracker 2 for one or more records
CS_OFFL_SIR_LRM_220180920T134736_20180920T135533_C001	Surface Model Unavailable	No DEM or Slope Model was used for the location of one or more records
CS_OFFL_SIR_LRM_220180920T135847_20180920T141255_C001	Height Error (Retracker 2), Backscatter Error (Retracker 2)	There is a height and backscatter error for Retracker 2 for one or more records
CS_OFFL_SIR_LRM_220180920T144725_20180920T152223_C001	Height Error (Retracker 2), Backscatter Error (Retracker 2)	There is a height and backscatter error for Retracker 2 for one or more records
CS_OFFL_SIR_LRM_220180920T152608_20180920T152818_C001	Surface Model Unavailable	No DEM or Slope Model was used for the location of one or more records
CS_OFFL_SIR_LRM_220180920T152843_20180920T153420_C001	Surface Model Unavailable	No DEM or Slope Model was used for the location of one or more records
CS_OFFL_SIR_LRM_220180920T153855_20180920T160212_C001	Height Error (Retracker 2), Backscatter Error (Retracker 2)	There is a height and backscatter error for Retracker 2 for one or more records
CS_OFFL_SIR_LRM_220180920T161244_20180920T161507_C001	Height Error (Retracker 2), Backscatter Error (Retracker 2)	There is a height and backscatter error for Retracker 2 for one or more records
CS_OFFL_SIR_LRM_220180920T163347_20180920T164518_C001	Height Error (Retracker 2), Backscatter Error (Retracker 2)	There is a height and backscatter error for Retracker 2 for one or more records
CS_OFFL_SIR_LRM_220180920T171748_20180920T174412_C001	Height Error (Retracker 2), Backscatter Error (Retracker 2)	There is a height and backscatter error for Retracker 2 for one or more records
CS_OFFL_SIR_LRM_220180920T174832_20180920T175525_C001	Height Error (Retracker 2), Backscatter Error (Retracker 2)	There is a height and backscatter error for Retracker 2 for one or more records
CS_OFFL_SIR_LRM_220180920T180804_20180920T183906_C001	Height Error (Retracker 2), Backscatter Error (Retracker 2)	There is a height and backscatter error for Retracker 2 for one or more records
CS_OFFL_SIR_LRM_220180920T193157_20180920T193423_C001	Height Error (Retracker 2), Backscatter Error (Retracker 2)	There is a height and backscatter error for Retracker 2 for one or more records
CS_OFFL_SIR_LRM_220180920T194646_20180920T201923_C001	Height Error (Retracker 2), Backscatter Error (Retracker 2)	There is a height and backscatter error for Retracker 2 for one or more records
CS_OFFL_SIR_LRM_220180920T212317_20180920T215811_C001	Height Error (Retracker 2), Height Error (Retracker 3), Backscatter Error (Retracker 2)	There is a height and backscatter error for Retracker 2 and a height error for Retracker 3 for one or more records
CS_OFFL_SIR_LRM_220180920T220646_20180920T221044_C001	Surface Model Unavailable	No DEM or Slope Model was used for the location of one or more records
CS_OFFL_SIR_LRM_220180920T221600_20180920T224147_C001	Height Error (Retracker 2), Backscatter Error (Retracker 2)	There is a height and backscatter error for Retracker 2 for one or more records
CS_OFFL_SIR_LRM_220180920T224203_20180920T224937_C001	Height Error (Retracker 2), Backscatter Error (Retracker 2)	There is a height and backscatter error for Retracker 2 for one or more records
CS_OFFL_SIR_LRM_220180920T230146_20180920T231608_C001	Height Error (Retracker 2), Backscatter Error (Retracker 2)	There is a height and backscatter error for Retracker 2 for one or more records
CS_OFFL_SIR_LRM_220180920T232049_20180920T232238_C001	Height Error (Retracker 2), Backscatter Error (Retracker 2)	There is a height and backscatter error for Retracker 2 for one or more records
CS_OFFL_SIR_LRM_220180920T232241_20180920T233744_C001	Height Error (Retracker 2), Backscatter Error (Retracker 2)	There is a height and backscatter error for Retracker 2 for one or more records
CS_OFFL_SIR_SIN_220180920T002927_20180920T003108_C001	SARIn X-track Angle Error	An ambiguous angle was detected for SARIn mode for one or more records
CS_OFFL_SIR_SIN_220180920T003641_20180920T003648_C001	SARIn X-track Angle Error	An ambiguous angle was detected for SARIn mode for one or more records
CS_OFFL_SIR_SIN_220180920T003811_20180920T004030_C001	SARIn X-track Angle Error	An ambiguous angle was detected for SARIn mode for one or more records
CS_OFFL_SIR_SIN_220180920T012205_20180920T012417_C001	SARIn X-track Angle Error, Surface Model Unavailable	An ambiguous angle was detected for SARIn mode and no DEM or Slope Model was used for one or more records
CS_OFFL_SIR_SIN_220180920T020823_20180920T021022_C001	SARIn X-track Angle Error	An ambiguous angle was detected for SARIn mode for one or more records
CS_OFFL_SIR_SIN_220180920T021555_20180920T021601_C001	SARIn X-track Angle Error	An ambiguous angle was detected for SARIn mode for one or more records
CS_OFFL_SIR_SIN_220180920T021708_20180920T022144_C001	SARIn X-track Angle Error	An ambiguous angle was detected for SARIn mode for one or more records
CS_OFFL_SIR_SIN_220180920T030758_20180920T030831_C001	SARIn X-track Angle Error, Surface Model Unavailable	An ambiguous angle was detected for SARIn mode and no DEM or Slope Model was used for one or more records
CS_OFFL_SIR_SIN_220180920T034835_20180920T035106_C001	SARIn X-track Angle Error	An ambiguous angle was detected for SARIn mode for one or more records
CS_OFFL_SIR_SIN_220180920T035437_20180920T035443_C001	SARIn X-track Angle Error	An ambiguous angle was detected for SARIn mode for one or more records

City City City City City City City City	CS_OFFL_SIR_SIN_220180920T035827_20180920T040010_C001	SARIn X-track Angle Error	An ambiguous angle was detected for SARIn mode for one or more records
Curr (Curr (Cu	CS_OFFL_SIR_SIN_220180920T052719_20180920T052849_C001	SARIn X-track Angle Error	
ColumbiaNotionNotionNotionColumbiaColumbiaNotionNotionNotionColumbiaNotionNotionNotionNot	CS_OFFL_SIR_SIN_220180920T053351_20180920T053357_C001	SARIn X-track Angle Error	
No. of Carlot, Sub. 2019;80:11980, Call Back States, CallKeat HousehowKeat HousehowCall, Ser, Jan, Jan, J. 2018;82:1191, 2018;82:1192;81:0200000000000000000000000000000000000	CS_OFFL_SIR_SIN_220180920T053725_20180920T053900_C001	SARIn X-track Angle Error	
CLUCTURY_INCLUCTURY_INTLATIONNon-Kathal Argin EndNon-KathCLUCTURY_INCLUCTURY_INTLATIONSafes Areas Argin EndAready and the set of	CS_OFFL_SIR_SIN_220180920T062610_20180920T062635_C001		
Col Chr (Link Sin 2, 2010/2011/11/2012/00000111/01/2010 Selfin Kink Kink Kink Kink Kink Kink Kink Ki	CS_OFFL_SIR_SIN_220180920T070733_20180920T070847_C001	SARIn X-track Angle Error	
Color Unity Sin 2: Discretional function of the set of the s	CS_OFFL_SIR_SIN_220180920T071423_20180920T071740_C001	SARIn X-track Angle Error	
Model Howelands CS OFFL SHT, SHT 2. 20180207100410, 20180207100410, 2010 CS OFFL SHT, SHT 2. 20180207100410, 20180207100410, 2010 CS OFFL SHT, SHT 2. 20180207100410, 20180207100410, 2001 CS OFFL SHT, SHT 2. 20180207100410, 20180207100410, 2001 CS OFFL SHT, SHT 2. 201802071102736, 201802071102732, 20180207112314, 20180207112	CS_OFFL_SIR_SIN_2_20180920T080536_20180920T080601_C001		
CLUTTL_SINUL_CLUTISADECTIONSHUL_CONDUCTIONS	CS_OFFL_SIR_SIN_220180920T080607_20180920T080632_C001		
CprL, Sing Sing 2, 201800007110219, 20180000711219, 20180000711319, 20180000711319, 20180000711319, 20180000713603, 201800000713603, 20180000713603, 20180000713603, 2018000071360	CS_OFFL_SIR_SIN_220180920T084648_20180920T084808_C001	SARIn X-track Angle Error	
Circuit Sing Sing Sing Sing Sing Sing Sing Sing	CS_OFFL_SIR_SIN_220180920T085317_20180920T085627_C001	SARIn X-track Angle Error	
Operation     Seconds       CS, OFFL, SIR, SIN, 2, 201800201110234, 201802001112752, C001     SARIN X-track Argie Error     An ambiguous angle was detected for SARIN mode for one or more mode.       CS, OFFL, SIR, SIN, 2, 201800201112016, 201802001121030, C001     SARIN X-track Argie Error     An ambiguous angle was detected for SARIN mode for one or more mode.       CS, OFFL, SIR, SIN, 2, 201800201121130, 201802001121130, 201802001121130, 201802001121130, 201802001121130, 201802001121130, 201802001121130, 20180201121131, 201802001120180, C001     SARIN X-track Argie Error     An ambiguous angle was detected for SARIN mode for one or more mode mode.       CS, OFFL, SIR, SIN, 2, 20180020113018, 2018020113018, C001     SARIN X-track Argie Error     An ambiguous angle was detected for SARIN mode for one or more mode.       CS, OFFL, SIR, SIN, 2, 201800201130418, 2018020113045, C001     SARIN X-track Argie Error     An ambiguous angle was detected for SARIN mode for one or more mode.       CS, OFFL, SIR, SIN, 2, 201800201130412, 201800201130420, C001     SARIN X-track Argie Error     An ambiguous angle was detected for SARIN mode for one or more mode.       CS, OFFL, SIR, SIN, 2, 201800201130420, 201800201130420, 201800201130420, 201800201130420, 201800201130420, 201800201130420, 201800201130420, 201800201130420, 201800201130420, 201800201130420, 201800201130420, 201800201130420, 201800201130420, 201800201130420, 201800201130420, 201800201130420, 201800201130420, 201800201130420, 201800201130420, 20180020113040, 20180020113040, 20180020113040, 201800201130440, 201800201116200, 20180020113040, 20180020113040, 201800201102	CS_OFFL_SIR_SIN_220180920T102739_20180920T103019_C001	SARIn X-track Angle Error	
CL_PFL_SR_SR_220188020112664_201800201120020_0001     SARIN X-track Angle End     inecude       CS_OFFL_SR_SR_2201800201120024_201800201120020_0001     SARIN X-track Angle End     An ambiguous angle was detected for SARIN mode for one or more accode       CS_OFFL_SR_SR_2201800201120021     SARIN X-track Angle End     An ambiguous angle was detected for SARIN mode for one or more accode       CS_OFFL_SR_SR_2201800201130221     SARIN X-track Angle End     An ambiguous angle was detected for SARIN mode for one or more accode       CS_OFFL_SR_SR_2_201800201130221     SARIN X-track Angle End     An ambiguous angle was detected for SARIN mode for one or more accode       CS_OFFL_SR_SR_2_201800201130221     SARIN X-track Angle End     An ambiguous angle was detected for SARIN mode for one or more accode       CS_OFFL_SR_SR_2_201800201130221     SARIN X-track Angle End     An ambiguous angle was detected for SARIN mode for one or more accode       CS_OFFL_SR_SR_2_201800201130221     SARIN X-track Angle End     An ambiguous angle was detected for SARIN mode for one or more accode       CS_OFFL_SR_SR_2_201800201130221     SARIN X-track Angle End     An ambiguous angle was detected for SARIN mode for one or more accode       CS_OFFL_SR_SR_2_201800201130221     SARIN X-track Angle End     An ambiguous angle was detected for SARIN mode for one or more accode       CS_OFFL_SR_SR_SR_2_2018002011130242     Color     SARIN	CS_OFFL_SIR_SIN_220180920T103220_20180920T103750_C001	SARIn X-track Angle Error	
Call, PFT_SRL, SRL 2018802011120140_0000011120040_L0000   SARIN X-Hank Angle End   inecode <sup>1</sup> Call, OFFL_SIR_SNL2001890201121130_01890201121130_01990201121130_000001   SARIN X-Hank Angle End   An antibiguous angle was detected for SARIN mode for one or more     Call, OFFL_SIR_SNL2001890201130217_01890201130212_0001   SARIN X-Hank Angle End   An antibiguous angle was detected for SARIN mode for one or more     Call, OFFL_SIR_SNL2001890201130217_01890201130215_0001   SARIN X-Hank Angle End   An antibiguous angle was detected for SARIN mode for one or more     Call, OFFL_SIR_SNL2001890201130213_00190201130215_0001   SARIN X-Hank Angle End   An antibiguous angle was detected for SARIN mode for one or more     Call, OFFL_SIR_SNL2001890201130412_01890201134733_0001   SARIN X-Hank Angle End   An antibiguous angle was detected for SARIN mode for one or more     Call, OFFL_SIR_SNL2001890201134731_001900201144724_0189020113473_0001   SARIN X-Hank Angle End   An antibiguous angle was detected for SARIN mode for one or more     Call, OFFL_SIR_SNL2001890201144724_01900201144724_001000   SARIN X-Hank Angle End   An antibiguous angle was detected for SARIN mode for one or more     Call, OFFL_SIR_SNL2001890201142840_0001   SARIN X-Hank Angle End   An antibiguous angle was detected for SARIN mode for one or more     Call, OFFL_SIR_SNL2001890201142412   Collspace   SARIN X-Hank Angle End   An antibiguous angle was detected for SARIN mode for	CS_OFFL_SIR_SIN_220180920T112314_20180920T112752_C001	SARIn X-track Angle Error	
CS_OPPL_SIR_SIR_2_0108020112103_0108202112012_001001   SARIN X-track Angle Error   An antiguous angle was detected for SARIN mode for one or more eccords     CS_OPPL_SIR_SIN_2_01080201130217_201692201130216_C001   SARIN X-track Angle Error   An antiguous angle was detected for SARIN mode for one or more eccords     CS_OPPL_SIR_SIN_2_01080201130217_201692201130216_C001   SARIN X-track Angle Error   An antiguous angle was detected for SARIN mode for one or more eccords     CS_OPPL_SIR_SIN_2_01080201130217_201692201130215_C001   SARIN X-track Angle Error   An antiguous angle was detected for SARIN mode for one or more eccords     CS_OPPL_SIR_SIN_2_01080201130211_3421_201802201136721_C001   SARIN X-track Angle Error   An antiguous angle was detected for SARIN mode for one or more eccords     CS_OPPL_SIR_SIN_2_0108020114221_00180201142721_C001   SARIN X-track Angle Error   An antiguous angle was detected for SARIN mode for one or more eccords     CS_OPPL_SIR_SIN_2_01080201142725_C001   SARIN X-track Angle Error   An antiguous angle was detected for SARIN mode for one or more eccords     CS_OPPL_SIR_SIN_2_01809201152402_01809201152808_C001   SARIN X-track Angle Error   An antiguous angle was detected for SARIN mode for one or more eccords     CS_OPPL_SIR_SIN_2_01809201152402_01809201152808_C001   SARIN X-track Angle Error   An antiguous angle was detected for SARIN mode for one or more eccords     CS_OPPL_SIR_SIN_2_018092011615804_C001   SARIN X-track Angle Error   A	CS_OFFL_SIR_SIN_220180920T120654_20180920T120929_C001	SARIn X-track Angle Error	
CS_OFFL_SIR_SIN_2_20160220T130217_20160820T130326_CO01   SARIN X-track Angle Error   An ambiguous angle was detected for SARIN mode for one or more mode models     CS_OFFL_SIR_SIN_2_20160220T130438_20160820T130326_CO01   SARIN X-track Angle Error   An ambiguous angle was detected for SARIN mode for one or more mode models     CS_OFFL_SIR_SIN_2_20160220T130438_20160820T130615_CO01   SARIN X-track Angle Error   An ambiguous angle was detected for SARIN mode for one or more models     CS_OFFL_SIR_SIN_2_20160220T134421_20160920T134735_CO01   SARIN X-track Angle Error   An ambiguous angle was detected for SARIN mode for one or more models     CS_OFFL_SIR_SIN_2_20160220T134421_20160920T144725_CO01   SARIN X-track Angle Error   An ambiguous angle was detected for SARIN mode for one or more models     CS_OFFL_SIR_SIN_2_20160220T162420_20160920T162080_CO01   SARIN X-track Angle Error   An ambiguous angle was detected for SARIN mode for one or more models     CS_OFFL_SIR_SIN_2_20160020T162420_20160920T162080_CO01   SARIN X-track Angle Error   An ambiguous angle was detected for SARIN mode for one or more models     CS_OFFL_SIR_SIN_2_20160020T162420_20160920T162061_CO01   SARIN X-track Angle Error   An ambiguous angle was detected for SARIN mode for one or more models     CS_OFFL_SIR_SIN_2_20160020T162420_20160920T162063_CO01   SARIN X-track Angle Error   An ambiguous angle was detected for SARIN mode for one or more models     CS_OFFL_SIR_SIN_2_20160020T161622_20160820T16665_CO01   S	CS_OFFL_SIR_SIN_220180920T121130_20180920T121238_C001	SARIn X-track Angle Error	
CS_OFFL_SIR_SIN_2_201802201130438_2018020113015_C001   SARIN Xtrack Angle Error   An ambiguous angle was detected for SARIn mode for one or more     CS_OFFL_SIR_SIN_2_201802201134212_001802201134735_C001   SARIN Xtrack Angle Error   An ambiguous angle was detected for SARIn mode for one or more     CS_OFFL_SIR_SIN_2_201802201134212_001002201134735_C001   SARIN Xtrack Angle Error   An ambiguous angle was detected for SARIn mode for one or more     CS_OFFL_SIR_SIN_2_20180220113523_01802201135721_C001   SARIN Xtrack Angle Error   An ambiguous angle was detected for SARIn mode for one or more     CS_OFFL_SIR_SIN_2_201802201152420_01802201135721_C001   SARIN Xtrack Angle Error   An ambiguous angle was detected for SARIn mode for one or more     CS_OFFL_SIR_SIN_2_201802201152420_0180220115208_C001   SARIN Xtrack Angle Error   An ambiguous angle was detected for SARIn mode for one or more     CS_OFFL_SIR_SIN_2_20180220115243_001   SARIN Xtrack Angle Error   An ambiguous angle was detected for SARIn mode for one or more     CS_OFFL_SIR_SIN_2_201802201162843_0001   SARIN Xtrack Angle Error   An ambiguous angle was detected for SARIn mode and no DEM or Slope     CS_OFFL_SIR_SIN_2_201802201161526_C001   SARIN Xtrack Angle Error, Surface   An ambiguous angle was detected for SARIn mode and no DEM or Slope     CS_OFFL_SIR_SIN_2_201802201161528_C001   SARIN Xtrack Angle Error, Surface   An ambiguous angle was detected for SARIn mode for one or more	CS_OFFL_SIR_SIN_220180920T121631_20180920T121810_C001	SARIn X-track Angle Error	0 0
CS_OFFL_SIR_SIN_2_2018020113433_0180820113675_001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_2_201809201134731_001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_2_201809201134732_001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_2_201809201134732_001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_2_201809201152809_001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_2_201809201152818_201809201152843_001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_2_201809201163843_001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_2_201809201161526_001   MARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode and no DEM or Slope Model Unavailable     CS_OFFL_SIR_SIN_2_201809201161526_001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode and no DEM or Slope Model Unavailable     CS_OFFL_SIR_SIN_2_201809201161526_001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records <td>CS_OFFL_SIR_SIN_220180920T130217_20180920T130326_C001</td> <td>SARIn X-track Angle Error</td> <td></td>	CS_OFFL_SIR_SIN_220180920T130217_20180920T130326_C001	SARIn X-track Angle Error	
CS_OFFL_SIR_SIN_2_20180820T1541_00180520T1543_0001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more     CS_OFFL_SIR_SIN_2_20180820T144124_20180920T144725_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode and no DEM or Slope     Model Unavailable   Model Unavailable   An ambiguous angle was detected for SARIn mode and no DEM or Slope     CS_OFFL_SIR_SIN_2_20180920T144124_20180920T152608_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more     CS_OFFL_SIR_SIN_2_20180920T152420_20180920T152608_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more     CS_OFFL_SIR_SIN_2_20180920T15243_0180920T152643_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more     CS_OFFL_SIR_SIN_2_20180920T161628_0180920T161626_C001   SARIN X-track Angle Error, Surface   An ambiguous angle was detected for SARIn mode and no DEM or Slope     Model Unavailable   Model Unavailable   Model Unavailable   Model Unavailable     CS_OFFL_SIR_SIN_2_20180920T161628_01105430_0001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more     CS_OFFL_SIR_SIN_2_20180920T161628_011070530_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more     CS_OFFL_SIR_SIN_2_20180920T171525_01	CS_OFFL_SIR_SIN_220180920T130438_20180920T130615_C001	SARIn X-track Angle Error	
CS_OFFL_SIR_SIN_2_20180920T152432_0180920T15225_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode and no DEM or Slope     Model Unavailable   An ambiguous angle was detected for SARIn mode for one or more   Fecords     CS_OFFL_SIR_SIN_2_20180920T152432_0180920T152836_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more     CS_OFFL_SIR_SIN_2_20180920T152836_0001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more     CS_OFFL_SIR_SIN_2_20180920T153843_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more     CS_OFFL_SIR_SIN_2_20180920T153843_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode and no DEM or Slope     Model Unavailable   Model Unavailable   An ambiguous angle was detected for SARIn mode and no DEM or Slope     Model Unavailable   Model Unavailable   An ambiguous angle was detected for SARIn mode and no DEM or Slope     Model Unavailable   Model Unavailable   An ambiguous angle was detected for SARIn mode for one or more     CS_OFFL_SIR_SIN_2_20180920T161528_C001   SARIN X-track Angle Error, Surface   An ambiguous angle was detected for SARIn mode for one or more     CS_OFFL_SIR_SIN_2_20180920T161625_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more	CS_OFFL_SIR_SIN_220180920T134421_20180920T134735_C001	SARIn X-track Angle Error	
LS_OFFL_SIR_SIN_2_201809201144124_201809201144125_C001   Model Unavailable   Model was used for one or more records     CS_OFFL_SIR_SIN_2_201809201152420_201809201152843_C001   SARIn X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_2_201809201152843_C001   SARIn X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_2_201809201153420_201809201153843_C001   SARIn X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_2_201809201161508_001161526_C001   SARIn X-track Angle Error, Surface   An ambiguous angle was detected for SARIn mode and no DEM or Slope     CS_OFFL_SIR_SIN_2_201809201161526_C001   SARIn X-track Angle Error, Surface   An ambiguous angle was detected for SARIn mode and no DEM or Slope     CS_OFFL_SIR_SIN_2_201809201161526_C001   SARIn X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_2_201809201170349_201809201170340   SARIn X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_2_201809201170349_201809201170347   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_2_201809201170349_201809201170847_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one	CS_OFFL_SIR_SIN_220180920T135533_20180920T135721_C001	SARIn X-track Angle Error	
CS_OFFL_SIR_SIN_2201609201152818_201609201152843_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_2201609201152818_201809201152843_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_2201809201153420_201809201161526_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_2201809201161508_201809201161526_C001   SARIN X-track Angle Error, Surface Model Unavailable   An ambiguous angle was detected for SARIn mode and no DEM or Slope Model Unavailable     CS_OFFL_SIR_SIN_2201809201161622_201809201161555_C001   SARIN X-track Angle Error, Surface Model Unavailable   An ambiguous angle was detected for SARIn mode and no DEM or Slope Model Unavailable     CS_OFFL_SIR_SIN_2201809201170349_201809201170530_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_2201809201170349_201809201170817_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_2201809201171525_201809201171535_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_2201809201171411_201809201171533_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records	CS_OFFL_SIR_SIN_220180920T144134_20180920T144725_C001	5	
CS_OFFL_SIR_SIN_220180920T152818_20180920T153643_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_220180920T161508_20180920T161526_C001   SARIN X-track Angle Error, Surface   An ambiguous angle was detected for SARIn mode and no DEM or Slope     CS_OFFL_SIR_SIN_220180920T161522_20180920T161655_C001   SARIN X-track Angle Error, Surface   An ambiguous angle was detected for SARIn mode and no DEM or Slope     CS_OFFL_SIR_SIN_220180920T161622_20180920T161655_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode and no DEM or Slope     CS_OFFL_SIR_SIN_220180920T170349_20180920T170350_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_220180920T170349_20180920T170817_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_220180920T171252_20180920T171355_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_220180920T1711252_20180920T171355_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_220180920T171411_20180920T171533_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_220180920T18454_20180920T184727_C001<	CS_OFFL_SIR_SIN_220180920T152420_20180920T152608_C001	SARIn X-track Angle Error	
CS_OFFL_SIR_SIN_2_201809201163420_201809201161526_C001   SARIN X-track Angle Error   records     CS_OFFL_SIR_SIN_2_20180920T161508_20180920T161526_C001   SARIN X-track Angle Error, Surface   An ambiguous angle was detected for SARIn mode and no DEM or Slope     Model Was used for one or more records   Model Was used for one or more records     CS_OFFL_SIR_SIN_2_20180920T161622_20180920T161655_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode and no DEM or Slope     Model Was used for one or more records   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more     CS_OFFL_SIR_SIN_2_20180920T170349_20180920T170530_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more     CS_OFFL_SIR_SIN_2_20180920T170639_20180920T170817_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more     CS_OFFL_SIR_SIN_2_20180920T171411_20180920T171355_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more     CS_OFFL_SIR_SIN_2_20180920T171411_20180920T171533_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more     CS_OFFL_SIR_SIN_2_20180920T184354_20180920T184727_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more     CS_OFFL_SIR_SIN_2_20180920T184354_20180920T185416_C001	CS_OFFL_SIR_SIN_220180920T152818_20180920T152843_C001	SARIn X-track Angle Error	
CS_OFFL_SIR_SIN_2_20180920T161508_20180920T161525_C001   Model Unavailable   Model was used for one or more records     CS_OFFL_SIR_SIN_2_20180920T161622_20180920T161655_C001   SARIn X-track Angle Error   An ambiguous angle was detected for SARIn mode and no DEM or Slope Model Unavailable     CS_OFFL_SIR_SIN_2_20180920T170349_20180920T170530_C001   SARIn X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_2_20180920T170639_20180920T170817_C001   SARIn X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_2_20180920T171252_20180920T171255_C001   SARIn X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_2_20180920T171411_20180920T171355_C001   SARIn X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_2_20180920T171411_20180920T171533_C001   SARIn X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_2_20180920T184354_20180920T184727_C001   SARIn X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_2_20180920T185316_C001   SARIn X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_2_20180920T185316_C001   SARIN X-track Angle Error   An ambiguous angle	CS_OFFL_SIR_SIN_220180920T153420_20180920T153643_C001	SARIn X-track Angle Error	0 0
DS_OFFL_SIR_SIN_2_201809201161822_201809201101835_C001   Model Unavailable   Model was used for one or more records     CS_OFFL_SIR_SIN_2_201809201170349_201809201170530_C001   SARIn X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_2_201809201170639_201809201170817_C001   SARIn X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_2_201809201171252_201809201171355_C001   SARIn X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_2_201809201171411_201809201171533_C001   SARIn X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_2_201809201184354_201809201184727_C001   SARIn X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_2_201809201184354_201809201184727_C001   SARIn X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_2_201809201185300_201809201185416_C001   SARIn X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_2_201809201202310_201809201202630_C001   SARIn X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_2_201809201202310_201809201202630_C001   SARIN X-track Angle Error	CS_OFFL_SIR_SIN_220180920T161508_20180920T161526_C001		
CS_OFFL_SIR_SIN_220180920T170539_20180920T170817_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_220180920T171252_20180920T171355_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_220180920T171252_20180920T171355_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_220180920T171411_20180920T171533_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_220180920T184354_20180920T184727_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_220180920T185300_20180920T185416_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_220180920T202310_20180920T185416_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_220180920T202310_20180920T202300_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_220180920T202310_20180920T202300_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_220180920T2023142_20180920T202306_C001	CS_OFFL_SIR_SIN_220180920T161622_20180920T161655_C001		
CS_OFFL_SIR_SIN_2_20180920T171252_20180920T171355_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_2_20180920T171252_20180920T171355_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_2_20180920T171411_20180920T171533_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_2_20180920T184354_20180920T184727_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_2_20180920T184354_20180920T185416_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_2_20180920T185300_20180920T185416_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_2_20180920T202310_20180920T202630_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_2_20180920T20310_20180920T202630_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records     CS_OFFL_SIR_SIN_2_20180920T20310_20180920T202306_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIn mode for one or more records	CS_OFFL_SIR_SIN_220180920T170349_20180920T170530_C001	SARIn X-track Angle Error	
CS_OFFL_SIR_SIN_2_20180920T171411_20180920T171533_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIN mode for one or more records     CS_OFFL_SIR_SIN_2_20180920T171411_20180920T171533_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIN mode for one or more records     CS_OFFL_SIR_SIN_2_20180920T184354_20180920T184727_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIN mode for one or more records     CS_OFFL_SIR_SIN_2_20180920T185300_20180920T185416_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIN mode for one or more records     CS_OFFL_SIR_SIN_2_20180920T202310_20180920T185416_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIN mode for one or more records     CS_OFFL_SIR_SIN_2_20180920T202310_20180920T202630_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIN mode for one or more records     CS_OFFL_SIR_SIN_2_20180920T202310_20180920T202630_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIN mode for one or more records     CS_OFFL_SIR_SIN_2_20180920T20310_20180920T203306_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIN mode for one or more records	CS_OFFL_SIR_SIN_220180920T170639_20180920T170817_C001	SARIn X-track Angle Error	
CS_OFFL_SIR_SIN_2_20180920T184354_20180920T184727_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIN mode for one or more records     CS_OFFL_SIR_SIN_2_20180920T184354_20180920T184727_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIN mode for one or more records     CS_OFFL_SIR_SIN_2_20180920T185300_20180920T185416_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIN mode for one or more records     CS_OFFL_SIR_SIN_2_20180920T202310_20180920T202630_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIN mode for one or more records     CS_OFFL_SIR_SIN_2_20180920T202310_20180920T202630_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIN mode for one or more records     CS_OFFL_SIR_SIN_2_20180920T202310_20180920T2023306_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIN mode for one or more records	CS_OFFL_SIR_SIN_220180920T171252_20180920T171355_C001	SARIn X-track Angle Error	
CS_OFFL_SIR_SIN_2_20180920T185300_20180920T185416_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIN mode for one or more records     CS_OFFL_SIR_SIN_2_20180920T202310_20180920T202630_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIN mode for one or more records     CS_OFFL_SIR_SIN_2_20180920T202310_20180920T202630_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIN mode for one or more records     CS_OFFL_SIR_SIN_2_20180920T202310_20180920T202630_C001   SARIN X-track Angle Error   An ambiguous angle was detected for SARIN mode for one or more records	CS_OFFL_SIR_SIN_220180920T171411_20180920T171533_C001	SARIn X-track Angle Error	
CS_OFFL_SIR_SIN_2_20180920T202310_20180920T202300_C001 SARIN X-track Angle Error An ambiguous angle was detected for SARIN mode for one or more records An ambiguous angle was detected for SARIN mode for one or more An ambiguous angle was detected for SARIN mode for one or more records An ambiguous angle was detected for SARIN mode for one or more records An ambiguous angle was detected for SARIN mode for one or more records An ambiguous angle was detected for SARIN mode for one or more records An ambiguous angle was detected for SARIN mode for one or more and the saring sector of the saring	CS_OFFL_SIR_SIN_220180920T184354_20180920T184727_C001	SARIn X-track Angle Error	
CS_OFFL_SIR_SIN_2_201809201203310_201809201203306_C001 SARIN X-track Angle Error An ambiguous angle was detected for SARIN mode for one or more	CS_OFFL_SIR_SIN_220180920T185300_20180920T185416_C001	SARIn X-track Angle Error	
	CS_OFFL_SIR_SIN_220180920T202310_20180920T202630_C001	SARIn X-track Angle Error	
	CS_OFFL_SIR_SIN_220180920T203142_20180920T203306_C001	SARIn X-track Angle Error	

CS_OFFL_SIR_SIN_220180920T211355_20180920T211514_C001	SARIn X-track Angle Error	An ambiguous angle was detected for SARIn mode for one or more records
CS_OFFL_SIR_SIN_220180920T220022_20180920T220309_C001	SARIn X-track Angle Error	An ambiguous angle was detected for SARIn mode for one or more records
CS_OFFL_SIR_SIN_220180920T221044_20180920T221152_C001	SARIn X-track Angle Error	An ambiguous angle was detected for SARIn mode for one or more records
CS_OFFL_SIR_SIN_220180920T224938_20180920T225038_C001	SARIn X-track Angle Error	An ambiguous angle was detected for SARIn mode for one or more records
CS_OFFL_SIR_SIN_220180920T225314_20180920T225424_C001	SARIn X-track Angle Error	An ambiguous angle was detected for SARIn mode for one or more records
CS_OFFL_SIR_SIN_220180920T233830_20180920T234010_C001	SARIn X-track Angle Error	An ambiguous angle was detected for SARIn mode for one or more records
CS_OFFL_SIR_SIN_220180920T234746_20180920T234938_C001	SARIn X-track Angle Error	An ambiguous angle was detected for SARIn mode for one or more records

# 6. QCC Report Analysis

The Quality Control for CryoSat (QCC) facility performs a primary survey of data products immediately after production by the PDS and LTA processing facilities. A list of the tests which raised errors or warnings is provided below.

Product type	No. Products	No. QCC Reports	No. Valid	No. Warnings	No. Errors
SIR_LRM_1B	127	127	127	0	0
SIR_LRM_2	127	127	127	0	0
SIR_LRMI2_	127	127	127	0	0
SIR_SAR_1B	86	86	86	0	0
SIR_SAR_2	86	86	86	0	0
SIR_SARI2_	86	86	86	0	0
SIR_SIN_1B	98	98	98	0	0
SIR_SIN_2	98	98	98	0	0
SIR_SINI2	98	98	98	0	0
SIR_GDR_2	14	14	14	0	0

# 6.1 QCC Errors

Number of products with QCC errors:

6.2 QCC Warnings		
Number of QCC reports with warnings	0	
6.2 Missing QCC Reports		
Number of products with missing QCC reports:	161	

0