



# ASAR Daily Report



Analysis from 20-JUN-2007 00:00:00 to 20-JUN-2007 23:59:59. Page generated on 21-JUN-2007 07:45:00.  
View log file: ASAR\_Daily\_Report\_20070621\_0730.log. For any anomalies please contact msantuari@serco.it,mtranfaglia@serco.it.

This report is automatically generated every day, every 2 hours. No comments are provided on the results.

## SUMMARY

1. DATA SUMMARY
  - 1.1 Summary tables
  - 1.2 Lists of products used
2. AUXILIARY FILES ANALYSIS
  - 2.1 IECF operational ADFs list
  - 2.2 Products with wrong ADFs
3. MODULE STEPPING PRODUCTS ANALYSIS
  - 3.1 V/V polarisation
  - 3.2 H/H polarisation
4. CALIBRATION PULSES ANALYSIS
  - 4.1 Analysis for WVS IS2 V/V
    - 4.1.1 Temporal Evolution Analysis for WVS IS2 V/V
    - 4.1.2 All Rows Analysis for WVS IS2 V/V
  - 4.2 Analysis for GM1 SS3 H/H
    - 4.2.1 Temporal Evolution Analysis for GM1 SS3 H/H
    - 4.2.2 All Rows Analysis for GM1 SS3 H/H
5. DOPPLER ANALYSIS
  - 5.1 Analysis for WVS IS2 V/V
    - 5.1.1 Doppler MAP Analysis for WVS IS2 V/V
    - 5.1.2 Doppler ANX Analysis for WVS IS2 V/V
  - 5.2 Analysis for GM1 SS1 H/H
    - 5.2.1 Doppler MAP Analysis for GM1 SS1 H/H
    - 5.2.2 Doppler ANX Analysis for GM1 SS1 H/H
  - 5.3 Doppler JUMPS Analysis for WSM
6. CHIRP ANALYSIS
  - 6.1 Analysis for WSM SS1
    - 6.1.1 ScaleFactor
7. RAW DATA ANALYSIS
  - 7.1 Analysis for WVS
  - 7.2 Analysis for IMM
8. TELEMETRY ANALYSIS
  - 8.1 Number of Missing Lines
  - 8.2 Number of Gaps

---

## 1 - DATA SUMMARY

### 1.1 - Summary tables

[ [BACK TO MENU](#) ]

WVS				GM1				APM				IMM				WSM				MS			
Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Time	Pol	Modules
PDE	IS1	V/V	5	PDE	WS	H/H	28	PDE	IS2	H/H	2	PDE	IS2	H/H	1	PDE	WS	H/H	36	PDK	2007-06-20 08:18:54	H	320
PDE	IS2	V/V	24	PDK	WS	H/H	49	PDE	IS2	H/V	1	PDE	IS2	V/V	5	PDE	WS	V/V	3				
PDK	IS2	V/V	24					PDE	IS2	V/H	3	PDE	IS4	V/V	1	PDK	WS	H/H	12				
								PDE	IS5	H/V	1	PDE	IS6	H/H	1	PDK	WS	V/V	8				
								PDE	IS6	H/H	2	PDE	IS7	H/H	1								
								PDK	IS2	H/H	1	PDK	IS2	H/H	1								
								PDK	IS5	H/V	1	PDK	IS5	H/H	1								
												PDK	IS6	V/V	1								
												PDK	IS7	H/H	1								

## 1.2 - Lists of products used

[ [BACK TO MENU](#) ]

[[TXT](#)] [[XLS](#)] [List\\_WVS\\_products\\_used](#)  
 [[TXT](#)] [[XLS](#)] [List\\_GM1\\_products\\_used](#)  
 [[TXT](#)] [[XLS](#)] [List\\_APM\\_products\\_used](#)  
 [[TXT](#)] [[XLS](#)] [List\\_IMM\\_products\\_used](#)  
 [[TXT](#)] [[XLS](#)] [List\\_WSM\\_products\\_used](#)  
 [[TXT](#)] [[XLS](#)] [List\\_MS\\_products\\_used](#)

## 2 - AUXILIARY FILES ANALYSIS

### 2.1 - IECF operational ADFs list

[ [BACK TO MENU](#) ]

ADFs disseminated for ASAR
ASA_CON_AXVIEC20070410_140202_20070204_165113_20071231_000000
ASA_INS_AXVIEC20070306_164819_20070307_060000_20071231_000000
ASA_XCH_AXVIEC20051219_162547_20020301_000000_20081231_000000
ASA_XCA_AXVIEC20070517_153558_20070204_165113_20071231_000000

### 2.2 - Products with wrong ADFs





[ [BACK TO MENU](#) ]

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
WVS	0	0	0	0
GM1	0	0	0	0
APM	0	0	0	0
IMM	0	0	0	0
WSM	0	0	0	0

[[TXT](#)] [[XLS](#)] [Check\\_ADFs\\_WVS](#)  
 [[TXT](#)] [[XLS](#)] [Check\\_ADFs\\_GM1](#)  
 [[TXT](#)] [[XLS](#)] [Check\\_ADFs\\_APM](#)  
 [[TXT](#)] [[XLS](#)] [Check\\_ADFs\\_IMM](#)  
 [[TXT](#)] [[XLS](#)] [Check\\_ADFs\\_WSM](#)

### 3 - MODULE STEPPING PRODUCTS ANALYSIS





### 3.2 - H/H polarisation


[ [BACK TO MENU](#) ]

SECOND FIXED REFERENCE	PREVIOUS PRODUCT REFERENCE
After antenna maintenance (2005-09-22/23)	Previous product in the same polarisation

Reference: 2005-09-22 06:26:51 H RxGain  
 Test : 2007-06-20 08:18:54 H




Reference: 2007-06-18 09:22:08 H RxGain  
 Test : 2007-06-20 08:18:54 H







Reference: 2005-09-22 06:26:51 H RxPhase  
 Test : 2007-06-20 08:18:54 H



Reference: 2007-06-18 09:22:08 H RxPhase  
 Test : 2007-06-20 08:18:54 H





## 4 - CALIBRATION PULSES ANALYSIS

### 4.1 - Analysis for WVS IS2 V/V

#### 4.1.1 - Temporal Evolution Analysis for WVS IS2 V/V

[ BACK TO MENU ]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

#### 4.1.2 - All Rows Analysis for WVS IS2 V/V

[ BACK TO MENU ]

## 4.2 - Analysis for GM1 SS3 H/H

### 4.2.1 - Temporal Evolution Analysis for GM1 SS3 H/H

[ BACK TO MENU ]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

### 4.2.2 - All Rows Analysis for GM1 SS3 H/H


[ BACK TO MENU ]



## 5 - DOPPLER ANALYSIS

### 5.1 - Analysis for WVS IS2 V/V

#### 5.1.1 - Doppler MAP Analysis for WVS IS2 V/V

[ BACK TO MENU ]





### 5.1.2 - Doppler ANX Analysis for WVS IS2 V/V



[ BACK TO MENU ]

---

## 5.2 - Analysis for GM1 SS1 H/H

### 5.2.1 - Doppler MAP Analysis for GM1 SS1 H/H

[ BACK TO MENU ]



### 5.2.2 - Doppler ANX Analysis for GM1 SS1 H/H

[ BACK TO MENU ]

---



### 5.3 - Doppler JUMPS Analysis for WSM


[ BACK TO MENU ]

## 6 - CHIRP ANALYSIS

### 6.1 - Analysis for WSM SS1

#### 6.1.1 - ScaleFactor

[ BACK TO MENU ]




## 7 - RAW DATA ANALYSIS

### 7.1 - Analysis for WVS

[ BACK TO MENU ]


Channel	Statistics	DSS-B
MEAN I	mean	0.000554494
	stdev	1.84085e-07
MEAN Q	mean	0.000532650
	stdev	2.19099e-07
Channel	Statistics	DSS-B
STDEV I	mean	0.137506
	stdev	0.00114213
STDEV Q	mean	0.137891
	stdev	0.00115853



## 7.2 - Analysis for IMM

[ [BACK TO MENU](#) ]

Channel	Statistics	DSS-B
MEAN I	mean	0.000318692
	stdev	4.58744e-09
MEAN Q	mean	0.000532340
	stdev	5.52535e-09
Channel	Statistics	DSS-B
STDEV I	mean	0.0632602
	stdev	0.000415368
STDEV Q	mean	0.0635029
	stdev	0.000419521



## 8 - TELEMETRY ANALYSIS

Processing Center	Product	Gaps	Missing lines
PDE	ASA_WSM_1PNPDE20070620_153622_000002632059_00126_27735_6349.N1	0	40
PDK	ASA_WSM_1PNPDK20070620_135546_000001472059_00125_27734_6370.N1	0	41

### 8.1 - Number of Missing lines

[ BACK TO MENU ]

### 8.2 - Number of Gaps

[ BACK TO MENU ]

#####  
ASAR DAILY REPORT for 070620  
#####

MODE: DAILY  
ANALYSIS: ALL  
DATE: YESTERDAY

Analysis will be performed from 2007-06-20 00:00:00 to 2007-06-20 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/070620/

DATA SUMMARY

#####  
Summary will be performed from 2007-06-20 00:00:00 to 2007-06-20 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/070620/DATA\_SUMMARY

Creating directory ./RESULTS/DAILY/070620/DATA\_SUMMARY...  
Writing file ./RESULTS/DAILY/070620/DATA\_SUMMARY/Data\_summary.html...

\*\*\*\*\*  
Getting WVS products list from 2007-06-20 00:00:00 to 2007-06-20 23:59:59...  
Writing file ./RESULTS/DAILY/070620/DATA\_SUMMARY/List\_WVS\_products\_used.xls...  
Writing file ./RESULTS/DAILY/070620/DATA\_SUMMARY/List\_WVS\_products\_used.txt...

\*\*\*\*\*  
Getting GM1 products list from 2007-06-20 00:00:00 to 2007-06-20 23:59:59...  
Writing file ./RESULTS/DAILY/070620/DATA\_SUMMARY/List\_GM1\_products\_used.xls...  
Writing file ./RESULTS/DAILY/070620/DATA\_SUMMARY/List\_GM1\_products\_used.txt...

\*\*\*\*\*  
Getting APM products list from 2007-06-20 00:00:00 to 2007-06-20 23:59:59...  
Writing file ./RESULTS/DAILY/070620/DATA\_SUMMARY/List\_APM\_products\_used.xls...  
Writing file ./RESULTS/DAILY/070620/DATA\_SUMMARY/List\_APM\_products\_used.txt...

\*\*\*\*\*  
Getting IMM products list from 2007-06-20 00:00:00 to 2007-06-20 23:59:59...  
Writing file ./RESULTS/DAILY/070620/DATA\_SUMMARY/List\_IMM\_products\_used.xls...  
Writing file ./RESULTS/DAILY/070620/DATA\_SUMMARY/List\_IMM\_products\_used.txt...

\*\*\*\*\*  
Getting WSM products list from 2007-06-20 00:00:00 to 2007-06-20 23:59:59...  
Writing file ./RESULTS/DAILY/070620/DATA\_SUMMARY/List\_WSM\_products\_used.xls...  
Writing file ./RESULTS/DAILY/070620/DATA\_SUMMARY/List\_WSM\_products\_used.txt...

\*\*\*\*\*  
Getting MS products list from 2007-06-20 00:00:00 to 2007-06-20 23:59:59...  
Writing file ./RESULTS/DAILY/070620/DATA\_SUMMARY/List\_MS\_products\_used.xls...  
Writing file ./RESULTS/DAILY/070620/DATA\_SUMMARY/List\_MS\_products\_used.txt...

DATA SUMMARY completed  
#####

AUXILIARY FILES ANALYSIS

#####  
Analysis will be performed from 2007-06-20 00:00:00 to 2007-06-20 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/070620/AUXILIARY

Creating directory ./RESULTS/DAILY/070620/AUXILIARY...

\*\*\*\*\*  
Looking for the IECF operational ADFs list...



Found list 20070620\_030001\_current\_3\_IECF\_ADFs.txt...  
Extracting ADFs...

ASA\_CON\_AXVIEC20070410\_140202\_20070204\_165113\_20071231\_000000  
ASA\_INS\_AXVIEC20070306\_164819\_20070307\_060000\_20071231\_000000  
ASA\_XCH\_AXVIEC20051219\_162547\_20020301\_000000\_20081231\_000000  
ASA\_XCA\_AXVIEC20070517\_153558\_20070204\_165113\_20071231\_000000

Writing file ./RESULTS/DAILY/070620/AUXILIARY/ASAR\_ADFs\_IECF\_List3.html...  
Writing file ./RESULTS/DAILY/070620/AUXILIARY/Auxiliary\_files\_summary.html...

\*\*\*\*\*  
Analysing WVS products...

Writing file ./RESULTS/DAILY/070620/AUXILIARY/Check\_ADFs\_WVS.xls...  
Writing file ./RESULTS/DAILY/070620/AUXILIARY/Check\_ADFs\_WVS.txt...

ASA_WVS_1PNPDE20070620_001319_000001642059_00116_27725_5359.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20070620_001504_000017542059_00116_27725_5496.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20070620_010712_000009552059_00117_27726_5503.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20070620_012930_000003752059_00117_27726_5508.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20070620_015236_000000592059_00117_27726_5516.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20070620_015236_000004202059_00117_27726_5619.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20070620_021224_000004942059_00118_27727_5626.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20070620_025748_000007342059_00118_27727_5629.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20070620_030933_000003002059_00118_27727_5754.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20070620_034019_000007042059_00118_27727_5761.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20070620_035615_000000592059_00119_27728_5772.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20070620_043839_000007342059_00119_27728_5788.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20070620_045024_000002852059_00119_27728_5910.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20070620_051350_000014842059_00119_27728_5945.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20070620_061703_000008392059_00120_27729_5925.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20070620_211131_000018892059_00129_27738_6423.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20070620_220220_000000752059_00129_27738_6545.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20070620_221010_000004342059_00129_27738_6553.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20070620_222854_000001202059_00130_27739_6550.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20070620_223314_000000602059_00130_27739_6558.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20070620_225008_000014092059_00130_27739_6568.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20070620_231833_000001952059_00130_27739_6579.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20070620_234142_000002242059_00130_27739_6593.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20070620_234427_000017392059_00130_27739_6685.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070620_063032_000004202059_00120_27729_5808.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070620_065424_000019942059_00120_27729_5816.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070620_081131_000004052059_00121_27730_5839.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070620_083500_000018292059_00121_27730_5844.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070620_090713_000001352059_00122_27731_5854.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070620_094110_000010492059_00122_27731_5967.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070620_101654_000017992059_00122_27731_5976.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070620_110502_000000602059_00123_27732_6081.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070620_110807_000017692059_00123_27732_6092.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070620_115730_000016942059_00123_27732_6166.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070620_124538_000010042059_00124_27733_6236.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070620_133648_000003752059_00124_27733_6239.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070620_134959_000002992059_00124_27733_6242.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070620_135810_000000592059_00125_27734_6272.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070620_143207_000004942059_00125_27734_6390.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070620_144813_000007502059_00125_27734_6395.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070620_151724_000010942059_00125_27734_6414.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070620_161655_000000742059_00126_27735_6568.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070620_162042_000012292059_00126_27735_6575.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070620_165800_000012892059_00126_27735_6589.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070620_175619_000014242059_00127_27736_6697.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070620_184238_000008092059_00127_27736_6711.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070620_193008_000019342059_00128_27737_6834.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20070620_201912_000004652059_00128_27737_6841.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

\*\*\*\*\*

Analysing GM1 products...

Writing file ./RESULTS/DAILY/070620/AUXILIARY/Check\_ADFs\_GM1.xls...

Writing file ./RESULTS/DAILY/070620/AUXILIARY/Check\_ADFs\_GM1.txt...

ASA_GM1_1PNPDE20070620_000049_000003982059_00116_27725_5361.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070620_005338_000008092059_00117_27726_5498.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070620_012402_000003262059_00117_27726_5500.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070620_013638_000001022059_00117_27726_5505.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070620_014548_000004042059_00117_27726_5518.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070620_020030_000007122059_00117_27726_5623.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070620_022136_000002352059_00118_27727_5621.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070620_023413_0000011532059_00118_27727_5700.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070620_032102_000002772059_00118_27727_5756.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070620_033430_000003442059_00118_27727_5758.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070620_035250_000002052059_00119_27728_5763.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070620_040452_000015882059_00119_27728_5850.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070620_043410_000001082059_00119_27728_5778.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070620_043655_000001022059_00119_27728_5785.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070620_045750_000003622059_00119_27728_5912.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070620_053924_000005552059_00120_27729_5914.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070620_055026_000004412059_00120_27729_5937.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070620_060419_000003502059_00120_27729_5935.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070620_061439_000001382059_00120_27729_5927.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070620_210542_000002592059_00129_27738_6420.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070620_214349_000000782059_00129_27738_6418.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070620_214737_000007432059_00129_27738_6433.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070620_221814_000005012059_00130_27739_6547.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070620_222743_000000662059_00130_27739_6555.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070620_224529_000002772059_00130_27739_6565.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070620_231422_000001322059_00130_27739_6563.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070620_231649_000001022059_00130_27739_6576.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20070620_232713_000005612059_00130_27739_6595.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_063826_000009242059_00120_27729_5805.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_073943_000005552059_00121_27730_5830.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_075602_000000722059_00121_27730_5836.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_080103_000001502059_00121_27730_5834.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_080735_000002352059_00121_27730_5832.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_082018_000008822059_00121_27730_5841.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_091012_000006642059_00122_27731_5868.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_092304_000001812059_00122_27731_5962.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_093216_000005312059_00122_27731_5964.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_095938_000001262059_00122_27731_5969.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_104902_000001502059_00123_27732_5971.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_105315_000001932059_00123_27732_5973.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_110320_000001022059_00123_27732_6083.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_114303_000002772059_00123_27732_6094.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_122627_000003982059_00124_27733_6096.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_123452_000003562059_00124_27733_6158.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_124007_000003262059_00124_27733_6229.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_130438_000005012059_00124_27733_6231.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_131313_000003202059_00124_27733_6233.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_131923_000010392059_00124_27733_6346.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_134353_000003622059_00124_27733_6250.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_140205_000001022059_00125_27734_6248.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_140524_000005492059_00125_27734_6274.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_141627_000001572059_00125_27734_6269.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_141823_000004472059_00125_27734_6385.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_142933_000001502059_00125_27734_6387.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_144107_000004222059_00125_27734_6392.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_150125_000009242059_00125_27734_6397.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_154057_000000782059_00126_27735_6410.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_160244_000001992059_00126_27735_6563.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_160948_000004222059_00126_27735_6565.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_161858_000001022059_00126_27735_6570.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

```
ASA_GM1_1PNPDK20070620_164201_000005072059_00126_27735_6572.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_165411_000002232059_00126_27735_6577.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_172016_000004652059_00127_27736_6579.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_172954_000002412059_00127_27736_6586.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_174447_000002412059_00127_27736_6692.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_175014_000003082059_00127_27736_6694.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_182727_000006642059_00127_27736_6699.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_185700_000006402059_00128_27737_6701.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_191030_000001632059_00128_27737_6708.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_191212_000001752059_00128_27737_6823.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_192747_000001382059_00128_27737_6825.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_200313_000004162059_00128_27737_6827.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_201623_000001692059_00128_27737_6829.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_202743_000002172059_00128_27737_6831.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_203229_000007182059_00128_27737_6838.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_204950_00000902059_00129_27738_6836.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20070620_205215_00000782059_00129_27738_6850.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```

\*\*\*\*\*

Analysing APM products...

Writing file ./RESULTS/DAILY/070620/AUXILIARY/Check\_ADFs\_APM.xls...

Writing file ./RESULTS/DAILY/070620/AUXILIARY/Check\_ADFs\_APM.txt...

```
ASA_APM_1PNPDE20070620_025645_00000562059_00118_27727_5708.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20070620_040344_00000402059_00119_27728_6228.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20070620_074857_00000422059_00121_27730_6077.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20070620_075716_000002002059_00121_27730_6145.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20070620_172802_00000852059_00127_27736_6347.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20070620_190741_00000402059_00128_27737_6373.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20070620_192609_00000712059_00128_27737_6412.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20070620_203121_00000422059_00128_27737_6386.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20070620_222636_00000402059_00130_27739_6526.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDK20070620_140014_00000842059_00125_27734_6366.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDK20070620_190829_00000952059_00128_27737_6795.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```

\*\*\*\*\*

Analysing IMM products...

Writing file ./RESULTS/DAILY/070620/AUXILIARY/Check\_ADFs\_IMM.xls...

Writing file ./RESULTS/DAILY/070620/AUXILIARY/Check\_ADFs\_IMM.txt...

```
ASA_IMM_1PNPDE20070620_043557_00000402059_00119_27728_6230.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20070620_061011_000002512059_00120_27729_6020.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20070620_104726_00000792059_00123_27732_6262.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20070620_154455_000001912059_00126_27735_6297.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20070620_174354_00000362059_00127_27736_6331.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20070620_174851_00000642059_00127_27736_6353.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20070620_175523_00000352059_00127_27736_6351.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20070620_204427_00000612059_00129_27738_6416.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20070620_211002_00000832059_00129_27738_6528.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20070620_131831_00000352059_00124_27733_6340.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20070620_140347_00000792059_00125_27734_6364.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20070620_205122_00000352059_00129_27738_6848.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20070620_223448_00000662059_00130_27739_6959.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```

\*\*\*\*\*

Analysing WSM products...

Writing file ./RESULTS/DAILY/070620/AUXILIARY/Check\_ADFs\_WSM.xls...

Writing file ./RESULTS/DAILY/070620/AUXILIARY/Check\_ADFs\_WSM.txt...

ASA\_WSM\_1PNPDE20070620\_000738\_000003422059\_00116\_27725\_5588.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDE20070620\_000738\_000003422059\_00116\_27725\_6174.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDE20070620\_004504\_000005022059\_00117\_27726\_5714.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDE20070620\_013829\_000004282059\_00117\_27726\_6131.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDE20070620\_022539\_000005002059\_00118\_27727\_5880.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDE20070620\_025337\_000001592059\_00118\_27727\_5712.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDE20070620\_031728\_000002022059\_00118\_27727\_5852.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDE20070620\_031835\_000001352059\_00118\_27727\_5745.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDE20070620\_032550\_000003852059\_00118\_27727\_5901.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDE20070620\_035810\_000002632059\_00119\_27728\_6133.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDE20070620\_043130\_000001522059\_00119\_27728\_6264.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDE20070620\_045604\_000000852059\_00119\_27728\_6260.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDE20070620\_050404\_000005872059\_00119\_27728\_6141.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDE20070620\_054852\_000000852059\_00120\_27729\_6037.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDE20070620\_073628\_000000852059\_00121\_27730\_6117.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDE20070620\_080343\_000002192059\_00121\_27730\_6161.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDE20070620\_100152\_000003422059\_00122\_27731\_6198.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDE20070620\_100813\_000005182059\_00122\_27731\_6270.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDE20070620\_113829\_000002632059\_00123\_27732\_6258.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDE20070620\_153622\_000002632059\_00126\_27735\_6349.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDE20070620\_154225\_000001412059\_00126\_27735\_6357.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDE20070620\_154333\_000000722059\_00126\_27735\_6339.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDE20070620\_154919\_000002012059\_00126\_27735\_6299.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDE20070620\_165038\_000001282059\_00126\_27735\_6315.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDE20070620\_165038\_000002012059\_00126\_27735\_6355.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDE20070620\_165341\_000000182059\_00126\_27735\_6307.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDE20070620\_174105\_000001472059\_00127\_27736\_6341.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDE20070620\_182053\_000003852059\_00127\_27736\_6379.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDE20070620\_192036\_000000852059\_00128\_27737\_6381.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDE20070620\_192105\_000002382059\_00128\_27737\_6414.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDE20070620\_201023\_000003482059\_00128\_27737\_6501.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDE20070620\_210009\_000002072059\_00129\_27738\_6657.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDE20070620\_210408\_000000852059\_00129\_27738\_6530.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDE20070620\_214516\_000001282059\_00129\_27738\_6659.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDE20070620\_220428\_000003422059\_00129\_27738\_6661.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDE20070620\_224001\_000003062059\_00130\_27739\_7090.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDE20070620\_232239\_000002632059\_00130\_27739\_7086.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDE20070620\_233645\_000003002059\_00130\_27739\_6682.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDK20070620\_055756\_000003662059\_00120\_27729\_5793.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDK20070620\_073029\_000002012059\_00121\_27730\_5803.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDK20070620\_092129\_000000672059\_00122\_27731\_6223.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDK20070620\_092129\_000000672059\_00122\_27731\_6381.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDK20070620\_092129\_000000672059\_00122\_27731\_6559.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDK20070620\_105641\_000003912059\_00123\_27732\_6190.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDK20070620\_110644\_000000852059\_00123\_27732\_6058.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDK20070620\_114750\_000005802059\_00123\_27732\_6227.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDK20070620\_123318\_000000852059\_00124\_27733\_6221.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDK20070620\_135546\_000001472059\_00125\_27734\_6370.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDK20070620\_141445\_000000922059\_00125\_27734\_6368.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDK20070620\_155214\_000000912059\_00126\_27735\_6479.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDK20070620\_155428\_000004842059\_00126\_27735\_6509.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDK20070620\_173405\_000005122059\_00127\_27736\_6690.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDK20070620\_191517\_000000862059\_00128\_27737\_6800.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDK20070620\_191731\_000002312059\_00128\_27737\_6815.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDK20070620\_205346\_000000852059\_00129\_27738\_6938.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDK20070620\_205538\_000003062059\_00129\_27738\_6943.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDK20070620\_223149\_000000862059\_00130\_27739\_6969.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
ASA\_WSM\_1PNPDK20070620\_223648\_000002452059\_00130\_27739\_6971.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK

AUXILIARY FILES ANALYSIS completed

#####

MODULE STEPPING ANALYSIS

#####



Analysis will be performed from 2007-06-20 00:00:00 to 2007-06-20 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/070620/MODULE\_STEPPING

Creating directory ./RESULTS/DAILY/070620/MODULE\_STEPPING...  
Creating directory ./RESULTS/DAILY/070620/MODULE\_STEPPING/FIRST\_REFERENCE...  
Creating directory ./RESULTS/DAILY/070620/MODULE\_STEPPING/SECOND\_REFERENCE...  
Creating directory ./RESULTS/DAILY/070620/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE...  
Deleting old files...

\*\*\*\*\*  
\*\*\*\*\*  
Creating images comparing with second reference...

Exporting results to the directory ../../RESULTS/DAILY/070620/MODULE\_STEPPING/SECOND\_REFERENCE...

Polarization: H  
Reference product: ASA\_MS\_\_0PNPDK20050922\_062651\_000000152041\_00034\_18625\_0041.N1  
Test product: ASA\_MS\_\_0PNPDK20070620\_081854\_000000162059\_00121\_27730\_0315.N1  
H  
H  
../../RESULTS/DAILY/070620/MODULE\_STEPPING/SECOND\_REFERENCE/TGH\_20070620\_081854-20050922\_062651.png  
../../RESULTS/DAILY/070620/MODULE\_STEPPING/SECOND\_REFERENCE/TPH\_20070620\_081854-20050922\_062651.png  
../../RESULTS/DAILY/070620/MODULE\_STEPPING/SECOND\_REFERENCE/RGH\_20070620\_081854-20050922\_062651.png  
../../RESULTS/DAILY/070620/MODULE\_STEPPING/SECOND\_REFERENCE/RPH\_20070620\_081854-20050922\_062651.png

Polarization: V  
Reference product: ASA\_MS\_\_0PNPDK20050923\_055514\_000000152041\_00048\_18639\_0042.N1  
Test product: ASA\_MS\_\_0PNPDK20070619\_085031\_000000162059\_00107\_27716\_0314.N1  
V  
V  
../../RESULTS/DAILY/070620/MODULE\_STEPPING/SECOND\_REFERENCE/TGV\_20070619\_085031-20050923\_055514.png  
../../RESULTS/DAILY/070620/MODULE\_STEPPING/SECOND\_REFERENCE/TPV\_20070619\_085031-20050923\_055514.png  
../../RESULTS/DAILY/070620/MODULE\_STEPPING/SECOND\_REFERENCE/RGV\_20070619\_085031-20050923\_055514.png  
../../RESULTS/DAILY/070620/MODULE\_STEPPING/SECOND\_REFERENCE/RPV\_20070619\_085031-20050923\_055514.png

\*\*\*\*\*  
\*\*\*\*\*  
Creating images comparing with previous product reference...

Exporting results to the directory ../../RESULTS/DAILY/070620/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE...

Polarization: H  
Reference product: ASA\_MS\_\_0PNPDK20070618\_092208\_000000162059\_00093\_27702\_0313.N1  
Test product: ASA\_MS\_\_0PNPDK20070620\_081854\_000000162059\_00121\_27730\_0315.N1  
H  
H  
../../RESULTS/DAILY/070620/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/TGH\_20070620\_081854-20070618\_092208.png  
../../RESULTS/DAILY/070620/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/TPH\_20070620\_081854-20070618\_092208.png  
../../RESULTS/DAILY/070620/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/RGH\_20070620\_081854-20070618\_092208.png  
../../RESULTS/DAILY/070620/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/RPH\_20070620\_081854-20070618\_092208.png

Polarization: V  
Reference product: ASA\_MS\_\_0PNPDK20070617\_095345\_000000162059\_00079\_27688\_0312.N1  
Test product: ASA\_MS\_\_0PNPDK20070619\_085031\_000000162059\_00107\_27716\_0314.N1  
V  
V  
../../RESULTS/DAILY/070620/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/TGV\_20070619\_085031-20070617\_095345.png  
../../RESULTS/DAILY/070620/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/TPV\_20070619\_085031-20070617\_095345.png  
../../RESULTS/DAILY/070620/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/RGV\_20070619\_085031-20070617\_095345.png  
../../RESULTS/DAILY/070620/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/RPV\_20070619\_085031-20070617\_095345.png

MODULE\_STEPPING ANALYSIS completed  
#####

#####

Creating directory ./RESULTS/DAILY/070620/CALIBRATION\_PULSES...

\*\*\*\*\*  
\*\*\*\*\*

ALL ROWS Analysis will be performed from 2007-06-20 00:00:00 to 2007-06-20 23:59:59

Analysing products WVS IS2 V/V

Writing image ../../RESULTS/DAILY/070620//CALIBRATION\_PULSES/Calibration\_pulses\_all\_rows\_WVS\_IS2\_VV.png...

Analysing products GM1 SS3 H/H

Writing image ../../RESULTS/DAILY/070620//CALIBRATION\_PULSES/Calibration\_pulses\_all\_rows\_GM1\_SS3\_HH.png...

\*\*\*\*\*  
\*\*\*\*\*

TEMPORAL EVOLUTION Analysis will be performed from 2007-06-20 00:00:00 to 2007-06-20 23:59:59

Analysing products WVS IS2 V/V

Getting calibration pulses data for WVS IS2 V/V from 2007-06-20 00:00:00 to 2007-06-20 23:59:59. Rows: 1/5/9/13/17/21/25/29

Writing file ./RESULTS/DAILY/070620/CALIBRATION\_PULSES/Calibration\_pulses\_data\_WVS\_IS2\_VV\_2007-06-20\_1.dat...

Writing ../../RESULTS/DAILY/070620//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_WVS\_IS2\_VV\_1.png...

Writing ../../RESULTS/DAILY/070620//CALIBRATION\_PULSES/Transmit\_Power\_WVS\_IS2\_VV\_1.png...

Getting calibration pulses data for WVS IS2 V/V from 2007-06-20 00:00:00 to 2007-06-20 23:59:59. Rows: 2/6/10/14/18/22/26/30

Writing file ./RESULTS/DAILY/070620/CALIBRATION\_PULSES/Calibration\_pulses\_data\_WVS\_IS2\_VV\_2007-06-20\_2.dat...

Writing ../../RESULTS/DAILY/070620//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_WVS\_IS2\_VV\_2.png...

Writing ../../RESULTS/DAILY/070620//CALIBRATION\_PULSES/Transmit\_Power\_WVS\_IS2\_VV\_2.png...

Getting calibration pulses data for WVS IS2 V/V from 2007-06-20 00:00:00 to 2007-06-20 23:59:59. Rows: 3/7/11/15/19/23/27/31

Writing file ./RESULTS/DAILY/070620/CALIBRATION\_PULSES/Calibration\_pulses\_data\_WVS\_IS2\_VV\_2007-06-20\_3.dat...

Writing ../../RESULTS/DAILY/070620//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_WVS\_IS2\_VV\_3.png...

Writing ../../RESULTS/DAILY/070620//CALIBRATION\_PULSES/Transmit\_Power\_WVS\_IS2\_VV\_3.png...

Getting calibration pulses data for WVS IS2 V/V from 2007-06-20 00:00:00 to 2007-06-20 23:59:59. Rows: 4/8/12/16/20/24/28/32

Writing file ./RESULTS/DAILY/070620/CALIBRATION\_PULSES/Calibration\_pulses\_data\_WVS\_IS2\_VV\_2007-06-20\_4.dat...

Writing ../../RESULTS/DAILY/070620//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_WVS\_IS2\_VV\_4.png...

Writing ../../RESULTS/DAILY/070620//CALIBRATION\_PULSES/Transmit\_Power\_WVS\_IS2\_VV\_4.png...

Analysing products GM1 SS3 H/H

Getting calibration pulses data for GM1 SS3 H/H from 2007-06-20 00:00:00 to 2007-06-20 23:59:59. Rows: 1/5/9/13/17/21/25/29

Writing file ./RESULTS/DAILY/070620/CALIBRATION\_PULSES/Calibration\_pulses\_data\_GM1\_SS3\_HH\_2007-06-20\_1.dat...

Writing ../../RESULTS/DAILY/070620//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_GM1\_SS3\_HH\_1.png...

Writing ../../RESULTS/DAILY/070620//CALIBRATION\_PULSES/Transmit\_Power\_GM1\_SS3\_HH\_1.png...

Getting calibration pulses data for GM1 SS3 H/H from 2007-06-20 00:00:00 to 2007-06-20 23:59:59. Rows: 2/6/10/14/18/22/26/30

Writing file ./RESULTS/DAILY/070620/CALIBRATION\_PULSES/Calibration\_pulses\_data\_GM1\_SS3\_HH\_2007-06-20\_2.dat...

Writing ../../RESULTS/DAILY/070620//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_GM1\_SS3\_HH\_2.png...

Writing ../../RESULTS/DAILY/070620//CALIBRATION\_PULSES/Transmit\_Power\_GM1\_SS3\_HH\_2.png...

Getting calibration pulses data for GM1 SS3 H/H from 2007-06-20 00:00:00 to 2007-06-20 23:59:59. Rows: 3/7/11/15/19/23/27/31

Writing file ./RESULTS/DAILY/070620/CALIBRATION\_PULSES/Calibration\_pulses\_data\_GM1\_SS3\_HH\_2007-06-20\_3.dat...

Writing ../../RESULTS/DAILY/070620//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_GM1\_SS3\_HH\_3.png...

Writing ../../RESULTS/DAILY/070620//CALIBRATION\_PULSES/Transmit\_Power\_GM1\_SS3\_HH\_3.png...

Getting calibration pulses data for GM1 SS3 H/H from 2007-06-20 00:00:00 to 2007-06-20 23:59:59. Rows: 4/8/12/16/20/24/28/32

Writing file ./RESULTS/DAILY/070620/CALIBRATION\_PULSES/Calibration\_pulses\_data\_GM1\_SS3\_HH\_2007-06-20\_4.dat...

Writing ../../RESULTS/DAILY/070620//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_GM1\_SS3\_HH\_4.png...

Writing ../../RESULTS/DAILY/070620//CALIBRATION\_PULSES/Transmit\_Power\_GM1\_SS3\_HH\_4.png...

CALIBRATION PULSES ANALYSIS completed

#####

DOPPLER ANALYSIS

#####

Creating directory ./RESULTS/DAILY/070620/DOPPLER...

\*\*\*\*\*  
\*\*\*\*\*

DOPPLER ANX Analysis will be performed from 2007-06-20 00:00:00 to 2007-06-20 23:59:59

Analysing products WVS IS2 V/V

Getting doppler data for WVS IS2 V/V from 2007-06-20 00:00:00 to 2007-06-20 23:59:59...

Writing file ./RESULTS/DAILY/070620/DOPPLER/Doppler\_data\_WVS\_IS2\_VV\_2007-06-20.dat...

Running IDL program...

Writing file ../../RESULTS/DAILY/070620/DOPPLER/DOPPLER\_ANX\_WVS\_IS2\_VV.png...

Analysing products GM1 SS1 H/H

Getting doppler data for GM1 SS1 H/H from 2007-06-20 00:00:00 to 2007-06-20 23:59:59...

Writing file ./RESULTS/DAILY/070620/DOPPLER/Doppler\_data\_GM1\_SS1\_HH\_2007-06-20.dat...

Running IDL program...

Writing file ../../RESULTS/DAILY/070620/DOPPLER/DOPPLER\_ANX\_GM1\_SS1\_HH.png...

\*\*\*\*\*  
\*\*\*\*\*

DOPPLER JUMPS Analysis will be performed on WSM products from 2007-06-20 00:00:00 to 2007-06-20 23:59:59

Analysing by default products WSM

Getting doppler jumps data for WSM from 2007-06-20 00:00:00 to 2007-06-20 23:59:59...

Writing file ./RESULTS/DAILY/070620/DOPPLER/Doppler\_Jumps\_data\_WSM\_2007-06-20.dat...

Running IDL program...

Writing file ../../RESULTS/DAILY/070620/DOPPLER/DOPPLER\_JUMPS\_ANX\_WSM.png...

Writing file ../../RESULTS/DAILY/070620/DOPPLER/DOPPLER\_JUMPS\_Date\_WSM.png...

\*\*\*\*\*  
\*\*\*\*\*

DOPPLER MAP Analysis will be performed from 2007-06-20 00:00:00 to 2007-06-20 23:59:59

Analysing products WVS IS2 V/V

Loading predicted doppler values....

Phase: descending

Found data...

Computing mean error doppler estimated-predicted...

Mean error = -19.286691 Hz

Writing file ../../RESULTS/DAILY/070620//DOPPLER/DOPPLER\_Estimated-Predicted-MeanError\_WVS\_IS2\_VV\_desc.jpg...

Writing file ../../RESULTS/DAILY/070620//DOPPLER/DOPPLER\_Absolute\_WVS\_IS2\_VV\_desc.jpg...

\*\*\*\*\*

Loading predicted doppler values....

Phase: ascending

Found data...

Computing mean error doppler estimated-predicted...

Mean error = -10.248904 Hz

Writing file ../../RESULTS/DAILY/070620//DOPPLER/DOPPLER\_Estimated-Predicted-MeanError\_WVS\_IS2\_VV\_asc.jpg...

Writing file ../../RESULTS/DAILY/070620//DOPPLER/DOPPLER\_Absolute\_WVS\_IS2\_VV\_asc.jpg...

\*\*\*\*\*

Analysing products GM1 SS1 H/H

Loading predicted doppler values....

Phase: descending  
Found data...  
Computing mean error doppler estimated-predicted...  
Mean error = -17.102637 Hz  
Writing file ../../RESULTS/DAILY/070620//DOPPLER/DOPPLER\_Estimated-Predicted-MeanError\_GM1\_SS1\_HH\_desc.jpg...  
Writing file ../../RESULTS/DAILY/070620//DOPPLER/DOPPLER\_Absolute\_GM1\_SS1\_HH\_desc.jpg...

\*\*\*\*\*  
Loading predicted doppler values....  
Phase: ascending  
Found data...  
Computing mean error doppler estimated-predicted...  
Mean error = -22.879405 Hz  
Writing file ../../RESULTS/DAILY/070620//DOPPLER/DOPPLER\_Estimated-Predicted-MeanError\_GM1\_SS1\_HH\_asc.jpg...  
Writing file ../../RESULTS/DAILY/070620//DOPPLER/DOPPLER\_Absolute\_GM1\_SS1\_HH\_asc.jpg...

\*\*\*\*\*

DOPPLER ANALYSIS completed  
#####

CHIRP ANALYSIS  
#####  
Creating directory ./RESULTS/DAILY/070620/CHIRP...

\*\*\*\*\*  
\*\*\*\*\*  
CHIRP Analysis will be performed from 2007-06-20 00:00:00 to 2007-06-20 23:59:59

Analysing products WSM SS1  
\*\*\*\*\*  
Getting ScaleFactor data for WSM SS1 from 2007-06-20 00:00:00 to 2007-06-20 23:59:59...  
Writing file ./RESULTS/DAILY/070620/CHIRP/ScaleFactor\_data\_WSM\_SS1\_2007-06-20.dat...  
Running IDL program...  
Writing file ../../RESULTS/DAILY/070620/CHIRP/ScaleFactor\_ANX\_WSM\_SS1.png...  
Writing file ../../RESULTS/DAILY/070620/CHIRP/ScaleFactor\_DATE\_WSM\_SS1.png...

CHIRP ANALYSIS completed  
#####

RAW DATA ANALYSIS  
#####  
Analysis will be performed from 2007-06-20 00:00:00 to 2007-06-20 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/070620/RAW\_DATA

Creating directory ./RESULTS/DAILY/070620/RAW\_DATA...

\*\*\*\*\*  
Getting raw data for WVS from 2007-06-20 00:00:00 to 2007-06-20 23:59:59...  
Writing file ./RESULTS/DAILY/070620/RAW\_DATA/Raw\_data\_WVS\_2007-06-20.dat...  
Running IDL program to create graphs...

Creating image ../../RESULTS/DAILY/070620/RAW\_DATA/Raw\_data\_WVS\_input\_mean.png...  
Creating image ../../RESULTS/DAILY/070620/RAW\_DATA/Raw\_data\_WVS\_input\_stdev.png...  
Creating image ../../RESULTS/DAILY/070620/RAW\_DATA/Raw\_data\_WVS\_gain\_imbalance.png...

\*\*\*\*\*  
Getting raw data for IMM from 2007-06-20 00:00:00 to 2007-06-20 23:59:59...  
Writing file ./RESULTS/DAILY/070620/RAW\_DATA/Raw\_data\_IMM\_2007-06-20.dat...

Running IDL program to create graphs...

Creating image ../../RESULTS/DAILY/070620/RAW\_DATA/Raw\_data\_IMM\_input\_mean.png...  
Creating image ../../RESULTS/DAILY/070620/RAW\_DATA/Raw\_data\_IMM\_input\_stdev.png...  
Creating image ../../RESULTS/DAILY/070620/RAW\_DATA/Raw\_data\_IMM\_gain\_imbalance.png...

RAW DATA ANALYSIS completed

#####

TELEMETRY ANALYSIS

#####

Analysis will be performed from 2007-06-20 00:00:00 to 2007-06-20 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/070620/TELEMETRY

Creating directory ./RESULTS/DAILY/070620/TELEMETRY...

Looking for gaps and missing lines in WVS products...

\*\*\*\*\*

Checking 24 products from PDE...  
Checking 24 products from PDK...

Looking for gaps and missing lines in GM1 products...

\*\*\*\*\*

Checking 28 products from PDE...  
Checking 49 products from PDK...

Looking for gaps and missing lines in APM products...

\*\*\*\*\*

Checking 9 products from PDE...  
Checking 2 products from PDK...

Looking for gaps and missing lines in IMM products...

\*\*\*\*\*

Checking 9 products from PDE...  
Checking 4 products from PDK...

Looking for gaps and missing lines in WSM products...

\*\*\*\*\*

Checking 39 products from PDE...  
Found product...ASA\_WSM\_1PNPDE20070620\_153622\_000002632059\_00126\_27735\_6349.N1 / 0 gaps / 40 missing lines  
Checking 20 products from PDK...  
Found product...ASA\_WSM\_1PNPDK20070620\_135546\_000001472059\_00125\_27734\_6370.N1 / 0 gaps / 41 missing lines

Creating graph of missing lines and gaps...

\*\*\*\*\*

Creating image: ./RESULTS/DAILY/070620/TELEMETRY/TELEMETRY\_Missing\_lines.png...  
Creating image: ./RESULTS/DAILY/070620/TELEMETRY/TELEMETRY\_Gaps.png...

TELEMETRY ANALYSIS completed

#####

BROWSE PRODUCTS ANALYSIS

#####

Analysis will be performed on 2007-06-20

\*\*\*\*\*

Scanning directory /nas3/ENVISAT/ASAR//ASA\_GM\_\_BP...  
Results will be exported to the directory: /nas3/ENVISAT/ASAR//ASA\_GM\_\_BP/JPG/20070620/

ANALYSIS COMPLETED: 0 GM browse products to see...



\*\*\*\*\*

\*\*\*\*\*

Scanning directory /nas3/ENVISAT/ASAR//ASA\_AP\_BP...
Results will be exported to the directory: /nas3/ENVISAT/ASAR//ASA\_AP\_BP/JPG/20070620/

Stripping browse product /nas3/ENVISAT/ASAR//ASA\_AP\_BP/ASA\_AP\_BPZPDE20070620\_040344\_000000402059\_00119\_27728\_6229.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_AP\_BP/ASA\_AP\_BPZPDE20070620\_074857\_000000422059\_00121\_27730\_6078.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_AP\_BP/ASA\_AP\_BPZPDE20070620\_075716\_000002002059\_00121\_27730\_6146.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_AP\_BP/ASA\_AP\_BPZPDE20070620\_172802\_000000852059\_00127\_27736\_6348.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_AP\_BP/ASA\_AP\_BPZPDE20070620\_190741\_000000402059\_00128\_27737\_6374.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_AP\_BP/ASA\_AP\_BPZPDE20070620\_192609\_000000712059\_00128\_27737\_6413.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_AP\_BP/ASA\_AP\_BPZPDE20070620\_203121\_000000422059\_00128\_27737\_6387.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_AP\_BP/ASA\_AP\_BPZPDE20070620\_222636\_000000402059\_00130\_27739\_6527.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_AP\_BP/ASA\_AP\_BPZPDK20070620\_190829\_000000952059\_00128\_27737\_6796.N1 ...

ANALYSIS COMPLETED: 9 AP browse products to see...
\*\*\*\*\*

\*\*\*\*\*

Scanning directory /nas3/ENVISAT/ASAR//ASA\_IM\_BP...
Results will be exported to the directory: /nas3/ENVISAT/ASAR//ASA\_IM\_BP/JPG/20070620/

ANALYSIS COMPLETED: 0 IM browse products to see...
\*\*\*\*\*

\*\*\*\*\*

Scanning directory /nas3/ENVISAT/ASAR//ASA\_WS\_BP...
Results will be exported to the directory: /nas3/ENVISAT/ASAR//ASA\_WS\_BP/JPG/20070620/

ANALYSIS COMPLETED: 0 WS browse products to see...
\*\*\*\*\*

BROWSE PRODUCTS ANALYSIS completed
#####

HTML REPORT generation
#####

Building file ./RESULTS/DAILY/070620/asarReport.html...
Building DATA SUMMARY section...
Building AUXILIARY FILES ANALYSIS section...
Building MODULE STEPPING ANALYSIS section...
Building CALIBRATION PULSES ANALYSIS section...
Building DOPPLER ANALYSIS section...
Building CHIRP ANALYSIS section...
Building RAW DATA ANALYSIS section...
Building TELEMETRY ANALYSIS section...

HTML REPORT generation completed
#####



# ASAR Daily Report



Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
ASA_APM_1PNPDE20070620_025645_000000562059_00118_27727_5708.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20070620_040344_000000402059_00119_27728_6228.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20070620_074857_000000422059_00121_27730_6077.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20070620_075716_000002002059_00121_27730_6145.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20070620_172802_000000852059_00127_27736_6347.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20070620_190741_000000402059_00128_27737_6373.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20070620_192609_000000712059_00128_27737_6412.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20070620_203121_000000422059_00128_27737_6386.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20070620_222636_000000402059_00130_27739_6526.N1	OK	OK	OK	OK
ASA_APM_1PNPDK20070620_140014_000000842059_00125_27734_6366.N1	OK	OK	OK	OK
ASA_APM_1PNPDK20070620_190829_000000952059_00128_27737_6795.N1	OK	OK	OK	OK



Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_GM1_1PNPDE20070620_000049_000003982059_00116_27725_5361.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070620_005338_000008092059_00117_27726_5498.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070620_012402_000003262059_00117_27726_5500.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070620_013638_000001022059_00117_27726_5505.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070620_014548_000004042059_00117_27726_5518.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070620_020030_000007122059_00117_27726_5623.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070620_022136_000002352059_00118_27727_5621.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070620_023413_000011532059_00118_27727_5700.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070620_032102_000002772059_00118_27727_5756.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070620_033430_000003442059_00118_27727_5758.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070620_035250_000002052059_00119_27728_5763.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070620_040452_000015882059_00119_27728_5850.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070620_043410_000001082059_00119_27728_5778.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070620_043655_000001022059_00119_27728_5785.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070620_045750_000003622059_00119_27728_5912.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070620_053924_000005552059_00120_27729_5914.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070620_055026_000004412059_00120_27729_5937.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070620_060419_000003502059_00120_27729_5935.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070620_061439_000001382059_00120_27729_5927.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070620_210542_000002592059_00129_27738_6420.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070620_214349_000000782059_00129_27738_6418.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070620_214737_000007432059_00129_27738_6433.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070620_221814_000005012059_00130_27739_6547.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070620_222743_000000662059_00130_27739_6555.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070620_224529_000002772059_00130_27739_6565.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070620_231422_000001322059_00130_27739_6563.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070620_231649_000001022059_00130_27739_6576.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20070620_232713_000005612059_00130_27739_6595.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_063826_000009242059_00120_27729_5805.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_073943_000005552059_00121_27730_5830.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_075602_000000722059_00121_27730_5836.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_080103_000001502059_00121_27730_5834.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_080735_000002352059_00121_27730_5832.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_082018_000008822059_00121_27730_5841.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_091012_000006642059_00122_27731_5868.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_092304_000001812059_00122_27731_5962.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_093216_000005312059_00122_27731_5964.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_095938_000001262059_00122_27731_5969.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_104902_000001502059_00123_27732_5971.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_105315_000001932059_00123_27732_5973.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_110320_000001022059_00123_27732_6083.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_114303_000002772059_00123_27732_6094.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_122627_000003982059_00124_27733_6096.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_123452_000003562059_00124_27733_6158.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_124007_000003262059_00124_27733_6229.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_130438_000005012059_00124_27733_6231.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_131313_000003202059_00124_27733_6233.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_131923_000010392059_00124_27733_6346.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_134353_000003622059_00124_27733_6250.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_140205_000001022059_00125_27734_6248.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_140524_000005492059_00125_27734_6274.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_141627_000001572059_00125_27734_6269.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_141823_000004472059_00125_27734_6385.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_142933_000001502059_00125_27734_6387.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_144107_000004222059_00125_27734_6392.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_150125_000009242059_00125_27734_6397.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_154057_000000782059_00126_27735_6410.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_160244_000001992059_00126_27735_6563.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_160948_000004222059_00126_27735_6565.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_161858_000001022059_00126_27735_6570.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_164201_000005072059_00126_27735_6572.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_165411_000002232059_00126_27735_6577.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_172016_000004652059_00127_27736_6579.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_172954_000002412059_00127_27736_6586.N1					OK	OK	OK	OK

ASA_GM1_1PNPDK20070620_174447_000002412059_00127_27736_6692.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_175014_000003082059_00127_27736_6694.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_182727_000006642059_00127_27736_6699.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_185700_000006402059_00128_27737_6701.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_191030_000001632059_00128_27737_6708.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_191212_000001752059_00128_27737_6823.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_192747_000001382059_00128_27737_6825.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_200313_000004162059_00128_27737_6827.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_201623_000001692059_00128_27737_6829.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_202743_000002172059_00128_27737_6831.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_203229_000007182059_00128_27737_6838.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_204950_00000902059_00129_27738_6836.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20070620_205215_000000782059_00129_27738_6850.N1	OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
ASA_IMM_1PNPDE20070620_043557_000000402059_00119_27728_6230.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20070620_061011_000002512059_00120_27729_6020.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20070620_104726_000000792059_00123_27732_6262.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20070620_154455_000001912059_00126_27735_6297.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20070620_174354_000000362059_00127_27736_6331.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20070620_174851_000000642059_00127_27736_6353.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20070620_175523_000000352059_00127_27736_6351.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20070620_204427_000000612059_00129_27738_6416.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20070620_211002_000000832059_00129_27738_6528.N1	OK	OK	OK	OK
ASA_IMM_1PNPDK20070620_131831_000000352059_00124_27733_6340.N1	OK	OK	OK	OK
ASA_IMM_1PNPDK20070620_140347_000000792059_00125_27734_6364.N1	OK	OK	OK	OK
ASA_IMM_1PNPDK20070620_205122_000000352059_00129_27738_6848.N1	OK	OK	OK	OK
ASA_IMM_1PNPDK20070620_223448_000000662059_00130_27739_6959.N1	OK	OK	OK	OK


Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WSM_1PNPDE20070620_000738_000003422059_00116_27725_5588.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070620_000738_000003422059_00116_27725_6174.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070620_004504_000005022059_00117_27726_5714.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070620_013829_000004282059_00117_27726_6131.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070620_022539_000005002059_00118_27727_5880.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070620_025337_000001592059_00118_27727_5712.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070620_031728_000002022059_00118_27727_5852.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070620_031835_000001352059_00118_27727_5745.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070620_032550_000003852059_00118_27727_5901.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070620_035810_000002632059_00119_27728_6133.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070620_043130_000001522059_00119_27728_6264.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070620_045604_000000852059_00119_27728_6260.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070620_050404_000005872059_00119_27728_6141.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070620_054852_000000852059_00120_27729_6037.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070620_073628_000000852059_00121_27730_6117.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070620_080343_000002192059_00121_27730_6161.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070620_100152_000003422059_00122_27731_6198.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070620_100813_000005182059_00122_27731_6270.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070620_113829_000002632059_00123_27732_6258.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070620_153622_000002632059_00126_27735_6349.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070620_154225_000001412059_00126_27735_6357.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070620_154333_000000722059_00126_27735_6339.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070620_154919_000002012059_00126_27735_6299.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070620_165038_000001282059_00126_27735_6315.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070620_165038_000002012059_00126_27735_6355.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070620_165341_000000182059_00126_27735_6307.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070620_174105_000001472059_00127_27736_6341.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070620_182053_000003852059_00127_27736_6379.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070620_192036_000000852059_00128_27737_6381.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070620_192105_000002382059_00128_27737_6414.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070620_201023_000003482059_00128_27737_6501.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070620_210009_000002072059_00129_27738_6657.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070620_210408_000000852059_00129_27738_6530.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070620_214516_000001282059_00129_27738_6659.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070620_220428_000003422059_00129_27738_6661.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070620_224001_000003062059_00130_27739_7090.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070620_232239_000002632059_00130_27739_7086.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20070620_233645_000003002059_00130_27739_6682.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20070620_055756_000003662059_00120_27729_5793.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20070620_073029_000002012059_00121_27730_5803.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20070620_092129_000000672059_00122_27731_6223.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20070620_092129_000000672059_00122_27731_6381.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20070620_092129_000000672059_00122_27731_6559.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20070620_105641_000003912059_00123_27732_6190.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20070620_110644_000000852059_00123_27732_6058.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20070620_114750_000005802059_00123_27732_6227.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20070620_123318_000000852059_00124_27733_6221.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20070620_135546_000001472059_00125_27734_6370.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20070620_141445_000000922059_00125_27734_6368.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20070620_155214_000000912059_00126_27735_6479.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20070620_155428_000004842059_00126_27735_6509.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20070620_173405_000005122059_00127_27736_6690.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20070620_191517_000000862059_00128_27737_6800.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20070620_191731_000002312059_00128_27737_6815.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20070620_205346_000000852059_00129_27738_6938.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20070620_205538_000003062059_00129_27738_6943.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20070620_223149_000000862059_00130_27739_6969.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20070620_223648_000002452059_00130_27739_6971.N1					OK	OK	OK	OK


Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WVS_1PNPDE20070620_001319_000001642059_00116_27725_5359.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20070620_001504_000017542059_00116_27725_5496.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20070620_010712_000009552059_00117_27726_5503.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20070620_012930_000003752059_00117_27726_5508.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20070620_015236_000000592059_00117_27726_5516.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20070620_015236_000004202059_00117_27726_5619.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20070620_021224_000004942059_00118_27727_5626.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20070620_025748_000007342059_00118_27727_5629.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20070620_030933_000003002059_00118_27727_5754.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20070620_034019_000007042059_00118_27727_5761.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20070620_035615_000000592059_00119_27728_5772.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20070620_043839_000007342059_00119_27728_5788.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20070620_045024_000002852059_00119_27728_5910.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20070620_051350_000014842059_00119_27728_5945.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20070620_061703_000008392059_00120_27729_5925.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20070620_211131_000018892059_00129_27738_6423.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20070620_220220_000000752059_00129_27738_6545.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20070620_221010_000004342059_00129_27738_6553.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20070620_222854_000001202059_00130_27739_6550.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20070620_223314_000000602059_00130_27739_6558.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20070620_225008_000014092059_00130_27739_6568.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20070620_231833_000001952059_00130_27739_6579.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20070620_234142_000002242059_00130_27739_6593.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20070620_234427_000017392059_00130_27739_6685.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070620_063032_000004202059_00120_27729_5808.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070620_065424_000019942059_00120_27729_5816.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070620_081131_000004052059_00121_27730_5839.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070620_083500_000018292059_00121_27730_5844.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070620_090713_000001352059_00122_27731_5854.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070620_094110_000010492059_00122_27731_5967.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070620_101654_000017992059_00122_27731_5976.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070620_110502_000000602059_00123_27732_6081.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070620_110807_000017692059_00123_27732_6092.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070620_115730_000016942059_00123_27732_6166.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070620_124538_000010042059_00124_27733_6236.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070620_133648_000003752059_00124_27733_6239.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070620_134959_000002992059_00124_27733_6242.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070620_135810_000000592059_00125_27734_6272.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070620_143207_000004942059_00125_27734_6390.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070620_144813_000007502059_00125_27734_6395.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070620_151724_000010942059_00125_27734_6414.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070620_161655_000000742059_00126_27735_6568.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070620_162042_000012292059_00126_27735_6575.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070620_165800_000012892059_00126_27735_6589.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070620_175619_000014242059_00127_27736_6697.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070620_184238_000008092059_00127_27736_6711.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070620_193008_000019342059_00128_27737_6834.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20070620_201912_000004652059_00128_27737_6841.N1					OK	OK	OK	OK


Calibration pulses for GM1 SS3 H/H



### Calibration pulses for GM1 SS3 H/H




### Calibration pulses for GM1 SS3 H/H







### Calibration pulses for GM1 SS3 H/H




### Calibration pulses for WVS IS2 V/V




### Calibration pulses for WVS IS2 V/V





### Calibration pulses for WVS IS2 V/V





### Calibration pulses for WVS IS2 V/V





























20-Jun  
rows: \_ 4 \_ 8 \_ 12 \_ 16 \_ 20 \_ 24 \_ 28 \_ 32






rows: \_ 1 \_ 5 \_ 9 \_ 13 \_ 17 \_ 21 \_ 25 \_ 29




rows: \_ 2 \_ 6 \_ 10 \_ 14 \_ 18 \_ 22 \_ 26 \_ 30











Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_APM_1PNPDE20070620_025645_000000562059_00118_27727_5708.N1						IS2	H/H	59	27727	118	4.04
ASA_APM_1PNPDE20070620_040344_000000402059_00119_27728_6228.N1						IS2	V/H	59	27728	119	4.04
ASA_APM_1PNPDE20070620_074857_000000422059_00121_27730_6077.N1						IS2	V/H	59	27730	121	4.04
ASA_APM_1PNPDE20070620_075716_000002002059_00121_27730_6145.N1						IS2	H/V	59	27730	121	4.04
ASA_APM_1PNPDK20070620_140014_000000842059_00125_27734_6366.N1						IS2	H/H	59	27734	125	4.04
ASA_APM_1PNPDE20070620_172802_000000852059_00127_27736_6347.N1						IS5	H/V	59	27736	127	4.04
ASA_APM_1PNPDE20070620_190741_000000402059_00128_27737_6373.N1						IS2	V/H	59	27737	128	4.04
ASA_APM_1PNPDK20070620_190829_000000952059_00128_27737_6795.N1						IS5	H/V	59	27737	128	4.04
ASA_APM_1PNPDE20070620_192609_000000712059_00128_27737_6412.N1						IS6	H/H	59	27737	128	4.04
ASA_APM_1PNPDE20070620_203121_000000422059_00128_27737_6386.N1						IS2	H/H	59	27737	128	4.04
ASA_APM_1PNPDE20070620_222636_000000402059_00130_27739_6526.N1						IS6	H/H	59	27739	130	4.04

Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_GM1_1PNPDE20070620_000049_000003982059_00116_27725_5361.N1						SS1	H/H	59	27725	116	4.04
ASA_GM1_1PNPDE20070620_005338_000008092059_00117_27726_5498.N1						SS1	H/H	59	27726	117	4.04
ASA_GM1_1PNPDE20070620_012402_000003262059_00117_27726_5500.N1						SS1	H/H	59	27726	117	4.04
ASA_GM1_1PNPDE20070620_013638_000001022059_00117_27726_5505.N1						SS1	H/H	59	27726	117	4.04
ASA_GM1_1PNPDE20070620_014548_000004042059_00117_27726_5518.N1						SS1	H/H	59	27726	117	4.04
ASA_GM1_1PNPDE20070620_020030_000007122059_00117_27726_5623.N1						SS1	H/H	59	27726	117	4.04
ASA_GM1_1PNPDE20070620_022136_000002352059_00118_27727_5621.N1						SS1	H/H	59	27727	118	4.04
ASA_GM1_1PNPDE20070620_023413_000011532059_00118_27727_5700.N1						SS1	H/H	59	27727	118	4.04
ASA_GM1_1PNPDE20070620_032102_000002772059_00118_27727_5756.N1						SS1	H/H	59	27727	118	4.04
ASA_GM1_1PNPDE20070620_033430_000003442059_00118_27727_5758.N1						SS1	H/H	59	27727	118	4.04
ASA_GM1_1PNPDE20070620_035250_000002052059_00119_27728_5763.N1						SS1	H/H	59	27728	119	4.04
ASA_GM1_1PNPDE20070620_040452_000015882059_00119_27728_5850.N1						SS1	H/H	59	27728	119	4.04
ASA_GM1_1PNPDE20070620_043410_000001082059_00119_27728_5778.N1						SS1	H/H	59	27728	119	4.04
ASA_GM1_1PNPDE20070620_043655_000001022059_00119_27728_5785.N1						SS1	H/H	59	27728	119	4.04
ASA_GM1_1PNPDE20070620_045750_000003622059_00119_27728_5912.N1						SS1	H/H	59	27728	119	4.04
ASA_GM1_1PNPDE20070620_053924_000005552059_00120_27729_5914.N1						SS1	H/H	59	27729	120	4.04
ASA_GM1_1PNPDE20070620_055026_000004412059_00120_27729_5937.N1						SS1	H/H	59	27729	120	4.04
ASA_GM1_1PNPDE20070620_060419_000003502059_00120_27729_5935.N1						SS1	H/H	59	27729	120	4.04
ASA_GM1_1PNPDE20070620_061439_000001382059_00120_27729_5927.N1						SS1	H/H	59	27729	120	4.04
ASA_GM1_1PNPDK20070620_063826_000009242059_00120_27729_5805.N1						SS1	H/H	59	27729	120	4.04
ASA_GM1_1PNPDK20070620_073943_000005552059_00121_27730_5830.N1						SS1	H/H	59	27730	121	4.04
ASA_GM1_1PNPDK20070620_075602_000000722059_00121_27730_5836.N1						SS1	H/H	59	27730	121	4.04
ASA_GM1_1PNPDK20070620_080103_000001502059_00121_27730_5834.N1						SS1	H/H	59	27730	121	4.04
ASA_GM1_1PNPDK20070620_080735_000002352059_00121_27730_5832.N1						SS1	H/H	59	27730	121	4.04
ASA_GM1_1PNPDK20070620_082018_000008822059_00121_27730_5841.N1						SS1	H/H	59	27730	121	4.04
ASA_GM1_1PNPDK20070620_091012_000006642059_00122_27731_5868.N1						SS1	H/H	59	27731	122	4.04
ASA_GM1_1PNPDK20070620_092304_000001812059_00122_27731_5962.N1						SS1	H/H	59	27731	122	4.04
ASA_GM1_1PNPDK20070620_093216_000005312059_00122_27731_5964.N1						SS1	H/H	59	27731	122	4.04
ASA_GM1_1PNPDK20070620_095938_000001262059_00122_27731_5969.N1						SS1	H/H	59	27731	122	4.04
ASA_GM1_1PNPDK20070620_104902_000001502059_00123_27732_5971.N1						SS1	H/H	59	27732	123	4.04
ASA_GM1_1PNPDK20070620_105315_000001932059_00123_27732_5973.N1						SS1	H/H	59	27732	123	4.04
ASA_GM1_1PNPDK20070620_110320_000001022059_00123_27732_6083.N1						SS1	H/H	59	27732	123	4.04
ASA_GM1_1PNPDK20070620_114303_000002772059_00123_27732_6094.N1						SS1	H/H	59	27732	123	4.04
ASA_GM1_1PNPDK20070620_122627_000003982059_00124_27733_6096.N1						SS1	H/H	59	27733	124	4.04
ASA_GM1_1PNPDK20070620_123452_000003562059_00124_27733_6158.N1						SS1	H/H	59	27733	124	4.04
ASA_GM1_1PNPDK20070620_124007_000003262059_00124_27733_6229.N1						SS1	H/H	59	27733	124	4.04
ASA_GM1_1PNPDK20070620_130438_000005012059_00124_27733_6231.N1						SS1	H/H	59	27733	124	4.04
ASA_GM1_1PNPDK20070620_131313_000003202059_00124_27733_6233.N1						SS1	H/H	59	27733	124	4.04
ASA_GM1_1PNPDK20070620_131923_000010392059_00124_27733_6346.N1						SS1	H/H	59	27733	124	4.04
ASA_GM1_1PNPDK20070620_134353_000003622059_00124_27733_6250.N1						SS1	H/H	59	27733	124	4.04
ASA_GM1_1PNPDK20070620_140205_000001022059_00125_27734_6248.N1						SS1	H/H	59	27734	125	4.04
ASA_GM1_1PNPDK20070620_140524_000005492059_00125_27734_6274.N1						SS1	H/H	59	27734	125	4.04
ASA_GM1_1PNPDK20070620_141627_000001572059_00125_27734_6269.N1						SS1	H/H	59	27734	125	4.04
ASA_GM1_1PNPDK20070620_141823_000004472059_00125_27734_6385.N1						SS1	H/H	59	27734	125	4.04
ASA_GM1_1PNPDK20070620_142933_000001502059_00125_27734_6387.N1						SS1	H/H	59	27734	125	4.04
ASA_GM1_1PNPDK20070620_144107_000004222059_00125_27734_6392.N1						SS1	H/H	59	27734	125	4.04
ASA_GM1_1PNPDK20070620_150125_000009242059_00125_27734_6397.N1						SS1	H/H	59	27734	125	4.04
ASA_GM1_1PNPDK20070620_154057_000000782059_00126_27735_6410.N1						SS1	H/H	59	27735	126	4.04
ASA_GM1_1PNPDK20070620_160244_000001992059_00126_27735_6563.N1						SS1	H/H	59	27735	126	4.04
ASA_GM1_1PNPDK20070620_160948_000004222059_00126_27735_6565.N1						SS1	H/H	59	27735	126	4.04
ASA_GM1_1PNPDK20070620_161858_000001022059_00126_27735_6570.N1						SS1	H/H	59	27735	126	4.04
ASA_GM1_1PNPDK20070620_164201_000005072059_00126_27735_6572.N1						SS1	H/H	59	27735	126	4.04
ASA_GM1_1PNPDK20070620_165411_000002232059_00126_27735_6577.N1						SS1	H/H	59	27735	126	4.04
ASA_GM1_1PNPDK20070620_172016_000004652059_00127_27736_6579.N1						SS1	H/H	59	27736	127	4.04
ASA_GM1_1PNPDK20070620_172954_000002412059_00127_27736_6586.N1						SS1	H/H	59	27736	127	4.04
ASA_GM1_1PNPDK20070620_174447_000002412059_00127_27736_6692.N1						SS1	H/H	59	27736	127	4.04
ASA_GM1_1PNPDK20070620_175014_000003082059_00127_27736_6694.N1						SS1	H/H	59	27736	127	4.04
ASA_GM1_1PNPDK20070620_182727_000006642059_00127_27736_6699.N1						SS1	H/H	59	27736	127	4.04
ASA_GM1_1PNPDK20070620_185700_000006402059_00128_27737_6701.N1						SS1	H/H	59	27737	128	4.04
ASA_GM1_1PNPDK20070620_191030_000001632059_00128_27737_6708.N1						SS1	H/H	59	27737	128	4.04
ASA_GM1_1PNPDK20070620_191212_000001752059_00128_27737_6823.N1						SS1	H/H	59	27737	128	4.04
ASA_GM1_1PNPDK20070620_192747_000001382059_00128_27737_6825.N1						SS1	H/H	59	27737	128	4.04
ASA_GM1_1PNPDK20070620_200313_000004162059_00128_27737_6827.N1						SS1	H/H	59	27737	128	4.04
ASA_GM1_1PNPDK20070620_201623_000001692059_00128_27737_6829.N1						SS1	H/H	59	27737	128	4.04
ASA_GM1_1PNPDK20070620_202743_000002172059_00128_27737_6831.N1						SS1	H/H	59	27737	128	4.04
ASA_GM1_1PNPDK20070620_203229_000007182059_00128_27737_6838.N1						SS1	H/H	59	27737	128	4.04
ASA_GM1_1PNPDK20070620_204950_000000902059_00129_27738_6836.N1						SS1	H/H	59	27738	129	4.04

ASA_GM1_1PNPDK20070620_205215_000000782059_00129_27738_6850.N1	SS1	H/H	59	27738	129	4.04
ASA_GM1_1PNPDE20070620_210542_000002592059_00129_27738_6420.N1	SS1	H/H	59	27738	129	4.04
ASA_GM1_1PNPDE20070620_214349_000000782059_00129_27738_6418.N1	SS1	H/H	59	27738	129	4.04
ASA_GM1_1PNPDE20070620_214737_000007432059_00129_27738_6433.N1	SS1	H/H	59	27738	129	4.04
ASA_GM1_1PNPDE20070620_221814_000005012059_00130_27739_6547.N1	SS1	H/H	59	27739	130	4.04
ASA_GM1_1PNPDE20070620_222743_000000662059_00130_27739_6555.N1	SS1	H/H	59	27739	130	4.04
ASA_GM1_1PNPDE20070620_224529_000002772059_00130_27739_6565.N1	SS1	H/H	59	27739	130	4.04
ASA_GM1_1PNPDE20070620_231422_000001322059_00130_27739_6563.N1	SS1	H/H	59	27739	130	4.04
ASA_GM1_1PNPDE20070620_231649_000001022059_00130_27739_6576.N1	SS1	H/H	59	27739	130	4.04
ASA_GM1_1PNPDE20070620_232713_000005612059_00130_27739_6595.N1	SS1	H/H	59	27739	130	4.04

Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_IMM_1PNPDE20070620_043557_000000402059_00119_27728_6230.N1						IS2	V/V	59	27728	119	4.04
ASA_IMM_1PNPDE20070620_061011_000002512059_00120_27729_6020.N1						IS2	V/V	59	27729	120	4.04
ASA_IMM_1PNPDE20070620_104726_000000792059_00123_27732_6262.N1						IS2	V/V	59	27732	123	4.04
ASA_IMM_1PNPDK20070620_131831_000000352059_00124_27733_6340.N1						IS5	H/H	59	27733	124	4.04
ASA_IMM_1PNPDK20070620_140347_000000792059_00125_27734_6364.N1						IS6	V/V	59	27734	125	4.04
ASA_IMM_1PNPDE20070620_154455_000001912059_00126_27735_6297.N1						IS2	V/V	59	27735	126	4.04
ASA_IMM_1PNPDE20070620_174354_000000362059_00127_27736_6331.N1						IS2	H/H	59	27736	127	4.04
ASA_IMM_1PNPDE20070620_174851_000000642059_00127_27736_6353.N1						IS4	V/V	59	27736	127	4.04
ASA_IMM_1PNPDE20070620_175523_000000352059_00127_27736_6351.N1						IS7	H/H	59	27736	127	4.04
ASA_IMM_1PNPDE20070620_204427_000000612059_00129_27738_6416.N1						IS6	H/H	59	27738	129	4.04
ASA_IMM_1PNPDK20070620_205122_000000352059_00129_27738_6848.N1						IS7	H/H	59	27738	129	4.04
ASA_IMM_1PNPDE20070620_211002_000000832059_00129_27738_6528.N1						IS2	V/V	59	27738	129	4.04
ASA_IMM_1PNPDK20070620_223448_000000662059_00130_27739_6959.N1						IS2	H/H	59	27739	130	4.04


Filename	Pol	Timestamp	count(Module)
ASA_MS__0PNPDK20070620_081854_000000162059_00121_27730_0315.N1	H	2007-06-20 08:18:54	320





Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WSM_1PNPDE20070619_235816_000001282059_00116_27725_5444.N1						SS1	H/H	59	27725	116	4.04
ASA_WSM_1PNPDE20070620_000738_000003422059_00116_27725_5588.N1						SS1	H/H	59	27725	116	4.04
ASA_WSM_1PNPDE20070620_000738_000003422059_00116_27725_6174.N1						SS1	H/H	59	27725	116	4.04
ASA_WSM_1PNPDE20070620_004504_000005022059_00117_27726_5714.N1						SS1	H/H	59	27726	117	4.04
ASA_WSM_1PNPDE20070620_013829_000004282059_00117_27726_6131.N1						SS1	H/H	59	27726	117	4.04
ASA_WSM_1PNPDE20070620_022539_000005002059_00118_27727_5880.N1						SS1	H/H	59	27727	118	4.04
ASA_WSM_1PNPDE20070620_025337_000001592059_00118_27727_5712.N1						SS1	H/H	59	27727	118	4.04
ASA_WSM_1PNPDE20070620_031728_000002022059_00118_27727_5852.N1						SS1	H/H	59	27727	118	4.04
ASA_WSM_1PNPDE20070620_031835_000001352059_00118_27727_5745.N1						SS1	H/H	59	27727	118	4.04
ASA_WSM_1PNPDE20070620_032550_000003852059_00118_27727_5901.N1						SS1	H/H	59	27727	118	4.04
ASA_WSM_1PNPDE20070620_035810_000002632059_00119_27728_6133.N1						SS1	H/H	59	27728	119	4.04
ASA_WSM_1PNPDE20070620_043130_000001522059_00119_27728_6264.N1						SS1	H/H	59	27728	119	4.04
ASA_WSM_1PNPDE20070620_045604_000000852059_00119_27728_6260.N1						SS1	H/H	59	27728	119	4.04
ASA_WSM_1PNPDE20070620_050404_000005872059_00119_27728_6141.N1						SS1	H/H	59	27728	119	4.04
ASA_WSM_1PNPDE20070620_054852_000000852059_00120_27729_6037.N1						SS1	H/H	59	27729	120	4.04
ASA_WSM_1PNPDK20070620_055756_000003662059_00120_27729_5793.N1						SS1	H/H	59	27729	120	4.04
ASA_WSM_1PNPDK20070620_073029_000002012059_00121_27730_5803.N1						SS1	H/H	59	27730	121	4.04
ASA_WSM_1PNPDE20070620_073628_000000852059_00121_27730_6117.N1						SS1	H/H	59	27730	121	4.04
ASA_WSM_1PNPDE20070620_080343_000002192059_00121_27730_6161.N1						SS1	H/H	59	27730	121	4.04
ASA_WSM_1PNPDK20070620_092129_000000672059_00122_27731_6223.N1						SS1	V/V	59	27731	122	4.04
ASA_WSM_1PNPDK20070620_092129_000000672059_00122_27731_6381.N1						SS1	V/V	59	27731	122	4.04
ASA_WSM_1PNPDK20070620_092129_000000672059_00122_27731_6559.N1						SS1	V/V	59	27731	122	4.04
ASA_WSM_1PNPDE20070620_100152_000003422059_00122_27731_6198.N1						SS1	H/H	59	27731	122	4.04
ASA_WSM_1PNPDE20070620_100813_000005182059_00122_27731_6270.N1						SS1	H/H	59	27731	122	4.04
ASA_WSM_1PNPDK20070620_105641_000003912059_00123_27732_6190.N1						SS1	H/H	59	27732	123	4.04
ASA_WSM_1PNPDK20070620_110644_000000852059_00123_27732_6058.N1						SS1	V/V	59	27732	123	4.04
ASA_WSM_1PNPDE20070620_113829_000002632059_00123_27732_6258.N1						SS1	H/H	59	27732	123	4.04
ASA_WSM_1PNPDK20070620_114750_000005802059_00123_27732_6227.N1						SS1	H/H	59	27732	123	4.04
ASA_WSM_1PNPDK20070620_123318_000000852059_00124_27733_6221.N1						SS1	H/H	59	27733	124	4.04
ASA_WSM_1PNPDK20070620_135546_000001472059_00125_27734_6370.N1						SS1	V/V	59	27734	125	4.04
ASA_WSM_1PNPDK20070620_141445_000000922059_00125_27734_6368.N1						SS1	H/H	59	27734	125	4.04
ASA_WSM_1PNPDE20070620_153622_000002632059_00126_27735_6349.N1						SS1	H/H	59	27735	126	4.04
ASA_WSM_1PNPDE20070620_154225_000001412059_00126_27735_6357.N1						SS1	V/V	59	27735	126	4.04
ASA_WSM_1PNPDE20070620_154333_000000722059_00126_27735_6339.N1						SS1	V/V	59	27735	126	4.04
ASA_WSM_1PNPDE20070620_154919_000002012059_00126_27735_6299.N1						SS1	H/H	59	27735	126	4.04
ASA_WSM_1PNPDK20070620_155214_000000912059_00126_27735_6479.N1						SS1	H/H	59	27735	126	4.04
ASA_WSM_1PNPDK20070620_155428_000004842059_00126_27735_6509.N1						SS1	H/H	59	27735	126	4.04
ASA_WSM_1PNPDE20070620_165038_000001282059_00126_27735_6315.N1						SS1	H/H	59	27735	126	4.04
ASA_WSM_1PNPDE20070620_165038_000002012059_00126_27735_6355.N1						SS1	H/H	59	27735	126	4.04
ASA_WSM_1PNPDE20070620_165341_000000182059_00126_27735_6307.N1						SS1	H/H	59	27735	126	4.04
ASA_WSM_1PNPDK20070620_173405_000005122059_00127_27736_6690.N1						SS1	H/H	59	27736	127	4.04
ASA_WSM_1PNPDE20070620_174105_000001472059_00127_27736_6341.N1						SS1	H/H	59	27736	127	4.04
ASA_WSM_1PNPDE20070620_182053_000003852059_00127_27736_6379.N1						SS1	H/H	59	27736	127	4.04
ASA_WSM_1PNPDK20070620_191517_000000862059_00128_27737_6800.N1						SS1	V/V	59	27737	128	4.04
ASA_WSM_1PNPDK20070620_191731_000002312059_00128_27737_6815.N1						SS1	H/H	59	27737	128	4.04
ASA_WSM_1PNPDE20070620_192036_000000852059_00128_27737_6381.N1						SS1	H/H	59	27737	128	4.04
ASA_WSM_1PNPDE20070620_192105_000002382059_00128_27737_6414.N1						SS1	H/H	59	27737	128	4.04
ASA_WSM_1PNPDE20070620_201023_000003482059_00128_27737_6501.N1						SS1	H/H	59	27737	128	4.04
ASA_WSM_1PNPDK20070620_205346_000000852059_00129_27738_6938.N1						SS1	V/V	59	27738	129	4.04
ASA_WSM_1PNPDK20070620_205538_000003062059_00129_27738_6943.N1						SS1	H/H	59	27738	129	4.04
ASA_WSM_1PNPDE20070620_210009_000002072059_00129_27738_6657.N1						SS1	H/H	59	27738	129	4.04
ASA_WSM_1PNPDE20070620_210408_000000852059_00129_27738_6530.N1						SS1	H/H	59	27738	129	4.04
ASA_WSM_1PNPDE20070620_214516_000001282059_00129_27738_6659.N1						SS1	H/H	59	27738	129	4.04
ASA_WSM_1PNPDE20070620_220428_000003422059_00129_27738_6661.N1						SS1	V/V	59	27738	129	4.04
ASA_WSM_1PNPDK20070620_223149_000000862059_00130_27739_6969.N1						SS1	V/V	59	27739	130	4.04
ASA_WSM_1PNPDK20070620_223648_000002452059_00130_27739_6971.N1						SS1	H/H	59	27739	130	4.04
ASA_WSM_1PNPDE20070620_224001_000003062059_00130_27739_7090.N1						SS1	H/H	59	27739	130	4.04
ASA_WSM_1PNPDE20070620_232239_000002632059_00130_27739_7086.N1						SS1	H/H	59	27739	130	4.04
ASA_WSM_1PNPDE20070620_233645_000003002059_00130_27739_6682.N1						SS1	H/H	59	27739	130	4.04


Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WVS_1PNPDE20070620_001319_000001642059_00116_27725_5359.N1						IS2	V/V	59	27725	116	4.04
ASA_WVS_1PNPDE20070620_001504_000017542059_00116_27725_5496.N1						IS2	V/V	59	27725	116	4.04
ASA_WVS_1PNPDE20070620_001319_000001642059_00116_27725_5359.N1						IS1	V/V	59	27725	116	4.04
ASA_WVS_1PNPDE20070620_010712_000009552059_00117_27726_5503.N1						IS2	V/V	59	27726	117	4.04
ASA_WVS_1PNPDE20070620_012930_000003752059_00117_27726_5508.N1						IS2	V/V	59	27726	117	4.04
ASA_WVS_1PNPDE20070620_015236_000000592059_00117_27726_5516.N1						IS2	V/V	59	27726	117	4.04
ASA_WVS_1PNPDE20070620_015236_000004202059_00117_27726_5619.N1						IS2	V/V	59	27726	117	4.04
ASA_WVS_1PNPDE20070620_015236_000000592059_00117_27726_5516.N1						IS1	V/V	59	27726	117	4.04
ASA_WVS_1PNPDE20070620_021224_000004942059_00118_27727_5626.N1						IS2	V/V	59	27727	118	4.04
ASA_WVS_1PNPDE20070620_025748_000007342059_00118_27727_5629.N1						IS2	V/V	59	27727	118	4.04
ASA_WVS_1PNPDE20070620_030933_000003002059_00118_27727_5754.N1						IS2	V/V	59	27727	118	4.04
ASA_WVS_1PNPDE20070620_034019_000007042059_00118_27727_5761.N1						IS2	V/V	59	27727	118	4.04
ASA_WVS_1PNPDE20070620_035615_000000592059_00119_27728_5772.N1						IS2	V/V	59	27728	119	4.04
ASA_WVS_1PNPDE20070620_043839_000007342059_00119_27728_5788.N1						IS2	V/V	59	27728	119	4.04
ASA_WVS_1PNPDE20070620_045024_000002852059_00119_27728_5910.N1						IS2	V/V	59	27728	119	4.04
ASA_WVS_1PNPDE20070620_043839_000007342059_00119_27728_5788.N1						IS1	V/V	59	27728	119	4.04
ASA_WVS_1PNPDE20070620_051350_000014842059_00119_27728_5945.N1						IS2	V/V	59	27728	119	4.04
ASA_WVS_1PNPDE20070620_061703_000008392059_00120_27729_5925.N1						IS2	V/V	59	27729	120	4.04
ASA_WVS_1PNPDK20070620_063032_000004202059_00120_27729_5808.N1						IS2	V/V	59	27729	120	4.04
ASA_WVS_1PNPDE20070620_061703_000008392059_00120_27729_5925.N1						IS1	V/V	59	27729	120	4.04
ASA_WVS_1PNPDK20070620_065424_000019942059_00120_27729_5816.N1						IS2	V/V	59	27729	120	4.04
ASA_WVS_1PNPDK20070620_081131_000004052059_00121_27730_5839.N1						IS2	V/V	59	27730	121	4.04
ASA_WVS_1PNPDK20070620_083500_000018292059_00121_27730_5844.N1						IS2	V/V	59	27730	121	4.04
ASA_WVS_1PNPDK20070620_090713_000001352059_00122_27731_5854.N1						IS2	V/V	59	27731	122	4.04
ASA_WVS_1PNPDK20070620_094110_000010492059_00122_27731_5967.N1						IS2	V/V	59	27731	122	4.04
ASA_WVS_1PNPDK20070620_101654_000017992059_00122_27731_5976.N1						IS2	V/V	59	27731	122	4.04
ASA_WVS_1PNPDK20070620_110502_000000602059_00123_27732_6081.N1						IS2	V/V	59	27732	123	4.04
ASA_WVS_1PNPDK20070620_110807_000017692059_00123_27732_6092.N1						IS2	V/V	59	27732	123	4.04
ASA_WVS_1PNPDK20070620_115730_000016942059_00123_27732_6166.N1						IS2	V/V	59	27732	123	4.04
ASA_WVS_1PNPDK20070620_124538_000010042059_00124_27733_6236.N1						IS2	V/V	59	27733	124	4.04
ASA_WVS_1PNPDK20070620_133648_000003752059_00124_27733_6239.N1						IS2	V/V	59	27733	124	4.04
ASA_WVS_1PNPDK20070620_134959_000002992059_00124_27733_6242.N1						IS2	V/V	59	27733	124	4.04
ASA_WVS_1PNPDK20070620_135810_000000592059_00125_27734_6272.N1						IS2	V/V	59	27734	125	4.04
ASA_WVS_1PNPDK20070620_143207_000004942059_00125_27734_6390.N1						IS2	V/V	59	27734	125	4.04
ASA_WVS_1PNPDK20070620_144813_000007502059_00125_27734_6395.N1						IS2	V/V	59	27734	125	4.04
ASA_WVS_1PNPDK20070620_151724_000010942059_00125_27734_6414.N1						IS2	V/V	59	27734	125	4.04
ASA_WVS_1PNPDK20070620_161655_000000742059_00126_27735_6568.N1						IS2	V/V	59	27735	126	4.04
ASA_WVS_1PNPDK20070620_162042_000012292059_00126_27735_6575.N1						IS2	V/V	59	27735	126	4.04
ASA_WVS_1PNPDK20070620_165800_000012892059_00126_27735_6589.N1						IS2	V/V	59	27735	126	4.04
ASA_WVS_1PNPDK20070620_175619_000014242059_00127_27736_6697.N1						IS2	V/V	59	27736	127	4.04
ASA_WVS_1PNPDK20070620_184238_000008092059_00127_27736_6711.N1						IS2	V/V	59	27736	127	4.04
ASA_WVS_1PNPDK20070620_193008_000019342059_00128_27737_6834.N1						IS2	V/V	59	27737	128	4.04
ASA_WVS_1PNPDK20070620_201912_000004652059_00128_27737_6841.N1						IS2	V/V	59	27737	128	4.04
ASA_WVS_1PNPDE20070620_211131_000018892059_00129_27738_6423.N1						IS2	V/V	59	27738	129	4.04
ASA_WVS_1PNPDE20070620_220220_000000752059_00129_27738_6545.N1						IS2	V/V	59	27738	129	4.04
ASA_WVS_1PNPDE20070620_221010_000004342059_00129_27738_6553.N1						IS2	V/V	59	27738	129	4.04
ASA_WVS_1PNPDE20070620_222854_000001202059_00130_27739_6550.N1						IS2	V/V	59	27739	130	4.04
ASA_WVS_1PNPDE20070620_223314_000000602059_00130_27739_6558.N1						IS2	V/V	59	27739	130	4.04
ASA_WVS_1PNPDE20070620_225008_000014092059_00130_27739_6568.N1						IS2	V/V	59	27739	130	4.04
ASA_WVS_1PNPDE20070620_231833_000001952059_00130_27739_6579.N1						IS2	V/V	59	27739	130	4.04
ASA_WVS_1PNPDE20070620_234142_000002242059_00130_27739_6593.N1						IS2	V/V	59	27739	130	4.04
ASA_WVS_1PNPDE20070620_234427_000017392059_00130_27739_6685.N1						IS2	V/V	59	27739	130	4.04
ASA_WVS_1PNPDE20070620_234142_000002242059_00130_27739_6593.N1						IS1	V/V	59	27739	130	4.04






































































20-Jun



20-Jun



20-Jun

