



# ASAR Daily Report



Analysis from 15-NOV-2008 00:00:00 to 15-NOV-2008 23:59:59. Page generated on 16-NOV-2008 08:04:51.  
View log file: ASAR\_Daily\_Report\_20081116\_0730.log. For any anomalies please contact [mtranfaglia@serco.it](mailto:mtranfaglia@serco.it), [gscarpino@serco.it](mailto:gscarpino@serco.it), [Emma.Griffiths@vega.co.uk](mailto:Emma.Griffiths@vega.co.uk).

This report is automatically generated every day, every 2 hours. No comments are provided on the results.

## SUMMARY

### 1. DATA SUMMARY

- 1.1 Summary tables
- 1.2 Lists of products used

### 2. AUXILIARY FILES ANALYSIS

- 2.1 IECF operational ADFs list
- 2.2 Products with wrong ADFs

### 3. MODULE STEPPING PRODUCTS ANALYSIS

- 3.1 V/V polarisation
- 3.2 H/H polarisation

### 4. CALIBRATION PULSES ANALYSIS

- 4.1 Analysis for WVS IS2 V/V
  - 4.1.1 Temporal Evolution Analysis for WVS IS2 V/V
  - 4.1.2 All Rows Analysis for WVS IS2 V/V
- 4.2 Analysis for GM1 SS3 H/H
  - 4.2.1 Temporal Evolution Analysis for GM1 SS3 H/H
  - 4.2.2 All Rows Analysis for GM1 SS3 H/H

### 5. DOPPLER ANALYSIS

- 5.1 Analysis for WVS IS2 V/V
  - 5.1.1 Doppler MAP Analysis for WVS IS2 V/V
  - 5.1.2 Doppler ANX Analysis for WVS IS2 V/V
- 5.2 Analysis for GM1 SS1 H/H
  - 5.2.1 Doppler MAP Analysis for GM1 SS1 H/H
  - 5.2.2 Doppler ANX Analysis for GM1 SS1 H/H
- 5.3 Doppler JUMPS Analysis for WSM

### 6. CHIRP ANALYSIS

- 6.1 Analysis for WSM SS1 H/H
  - 6.1.1 ScaleFactor
- 6.2 Analysis for WSM SS1 V/V
  - 6.2.1 ScaleFactor

### 7. RAW DATA ANALYSIS

- 7.1 Analysis for WVS
- 7.2 Analysis for IMM

### 8. TELEMETRY ANALYSIS

- 8.1 Number of Missing Lines
- 8.2 Number of Gaps

---

## 1 - DATA SUMMARY

### 1.1 - Summary tables

[ [BACK TO MENU](#) ]

WVS				GM1				APM				IMM				WSM				MS			
Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Time	Pol	Modules
PDE	IS1	V/V	1	PDE	WS	H/H	20	PDE	IS1	H/H	1	PDE	IS1	V/V	1	PDE	WS	H/H	20	PDE	2008-11-15 07:08:26	H	320
PDE	IS2	V/V	14	PDK	WS	H/H	44	PDK	IS3	H/H	1	PDE	IS2	H/H	13	PDE	WS	V/V	11	PDE	2008-11-15 20:48:54	V	320
PDK	IS2	V/V	20									PDE	IS2	V/V	3								
												PDE	IS5	H/H	1								
												PDE	IS6	V/V	1								
												PDE	IS7	H/H	1								
												PDE	IS7	V/V	1								
												PDK	IS2	H/H	3								
												PDK	IS2	V/V	2								
												PDK	IS3	H/H	1								
												PDK	IS4	H/H	1								
												PDK	IS7	V/V	1								

## 1.2 - Lists of products used

[ [BACK TO MENU](#) ]

[[TXT](#)] [[XLS](#)] [List\\_WVS\\_products\\_used](#)  
 [[TXT](#)] [[XLS](#)] [List\\_GM1\\_products\\_used](#)  
 [[TXT](#)] [[XLS](#)] [List\\_APM\\_products\\_used](#)  
 [[TXT](#)] [[XLS](#)] [List\\_IMM\\_products\\_used](#)  
 [[TXT](#)] [[XLS](#)] [List\\_WSM\\_products\\_used](#)  
 [[TXT](#)] [[XLS](#)] [List\\_MS\\_products\\_used](#)

## 2 - AUXILIARY FILES ANALYSIS

### 2.1 - IECF operational ADFs list

[ [BACK TO MENU](#) ]

ADFs disseminated for ASAR
ASA_CON_AXVIEC20080710_132557_20070204_165113_20081231_000000
ASA_INS_AXVIEC20071218_083603_20070307_060000_20081231_000000
ASA_XCH_AXVIEC20051219_162547_20020301_000000_20081231_000000
ASA_XCA_AXVIEC20080710_133546_20070204_165113_20081231_000000

### 2.2 - Products with wrong ADFs

[ [BACK TO MENU](#) ]

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
WVS	0	0	0	0
GM1	0	0	0	0
APM	0	0	0	0
IMM	0	0	0	0
WSM	0	0	0	0

### 3 - MODULE STEPPING PRODUCTS ANALYSIS






### 3.2 - H/H polarisation

[ [BACK TO MENU](#) ]

SECOND FIXED REFERENCE	PREVIOUS PRODUCT REFERENCE
After antenna maintenance (2005-09-22/23)	Previous product in the same polarisation

Reference: 2005-09-22 06:26:51 H RxGain  
 Test : 2008-11-15 07:08:26 H



Reference: 2008-11-14 14:38:07 H RxGain  
 Test : 2008-11-15 07:08:26 H



Reference: 2005-09-22 06:26:51 H RxPhase  
 Test : 2008-11-15 07:08:26 H



Reference: 2008-11-14 14:38:07 H RxPhase  
 Test : 2008-11-15 07:08:26 H





## 4 - CALIBRATION PULSES ANALYSIS

### 4.1 - Analysis for WVS IS2 V/V


#### 4.1.1 - Temporal Evolution Analysis for WVS IS2 V/V

[ BACK TO MENU ]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Calibration pulses for WVS IS2 V/V




Transmit power (P1 - P1a) for WVS IS2 V/V



#### 4.1.2 - All Rows Analysis for WVS IS2 V/V

[ [BACK TO MENU](#) ]





## 4.2 - Analysis for GM1 SS3 H/H

### 4.2.1 - Temporal Evolution Analysis for GM1 SS3 H/H


[ BACK TO MENU ]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]



Calibration pulses for GM1 SS3 H/H




Transmit power (P1 - P1a) for GM1 SS3 H/H



#### 4.2.2 - All Rows Analysis for GM1 SS3 H/H

[ [BACK TO MENU](#) ]






## 5 - DOPPLER ANALYSIS

### 5.1 - Analysis for WVS IS2 V/V

#### 5.1.1 - Doppler MAP Analysis for WVS IS2 V/V

[ [BACK TO MENU](#) ]






### 5.1.2 - Doppler ANX Analysis for WVS IS2 V/V

[ [BACK TO MENU](#) ]






## 5.2 - Analysis for GM1 SS1 H/H

### 5.2.1 - Doppler MAP Analysis for GM1 SS1 H/H

[ BACK TO MENU ]






### 5.2.2 - Doppler ANX Analysis for GM1 SS1 H/H


[ [BACK TO MENU](#) ]






### 5.3 - Doppler JUMPS Analysis for WSM

[ [BACK TO MENU](#) ]







## 6 - CHIRP ANALYSIS

### 6.1 - Analysis for WSM SS1 H/H

#### 6.1.1 - ScaleFactor

[ [BACK TO MENU](#) ]







## 6.2 - Analysis for WSM SS1 V/V

### 6.2.1 - ScaleFactor

[ [BACK TO MENU](#) ]






## 7 - RAW DATA ANALYSIS

### 7.1 - Analysis for WVS

[ [BACK TO MENU](#) ]

--	--	--






Channel	Statistics	DSS-B
MEAN I	mean	0.000534840
	stdev	1.82572e-07
MEAN Q	mean	0.000566716
	stdev	2.14516e-07
Channel	Statistics	DSS-B
STDEV I	mean	0.134723
	stdev	0.000879412
STDEV Q	mean	0.135069
	stdev	0.000892246

## 7.2 - Analysis for IMM

[ [BACK TO MENU](#) ]







## 8 - TELEMETRY ANALYSIS

### 8.1 - Number of Missing lines


[ BACK TO MENU ]





## 8.2 - Number of Gaps

[\[ BACK TO MENU \]](#)



#####  
ASAR DAILY REPORT for 081115  
#####

MODE: DAILY  
ANALYSIS: ALL  
DATE: YESTERDAY

Analysis will be performed from 2008-11-15 00:00:00 to 2008-11-15 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/081115/

DATA SUMMARY

#####  
Summary will be performed from 2008-11-15 00:00:00 to 2008-11-15 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/081115/DATA\_SUMMARY

Creating directory ./RESULTS/DAILY/081115/DATA\_SUMMARY...  
Writing file ./RESULTS/DAILY/081115/DATA\_SUMMARY/Data\_summary.html...

\*\*\*\*\*  
Getting WVS products list from 2008-11-15 00:00:00 to 2008-11-15 23:59:59...  
Writing file ./RESULTS/DAILY/081115/DATA\_SUMMARY/List\_WVS\_products\_used.xls...  
Writing file ./RESULTS/DAILY/081115/DATA\_SUMMARY/List\_WVS\_products\_used.txt...

\*\*\*\*\*  
Getting GM1 products list from 2008-11-15 00:00:00 to 2008-11-15 23:59:59...  
Writing file ./RESULTS/DAILY/081115/DATA\_SUMMARY/List\_GM1\_products\_used.xls...  
Writing file ./RESULTS/DAILY/081115/DATA\_SUMMARY/List\_GM1\_products\_used.txt...

\*\*\*\*\*  
Getting APM products list from 2008-11-15 00:00:00 to 2008-11-15 23:59:59...  
Writing file ./RESULTS/DAILY/081115/DATA\_SUMMARY/List\_APM\_products\_used.xls...  
Writing file ./RESULTS/DAILY/081115/DATA\_SUMMARY/List\_APM\_products\_used.txt...

\*\*\*\*\*  
Getting IMM products list from 2008-11-15 00:00:00 to 2008-11-15 23:59:59...  
Writing file ./RESULTS/DAILY/081115/DATA\_SUMMARY/List\_IMM\_products\_used.xls...  
Writing file ./RESULTS/DAILY/081115/DATA\_SUMMARY/List\_IMM\_products\_used.txt...

\*\*\*\*\*  
Getting WSM products list from 2008-11-15 00:00:00 to 2008-11-15 23:59:59...  
Writing file ./RESULTS/DAILY/081115/DATA\_SUMMARY/List\_WSM\_products\_used.xls...  
Writing file ./RESULTS/DAILY/081115/DATA\_SUMMARY/List\_WSM\_products\_used.txt...

\*\*\*\*\*  
Getting MS products list from 2008-11-15 00:00:00 to 2008-11-15 23:59:59...  
Writing file ./RESULTS/DAILY/081115/DATA\_SUMMARY/List\_MS\_products\_used.xls...  
Writing file ./RESULTS/DAILY/081115/DATA\_SUMMARY/List\_MS\_products\_used.txt...

DATA SUMMARY completed  
#####

AUXILIARY FILES ANALYSIS

#####  
Analysis will be performed from 2008-11-15 00:00:00 to 2008-11-15 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/081115/AUXILIARY

Creating directory ./RESULTS/DAILY/081115/AUXILIARY...

\*\*\*\*\*  
Looking for the IECF operational ADFs list...



Found list 20081115\_030001\_current\_3\_IECF\_ADFs.txt...  
 Extracting ADFs...

ASA\_CON\_AXVIEC20080710\_132557\_20070204\_165113\_20081231\_000000  
 ASA\_INS\_AXVIEC20071218\_083603\_20070307\_060000\_20081231\_000000  
 ASA\_XCH\_AXVIEC20051219\_162547\_20020301\_000000\_20081231\_000000  
 ASA\_XCA\_AXVIEC20080710\_133546\_20070204\_165113\_20081231\_000000

Writing file ./RESULTS/DAILY/081115/AUXILIARY/ASAR\_ADFs\_IECF\_List3.html...  
 Writing file ./RESULTS/DAILY/081115/AUXILIARY/Auxiliary\_files\_summary.html...

\*\*\*\*\*

Analysing WVS products...

Writing file ./RESULTS/DAILY/081115/AUXILIARY/Check\_ADFs\_WVS.xls...  
 Writing file ./RESULTS/DAILY/081115/AUXILIARY/Check\_ADFs\_WVS.txt...

ASA_WVS_1PNPDE20081115_000944_000010642073_00460_35083_5666.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20081115_003358_000004202073_00460_35083_5659.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20081115_005749_000003002073_00460_35083_5676.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20081115_010204_000003452073_00460_35083_5797.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20081115_011439_000008242073_00460_35083_5804.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20081115_015926_000012142073_00461_35084_5807.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20081115_021910_000001502073_00461_35084_5915.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20081115_023825_000003152073_00461_35084_5946.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20081115_201524_000005842073_00472_35095_6794.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20081115_202651_000012892073_00472_35095_6445.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20081115_210500_000000152073_00472_35095_6448.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20081115_210500_000002402073_00472_35095_7014.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20081115_215821_000018292073_00473_35096_6817.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20081115_225136_000007192073_00473_35096_6996.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20081115_071921_000002252073_00464_35087_5618.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20081115_074013_000018892073_00464_35087_5632.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20081115_092306_000018742073_00465_35088_5722.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20081115_102702_000010492073_00466_35089_5930.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20081115_110410_000018142073_00466_35089_5995.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20081115_115113_000010792073_00467_35090_5921.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20081115_121638_000005102073_00467_35090_5911.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20081115_124200_000003302073_00467_35090_5893.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20081115_125601_000008202073_00467_35090_5898.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20081115_133326_000007792073_00468_35091_6122.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20081115_140352_000001202073_00468_35091_6125.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20081115_142236_000003902073_00468_35091_6130.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20081115_143353_000005842073_00468_35091_6137.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20081115_152306_000001192073_00469_35092_6276.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20081115_152731_000011392073_00469_35092_6289.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20081115_160312_000012742073_00469_35092_6303.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20081115_170458_000013192073_00470_35093_6429.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20081115_174348_000013042073_00470_35093_6443.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20081115_183837_000017392073_00471_35094_6564.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20081115_192424_000007202073_00471_35094_6572.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

\*\*\*\*\*

Analysing GM1 products...

Writing file ./RESULTS/DAILY/081115/AUXILIARY/Check\_ADFs\_GM1.xls...  
 Writing file ./RESULTS/DAILY/081115/AUXILIARY/Check\_ADFs\_GM1.txt...

ASA_GM1_1PNPDE20081115_002812_000003442073_00460_35083_5661.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081115_005536_000001322073_00460_35083_5673.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081115_010831_000003622073_00460_35083_5799.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081115_013033_000007372073_00461_35084_5801.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081115_015026_000001992073_00461_35084_5814.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081115_022220_000002772073_00461_35084_5912.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

ASA_GM1_1PNPDE20081115_023245_000003382073_00461_35084_5917.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081115_071216_000001322073_00464_35087_6135.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081115_200758_000002292073_00472_35095_6442.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081115_205603_000005312073_00472_35095_6450.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081115_214621_000004832073_00473_35096_6803.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081115_214621_000004832073_00473_35096_6900.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081115_222931_00000842073_00473_35096_6796.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081115_222931_00000842073_00473_35096_6991.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081115_223429_000003262073_00473_35096_6791.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081115_223429_000003262073_00473_35096_7016.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081115_230426_000002832073_00474_35097_6987.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081115_232559_000003202073_00474_35097_6964.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20081115_235643_000004042073_00474_35097_6718.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081115_072348_000009852073_00464_35087_5668.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081115_081328_000001812073_00465_35088_5624.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081115_082332_000001382073_00465_35088_5634.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081115_082434_000003562073_00465_35088_5707.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081115_084355_000004162073_00465_35088_5709.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081115_090444_000008272073_00465_35088_5712.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081115_095507_000003742073_00466_35089_5714.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081115_100258_000002712073_00466_35089_5725.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081115_100618_000001752073_00466_35089_6072.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081115_101532_000001022073_00466_35089_6068.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081115_102038_000003802073_00466_35089_6070.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081115_104520_000002532073_00466_35089_5992.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081115_105608_000001692073_00466_35089_5925.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081115_113852_000001872073_00467_35090_5923.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081115_114830_000000782073_00467_35090_5901.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081115_121223_000001202073_00467_35090_5895.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081115_123111_000006462073_00467_35090_5903.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081115_124929_000003922073_00467_35090_5890.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081115_131018_000002112073_00468_35091_5887.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081115_132032_000002532073_00468_35091_5885.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081115_132335_000004952073_00468_35091_6099.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081115_134711_000002412073_00468_35091_6115.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081115_135239_000003682073_00468_35091_6119.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081115_135855_000002952073_00468_35091_6117.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081115_140632_000009302073_00468_35091_6134.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081115_142950_000002412073_00468_35091_6127.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081115_145133_000004102073_00469_35092_6132.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081115_151444_000001202073_00469_35092_6273.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081115_151804_000003022073_00469_35092_6278.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081115_152553_000000962073_00469_35092_6286.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081115_154708_000009302073_00469_35092_6293.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081115_162510_000001082073_00470_35093_6291.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081115_163333_000002112073_00470_35093_6300.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081115_165442_000006162073_00470_35093_6424.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081115_172744_000005612073_00470_35093_6426.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081115_174037_000001872073_00470_35093_6431.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081115_180618_000000722073_00471_35094_6433.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081115_180901_000002412073_00471_35094_6440.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081115_182930_000001142073_00471_35094_6553.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081115_183704_000000902073_00471_35094_6555.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081115_190820_000001692073_00471_35094_6557.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081115_191543_000002652073_00471_35094_6559.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081115_192258_000000842073_00471_35094_6561.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20081115_193702_000007612073_00471_35094_6574.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

\*\*\*\*\*

Analysing APM products...

Writing file ./RESULTS/DAILY/081115/AUXILIARY/Check\_ADFs\_APM.xls...

Writing file ./RESULTS/DAILY/081115/AUXILIARY/Check\_ADFs\_APM.txt...

ASA_APM_1PNPDE20081115_012930_000000432073_00461_35084_5816.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDK20081115_195730_000000562073_00472_35095_6577.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

\*\*\*\*\*

Analysing IMM products...

Writing file ./RESULTS/DAILY/081115/AUXILIARY/Check\_ADFs\_IMM.xls...

Writing file ./RESULTS/DAILY/081115/AUXILIARY/Check\_ADFs\_IMM.txt...

ASA_IMM_1PNPDE20081115_004236_000005622073_00460_35083_5794.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20081115_005236_000001692073_00460_35083_5761.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20081115_015342_000000792073_00461_35084_5871.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20081115_022658_000003372073_00461_35084_6575.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20081115_022802_000002732073_00461_35084_5894.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20081115_071048_000000772073_00464_35087_6128.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20081115_101715_000000372073_00466_35089_6233.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20081115_104935_000002622073_00466_35089_6254.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20081115_105330_000001472073_00466_35089_6265.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20081115_122645_000000632073_00467_35090_6287.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20081115_122645_000000822073_00467_35090_6902.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20081115_135111_000000772073_00468_35091_6315.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20081115_144701_000002612073_00469_35092_6331.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20081115_173704_000002022073_00470_35093_6361.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20081115_180728_000000822073_00471_35094_6385.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20081115_181300_000000832073_00471_35094_6387.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20081115_191110_000002612073_00471_35094_6431.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20081115_192010_000001572073_00471_35094_6407.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20081115_202553_000000522073_00472_35095_6524.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20081115_205113_000002762073_00472_35095_6561.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20081115_223956_000001782073_00473_35096_7068.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20081115_081216_000000392073_00465_35088_5666.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20081115_083028_000000382073_00465_35088_5676.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20081115_083127_000001872073_00465_35088_5700.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20081115_114944_000000822073_00467_35090_6078.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20081115_122838_000001422073_00467_35090_6076.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20081115_124841_000000372073_00467_35090_5871.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20081115_214249_000002012073_00473_35096_6696.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20081115_232029_000003192073_00474_35097_6712.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

\*\*\*\*\*

Analysing WSM products...

Writing file ./RESULTS/DAILY/081115/AUXILIARY/Check\_ADFs\_WSM.xls...

Writing file ./RESULTS/DAILY/081115/AUXILIARY/Check\_ADFs\_WSM.txt...

ASA_WSM_1PNPDE20081115_014252_000001342073_00461_35084_5919.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081115_014252_000004522073_00461_35084_6589.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081115_014601_000002632073_00461_35084_5920.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081115_024514_000000912073_00461_35084_5996.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081115_071432_000001352073_00464_35087_6208.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081115_071432_000002872073_00464_35087_6603.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081115_071742_000000962073_00464_35087_6209.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081115_082156_000000912073_00465_35088_6223.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081115_084219_000000912073_00465_35088_6225.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081115_100124_000000922073_00466_35089_6239.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081115_105900_000003122073_00466_35089_6298.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081115_113702_000001022073_00467_35090_6295.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081115_120955_000001352073_00467_35090_6300.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081115_121541_000000612073_00467_35090_6293.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081115_133156_000000922073_00468_35091_6329.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081115_151040_000000922073_00469_35092_6333.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081115_151649_000000672073_00469_35092_6327.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081115_162815_000000612073_00470_35093_6337.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081115_163011_000001842073_00470_35093_6347.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081115_164625_000002142073_00470_35093_6395.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081115_165118_000000182073_00470_35093_6359.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

```
ASA_WSM_1PNPDE20081115_165208_000001522073_00470_35093_6397.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081115_182629_000001772073_00471_35094_6399.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081115_183130_000003302073_00471_35094_6433.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081115_200616_000000972073_00472_35095_6544.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081115_201151_000002142073_00472_35095_6559.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081115_210948_000001342073_00472_35095_6569.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081115_211257_000000862073_00472_35095_6570.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081115_233121_000000732073_00474_35097_6729.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081115_233255_000001342073_00474_35097_7003.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20081115_233604_000001842073_00474_35097_7004.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```

AUXILIARY FILES ANALYSIS completed

#####

MODULE STEPPING ANALYSIS

#####

Analysis will be performed from 2008-11-15 00:00:00 to 2008-11-15 23:59:59

Results will be exported to the directory: ./RESULTS/DAILY/081115/MODULE\_STEPPING

Creating directory ./RESULTS/DAILY/081115/MODULE\_STEPPING...

Creating directory ./RESULTS/DAILY/081115/MODULE\_STEPPING/FIRST\_REFERENCE...

Creating directory ./RESULTS/DAILY/081115/MODULE\_STEPPING/SECOND\_REFERENCE...

Creating directory ./RESULTS/DAILY/081115/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE...

Deleting old files...

\*\*\*\*\*

\*\*\*\*\*

Creating images comparing with second reference...

Exporting results to the directory ../../RESULTS/DAILY/081115/MODULE\_STEPPING/SECOND\_REFERENCE...

Polarization: H

Reference product: ASA\_MS\_0PNPDK20050922\_062651\_00000152041\_00034\_18625\_0041.N1

Test product: ASA\_MS\_0PNPDE20081115\_070826\_00000162073\_00464\_35087\_0357.N1

H

H

../../RESULTS/DAILY/081115/MODULE\_STEPPING/SECOND\_REFERENCE/TGH\_20081115\_070826-20050922\_062651.png

../../RESULTS/DAILY/081115/MODULE\_STEPPING/SECOND\_REFERENCE/TPH\_20081115\_070826-20050922\_062651.png

../../RESULTS/DAILY/081115/MODULE\_STEPPING/SECOND\_REFERENCE/RGH\_20081115\_070826-20050922\_062651.png

../../RESULTS/DAILY/081115/MODULE\_STEPPING/SECOND\_REFERENCE/RPH\_20081115\_070826-20050922\_062651.png

Polarization: V

Reference product: ASA\_MS\_0PNPDK20050923\_055514\_00000152041\_00048\_18639\_0042.N1

Test product: ASA\_MS\_0PNPDE20081115\_204854\_00000162073\_00472\_35095\_0358.N1

V

V

../../RESULTS/DAILY/081115/MODULE\_STEPPING/SECOND\_REFERENCE/TGV\_20081115\_204854-20050923\_055514.png

../../RESULTS/DAILY/081115/MODULE\_STEPPING/SECOND\_REFERENCE/TPV\_20081115\_204854-20050923\_055514.png

../../RESULTS/DAILY/081115/MODULE\_STEPPING/SECOND\_REFERENCE/RGV\_20081115\_204854-20050923\_055514.png

../../RESULTS/DAILY/081115/MODULE\_STEPPING/SECOND\_REFERENCE/RPV\_20081115\_204854-20050923\_055514.png

\*\*\*\*\*

\*\*\*\*\*

Creating images comparing with previous product reference...

Exporting results to the directory ../../RESULTS/DAILY/081115/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE...

Polarization: H

Reference product: ASA\_MS\_0PNPDK20081114\_143807\_00000162073\_00454\_35077\_0678.N1

Test product: ASA\_MS\_0PNPDE20081115\_070826\_00000162073\_00464\_35087\_0357.N1

H

H

../../RESULTS/DAILY/081115/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/TGH\_20081115\_070826-20081114\_143807.png

../../RESULTS/DAILY/081115/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/TPH\_20081115\_070826-20081114\_143807.png



../../RESULTS/DAILY/081115/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/RGH\_20081115\_070826-20081114\_143807.png  
../../RESULTS/DAILY/081115/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/RPH\_20081115\_070826-20081114\_143807.png

Polarization: V  
Reference product: ASA\_MS\_0PNPDK20081113\_100756\_000000162073\_00437\_35060\_0677.N1  
Test product: ASA\_MS\_0PNPDE20081115\_204854\_000000162073\_00472\_35095\_0358.N1

V  
V  
../../RESULTS/DAILY/081115/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/TGV\_20081115\_204854-20081113\_100756.png  
../../RESULTS/DAILY/081115/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/TPV\_20081115\_204854-20081113\_100756.png  
../../RESULTS/DAILY/081115/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/RGV\_20081115\_204854-20081113\_100756.png  
../../RESULTS/DAILY/081115/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/RPV\_20081115\_204854-20081113\_100756.png

MODULE\_STEPPING ANALYSIS completed  
#####

CALIBRATION PULSES ANALYSIS  
#####

Creating directory ./RESULTS/DAILY/081115/CALIBRATION\_PULSES...

\*\*\*\*\*  
\*\*\*\*\*  
ALL ROWS Analysis will be performed from 2008-11-15 00:00:00 to 2008-11-15 23:59:59

Analysing products WVS IS2 V/V  
Writing image ../../RESULTS/DAILY/081115//CALIBRATION\_PULSES/Calibration\_pulses\_all\_rows\_WVS\_IS2\_VV.png...  
Analysing products GM1 SS3 H/H  
Writing image ../../RESULTS/DAILY/081115//CALIBRATION\_PULSES/Calibration\_pulses\_all\_rows\_GM1\_SS3\_HH.png...

\*\*\*\*\*  
\*\*\*\*\*  
TEMPORAL EVOLUTION Analysis will be performed from 2008-11-15 00:00:00 to 2008-11-15 23:59:59

Analysing products WVS IS2 V/V  
Getting calibration pulses data for WVS IS2 V/V from 2008-11-15 00:00:00 to 2008-11-15 23:59:59. Rows: 1/5/9/13/17/21/25/29  
Writing file ./RESULTS/DAILY/081115/CALIBRATION\_PULSES/Calibration\_pulses\_data\_WVS\_IS2\_VV\_2008-11-15\_1.dat...  
Writing ../../RESULTS/DAILY/081115//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_WVS\_IS2\_VV\_1.png...  
Writing ../../RESULTS/DAILY/081115//CALIBRATION\_PULSES/Transmit\_Power\_WVS\_IS2\_VV\_1.png...

Getting calibration pulses data for WVS IS2 V/V from 2008-11-15 00:00:00 to 2008-11-15 23:59:59. Rows: 2/6/10/14/18/22/26/30  
Writing file ./RESULTS/DAILY/081115/CALIBRATION\_PULSES/Calibration\_pulses\_data\_WVS\_IS2\_VV\_2008-11-15\_2.dat...  
Writing ../../RESULTS/DAILY/081115//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_WVS\_IS2\_VV\_2.png...  
Writing ../../RESULTS/DAILY/081115//CALIBRATION\_PULSES/Transmit\_Power\_WVS\_IS2\_VV\_2.png...

Getting calibration pulses data for WVS IS2 V/V from 2008-11-15 00:00:00 to 2008-11-15 23:59:59. Rows: 3/7/11/15/19/23/27/31  
Writing file ./RESULTS/DAILY/081115/CALIBRATION\_PULSES/Calibration\_pulses\_data\_WVS\_IS2\_VV\_2008-11-15\_3.dat...  
Writing ../../RESULTS/DAILY/081115//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_WVS\_IS2\_VV\_3.png...  
Writing ../../RESULTS/DAILY/081115//CALIBRATION\_PULSES/Transmit\_Power\_WVS\_IS2\_VV\_3.png...

Getting calibration pulses data for WVS IS2 V/V from 2008-11-15 00:00:00 to 2008-11-15 23:59:59. Rows: 4/8/12/16/20/24/28/32  
Writing file ./RESULTS/DAILY/081115/CALIBRATION\_PULSES/Calibration\_pulses\_data\_WVS\_IS2\_VV\_2008-11-15\_4.dat...  
Writing ../../RESULTS/DAILY/081115//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_WVS\_IS2\_VV\_4.png...  
Writing ../../RESULTS/DAILY/081115//CALIBRATION\_PULSES/Transmit\_Power\_WVS\_IS2\_VV\_4.png...

Analysing products GM1 SS3 H/H  
Getting calibration pulses data for GM1 SS3 H/H from 2008-11-15 00:00:00 to 2008-11-15 23:59:59. Rows: 1/5/9/13/17/21/25/29  
Writing file ./RESULTS/DAILY/081115/CALIBRATION\_PULSES/Calibration\_pulses\_data\_GM1\_SS3\_HH\_2008-11-15\_1.dat...  
Writing ../../RESULTS/DAILY/081115//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_GM1\_SS3\_HH\_1.png...  
Writing ../../RESULTS/DAILY/081115//CALIBRATION\_PULSES/Transmit\_Power\_GM1\_SS3\_HH\_1.png...

Getting calibration pulses data for GM1 SS3 H/H from 2008-11-15 00:00:00 to 2008-11-15 23:59:59. Rows: 2/6/10/14/18/22/26/30  
Writing file ./RESULTS/DAILY/081115/CALIBRATION\_PULSES/Calibration\_pulses\_data\_GM1\_SS3\_HH\_2008-11-15\_2.dat...  
Writing ../../RESULTS/DAILY/081115//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_GM1\_SS3\_HH\_2.png...  
Writing ../../RESULTS/DAILY/081115//CALIBRATION\_PULSES/Transmit\_Power\_GM1\_SS3\_HH\_2.png...

Getting calibration pulses data for GM1 SS3 H/H from 2008-11-15 00:00:00 to 2008-11-15 23:59:59. Rows: 3/7/11/15/19/23/27/31  
Writing file ./RESULTS/DAILY/081115/CALIBRATION\_PULSES/Calibration\_pulses\_data\_GM1\_SS3\_HH\_2008-11-15\_3.dat...  
Writing ../../RESULTS/DAILY/081115//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_GM1\_SS3\_HH\_3.png...  
Writing ../../RESULTS/DAILY/081115//CALIBRATION\_PULSES/Transmit\_Power\_GM1\_SS3\_HH\_3.png...

Getting calibration pulses data for GM1 SS3 H/H from 2008-11-15 00:00:00 to 2008-11-15 23:59:59. Rows: 4/8/12/16/20/24/28/32  
Writing file ./RESULTS/DAILY/081115/CALIBRATION\_PULSES/Calibration\_pulses\_data\_GM1\_SS3\_HH\_2008-11-15\_4.dat...  
Writing ../../RESULTS/DAILY/081115//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_GM1\_SS3\_HH\_4.png...  
Writing ../../RESULTS/DAILY/081115//CALIBRATION\_PULSES/Transmit\_Power\_GM1\_SS3\_HH\_4.png...

CALIBRATION PULSES ANALYSIS completed  
#####

DOPPLER ANALYSIS  
#####  
Creating directory ./RESULTS/DAILY/081115/DOPPLER...

\*\*\*\*\*  
\*\*\*\*\*  
DOPPLER ANX Analysis will be performed from 2008-11-15 00:00:00 to 2008-11-15 23:59:59

Analysing products WVS IS2 V/V  
Getting doppler data for WVS IS2 V/V from 2008-11-15 00:00:00 to 2008-11-15 23:59:59...  
Writing file ./RESULTS/DAILY/081115/DOPPLER/Doppler\_data\_WVS\_IS2\_VV\_2008-11-15.dat...  
Running IDL program...  
Writing file ../../RESULTS/DAILY/081115/DOPPLER/DOPPLER\_ANX\_WVS\_IS2\_VV.png...

Analysing products GM1 SS1 H/H  
Getting doppler data for GM1 SS1 H/H from 2008-11-15 00:00:00 to 2008-11-15 23:59:59...  
Writing file ./RESULTS/DAILY/081115/DOPPLER/Doppler\_data\_GM1\_SS1\_HH\_2008-11-15.dat...  
Running IDL program...  
Writing file ../../RESULTS/DAILY/081115/DOPPLER/DOPPLER\_ANX\_GM1\_SS1\_HH.png...

\*\*\*\*\*  
\*\*\*\*\*  
DOPPLER JUMPS Analysis will be performed on WSM products from 2008-11-15 00:00:00 to 2008-11-15 23:59:59

Analysing by default products WSM  
Getting doppler jumps data for WSM from 2008-11-15 00:00:00 to 2008-11-15 23:59:59...  
Writing file ./RESULTS/DAILY/081115/DOPPLER/Doppler\_Jumps\_data\_WSM\_2008-11-15.dat...  
Running IDL program...  
Writing file ../../RESULTS/DAILY/081115/DOPPLER/DOPPLER\_JUMPS\_ANX\_WSM.png...  
Writing file ../../RESULTS/DAILY/081115/DOPPLER/DOPPLER\_JUMPS\_Date\_WSM.png...

\*\*\*\*\*  
\*\*\*\*\*  
DOPPLER MAP Analysis will be performed from 2008-11-15 00:00:00 to 2008-11-15 23:59:59

Analysing products WVS IS2 V/V  
Loading predicted doppler values....  
Phase: descending

```
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -35.066328 Hz
Writing file ../../RESULTS/DAILY/081115//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_WVS_IS2_VV_desc.jpg...
Writing file ../../RESULTS/DAILY/081115//DOPPLER/DOPPLER_Absolute_WVS_IS2_VV_desc.jpg...
```

```
*****
Loading predicted doppler values...
Phase: ascending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -30.836351 Hz
Writing file ../../RESULTS/DAILY/081115//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_WVS_IS2_VV_asc.jpg...
Writing file ../../RESULTS/DAILY/081115//DOPPLER/DOPPLER_Absolute_WVS_IS2_VV_asc.jpg...
```

```
*****
Analysing products GM1 SS1 H/H
Loading predicted doppler values...
Phase: descending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -17.694817 Hz
Writing file ../../RESULTS/DAILY/081115//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_GM1_SS1_HH_desc.jpg...
Writing file ../../RESULTS/DAILY/081115//DOPPLER/DOPPLER_Absolute_GM1_SS1_HH_desc.jpg...
```

```
*****
Loading predicted doppler values...
Phase: ascending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -29.176450 Hz
Writing file ../../RESULTS/DAILY/081115//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_GM1_SS1_HH_asc.jpg...
Writing file ../../RESULTS/DAILY/081115//DOPPLER/DOPPLER_Absolute_GM1_SS1_HH_asc.jpg...
```

```
*****
DOPPLER ANALYSIS completed
#####
```

```
CHIRP ANALYSIS
#####
Creating directory ./RESULTS/DAILY/081115/CHIRP...
```

```
*****
*****
CHIRP Analysis will be performed from 2008-11-15 00:00:00 to 2008-11-15 23:59:59
```

```
Analysing products WSM SS1 H/H
*****
Getting ScaleFactor data for WSM SS1 H/H from 2008-11-15 00:00:00 to 2008-11-15 23:59:59...
Writing file ./RESULTS/DAILY/081115/CHIRP/ScaleFactor_data_WSM_SS1_HH_2008-11-15.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/081115/CHIRP/ScaleFactor_ANX_WSM_SS1_HH.png...
Writing file ../../RESULTS/DAILY/081115/CHIRP/ScaleFactor_DATE_WSM_SS1_HH.png...
```

```
Analysing products WSM SS1 V/V
*****
Getting ScaleFactor data for WSM SS1 V/V from 2008-11-15 00:00:00 to 2008-11-15 23:59:59...
Writing file ./RESULTS/DAILY/081115/CHIRP/ScaleFactor_data_WSM_SS1_VV_2008-11-15.dat...
```

Running IDL program...  
Writing file ../../RESULTS/DAILY/081115/CHIRP/ScaleFactor\_ANX\_WSM\_SS1\_VV.png...  
Writing file ../../RESULTS/DAILY/081115/CHIRP/ScaleFactor\_DATE\_WSM\_SS1\_VV.png...

CHIRP ANALYSIS completed  
#####

RAW DATA ANALYSIS  
#####  
Analysis will be performed from 2008-11-15 00:00:00 to 2008-11-15 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/081115/RAW\_DATA

Creating directory ./RESULTS/DAILY/081115/RAW\_DATA...

\*\*\*\*\*  
Getting raw data for WVS from 2008-11-15 00:00:00 to 2008-11-15 23:59:59...  
Writing file ./RESULTS/DAILY/081115/RAW\_DATA/Raw\_data\_WVS\_2008-11-15.dat...  
Running IDL program to create graphs...

Creating image ../../RESULTS/DAILY/081115/RAW\_DATA/Raw\_data\_WVS\_input\_mean.png...  
Creating image ../../RESULTS/DAILY/081115/RAW\_DATA/Raw\_data\_WVS\_input\_stdev.png...  
Creating image ../../RESULTS/DAILY/081115/RAW\_DATA/Raw\_data\_WVS\_gain\_imbalance.png...

\*\*\*\*\*  
Getting raw data for IMM from 2008-11-15 00:00:00 to 2008-11-15 23:59:59...  
Writing file ./RESULTS/DAILY/081115/RAW\_DATA/Raw\_data\_IMM\_2008-11-15.dat...  
Running IDL program to create graphs...

Creating image ../../RESULTS/DAILY/081115/RAW\_DATA/Raw\_data\_IMM\_input\_mean.png...  
Creating image ../../RESULTS/DAILY/081115/RAW\_DATA/Raw\_data\_IMM\_input\_stdev.png...  
Creating image ../../RESULTS/DAILY/081115/RAW\_DATA/Raw\_data\_IMM\_gain\_imbalance.png...

RAW DATA ANALYSIS completed  
#####

TELEMETRY ANALYSIS  
#####  
Analysis will be performed from 2008-11-15 00:00:00 to 2008-11-15 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/081115/TELEMETRY

Creating directory ./RESULTS/DAILY/081115/TELEMETRY...

Looking for gaps and missing lines in WVS products...  
\*\*\*\*\*  
Checking 14 products from PDE...  
Checking 20 products from PDK...

Looking for gaps and missing lines in GM1 products...  
\*\*\*\*\*  
Checking 20 products from PDE...  
Checking 44 products from PDK...

Looking for gaps and missing lines in APM products...  
\*\*\*\*\*  
Checking 1 products from PDE...  
Checking 1 products from PDK...

Looking for gaps and missing lines in IMM products...  
\*\*\*\*\*  
Checking 21 products from PDE...  
Checking 8 products from PDK...

Looking for gaps and missing lines in WSM products...

\*\*\*\*\*

Checking 31 products from PDE...

No products from PDK...

Creating graph of missing lines and gaps...

\*\*\*\*\*

Creating image: ./RESULTS/DAILY/081115/TELEMETRY/TELEMETRY\_Missing\_lines.png...

Creating image: ./RESULTS/DAILY/081115/TELEMETRY/TELEMETRY\_Gaps.png...

TELEMETRY ANALYSIS completed

#####

BROWSE PRODUCTS ANALYSIS

#####

Analysis will be performed on 2008-11-15

\*\*\*\*\*

Scanning directory /nas3/ENVISAT/ASAR//ASA\_GM\_BP...

Results will be exported to the directory: /nas3/ENVISAT/ASAR//ASA\_GM\_BP/JPG/20081115/

Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20081115\_200758\_000002292073\_00472\_35095\_6443.N1 ...

Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20081115\_205603\_000005312073\_00472\_35095\_6451.N1 ...

Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20081115\_214621\_000004832073\_00473\_35096\_6804.N1 ...

Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20081115\_214621\_000004832073\_00473\_35096\_6901.N1 ...

Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20081115\_222931\_000000842073\_00473\_35096\_6797.N1 ...

Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20081115\_222931\_000000842073\_00473\_35096\_6992.N1 ...

Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20081115\_223429\_000003262073\_00473\_35096\_6792.N1 ...

Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20081115\_223429\_000003262073\_00473\_35096\_7017.N1 ...

Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20081115\_230426\_000002832073\_00474\_35097\_6988.N1 ...

Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20081115\_232559\_000003202073\_00474\_35097\_6965.N1 ...

Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20081115\_235643\_000004042073\_00474\_35097\_6719.N1 ...

ANALYSIS COMPLETED: 11 GM browse products to see...

\*\*\*\*\*

\*\*\*\*\*

Scanning directory /nas3/ENVISAT/ASAR//ASA\_AP\_BP...

Results will be exported to the directory: /nas3/ENVISAT/ASAR//ASA\_AP\_BP/JPG/20081115/

ANALYSIS COMPLETED: 0 AP browse products to see...

\*\*\*\*\*

\*\*\*\*\*

Scanning directory /nas3/ENVISAT/ASAR//ASA\_IM\_BP...

Results will be exported to the directory: /nas3/ENVISAT/ASAR//ASA\_IM\_BP/JPG/20081115/

Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20081115\_022658\_000003372073\_00461\_35084\_6576.N1 ...

Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20081115\_101715\_000000372073\_00466\_35089\_6234.N1 ...

Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20081115\_104935\_000002622073\_00466\_35089\_6255.N1 ...

Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20081115\_105330\_000001472073\_00466\_35089\_6266.N1 ...

Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20081115\_122645\_000000632073\_00467\_35090\_6288.N1 ...

Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20081115\_122645\_000000822073\_00467\_35090\_6903.N1 ...

Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20081115\_135111\_000000772073\_00468\_35091\_6316.N1 ...

Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20081115\_144701\_000002612073\_00469\_35092\_6332.N1 ...

Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20081115\_173704\_000002022073\_00470\_35093\_6362.N1 ...

Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20081115\_180728\_000000822073\_00471\_35094\_6386.N1 ...

Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20081115\_181300\_000000832073\_00471\_35094\_6388.N1 ...

Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20081115\_191110\_000002612073\_00471\_35094\_6432.N1 ...

Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20081115\_192010\_000001572073\_00471\_35094\_6408.N1 ...

Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20081115\_202553\_000000522073\_00472\_35095\_6525.N1 ...

Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20081115\_205113\_000002762073\_00472\_35095\_6562.N1 ...

Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20081115\_223956\_000001782073\_00473\_35096\_7069.N1 ...

ANALYSIS COMPLETED: 16 IM browse products to see...

\*\*\*\*\*

\*\*\*\*\*

Scanning directory /nas3/ENVISAT/ASAR//ASA\_WS\_BP...

Results will be exported to the directory: /nas3/ENVISAT/ASAR//ASA\_WS\_BP/JPG/20081115/

Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_BP/ASA\_WS\_BPZPDE20081115\_014252\_000004522073\_00461\_35084\_6590.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_BP/ASA\_WS\_BPZPDE20081115\_100124\_000000922073\_00466\_35089\_6240.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_BP/ASA\_WS\_BPZPDE20081115\_105900\_000003122073\_00466\_35089\_6299.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_BP/ASA\_WS\_BPZPDE20081115\_113702\_000001022073\_00467\_35090\_6296.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_BP/ASA\_WS\_BPZPDE20081115\_120955\_000001352073\_00467\_35090\_6301.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_BP/ASA\_WS\_BPZPDE20081115\_121541\_000000612073\_00467\_35090\_6294.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_BP/ASA\_WS\_BPZPDE20081115\_133156\_000000922073\_00468\_35091\_6330.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_BP/ASA\_WS\_BPZPDE20081115\_151040\_000000922073\_00469\_35092\_6334.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_BP/ASA\_WS\_BPZPDE20081115\_151649\_000000672073\_00469\_35092\_6328.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_BP/ASA\_WS\_BPZPDE20081115\_162815\_000000612073\_00470\_35093\_6338.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_BP/ASA\_WS\_BPZPDE20081115\_163011\_000001842073\_00470\_35093\_6348.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_BP/ASA\_WS\_BPZPDE20081115\_164625\_000002142073\_00470\_35093\_6396.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_BP/ASA\_WS\_BPZPDE20081115\_165118\_000000182073\_00470\_35093\_6360.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_BP/ASA\_WS\_BPZPDE20081115\_165208\_000001522073\_00470\_35093\_6398.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_BP/ASA\_WS\_BPZPDE20081115\_182629\_000001772073\_00471\_35094\_6400.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_BP/ASA\_WS\_BPZPDE20081115\_183130\_000003302073\_00471\_35094\_6434.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_BP/ASA\_WS\_BPZPDE20081115\_200616\_000000972073\_00472\_35095\_6545.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_BP/ASA\_WS\_BPZPDE20081115\_201151\_000002142073\_00472\_35095\_6560.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_BP/ASA\_WS\_BPZPDE20081115\_210948\_000001342073\_00472\_35095\_6571.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_BP/ASA\_WS\_BPZPDE20081115\_211257\_000000862073\_00472\_35095\_6572.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_BP/ASA\_WS\_BPZPDE20081115\_233121\_000000732073\_00474\_35097\_6730.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_BP/ASA\_WS\_BPZPDE20081115\_233255\_000001342073\_00474\_35097\_7005.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_BP/ASA\_WS\_BPZPDE20081115\_233604\_000001842073\_00474\_35097\_7012.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_BP/ASA\_WS\_BPZPDK20081115\_195846\_000004822073\_00472\_35095\_6677.N1 ...

ANALYSIS COMPLETED: 24 WS browse products to see...

\*\*\*\*\*

BROWSE PRODUCTS ANALYSIS completed

#####

HTML REPORT generation

#####

Building file ./RESULTS/DAILY/081115/asarReport.html...

Building DATA SUMMARY section...

Building AUXILIARY FILES ANALYSIS section...

Building MODULE STEPPING ANALYSIS section...

Building CALIBRATION PULSES ANALYSIS section...

Building DOPPLER ANALYSIS section...

Building CHIRP ANALYSIS section...

Building RAW DATA ANALYSIS section...

Building TELEMETRY ANALYSIS section...

HTML REPORT generation completed

#####



# ASAR Daily Report



Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
ASA_APM_1PNPDE20081115_012930_000000432073_00461_35084_5816.N1	OK	OK	OK	OK
ASA_APM_1PNPDK20081115_195730_000000562073_00472_35095_6577.N1	OK	OK	OK	OK



Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_GM1_1PNPDE20081115_002812_000003442073_00460_35083_5661.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081115_005536_000001322073_00460_35083_5673.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081115_010831_000003622073_00460_35083_5799.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081115_013033_000007372073_00461_35084_5801.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081115_015026_000001992073_00461_35084_5814.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081115_022220_000002772073_00461_35084_5912.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081115_023245_000003382073_00461_35084_5917.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081115_071216_000001322073_00464_35087_6135.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081115_200758_000002292073_00472_35095_6442.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081115_205603_000005312073_00472_35095_6450.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081115_214621_000004832073_00473_35096_6803.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081115_214621_000004832073_00473_35096_6900.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081115_222931_000000842073_00473_35096_6796.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081115_222931_000000842073_00473_35096_6991.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081115_223429_000003262073_00473_35096_6791.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081115_223429_000003262073_00473_35096_7016.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081115_230426_000002832073_00474_35097_6987.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081115_232559_000003202073_00474_35097_6964.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20081115_235643_000004042073_00474_35097_6718.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081115_072348_000009852073_00464_35087_5668.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081115_081328_000001812073_00465_35088_5624.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081115_082332_000001382073_00465_35088_5634.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081115_082434_000003562073_00465_35088_5707.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081115_084355_000004162073_00465_35088_5709.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081115_090444_000008272073_00465_35088_5712.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081115_095507_000003742073_00466_35089_5714.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081115_100258_000002712073_00466_35089_5725.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081115_100618_000001752073_00466_35089_6072.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081115_101532_000001022073_00466_35089_6068.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081115_102038_000003802073_00466_35089_6070.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081115_104520_000002532073_00466_35089_5992.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081115_105608_000001692073_00466_35089_5925.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081115_113852_000001872073_00467_35090_5923.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081115_114830_000000782073_00467_35090_5901.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081115_121223_000001202073_00467_35090_5895.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081115_123111_000006462073_00467_35090_5903.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081115_124929_000003922073_00467_35090_5890.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081115_131018_000002112073_00468_35091_5887.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081115_132032_000002532073_00468_35091_5885.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081115_132335_000004952073_00468_35091_6099.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081115_134711_000002412073_00468_35091_6115.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081115_135239_000003682073_00468_35091_6119.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081115_135855_000002952073_00468_35091_6117.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081115_140632_000009302073_00468_35091_6134.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081115_142950_000002412073_00468_35091_6127.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081115_145133_000004102073_00469_35092_6132.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081115_151444_000001202073_00469_35092_6273.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081115_151804_000003022073_00469_35092_6278.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081115_152553_000000962073_00469_35092_6286.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081115_154708_000009302073_00469_35092_6293.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081115_162510_000001082073_00470_35093_6291.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081115_163333_000002112073_00470_35093_6300.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081115_165442_000006162073_00470_35093_6424.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081115_172744_000005612073_00470_35093_6426.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081115_174037_000001872073_00470_35093_6431.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081115_180618_000000722073_00471_35094_6433.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081115_180901_000002412073_00471_35094_6440.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081115_182930_000001142073_00471_35094_6553.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081115_183704_000000902073_00471_35094_6555.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081115_190820_000001692073_00471_35094_6557.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081115_191543_000002652073_00471_35094_6559.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081115_192258_000000842073_00471_35094_6561.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20081115_193702_000007612073_00471_35094_6574.N1					OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_IMM_1PNPDE20081115_004236_000005622073_00460_35083_5794.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20081115_005236_000001692073_00460_35083_5761.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20081115_015342_000000792073_00461_35084_5871.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20081115_022658_000003372073_00461_35084_6575.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20081115_022802_000002732073_00461_35084_5894.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20081115_071048_000000772073_00464_35087_6128.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20081115_101715_000000372073_00466_35089_6233.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20081115_104935_000002622073_00466_35089_6254.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20081115_105330_000001472073_00466_35089_6265.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20081115_122645_000000632073_00467_35090_6287.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20081115_122645_000000822073_00467_35090_6902.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20081115_135111_000000772073_00468_35091_6315.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20081115_144701_000002612073_00469_35092_6331.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20081115_173704_000002022073_00470_35093_6361.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20081115_180728_000000822073_00471_35094_6385.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20081115_181300_000000832073_00471_35094_6387.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20081115_191110_000002612073_00471_35094_6431.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20081115_192010_000001572073_00471_35094_6407.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20081115_202553_000000522073_00472_35095_6524.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20081115_205113_000002762073_00472_35095_6561.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20081115_223956_000001782073_00473_35096_7068.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20081115_081216_000000392073_00465_35088_5666.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20081115_083028_000000382073_00465_35088_5676.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20081115_083127_000001872073_00465_35088_5700.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20081115_114944_000000822073_00467_35090_6078.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20081115_122838_000001422073_00467_35090_6076.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20081115_124841_000000372073_00467_35090_5871.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20081115_214249_000002012073_00473_35096_6696.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20081115_232029_000003192073_00474_35097_6712.N1					OK	OK	OK	OK


Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WSM_1PNPDE20081115_014252_000001342073_00461_35084_5919.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081115_014252_000004522073_00461_35084_6589.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081115_014601_000002632073_00461_35084_5920.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081115_024514_000000912073_00461_35084_5996.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081115_071432_000001352073_00464_35087_6208.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081115_071432_000002872073_00464_35087_6603.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081115_071742_000000962073_00464_35087_6209.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081115_082156_000000912073_00465_35088_6223.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081115_084219_000000912073_00465_35088_6225.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081115_100124_000000922073_00466_35089_6239.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081115_105900_000003122073_00466_35089_6298.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081115_113702_000001022073_00467_35090_6295.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081115_120955_000001352073_00467_35090_6300.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081115_121541_000000612073_00467_35090_6293.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081115_133156_000000922073_00468_35091_6329.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081115_151040_000000922073_00469_35092_6333.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081115_151649_000000672073_00469_35092_6327.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081115_162815_000000612073_00470_35093_6337.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081115_163011_000001842073_00470_35093_6347.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081115_164625_000002142073_00470_35093_6395.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081115_165118_000000182073_00470_35093_6359.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081115_165208_000001522073_00470_35093_6397.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081115_182629_000001772073_00471_35094_6399.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081115_183130_000003302073_00471_35094_6433.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081115_200616_000000972073_00472_35095_6544.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081115_201151_000002142073_00472_35095_6559.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081115_210948_000001342073_00472_35095_6569.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081115_211257_000000862073_00472_35095_6570.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081115_233121_000000732073_00474_35097_6729.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081115_233255_000001342073_00474_35097_7003.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20081115_233604_000001842073_00474_35097_7004.N1					OK	OK	OK	OK


Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WVS_1PNPDE20081115_000944_000010642073_00460_35083_5666.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20081115_003358_000004202073_00460_35083_5659.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20081115_005749_000003002073_00460_35083_5676.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20081115_010204_000003452073_00460_35083_5797.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20081115_011439_000008242073_00460_35083_5804.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20081115_015926_000012142073_00461_35084_5807.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20081115_021910_000001502073_00461_35084_5915.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20081115_023825_000003152073_00461_35084_5946.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20081115_201524_000005842073_00472_35095_6794.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20081115_202651_000012892073_00472_35095_6445.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20081115_210500_000000152073_00472_35095_6448.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20081115_210500_000002402073_00472_35095_7014.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20081115_215821_000018292073_00473_35096_6817.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20081115_225136_000007192073_00473_35096_6996.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20081115_071921_000002252073_00464_35087_5618.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20081115_074013_000018892073_00464_35087_5632.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20081115_092306_000018742073_00465_35088_5722.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20081115_102702_000010492073_00466_35089_5930.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20081115_110410_000018142073_00466_35089_5995.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20081115_115113_000010792073_00467_35090_5921.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20081115_121638_000005102073_00467_35090_5911.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20081115_124200_000003302073_00467_35090_5893.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20081115_125601_000008202073_00467_35090_5898.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20081115_133326_000007792073_00468_35091_6122.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20081115_140352_000001202073_00468_35091_6125.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20081115_142236_000003902073_00468_35091_6130.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20081115_143353_000005842073_00468_35091_6137.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20081115_152306_000001192073_00469_35092_6276.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20081115_152731_000011392073_00469_35092_6289.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20081115_160312_000012742073_00469_35092_6303.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20081115_170458_000013192073_00470_35093_6429.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20081115_174348_000013042073_00470_35093_6443.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20081115_183837_000017392073_00471_35094_6564.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20081115_192424_000007202073_00471_35094_6572.N1					OK	OK	OK	OK


Calibration pulses for GM1 SS3 H/H




### Calibration pulses for GM1 SS3 H/H



Calibration pulses for GM1 SS3 H/H




Calibration pulses for GM1 SS3 H/H







Calibration pulses for WVS IS2 V/V




Calibration pulses for WVS IS2 V/V





Calibration pulses for WVS IS2 V/V







Calibration pulses for WVS IS2 V/V



































15-Nov  
rows: \_ 2 \_ 6 \_ 10 \_ 14 \_ 18 \_ 22 \_ 26 \_ 30

















Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion			
ASA_APM_1PNPDE20081115_012930_000000432073_00461_35084_5816.N1						IS1	H/H	73	35084 461 4.07
ASA_APM_1PNPDK20081115_195730_000000562073_00472_35095_6577.N1						IS3	H/H	73	35095 472 4.07

Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_GM1_1PNPDE20081114_235610_000008092073_00460_35083_5663.N1						SS1	H/H	73	35083	460	4.07
ASA_GM1_1PNPDE20081115_002812_000003442073_00460_35083_5661.N1						SS1	H/H	73	35083	460	4.07
ASA_GM1_1PNPDE20081115_005536_000001322073_00460_35083_5673.N1						SS1	H/H	73	35083	460	4.07
ASA_GM1_1PNPDE20081115_010831_000003622073_00460_35083_5799.N1						SS1	H/H	73	35083	460	4.07
ASA_GM1_1PNPDE20081115_013033_000007372073_00461_35084_5801.N1						SS1	H/H	73	35084	461	4.07
ASA_GM1_1PNPDE20081115_015026_000001992073_00461_35084_5814.N1						SS1	H/H	73	35084	461	4.07
ASA_GM1_1PNPDE20081115_022220_000002772073_00461_35084_5912.N1						SS1	H/H	73	35084	461	4.07
ASA_GM1_1PNPDE20081115_023245_000003382073_00461_35084_5917.N1						SS1	H/H	73	35084	461	4.07
ASA_GM1_1PNPDE20081115_071216_000001322073_00464_35087_6135.N1						SS1	H/H	73	35087	464	4.07
ASA_GM1_1PNPDK20081115_072348_000009852073_00464_35087_5668.N1						SS1	H/H	73	35087	464	4.07
ASA_GM1_1PNPDK20081115_081328_000001812073_00465_35088_5624.N1						SS1	H/H	73	35088	465	4.07
ASA_GM1_1PNPDK20081115_082332_000001382073_00465_35088_5634.N1						SS1	H/H	73	35088	465	4.07
ASA_GM1_1PNPDK20081115_082434_000003562073_00465_35088_5707.N1						SS1	H/H	73	35088	465	4.07
ASA_GM1_1PNPDK20081115_084355_000004162073_00465_35088_5709.N1						SS1	H/H	73	35088	465	4.07
ASA_GM1_1PNPDK20081115_090444_000008272073_00465_35088_5712.N1						SS1	H/H	73	35088	465	4.07
ASA_GM1_1PNPDK20081115_095507_000003742073_00466_35089_5714.N1						SS1	H/H	73	35089	466	4.07
ASA_GM1_1PNPDK20081115_100258_000002712073_00466_35089_5725.N1						SS1	H/H	73	35089	466	4.07
ASA_GM1_1PNPDK20081115_100618_000001752073_00466_35089_6072.N1						SS1	H/H	73	35089	466	4.07
ASA_GM1_1PNPDK20081115_101532_000001022073_00466_35089_6068.N1						SS1	H/H	73	35089	466	4.07
ASA_GM1_1PNPDK20081115_102038_000003802073_00466_35089_6070.N1						SS1	H/H	73	35089	466	4.07
ASA_GM1_1PNPDK20081115_104520_000002532073_00466_35089_5992.N1						SS1	H/H	73	35089	466	4.07
ASA_GM1_1PNPDK20081115_105608_000001692073_00466_35089_5925.N1						SS1	H/H	73	35089	466	4.07
ASA_GM1_1PNPDK20081115_113852_000001872073_00467_35090_5923.N1						SS1	H/H	73	35090	467	4.07
ASA_GM1_1PNPDK20081115_114830_000000782073_00467_35090_5901.N1						SS1	H/H	73	35090	467	4.07
ASA_GM1_1PNPDK20081115_121223_000001202073_00467_35090_5895.N1						SS1	H/H	73	35090	467	4.07
ASA_GM1_1PNPDK20081115_123111_000006462073_00467_35090_5903.N1						SS1	H/H	73	35090	467	4.07
ASA_GM1_1PNPDK20081115_124929_000003922073_00467_35090_5890.N1						SS1	H/H	73	35090	467	4.07
ASA_GM1_1PNPDK20081115_131018_000002112073_00468_35091_5887.N1						SS1	H/H	73	35091	468	4.07
ASA_GM1_1PNPDK20081115_132032_000002532073_00468_35091_5885.N1						SS1	H/H	73	35091	468	4.07
ASA_GM1_1PNPDK20081115_132335_000004952073_00468_35091_6099.N1						SS1	H/H	73	35091	468	4.07
ASA_GM1_1PNPDK20081115_134711_000002412073_00468_35091_6115.N1						SS1	H/H	73	35091	468	4.07
ASA_GM1_1PNPDK20081115_135239_000003682073_00468_35091_6119.N1						SS1	H/H	73	35091	468	4.07
ASA_GM1_1PNPDK20081115_135855_000002952073_00468_35091_6117.N1						SS1	H/H	73	35091	468	4.07
ASA_GM1_1PNPDK20081115_140632_000009302073_00468_35091_6134.N1						SS1	H/H	73	35091	468	4.07
ASA_GM1_1PNPDK20081115_142950_000002412073_00468_35091_6127.N1						SS1	H/H	73	35091	468	4.07
ASA_GM1_1PNPDK20081115_145133_000004102073_00469_35092_6132.N1						SS1	H/H	73	35092	469	4.07
ASA_GM1_1PNPDK20081115_151444_000001202073_00469_35092_6273.N1						SS1	H/H	73	35092	469	4.07
ASA_GM1_1PNPDK20081115_151804_000003022073_00469_35092_6278.N1						SS1	H/H	73	35092	469	4.07
ASA_GM1_1PNPDK20081115_152553_000000962073_00469_35092_6286.N1						SS1	H/H	73	35092	469	4.07
ASA_GM1_1PNPDK20081115_154708_000009302073_00469_35092_6293.N1						SS1	H/H	73	35092	469	4.07
ASA_GM1_1PNPDK20081115_162510_000001082073_00470_35093_6291.N1						SS1	H/H	73	35093	470	4.07
ASA_GM1_1PNPDK20081115_163333_000002112073_00470_35093_6300.N1						SS1	H/H	73	35093	470	4.07
ASA_GM1_1PNPDK20081115_165442_000006162073_00470_35093_6424.N1						SS1	H/H	73	35093	470	4.07
ASA_GM1_1PNPDK20081115_172744_000005612073_00470_35093_6426.N1						SS1	H/H	73	35093	470	4.07
ASA_GM1_1PNPDK20081115_174037_000001872073_00470_35093_6431.N1						SS1	H/H	73	35093	470	4.07
ASA_GM1_1PNPDK20081115_180618_000000722073_00471_35094_6433.N1						SS1	H/H	73	35094	471	4.07
ASA_GM1_1PNPDK20081115_180901_000002412073_00471_35094_6440.N1						SS1	H/H	73	35094	471	4.07
ASA_GM1_1PNPDK20081115_182930_000001142073_00471_35094_6553.N1						SS1	H/H	73	35094	471	4.07
ASA_GM1_1PNPDK20081115_183704_000000902073_00471_35094_6555.N1						SS1	H/H	73	35094	471	4.07
ASA_GM1_1PNPDK20081115_190820_000001692073_00471_35094_6557.N1						SS1	H/H	73	35094	471	4.07
ASA_GM1_1PNPDK20081115_191543_000002652073_00471_35094_6559.N1						SS1	H/H	73	35094	471	4.07
ASA_GM1_1PNPDK20081115_192258_000000842073_00471_35094_6561.N1						SS1	H/H	73	35094	471	4.07
ASA_GM1_1PNPDK20081115_193702_000007612073_00471_35094_6574.N1						SS1	H/H	73	35094	471	4.07
ASA_GM1_1PNPDE20081115_200758_000002292073_00472_35095_6442.N1						SS1	H/H	73	35095	472	4.07
ASA_GM1_1PNPDE20081115_205603_000005312073_00472_35095_6450.N1						SS1	H/H	73	35095	472	4.07
ASA_GM1_1PNPDE20081115_214621_000004832073_00473_35096_6803.N1						SS1	H/H	73	35096	473	4.07
ASA_GM1_1PNPDE20081115_214621_000004832073_00473_35096_6900.N1						SS1	H/H	73	35096	473	4.07
ASA_GM1_1PNPDE20081115_222931_000000842073_00473_35096_6796.N1						SS1	H/H	73	35096	473	4.07
ASA_GM1_1PNPDE20081115_222931_000000842073_00473_35096_6991.N1						SS1	H/H	73	35096	473	4.07
ASA_GM1_1PNPDE20081115_223429_000003262073_00473_35096_6791.N1						SS1	H/H	73	35096	473	4.07
ASA_GM1_1PNPDE20081115_223429_000003262073_00473_35096_7016.N1						SS1	H/H	73	35096	473	4.07
ASA_GM1_1PNPDE20081115_230426_000002832073_00474_35097_6987.N1						SS1	H/H	73	35097	474	4.07
ASA_GM1_1PNPDE20081115_232559_000003202073_00474_35097_6964.N1						SS1	H/H	73	35097	474	4.07
ASA_GM1_1PNPDE20081115_235643_000004042073_00474_35097_6718.N1						SS1	H/H	73	35097	474	4.07


Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_IMM_1PNPDE20081115_004236_000005622073_00460_35083_5794.N1						IS2	H/H	73	35083	460	4.07
ASA_IMM_1PNPDE20081115_005236_000001692073_00460_35083_5761.N1						IS2	H/H	73	35083	460	4.07
ASA_IMM_1PNPDE20081115_015342_000000792073_00461_35084_5871.N1						IS7	V/V	73	35084	461	4.07
ASA_IMM_1PNPDE20081115_022658_000003372073_00461_35084_6575.N1						IS2	H/H	73	35084	461	4.07
ASA_IMM_1PNPDE20081115_022802_000002732073_00461_35084_5894.N1						IS2	H/H	73	35084	461	4.07
ASA_IMM_1PNPDE20081115_071048_000000772073_00464_35087_6128.N1						IS5	H/H	73	35087	464	4.07
ASA_IMM_1PNPDK20081115_081216_000000392073_00465_35088_5666.N1						IS2	V/V	73	35088	465	4.07
ASA_IMM_1PNPDK20081115_083028_000000382073_00465_35088_5676.N1						IS4	H/H	73	35088	465	4.07
ASA_IMM_1PNPDK20081115_083127_000001872073_00465_35088_5700.N1						IS2	V/V	73	35088	465	4.07
ASA_IMM_1PNPDE20081115_101715_000000372073_00466_35089_6233.N1						IS2	V/V	73	35089	466	4.07
ASA_IMM_1PNPDE20081115_104935_000002622073_00466_35089_6254.N1						IS2	H/H	73	35089	466	4.07
ASA_IMM_1PNPDE20081115_105330_000001472073_00466_35089_6265.N1						IS2	H/H	73	35089	466	4.07
ASA_IMM_1PNPDK20081115_114944_000000822073_00467_35090_6078.N1						IS2	H/H	73	35090	467	4.07
ASA_IMM_1PNPDE20081115_122645_000000632073_00467_35090_6287.N1						IS2	H/H	73	35090	467	4.07
ASA_IMM_1PNPDE20081115_122645_000000822073_00467_35090_6902.N1						IS2	H/H	73	35090	467	4.07
ASA_IMM_1PNPDK20081115_122838_000001422073_00467_35090_6076.N1						IS3	H/H	73	35090	467	4.07
ASA_IMM_1PNPDK20081115_124841_000000372073_00467_35090_5871.N1						IS7	V/V	73	35090	467	4.07
ASA_IMM_1PNPDE20081115_135111_000000772073_00468_35091_6315.N1						IS7	H/H	73	35091	468	4.07
ASA_IMM_1PNPDE20081115_144701_000002612073_00469_35092_6331.N1						IS2	V/V	73	35092	469	4.07
ASA_IMM_1PNPDE20081115_173704_000002022073_00470_35093_6361.N1						IS2	H/H	73	35093	470	4.07
ASA_IMM_1PNPDE20081115_180728_000000822073_00471_35094_6385.N1						IS6	V/V	73	35094	471	4.07
ASA_IMM_1PNPDE20081115_181300_000000832073_00471_35094_6387.N1						IS2	V/V	73	35094	471	4.07
ASA_IMM_1PNPDE20081115_191110_000002612073_00471_35094_6431.N1						IS2	H/H	73	35094	471	4.07
ASA_IMM_1PNPDE20081115_192010_000001572073_00471_35094_6407.N1						IS2	H/H	73	35094	471	4.07
ASA_IMM_1PNPDE20081115_202553_000000522073_00472_35095_6524.N1						IS1	V/V	73	35095	472	4.07
ASA_IMM_1PNPDE20081115_205113_000002762073_00472_35095_6561.N1						IS2	H/H	73	35095	472	4.07
ASA_IMM_1PNPDK20081115_214249_000002012073_00473_35096_6696.N1						IS2	H/H	73	35096	473	4.07
ASA_IMM_1PNPDE20081115_223956_000001782073_00473_35096_7068.N1						IS2	H/H	73	35096	473	4.07
ASA_IMM_1PNPDK20081115_232029_000003192073_00474_35097_6712.N1						IS2	H/H	73	35097	474	4.07


Filename	Pol	Timestamp	count(Module)
ASA_MS__0PNPDE20081115_070826_000000162073_00464_35087_0357.N1	H	2008-11-15 07:08:26	320
ASA_MS__0PNPDE20081115_204854_000000162073_00472_35095_0358.N1	V	2008-11-15 20:48:54	320


Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WSM_1PNPDE20081115_014252_000001342073_00461_35084_5919.N1						SS1	H/H	73	35084	461	4.07
ASA_WSM_1PNPDE20081115_014252_000004522073_00461_35084_6589.N1						SS1	H/H	73	35084	461	4.07
ASA_WSM_1PNPDE20081115_014601_000002632073_00461_35084_5920.N1						SS1	H/H	73	35084	461	4.07
ASA_WSM_1PNPDE20081115_024514_000000912073_00461_35084_5996.N1						SS1	H/H	73	35084	461	4.07
ASA_WSM_1PNPDE20081115_071432_000001352073_00464_35087_6208.N1						SS1	V/V	73	35087	464	4.07
ASA_WSM_1PNPDE20081115_071432_000002872073_00464_35087_6603.N1						SS1	V/V	73	35087	464	4.07
ASA_WSM_1PNPDE20081115_071742_000000962073_00464_35087_6209.N1						SS1	V/V	73	35087	464	4.07
ASA_WSM_1PNPDE20081115_082156_000000912073_00465_35088_6223.N1						SS1	H/H	73	35088	465	4.07
ASA_WSM_1PNPDE20081115_084219_000000912073_00465_35088_6225.N1						SS1	V/V	73	35088	465	4.07
ASA_WSM_1PNPDE20081115_100124_000000922073_00466_35089_6239.N1						SS1	H/H	73	35089	466	4.07
ASA_WSM_1PNPDE20081115_105900_000003122073_00466_35089_6298.N1						SS1	H/H	73	35089	466	4.07
ASA_WSM_1PNPDE20081115_113702_000001022073_00467_35090_6295.N1						SS1	H/H	73	35090	467	4.07
ASA_WSM_1PNPDE20081115_120955_000001352073_00467_35090_6300.N1						SS1	V/V	73	35090	467	4.07
ASA_WSM_1PNPDE20081115_121541_000000612073_00467_35090_6293.N1						SS1	H/H	73	35090	467	4.07
ASA_WSM_1PNPDE20081115_133156_000000922073_00468_35091_6329.N1						SS1	H/H	73	35091	468	4.07
ASA_WSM_1PNPDE20081115_151040_000000922073_00469_35092_6333.N1						SS1	H/H	73	35092	469	4.07
ASA_WSM_1PNPDE20081115_151649_000000672073_00469_35092_6327.N1						SS1	V/V	73	35092	469	4.07
ASA_WSM_1PNPDE20081115_162815_000000612073_00470_35093_6337.N1						SS1	H/H	73	35093	470	4.07
ASA_WSM_1PNPDE20081115_163011_000001842073_00470_35093_6347.N1						SS1	H/H	73	35093	470	4.07
ASA_WSM_1PNPDE20081115_164625_000002142073_00470_35093_6395.N1						SS1	H/H	73	35093	470	4.07
ASA_WSM_1PNPDE20081115_165118_000000182073_00470_35093_6359.N1						SS1	V/V	73	35093	470	4.07
ASA_WSM_1PNPDE20081115_165208_000001522073_00470_35093_6397.N1						SS1	H/H	73	35093	470	4.07
ASA_WSM_1PNPDE20081115_182629_000001772073_00471_35094_6399.N1						SS1	H/H	73	35094	471	4.07
ASA_WSM_1PNPDE20081115_183130_000003302073_00471_35094_6433.N1						SS1	V/V	73	35094	471	4.07
ASA_WSM_1PNPDE20081115_200616_000000972073_00472_35095_6544.N1						SS1	H/H	73	35095	472	4.07
ASA_WSM_1PNPDE20081115_201151_000002142073_00472_35095_6559.N1						SS1	V/V	73	35095	472	4.07
ASA_WSM_1PNPDE20081115_210948_000001342073_00472_35095_6569.N1						SS1	V/V	73	35095	472	4.07
ASA_WSM_1PNPDE20081115_211257_000000862073_00472_35095_6570.N1						SS1	V/V	73	35095	472	4.07
ASA_WSM_1PNPDE20081115_233121_000000732073_00474_35097_6729.N1						SS1	H/H	73	35097	474	4.07
ASA_WSM_1PNPDE20081115_233255_000001342073_00474_35097_7003.N1						SS1	H/H	73	35097	474	4.07
ASA_WSM_1PNPDE20081115_233604_000001842073_00474_35097_7004.N1						SS1	H/H	73	35097	474	4.07


Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WVS_1PNPDE20081115_000944_000010642073_00460_35083_5666.N1						IS2	V/V	73	35083	460	4.07
ASA_WVS_1PNPDE20081115_003358_000004202073_00460_35083_5659.N1						IS2	V/V	73	35083	460	4.07
ASA_WVS_1PNPDE20081115_005749_000003002073_00460_35083_5676.N1						IS2	V/V	73	35083	460	4.07
ASA_WVS_1PNPDE20081115_010204_000003452073_00460_35083_5797.N1						IS2	V/V	73	35083	460	4.07
ASA_WVS_1PNPDE20081115_011439_000008242073_00460_35083_5804.N1						IS2	V/V	73	35083	460	4.07
ASA_WVS_1PNPDE20081115_015926_000012142073_00461_35084_5807.N1						IS2	V/V	73	35084	461	4.07
ASA_WVS_1PNPDE20081115_021910_000001502073_00461_35084_5915.N1						IS2	V/V	73	35084	461	4.07
ASA_WVS_1PNPDE20081115_015926_000012142073_00461_35084_5807.N1						IS1	V/V	73	35084	461	4.07
ASA_WVS_1PNPDE20081115_023825_000003152073_00461_35084_5946.N1						IS2	V/V	73	35084	461	4.07
ASA_WVS_1PNPDK20081115_071921_000002252073_00464_35087_5618.N1						IS2	V/V	73	35087	464	4.07
ASA_WVS_1PNPDK20081115_074013_000018892073_00464_35087_5632.N1						IS2	V/V	73	35087	464	4.07
ASA_WVS_1PNPDK20081115_092306_000018742073_00465_35088_5722.N1						IS2	V/V	73	35088	465	4.07
ASA_WVS_1PNPDK20081115_102702_000010492073_00466_35089_5930.N1						IS2	V/V	73	35089	466	4.07
ASA_WVS_1PNPDK20081115_110410_000018142073_00466_35089_5995.N1						IS2	V/V	73	35089	466	4.07
ASA_WVS_1PNPDK20081115_115113_000010792073_00467_35090_5921.N1						IS2	V/V	73	35090	467	4.07
ASA_WVS_1PNPDK20081115_121638_000005102073_00467_35090_5911.N1						IS2	V/V	73	35090	467	4.07
ASA_WVS_1PNPDK20081115_124200_000003302073_00467_35090_5893.N1						IS2	V/V	73	35090	467	4.07
ASA_WVS_1PNPDK20081115_125601_000008202073_00467_35090_5898.N1						IS2	V/V	73	35090	467	4.07
ASA_WVS_1PNPDK20081115_133326_000007792073_00468_35091_6122.N1						IS2	V/V	73	35091	468	4.07
ASA_WVS_1PNPDK20081115_140352_000001202073_00468_35091_6125.N1						IS2	V/V	73	35091	468	4.07
ASA_WVS_1PNPDK20081115_142236_000003902073_00468_35091_6130.N1						IS2	V/V	73	35091	468	4.07
ASA_WVS_1PNPDK20081115_143353_000005842073_00468_35091_6137.N1						IS2	V/V	73	35091	468	4.07
ASA_WVS_1PNPDK20081115_152306_000001192073_00469_35092_6276.N1						IS2	V/V	73	35092	469	4.07
ASA_WVS_1PNPDK20081115_152731_000011392073_00469_35092_6289.N1						IS2	V/V	73	35092	469	4.07
ASA_WVS_1PNPDK20081115_160312_000012742073_00469_35092_6303.N1						IS2	V/V	73	35092	469	4.07
ASA_WVS_1PNPDK20081115_170458_000013192073_00470_35093_6429.N1						IS2	V/V	73	35093	470	4.07
ASA_WVS_1PNPDK20081115_174348_000013042073_00470_35093_6443.N1						IS2	V/V	73	35093	470	4.07
ASA_WVS_1PNPDK20081115_183837_000017392073_00471_35094_6564.N1						IS2	V/V	73	35094	471	4.07
ASA_WVS_1PNPDK20081115_192424_000007202073_00471_35094_6572.N1						IS2	V/V	73	35094	471	4.07
ASA_WVS_1PNPDE20081115_201524_000005842073_00472_35095_6794.N1						IS2	V/V	73	35095	472	4.07
ASA_WVS_1PNPDE20081115_202651_000012892073_00472_35095_6445.N1						IS2	V/V	73	35095	472	4.07
ASA_WVS_1PNPDE20081115_210500_000000152073_00472_35095_6448.N1						IS2	V/V	73	35095	472	4.07
ASA_WVS_1PNPDE20081115_210500_000002402073_00472_35095_7014.N1						IS2	V/V	73	35095	472	4.07
ASA_WVS_1PNPDE20081115_215821_000018292073_00473_35096_6817.N1						IS2	V/V	73	35096	473	4.07
ASA_WVS_1PNPDE20081115_225136_000007192073_00473_35096_6996.N1						IS2	V/V	73	35096	473	4.07












































































15-Nov




15-Nov




15-Nov












15-Nov




15-Nov




15-Nov



15-Nov



15-Nov



15-Nov

