

Analysis from 04-APR-2009 00:00:00 to 04-APR-2009 23:59:59. Page generated on 05-APR-2009 07:42:16.  
View log file: ASAR\_Daily\_Report\_20090405\_0730.log. For any anomalies please contact [mtranfaglia@serco.it](mailto:mtranfaglia@serco.it), [Emma.Griffiths@vega.co.uk](mailto:Emma.Griffiths@vega.co.uk).

This report is automatically generated every day, every 2 hours. No comments are provided on the results.

## SUMMARY

1. DATA SUMMARY
  - 1.1 Summary tables
  - 1.2 Lists of products used
2. AUXILIARY FILES ANALYSIS
  - 2.1 IECF operational ADFs list
  - 2.2 Products with wrong ADFs
3. MODULE STEPPING PRODUCTS ANALYSIS
  - 3.1 V/V polarisation
  - 3.2 H/H polarisation
4. CALIBRATION PULSES ANALYSIS
  - 4.1 Analysis for WVS IS2 V/V
    - 4.1.1 Temporal Evolution Analysis for WVS IS2 V/V
    - 4.1.2 All Rows Analysis for WVS IS2 V/V
  - 4.2 Analysis for GM1 SS3 H/H
    - 4.2.1 Temporal Evolution Analysis for GM1 SS3 H/H
    - 4.2.2 All Rows Analysis for GM1 SS3 H/H
5. DOPPLER ANALYSIS
  - 5.1 Analysis for WVS IS2 V/V
    - 5.1.1 Doppler MAP Analysis for WVS IS2 V/V
    - 5.1.2 Doppler ANX Analysis for WVS IS2 V/V
  - 5.2 Analysis for GM1 SS1 H/H
    - 5.2.1 Doppler MAP Analysis for GM1 SS1 H/H
    - 5.2.2 Doppler ANX Analysis for GM1 SS1 H/H
  - 5.3 Doppler JUMPS Analysis for WSM
6. CHIRP ANALYSIS
  - 6.1 Analysis for WSM SS1 H/H
    - 6.1.1 ScaleFactor
  - 6.2 Analysis for WSM SS1 V/V
    - 6.2.1 ScaleFactor
7. RAW DATA ANALYSIS
  - 7.1 Analysis for WVS
  - 7.2 Analysis for IMM
8. TELEMETRY ANALYSIS
  - 8.1 Number of Missing Lines
  - 8.2 Number of Gaps

---

## 1 - DATA SUMMARY

### 1.1 - Summary tables

[ [BACK TO MENU](#) ]

WVS				GM1				APM				IMM				WSM				MS			
Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Time	Pol	Modules
PDE	IS1	V/V	3	PDE	WS	H/H	42	PDE	IS1	H/H	1	PDE	IS1	V/V	1	PDE	WS	H/H	15	PDE	2009-04-04 20:48:53	V	320
PDE	IS2	V/V	25	PDK	WS	H/H	37	PDE	IS2	H/H	1	PDE	IS2	***	2	PDE	WS	V/V	17				
PDK	IS2	V/V	22					PDE	IS6	H/V	1	PDE	IS2	H/H	16								
												PDE	IS2	V/V	15								
												PDE	IS3	H/H	1								
												PDE	IS5	***	1								
												PDE	IS5	H/H	3								
												PDE	IS6	H/H	1								
												PDE	IS6	V/V	1								
												PDE	IS7	H/H	2								
												PDK	IS2	H/H	3								
												PDK	IS2	V/V	3								
												PDK	IS3	H/H	2								
												PDK	IS7	V/V	1								

## 1.2 - Lists of products used

[ [BACK TO MENU](#) ]

[[TXT](#)] [[XLS](#)] [List\\_WVS\\_products\\_used](#)  
 [[TXT](#)] [[XLS](#)] [List\\_GM1\\_products\\_used](#)  
 [[TXT](#)] [[XLS](#)] [List\\_APM\\_products\\_used](#)  
 [[TXT](#)] [[XLS](#)] [List\\_IMM\\_products\\_used](#)  
 [[TXT](#)] [[XLS](#)] [List\\_WSM\\_products\\_used](#)  
 [[TXT](#)] [[XLS](#)] [List\\_MS\\_products\\_used](#)

## 2 - AUXILIARY FILES ANALYSIS

### 2.1 - IECF operational ADFs list

[ [BACK TO MENU](#) ]

ADFs disseminated for ASAR
ASA_CON_AXVIEC20081215_141339_20070204_165113_20091231_000000
ASA_INS_AXVIEC20081215_140905_20070307_060000_20091231_000000
ASA_XCH_AXVIEC20081215_143642_20020301_000000_20091231_000000
ASA_XCA_AXVIEC20090311_104501_20080801_000000_20091231_235959

### 2.2 - Products with wrong ADFs

[ [BACK TO MENU](#) ]

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
WVS	0	0	0	0
GM1	0	0	0	0
APM	0	0	0	0
IMM	0	0	0	0

WSM	0	0	0	0
-----	---	---	---	---

- [TXT] [XLS] Check\_ADFs\_WVS
- [TXT] [XLS] Check\_ADFs\_GM1
- [TXT] [XLS] Check\_ADFs\_APM
- [TXT] [XLS] Check\_ADFs\_IMM
- [TXT] [XLS] Check\_ADFs\_WSM

### 3 - MODULE STEPPING PRODUCTS ANALYSIS






### 3.2 - H/H polarisation


[ [BACK TO MENU](#) ]

SECOND FIXED REFERENCE	PREVIOUS PRODUCT REFERENCE
After antenna maintenance (2005-09-22/23)	Previous product in the same polarisation

Reference: 2005-09-22 06:26:51 H RxGain  
 Test : 2009-04-03 14:38:07 H




Reference: 2009-04-01 07:18:22 H RxGain  
 Test : 2009-04-03 14:38:07 H






Reference: 2005-09-22 06:26:51 H RxPhase  
 Test : 2009-04-03 14:38:07 H



Reference: 2009-04-01 07:18:22 H RxPhase  
 Test : 2009-04-03 14:38:07 H





## 4 - CALIBRATION PULSES ANALYSIS

### 4.1 - Analysis for WVS IS2 V/V


#### 4.1.1 - Temporal Evolution Analysis for WVS IS2 V/V

[ BACK TO MENU ]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Calibration pulses for WVS IS2 V/V




Transmit power (P1 - P1a) for WVS IS2 V/V



#### 4.1.2 - All Rows Analysis for WVS IS2 V/V

[ [BACK TO MENU](#) ]





## 4.2 - Analysis for GM1 SS3 H/H

### 4.2.1 - Temporal Evolution Analysis for GM1 SS3 H/H


[ BACK TO MENU ]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]



Calibration pulses for GM1 SS3 H/H




Transmit power (P1 - P1a) for GM1 SS3 H/H



4.2.2 - All Rows Analysis for GM1 SS3 H/H

[ [BACK TO MENU](#) ]






## 5 - DOPPLER ANALYSIS

### 5.1 - Analysis for WVS IS2 V/V

#### 5.1.1 - Doppler MAP Analysis for WVS IS2 V/V

[ [BACK TO MENU](#) ]






### 5.1.2 - Doppler ANX Analysis for WVS IS2 V/V

[ [BACK TO MENU](#) ]






## 5.2 - Analysis for GM1 SS1 H/H

### 5.2.1 - Doppler MAP Analysis for GM1 SS1 H/H

[ [BACK TO MENU](#) ]






### 5.2.2 - Doppler ANX Analysis for GM1 SS1 H/H


[ [BACK TO MENU](#) ]






### 5.3 - Doppler JUMPS Analysis for WSM

[ [BACK TO MENU](#) ]







## 6 - CHIRP ANALYSIS

### 6.1 - Analysis for WSM SS1 H/H

#### 6.1.1 - ScaleFactor

[ [BACK TO MENU](#) ]







## 6.2 - Analysis for WSM SS1 V/V

### 6.2.1 - ScaleFactor

[ [BACK TO MENU](#) ]






## 7 - RAW DATA ANALYSIS

### 7.1 - Analysis for WVS

[ [BACK TO MENU](#) ]

--	--	--







Channel	Statistics	DSS-B
MEAN I	mean	0.000533964
	stdev	1.77717e-07
MEAN Q	mean	0.000531247
	stdev	2.15837e-07
Channel	Statistics	DSS-B
STDEV I	mean	0.135927
	stdev	0.00108667
STDEV Q	mean	0.136306
	stdev	0.00110690

## 7.2 - Analysis for IMM

[ [BACK TO MENU](#) ]






## 8 - TELEMETRY ANALYSIS

Processing Center	Product	Gaps	Missing lines
PDK	ASA_GM1_1PNPDK20090404_150244_000000902077_00469_37096_0739.N1	0	37

### 8.1 - Number of Missing lines


[ [BACK TO MENU](#) ]





## 8.2 - Number of Gaps

[\[ BACK TO MENU \]](#)



#####  
ASAR DAILY REPORT for 090404  
#####

MODE: DAILY  
ANALYSIS: ALL  
DATE: YESTERDAY

Analysis will be performed from 2009-04-04 00:00:00 to 2009-04-04 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/090404/

DATA SUMMARY

#####  
Summary will be performed from 2009-04-04 00:00:00 to 2009-04-04 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/090404/DATA\_SUMMARY

Creating directory ./RESULTS/DAILY/090404/DATA\_SUMMARY...  
Writing file ./RESULTS/DAILY/090404/DATA\_SUMMARY/Data\_summary.html...

\*\*\*\*\*  
Getting WVS products list from 2009-04-04 00:00:00 to 2009-04-04 23:59:59...  
Writing file ./RESULTS/DAILY/090404/DATA\_SUMMARY/List\_WVS\_products\_used.xls...  
Writing file ./RESULTS/DAILY/090404/DATA\_SUMMARY/List\_WVS\_products\_used.txt...

\*\*\*\*\*  
Getting GM1 products list from 2009-04-04 00:00:00 to 2009-04-04 23:59:59...  
Writing file ./RESULTS/DAILY/090404/DATA\_SUMMARY/List\_GM1\_products\_used.xls...  
Writing file ./RESULTS/DAILY/090404/DATA\_SUMMARY/List\_GM1\_products\_used.txt...

\*\*\*\*\*  
Getting APM products list from 2009-04-04 00:00:00 to 2009-04-04 23:59:59...  
Writing file ./RESULTS/DAILY/090404/DATA\_SUMMARY/List\_APM\_products\_used.xls...  
Writing file ./RESULTS/DAILY/090404/DATA\_SUMMARY/List\_APM\_products\_used.txt...

\*\*\*\*\*  
Getting IMM products list from 2009-04-04 00:00:00 to 2009-04-04 23:59:59...  
Writing file ./RESULTS/DAILY/090404/DATA\_SUMMARY/List\_IMM\_products\_used.xls...  
Writing file ./RESULTS/DAILY/090404/DATA\_SUMMARY/List\_IMM\_products\_used.txt...

\*\*\*\*\*  
Getting WSM products list from 2009-04-04 00:00:00 to 2009-04-04 23:59:59...  
Writing file ./RESULTS/DAILY/090404/DATA\_SUMMARY/List\_WSM\_products\_used.xls...  
Writing file ./RESULTS/DAILY/090404/DATA\_SUMMARY/List\_WSM\_products\_used.txt...

\*\*\*\*\*  
Getting MS products list from 2009-04-04 00:00:00 to 2009-04-04 23:59:59...  
Writing file ./RESULTS/DAILY/090404/DATA\_SUMMARY/List\_MS\_products\_used.xls...  
Writing file ./RESULTS/DAILY/090404/DATA\_SUMMARY/List\_MS\_products\_used.txt...

DATA SUMMARY completed  
#####

AUXILIARY FILES ANALYSIS

#####  
Analysis will be performed from 2009-04-04 00:00:00 to 2009-04-04 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/090404/AUXILIARY

Creating directory ./RESULTS/DAILY/090404/AUXILIARY...

\*\*\*\*\*  
Looking for the IECF operational ADFs list...



Found list 20090404\_030001\_current\_3\_IECF\_ADFs.txt...  
Extracting ADFs...

ASA\_CON\_AXVIEC20081215\_141339\_20070204\_165113\_20091231\_000000  
ASA\_INS\_AXVIEC20081215\_140905\_20070307\_060000\_20091231\_000000  
ASA\_XCH\_AXVIEC20081215\_143642\_20020301\_000000\_20091231\_000000  
ASA\_XCA\_AXVIEC20090311\_104501\_20080801\_000000\_20091231\_235959

Writing file ./RESULTS/DAILY/090404/AUXILIARY/ASAR\_ADFs\_IECF\_List3.html...  
Writing file ./RESULTS/DAILY/090404/AUXILIARY/Auxiliary\_files\_summary.html...

\*\*\*\*\*

Analysing WVS products...

Writing file ./RESULTS/DAILY/090404/AUXILIARY/Check\_ADFs\_WVS.xls...  
Writing file ./RESULTS/DAILY/090404/AUXILIARY/Check\_ADFs\_WVS.txt...

ASA_WVS_1PNPDE20090404_000944_000010642077_00460_37087_0952.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090404_003358_000004202077_00460_37087_0962.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090404_005748_000004052077_00460_37087_0965.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090404_010348_000002402077_00460_37087_1085.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090404_011439_000007342077_00460_37087_1090.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090404_015925_000013342077_00461_37088_1102.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090404_023824_000003152077_00461_37088_1241.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090404_025840_000003142077_00462_37089_1232.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090404_034140_000008392077_00462_37089_1229.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090404_035525_000001802077_00462_37089_1442.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090404_041900_000012292077_00462_37089_1437.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090404_052052_000004792077_00463_37090_1432.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090404_053101_000003752077_00463_37090_1429.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090404_053646_000003602077_00463_37090_1574.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090404_055936_000018892077_00463_37090_1621.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090404_201458_000006142077_00472_37099_1938.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090404_202650_000012892077_00472_37099_1957.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090404_210459_000000292077_00472_37099_1952.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090404_210459_000002402077_00472_37099_2075.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090404_215419_000001502077_00473_37100_2086.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090404_215821_000018292077_00473_37100_2091.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090404_224535_000003142077_00473_37100_2099.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090404_225005_000008092077_00473_37100_2220.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090404_230911_000006142077_00474_37101_2225.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090404_233840_000010342077_00474_37101_2231.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090404_071919_000002252077_00464_37091_0131.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090404_074012_000019492077_00464_37091_0156.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090404_085055_000007792077_00465_37092_0212.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090404_092048_000020092077_00465_37092_0225.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090404_102720_000010342077_00466_37093_0339.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090404_110124_000019792077_00466_37093_0406.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090404_115245_000009742077_00467_37094_0470.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090404_121539_000004202077_00467_37094_0475.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090404_124200_000002852077_00467_37094_0478.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090404_125601_000008202077_00467_37094_0483.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090404_133706_000005542077_00468_37095_0609.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090404_140351_000001202077_00468_37095_0612.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090404_142236_000003902077_00468_37095_0619.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090404_143353_000006592077_00468_37095_0629.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090404_152306_000001192077_00469_37096_0744.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090404_152731_000011392077_00469_37096_0751.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090404_160312_000012742077_00469_37096_0763.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090404_170458_000013192077_00470_37097_0895.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090404_174348_000013042077_00470_37097_0909.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090404_183837_000017392077_00471_37098_1027.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090404_192424_000004802077_00471_37098_1020.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090404_193428_000001042077_00471_37098_1032.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

\*\*\*\*\*

Analysing GM1 products...

Writing file ./RESULTS/DAILY/090404/AUXILIARY/Check\_ADFs\_GM1.xls...

Writing file ./RESULTS/DAILY/090404/AUXILIARY/Check\_ADFs\_GM1.txt...

ASA_GM1_1PNPDE20090404_002811_000003442077_00460_37087_0954.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090404_005409_000002172077_00460_37087_0967.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090404_010830_000003622077_00460_37087_1087.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090404_013832_000009122077_00461_37088_1092.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090404_022220_000001692077_00461_37088_1099.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090404_022403_000002352077_00461_37088_1249.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090404_023345_00000902077_00461_37088_1245.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090404_023706_00000782077_00461_37088_1243.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090404_024648_000003562077_00461_37088_1247.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090404_025407_000002712077_00461_37088_1236.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090404_030437_00000962077_00462_37089_1234.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090404_030857_000008632077_00462_37089_1238.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090404_032601_000005072077_00462_37089_1251.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090404_040256_000009302077_00462_37089_1456.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090404_044007_000006822077_00463_37090_1439.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090404_045247_000006702077_00463_37090_1434.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090404_051210_00000902077_00463_37090_1426.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090404_051711_000002172077_00463_37090_1424.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090404_054332_00000962077_00463_37090_1569.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090404_054743_000003502077_00463_37090_1571.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090404_055740_000001142077_00463_37090_1580.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090404_063143_000006642077_00464_37091_1610.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090404_065045_000001142077_00464_37091_1594.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090404_065507_000001692077_00464_37091_1592.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090404_065901_000002592077_00464_37091_1596.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090404_070449_000003622077_00464_37091_1590.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090404_071217_000001322077_00464_37091_1617.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090404_200443_000002832077_00472_37099_1935.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090404_201116_000002172077_00472_37099_1940.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090404_205011_000004832077_00472_37099_1942.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090404_210307_000001082077_00472_37099_1954.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090404_211422_000007852077_00472_37099_2079.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090404_214005_000001632077_00473_37100_2077.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090404_214620_000003322077_00473_37100_2088.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090404_222931_000000842077_00473_37100_2083.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090404_223428_00000902077_00473_37100_2081.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090404_224306_000001442077_00473_37100_2101.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090404_230426_000000842077_00474_37101_2217.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090404_230731_000009062077_00474_37101_2222.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090404_232741_000006582077_00474_37101_2228.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090404_235643_000004042077_00474_37101_2233.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090404_072348_000009842077_00464_37091_0176.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090404_081327_000007372077_00465_37092_0164.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090404_084309_000004652077_00465_37092_0209.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090404_090444_000009302077_00465_37092_0214.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090404_095506_000005862077_00466_37093_0221.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090404_101431_00000722077_00466_37093_0336.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090404_105803_000001992077_00466_37093_0341.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090404_113502_000006102077_00467_37094_0343.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090404_123025_000006942077_00467_37094_0472.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090404_124929_000003922077_00467_37094_0480.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090404_131018_000008512077_00468_37095_0550.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090404_134711_000002412077_00468_37095_0602.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090404_135239_000003682077_00468_37095_0604.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090404_135855_000002952077_00468_37095_0606.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090404_140631_000009302077_00468_37095_0616.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090404_142949_000002412077_00468_37095_0614.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090404_144536_000000842077_00469_37096_0621.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090404_145132_000004102077_00469_37096_0631.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090404_150244_00000902077_00469_37096_0739.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090404_151142_000003022077_00469_37096_0741.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

ASA_GM1_1PNPDK20090404_151804_000003022077_00469_37096_0746.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090404_152552_000000962077_00469_37096_0748.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090404_154707_000009302077_00469_37096_0753.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090404_162510_000001082077_00470_37097_0755.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090404_163333_000002112077_00470_37097_0765.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090404_164346_000001022077_00470_37097_0888.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090404_165639_000004952077_00470_37097_0892.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090404_172743_000001992077_00470_37097_0890.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090404_173536_000004892077_00470_37097_0897.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090404_180618_000000722077_00471_37098_0899.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090404_180900_000002832077_00471_37098_0906.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090404_182634_000007182077_00471_37098_1013.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090404_190819_000001692077_00471_37098_1017.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090404_191542_000002652077_00471_37098_1015.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090404_192257_000000842077_00471_37098_1022.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090404_193811_000005192077_00471_37098_1024.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090404_195536_000000842077_00472_37099_1029.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

\*\*\*\*\*

Analysing APM products...

Writing file ./RESULTS/DAILY/090404/AUXILIARY/Check\_ADFs\_APM.xls...

Writing file ./RESULTS/DAILY/090404/AUXILIARY/Check\_ADFs\_APM.txt...

ASA_APM_1PNPDE20090404_033429_000000602077_00462_37089_1221.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20090404_065758_000000432077_00464_37091_1555.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20090404_122311_000001032077_00467_37094_1806.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

\*\*\*\*\*

Analysing IMM products...

Writing file ./RESULTS/DAILY/090404/AUXILIARY/Check\_ADFs\_IMM.xls...

Writing file ./RESULTS/DAILY/090404/AUXILIARY/Check\_ADFs\_IMM.txt...

ASA_IMM_1PNPDE20090404_004236_000000822077_00460_37087_1368.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090404_004340_000000182077_00460_37087_0939.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090404_004436_000005622077_00460_37087_1175.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090404_022757_000003372077_00461_37088_1209.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090404_023512_000001042077_00461_37088_1320.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090404_025240_000000762077_00461_37088_1366.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090404_025342_000000142077_00461_37088_1260.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090404_033550_000001832077_00462_37089_1364.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090404_033550_000003432077_00462_37089_1370.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090404_045129_000000672077_00463_37090_1516.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090404_050836_000002042077_00463_37090_1529.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090404_051338_000000632077_00463_37090_1380.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090404_051338_000002022077_00463_37090_1535.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090404_051641_000000192077_00463_37090_1386.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090404_054510_000001422077_00463_37090_1518.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090404_055330_000002392077_00463_37090_1586.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090404_070316_000000822077_00464_37091_1588.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090404_071050_000000622077_00464_37091_1582.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090404_071050_000000752077_00464_37091_1671.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090404_101717_000000372077_00466_37093_1712.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090404_104612_000001632077_00466_37093_1762.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090404_104935_000002022077_00466_37093_1756.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090404_105038_000000592077_00466_37093_1748.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090404_105230_000000322077_00466_37093_1787.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090404_105238_000000192077_00466_37093_1752.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090404_135111_000000772077_00468_37095_1827.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090404_144701_000002612077_00469_37096_1843.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090404_164853_000000672077_00470_37097_1861.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090404_173103_000002612077_00470_37097_1899.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090404_180727_000000822077_00471_37098_1877.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

```
ASA_IMM_1PNPDE20090404_191109_000002622077_00471_37098_1933.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090404_192009_000001572077_00471_37098_1919.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090404_193259_000000832077_00471_37098_1921.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090404_193737_000002222077_00471_37098_1913.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090404_200927_000000982077_00472_37099_2033.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090404_202554_000000482077_00472_37099_1944.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090404_205812_000002852077_00472_37099_2045.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090404_213321_000000432077_00473_37100_2170.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090404_215150_000001422077_00473_37100_2188.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090404_215719_000000562077_00473_37100_2172.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090404_223055_000002002077_00473_37100_2193.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090404_223555_000004202077_00473_37100_2209.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090404_230548_000000922077_00474_37101_2346.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20090404_064957_000000372077_00464_37091_0112.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20090404_083019_000000502077_00465_37092_0178.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20090404_101320_000000602077_00466_37093_0299.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20090404_122837_000000972077_00467_37094_0571.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20090404_124719_000000682077_00467_37094_0569.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20090404_124841_000000352077_00467_37094_0567.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20090404_164228_000000662077_00470_37097_0854.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20090404_214248_000002022077_00473_37100_1159.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20090404_232204_000001232077_00474_37101_1237.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```

\*\*\*\*\*

Analysing WSM products...

Writing file ./RESULTS/DAILY/090404/AUXILIARY/Check\_ADFs\_WSM.xls...

Writing file ./RESULTS/DAILY/090404/AUXILIARY/Check\_ADFs\_WSM.txt...

```
ASA_WSM_1PNPDE20090404_012753_000001282077_00461_37088_1181.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090404_013116_000002512077_00461_37088_1326.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090404_013116_000004282077_00461_37088_1374.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090404_024513_000000922077_00461_37088_1352.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090404_030620_000001532077_00462_37089_1356.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090404_032327_000001352077_00462_37089_1354.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090404_050403_000001342077_00463_37090_1531.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090404_050403_000002692077_00463_37090_1553.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090404_050713_000000782077_00463_37090_1532.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090404_052931_000000922077_00463_37090_1537.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090404_065241_000001342077_00464_37091_1690.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090404_071432_000002872077_00464_37091_1701.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090404_101546_000000912077_00466_37093_1724.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090404_102053_000003732077_00466_37093_1765.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090404_102206_000003002077_00466_37093_1754.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090404_120949_000001342077_00467_37094_1802.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090404_120949_000003482077_00467_37094_1811.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090404_121258_000001592077_00467_37094_1803.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090404_122544_000001152077_00467_37094_1808.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090404_133154_000000912077_00468_37095_1839.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090404_151008_000000922077_00469_37096_1841.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090404_151649_000000672077_00469_37096_1821.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090404_162701_000000732077_00470_37097_1845.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090404_162701_000003732077_00470_37097_2072.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090404_162916_000000552077_00470_37097_1849.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090404_163213_000000612077_00470_37097_1855.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090404_165104_000001352077_00470_37097_1901.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090404_165104_000003302077_00470_37097_2057.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090404_165515_000000782077_00470_37097_1902.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090404_181346_000002072077_00471_37098_1905.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090404_210947_000002692077_00472_37099_2064.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090404_232444_000001712077_00474_37101_2371.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```

AUXILIARY FILES ANALYSIS completed

#####



MODULE STEPPING ANALYSIS

#####

Analysis will be performed from 2009-04-04 00:00:00 to 2009-04-04 23:59:59

Results will be exported to the directory: ./RESULTS/DAILY/090404/MODULE\_STEPPING

Creating directory ./RESULTS/DAILY/090404/MODULE\_STEPPING...

Creating directory ./RESULTS/DAILY/090404/MODULE\_STEPPING/FIRST\_REFERENCE...

Creating directory ./RESULTS/DAILY/090404/MODULE\_STEPPING/SECOND\_REFERENCE...

Creating directory ./RESULTS/DAILY/090404/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE...

Deleting old files...

\*\*\*\*\*  
\*\*\*\*\*

Creating images comparing with second reference...

Exporting results to the directory ../../RESULTS/DAILY/090404/MODULE\_STEPPING/SECOND\_REFERENCE...

Polarization: H

Reference product: ASA\_MS\_\_0PNPDK20050922\_062651\_00000152041\_00034\_18625\_0041.N1

Test product: ASA\_MS\_\_0PNPDK20090403\_143807\_00000162077\_00454\_37081\_0776.N1

H

H

../../RESULTS/DAILY/090404/MODULE\_STEPPING/SECOND\_REFERENCE/TGH\_20090403\_143807-20050922\_062651.png

../../RESULTS/DAILY/090404/MODULE\_STEPPING/SECOND\_REFERENCE/TPH\_20090403\_143807-20050922\_062651.png

../../RESULTS/DAILY/090404/MODULE\_STEPPING/SECOND\_REFERENCE/RGH\_20090403\_143807-20050922\_062651.png

../../RESULTS/DAILY/090404/MODULE\_STEPPING/SECOND\_REFERENCE/RPH\_20090403\_143807-20050922\_062651.png

Polarization: V

Reference product: ASA\_MS\_\_0PNPDK20050923\_055514\_00000152041\_00048\_18639\_0042.N1

Test product: ASA\_MS\_\_0PNPDE20090404\_204853\_00000162077\_00472\_37099\_0404.N1

V

V

../../RESULTS/DAILY/090404/MODULE\_STEPPING/SECOND\_REFERENCE/TGV\_20090404\_204853-20050923\_055514.png

../../RESULTS/DAILY/090404/MODULE\_STEPPING/SECOND\_REFERENCE/TPV\_20090404\_204853-20050923\_055514.png

../../RESULTS/DAILY/090404/MODULE\_STEPPING/SECOND\_REFERENCE/RGV\_20090404\_204853-20050923\_055514.png

../../RESULTS/DAILY/090404/MODULE\_STEPPING/SECOND\_REFERENCE/RPV\_20090404\_204853-20050923\_055514.png

\*\*\*\*\*  
\*\*\*\*\*

Creating images comparing with previous product reference...

Exporting results to the directory ../../RESULTS/DAILY/090404/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE...

Polarization: H

Reference product: ASA\_MS\_\_0PNPDK20090401\_071822\_00000162077\_00421\_37048\_0774.N1

Test product: ASA\_MS\_\_0PNPDK20090403\_143807\_00000162077\_00454\_37081\_0776.N1

H

H

../../RESULTS/DAILY/090404/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/TGH\_20090403\_143807-20090401\_071822.png

../../RESULTS/DAILY/090404/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/TPH\_20090403\_143807-20090401\_071822.png

../../RESULTS/DAILY/090404/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/RGH\_20090403\_143807-20090401\_071822.png

../../RESULTS/DAILY/090404/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/RPH\_20090403\_143807-20090401\_071822.png

Polarization: V

Reference product: ASA\_MS\_\_0PNPDK20090402\_100756\_00000162077\_00437\_37064\_0775.N1

Test product: ASA\_MS\_\_0PNPDE20090404\_204853\_00000162077\_00472\_37099\_0404.N1

V

V

../../RESULTS/DAILY/090404/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/TGV\_20090404\_204853-20090402\_100756.png

../../RESULTS/DAILY/090404/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/TPV\_20090404\_204853-20090402\_100756.png

../../RESULTS/DAILY/090404/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/RGV\_20090404\_204853-20090402\_100756.png

../../RESULTS/DAILY/090404/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/RPV\_20090404\_204853-20090402\_100756.png

MODULE\_STEPPING ANALYSIS completed

#####

CALIBRATION PULSES ANALYSIS

#####

Creating directory ./RESULTS/DAILY/090404/CALIBRATION\_PULSES...

\*\*\*\*\*  
\*\*\*\*\*

ALL ROWS Analysis will be performed from 2009-04-04 00:00:00 to 2009-04-04 23:59:59

Analysing products WVS IS2 V/V

Writing image ../../RESULTS/DAILY/090404//CALIBRATION\_PULSES/Calibration\_pulses\_all\_rows\_WVS\_IS2\_VV.png...

Analysing products GM1 SS3 H/H

Writing image ../../RESULTS/DAILY/090404//CALIBRATION\_PULSES/Calibration\_pulses\_all\_rows\_GM1\_SS3\_HH.png...

\*\*\*\*\*  
\*\*\*\*\*

TEMPORAL EVOLUTION Analysis will be performed from 2009-04-04 00:00:00 to 2009-04-04 23:59:59

Analysing products WVS IS2 V/V

Getting calibration pulses data for WVS IS2 V/V from 2009-04-04 00:00:00 to 2009-04-04 23:59:59. Rows: 1/5/9/13/17/21/25/29

Writing file ./RESULTS/DAILY/090404/CALIBRATION\_PULSES/Calibration\_pulses\_data\_WVS\_IS2\_VV\_2009-04-04\_1.dat...

Writing ../../RESULTS/DAILY/090404//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_WVS\_IS2\_VV\_1.png...

Writing ../../RESULTS/DAILY/090404//CALIBRATION\_PULSES/Transmit\_Power\_WVS\_IS2\_VV\_1.png...

Getting calibration pulses data for WVS IS2 V/V from 2009-04-04 00:00:00 to 2009-04-04 23:59:59. Rows: 2/6/10/14/18/22/26/30

Writing file ./RESULTS/DAILY/090404/CALIBRATION\_PULSES/Calibration\_pulses\_data\_WVS\_IS2\_VV\_2009-04-04\_2.dat...

Writing ../../RESULTS/DAILY/090404//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_WVS\_IS2\_VV\_2.png...

Writing ../../RESULTS/DAILY/090404//CALIBRATION\_PULSES/Transmit\_Power\_WVS\_IS2\_VV\_2.png...

Getting calibration pulses data for WVS IS2 V/V from 2009-04-04 00:00:00 to 2009-04-04 23:59:59. Rows: 3/7/11/15/19/23/27/31

Writing file ./RESULTS/DAILY/090404/CALIBRATION\_PULSES/Calibration\_pulses\_data\_WVS\_IS2\_VV\_2009-04-04\_3.dat...

Writing ../../RESULTS/DAILY/090404//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_WVS\_IS2\_VV\_3.png...

Writing ../../RESULTS/DAILY/090404//CALIBRATION\_PULSES/Transmit\_Power\_WVS\_IS2\_VV\_3.png...

Getting calibration pulses data for WVS IS2 V/V from 2009-04-04 00:00:00 to 2009-04-04 23:59:59. Rows: 4/8/12/16/20/24/28/32

Writing file ./RESULTS/DAILY/090404/CALIBRATION\_PULSES/Calibration\_pulses\_data\_WVS\_IS2\_VV\_2009-04-04\_4.dat...

Writing ../../RESULTS/DAILY/090404//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_WVS\_IS2\_VV\_4.png...

Writing ../../RESULTS/DAILY/090404//CALIBRATION\_PULSES/Transmit\_Power\_WVS\_IS2\_VV\_4.png...

Analysing products GM1 SS3 H/H

Getting calibration pulses data for GM1 SS3 H/H from 2009-04-04 00:00:00 to 2009-04-04 23:59:59. Rows: 1/5/9/13/17/21/25/29

Writing file ./RESULTS/DAILY/090404/CALIBRATION\_PULSES/Calibration\_pulses\_data\_GM1\_SS3\_HH\_2009-04-04\_1.dat...

Writing ../../RESULTS/DAILY/090404//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_GM1\_SS3\_HH\_1.png...

Writing ../../RESULTS/DAILY/090404//CALIBRATION\_PULSES/Transmit\_Power\_GM1\_SS3\_HH\_1.png...

Getting calibration pulses data for GM1 SS3 H/H from 2009-04-04 00:00:00 to 2009-04-04 23:59:59. Rows: 2/6/10/14/18/22/26/30

Writing file ./RESULTS/DAILY/090404/CALIBRATION\_PULSES/Calibration\_pulses\_data\_GM1\_SS3\_HH\_2009-04-04\_2.dat...

Writing ../../RESULTS/DAILY/090404//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_GM1\_SS3\_HH\_2.png...

Writing ../../RESULTS/DAILY/090404//CALIBRATION\_PULSES/Transmit\_Power\_GM1\_SS3\_HH\_2.png...

Getting calibration pulses data for GM1 SS3 H/H from 2009-04-04 00:00:00 to 2009-04-04 23:59:59. Rows: 3/7/11/15/19/23/27/31

Writing file ./RESULTS/DAILY/090404/CALIBRATION\_PULSES/Calibration\_pulses\_data\_GM1\_SS3\_HH\_2009-04-04\_3.dat...

Writing ../../RESULTS/DAILY/090404//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_GM1\_SS3\_HH\_3.png...

Writing ../../RESULTS/DAILY/090404//CALIBRATION\_PULSES/Transmit\_Power\_GM1\_SS3\_HH\_3.png...

Getting calibration pulses data for GM1 SS3 H/H from 2009-04-04 00:00:00 to 2009-04-04 23:59:59. Rows: 4/8/12/16/20/24/28/32

Writing file ./RESULTS/DAILY/090404/CALIBRATION\_PULSES/Calibration\_pulses\_data\_GM1\_SS3\_HH\_2009-04-04\_4.dat...  
Writing ../../RESULTS/DAILY/090404//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_GM1\_SS3\_HH\_4.png...  
Writing ../../RESULTS/DAILY/090404//CALIBRATION\_PULSES/Transmit\_Power\_GM1\_SS3\_HH\_4.png...

CALIBRATION PULSES ANALYSIS completed

#####

DOPPLER ANALYSIS

#####

Creating directory ./RESULTS/DAILY/090404/DOPPLER...

\*\*\*\*\*  
\*\*\*\*\*

DOPPLER ANX Analysis will be performed from 2009-04-04 00:00:00 to 2009-04-04 23:59:59

Analysing products WVS IS2 V/V

Getting doppler data for WVS IS2 V/V from 2009-04-04 00:00:00 to 2009-04-04 23:59:59...

Writing file ./RESULTS/DAILY/090404/DOPPLER/Doppler\_data\_WVS\_IS2\_VV\_2009-04-04.dat...

Running IDL program...

Writing file ../../RESULTS/DAILY/090404/DOPPLER/DOPPLER\_ANX\_WVS\_IS2\_VV.png...

Analysing products GM1 SS1 H/H

Getting doppler data for GM1 SS1 H/H from 2009-04-04 00:00:00 to 2009-04-04 23:59:59...

Writing file ./RESULTS/DAILY/090404/DOPPLER/Doppler\_data\_GM1\_SS1\_HH\_2009-04-04.dat...

Running IDL program...

Writing file ../../RESULTS/DAILY/090404/DOPPLER/DOPPLER\_ANX\_GM1\_SS1\_HH.png...

\*\*\*\*\*  
\*\*\*\*\*

DOPPLER JUMPS Analysis will be performed on WSM products from 2009-04-04 00:00:00 to 2009-04-04 23:59:59

Analysing by default products WSM

Getting doppler jumps data for WSM from 2009-04-04 00:00:00 to 2009-04-04 23:59:59...

Writing file ./RESULTS/DAILY/090404/DOPPLER/Doppler\_Jumps\_data\_WSM\_2009-04-04.dat...

Running IDL program...

Writing file ../../RESULTS/DAILY/090404/DOPPLER/DOPPLER\_JUMPS\_ANX\_WSM.png...

Writing file ../../RESULTS/DAILY/090404/DOPPLER/DOPPLER\_JUMPS\_Date\_WSM.png...

\*\*\*\*\*  
\*\*\*\*\*

DOPPLER MAP Analysis will be performed from 2009-04-04 00:00:00 to 2009-04-04 23:59:59

Analysing products WVS IS2 V/V

Loading predicted doppler values....

Phase: descending

Found data...

Computing mean error doppler estimated-predicted...

Mean error = -36.803277 Hz

Writing file ../../RESULTS/DAILY/090404//DOPPLER/DOPPLER\_Estimated-Predicted-MeanError\_WVS\_IS2\_VV\_desc.jpg...

Writing file ../../RESULTS/DAILY/090404//DOPPLER/DOPPLER\_Absolute\_WVS\_IS2\_VV\_desc.jpg...

\*\*\*\*\*

Loading predicted doppler values....

Phase: ascending

Found data...

Computing mean error doppler estimated-predicted...

Mean error = -30.325887 Hz

Writing file ../../RESULTS/DAILY/090404//DOPPLER/DOPPLER\_Estimated-Predicted-MeanError\_WVS\_IS2\_VV\_asc.jpg...

Writing file ../../RESULTS/DAILY/090404//DOPPLER/DOPPLER\_Absolute\_WVS\_IS2\_VV\_asc.jpg...

\*\*\*\*\*

Analysing products GM1 SS1 H/H  
Loading predicted doppler values....  
Phase: descending  
Found data...  
Computing mean error doppler estimated-predicted...  
Mean error = -20.166028 Hz  
Writing file ../././RESULTS/DAILY/090404//DOPPLER/DOPPLER\_Estimated-Predicted-MeanError\_GM1\_SS1\_HH\_desc.jpg...  
Writing file ../././RESULTS/DAILY/090404//DOPPLER/DOPPLER\_Absolute\_GM1\_SS1\_HH\_desc.jpg...

\*\*\*\*\*

Loading predicted doppler values....  
Phase: ascending  
Found data...  
Computing mean error doppler estimated-predicted...  
Mean error = -24.178726 Hz  
Writing file ../././RESULTS/DAILY/090404//DOPPLER/DOPPLER\_Estimated-Predicted-MeanError\_GM1\_SS1\_HH\_asc.jpg...  
Writing file ../././RESULTS/DAILY/090404//DOPPLER/DOPPLER\_Absolute\_GM1\_SS1\_HH\_asc.jpg...

\*\*\*\*\*

DOPPLER ANALYSIS completed  
#####

CHIRP ANALYSIS  
#####  
Creating directory ./RESULTS/DAILY/090404/CHIRP...

\*\*\*\*\*

CHIRP Analysis will be performed from 2009-04-04 00:00:00 to 2009-04-04 23:59:59

Analysing products WSM SS1 H/H  
\*\*\*\*\*  
Getting ScaleFactor data for WSM SS1 H/H from 2009-04-04 00:00:00 to 2009-04-04 23:59:59...  
Writing file ./RESULTS/DAILY/090404/CHIRP/ScaleFactor\_data\_WSM\_SS1\_HH\_2009-04-04.dat...  
Running IDL program...  
Writing file .././RESULTS/DAILY/090404/CHIRP/ScaleFactor\_ANX\_WSM\_SS1\_HH.png...  
Writing file .././RESULTS/DAILY/090404/CHIRP/ScaleFactor\_DATE\_WSM\_SS1\_HH.png...

Analysing products WSM SS1 V/V  
\*\*\*\*\*  
Getting ScaleFactor data for WSM SS1 V/V from 2009-04-04 00:00:00 to 2009-04-04 23:59:59...  
Writing file ./RESULTS/DAILY/090404/CHIRP/ScaleFactor\_data\_WSM\_SS1\_VV\_2009-04-04.dat...  
Running IDL program...  
Writing file .././RESULTS/DAILY/090404/CHIRP/ScaleFactor\_ANX\_WSM\_SS1\_VV.png...  
Writing file .././RESULTS/DAILY/090404/CHIRP/ScaleFactor\_DATE\_WSM\_SS1\_VV.png...

CHIRP ANALYSIS completed  
#####

RAW DATA ANALYSIS  
#####  
Analysis will be performed from 2009-04-04 00:00:00 to 2009-04-04 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/090404/RAW\_DATA

Creating directory ./RESULTS/DAILY/090404/RAW\_DATA...

\*\*\*\*\*

Getting raw data for WVS from 2009-04-04 00:00:00 to 2009-04-04 23:59:59...

Writing file ./RESULTS/DAILY/090404/RAW\_DATA/Raw\_data\_WVS\_2009-04-04.dat...

Running IDL program to create graphs...

Creating image ../RESULTS/DAILY/090404/RAW\_DATA/Raw\_data\_WVS\_input\_mean.png...

Creating image ../RESULTS/DAILY/090404/RAW\_DATA/Raw\_data\_WVS\_input\_stdev.png...

Creating image ../RESULTS/DAILY/090404/RAW\_DATA/Raw\_data\_WVS\_gain\_imbalance.png...

\*\*\*\*\*

Getting raw data for IMM from 2009-04-04 00:00:00 to 2009-04-04 23:59:59...

Writing file ./RESULTS/DAILY/090404/RAW\_DATA/Raw\_data\_IMM\_2009-04-04.dat...

Running IDL program to create graphs...

Creating image ../RESULTS/DAILY/090404/RAW\_DATA/Raw\_data\_IMM\_input\_mean.png...

Creating image ../RESULTS/DAILY/090404/RAW\_DATA/Raw\_data\_IMM\_input\_stdev.png...

Creating image ../RESULTS/DAILY/090404/RAW\_DATA/Raw\_data\_IMM\_gain\_imbalance.png...

RAW DATA ANALYSIS completed

#####

TELEMETRY ANALYSIS

#####

Analysis will be performed from 2009-04-04 00:00:00 to 2009-04-04 23:59:59

Results will be exported to the directory: ./RESULTS/DAILY/090404/TELEMETRY

Creating directory ./RESULTS/DAILY/090404/TELEMETRY...

Looking for gaps and missing lines in WVS products...

\*\*\*\*\*

Checking 25 products from PDE...

Checking 22 products from PDK...

Looking for gaps and missing lines in GM1 products...

\*\*\*\*\*

Checking 42 products from PDE...

Checking 37 products from PDK...

Found product..ASA\_GM1\_1PNPDK20090404\_150244\_00000902077\_00469\_37096\_0739.N1 / 0 gaps / 37 missing lines

Looking for gaps and missing lines in APM products...

\*\*\*\*\*

Checking 3 products from PDE...

No products from PDK...

Looking for gaps and missing lines in IMM products...

\*\*\*\*\*

Checking 43 products from PDE...

Checking 9 products from PDK...

Looking for gaps and missing lines in WSM products...

\*\*\*\*\*

Checking 32 products from PDE...

No products from PDK...

Creating graph of missing lines and gaps...

\*\*\*\*\*

Creating image: ./RESULTS/DAILY/090404/TELEMETRY/TELEMETRY\_Missing\_lines.png...

Creating image: ./RESULTS/DAILY/090404/TELEMETRY/TELEMETRY\_Gaps.png...

TELEMETRY ANALYSIS completed

#####

BROWSE PRODUCTS ANALYSIS

#####

Analysis will be performed on 2009-04-04

\*\*\*\*\*

Scanning directory /nas3/ENVISAT/ASAR//ASA\_GM\_BP...

Results will be exported to the directory: /nas3/ENVISAT/ASAR//ASA\_GM\_BP/JPG/20090404/

Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20090404\_200443\_000002832077\_00472\_37099\_1936.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20090404\_201116\_000002172077\_00472\_37099\_1941.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20090404\_205011\_000004832077\_00472\_37099\_1943.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20090404\_210307\_000001082077\_00472\_37099\_1955.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20090404\_211422\_000007852077\_00472\_37099\_2080.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20090404\_214005\_000001632077\_00473\_37100\_2078.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20090404\_214620\_000003322077\_00473\_37100\_2089.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20090404\_222931\_000000842077\_00473\_37100\_2084.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20090404\_223428\_000000902077\_00473\_37100\_2082.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20090404\_224306\_000001442077\_00473\_37100\_2102.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20090404\_230426\_000000842077\_00474\_37101\_2218.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20090404\_230731\_000000962077\_00474\_37101\_2223.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20090404\_232741\_000006582077\_00474\_37101\_2229.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_GM\_BP/ASA\_GM\_BPZPDE20090404\_235643\_000004042077\_00474\_37101\_2234.N1 ...

ANALYSIS COMPLETED: 14 GM browse products to see...

\*\*\*\*\*

\*\*\*\*\*

Scanning directory /nas3/ENVISAT/ASAR//ASA\_AP\_BP...

Results will be exported to the directory: /nas3/ENVISAT/ASAR//ASA\_AP\_BP/JPG/20090404/

Stripping browse product /nas3/ENVISAT/ASAR//ASA\_AP\_BP/ASA\_AP\_BPZPDE20090404\_122311\_000001032077\_00467\_37094\_1807.N1 ...

ANALYSIS COMPLETED: 1 AP browse products to see...

\*\*\*\*\*

\*\*\*\*\*

Scanning directory /nas3/ENVISAT/ASAR//ASA\_IM\_BP...

Results will be exported to the directory: /nas3/ENVISAT/ASAR//ASA\_IM\_BP/JPG/20090404/

Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20090404\_104612\_000001632077\_00466\_37093\_1763.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20090404\_104935\_000002022077\_00466\_37093\_1757.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20090404\_105038\_000000592077\_00466\_37093\_1749.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20090404\_105230\_000003222077\_00466\_37093\_1788.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20090404\_105238\_000000192077\_00466\_37093\_1753.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20090404\_135111\_000000772077\_00468\_37095\_1828.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20090404\_144701\_000002612077\_00469\_37096\_1844.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20090404\_164853\_000000672077\_00470\_37097\_1862.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20090404\_173103\_000002612077\_00470\_37097\_1900.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20090404\_180727\_000000822077\_00471\_37098\_1878.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20090404\_191109\_000002622077\_00471\_37098\_1934.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20090404\_192009\_000001572077\_00471\_37098\_1920.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20090404\_193259\_000000832077\_00471\_37098\_1922.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20090404\_193737\_000000222077\_00471\_37098\_1914.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20090404\_200927\_000000982077\_00472\_37099\_2034.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20090404\_202554\_000000482077\_00472\_37099\_1945.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20090404\_205812\_000002852077\_00472\_37099\_2046.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20090404\_213321\_000000432077\_00473\_37100\_2171.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20090404\_215150\_000001422077\_00473\_37100\_2189.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20090404\_215719\_000000562077\_00473\_37100\_2173.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20090404\_223055\_000002002077\_00473\_37100\_2194.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20090404\_223555\_000004202077\_00473\_37100\_2210.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_IM\_BP/ASA\_IM\_BPZPDE20090404\_230548\_000000922077\_00474\_37101\_2347.N1 ...

ANALYSIS COMPLETED: 23 IM browse products to see...

\*\*\*\*\*

\*\*\*\*\*

Scanning directory /nas3/ENVISAT/ASAR//ASA\_WS\_\_BP...

Results will be exported to the directory: /nas3/ENVISAT/ASAR//ASA\_WS\_\_BP/JPG/20090404/

Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_\_BP/ASA\_WS\_\_BPZPDE20090404\_101546\_000000912077\_00466\_37093\_1725.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_\_BP/ASA\_WS\_\_BPZPDE20090404\_102053\_000003732077\_00466\_37093\_1766.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_\_BP/ASA\_WS\_\_BPZPDE20090404\_102206\_000003002077\_00466\_37093\_1755.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_\_BP/ASA\_WS\_\_BPZPDE20090404\_120949\_000001342077\_00467\_37094\_1804.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_\_BP/ASA\_WS\_\_BPZPDE20090404\_120949\_000003482077\_00467\_37094\_1812.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_\_BP/ASA\_WS\_\_BPZPDE20090404\_121258\_000001592077\_00467\_37094\_1805.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_\_BP/ASA\_WS\_\_BPZPDE20090404\_122544\_000001152077\_00467\_37094\_1809.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_\_BP/ASA\_WS\_\_BPZPDE20090404\_133154\_000000912077\_00468\_37095\_1840.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_\_BP/ASA\_WS\_\_BPZPDE20090404\_151008\_000000922077\_00469\_37096\_1842.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_\_BP/ASA\_WS\_\_BPZPDE20090404\_151649\_000000672077\_00469\_37096\_1822.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_\_BP/ASA\_WS\_\_BPZPDE20090404\_162701\_000000732077\_00470\_37097\_1846.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_\_BP/ASA\_WS\_\_BPZPDE20090404\_162701\_000003732077\_00470\_37097\_2073.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_\_BP/ASA\_WS\_\_BPZPDE20090404\_162916\_000000552077\_00470\_37097\_1850.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_\_BP/ASA\_WS\_\_BPZPDE20090404\_163213\_000000612077\_00470\_37097\_1856.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_\_BP/ASA\_WS\_\_BPZPDE20090404\_165104\_000001352077\_00470\_37097\_1903.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_\_BP/ASA\_WS\_\_BPZPDE20090404\_165104\_000003302077\_00470\_37097\_2058.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_\_BP/ASA\_WS\_\_BPZPDE20090404\_165515\_000000782077\_00470\_37097\_1904.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_\_BP/ASA\_WS\_\_BPZPDE20090404\_181346\_000002072077\_00471\_37098\_1906.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_\_BP/ASA\_WS\_\_BPZPDE20090404\_210947\_000002692077\_00472\_37099\_2065.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_\_BP/ASA\_WS\_\_BPZPDE20090404\_232444\_000001712077\_00474\_37101\_2372.N1 ...  
Stripping browse product /nas3/ENVISAT/ASAR//ASA\_WS\_\_BP/ASA\_WS\_\_BPZPDK20090404\_195707\_000004532077\_00472\_37099\_1142.N1 ...

ANALYSIS COMPLETED: 21 WS browse products to see...

\*\*\*\*\*

BROWSE PRODUCTS ANALYSIS completed

#####

HTML REPORT generation

#####

Building file ./RESULTS/DAILY/090404/asarReport.html...

Building DATA SUMMARY section...

Building AUXILIARY FILES ANALYSIS section...

Building MODULE STEPPING ANALYSIS section...

Building CALIBRATION PULSES ANALYSIS section...

Building DOPPLER ANALYSIS section...

Building CHIRP ANALYSIS section...

Building RAW DATA ANALYSIS section...

Building TELEMETRY ANALYSIS section...

HTML REPORT generation completed

#####



# ASAR Daily Report





Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
ASA_APM_1PNPDE20090404_033429_000000602077_00462_37089_1221.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20090404_065758_000000432077_00464_37091_1555.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20090404_122311_000001032077_00467_37094_1806.N1	OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_GM1_1PNPDE20090404_002811_000003442077_00460_37087_0954.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090404_005409_000002172077_00460_37087_0967.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090404_010830_000003622077_00460_37087_1087.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090404_013832_000009122077_00461_37088_1092.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090404_022220_000001692077_00461_37088_1099.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090404_022403_000002352077_00461_37088_1249.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090404_023345_000000902077_00461_37088_1245.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090404_023706_000000782077_00461_37088_1243.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090404_024648_000003562077_00461_37088_1247.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090404_025407_000002712077_00461_37088_1236.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090404_030437_000000962077_00462_37089_1234.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090404_030857_000008632077_00462_37089_1238.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090404_032601_000005072077_00462_37089_1251.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090404_040256_000009302077_00462_37089_1456.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090404_044007_000006822077_00463_37090_1439.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090404_045247_000006702077_00463_37090_1434.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090404_051210_000000902077_00463_37090_1426.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090404_051711_000002172077_00463_37090_1424.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090404_054332_000000962077_00463_37090_1569.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090404_054743_000003502077_00463_37090_1571.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090404_055740_000001142077_00463_37090_1580.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090404_063143_000006642077_00464_37091_1610.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090404_065045_000001142077_00464_37091_1594.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090404_065507_000001692077_00464_37091_1592.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090404_065901_000002592077_00464_37091_1596.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090404_070449_000003622077_00464_37091_1590.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090404_071217_000001322077_00464_37091_1617.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090404_200443_000002832077_00472_37099_1935.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090404_201116_000002172077_00472_37099_1940.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090404_205011_000004832077_00472_37099_1942.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090404_210307_000001082077_00472_37099_1954.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090404_211422_000007852077_00472_37099_2079.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090404_214005_000001632077_00473_37100_2077.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090404_214620_000003322077_00473_37100_2088.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090404_222931_000000842077_00473_37100_2083.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090404_223428_000000902077_00473_37100_2081.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090404_224306_000001442077_00473_37100_2101.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090404_230426_000000842077_00474_37101_2217.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090404_230731_000000962077_00474_37101_2222.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090404_232741_000006582077_00474_37101_2228.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090404_235643_000004042077_00474_37101_2233.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090404_072348_000009842077_00464_37091_0176.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090404_081327_000007372077_00465_37092_0164.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090404_084309_000004652077_00465_37092_0209.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090404_090444_000009302077_00465_37092_0214.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090404_095506_000005862077_00466_37093_0221.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090404_101431_000000722077_00466_37093_0336.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090404_105803_000001992077_00466_37093_0341.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090404_113502_000006102077_00467_37094_0343.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090404_123025_000006942077_00467_37094_0472.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090404_124929_000003922077_00467_37094_0480.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090404_131018_000008512077_00468_37095_0550.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090404_134711_000002412077_00468_37095_0602.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090404_135239_000003682077_00468_37095_0604.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090404_135855_000002952077_00468_37095_0606.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090404_140631_000009302077_00468_37095_0616.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090404_142949_000002412077_00468_37095_0614.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090404_144536_000000842077_00469_37096_0621.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090404_145132_000004102077_00469_37096_0631.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090404_150244_000000902077_00469_37096_0739.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090404_151142_000003022077_00469_37096_0741.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090404_151804_000003022077_00469_37096_0746.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090404_152552_000000962077_00469_37096_0748.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090404_154707_000009302077_00469_37096_0753.N1					OK	OK	OK	OK

ASA_GM1_1PNPDK20090404_162510_000001082077_00470_37097_0755.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20090404_163333_000002112077_00470_37097_0765.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20090404_164346_000001022077_00470_37097_0888.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20090404_165639_000004952077_00470_37097_0892.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20090404_172743_000001992077_00470_37097_0890.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20090404_173536_000004892077_00470_37097_0897.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20090404_180618_000000722077_00471_37098_0899.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20090404_180900_000002832077_00471_37098_0906.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20090404_182634_000007182077_00471_37098_1013.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20090404_190819_000001692077_00471_37098_1017.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20090404_191542_000002652077_00471_37098_1015.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20090404_192257_000000842077_00471_37098_1022.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20090404_193811_000005192077_00471_37098_1024.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20090404_195536_000000842077_00472_37099_1029.N1	OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_IMM_1PNPDE20090404_004236_000000822077_00460_37087_1368.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090404_004340_00000182077_00460_37087_0939.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090404_004436_000005622077_00460_37087_1175.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090404_022757_000003372077_00461_37088_1209.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090404_023512_000001042077_00461_37088_1320.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090404_025240_000000762077_00461_37088_1366.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090404_025342_00000142077_00461_37088_1260.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090404_033550_000001832077_00462_37089_1364.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090404_033550_000003432077_00462_37089_1370.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090404_045129_000000672077_00463_37090_1516.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090404_050836_000002042077_00463_37090_1529.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090404_051338_000000632077_00463_37090_1380.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090404_051338_000002022077_00463_37090_1535.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090404_051641_00000192077_00463_37090_1386.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090404_054510_000001422077_00463_37090_1518.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090404_055330_000002392077_00463_37090_1586.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090404_070316_000000822077_00464_37091_1588.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090404_071050_000000622077_00464_37091_1582.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090404_071050_000000752077_00464_37091_1671.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090404_101717_000000372077_00466_37093_1712.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090404_104612_000001632077_00466_37093_1762.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090404_104935_000002022077_00466_37093_1756.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090404_105038_000000592077_00466_37093_1748.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090404_105230_000003222077_00466_37093_1787.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090404_105238_00000192077_00466_37093_1752.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090404_135111_000000772077_00468_37095_1827.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090404_144701_000002612077_00469_37096_1843.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090404_164853_000000672077_00470_37097_1861.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090404_173103_000002612077_00470_37097_1899.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090404_180727_000000822077_00471_37098_1877.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090404_191109_000002622077_00471_37098_1933.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090404_192009_000001572077_00471_37098_1919.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090404_193259_000000832077_00471_37098_1921.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090404_193737_000000222077_00471_37098_1913.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090404_200927_000000982077_00472_37099_2033.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090404_202554_000000482077_00472_37099_1944.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090404_205812_000002852077_00472_37099_2045.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090404_213321_000000432077_00473_37100_2170.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090404_215150_000001422077_00473_37100_2188.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090404_215719_000000562077_00473_37100_2172.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090404_223055_000002002077_00473_37100_2193.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090404_223555_000004202077_00473_37100_2209.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090404_230548_000000922077_00474_37101_2346.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20090404_064957_000000372077_00464_37091_0112.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20090404_083019_000000502077_00465_37092_0178.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20090404_101320_000000602077_00466_37093_0299.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20090404_122837_000000972077_00467_37094_0571.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20090404_124719_000000682077_00467_37094_0569.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20090404_124841_000000352077_00467_37094_0567.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20090404_164228_000000662077_00470_37097_0854.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20090404_214248_000002022077_00473_37100_1159.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20090404_232204_000001232077_00474_37101_1237.N1					OK	OK	OK	OK


Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WSM_1PNPDE20090404_012753_000001282077_00461_37088_1181.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090404_013116_000002512077_00461_37088_1326.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090404_013116_000004282077_00461_37088_1374.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090404_024513_000000922077_00461_37088_1352.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090404_030620_000001532077_00462_37089_1356.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090404_032327_000001352077_00462_37089_1354.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090404_050403_000001342077_00463_37090_1531.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090404_050403_000002692077_00463_37090_1553.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090404_050713_000000782077_00463_37090_1532.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090404_052931_000000922077_00463_37090_1537.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090404_065241_000001342077_00464_37091_1690.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090404_071432_000002872077_00464_37091_1701.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090404_101546_000000912077_00466_37093_1724.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090404_102053_000003732077_00466_37093_1765.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090404_102206_000003002077_00466_37093_1754.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090404_120949_000001342077_00467_37094_1802.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090404_120949_000003482077_00467_37094_1811.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090404_121258_000001592077_00467_37094_1803.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090404_122544_000001152077_00467_37094_1808.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090404_133154_000000912077_00468_37095_1839.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090404_151008_000000922077_00469_37096_1841.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090404_151649_000000672077_00469_37096_1821.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090404_162701_000000732077_00470_37097_1845.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090404_162701_0000003732077_00470_37097_2072.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090404_162916_000000552077_00470_37097_1849.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090404_163213_000000612077_00470_37097_1855.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090404_165104_000001352077_00470_37097_1901.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090404_165104_000003302077_00470_37097_2057.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090404_165515_000000782077_00470_37097_1902.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090404_181346_000002072077_00471_37098_1905.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090404_210947_000002692077_00472_37099_2064.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090404_232444_000001712077_00474_37101_2371.N1					OK	OK	OK	OK


Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WVS_1PNPDE20090404_000944_000010642077_00460_37087_0952.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090404_003358_000004202077_00460_37087_0962.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090404_005748_000004052077_00460_37087_0965.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090404_010348_000002402077_00460_37087_1085.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090404_011439_000007342077_00460_37087_1090.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090404_015925_000013342077_00461_37088_1102.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090404_023824_000003152077_00461_37088_1241.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090404_025840_000003142077_00462_37089_1232.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090404_034140_000008392077_00462_37089_1229.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090404_035525_000001802077_00462_37089_1442.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090404_041900_000012292077_00462_37089_1437.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090404_052052_000004792077_00463_37090_1432.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090404_053101_000003752077_00463_37090_1429.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090404_053646_000003602077_00463_37090_1574.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090404_055936_000018892077_00463_37090_1621.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090404_201458_000006142077_00472_37099_1938.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090404_202650_000012892077_00472_37099_1957.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090404_210459_000000292077_00472_37099_1952.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090404_210459_000002402077_00472_37099_2075.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090404_215419_000001502077_00473_37100_2086.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090404_215821_000018292077_00473_37100_2091.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090404_224535_000003142077_00473_37100_2099.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090404_225005_000008092077_00473_37100_2220.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090404_230911_000006142077_00474_37101_2225.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090404_233840_000010342077_00474_37101_2231.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090404_071919_000002252077_00464_37091_0131.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090404_074012_000019492077_00464_37091_0156.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090404_085055_000007792077_00465_37092_0212.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090404_092048_000020092077_00465_37092_0225.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090404_102720_000010342077_00466_37093_0339.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090404_110124_000019792077_00466_37093_0406.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090404_115245_000009742077_00467_37094_0470.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090404_121539_000004202077_00467_37094_0475.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090404_124200_000002852077_00467_37094_0478.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090404_125601_000008202077_00467_37094_0483.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090404_133706_000005542077_00468_37095_0609.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090404_140351_000001202077_00468_37095_0612.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090404_142236_000003902077_00468_37095_0619.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090404_143353_000006592077_00468_37095_0629.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090404_152306_000001192077_00469_37096_0744.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090404_152731_000011392077_00469_37096_0751.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090404_160312_000012742077_00469_37096_0763.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090404_170458_000013192077_00470_37097_0895.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090404_174348_000013042077_00470_37097_0909.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090404_183837_000017392077_00471_37098_1027.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090404_192424_000004802077_00471_37098_1020.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090404_193428_000001042077_00471_37098_1032.N1					OK	OK	OK	OK

Calibration pulses for GM1 SS3 H/H




Calibration pulses for GM1 SS3 H/H







### Calibration pulses for GM1 SS3 H/H




### Calibration pulses for GM1 SS3 H/H




Calibration pulses for WVS IS2 V/V




### Calibration pulses for WVS IS2 V/V





Calibration pulses for WVS IS2 V/V





Calibration pulses for WVS IS2 V/V



















rows: \_ 1 \_ 5 \_ 9 \_ 13 \_ 17 \_ 21 \_ 25 \_ 29







rows: \_ 2 \_ 6 \_ 10 \_ 14 \_ 18 \_ 22 \_ 26 \_ 30



















rows: \_ 4 \_ 8 \_ 12 \_ 16 \_ 20 \_ 24 \_ 28 \_ 32











Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_APM_1PNPDE20090404_033429_000000602077_00462_37089_1221.N1						IS1	H/H	77	37089	462	4.07
ASA_APM_1PNPDE20090404_065758_000000432077_00464_37091_1555.N1						IS2	H/H	77	37091	464	4.07
ASA_APM_1PNPDE20090404_122311_000001032077_00467_37094_1806.N1						IS6	H/V	77	37094	467	4.07



ASA_GM1_1PNPDE20090404_205011_000004832077_00472_37099_1942.N1	SS1	H/H	77	37099	472	4.07
ASA_GM1_1PNPDE20090404_210307_000001082077_00472_37099_1954.N1	SS1	H/H	77	37099	472	4.07
ASA_GM1_1PNPDE20090404_211422_000007852077_00472_37099_2079.N1	SS1	H/H	77	37099	472	4.07
ASA_GM1_1PNPDE20090404_214005_000001632077_00473_37100_2077.N1	SS1	H/H	77	37100	473	4.07
ASA_GM1_1PNPDE20090404_214620_000003322077_00473_37100_2088.N1	SS1	H/H	77	37100	473	4.07
ASA_GM1_1PNPDE20090404_222931_000000842077_00473_37100_2083.N1	SS1	H/H	77	37100	473	4.07
ASA_GM1_1PNPDE20090404_223428_000000902077_00473_37100_2081.N1	SS1	H/H	77	37100	473	4.07
ASA_GM1_1PNPDE20090404_224306_000001442077_00473_37100_2101.N1	SS1	H/H	77	37100	473	4.07
ASA_GM1_1PNPDE20090404_230426_000000842077_00474_37101_2217.N1	SS1	H/H	77	37101	474	4.07
ASA_GM1_1PNPDE20090404_230731_000000962077_00474_37101_2222.N1	SS1	H/H	77	37101	474	4.07
ASA_GM1_1PNPDE20090404_232741_000006582077_00474_37101_2228.N1	SS1	H/H	77	37101	474	4.07
ASA_GM1_1PNPDE20090404_235643_000004042077_00474_37101_2233.N1	SS1	H/H	77	37101	474	4.07

Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_IMM_1PNPDE20090404_004236_00000822077_00460_37087_1368.N1						IS2	H/H	77	37087	460	4.07
ASA_IMM_1PNPDE20090404_004340_00000182077_00460_37087_0939.N1						IS2	H/H	77	37087	460	4.07
ASA_IMM_1PNPDE20090404_004436_000005622077_00460_37087_1175.N1						IS2	H/H	77	37087	460	4.07
ASA_IMM_1PNPDE20090404_022757_000003372077_00461_37088_1209.N1						IS2	H/H	77	37088	461	4.07
ASA_IMM_1PNPDE20090404_023512_000001042077_00461_37088_1320.N1						IS2	H/H	77	37088	461	4.07
ASA_IMM_1PNPDE20090404_025240_00000762077_00461_37088_1366.N1						IS5	H/H	77	37088	461	4.07
ASA_IMM_1PNPDE20090404_025342_00000142077_00461_37088_1260.N1						IS5	***	77	37088	461	4.07
ASA_IMM_1PNPDE20090404_033550_000001832077_00462_37089_1364.N1						IS2	V/V	77	37089	462	4.07
ASA_IMM_1PNPDE20090404_033550_000003432077_00462_37089_1370.N1						IS2	V/V	77	37089	462	4.07
ASA_IMM_1PNPDE20090404_045129_000000672077_00463_37090_1516.N1						IS2	V/V	77	37090	463	4.07
ASA_IMM_1PNPDE20090404_050836_000002042077_00463_37090_1529.N1						IS2	V/V	77	37090	463	4.07
ASA_IMM_1PNPDE20090404_051338_000000632077_00463_37090_1380.N1						IS2	V/V	77	37090	463	4.07
ASA_IMM_1PNPDE20090404_051338_000002022077_00463_37090_1535.N1						IS2	V/V	77	37090	463	4.07
ASA_IMM_1PNPDE20090404_051641_00000192077_00463_37090_1386.N1						IS2	***	77	37090	463	4.07
ASA_IMM_1PNPDE20090404_054510_000001422077_00463_37090_1518.N1						IS2	H/H	77	37090	463	4.07
ASA_IMM_1PNPDE20090404_055330_000002392077_00463_37090_1586.N1						IS6	H/H	77	37090	463	4.07
ASA_IMM_1PNPDK20090404_064957_00000372077_00464_37091_0112.N1						IS2	V/V	77	37091	464	4.07
ASA_IMM_1PNPDE20090404_070316_00000822077_00464_37091_1588.N1						IS2	V/V	77	37091	464	4.07
ASA_IMM_1PNPDE20090404_071050_00000622077_00464_37091_1582.N1						IS5	H/H	77	37091	464	4.07
ASA_IMM_1PNPDE20090404_071050_00000752077_00464_37091_1671.N1						IS5	H/H	77	37091	464	4.07
ASA_IMM_1PNPDK20090404_083019_00000502077_00465_37092_0178.N1						IS3	H/H	77	37092	465	4.07
ASA_IMM_1PNPDK20090404_101320_000000602077_00466_37093_0299.N1						IS2	V/V	77	37093	466	4.07
ASA_IMM_1PNPDE20090404_101717_000000372077_00466_37093_1712.N1						IS2	V/V	77	37093	466	4.07
ASA_IMM_1PNPDE20090404_104612_000001632077_00466_37093_1762.N1						IS2	H/H	77	37093	466	4.07
ASA_IMM_1PNPDE20090404_104935_000002022077_00466_37093_1756.N1						IS2	H/H	77	37093	466	4.07
ASA_IMM_1PNPDE20090404_105038_000000592077_00466_37093_1748.N1						IS2	H/H	77	37093	466	4.07
ASA_IMM_1PNPDE20090404_105230_00000322077_00466_37093_1787.N1						IS2	H/H	77	37093	466	4.07
ASA_IMM_1PNPDE20090404_105238_00000192077_00466_37093_1752.N1						IS2	***	77	37093	466	4.07
ASA_IMM_1PNPDK20090404_122837_000000972077_00467_37094_0571.N1						IS3	H/H	77	37094	467	4.07
ASA_IMM_1PNPDK20090404_124719_000000682077_00467_37094_0569.N1						IS2	V/V	77	37094	467	4.07
ASA_IMM_1PNPDK20090404_124841_000000352077_00467_37094_0567.N1						IS7	V/V	77	37094	467	4.07
ASA_IMM_1PNPDE20090404_135111_000000772077_00468_37095_1827.N1						IS7	H/H	77	37095	468	4.07
ASA_IMM_1PNPDE20090404_144701_000002612077_00469_37096_1843.N1						IS2	V/V	77	37096	469	4.07
ASA_IMM_1PNPDK20090404_164228_000000662077_00470_37097_0854.N1						IS2	H/H	77	37097	470	4.07
ASA_IMM_1PNPDE20090404_164853_000000672077_00470_37097_1861.N1						IS2	V/V	77	37097	470	4.07
ASA_IMM_1PNPDE20090404_173103_000002612077_00470_37097_1899.N1						IS2	H/H	77	37097	470	4.07
ASA_IMM_1PNPDE20090404_180727_000000822077_00471_37098_1877.N1						IS6	V/V	77	37098	471	4.07
ASA_IMM_1PNPDE20090404_191109_000002622077_00471_37098_1933.N1						IS2	H/H	77	37098	471	4.07
ASA_IMM_1PNPDE20090404_192009_000001572077_00471_37098_1919.N1						IS2	H/H	77	37098	471	4.07
ASA_IMM_1PNPDE20090404_193259_000000832077_00471_37098_1921.N1						IS2	V/V	77	37098	471	4.07
ASA_IMM_1PNPDE20090404_193737_000000222077_00471_37098_1913.N1						IS7	H/H	77	37098	471	4.07
ASA_IMM_1PNPDE20090404_200927_000000982077_00472_37099_2033.N1						IS2	V/V	77	37099	472	4.07
ASA_IMM_1PNPDE20090404_202554_000000482077_00472_37099_1944.N1						IS1	V/V	77	37099	472	4.07
ASA_IMM_1PNPDE20090404_205812_000002852077_00472_37099_2045.N1						IS2	H/H	77	37099	472	4.07
ASA_IMM_1PNPDE20090404_213321_000000432077_00473_37100_2170.N1						IS2	V/V	77	37100	473	4.07
ASA_IMM_1PNPDK20090404_214248_000002022077_00473_37100_1159.N1						IS2	H/H	77	37100	473	4.07
ASA_IMM_1PNPDE20090404_215150_000001422077_00473_37100_2188.N1						IS2	V/V	77	37100	473	4.07
ASA_IMM_1PNPDE20090404_215719_000000562077_00473_37100_2172.N1						IS2	V/V	77	37100	473	4.07
ASA_IMM_1PNPDE20090404_223055_000002002077_00473_37100_2193.N1						IS2	H/H	77	37100	473	4.07
ASA_IMM_1PNPDE20090404_223555_000004202077_00473_37100_2209.N1						IS2	H/H	77	37100	473	4.07
ASA_IMM_1PNPDE20090404_230548_000000922077_00474_37101_2346.N1						IS3	H/H	77	37101	474	4.07
ASA_IMM_1PNPDK20090404_232204_000001232077_00474_37101_1237.N1						IS2	H/H	77	37101	474	4.07





Filename	Pol	Timestamp	count(Module)
ASA_MS__0PNPDE20090404_204853_000000162077_00472_37099_0404.N1	V	2009-04-04 20:48:53	320





Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WSM_1PNPDE20090404_012753_000001282077_00461_37088_1181.N1						SS1	H/H	77	37088	461	4.07
ASA_WSM_1PNPDE20090404_013116_000002512077_00461_37088_1326.N1						SS1	H/H	77	37088	461	4.07
ASA_WSM_1PNPDE20090404_013116_000004282077_00461_37088_1374.N1						SS1	H/H	77	37088	461	4.07
ASA_WSM_1PNPDE20090404_024513_000000922077_00461_37088_1352.N1						SS1	H/H	77	37088	461	4.07
ASA_WSM_1PNPDE20090404_030620_000001532077_00462_37089_1356.N1						SS1	H/H	77	37089	462	4.07
ASA_WSM_1PNPDE20090404_032327_000001352077_00462_37089_1354.N1						SS1	H/H	77	37089	462	4.07
ASA_WSM_1PNPDE20090404_050403_000001342077_00463_37090_1531.N1						SS1	H/H	77	37090	463	4.07
ASA_WSM_1PNPDE20090404_050403_000002692077_00463_37090_1553.N1						SS1	H/H	77	37090	463	4.07
ASA_WSM_1PNPDE20090404_050713_000000782077_00463_37090_1532.N1						SS1	H/H	77	37090	463	4.07
ASA_WSM_1PNPDE20090404_052931_000000922077_00463_37090_1537.N1						SS1	H/H	77	37090	463	4.07
ASA_WSM_1PNPDE20090404_065241_000001342077_00464_37091_1690.N1						SS1	H/H	77	37091	464	4.07
ASA_WSM_1PNPDE20090404_071432_000002872077_00464_37091_1701.N1						SS1	V/V	77	37091	464	4.07
ASA_WSM_1PNPDE20090404_101546_000000912077_00466_37093_1724.N1						SS1	V/V	77	37093	466	4.07
ASA_WSM_1PNPDE20090404_102053_000003732077_00466_37093_1765.N1						SS1	V/V	77	37093	466	4.07
ASA_WSM_1PNPDE20090404_102206_000003002077_00466_37093_1754.N1						SS1	V/V	77	37093	466	4.07
ASA_WSM_1PNPDE20090404_120949_000001342077_00467_37094_1802.N1						SS1	V/V	77	37094	467	4.07
ASA_WSM_1PNPDE20090404_120949_000003482077_00467_37094_1811.N1						SS1	V/V	77	37094	467	4.07
ASA_WSM_1PNPDE20090404_121258_000001592077_00467_37094_1803.N1						SS1	V/V	77	37094	467	4.07
ASA_WSM_1PNPDE20090404_122544_000001152077_00467_37094_1808.N1						SS1	V/V	77	37094	467	4.07
ASA_WSM_1PNPDE20090404_133154_000000912077_00468_37095_1839.N1						SS1	H/H	77	37095	468	4.07
ASA_WSM_1PNPDE20090404_151008_000000922077_00469_37096_1841.N1						SS1	H/H	77	37096	469	4.07
ASA_WSM_1PNPDE20090404_151649_000000672077_00469_37096_1821.N1						SS1	V/V	77	37096	469	4.07
ASA_WSM_1PNPDE20090404_162701_000000732077_00470_37097_1845.N1						SS1	V/V	77	37097	470	4.07
ASA_WSM_1PNPDE20090404_162701_000003732077_00470_37097_2072.N1						SS1	V/V	77	37097	470	4.07
ASA_WSM_1PNPDE20090404_162916_000000552077_00470_37097_1849.N1						SS1	V/V	77	37097	470	4.07
ASA_WSM_1PNPDE20090404_163213_000000612077_00470_37097_1855.N1						SS1	V/V	77	37097	470	4.07
ASA_WSM_1PNPDE20090404_165104_000001352077_00470_37097_1901.N1						SS1	V/V	77	37097	470	4.07
ASA_WSM_1PNPDE20090404_165104_000003302077_00470_37097_2057.N1						SS1	V/V	77	37097	470	4.07
ASA_WSM_1PNPDE20090404_165515_000000782077_00470_37097_1902.N1						SS1	V/V	77	37097	470	4.07
ASA_WSM_1PNPDE20090404_181346_000002072077_00471_37098_1905.N1						SS1	H/H	77	37098	471	4.07
ASA_WSM_1PNPDE20090404_210947_000002692077_00472_37099_2064.N1						SS1	V/V	77	37099	472	4.07
ASA_WSM_1PNPDE20090404_232444_000001712077_00474_37101_2371.N1						SS1	H/H	77	37101	474	4.07




Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WVS_1PNPDE20090404_000944_000010642077_00460_37087_0952.N1						IS2	V/V	77	37087	460	4.07
ASA_WVS_1PNPDE20090404_003358_000004202077_00460_37087_0962.N1						IS2	V/V	77	37087	460	4.07
ASA_WVS_1PNPDE20090404_005748_000004052077_00460_37087_0965.N1						IS2	V/V	77	37087	460	4.07
ASA_WVS_1PNPDE20090404_010348_000002402077_00460_37087_1085.N1						IS2	V/V	77	37087	460	4.07
ASA_WVS_1PNPDE20090404_011439_000007342077_00460_37087_1090.N1						IS2	V/V	77	37087	460	4.07
ASA_WVS_1PNPDE20090404_015925_000013342077_00461_37088_1102.N1						IS2	V/V	77	37088	461	4.07
ASA_WVS_1PNPDE20090404_023824_000003152077_00461_37088_1241.N1						IS2	V/V	77	37088	461	4.07
ASA_WVS_1PNPDE20090404_025840_000003142077_00462_37089_1232.N1						IS2	V/V	77	37089	462	4.07
ASA_WVS_1PNPDE20090404_034140_000008392077_00462_37089_1229.N1						IS2	V/V	77	37089	462	4.07
ASA_WVS_1PNPDE20090404_035525_000001802077_00462_37089_1442.N1						IS2	V/V	77	37089	462	4.07
ASA_WVS_1PNPDE20090404_041900_000012292077_00462_37089_1437.N1						IS2	V/V	77	37089	462	4.07
ASA_WVS_1PNPDE20090404_052052_000004792077_00463_37090_1432.N1						IS2	V/V	77	37090	463	4.07
ASA_WVS_1PNPDE20090404_053101_000003752077_00463_37090_1429.N1						IS2	V/V	77	37090	463	4.07
ASA_WVS_1PNPDE20090404_053646_000003602077_00463_37090_1574.N1						IS2	V/V	77	37090	463	4.07
ASA_WVS_1PNPDE20090404_053101_000003752077_00463_37090_1429.N1						IS1	V/V	77	37090	463	4.07
ASA_WVS_1PNPDE20090404_055936_000018892077_00463_37090_1621.N1						IS2	V/V	77	37090	463	4.07
ASA_WVS_1PNPDK20090404_071919_000002252077_00464_37091_0131.N1						IS2	V/V	77	37091	464	4.07
ASA_WVS_1PNPDK20090404_074012_000019492077_00464_37091_0156.N1						IS2	V/V	77	37091	464	4.07
ASA_WVS_1PNPDK20090404_085055_000007792077_00465_37092_0212.N1						IS2	V/V	77	37092	465	4.07
ASA_WVS_1PNPDK20090404_092048_000020092077_00465_37092_0225.N1						IS2	V/V	77	37092	465	4.07
ASA_WVS_1PNPDK20090404_102720_000010342077_00466_37093_0339.N1						IS2	V/V	77	37093	466	4.07
ASA_WVS_1PNPDK20090404_110124_000019792077_00466_37093_0406.N1						IS2	V/V	77	37093	466	4.07
ASA_WVS_1PNPDK20090404_115245_000009742077_00467_37094_0470.N1						IS2	V/V	77	37094	467	4.07
ASA_WVS_1PNPDK20090404_121539_000004202077_00467_37094_0475.N1						IS2	V/V	77	37094	467	4.07
ASA_WVS_1PNPDK20090404_124200_000002852077_00467_37094_0478.N1						IS2	V/V	77	37094	467	4.07
ASA_WVS_1PNPDK20090404_125601_000008202077_00467_37094_0483.N1						IS2	V/V	77	37094	467	4.07
ASA_WVS_1PNPDK20090404_133706_000005542077_00468_37095_0609.N1						IS2	V/V	77	37095	468	4.07
ASA_WVS_1PNPDK20090404_140351_000001202077_00468_37095_0612.N1						IS2	V/V	77	37095	468	4.07
ASA_WVS_1PNPDK20090404_142236_000003902077_00468_37095_0619.N1						IS2	V/V	77	37095	468	4.07
ASA_WVS_1PNPDK20090404_143353_000006592077_00468_37095_0629.N1						IS2	V/V	77	37095	468	4.07
ASA_WVS_1PNPDK20090404_152306_000001192077_00469_37096_0744.N1						IS2	V/V	77	37096	469	4.07
ASA_WVS_1PNPDK20090404_152731_000011392077_00469_37096_0751.N1						IS2	V/V	77	37096	469	4.07
ASA_WVS_1PNPDK20090404_160312_000012742077_00469_37096_0763.N1						IS2	V/V	77	37096	469	4.07
ASA_WVS_1PNPDK20090404_170458_000013192077_00470_37097_0895.N1						IS2	V/V	77	37097	470	4.07
ASA_WVS_1PNPDK20090404_174348_000013042077_00470_37097_0909.N1						IS2	V/V	77	37097	470	4.07
ASA_WVS_1PNPDK20090404_183837_000017392077_00471_37098_1027.N1						IS2	V/V	77	37098	471	4.07
ASA_WVS_1PNPDK20090404_192424_000004802077_00471_37098_1020.N1						IS2	V/V	77	37098	471	4.07
ASA_WVS_1PNPDK20090404_193428_000001042077_00471_37098_1032.N1						IS2	V/V	77	37098	471	4.07
ASA_WVS_1PNPDE20090404_201458_000006142077_00472_37099_1938.N1						IS2	V/V	77	37099	472	4.07
ASA_WVS_1PNPDE20090404_202650_000012892077_00472_37099_1957.N1						IS2	V/V	77	37099	472	4.07
ASA_WVS_1PNPDE20090404_210459_000000292077_00472_37099_1952.N1						IS2	V/V	77	37099	472	4.07
ASA_WVS_1PNPDE20090404_210459_000002402077_00472_37099_2075.N1						IS2	V/V	77	37099	472	4.07
ASA_WVS_1PNPDE20090404_210459_000000292077_00472_37099_1952.N1						IS1	V/V	77	37099	472	4.07
ASA_WVS_1PNPDE20090404_215419_000001502077_00473_37100_2086.N1						IS2	V/V	77	37100	473	4.07
ASA_WVS_1PNPDE20090404_215821_000018292077_00473_37100_2091.N1						IS2	V/V	77	37100	473	4.07
ASA_WVS_1PNPDE20090404_224535_000003142077_00473_37100_2099.N1						IS2	V/V	77	37100	473	4.07
ASA_WVS_1PNPDE20090404_225005_000008092077_00473_37100_2220.N1						IS2	V/V	77	37100	473	4.07
ASA_WVS_1PNPDE20090404_224535_000003142077_00473_37100_2099.N1						IS1	V/V	77	37100	473	4.07
ASA_WVS_1PNPDE20090404_230911_000006142077_00474_37101_2225.N1						IS2	V/V	77	37101	474	4.07
ASA_WVS_1PNPDE20090404_233840_000010342077_00474_37101_2231.N1						IS2	V/V	77	37101	474	4.07




















































































04-Apr




04-Apr




04-Apr



04-Apr



04-Apr



04-Apr

