



ASAR Daily Report



Analysis from 03-MAY-2009 00:00:00 to 03-MAY-2009 23:59:59. Page generated on 04-MAY-2009 07:42:04.
View log file: ASAR_Daily_Report_20090504_0730.log. For any anomalies please contact mtranfaglia@serco.it, Emma.Griffiths@vega.co.uk.

This report is automatically generated every day, every 2 hours. No comments are provided on the results.

SUMMARY

1. DATA SUMMARY
 - 1.1 Summary tables
 - 1.2 Lists of products used
2. AUXILIARY FILES ANALYSIS
 - 2.1 IECF operational ADFs list
 - 2.2 Products with wrong ADFs
3. MODULE STEPPING PRODUCTS ANALYSIS
 - 3.1 V/V polarisation
 - 3.2 H/H polarisation
4. CALIBRATION PULSES ANALYSIS
 - 4.1 Analysis for WVS IS2 V/V
 - 4.1.1 Temporal Evolution Analysis for WVS IS2 V/V
 - 4.1.2 All Rows Analysis for WVS IS2 V/V
 - 4.2 Analysis for GM1 SS3 H/H
 - 4.2.1 Temporal Evolution Analysis for GM1 SS3 H/H
 - 4.2.2 All Rows Analysis for GM1 SS3 H/H
5. DOPPLER ANALYSIS
 - 5.1 Analysis for WVS IS2 V/V
 - 5.1.1 Doppler MAP Analysis for WVS IS2 V/V
 - 5.1.2 Doppler ANX Analysis for WVS IS2 V/V
 - 5.2 Analysis for GM1 SS1 H/H
 - 5.2.1 Doppler MAP Analysis for GM1 SS1 H/H
 - 5.2.2 Doppler ANX Analysis for GM1 SS1 H/H
 - 5.3 Doppler JUMPS Analysis for WSM
6. CHIRP ANALYSIS
 - 6.1 Analysis for WSM SS1 H/H
 - 6.1.1 ScaleFactor
 - 6.2 Analysis for WSM SS1 V/V
 - 6.2.1 ScaleFactor
7. RAW DATA ANALYSIS
 - 7.1 Analysis for WVS
 - 7.2 Analysis for IMM
8. TELEMETRY ANALYSIS
 - 8.1 Number of Missing Lines
 - 8.2 Number of Gaps

1 - DATA SUMMARY

1.1 - Summary tables

[[BACK TO MENU](#)]

WVS				GM1				APM				IMM				WSM				MS			
Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Time	Pol	Modules
PDE	IS2	V/V	30	PDE	WS	H/H	37	PDE	IS1	H/H	1	PDE	IS1	V/V	1	PDE	WS	H/H	22	PDE	2009-05-03 05:32:02	V	320
PDK	IS2	V/V	21	PDK	WS	H/H	38	PDE	IS3	H/H	1	PDE	IS2	***	2	PDE	WS	V/V	14				
								PDE	IS6	H/H	1	PDE	IS2	H/H	29								
												PDE	IS2	V/V	7								
												PDE	IS3	V/V	1								
												PDE	IS4	H/H	2								
												PDE	IS4	V/V	2								
												PDE	IS5	H/H	3								
												PDE	IS5	V/V	2								
												PDE	IS7	H/H	2								
												PDK	IS2	H/H	7								
												PDK	IS2	V/V	1								
												PDK	IS3	V/V	1								

1.2 - Lists of products used

[[BACK TO MENU](#)]

[[TXT](#)] [[XLS](#)] [List_WVS_products_used](#)
 [[TXT](#)] [[XLS](#)] [List_GM1_products_used](#)
 [[TXT](#)] [[XLS](#)] [List_APM_products_used](#)
 [[TXT](#)] [[XLS](#)] [List_IMM_products_used](#)
 [[TXT](#)] [[XLS](#)] [List_WSM_products_used](#)
 [[TXT](#)] [[XLS](#)] [List_MS_products_used](#)

2 - AUXILIARY FILES ANALYSIS

2.1 - IECF operational ADFs list

[[BACK TO MENU](#)]

ADFs disseminated for ASAR
ASA_CON_AXVIEC20081215_141339_20070204_165113_20091231_000000
ASA_INS_AXVIEC20081215_140905_20070307_060000_20091231_000000
ASA_XCH_AXVIEC20081215_143642_20020301_000000_20091231_000000
ASA_XCA_AXVIEC20090311_104501_20080801_000000_20091231_235959

2.2 - Products with wrong ADFs

[[BACK TO MENU](#)]

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
WVS	0	0	0	0
GM1	0	0	0	0
APM	0	0	0	0
IMM	0	0	0	0
WSM	0	0	0	0

- [TXT] [XLS] Check_ADFs_WVS
- [TXT] [XLS] Check_ADFs_GM1
- [TXT] [XLS] Check_ADFs_APM
- [TXT] [XLS] Check_ADFs_IMM
- [TXT] [XLS] Check_ADFs_WSM

3 - MODULE STEPPING PRODUCTS ANALYSIS










3.2 - H/H polarisation

[[BACK TO MENU](#)]

SECOND FIXED REFERENCE	PREVIOUS PRODUCT REFERENCE
After antenna maintenance (2005-09-22/23)	Previous product in the same polarisation





4 - CALIBRATION PULSES ANALYSIS

4.1 - Analysis for WVS IS2 V/V


4.1.1 - Temporal Evolution Analysis for WVS IS2 V/V

[BACK TO MENU]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]


Calibration pulses for WVS IS2 V/V




03-May



03-May




03-May



03-May


rows: _ 1 _ 5 _ 9 _ 13 _ 17 _ 21 _ 25 _ 29

Transmit power (P1 - P1a) for WVS IS2 V/V



03-May

Transmit power (P1 - P1a) for WVS IS2 V/V




03-May

rows: _ 1 _ 5 _ 9 _ 13 _ 17 _ 21 _ 25 _ 29

4.1.2 - All Rows Analysis for WVS IS2 V/V

[[BACK TO MENU](#)]





4.2 - Analysis for GM1 SS3 H/H


4.2.1 - Temporal Evolution Analysis for GM1 SS3 H/H

[BACK TO MENU]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]


Calibration pulses for GM1 SS3 H/H




03-May



03-May




03-May



03-May


rows: _ 1 _ 5 _ 9 _ 13 _ 17 _ 21 _ 25 _ 29

Transmit power (P1 - P1a) for GM1 SS3 H/H



03-May

Transmit power (P1 - P1a) for GM1 SS3 H/H




03-May

rows: _ 1 _ 5 _ 9 _ 13 _ 17 _ 21 _ 25 _ 29

4.2.2 - All Rows Analysis for GM1 SS3 H/H

[[BACK TO MENU](#)]






5 - DOPPLER ANALYSIS

5.1 - Analysis for WVS IS2 V/V

5.1.1 - Doppler MAP Analysis for WVS IS2 V/V

[[BACK TO MENU](#)]






5.1.2 - Doppler ANX Analysis for WVS IS2 V/V

[[BACK TO MENU](#)]






5.2 - Analysis for GM1 SS1 H/H

5.2.1 - Doppler MAP Analysis for GM1 SS1 H/H

[[BACK TO MENU](#)]






5.2.2 - Doppler ANX Analysis for GM1 SS1 H/H

[[BACK TO MENU](#)]






5.3 - Doppler JUMPS Analysis for WSM

[[BACK TO MENU](#)]








6 - CHIRP ANALYSIS

6.1 - Analysis for WSM SS1 H/H

6.1.1 - ScaleFactor

[[BACK TO MENU](#)]







6.2 - Analysis for WSM SS1 V/V

6.2.1 - ScaleFactor

[[BACK TO MENU](#)]






7 - RAW DATA ANALYSIS

7.1 - Analysis for WVS

[[BACK TO MENU](#)]


--	--	--	--




Channel	Statistics	DSS-B
MEAN I	mean	0.000481479
	stdev	2.18016e-07
MEAN Q	mean	0.000457924
	stdev	2.57458e-07
Channel	Statistics	DSS-B
STDEV I	mean	0.131512
	stdev	0.00128393
STDEV Q	mean	0.131898
	stdev	0.00130689

7.2 - Analysis for IMM

[[BACK TO MENU](#)]






8 - TELEMETRY ANALYSIS

Processing Center	Product	Gaps	Missing lines
PDE	ASA_WSM_1PNPDE20090503_161420_00002262078_00384_37512_9504.N1	0	50

8.1 - Number of Missing lines


[[BACK TO MENU](#)]





8.2 - Number of Gaps

[[BACK TO MENU](#)]



ASAR DAILY REPORT for 090503
#####

MODE: DAILY
ANALYSIS: ALL
DATE: YESTERDAY

Analysis will be performed from 2009-05-03 00:00:00 to 2009-05-03 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/090503/

DATA SUMMARY

Summary will be performed from 2009-05-03 00:00:00 to 2009-05-03 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/090503/DATA_SUMMARY

Creating directory ./RESULTS/DAILY/090503/DATA_SUMMARY...
Writing file ./RESULTS/DAILY/090503/DATA_SUMMARY/Data_summary.html...

Getting WVS products list from 2009-05-03 00:00:00 to 2009-05-03 23:59:59...
Writing file ./RESULTS/DAILY/090503/DATA_SUMMARY/List_WVS_products_used.xls...
Writing file ./RESULTS/DAILY/090503/DATA_SUMMARY/List_WVS_products_used.txt...

Getting GM1 products list from 2009-05-03 00:00:00 to 2009-05-03 23:59:59...
Writing file ./RESULTS/DAILY/090503/DATA_SUMMARY/List_GM1_products_used.xls...
Writing file ./RESULTS/DAILY/090503/DATA_SUMMARY/List_GM1_products_used.txt...

Getting APM products list from 2009-05-03 00:00:00 to 2009-05-03 23:59:59...
Writing file ./RESULTS/DAILY/090503/DATA_SUMMARY/List_APM_products_used.xls...
Writing file ./RESULTS/DAILY/090503/DATA_SUMMARY/List_APM_products_used.txt...

Getting IMM products list from 2009-05-03 00:00:00 to 2009-05-03 23:59:59...
Writing file ./RESULTS/DAILY/090503/DATA_SUMMARY/List_IMM_products_used.xls...
Writing file ./RESULTS/DAILY/090503/DATA_SUMMARY/List_IMM_products_used.txt...

Getting WSM products list from 2009-05-03 00:00:00 to 2009-05-03 23:59:59...
Writing file ./RESULTS/DAILY/090503/DATA_SUMMARY/List_WSM_products_used.xls...
Writing file ./RESULTS/DAILY/090503/DATA_SUMMARY/List_WSM_products_used.txt...

Getting MS products list from 2009-05-03 00:00:00 to 2009-05-03 23:59:59...
Writing file ./RESULTS/DAILY/090503/DATA_SUMMARY/List_MS_products_used.xls...
Writing file ./RESULTS/DAILY/090503/DATA_SUMMARY/List_MS_products_used.txt...

DATA SUMMARY completed
#####

AUXILIARY FILES ANALYSIS

Analysis will be performed from 2009-05-03 00:00:00 to 2009-05-03 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/090503/AUXILIARY

Creating directory ./RESULTS/DAILY/090503/AUXILIARY...

Looking for the IECF operational ADFs list...



Found list 20090503_030003_current_3_IECF_ADFs.txt...
Extracting ADFs...

ASA_CON_AXVIEC20081215_141339_20070204_165113_20091231_000000
ASA_INS_AXVIEC20081215_140905_20070307_060000_20091231_000000
ASA_XCH_AXVIEC20081215_143642_20020301_000000_20091231_000000
ASA_XCA_AXVIEC20090311_104501_20080801_000000_20091231_235959

Writing file ./RESULTS/DAILY/090503/AUXILIARY/ASAR_ADFs_IECF_List3.html...
Writing file ./RESULTS/DAILY/090503/AUXILIARY/Auxiliary_files_summary.html...

Analysing WVS products...

Writing file ./RESULTS/DAILY/090503/AUXILIARY/Check_ADFs_WVS.xls...
Writing file ./RESULTS/DAILY/090503/AUXILIARY/Check_ADFs_WVS.txt...

ASA_WVS_1PNPDE20090503_002303_000003902078_00374_37502_8573.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090503_004621_000004052078_00374_37502_8580.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090503_005221_000002992078_00374_37502_8702.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090503_010251_000009292078_00374_37502_8707.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090503_014405_000000442078_00375_37503_8710.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090503_014758_000003142078_00375_37503_8713.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090503_015437_000009292078_00375_37503_8721.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090503_020937_00000302078_00375_37503_8860.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090503_022657_000003152078_00375_37503_8871.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090503_024714_000002392078_00376_37504_8876.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090503_033012_000002842078_00376_37504_9456.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090503_034427_000001802078_00376_37504_9036.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090503_041040_000007342078_00376_37504_9051.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090503_042454_000001942078_00377_37505_9029.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090503_051141_000008842078_00377_37505_9069.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090503_052611_000003152078_00377_37505_9217.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090503_054809_000018292078_00377_37505_9252.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090503_070251_000001642078_00378_37506_9236.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090503_200341_000006142078_00386_37514_9607.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090503_201533_000012742078_00386_37514_9620.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090503_205332_00000302078_00386_37514_9617.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090503_205332_000002402078_00386_37514_9741.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090503_214401_000015292078_00387_37515_9748.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090503_221301_000002552078_00387_37515_9757.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090503_223408_000003302078_00387_37515_9760.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090503_223853_000007642078_00387_37515_9898.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090503_230048_000003892078_00388_37516_9905.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090503_232625_000011392078_00388_37516_9914.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090503_235235_000003152078_00388_37516_9919.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090503_070753_000002402078_00378_37506_3656.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090503_072845_000019492078_00378_37506_3677.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090503_084224_000006152078_00379_37507_3757.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090503_090921_000020242078_00379_37507_3767.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090503_101601_000010342078_00380_37508_3910.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090503_104957_000018292078_00380_37508_3924.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090503_114031_000010042078_00381_37509_4041.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090503_120355_000005852078_00381_37509_4046.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090503_123032_000003452078_00381_37509_4049.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090503_124440_000008402078_00381_37509_4122.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090503_132236_000007642078_00382_37510_4153.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090503_135329_000000452078_00382_37510_4156.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090503_141108_000004052078_00382_37510_4164.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090503_142259_000002092078_00382_37510_4159.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090503_142820_000001642078_00383_37511_4174.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090503_151044_000014542078_00383_37511_4301.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090503_155144_000013042078_00383_37511_4306.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090503_165410_000012742078_00384_37512_4418.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090503_173220_000013942078_00384_37512_4430.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090503_182853_000016342078_00385_37513_4533.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK



ASA_WVS_1PNPDK20090503_191256_000009292078_00385_37513_4544.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

Analysing GM1 products...

Writing file ./RESULTS/DAILY/090503/AUXILIARY/Check_ADFs_GM1.xls...

Writing file ./RESULTS/DAILY/090503/AUXILIARY/Check_ADFs_GM1.txt...

ASA_GM1_1PNPDE20090503_001753_000003082078_00374_37502_8575.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090503_004403_000001382078_00374_37502_8577.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090503_005811_000002772078_00374_37502_8704.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090503_012649_000010322078_00375_37503_8794.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090503_021052_000002292078_00375_37503_8864.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090503_022315_000002172078_00375_37503_8862.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090503_023259_000004952078_00375_37503_8857.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090503_024240_000002712078_00375_37503_8873.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090503_025700_000002292078_00376_37504_8868.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090503_030325_000000782078_00376_37504_8866.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090503_030534_000009302078_00376_37504_8885.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090503_032745_000001442078_00376_37504_8883.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090503_035128_000001502078_00376_37504_9059.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090503_035529_000001262078_00376_37504_9057.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090503_040605_000000842078_00376_37504_9053.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090503_040828_000001322078_00376_37504_9033.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090503_042848_000001632078_00377_37505_9031.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090503_043302_0000021932078_00377_37505_9164.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090503_054539_000001442078_00377_37505_9219.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090503_061915_000002712078_00378_37506_9221.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090503_062452_000004652078_00378_37506_9233.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090503_063618_000006102078_00378_37506_9238.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090503_064713_000005792078_00378_37506_9240.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090503_065751_000002952078_00378_37506_9249.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090503_195733_000003682078_00386_37514_9604.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090503_203728_000001752078_00386_37514_9602.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090503_204253_000006342078_00386_37514_9633.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090503_210256_000010152078_00386_37514_9839.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090503_213948_000002532078_00387_37515_9754.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090503_221804_000000902078_00387_37515_9750.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090503_222308_000000902078_00387_37515_9752.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090503_222608_000004772078_00387_37515_9762.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090503_225216_000003802078_00388_37516_9902.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090503_231709_000005552078_00388_37516_9907.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090503_234610_000002892078_00388_37516_9909.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090503_235103_000000902078_00388_37516_9911.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20090503_235839_000000722078_00388_37516_9916.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090503_071240_000001442078_00378_37506_3653.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090503_071935_000001502078_00378_37506_3658.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090503_072535_000001872078_00378_37506_3660.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090503_080205_000006282078_00379_37507_3674.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090503_081923_000002172078_00379_37507_3750.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090503_083236_000005862078_00379_37507_3752.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090503_085316_000009302078_00379_37507_3759.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090503_094347_000005372078_00380_37508_3841.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090503_103352_000000842078_00380_37508_3907.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090503_104445_000003082078_00380_37508_3912.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090503_112116_000007122078_00381_37509_3914.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090503_122746_000001632078_00381_37509_4043.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090503_123813_000003862078_00381_37509_4051.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090503_125919_000008882078_00382_37510_4113.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090503_131325_000004162078_00382_37510_4144.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090503_133604_000006762078_00382_37510_4146.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090503_134728_000003562078_00382_37510_4150.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090503_135504_000001262078_00382_37510_4148.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090503_135845_000007432078_00382_37510_4161.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090503_141833_000002652078_00382_37510_4166.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090503_143411_000007972078_00383_37511_4236.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

ASA_GM1_1PNPDK20090503_145228_000000782078_00383_37511_4295.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090503_150015_000000782078_00383_37511_4293.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090503_150234_000001872078_00383_37511_4297.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090503_153540_000009302078_00383_37511_4303.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090503_161810_000004772078_00384_37512_4313.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090503_164111_000002352078_00384_37512_4410.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090503_164647_000004412078_00384_37512_4415.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090503_171616_000002052078_00384_37512_4413.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090503_172413_000004832078_00384_37512_4420.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090503_175842_000005372078_00385_37513_4427.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090503_180628_000000722078_00385_37513_4526.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090503_182259_000001812078_00385_37513_4528.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090503_185652_000002352078_00385_37513_4530.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090503_190918_000002172078_00385_37513_4537.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090503_192907_000003682078_00385_37513_4535.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090503_193653_000001142078_00386_37514_4539.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090503_194025_000003202078_00386_37514_4541.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

Analysing APM products...

Writing file ./RESULTS/DAILY/090503/AUXILIARY/Check_ADFs_APM.xls...

Writing file ./RESULTS/DAILY/090503/AUXILIARY/Check_ADFs_APM.txt...

ASA_APM_1PNPDE20090503_043130_000000702078_00377_37505_9162.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20090503_062349_000000422078_00378_37506_9191.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20090503_150131_000000432078_00383_37511_9474.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

Analysing IMM products...

Writing file ./RESULTS/DAILY/090503/AUXILIARY/Check_ADFs_IMM.xls...

Writing file ./RESULTS/DAILY/090503/AUXILIARY/Check_ADFs_IMM.txt...

ASA_IMM_1PNPDE20090503_003111_000003812078_00374_37502_8699.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_003811_000000632078_00374_37502_8663.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_003811_000003422078_00374_37502_8796.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_004013_000002202078_00374_37502_8695.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_015345_000000452078_00375_37503_8801.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_021443_000004822078_00375_37503_8823.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_021443_000005012078_00375_37503_8996.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_024112_000000772078_00375_37503_8985.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_025611_000000382078_00376_37504_8855.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_030444_000000362078_00376_37504_8890.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_035356_000000822078_00376_37504_8990.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_035500_000000182078_00376_37504_8983.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_035734_000001812078_00376_37504_9179.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_035734_000005002078_00376_37504_9183.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_040136_000001802078_00376_37504_9180.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_040537_000000182078_00376_37504_9154.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_042332_000000762078_00376_37504_9055.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_053338_000001402078_00377_37505_9171.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_053540_000000192078_00377_37505_9160.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_053638_000003222078_00377_37505_9247.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_054213_000000622078_00377_37505_9208.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_054213_000001942078_00377_37505_9336.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_054415_000000612078_00377_37505_9212.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_064625_000000372078_00378_37506_9193.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_071502_000001222078_00378_37506_9341.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_071502_000002612078_00378_37506_9349.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_082909_000000372078_00379_37507_9343.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_100446_000000372078_00380_37508_9362.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_103512_000004422078_00380_37508_9415.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_104207_000001472078_00380_37508_9413.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

ASA_IMM_1PNPDE20090503_121506_000002392078_00381_37509_9445.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_135712_000000822078_00382_37510_9468.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_143140_000000832078_00383_37511_9482.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_150541_000000382078_00383_37511_9476.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_171940_000002612078_00384_37512_9546.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_172044_000001192078_00384_37512_9544.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_172343_000000182078_00384_37512_9536.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_175609_000001422078_00385_37513_9552.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_182557_000001452078_00385_37513_9594.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_190045_000002522078_00385_37513_9600.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_190545_000002022078_00385_37513_9570.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_201437_000000502078_00386_37514_9609.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_204022_000001362078_00386_37514_9710.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_221002_000000832078_00387_37515_9856.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_221133_000000822078_00387_37515_9862.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_221935_000001992078_00387_37515_9877.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_222435_000000822078_00387_37515_9879.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_222538_000000192078_00387_37515_9745.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_225834_000000532078_00388_37516_9858.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_225950_000000532078_00388_37516_9860.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090503_235952_000000822078_00388_37516_0008.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20090503_072202_000000632078_00378_37506_3715.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20090503_072202_000002022078_00378_37506_3916.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20090503_072404_000000792078_00378_37506_3742.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20090503_081232_000000922078_00379_37507_3713.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20090503_100106_000001572078_00380_37508_3875.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20090503_121910_0000005062078_00381_37509_4406.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20090503_123725_000000362078_00381_37509_4130.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20090503_145054_000000832078_00383_37511_4255.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20090503_180739_000000362078_00385_37513_4433.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

Analysing WSM products...

Writing file ./RESULTS/DAILY/090503/AUXILIARY/Check_ADFs_WSM.xls...

Writing file ./RESULTS/DAILY/090503/AUXILIARY/Check_ADFs_WSM.txt...

ASA_WSM_1PNPDE20090503_011948_000000732078_00375_37503_8825.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090503_011948_000004162078_00375_37503_9022.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090503_012203_000002812078_00375_37503_8892.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090503_025152_000000732078_00376_37504_8955.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090503_025152_000002132078_00376_37504_9066.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090503_025406_000000792078_00376_37504_8994.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090503_030051_000001342078_00376_37504_9010.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090503_030051_000001522078_00376_37504_9012.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090503_032123_000003732078_00376_37504_8992.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090503_050940_000001222078_00377_37505_9169.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090503_070623_000000922078_00378_37506_9334.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090503_083100_000000912078_00379_37507_9360.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090503_100953_000002502078_00380_37508_9403.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090503_100953_000003672078_00380_37508_9411.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090503_101505_000000552078_00380_37508_9379.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090503_115803_000003542078_00381_37509_9453.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090503_132056_000000982078_00382_37510_9490.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090503_142709_000000732078_00382_37510_9466.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090503_145841_000000912078_00383_37511_9500.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090503_150714_000001902078_00383_37511_9502.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090503_161420_000002262078_00384_37512_9504.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090503_163502_000001832078_00384_37512_9550.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090503_163837_000001532078_00384_37512_9554.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090503_164513_000000912078_00384_37512_9548.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090503_181527_000001522078_00385_37513_9556.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090503_181722_000000982078_00385_37513_9596.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090503_181929_000001902078_00385_37513_9598.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090503_193519_000000922078_00386_37514_9724.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090503_195452_000001592078_00386_37514_9728.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK


```
ASA_WSM_1PNPDE20090503_195606_00000842078_00386_37514_9722.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090503_205819_000002752078_00386_37514_9726.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090503_213422_00000982078_00387_37515_9875.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090503_213714_000001522078_00387_37515_9891.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090503_231235_00000732078_00388_37516_0013.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090503_231235_000002692078_00388_37516_0079.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090503_231450_000001332078_00388_37516_0041.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```

AUXILIARY FILES ANALYSIS completed

#####

MODULE STEPPING ANALYSIS

#####

Analysis will be performed from 2009-05-03 00:00:00 to 2009-05-03 23:59:59

Results will be exported to the directory: ./RESULTS/DAILY/090503/MODULE_STEPPING

Creating directory ./RESULTS/DAILY/090503/MODULE_STEPPING...

Creating directory ./RESULTS/DAILY/090503/MODULE_STEPPING/FIRST_REFERENCE...

Creating directory ./RESULTS/DAILY/090503/MODULE_STEPPING/SECOND_REFERENCE...

Creating directory ./RESULTS/DAILY/090503/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE...

Deleting old files...

Creating images comparing with second reference...

Exporting results to the directory ../../RESULTS/DAILY/090503/MODULE_STEPPING/SECOND_REFERENCE...

Polarization: H

Reference product: ASA_MS_0PNPDK20050922_062651_00000152041_00034_18625_0041.N1

Test product: ASA_MS_0PNPDK20090502_060339_00000162078_00363_37491_0799.N1

H

H

../../RESULTS/DAILY/090503/MODULE_STEPPING/SECOND_REFERENCE/TGH_20090502_060339-20050922_062651.png

../../RESULTS/DAILY/090503/MODULE_STEPPING/SECOND_REFERENCE/TPH_20090502_060339-20050922_062651.png

../../RESULTS/DAILY/090503/MODULE_STEPPING/SECOND_REFERENCE/RGH_20090502_060339-20050922_062651.png

../../RESULTS/DAILY/090503/MODULE_STEPPING/SECOND_REFERENCE/RPH_20090502_060339-20050922_062651.png

Polarization: V

Reference product: ASA_MS_0PNPDK20050923_055514_00000152041_00048_18639_0042.N1

Test product: ASA_MS_0PNPDE20090503_053202_00000162078_00377_37505_0414.N1

V

V

../../RESULTS/DAILY/090503/MODULE_STEPPING/SECOND_REFERENCE/TGV_20090503_053202-20050923_055514.png

../../RESULTS/DAILY/090503/MODULE_STEPPING/SECOND_REFERENCE/TPV_20090503_053202-20050923_055514.png

../../RESULTS/DAILY/090503/MODULE_STEPPING/SECOND_REFERENCE/RGV_20090503_053202-20050923_055514.png

../../RESULTS/DAILY/090503/MODULE_STEPPING/SECOND_REFERENCE/RPV_20090503_053202-20050923_055514.png

Creating images comparing with previous product reference...

Exporting results to the directory ../../RESULTS/DAILY/090503/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE...

Polarization: H

Reference product: ASA_MS_0PNPDK20090430_070653_00000162078_00335_37463_0797.N1

Test product: ASA_MS_0PNPDK20090502_060339_00000162078_00363_37491_0799.N1

H

H

../../RESULTS/DAILY/090503/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TGH_20090502_060339-20090430_070653.png

../../RESULTS/DAILY/090503/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TPH_20090502_060339-20090430_070653.png

../../RESULTS/DAILY/090503/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RGH_20090502_060339-20090430_070653.png

../../RESULTS/DAILY/090503/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RPH_20090502_060339-20090430_070653.png

Polarization: V
Reference product: ASA_MS_0PNPDK20090501_063516_000000162078_00349_37477_0798.N1
Test product: ASA_MS_0PNPDE20090503_053202_000000162078_00377_37505_0414.N1

V
V

../../RESULTS/DAILY/090503/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TGV_20090503_053202-20090501_063516.png
../../RESULTS/DAILY/090503/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TPV_20090503_053202-20090501_063516.png
../../RESULTS/DAILY/090503/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RGV_20090503_053202-20090501_063516.png
../../RESULTS/DAILY/090503/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RPV_20090503_053202-20090501_063516.png

MODULE_STEPPING ANALYSIS completed

#####

CALIBRATION PULSES ANALYSIS

#####

Creating directory ./RESULTS/DAILY/090503/CALIBRATION_PULSES...

ALL ROWS Analysis will be performed from 2009-05-03 00:00:00 to 2009-05-03 23:59:59

Analysing products WVS IS2 V/V

Writing image ../../RESULTS/DAILY/090503//CALIBRATION_PULSES/Calibration_pulses_all_rows_WVS_IS2_VV.png...

Analysing products GM1 SS3 H/H

Writing image ../../RESULTS/DAILY/090503//CALIBRATION_PULSES/Calibration_pulses_all_rows_GM1_SS3_HH.png...

TEMPORAL EVOLUTION Analysis will be performed from 2009-05-03 00:00:00 to 2009-05-03 23:59:59

Analysing products WVS IS2 V/V

Getting calibration pulses data for WVS IS2 V/V from 2009-05-03 00:00:00 to 2009-05-03 23:59:59. Rows: 1/5/9/13/17/21/25/29

Writing file ./RESULTS/DAILY/090503/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2009-05-03_1.dat...

Writing ../../RESULTS/DAILY/090503//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_1.png...

Writing ../../RESULTS/DAILY/090503//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_1.png...

Getting calibration pulses data for WVS IS2 V/V from 2009-05-03 00:00:00 to 2009-05-03 23:59:59. Rows: 2/6/10/14/18/22/26/30

Writing file ./RESULTS/DAILY/090503/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2009-05-03_2.dat...

Writing ../../RESULTS/DAILY/090503//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_2.png...

Writing ../../RESULTS/DAILY/090503//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_2.png...

Getting calibration pulses data for WVS IS2 V/V from 2009-05-03 00:00:00 to 2009-05-03 23:59:59. Rows: 3/7/11/15/19/23/27/31

Writing file ./RESULTS/DAILY/090503/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2009-05-03_3.dat...

Writing ../../RESULTS/DAILY/090503//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_3.png...

Writing ../../RESULTS/DAILY/090503//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_3.png...

Getting calibration pulses data for WVS IS2 V/V from 2009-05-03 00:00:00 to 2009-05-03 23:59:59. Rows: 4/8/12/16/20/24/28/32

Writing file ./RESULTS/DAILY/090503/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2009-05-03_4.dat...

Writing ../../RESULTS/DAILY/090503//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_4.png...

Writing ../../RESULTS/DAILY/090503//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_4.png...

Analysing products GM1 SS3 H/H

Getting calibration pulses data for GM1 SS3 H/H from 2009-05-03 00:00:00 to 2009-05-03 23:59:59. Rows: 1/5/9/13/17/21/25/29

Writing file ./RESULTS/DAILY/090503/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2009-05-03_1.dat...

Writing ../../RESULTS/DAILY/090503//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_1.png...

Writing ../../RESULTS/DAILY/090503//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_1.png...

Getting calibration pulses data for GM1 SS3 H/H from 2009-05-03 00:00:00 to 2009-05-03 23:59:59. Rows: 2/6/10/14/18/22/26/30

Writing file ./RESULTS/DAILY/090503/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2009-05-03_2.dat...
Writing ../../RESULTS/DAILY/090503//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_2.png...
Writing ../../RESULTS/DAILY/090503//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_2.png...

Getting calibration pulses data for GM1 SS3 H/H from 2009-05-03 00:00:00 to 2009-05-03 23:59:59. Rows: 3/7/11/15/19/23/27/31
Writing file ./RESULTS/DAILY/090503/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2009-05-03_3.dat...
Writing ../../RESULTS/DAILY/090503//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_3.png...
Writing ../../RESULTS/DAILY/090503//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_3.png...

Getting calibration pulses data for GM1 SS3 H/H from 2009-05-03 00:00:00 to 2009-05-03 23:59:59. Rows: 4/8/12/16/20/24/28/32
Writing file ./RESULTS/DAILY/090503/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2009-05-03_4.dat...
Writing ../../RESULTS/DAILY/090503//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_4.png...
Writing ../../RESULTS/DAILY/090503//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_4.png...

CALIBRATION PULSES ANALYSIS completed
#####

DOPPLER ANALYSIS
#####

Creating directory ./RESULTS/DAILY/090503/DOPPLER...

DOPPLER ANX Analysis will be performed from 2009-05-03 00:00:00 to 2009-05-03 23:59:59

Analysing products WVS IS2 V/V
Getting doppler data for WVS IS2 V/V from 2009-05-03 00:00:00 to 2009-05-03 23:59:59...
Writing file ./RESULTS/DAILY/090503/DOPPLER/Doppler_data_WVS_IS2_VV_2009-05-03.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/090503/DOPPLER/DOPPLER_ANX_WVS_IS2_VV.png...

Analysing products GM1 SS1 H/H
Getting doppler data for GM1 SS1 H/H from 2009-05-03 00:00:00 to 2009-05-03 23:59:59...
Writing file ./RESULTS/DAILY/090503/DOPPLER/Doppler_data_GM1_SS1_HH_2009-05-03.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/090503/DOPPLER/DOPPLER_ANX_GM1_SS1_HH.png...

DOPPLER JUMPS Analysis will be performed on WSM products from 2009-05-03 00:00:00 to 2009-05-03 23:59:59

Analysing by default products WSM
Getting doppler jumps data for WSM from 2009-05-03 00:00:00 to 2009-05-03 23:59:59...
Writing file ./RESULTS/DAILY/090503/DOPPLER/Doppler_Jumps_data_WSM_2009-05-03.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/090503/DOPPLER/DOPPLER_JUMPS_ANX_WSM.png...
Writing file ../../RESULTS/DAILY/090503/DOPPLER/DOPPLER_JUMPS_Date_WSM.png...

DOPPLER MAP Analysis will be performed from 2009-05-03 00:00:00 to 2009-05-03 23:59:59

Analysing products WVS IS2 V/V
Loading predicted doppler values....
Phase: descending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -36.124366 Hz

Writing file ../../RESULTS/DAILY/090503//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_WVS_IS2_VV_desc.jpg...
Writing file ../../RESULTS/DAILY/090503//DOPPLER/DOPPLER_Absolute_WVS_IS2_VV_desc.jpg...

Loading predicted doppler values....
Phase: ascending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -30.964295 Hz
Writing file ../../RESULTS/DAILY/090503//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_WVS_IS2_VV_asc.jpg...
Writing file ../../RESULTS/DAILY/090503//DOPPLER/DOPPLER_Absolute_WVS_IS2_VV_asc.jpg...

Analysing products GM1 SS1 H/H
Loading predicted doppler values....
Phase: descending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -20.810933 Hz
Writing file ../../RESULTS/DAILY/090503//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_GM1_SS1_HH_desc.jpg...
Writing file ../../RESULTS/DAILY/090503//DOPPLER/DOPPLER_Absolute_GM1_SS1_HH_desc.jpg...

Loading predicted doppler values....
Phase: ascending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -25.417765 Hz
Writing file ../../RESULTS/DAILY/090503//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_GM1_SS1_HH_asc.jpg...
Writing file ../../RESULTS/DAILY/090503//DOPPLER/DOPPLER_Absolute_GM1_SS1_HH_asc.jpg...

DOPPLER ANALYSIS completed
#####

CHIRP ANALYSIS

Creating directory ./RESULTS/DAILY/090503/CHIRP...

CHIRP Analysis will be performed from 2009-05-03 00:00:00 to 2009-05-03 23:59:59

Analysing products WSM SS1 H/H

Getting ScaleFactor data for WSM SS1 H/H from 2009-05-03 00:00:00 to 2009-05-03 23:59:59...
Writing file ./RESULTS/DAILY/090503/CHIRP/ScaleFactor_data_WSM_SS1_HH_2009-05-03.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/090503/CHIRP/ScaleFactor_ANX_WSM_SS1_HH.png...
Writing file ../../RESULTS/DAILY/090503/CHIRP/ScaleFactor_DATE_WSM_SS1_HH.png...

Analysing products WSM SS1 V/V

Getting ScaleFactor data for WSM SS1 V/V from 2009-05-03 00:00:00 to 2009-05-03 23:59:59...
Writing file ./RESULTS/DAILY/090503/CHIRP/ScaleFactor_data_WSM_SS1_VV_2009-05-03.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/090503/CHIRP/ScaleFactor_ANX_WSM_SS1_VV.png...
Writing file ../../RESULTS/DAILY/090503/CHIRP/ScaleFactor_DATE_WSM_SS1_VV.png...

CHIRP ANALYSIS completed
#####

RAW DATA ANALYSIS
#####

Analysis will be performed from 2009-05-03 00:00:00 to 2009-05-03 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/090503/RAW_DATA

Creating directory ./RESULTS/DAILY/090503/RAW_DATA...

Getting raw data for WVS from 2009-05-03 00:00:00 to 2009-05-03 23:59:59...
Writing file ./RESULTS/DAILY/090503/RAW_DATA/Raw_data_WVS_2009-05-03.dat...
Running IDL program to create graphs...

Creating image ../RESULTS/DAILY/090503/RAW_DATA/Raw_data_WVS_input_mean.png...
Creating image ../RESULTS/DAILY/090503/RAW_DATA/Raw_data_WVS_input_stdev.png...
Creating image ../RESULTS/DAILY/090503/RAW_DATA/Raw_data_WVS_gain_imbalance.png...

Getting raw data for IMM from 2009-05-03 00:00:00 to 2009-05-03 23:59:59...
Writing file ./RESULTS/DAILY/090503/RAW_DATA/Raw_data_IMM_2009-05-03.dat...
Running IDL program to create graphs...

Creating image ../RESULTS/DAILY/090503/RAW_DATA/Raw_data_IMM_input_mean.png...
Creating image ../RESULTS/DAILY/090503/RAW_DATA/Raw_data_IMM_input_stdev.png...
Creating image ../RESULTS/DAILY/090503/RAW_DATA/Raw_data_IMM_gain_imbalance.png...

RAW DATA ANALYSIS completed
#####

TELEMETRY ANALYSIS
#####

Analysis will be performed from 2009-05-03 00:00:00 to 2009-05-03 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/090503/TELEMETRY

Creating directory ./RESULTS/DAILY/090503/TELEMETRY...

Looking for gaps and missing lines in WVS products...

Checking 30 products from PDE...
Checking 21 products from PDK...

Looking for gaps and missing lines in GM1 products...

Checking 37 products from PDE...
Checking 38 products from PDK...

Looking for gaps and missing lines in APM products...

Checking 3 products from PDE...
No products from PDK...

Looking for gaps and missing lines in IMM products...

Checking 51 products from PDE...
Checking 9 products from PDK...

Looking for gaps and missing lines in WSM products...

Checking 36 products from PDE...

Found product...ASA_WSM_1PNPDE20090503_161420_000002262078_00384_37512_9504.N1 / 0 gaps / 50 missing lines
No products from PDK...

Creating graph of missing lines and gaps...

Creating image: ./RESULTS/DAILY/090503/TELEMETRY/TELEMETRY_Missing_lines.png...

Creating image: ./RESULTS/DAILY/090503/TELEMETRY/TELEMETRY_Gaps.png...

TELEMETRY ANALYSIS completed

#####

BROWSE PRODUCTS ANALYSIS

#####

Analysis will be performed on 2009-05-03

Scanning directory /nas3/ENVISAT/ASAR//ASA_GM_BP...

Results will be exported to the directory: /nas3/ENVISAT/ASAR//ASA_GM_BP/JPG/20090503/

Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDE20090503_195733_000003682078_00386_37514_9605.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDE20090503_203728_000001752078_00386_37514_9603.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDE20090503_204253_000006342078_00386_37514_9634.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDE20090503_210256_000010152078_00386_37514_9840.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDE20090503_213948_000002532078_00387_37515_9755.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDE20090503_221804_000000902078_00387_37515_9751.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDE20090503_222308_000000902078_00387_37515_9753.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDE20090503_222608_000004772078_00387_37515_9763.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDE20090503_225216_000003802078_00388_37516_9903.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDE20090503_231709_000005552078_00388_37516_9908.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDE20090503_234610_000002892078_00388_37516_9910.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDE20090503_235103_000000902078_00388_37516_9912.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_GM_BP/ASA_GM_BPZPDE20090503_235839_000000722078_00388_37516_9917.N1 ...

ANALYSIS COMPLETED: 13 GM browse products to see...

Scanning directory /nas3/ENVISAT/ASAR//ASA_AP_BP...

Results will be exported to the directory: /nas3/ENVISAT/ASAR//ASA_AP_BP/JPG/20090503/

Stripping browse product /nas3/ENVISAT/ASAR//ASA_AP_BP/ASA_AP_BPZPDE20090503_150131_000000432078_00383_37511_9475.N1 ...

ANALYSIS COMPLETED: 1 AP browse products to see...

Scanning directory /nas3/ENVISAT/ASAR//ASA_IM_BP...

Results will be exported to the directory: /nas3/ENVISAT/ASAR//ASA_IM_BP/JPG/20090503/

Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20090503_100446_000000372078_00380_37508_9363.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20090503_103512_000004422078_00380_37508_9416.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20090503_104207_000001472078_00380_37508_9414.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20090503_121506_000002392078_00381_37509_9446.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20090503_135712_000000822078_00382_37510_9469.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20090503_143140_000000832078_00383_37511_9483.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20090503_150541_000000382078_00383_37511_9477.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20090503_171940_000002612078_00384_37512_9547.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20090503_172044_000001192078_00384_37512_9545.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20090503_172343_000000182078_00384_37512_9537.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20090503_175609_000001422078_00385_37513_9553.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20090503_182557_000001452078_00385_37513_9595.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20090503_190045_000002522078_00385_37513_9601.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20090503_190545_000002022078_00385_37513_9571.N1 ...
Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20090503_201437_000000502078_00386_37514_9610.N1 ...



Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20090503_204022_000001362078_00386_37514_9711.N1 ...
 Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20090503_221002_000000832078_00387_37515_9857.N1 ...
 Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20090503_221133_000000822078_00387_37515_9863.N1 ...
 Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20090503_221935_000001992078_00387_37515_9878.N1 ...
 Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20090503_222435_000000822078_00387_37515_9880.N1 ...
 Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20090503_222538_000000192078_00387_37515_9746.N1 ...
 Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20090503_225834_000000532078_00388_37516_9859.N1 ...
 Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20090503_225950_000000532078_00388_37516_9861.N1 ...
 Stripping browse product /nas3/ENVISAT/ASAR//ASA_IM_BP/ASA_IM_BPZPDE20090503_235952_000000822078_00388_37516_0009.N1 ...

ANALYSIS COMPLETED: 24 IM browse products to see...

 Scanning directory /nas3/ENVISAT/ASAR//ASA_WS_BP...
 Results will be exported to the directory: /nas3/ENVISAT/ASAR//ASA_WS_BP/JPG/20090503/

Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20090503_100953_000002502078_00380_37508_9404.N1 ...
 Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20090503_100953_000003672078_00380_37508_9412.N1 ...
 Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20090503_101505_000000552078_00380_37508_9380.N1 ...
 Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20090503_115803_000003542078_00381_37509_9454.N1 ...
 Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20090503_132056_000000982078_00382_37510_9491.N1 ...
 Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20090503_142709_000000732078_00382_37510_9467.N1 ...
 Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20090503_145841_000000912078_00383_37511_9501.N1 ...
 Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20090503_150714_000001902078_00383_37511_9503.N1 ...
 Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20090503_161420_000002262078_00384_37512_9505.N1 ...
 Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20090503_163502_000001832078_00384_37512_9551.N1 ...
 Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20090503_163837_000001532078_00384_37512_9555.N1 ...
 Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20090503_164513_000000912078_00384_37512_9549.N1 ...
 Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20090503_181527_000001522078_00385_37513_9557.N1 ...
 Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20090503_181722_000000982078_00385_37513_9597.N1 ...
 Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20090503_181929_000001902078_00385_37513_9599.N1 ...
 Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20090503_193519_000000922078_00386_37514_9725.N1 ...
 Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20090503_195452_000001592078_00386_37514_9729.N1 ...
 Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20090503_195606_000000842078_00386_37514_9723.N1 ...
 Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20090503_205819_000002752078_00386_37514_9727.N1 ...
 Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20090503_213422_000000982078_00387_37515_9876.N1 ...
 Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20090503_213714_000001522078_00387_37515_9892.N1 ...
 Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20090503_231235_000000732078_00388_37516_0014.N1 ...
 Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20090503_231235_000002692078_00388_37516_0080.N1 ...
 Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDE20090503_231450_000001332078_00388_37516_0042.N1 ...
 Stripping browse product /nas3/ENVISAT/ASAR//ASA_WS_BP/ASA_WS_BPZPDK20090503_195050_000003062078_00386_37514_4652.N1 ...

ANALYSIS COMPLETED: 25 WS browse products to see...

BROWSE PRODUCTS ANALYSIS completed
 #####

HTML REPORT generation
 #####

Building file ./RESULTS/DAILY/090503/asarReport.html...
 Building DATA SUMMARY section...
 Building AUXILIARY FILES ANALYSIS section...
 Building MODULE STEPPING ANALYSIS section...
 Building CALIBRATION PULSES ANALYSIS section...
 Building DOPPLER ANALYSIS section...
 Building CHIRP ANALYSIS section...
 Building RAW DATA ANALYSIS section...
 Building TELEMETRY ANALYSIS section...

HTML REPORT generation completed
 #####



ASAR Daily Report



Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
ASA_APM_1PNPDE20090503_043130_000000702078_00377_37505_9162.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20090503_062349_000000422078_00378_37506_9191.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20090503_150131_000000432078_00383_37511_9474.N1	OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_GM1_1PNPDE20090503_001753_000003082078_00374_37502_8575.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090503_004403_000001382078_00374_37502_8577.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090503_005811_000002772078_00374_37502_8704.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090503_012649_000010322078_00375_37503_8794.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090503_021052_000002292078_00375_37503_8864.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090503_022315_000002172078_00375_37503_8862.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090503_023259_000004952078_00375_37503_8857.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090503_024240_000002712078_00375_37503_8873.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090503_025700_000002292078_00376_37504_8868.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090503_030325_000000782078_00376_37504_8866.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090503_030534_000009302078_00376_37504_8885.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090503_032745_000001442078_00376_37504_8883.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090503_035128_000001502078_00376_37504_9059.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090503_035529_000001262078_00376_37504_9057.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090503_040605_000000842078_00376_37504_9053.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090503_040828_000001322078_00376_37504_9033.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090503_042848_000001632078_00377_37505_9031.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090503_043302_000021932078_00377_37505_9164.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090503_054539_000001442078_00377_37505_9219.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090503_061915_000002712078_00378_37506_9221.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090503_062452_000004652078_00378_37506_9233.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090503_063618_000006102078_00378_37506_9238.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090503_064713_000005792078_00378_37506_9240.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090503_065751_000002952078_00378_37506_9249.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090503_195733_000003682078_00386_37514_9604.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090503_203728_000001752078_00386_37514_9602.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090503_204253_000006342078_00386_37514_9633.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090503_210256_000010152078_00386_37514_9839.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090503_213948_000002532078_00387_37515_9754.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090503_221804_000000902078_00387_37515_9750.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090503_222308_000000902078_00387_37515_9752.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090503_222608_000004772078_00387_37515_9762.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090503_225216_000003802078_00388_37516_9902.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090503_231709_000005552078_00388_37516_9907.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090503_234610_000002892078_00388_37516_9909.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090503_235103_000000902078_00388_37516_9911.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090503_235839_000000722078_00388_37516_9916.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090503_071240_000001442078_00378_37506_3653.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090503_071935_000001502078_00378_37506_3658.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090503_072535_000001872078_00378_37506_3660.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090503_080205_000006282078_00379_37507_3674.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090503_081923_000002172078_00379_37507_3750.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090503_083236_000005862078_00379_37507_3752.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090503_085316_000009302078_00379_37507_3759.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090503_094347_000005372078_00380_37508_3841.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090503_103352_000000842078_00380_37508_3907.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090503_104445_000003082078_00380_37508_3912.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090503_112116_000007122078_00381_37509_3914.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090503_122746_000001632078_00381_37509_4043.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090503_123813_000003862078_00381_37509_4051.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090503_125919_000008882078_00382_37510_4113.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090503_131325_000004162078_00382_37510_4144.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090503_133604_000006762078_00382_37510_4146.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090503_134728_000003562078_00382_37510_4150.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090503_135504_000001262078_00382_37510_4148.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090503_135845_000007432078_00382_37510_4161.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090503_141833_000002652078_00382_37510_4166.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090503_143411_000007972078_00383_37511_4236.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090503_145228_000000782078_00383_37511_4295.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090503_150015_000000782078_00383_37511_4293.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090503_150234_000001872078_00383_37511_4297.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090503_153540_000009302078_00383_37511_4303.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090503_161810_000004772078_00384_37512_4313.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090503_164111_000002352078_00384_37512_4410.N1					OK	OK	OK	OK

ASA_GM1_1PNPDK20090503_164647_000004412078_00384_37512_4415.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20090503_171616_000002052078_00384_37512_4413.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20090503_172413_000004832078_00384_37512_4420.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20090503_175842_000005372078_00385_37513_4427.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20090503_180628_000000722078_00385_37513_4526.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20090503_182259_000001812078_00385_37513_4528.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20090503_185652_000002352078_00385_37513_4530.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20090503_190918_000002172078_00385_37513_4537.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20090503_192907_000003682078_00385_37513_4535.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20090503_193653_000001142078_00386_37514_4539.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20090503_194025_000003202078_00386_37514_4541.N1	OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_IMM_1PNPDE20090503_003111_000003812078_00374_37502_8699.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_003811_000000632078_00374_37502_8663.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_003811_000003422078_00374_37502_8796.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_004013_000002202078_00374_37502_8695.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_015345_000000452078_00375_37503_8801.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_021443_000004822078_00375_37503_8823.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_021443_000005012078_00375_37503_8996.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_024112_000000772078_00375_37503_8985.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_025611_000000382078_00376_37504_8855.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_030444_000000362078_00376_37504_8890.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_035356_000000822078_00376_37504_8990.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_035500_000000182078_00376_37504_8983.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_035734_000001812078_00376_37504_9179.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_035734_000005002078_00376_37504_9183.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_040136_000001802078_00376_37504_9180.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_040537_000000182078_00376_37504_9154.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_042332_000000762078_00376_37504_9055.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_053338_000001402078_00377_37505_9171.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_053540_000000192078_00377_37505_9160.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_053638_000003222078_00377_37505_9247.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_054213_000000622078_00377_37505_9208.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_054213_000001942078_00377_37505_9336.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_054415_000000612078_00377_37505_9212.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_064625_000000372078_00378_37506_9193.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_071502_000001222078_00378_37506_9341.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_071502_000002612078_00378_37506_9349.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_082909_000000372078_00379_37507_9343.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_100446_000000372078_00380_37508_9362.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_103512_000004422078_00380_37508_9415.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_104207_000001472078_00380_37508_9413.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_121506_000002392078_00381_37509_9445.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_135712_000000822078_00382_37510_9468.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_143140_000000832078_00383_37511_9482.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_150541_000000382078_00383_37511_9476.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_171940_000002612078_00384_37512_9546.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_172044_000001192078_00384_37512_9544.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_172343_000000182078_00384_37512_9536.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_175609_000001422078_00385_37513_9552.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_182557_000001452078_00385_37513_9594.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_190045_000002522078_00385_37513_9600.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_190545_000002022078_00385_37513_9570.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_201437_000000502078_00386_37514_9609.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_204022_000001362078_00386_37514_9710.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_221002_000000832078_00387_37515_9856.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_221133_000000822078_00387_37515_9862.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_221935_000001992078_00387_37515_9877.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_222435_000000822078_00387_37515_9879.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_222538_00000192078_00387_37515_9745.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_225834_000000532078_00388_37516_9858.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_225950_000000532078_00388_37516_9860.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090503_235952_000000822078_00388_37516_0008.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20090503_072202_000000632078_00378_37506_3715.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20090503_072202_000002022078_00378_37506_3916.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20090503_072404_000000792078_00378_37506_3742.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20090503_081232_000000922078_00379_37507_3713.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20090503_100106_000001572078_00380_37508_3875.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20090503_121910_000005062078_00381_37509_4406.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20090503_123725_000000362078_00381_37509_4130.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20090503_145054_000000832078_00383_37511_4255.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20090503_180739_000000362078_00385_37513_4433.N1					OK	OK	OK	OK


Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WSM_1PNPDE20090503_011948_000000732078_00375_37503_8825.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090503_011948_000004162078_00375_37503_9022.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090503_012203_000002812078_00375_37503_8892.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090503_025152_000000732078_00376_37504_8955.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090503_025152_000002132078_00376_37504_9066.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090503_025406_000000792078_00376_37504_8994.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090503_030051_000001342078_00376_37504_9010.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090503_030051_000001522078_00376_37504_9012.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090503_032123_000003732078_00376_37504_8992.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090503_050940_000001222078_00377_37505_9169.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090503_070623_000000922078_00378_37506_9334.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090503_083100_000000912078_00379_37507_9360.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090503_100953_000002502078_00380_37508_9403.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090503_100953_000003672078_00380_37508_9411.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090503_101505_000000552078_00380_37508_9379.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090503_115803_000003542078_00381_37509_9453.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090503_132056_000000982078_00382_37510_9490.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090503_142709_000000732078_00382_37510_9466.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090503_145841_000000912078_00383_37511_9500.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090503_150714_000001902078_00383_37511_9502.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090503_161420_000002262078_00384_37512_9504.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090503_163502_000001832078_00384_37512_9550.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090503_163837_000001532078_00384_37512_9554.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090503_164513_000000912078_00384_37512_9548.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090503_181527_000001522078_00385_37513_9556.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090503_181722_000000982078_00385_37513_9596.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090503_181929_000001902078_00385_37513_9598.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090503_193519_000000922078_00386_37514_9724.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090503_195452_000001592078_00386_37514_9728.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090503_195606_000000842078_00386_37514_9722.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090503_205819_000002752078_00386_37514_9726.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090503_213422_000000982078_00387_37515_9875.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090503_213714_000001522078_00387_37515_9891.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090503_231235_000000732078_00388_37516_0013.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090503_231235_000002692078_00388_37516_0079.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090503_231450_000001332078_00388_37516_0041.N1					OK	OK	OK	OK


Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WVS_1PNPDE20090503_002303_000003902078_00374_37502_8573.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090503_004621_000004052078_00374_37502_8580.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090503_005221_000002992078_00374_37502_8702.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090503_010251_000009292078_00374_37502_8707.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090503_014405_000000442078_00375_37503_8710.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090503_014758_000003142078_00375_37503_8713.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090503_015437_000009292078_00375_37503_8721.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090503_020937_000000302078_00375_37503_8860.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090503_022657_000003152078_00375_37503_8871.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090503_024714_000002392078_00376_37504_8876.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090503_033012_000002842078_00376_37504_9456.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090503_034427_000001802078_00376_37504_9036.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090503_041040_000007342078_00376_37504_9051.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090503_042454_000001942078_00377_37505_9029.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090503_051141_000008842078_00377_37505_9069.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090503_052611_000003152078_00377_37505_9217.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090503_054809_000018292078_00377_37505_9252.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090503_070251_000001642078_00378_37506_9236.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090503_200341_000006142078_00386_37514_9607.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090503_201533_000012742078_00386_37514_9620.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090503_205332_000000302078_00386_37514_9617.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090503_205332_000002402078_00386_37514_9741.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090503_214401_000015292078_00387_37515_9748.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090503_221301_000002552078_00387_37515_9757.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090503_223408_000003302078_00387_37515_9760.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090503_223853_000007642078_00387_37515_9898.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090503_230048_000003892078_00388_37516_9905.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090503_232625_000011392078_00388_37516_9914.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090503_235235_000003152078_00388_37516_9919.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090503_070753_000002402078_00378_37506_3656.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090503_072845_000019492078_00378_37506_3677.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090503_084224_000006152078_00379_37507_3757.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090503_090921_000020242078_00379_37507_3767.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090503_101601_000010342078_00380_37508_3910.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090503_104957_000018292078_00380_37508_3924.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090503_114031_000010042078_00381_37509_4041.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090503_120355_000005852078_00381_37509_4046.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090503_123032_000003452078_00381_37509_4049.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090503_124440_000008402078_00381_37509_4122.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090503_132236_000007642078_00382_37510_4153.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090503_135329_000000452078_00382_37510_4156.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090503_141108_000004052078_00382_37510_4164.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090503_142259_000002092078_00382_37510_4159.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090503_142820_000001642078_00383_37511_4174.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090503_151044_000014542078_00383_37511_4301.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090503_155144_000013042078_00383_37511_4306.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090503_165410_000012742078_00384_37512_4418.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090503_173220_000013942078_00384_37512_4430.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090503_182853_000016342078_00385_37513_4533.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090503_191256_000009292078_00385_37513_4544.N1					OK	OK	OK	OK


Calibration pulses for GM1 SS3 H/H




Calibration pulses for GM1 SS3 H/H




Calibration pulses for GM1 SS3 H/H




Calibration pulses for GM1 SS3 H/H




Calibration pulses for WVS IS2 V/V




Calibration pulses for WVS IS2 V/V





Calibration pulses for WVS IS2 V/V





Calibration pulses for WVS IS2 V/V



















03-May
rows: _ 1 _ 5 _ 9 _ 13 _ 17 _ 21 _ 25 _ 29































Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_APM_1PNPDE20090503_043130_000000702078_00377_37505_9162.N1						IS6	H/H	78	37505	377	4.07
ASA_APM_1PNPDE20090503_062349_000000422078_00378_37506_9191.N1						IS3	H/H	78	37506	378	4.07
ASA_APM_1PNPDE20090503_150131_000000432078_00383_37511_9474.N1						IS1	H/H	78	37511	383	4.07

Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_GM1_1PNPDE20090503_001753_000003082078_00374_37502_8575.N1						SS1	H/H	78	37502	374	4.07
ASA_GM1_1PNPDE20090503_004403_000001382078_00374_37502_8577.N1						SS1	H/H	78	37502	374	4.07
ASA_GM1_1PNPDE20090503_005811_000002772078_00374_37502_8704.N1						SS1	H/H	78	37502	374	4.07
ASA_GM1_1PNPDE20090503_012649_000010322078_00375_37503_8794.N1						SS1	H/H	78	37503	375	4.07
ASA_GM1_1PNPDE20090503_021052_000002292078_00375_37503_8864.N1						SS1	H/H	78	37503	375	4.07
ASA_GM1_1PNPDE20090503_022315_000002172078_00375_37503_8862.N1						SS1	H/H	78	37503	375	4.07
ASA_GM1_1PNPDE20090503_023259_000004952078_00375_37503_8857.N1						SS1	H/H	78	37503	375	4.07
ASA_GM1_1PNPDE20090503_024240_000002712078_00375_37503_8873.N1						SS1	H/H	78	37503	375	4.07
ASA_GM1_1PNPDE20090503_025700_000002292078_00376_37504_8868.N1						SS1	H/H	78	37504	376	4.07
ASA_GM1_1PNPDE20090503_030325_000000782078_00376_37504_8866.N1						SS1	H/H	78	37504	376	4.07
ASA_GM1_1PNPDE20090503_030534_000009302078_00376_37504_8885.N1						SS1	H/H	78	37504	376	4.07
ASA_GM1_1PNPDE20090503_032745_000001442078_00376_37504_8883.N1						SS1	H/H	78	37504	376	4.07
ASA_GM1_1PNPDE20090503_035128_000001502078_00376_37504_9059.N1						SS1	H/H	78	37504	376	4.07
ASA_GM1_1PNPDE20090503_035529_000001262078_00376_37504_9057.N1						SS1	H/H	78	37504	376	4.07
ASA_GM1_1PNPDE20090503_040605_000000842078_00376_37504_9053.N1						SS1	H/H	78	37504	376	4.07
ASA_GM1_1PNPDE20090503_040828_000001322078_00376_37504_9033.N1						SS1	H/H	78	37504	376	4.07
ASA_GM1_1PNPDE20090503_042848_000001632078_00377_37505_9031.N1						SS1	H/H	78	37505	377	4.07
ASA_GM1_1PNPDE20090503_043302_000021932078_00377_37505_9164.N1						SS1	H/H	78	37505	377	4.07
ASA_GM1_1PNPDE20090503_054539_000001442078_00377_37505_9219.N1						SS1	H/H	78	37505	377	4.07
ASA_GM1_1PNPDE20090503_061915_000002712078_00378_37506_9221.N1						SS1	H/H	78	37506	378	4.07
ASA_GM1_1PNPDE20090503_062452_000004652078_00378_37506_9233.N1						SS1	H/H	78	37506	378	4.07
ASA_GM1_1PNPDE20090503_063618_000006102078_00378_37506_9238.N1						SS1	H/H	78	37506	378	4.07
ASA_GM1_1PNPDE20090503_064713_000005792078_00378_37506_9240.N1						SS1	H/H	78	37506	378	4.07
ASA_GM1_1PNPDE20090503_065751_000002952078_00378_37506_9249.N1						SS1	H/H	78	37506	378	4.07
ASA_GM1_1PNPDK20090503_071240_000001442078_00378_37506_3653.N1						SS1	H/H	78	37506	378	4.07
ASA_GM1_1PNPDK20090503_071935_000001502078_00378_37506_3658.N1						SS1	H/H	78	37506	378	4.07
ASA_GM1_1PNPDK20090503_072535_000001872078_00378_37506_3660.N1						SS1	H/H	78	37506	378	4.07
ASA_GM1_1PNPDK20090503_080205_000006282078_00379_37507_3674.N1						SS1	H/H	78	37507	379	4.07
ASA_GM1_1PNPDK20090503_081923_000002172078_00379_37507_3750.N1						SS1	H/H	78	37507	379	4.07
ASA_GM1_1PNPDK20090503_083236_000005862078_00379_37507_3752.N1						SS1	H/H	78	37507	379	4.07
ASA_GM1_1PNPDK20090503_085316_000009302078_00379_37507_3759.N1						SS1	H/H	78	37507	379	4.07
ASA_GM1_1PNPDK20090503_094347_000005372078_00380_37508_3841.N1						SS1	H/H	78	37508	380	4.07
ASA_GM1_1PNPDK20090503_103352_000000842078_00380_37508_3907.N1						SS1	H/H	78	37508	380	4.07
ASA_GM1_1PNPDK20090503_104445_000003082078_00380_37508_3912.N1						SS1	H/H	78	37508	380	4.07
ASA_GM1_1PNPDK20090503_112116_000007122078_00381_37509_3914.N1						SS1	H/H	78	37509	381	4.07
ASA_GM1_1PNPDK20090503_122746_000001632078_00381_37509_4043.N1						SS1	H/H	78	37509	381	4.07
ASA_GM1_1PNPDK20090503_123813_000003862078_00381_37509_4051.N1						SS1	H/H	78	37509	381	4.07
ASA_GM1_1PNPDK20090503_125919_000008882078_00382_37510_4113.N1						SS1	H/H	78	37510	382	4.07
ASA_GM1_1PNPDK20090503_131325_000004162078_00382_37510_4144.N1						SS1	H/H	78	37510	382	4.07
ASA_GM1_1PNPDK20090503_133604_000006762078_00382_37510_4146.N1						SS1	H/H	78	37510	382	4.07
ASA_GM1_1PNPDK20090503_134728_000003562078_00382_37510_4150.N1						SS1	H/H	78	37510	382	4.07
ASA_GM1_1PNPDK20090503_135504_000001262078_00382_37510_4148.N1						SS1	H/H	78	37510	382	4.07
ASA_GM1_1PNPDK20090503_135845_000007432078_00382_37510_4161.N1						SS1	H/H	78	37510	382	4.07
ASA_GM1_1PNPDK20090503_141833_000002652078_00382_37510_4166.N1						SS1	H/H	78	37510	382	4.07
ASA_GM1_1PNPDK20090503_143411_000007972078_00383_37511_4236.N1						SS1	H/H	78	37511	383	4.07
ASA_GM1_1PNPDK20090503_145228_000000782078_00383_37511_4295.N1						SS1	H/H	78	37511	383	4.07
ASA_GM1_1PNPDK20090503_150015_000000782078_00383_37511_4293.N1						SS1	H/H	78	37511	383	4.07
ASA_GM1_1PNPDK20090503_150234_000001872078_00383_37511_4297.N1						SS1	H/H	78	37511	383	4.07
ASA_GM1_1PNPDK20090503_153540_000009302078_00383_37511_4303.N1						SS1	H/H	78	37511	383	4.07
ASA_GM1_1PNPDK20090503_161810_000004772078_00384_37512_4313.N1						SS1	H/H	78	37512	384	4.07
ASA_GM1_1PNPDK20090503_164111_000002352078_00384_37512_4410.N1						SS1	H/H	78	37512	384	4.07
ASA_GM1_1PNPDK20090503_164647_000004412078_00384_37512_4415.N1						SS1	H/H	78	37512	384	4.07
ASA_GM1_1PNPDK20090503_171616_000002052078_00384_37512_4413.N1						SS1	H/H	78	37512	384	4.07
ASA_GM1_1PNPDK20090503_172413_000004832078_00384_37512_4420.N1						SS1	H/H	78	37512	384	4.07
ASA_GM1_1PNPDK20090503_175842_000005372078_00385_37513_4427.N1						SS1	H/H	78	37513	385	4.07
ASA_GM1_1PNPDK20090503_180628_000000722078_00385_37513_4526.N1						SS1	H/H	78	37513	385	4.07
ASA_GM1_1PNPDK20090503_182259_000001812078_00385_37513_4528.N1						SS1	H/H	78	37513	385	4.07
ASA_GM1_1PNPDK20090503_185652_000002352078_00385_37513_4530.N1						SS1	H/H	78	37513	385	4.07
ASA_GM1_1PNPDK20090503_190918_000002172078_00385_37513_4537.N1						SS1	H/H	78	37513	385	4.07
ASA_GM1_1PNPDK20090503_192907_000003682078_00385_37513_4535.N1						SS1	H/H	78	37513	385	4.07
ASA_GM1_1PNPDK20090503_193653_000001142078_00386_37514_4539.N1						SS1	H/H	78	37514	386	4.07
ASA_GM1_1PNPDK20090503_194025_000003202078_00386_37514_4541.N1						SS1	H/H	78	37514	386	4.07
ASA_GM1_1PNPDE20090503_195733_000003682078_00386_37514_9604.N1						SS1	H/H	78	37514	386	4.07
ASA_GM1_1PNPDE20090503_203728_000001752078_00386_37514_9602.N1						SS1	H/H	78	37514	386	4.07
ASA_GM1_1PNPDE20090503_204253_000006342078_00386_37514_9633.N1						SS1	H/H	78	37514	386	4.07
ASA_GM1_1PNPDE20090503_210256_000010152078_00386_37514_9839.N1						SS1	H/H	78	37514	386	4.07
ASA_GM1_1PNPDE20090503_213948_000002532078_00387_37515_9754.N1						SS1	H/H	78	37515	387	4.07

ASA_GM1_1PNPDE20090503_221804_000000902078_00387_37515_9750.N1	SS1	H/H	78	37515	387	4.07
ASA_GM1_1PNPDE20090503_222308_000000902078_00387_37515_9752.N1	SS1	H/H	78	37515	387	4.07
ASA_GM1_1PNPDE20090503_222608_000004772078_00387_37515_9762.N1	SS1	H/H	78	37515	387	4.07
ASA_GM1_1PNPDE20090503_225216_000003802078_00388_37516_9902.N1	SS1	H/H	78	37516	388	4.07
ASA_GM1_1PNPDE20090503_231709_000005552078_00388_37516_9907.N1	SS1	H/H	78	37516	388	4.07
ASA_GM1_1PNPDE20090503_234610_000002892078_00388_37516_9909.N1	SS1	H/H	78	37516	388	4.07
ASA_GM1_1PNPDE20090503_235103_000000902078_00388_37516_9911.N1	SS1	H/H	78	37516	388	4.07
ASA_GM1_1PNPDE20090503_235839_000000722078_00388_37516_9916.N1	SS1	H/H	78	37516	388	4.07


Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_IMM_1PNPDE20090503_003111_000003812078_00374_37502_8699.N1						IS2	H/H	78	37502	374	4.07
ASA_IMM_1PNPDE20090503_003811_000000632078_00374_37502_8663.N1						IS2	H/H	78	37502	374	4.07
ASA_IMM_1PNPDE20090503_003811_000003422078_00374_37502_8796.N1						IS2	H/H	78	37502	374	4.07
ASA_IMM_1PNPDE20090503_004013_000002202078_00374_37502_8695.N1						IS2	H/H	78	37502	374	4.07
ASA_IMM_1PNPDE20090503_015345_000000452078_00375_37503_8801.N1						IS4	H/H	78	37503	375	4.07
ASA_IMM_1PNPDE20090503_021443_000004822078_00375_37503_8823.N1						IS2	H/H	78	37503	375	4.07
ASA_IMM_1PNPDE20090503_021443_000005012078_00375_37503_8996.N1						IS2	H/H	78	37503	375	4.07
ASA_IMM_1PNPDE20090503_024112_000000772078_00375_37503_8985.N1						IS4	V/V	78	37503	375	4.07
ASA_IMM_1PNPDE20090503_025611_000000382078_00376_37504_8855.N1						IS5	V/V	78	37504	376	4.07
ASA_IMM_1PNPDE20090503_030444_000000362078_00376_37504_8890.N1						IS3	V/V	78	37504	376	4.07
ASA_IMM_1PNPDE20090503_035356_000000822078_00376_37504_8990.N1						IS2	H/H	78	37504	376	4.07
ASA_IMM_1PNPDE20090503_035500_000000182078_00376_37504_8983.N1						IS2	H/H	78	37504	376	4.07
ASA_IMM_1PNPDE20090503_035734_000001812078_00376_37504_9179.N1						IS2	H/H	78	37504	376	4.07
ASA_IMM_1PNPDE20090503_035734_000005002078_00376_37504_9183.N1						IS2	H/H	78	37504	376	4.07
ASA_IMM_1PNPDE20090503_040136_000001802078_00376_37504_9180.N1						IS2	H/H	78	37504	376	4.07
ASA_IMM_1PNPDE20090503_040537_000000182078_00376_37504_9154.N1						IS2	***	78	37504	376	4.07
ASA_IMM_1PNPDE20090503_042332_000000762078_00376_37504_9055.N1						IS5	V/V	78	37504	376	4.07
ASA_IMM_1PNPDE20090503_053338_000001402078_00377_37505_9171.N1						IS2	H/H	78	37505	377	4.07
ASA_IMM_1PNPDE20090503_053540_000000192078_00377_37505_9160.N1						IS2	H/H	78	37505	377	4.07
ASA_IMM_1PNPDE20090503_053638_000003222078_00377_37505_9247.N1						IS2	H/H	78	37505	377	4.07
ASA_IMM_1PNPDE20090503_054213_000000622078_00377_37505_9208.N1						IS5	H/H	78	37505	377	4.07
ASA_IMM_1PNPDE20090503_054213_000001942078_00377_37505_9336.N1						IS5	H/H	78	37505	377	4.07
ASA_IMM_1PNPDE20090503_054415_000000612078_00377_37505_9212.N1						IS5	H/H	78	37505	377	4.07
ASA_IMM_1PNPDE20090503_064625_000000372078_00378_37506_9193.N1						IS7	H/H	78	37506	378	4.07
ASA_IMM_1PNPDE20090503_071502_000001222078_00378_37506_9341.N1						IS2	H/H	78	37506	378	4.07
ASA_IMM_1PNPDE20090503_071502_000002612078_00378_37506_9349.N1						IS2	H/H	78	37506	378	4.07
ASA_IMM_1PNPDK20090503_072202_000000632078_00378_37506_3715.N1						IS2	H/H	78	37506	378	4.07
ASA_IMM_1PNPDK20090503_072202_000002022078_00378_37506_3916.N1						IS2	H/H	78	37506	378	4.07
ASA_IMM_1PNPDK20090503_072404_000000792078_00378_37506_3742.N1						IS2	H/H	78	37506	378	4.07
ASA_IMM_1PNPDK20090503_081232_000000922078_00379_37507_3713.N1						IS2	H/H	78	37507	379	4.07
ASA_IMM_1PNPDE20090503_082909_000000372078_00379_37507_9343.N1						IS2	H/H	78	37507	379	4.07
ASA_IMM_1PNPDK20090503_100106_000001572078_00380_37508_3875.N1						IS2	V/V	78	37508	380	4.07
ASA_IMM_1PNPDE20090503_100446_000000372078_00380_37508_9362.N1						IS2	V/V	78	37508	380	4.07
ASA_IMM_1PNPDE20090503_103512_000004422078_00380_37508_9415.N1						IS2	H/H	78	37508	380	4.07
ASA_IMM_1PNPDE20090503_104207_000001472078_00380_37508_9413.N1						IS2	H/H	78	37508	380	4.07
ASA_IMM_1PNPDE20090503_121506_000002392078_00381_37509_9445.N1						IS4	H/H	78	37509	381	4.07
ASA_IMM_1PNPDK20090503_121910_000005062078_00381_37509_4406.N1						IS2	H/H	78	37509	381	4.07
ASA_IMM_1PNPDK20090503_123725_000000362078_00381_37509_4130.N1						IS3	V/V	78	37509	381	4.07
ASA_IMM_1PNPDE20090503_135712_000000822078_00382_37510_9468.N1						IS2	H/H	78	37510	382	4.07
ASA_IMM_1PNPDE20090503_143140_000000832078_00383_37511_9482.N1						IS1	V/V	78	37511	383	4.07
ASA_IMM_1PNPDK20090503_145054_000000832078_00383_37511_4255.N1						IS2	H/H	78	37511	383	4.07
ASA_IMM_1PNPDE20090503_150541_000000382078_00383_37511_9476.N1						IS7	H/H	78	37511	383	4.07
ASA_IMM_1PNPDE20090503_171940_000002612078_00384_37512_9546.N1						IS2	H/H	78	37512	384	4.07
ASA_IMM_1PNPDE20090503_172044_000001192078_00384_37512_9544.N1						IS2	H/H	78	37512	384	4.07
ASA_IMM_1PNPDE20090503_172343_000000182078_00384_37512_9536.N1						IS2	***	78	37512	384	4.07
ASA_IMM_1PNPDE20090503_175609_000001422078_00385_37513_9552.N1						IS2	V/V	78	37513	385	4.07
ASA_IMM_1PNPDK20090503_180739_000000362078_00385_37513_4433.N1						IS2	H/H	78	37513	385	4.07
ASA_IMM_1PNPDE20090503_182557_000001452078_00385_37513_9594.N1						IS2	V/V	78	37513	385	4.07
ASA_IMM_1PNPDE20090503_190045_000002522078_00385_37513_9600.N1						IS2	H/H	78	37513	385	4.07
ASA_IMM_1PNPDE20090503_190545_000002022078_00385_37513_9570.N1						IS2	H/H	78	37513	385	4.07
ASA_IMM_1PNPDE20090503_201437_000000502078_00386_37514_9609.N1						IS4	V/V	78	37514	386	4.07
ASA_IMM_1PNPDE20090503_204022_000001362078_00386_37514_9710.N1						IS2	H/H	78	37514	386	4.07
ASA_IMM_1PNPDE20090503_221002_000000832078_00387_37515_9856.N1						IS2	V/V	78	37515	387	4.07
ASA_IMM_1PNPDE20090503_221133_000000822078_00387_37515_9862.N1						IS2	V/V	78	37515	387	4.07
ASA_IMM_1PNPDE20090503_221935_000001992078_00387_37515_9877.N1						IS2	H/H	78	37515	387	4.07
ASA_IMM_1PNPDE20090503_222435_000000822078_00387_37515_9879.N1						IS2	H/H	78	37515	387	4.07
ASA_IMM_1PNPDE20090503_222538_000000192078_00387_37515_9745.N1						IS2	H/H	78	37515	387	4.07
ASA_IMM_1PNPDE20090503_225834_000000532078_00388_37516_9858.N1						IS2	V/V	78	37516	388	4.07
ASA_IMM_1PNPDE20090503_225950_000000532078_00388_37516_9860.N1						IS2	V/V	78	37516	388	4.07
ASA_IMM_1PNPDE20090503_235952_000000822078_00388_37516_0008.N1						IS2	H/H	78	37516	388	4.07


Filename	Pol	Timestamp	count(Module)
ASA_MS__0PNPDE20090503_053202_000000162078_00377_37505_0414.N1	V	2009-05-03 05:32:02	320





Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WSM_1PNPDE20090503_011948_000000732078_00375_37503_8825.N1						SS1	H/H	78	37503	375	4.07
ASA_WSM_1PNPDE20090503_011948_000004162078_00375_37503_9022.N1						SS1	H/H	78	37503	375	4.07
ASA_WSM_1PNPDE20090503_012203_000002812078_00375_37503_8892.N1						SS1	H/H	78	37503	375	4.07
ASA_WSM_1PNPDE20090503_025152_000000732078_00376_37504_8955.N1						SS1	V/V	78	37504	376	4.07
ASA_WSM_1PNPDE20090503_025152_000002132078_00376_37504_9066.N1						SS1	V/V	78	37504	376	4.07
ASA_WSM_1PNPDE20090503_025406_000000792078_00376_37504_8994.N1						SS1	V/V	78	37504	376	4.07
ASA_WSM_1PNPDE20090503_030051_000001342078_00376_37504_9010.N1						SS1	H/H	78	37504	376	4.07
ASA_WSM_1PNPDE20090503_030051_000001522078_00376_37504_9012.N1						SS1	H/H	78	37504	376	4.07
ASA_WSM_1PNPDE20090503_032123_000003732078_00376_37504_8992.N1						SS1	V/V	78	37504	376	4.07
ASA_WSM_1PNPDE20090503_050940_000001222078_00377_37505_9169.N1						SS1	V/V	78	37505	377	4.07
ASA_WSM_1PNPDE20090503_070623_000000922078_00378_37506_9334.N1						SS1	V/V	78	37506	378	4.07
ASA_WSM_1PNPDE20090503_083100_000000912078_00379_37507_9360.N1						SS1	V/V	78	37507	379	4.07
ASA_WSM_1PNPDE20090503_100953_000002502078_00380_37508_9403.N1						SS1	V/V	78	37508	380	4.07
ASA_WSM_1PNPDE20090503_100953_000003672078_00380_37508_9411.N1						SS1	V/V	78	37508	380	4.07
ASA_WSM_1PNPDE20090503_101505_000000552078_00380_37508_9379.N1						SS1	V/V	78	37508	380	4.07
ASA_WSM_1PNPDE20090503_115803_000003542078_00381_37509_9453.N1						SS1	V/V	78	37509	381	4.07
ASA_WSM_1PNPDE20090503_132056_000000982078_00382_37510_9490.N1						SS1	H/H	78	37510	382	4.07
ASA_WSM_1PNPDE20090503_142709_000000732078_00382_37510_9466.N1						SS1	H/H	78	37510	382	4.07
ASA_WSM_1PNPDE20090503_145841_000000912078_00383_37511_9500.N1						SS1	H/H	78	37511	383	4.07
ASA_WSM_1PNPDE20090503_150714_000001902078_00383_37511_9502.N1						SS1	V/V	78	37511	383	4.07
ASA_WSM_1PNPDE20090503_161420_000002262078_00384_37512_9504.N1						SS1	H/H	78	37512	384	4.07
ASA_WSM_1PNPDE20090503_163502_000001832078_00384_37512_9550.N1						SS1	H/H	78	37512	384	4.07
ASA_WSM_1PNPDE20090503_163837_000001532078_00384_37512_9554.N1						SS1	H/H	78	37512	384	4.07
ASA_WSM_1PNPDE20090503_164513_000000912078_00384_37512_9548.N1						SS1	H/H	78	37512	384	4.07
ASA_WSM_1PNPDE20090503_181527_000001522078_00385_37513_9556.N1						SS1	H/H	78	37513	385	4.07
ASA_WSM_1PNPDE20090503_181722_000000982078_00385_37513_9596.N1						SS1	H/H	78	37513	385	4.07
ASA_WSM_1PNPDE20090503_181929_000001902078_00385_37513_9598.N1						SS1	H/H	78	37513	385	4.07
ASA_WSM_1PNPDE20090503_193519_000000922078_00386_37514_9724.N1						SS1	V/V	78	37514	386	4.07
ASA_WSM_1PNPDE20090503_195452_000001592078_00386_37514_9728.N1						SS1	H/H	78	37514	386	4.07
ASA_WSM_1PNPDE20090503_195606_000000842078_00386_37514_9722.N1						SS1	H/H	78	37514	386	4.07
ASA_WSM_1PNPDE20090503_205819_000002752078_00386_37514_9726.N1						SS1	V/V	78	37514	386	4.07
ASA_WSM_1PNPDE20090503_213422_000000982078_00387_37515_9875.N1						SS1	H/H	78	37515	387	4.07
ASA_WSM_1PNPDE20090503_213714_000001522078_00387_37515_9891.N1						SS1	H/H	78	37515	387	4.07
ASA_WSM_1PNPDE20090503_231235_000000732078_00388_37516_0013.N1						SS1	H/H	78	37516	388	4.07
ASA_WSM_1PNPDE20090503_231235_000002692078_00388_37516_0079.N1						SS1	H/H	78	37516	388	4.07
ASA_WSM_1PNPDE20090503_231450_000001332078_00388_37516_0041.N1						SS1	H/H	78	37516	388	4.07




Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WVS_1PNPDE20090502_235851_000010942078_00374_37502_8568.N1						IS2	V/V	78	37502	374	4.07
ASA_WVS_1PNPDE20090503_002303_000003902078_00374_37502_8573.N1						IS2	V/V	78	37502	374	4.07
ASA_WVS_1PNPDE20090503_004621_000004052078_00374_37502_8580.N1						IS2	V/V	78	37502	374	4.07
ASA_WVS_1PNPDE20090503_005221_000002992078_00374_37502_8702.N1						IS2	V/V	78	37502	374	4.07
ASA_WVS_1PNPDE20090503_010251_000009292078_00374_37502_8707.N1						IS2	V/V	78	37502	374	4.07
ASA_WVS_1PNPDE20090503_014405_000000442078_00375_37503_8710.N1						IS2	V/V	78	37503	375	4.07
ASA_WVS_1PNPDE20090503_014758_000003142078_00375_37503_8713.N1						IS2	V/V	78	37503	375	4.07
ASA_WVS_1PNPDE20090503_015437_000009292078_00375_37503_8721.N1						IS2	V/V	78	37503	375	4.07
ASA_WVS_1PNPDE20090503_020937_000000302078_00375_37503_8860.N1						IS2	V/V	78	37503	375	4.07
ASA_WVS_1PNPDE20090503_022657_000003152078_00375_37503_8871.N1						IS2	V/V	78	37503	375	4.07
ASA_WVS_1PNPDE20090503_024714_000002392078_00376_37504_8876.N1						IS2	V/V	78	37504	376	4.07
ASA_WVS_1PNPDE20090503_033012_000002842078_00376_37504_9456.N1						IS2	V/V	78	37504	376	4.07
ASA_WVS_1PNPDE20090503_034427_000001802078_00376_37504_9036.N1						IS2	V/V	78	37504	376	4.07
ASA_WVS_1PNPDE20090503_041040_000007342078_00376_37504_9051.N1						IS2	V/V	78	37504	376	4.07
ASA_WVS_1PNPDE20090503_042454_000001942078_00377_37505_9029.N1						IS2	V/V	78	37505	377	4.07
ASA_WVS_1PNPDE20090503_051141_000008842078_00377_37505_9069.N1						IS2	V/V	78	37505	377	4.07
ASA_WVS_1PNPDE20090503_052611_000003152078_00377_37505_9217.N1						IS2	V/V	78	37505	377	4.07
ASA_WVS_1PNPDE20090503_054809_000018292078_00377_37505_9252.N1						IS2	V/V	78	37505	377	4.07
ASA_WVS_1PNPDE20090503_070251_000001642078_00378_37506_9236.N1						IS2	V/V	78	37506	378	4.07
ASA_WVS_1PNPDK20090503_070753_000002402078_00378_37506_3656.N1						IS2	V/V	78	37506	378	4.07
ASA_WVS_1PNPDK20090503_072845_000019492078_00378_37506_3677.N1						IS2	V/V	78	37506	378	4.07
ASA_WVS_1PNPDK20090503_084224_000006152078_00379_37507_3757.N1						IS2	V/V	78	37507	379	4.07
ASA_WVS_1PNPDK20090503_090921_000020242078_00379_37507_3767.N1						IS2	V/V	78	37507	379	4.07
ASA_WVS_1PNPDK20090503_101601_000010342078_00380_37508_3910.N1						IS2	V/V	78	37508	380	4.07
ASA_WVS_1PNPDK20090503_104957_000018292078_00380_37508_3924.N1						IS2	V/V	78	37508	380	4.07
ASA_WVS_1PNPDK20090503_114031_000010042078_00381_37509_4041.N1						IS2	V/V	78	37509	381	4.07
ASA_WVS_1PNPDK20090503_120355_000005852078_00381_37509_4046.N1						IS2	V/V	78	37509	381	4.07
ASA_WVS_1PNPDK20090503_123032_000003452078_00381_37509_4049.N1						IS2	V/V	78	37509	381	4.07
ASA_WVS_1PNPDK20090503_124440_000008402078_00381_37509_4122.N1						IS2	V/V	78	37509	381	4.07
ASA_WVS_1PNPDK20090503_132236_000007642078_00382_37510_4153.N1						IS2	V/V	78	37510	382	4.07
ASA_WVS_1PNPDK20090503_135329_000000452078_00382_37510_4156.N1						IS2	V/V	78	37510	382	4.07
ASA_WVS_1PNPDK20090503_141108_000004052078_00382_37510_4164.N1						IS2	V/V	78	37510	382	4.07
ASA_WVS_1PNPDK20090503_142259_000002092078_00382_37510_4159.N1						IS2	V/V	78	37510	382	4.07
ASA_WVS_1PNPDK20090503_142820_000001642078_00383_37511_4174.N1						IS2	V/V	78	37511	383	4.07
ASA_WVS_1PNPDK20090503_151044_000014542078_00383_37511_4301.N1						IS2	V/V	78	37511	383	4.07
ASA_WVS_1PNPDK20090503_155144_000013042078_00383_37511_4306.N1						IS2	V/V	78	37511	383	4.07
ASA_WVS_1PNPDK20090503_165410_000012742078_00384_37512_4418.N1						IS2	V/V	78	37512	384	4.07
ASA_WVS_1PNPDK20090503_173220_000013942078_00384_37512_4430.N1						IS2	V/V	78	37512	384	4.07
ASA_WVS_1PNPDK20090503_182853_000016342078_00385_37513_4533.N1						IS2	V/V	78	37513	385	4.07
ASA_WVS_1PNPDK20090503_191256_000009292078_00385_37513_4544.N1						IS2	V/V	78	37513	385	4.07
ASA_WVS_1PNPDE20090503_200341_000006142078_00386_37514_9607.N1						IS2	V/V	78	37514	386	4.07
ASA_WVS_1PNPDE20090503_201533_000012742078_00386_37514_9620.N1						IS2	V/V	78	37514	386	4.07
ASA_WVS_1PNPDE20090503_205332_000000302078_00386_37514_9617.N1						IS2	V/V	78	37514	386	4.07
ASA_WVS_1PNPDE20090503_205332_000002402078_00386_37514_9741.N1						IS2	V/V	78	37514	386	4.07
ASA_WVS_1PNPDE20090503_214401_000015292078_00387_37515_9748.N1						IS2	V/V	78	37515	387	4.07
ASA_WVS_1PNPDE20090503_221301_000002552078_00387_37515_9757.N1						IS2	V/V	78	37515	387	4.07
ASA_WVS_1PNPDE20090503_223408_000003302078_00387_37515_9760.N1						IS2	V/V	78	37515	387	4.07
ASA_WVS_1PNPDE20090503_223853_000007642078_00387_37515_9898.N1						IS2	V/V	78	37515	387	4.07
ASA_WVS_1PNPDE20090503_230048_000003892078_00388_37516_9905.N1						IS2	V/V	78	37516	388	4.07
ASA_WVS_1PNPDE20090503_232625_000011392078_00388_37516_9914.N1						IS2	V/V	78	37516	388	4.07
ASA_WVS_1PNPDE20090503_235235_000003152078_00388_37516_9919.N1						IS2	V/V	78	37516	388	4.07



















































03-May





03-May




03-May











03-May



03-May



03-May



03-May

