



Analysis from 17-SEP-2009 00:00:00 to 17-SEP-2009 23:59:59. Page generated on 18-SEP-2009 08:02:26.  
View log file: ASAR\_Daily\_Report\_20090918\_0731.log. For any anomalies please contact emma.griffiths@vega.co.uk.

This report is automatically generated every day, every 2 hours. No comments are provided on the results.

## SUMMARY

1. DATA SUMMARY
  - 1.1 Summary tables
  - 1.2 Lists of products used
2. AUXILIARY FILES ANALYSIS
  - 2.1 IECF operational ADFs list
  - 2.2 Products with wrong ADFs
3. MODULE STEPPING PRODUCTS ANALYSIS
  - 3.1 V/V polarisation
  - 3.2 H/H polarisation
4. CALIBRATION PULSES ANALYSIS
  - 4.1 Analysis for WVS IS2 V/V
    - 4.1.1 Temporal Evolution Analysis for WVS IS2 V/V
    - 4.1.2 All Rows Analysis for WVS IS2 V/V
  - 4.2 Analysis for GM1 SS3 H/H
    - 4.2.1 Temporal Evolution Analysis for GM1 SS3 H/H
    - 4.2.2 All Rows Analysis for GM1 SS3 H/H
5. DOPPLER ANALYSIS
  - 5.1 Analysis for WVS IS2 V/V
    - 5.1.1 Doppler MAP Analysis for WVS IS2 V/V
    - 5.1.2 Doppler ANX Analysis for WVS IS2 V/V
  - 5.2 Analysis for GM1 SS1 H/H
    - 5.2.1 Doppler MAP Analysis for GM1 SS1 H/H
    - 5.2.2 Doppler ANX Analysis for GM1 SS1 H/H
  - 5.3 Doppler JUMPS Analysis for WSM
6. CHIRP ANALYSIS
  - 6.1 Analysis for WSM SS1 H/H
    - 6.1.1 ScaleFactor
  - 6.2 Analysis for WSM SS1 V/V
    - 6.2.1 ScaleFactor
7. RAW DATA ANALYSIS
  - 7.1 Analysis for WVS
  - 7.2 Analysis for IMM
8. TELEMETRY ANALYSIS
  - 8.1 Number of Missing Lines
  - 8.2 Number of Gaps

---

## 1 - DATA SUMMARY

### 1.1 - Summary tables

[ [BACK TO MENU](#) ]

WVS				GM1				APM				IMM				WSM				MS			
Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Time	Pol	Modules
PDE	IS1	V/V	1	PDE	WS	H/H	45	PDE	IS4	V/H	1	PDE	IS2	H/H	2	PDE	WS	H/H	49	PDK	2009-09-17 07:06:51	H	320
PDE	IS2	V/V	29	PDK	WS	H/H	40	PDK	IS4	V/H	1	PDE	IS2	V/V	16	PDE	WS	V/V	16				
PDK	IS2	V/V	21									PDE	IS3	V/V	3	PDK	WS	H/H	13				
												PDE	IS4	H/H	1	PDK	WS	V/V	4				
												PDE	IS6	V/V	3								
												PDE	IS7	V/V	1								
												PDK	IS1	V/V	1								
												PDK	IS2	V/V	3								

## 1.2 - Lists of products used

[ [BACK TO MENU](#) ]

[\[TXT\]](#) [\[XLS\]](#) List\_WVS\_products\_used  
[\[TXT\]](#) [\[XLS\]](#) List\_GM1\_products\_used  
[\[TXT\]](#) [\[XLS\]](#) List\_APM\_products\_used  
[\[TXT\]](#) [\[XLS\]](#) List\_IMM\_products\_used  
[\[TXT\]](#) [\[XLS\]](#) List\_WSM\_products\_used  
[\[TXT\]](#) [\[XLS\]](#) List\_MS\_products\_used

## 2 - AUXILIARY FILES ANALYSIS

### 2.1 - IECF operational ADFs list

[ [BACK TO MENU](#) ]

ADFs disseminated for ASAR
ASA_CON_AXVIEC20081215_141339_20070204_165113_20091231_000000
ASA_INS_AXVIEC20090525_114808_20090428_100000_20091231_235959
ASA_XCH_AXVIEC20081215_143642_20020301_000000_20091231_000000
ASA_XCA_AXVIEC20090311_104501_20080801_000000_20091231_235959

### 2.2 - Products with wrong ADFs

[ [BACK TO MENU](#) ]

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
WVS	0	0	0	0
GM1	0	0	0	0
APM	0	0	0	0
IMM	0	0	0	0
WSM	0	0	0	0

[\[TXT\]](#) [\[XLS\]](#) Check\_ADFs\_WVS  
[\[TXT\]](#) [\[XLS\]](#) Check\_ADFs\_GM1  
[\[TXT\]](#) [\[XLS\]](#) Check\_ADFs\_APM  
[\[TXT\]](#) [\[XLS\]](#) Check\_ADFs\_IMM

### 3 - MODULE STEPPING PRODUCTS ANALYSIS








### 3.2 - H/H polarisation

[ [BACK TO MENU](#) ]


SECOND FIXED REFERENCE	PREVIOUS PRODUCT REFERENCE
After antenna maintenance (2005-09-22/23)	Previous product in the same polarisation



Reference: 2005-09-22 06:26:51 H RxGain  
 Test : 2009-09-17 07:06:51 H




Reference: 2009-09-15 08:10:05 H RxGain  
 Test : 2009-09-17 07:06:51 H







Reference: 2005-09-22 06:26:51 H RxPhase  
 Test : 2009-09-17 07:06:51 H



Reference: 2009-09-15 08:10:05 H RxPhase  
 Test : 2009-09-17 07:06:51 H







## 4 - CALIBRATION PULSES ANALYSIS

### 4.1 - Analysis for WVS IS2 V/V

#### 4.1.1 - Temporal Evolution Analysis for WVS IS2 V/V


[ BACK TO MENU ]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]



Calibration pulses for WVS IS2 V/V




Transmit power (P1 - P1a) for WVS IS2 V/V



#### 4.1.2 - All Rows Analysis for WVS IS2 V/V

[ [BACK TO MENU](#) ]





## 4.2 - Analysis for GM1 SS3 H/H

### 4.2.1 - Temporal Evolution Analysis for GM1 SS3 H/H


[ BACK TO MENU ]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]



Calibration pulses for GM1 SS3 H/H




Transmit power (P1 - P1a) for GM1 SS3 H/H



#### 4.2.2 - All Rows Analysis for GM1 SS3 H/H

[ [BACK TO MENU](#) ]






## 5 - DOPPLER ANALYSIS


### 5.1 - Analysis for WVS IS2 V/V

#### 5.1.1 - Doppler MAP Analysis for WVS IS2 V/V

[ [BACK TO MENU](#) ]








### 5.1.2 - Doppler ANX Analysis for WVS IS2 V/V

[ [BACK TO MENU](#) ]






## 5.2 - Analysis for GM1 SS1 H/H

### 5.2.1 - Doppler MAP Analysis for GM1 SS1 H/H

[ [BACK TO MENU](#) ]








### 5.2.2 - Doppler ANX Analysis for GM1 SS1 H/H

[ [BACK TO MENU](#) ]






### 5.3 - Doppler JUMPS Analysis for WSM

[ BACK TO MENU ]










## 6 - CHIRP ANALYSIS

### 6.1 - Analysis for WSM SS1 H/H

#### 6.1.1 - ScaleFactor

[ [BACK TO MENU](#) ]







## 6.2 - Analysis for WSM SS1 V/V

### 6.2.1 - ScaleFactor

[ [BACK TO MENU](#) ]






## 7 - RAW DATA ANALYSIS

### 7.1 - Analysis for WVS

[ [BACK TO MENU](#) ]

--	--	--






Channel	Statistics	DSS-B
MEAN I	mean	0.000521309
	stdev	1.93446e-07
MEAN Q	mean	0.000529272
	stdev	2.31803e-07
Channel	Statistics	DSS-B
STDEV I	mean	0.132469
	stdev	0.000970852
STDEV Q	mean	0.132809
	stdev	0.000982780

7.2 - Analysis for IMM

[ BACK TO MENU ]






## 8 - TELEMETRY ANALYSIS


Processing Center	Product	Gaps	Missing lines
PDE	ASA_WSM_1PNPDE20090917_063622_000001522082_00335_39467_7794.N1	0	1
PDE	ASA_WSM_1PNPDE20090917_081725_000000922082_00336_39468_7955.N1	0	1

### 8.1 - Number of Missing lines

[ BACK TO MENU ]








### 8.2 - Number of Gaps

[\[ BACK TO MENU \]](#)



#####  
ASAR DAILY REPORT for 090917  
#####

MODE: DAILY  
ANALYSIS: ALL  
DATE: YESTERDAY

Analysis will be performed from 2009-09-17 00:00:00 to 2009-09-17 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/090917/

DATA SUMMARY

#####  
Summary will be performed from 2009-09-17 00:00:00 to 2009-09-17 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/090917/DATA\_SUMMARY

Creating directory ./RESULTS/DAILY/090917/DATA\_SUMMARY...  
Writing file ./RESULTS/DAILY/090917/DATA\_SUMMARY/Data\_summary.html...

\*\*\*\*\*  
Getting WVS products list from 2009-09-17 00:00:00 to 2009-09-17 23:59:59...  
Writing file ./RESULTS/DAILY/090917/DATA\_SUMMARY/List\_WVS\_products\_used.xls...  
Writing file ./RESULTS/DAILY/090917/DATA\_SUMMARY/List\_WVS\_products\_used.txt...

\*\*\*\*\*  
Getting GM1 products list from 2009-09-17 00:00:00 to 2009-09-17 23:59:59...  
Writing file ./RESULTS/DAILY/090917/DATA\_SUMMARY/List\_GM1\_products\_used.xls...  
Writing file ./RESULTS/DAILY/090917/DATA\_SUMMARY/List\_GM1\_products\_used.txt...

\*\*\*\*\*  
Getting APM products list from 2009-09-17 00:00:00 to 2009-09-17 23:59:59...  
Writing file ./RESULTS/DAILY/090917/DATA\_SUMMARY/List\_APM\_products\_used.xls...  
Writing file ./RESULTS/DAILY/090917/DATA\_SUMMARY/List\_APM\_products\_used.txt...

\*\*\*\*\*  
Getting IMM products list from 2009-09-17 00:00:00 to 2009-09-17 23:59:59...  
Writing file ./RESULTS/DAILY/090917/DATA\_SUMMARY/List\_IMM\_products\_used.xls...  
Writing file ./RESULTS/DAILY/090917/DATA\_SUMMARY/List\_IMM\_products\_used.txt...

\*\*\*\*\*  
Getting WSM products list from 2009-09-17 00:00:00 to 2009-09-17 23:59:59...  
Writing file ./RESULTS/DAILY/090917/DATA\_SUMMARY/List\_WSM\_products\_used.xls...  
Writing file ./RESULTS/DAILY/090917/DATA\_SUMMARY/List\_WSM\_products\_used.txt...

\*\*\*\*\*  
Getting MS products list from 2009-09-17 00:00:00 to 2009-09-17 23:59:59...  
Writing file ./RESULTS/DAILY/090917/DATA\_SUMMARY/List\_MS\_products\_used.xls...  
Writing file ./RESULTS/DAILY/090917/DATA\_SUMMARY/List\_MS\_products\_used.txt...

DATA SUMMARY completed  
#####

AUXILIARY FILES ANALYSIS

#####  
Analysis will be performed from 2009-09-17 00:00:00 to 2009-09-17 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/090917/AUXILIARY

Creating directory ./RESULTS/DAILY/090917/AUXILIARY...

\*\*\*\*\*  
Looking for the IECF operational ADFs list...





ADF filter 20090917\*current\_3\_IECF\_ADFs.txt  
 Found list 20090917\_030003\_current\_3\_IECF\_ADFs.txt...  
 Extracting ADFs...

ASA\_CON\_AXVIEC20081215\_141339\_20070204\_165113\_20091231\_000000  
 ASA\_INS\_AXVIEC20090525\_114808\_20090428\_100000\_20091231\_235959  
 ASA\_XCH\_AXVIEC20081215\_143642\_20020301\_000000\_20091231\_000000  
 ASA\_XCA\_AXVIEC20090311\_104501\_20080801\_000000\_20091231\_235959

Writing file ./RESULTS/DAILY/090917/AUXILIARY/ASAR\_ADFs\_IECF\_List3.html...  
 Writing file ./RESULTS/DAILY/090917/AUXILIARY/Auxiliary\_files\_summary.html...

\*\*\*\*\*

Analysing WVS products...

Writing file ./RESULTS/DAILY/090917/AUXILIARY/Check\_ADFs\_WVS.xls...  
 Writing file ./RESULTS/DAILY/090917/AUXILIARY/Check\_ADFs\_WVS.txt...

ASA_WVS_1PNPDE20090917_001722_000003002082_00331_39463_7200.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090917_004203_000002392082_00331_39463_7195.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090917_004503_000004642082_00331_39463_7285.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090917_005654_000009442082_00331_39463_7290.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090917_014210_000003142082_00332_39464_7293.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090917_014854_000002542082_00332_39464_7311.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090917_015600_000004052082_00332_39464_7328.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090917_022238_000000302082_00332_39464_7316.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090917_022238_000002402082_00332_39464_7432.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090917_032429_000008242082_00333_39465_7448.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090917_033758_000002252082_00333_39465_7559.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090917_040531_000009892082_00333_39465_7590.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090917_050457_000009142082_00334_39466_7600.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090917_051957_000002402082_00334_39466_7771.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090917_054350_000014992082_00334_39466_7819.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090917_065021_000001042082_00335_39467_7809.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090917_065459_000003292082_00335_39467_7806.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090917_195759_000006142082_00343_39475_8281.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090917_201004_000011692082_00343_39475_8297.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090917_204914_000001502082_00343_39475_8418.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090917_214038_000017692082_00344_39476_8425.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090917_222950_000002852082_00344_39476_8430.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090917_223350_000007042082_00344_39476_8566.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090917_223350_000007042082_00344_39476_9170.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090917_225459_000001642082_00345_39477_8573.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090917_225459_000001642082_00345_39477_9161.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090917_231907_000012742082_00345_39477_8582.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20090917_234653_000002252082_00345_39477_8587.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090917_070014_000002702082_00335_39467_1723.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090917_072426_000018142082_00335_39467_1762.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090917_083725_000004652082_00336_39468_1805.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090917_090502_000019342082_00336_39468_1874.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090917_101006_000009442082_00337_39469_1941.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090917_104538_000001952082_00337_39469_1944.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090917_105114_000014092082_00337_39469_1960.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090917_113443_000010192082_00338_39470_2071.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090917_115549_000006442082_00338_39470_2080.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090917_122614_000002852082_00338_39470_2083.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090917_123742_000009242082_00338_39470_2095.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090917_131525_000008692082_00339_39471_2203.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090917_140650_000003302082_00339_39471_2206.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090917_141733_000002092082_00339_39471_2213.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090917_142224_000003142082_00339_39471_2220.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090917_151010_000010492082_00340_39472_2310.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090917_154726_000012442082_00340_39472_2334.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090917_164833_000011842082_00341_39473_2471.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090917_172802_000012892082_00341_39473_2482.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20090917_182354_000014992082_00342_39474_2688.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK



ASA\_WVS\_1PNPDK20090917\_190838\_000008692082\_00342\_39474\_2706.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK

\*\*\*\*\*

Analysing GM1 products...

Writing file ./RESULTS/DAILY/090917/AUXILIARY/Check\_ADFs\_GM1.xls...

Writing file ./RESULTS/DAILY/090917/AUXILIARY/Check\_ADFs\_GM1.txt...

ASA\_GM1\_1PNPDE20090917\_001023\_000004162082\_00331\_39463\_7204.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDE20090917\_002300\_000003562082\_00331\_39463\_7202.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDE20090917\_003902\_000001812082\_00331\_39463\_7197.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDE20090917\_005324\_000002112082\_00331\_39463\_7287.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDE20090917\_012324\_000008942082\_00332\_39464\_7332.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDE20090917\_015356\_000001202082\_00332\_39464\_7313.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDE20090917\_020336\_000006102082\_00332\_39464\_7330.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDE20090917\_021938\_000001812082\_00332\_39464\_7318.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDE20090917\_022717\_000004892082\_00332\_39464\_7427.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDE20090917\_023653\_000003322082\_00332\_39464\_7425.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDE20090917\_025138\_000001692082\_00333\_39465\_7409.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDE20090917\_025647\_000001322082\_00333\_39465\_7429.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDE20090917\_025950\_000009722082\_00333\_39465\_7550.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDE20090917\_031520\_000000422082\_00333\_39465\_7436.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDE20090917\_032215\_000001322082\_00333\_39465\_7444.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDE20090917\_034515\_000012132082\_00333\_39465\_7667.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDE20090917\_042715\_000009302082\_00334\_39466\_7585.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDE20090917\_042715\_000011292082\_00334\_39466\_7681.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDE20090917\_045034\_000001752082\_00334\_39466\_7583.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDE20090917\_050223\_000001502082\_00334\_39466\_7597.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDE20090917\_052448\_000001502082\_00334\_39466\_7814.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDE20090917\_053019\_000001022082\_00334\_39466\_7796.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDE20090917\_054050\_000001812082\_00334\_39466\_7798.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDE20090917\_060941\_000001382082\_00335\_39467\_7785.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDE20090917\_061503\_000007002082\_00335\_39467\_7768.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDE20090917\_063033\_000003442082\_00335\_39467\_7766.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDE20090917\_063855\_000006822082\_00335\_39467\_7869.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDE20090917\_065256\_000001202082\_00335\_39467\_7816.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDE20090917\_194622\_000004712082\_00343\_39475\_8278.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDE20090917\_195507\_000001692082\_00343\_39475\_8283.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDE20090917\_203011\_000001502082\_00343\_39475\_8287.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDE20090917\_203802\_000005732082\_00343\_39475\_8294.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDE20090917\_204613\_000001812082\_00343\_39475\_8411.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDE20090917\_205708\_000010512082\_00343\_39475\_8501.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDE20090917\_213029\_000001932082\_00344\_39476\_8420.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDE20090917\_213522\_000001812082\_00344\_39476\_8422.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDE20090917\_221047\_000002232082\_00344\_39476\_8427.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDE20090917\_221618\_000002592082\_00344\_39476\_8437.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDE20090917\_222649\_000001812082\_00344\_39476\_8439.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDE20090917\_224622\_000004042082\_00345\_39477\_9158.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDE20090917\_230822\_000002172082\_00345\_39477\_8568.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDE20090917\_230822\_000002172082\_00345\_39477\_9156.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDE20090917\_231720\_000001022082\_00345\_39477\_8575.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDE20090917\_234515\_000000962082\_00345\_39477\_8579.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDE20090917\_235123\_000002952082\_00345\_39477\_8584.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDK20090917\_070524\_000000842082\_00335\_39467\_1720.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDK20090917\_071242\_000001022082\_00335\_39467\_1725.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDK20090917\_071943\_000002832082\_00335\_39467\_1727.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDK20090917\_080131\_000004162082\_00336\_39468\_1752.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDK20090917\_080743\_000005492082\_00336\_39468\_1802.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDK20090917\_082728\_000005982082\_00336\_39468\_1807.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDK20090917\_084600\_000011412082\_00336\_39468\_1897.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDK20090917\_093804\_000005372082\_00337\_39469\_1882.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDK20090917\_100421\_000003442082\_00337\_39469\_1936.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDK20090917\_102635\_000003622082\_00337\_39469\_1938.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDK20090917\_104238\_000001812082\_00337\_39469\_1946.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDK20090917\_111531\_000006522082\_00338\_39470\_1962.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_GM1\_1PNPDK20090917\_120711\_000001382082\_00338\_39470\_2073.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK



ASA_GM1_1PNPDK20090917_121307_000007852082_00338_39470_2077.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090917_123230_000003082082_00338_39470_2085.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090917_125345_000003562082_00339_39471_2087.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090917_130112_000002832082_00339_39471_2158.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090917_130929_00000902082_00339_39471_2198.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090917_133258_000005192082_00339_39471_2200.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090917_134140_000015092082_00339_39471_2429.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090917_135710_000005792082_00339_39471_2210.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090917_141304_000002652082_00339_39471_2215.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090917_142828_000007062082_00340_39472_2217.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090917_144353_000000782082_00340_39472_2227.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090917_145453_000003922082_00340_39472_2307.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090917_152823_000011422082_00340_39472_2405.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090917_160848_000000962082_00341_39473_2316.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090917_161614_000003742082_00341_39473_2336.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090917_163931_000005372082_00341_39473_2467.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090917_170859_000006822082_00341_39473_2473.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090917_172206_000003562082_00341_39473_2477.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090917_175339_000001632082_00342_39474_2475.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090917_175810_000001322082_00342_39474_2479.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090917_181711_000001322082_00342_39474_2683.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090917_184935_000006102082_00342_39474_2685.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090917_190244_000003502082_00342_39474_2690.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090917_192344_000001442082_00342_39474_2696.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090917_192845_000000962082_00343_39475_2694.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090917_193308_000001022082_00343_39475_2692.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20090917_193828_000001502082_00343_39475_2703.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

\*\*\*\*\*

Analysing APM products...

Writing file ./RESULTS/DAILY/090917/AUXILIARY/Check\_ADFs\_APM.xls...

Writing file ./RESULTS/DAILY/090917/AUXILIARY/Check\_ADFs\_APM.txt...

ASA_APM_1PNPDE20090917_133100_000000542082_00339_39471_8045.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDK20090917_131102_000000542082_00339_39471_2166.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

\*\*\*\*\*

Analysing IMM products...

Writing file ./RESULTS/DAILY/090917/AUXILIARY/Check\_ADFs\_IMM.xls...

Writing file ./RESULTS/DAILY/090917/AUXILIARY/Check\_ADFs\_IMM.txt...

ASA_IMM_1PNPDE20090917_013927_000000532082_00332_39464_7399.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090917_014757_000000492082_00332_39464_7397.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090917_023524_000000792082_00332_39464_7536.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090917_025900_000000362082_00333_39465_7513.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090917_031559_000000632082_00333_39465_7538.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090917_031559_000003632082_00333_39465_7603.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090917_031802_000000602082_00333_39465_7542.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090917_032002_000000602082_00333_39465_7546.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090917_045326_000000632082_00334_39466_7718.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090917_045326_000005272082_00334_39466_7758.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090917_045629_000001802082_00334_39466_7744.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090917_061320_000000912082_00335_39467_7880.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090917_082459_000001382082_00336_39468_7936.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090917_104926_000001022082_00337_39469_7998.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090917_133209_000000372082_00339_39471_8051.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090917_142139_000000392082_00339_39471_8055.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090917_161020_000000372082_00341_39473_8083.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090917_163100_000000672082_00341_39473_8186.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090917_175009_000000622082_00342_39474_8205.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090917_175009_000002002082_00342_39474_8231.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090917_181924_000001092082_00342_39474_8259.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

```
ASA_IMM_1PNPDE20090917_182214_000000942082_00342_39474_8262.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090917_195411_000000452082_00343_39475_8285.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090917_200847_000000702082_00343_39475_8407.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090917_213943_000000502082_00344_39476_8512.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20090917_225401_000000532082_00345_39477_8518.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20090917_075515_000001202082_00336_39468_1793.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20090917_095459_000001512082_00337_39469_1922.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20090917_123142_000000372082_00338_39470_2075.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20090917_145210_000000372082_00340_39472_2296.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```

\*\*\*\*\*

Analysing WSM products...

Writing file ./RESULTS/DAILY/090917/AUXILIARY/Check\_ADFs\_WSM.xls...

Writing file ./RESULTS/DAILY/090917/AUXILIARY/Check\_ADFs\_WSM.txt...

```
ASA_WSM_1PNPDE20090917_011401_000000732082_00332_39464_7938.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_011401_000004092082_00332_39464_7534.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_011401_000004092082_00332_39464_7979.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_011615_000000552082_00332_39464_7942.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_011913_000000612082_00332_39464_7948.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_012159_000000732082_00332_39464_7401.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_021351_000001902082_00332_39464_7760.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_021351_000003422082_00332_39464_7904.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_021802_000000902082_00332_39464_7761.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_024557_000001902082_00333_39465_7554.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_024557_000002202082_00333_39465_7556.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_025116_000000182082_00333_39465_7517.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_025429_000001352082_00333_39465_7552.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_044607_000002512082_00334_39466_7736.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_052725_000000732082_00334_39466_7698.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_052725_000001712082_00334_39466_7764.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_052940_000000362082_00334_39466_7702.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_053205_000001342082_00334_39466_8219.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_053205_000001902082_00334_39466_7965.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_053205_000005192082_00334_39466_7969.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_053205_000005192082_00334_39466_8233.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_053515_000001822082_00334_39466_8220.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_053616_000001822082_00334_39466_7966.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_063622_000001522082_00335_39467_7794.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_070911_000001902082_00335_39467_7928.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_081725_000000922082_00336_39468_7955.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_081839_000000182082_00336_39468_7926.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_103243_000001892082_00337_39469_7977.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_103534_000004212082_00337_39469_8141.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_103749_000002852082_00337_39469_8034.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_115231_000001902082_00338_39470_7987.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_120934_000002082082_00338_39470_8057.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_121048_000000612082_00338_39470_8028.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_121244_000000182082_00338_39470_8032.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_144018_000000732082_00340_39472_8059.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_144018_000002142082_00340_39472_8174.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_144233_000000792082_00340_39472_8145.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_145259_000001102082_00340_39472_8176.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_150314_000001032082_00340_39472_8143.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_161141_000001902082_00341_39473_8172.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_161141_000002512082_00341_39473_8194.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_163318_000001892082_00341_39473_8217.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_163637_000001712082_00341_39473_8223.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_172026_000000972082_00341_39473_8203.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_175627_000000982082_00342_39474_8225.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_181056_000000982082_00342_39474_8235.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_181200_000003052082_00342_39474_8276.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_185951_000001702082_00342_39474_8274.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_192611_000001532082_00343_39475_8395.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_203248_000003062082_00343_39475_8409.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```



ASA_WSM_1PNPDE20090917_205231_000000732082_00343_39475_8385.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_205231_000002752082_00343_39475_8551.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_205446_000001392082_00343_39475_8510.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_212838_000001102082_00344_39476_8683.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_213348_000000912082_00344_39476_8549.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_221434_000000982082_00344_39476_8547.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_222044_000002502082_00344_39476_8563.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_222044_000003602082_00344_39476_8676.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_222556_000000482082_00344_39476_8537.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_225828_000000732082_00345_39477_8539.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_225828_000002382082_00345_39477_8705.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_230043_000001032082_00345_39477_8678.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_231201_000003122082_00345_39477_8725.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_235620_000001902082_00345_39477_8864.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20090917_235620_000005502082_00345_39477_9119.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20090917_062651_000002202082_00335_39467_1718.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20090917_071429_000003122082_00335_39467_1798.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20090917_075801_000001892082_00336_39468_1800.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20090917_094706_000004212082_00337_39469_1926.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20090917_112630_000004892082_00338_39470_2059.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20090917_125942_000000732082_00339_39471_2168.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20090917_130602_000001892082_00339_39471_2186.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20090917_131318_000001152082_00339_39471_2183.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20090917_144515_000004102082_00340_39472_2465.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20090917_162234_000004522082_00341_39473_2451.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20090917_180026_000005872082_00342_39474_2681.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20090917_194102_000000982082_00343_39475_2794.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20090917_194253_000001902082_00343_39475_2806.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20090917_211743_000004092082_00344_39476_2839.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20090917_212508_000002452082_00344_39476_2837.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20090917_230156_000001042082_00345_39477_2853.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20090917_230355_000002502082_00345_39477_2855.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

AUXILIARY FILES ANALYSIS completed

#####

MODULE STEPPING ANALYSIS

#####

Analysis will be performed from 2009-09-17 00:00:00 to 2009-09-17 23:59:59

Results will be exported to the directory: ./RESULTS/DAILY/090917/MODULE\_STEPPING

Creating directory ./RESULTS/DAILY/090917/MODULE\_STEPPING...

Creating directory ./RESULTS/DAILY/090917/MODULE\_STEPPING/FIRST\_REFERENCE...

Creating directory ./RESULTS/DAILY/090917/MODULE\_STEPPING/SECOND\_REFERENCE...

Creating directory ./RESULTS/DAILY/090917/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE...

Deleting old files...

\*\*\*\*\*  
\*\*\*\*\*

Creating images comparing with second reference...

Exporting results to the directory ../../RESULTS/DAILY/090917/MODULE\_STEPPING/SECOND\_REFERENCE...

Polarization: H

Reference product: ASA\_MS\_0PNPDK20050922\_062651\_00000152041\_00034\_18625\_0041.N1

Test product: ASA\_MS\_0PNPDK20090917\_070651\_00000162082\_00335\_39467\_0877.N1

H

H

../../RESULTS/DAILY/090917/MODULE\_STEPPING/SECOND\_REFERENCE/TGH\_20090917\_070651-20050922\_062651.png

../../RESULTS/DAILY/090917/MODULE\_STEPPING/SECOND\_REFERENCE/TPH\_20090917\_070651-20050922\_062651.png

../../RESULTS/DAILY/090917/MODULE\_STEPPING/SECOND\_REFERENCE/RGH\_20090917\_070651-20050922\_062651.png

../../RESULTS/DAILY/090917/MODULE\_STEPPING/SECOND\_REFERENCE/RPH\_20090917\_070651-20050922\_062651.png

Polarization: V

Reference product: ASA\_MS\_\_0PNPDK20050923\_055514\_000000152041\_00048\_18639\_0042.N1  
Test product: ASA\_MS\_\_0PNPDK20090916\_073828\_000000162082\_00321\_39453\_0876.N1

V  
V

../../RESULTS/DAILY/090917/MODULE\_STEPPING/SECOND\_REFERENCE/TGV\_20090916\_073828-20050923\_055514.png  
../../RESULTS/DAILY/090917/MODULE\_STEPPING/SECOND\_REFERENCE/TPV\_20090916\_073828-20050923\_055514.png  
../../RESULTS/DAILY/090917/MODULE\_STEPPING/SECOND\_REFERENCE/RGV\_20090916\_073828-20050923\_055514.png  
../../RESULTS/DAILY/090917/MODULE\_STEPPING/SECOND\_REFERENCE/RPV\_20090916\_073828-20050923\_055514.png

\*\*\*\*\*  
\*\*\*\*\*

Creating images comparing with previous product reference...

Exporting results to the directory ../../RESULTS/DAILY/090917/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE...

Polarization: H

Reference product: ASA\_MS\_\_0PNPDK20090915\_081005\_000000162082\_00307\_39439\_0875.N1  
Test product: ASA\_MS\_\_0PNPDK20090917\_070651\_000000162082\_00335\_39467\_0877.N1

H  
H

../../RESULTS/DAILY/090917/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/TGH\_20090917\_070651-20090915\_081005.png  
../../RESULTS/DAILY/090917/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/TPH\_20090917\_070651-20090915\_081005.png  
../../RESULTS/DAILY/090917/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/RGH\_20090917\_070651-20090915\_081005.png  
../../RESULTS/DAILY/090917/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/RPH\_20090917\_070651-20090915\_081005.png

Polarization: V

Reference product: ASA\_MS\_\_0PNPDK20090914\_084143\_000000162082\_00293\_39425\_0874.N1  
Test product: ASA\_MS\_\_0PNPDK20090916\_073828\_000000162082\_00321\_39453\_0876.N1

V  
V

../../RESULTS/DAILY/090917/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/TGV\_20090916\_073828-20090914\_084143.png  
../../RESULTS/DAILY/090917/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/TPV\_20090916\_073828-20090914\_084143.png  
../../RESULTS/DAILY/090917/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/RGV\_20090916\_073828-20090914\_084143.png  
../../RESULTS/DAILY/090917/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/RPV\_20090916\_073828-20090914\_084143.png

MODULE\_STEPPING ANALYSIS completed

#####

CALIBRATION PULSES ANALYSIS

#####

Creating directory ./RESULTS/DAILY/090917/CALIBRATION\_PULSES...

\*\*\*\*\*  
\*\*\*\*\*

ALL ROWS Analysis will be performed from 2009-09-17 00:00:00 to 2009-09-17 23:59:59

Analysing products WVS IS2 V/V

Writing image ../../RESULTS/DAILY/090917//CALIBRATION\_PULSES/Calibration\_pulses\_all\_rows\_WVS\_IS2\_VV.png...

Analysing products GM1 SS3 H/H

Writing image ../../RESULTS/DAILY/090917//CALIBRATION\_PULSES/Calibration\_pulses\_all\_rows\_GM1\_SS3\_HH.png...

\*\*\*\*\*  
\*\*\*\*\*

TEMPORAL EVOLUTION Analysis will be performed from 2009-09-17 00:00:00 to 2009-09-17 23:59:59

Analysing products WVS IS2 V/V

Getting calibration pulses data for WVS IS2 V/V from 2009-09-17 00:00:00 to 2009-09-17 23:59:59. Rows: 1/5/9/13/17/21/25/29

Writing file ./RESULTS/DAILY/090917/CALIBRATION\_PULSES/Calibration\_pulses\_data\_WVS\_IS2\_VV\_2009-09-17\_1.dat...

Writing ../../RESULTS/DAILY/090917//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_WVS\_IS2\_VV\_1.png...

Writing ../../RESULTS/DAILY/090917//CALIBRATION\_PULSES/Transmit\_Power\_WVS\_IS2\_VV\_1.png...

Getting calibration pulses data for WVS IS2 V/V from 2009-09-17 00:00:00 to 2009-09-17 23:59:59. Rows: 2/6/10/14/18/22/26/30





Writing file ./RESULTS/DAILY/090917/CALIBRATION\_PULSES/Calibration\_pulses\_data\_WVS\_IS2\_VV\_2009-09-17\_2.dat...  
Writing ../../RESULTS/DAILY/090917//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_WVS\_IS2\_VV\_2.png...  
Writing ../../RESULTS/DAILY/090917//CALIBRATION\_PULSES/Transmit\_Power\_WVS\_IS2\_VV\_2.png...

Getting calibration pulses data for WVS IS2 V/V from 2009-09-17 00:00:00 to 2009-09-17 23:59:59. Rows: 3/7/11/15/19/23/27/31  
Writing file ./RESULTS/DAILY/090917/CALIBRATION\_PULSES/Calibration\_pulses\_data\_WVS\_IS2\_VV\_2009-09-17\_3.dat...  
Writing ../../RESULTS/DAILY/090917//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_WVS\_IS2\_VV\_3.png...  
Writing ../../RESULTS/DAILY/090917//CALIBRATION\_PULSES/Transmit\_Power\_WVS\_IS2\_VV\_3.png...

Getting calibration pulses data for WVS IS2 V/V from 2009-09-17 00:00:00 to 2009-09-17 23:59:59. Rows: 4/8/12/16/20/24/28/32  
Writing file ./RESULTS/DAILY/090917/CALIBRATION\_PULSES/Calibration\_pulses\_data\_WVS\_IS2\_VV\_2009-09-17\_4.dat...  
Writing ../../RESULTS/DAILY/090917//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_WVS\_IS2\_VV\_4.png...  
Writing ../../RESULTS/DAILY/090917//CALIBRATION\_PULSES/Transmit\_Power\_WVS\_IS2\_VV\_4.png...

Analysing products GM1 SS3 H/H  
Getting calibration pulses data for GM1 SS3 H/H from 2009-09-17 00:00:00 to 2009-09-17 23:59:59. Rows: 1/5/9/13/17/21/25/29  
Writing file ./RESULTS/DAILY/090917/CALIBRATION\_PULSES/Calibration\_pulses\_data\_GM1\_SS3\_HH\_2009-09-17\_1.dat...  
Writing ../../RESULTS/DAILY/090917//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_GM1\_SS3\_HH\_1.png...  
Writing ../../RESULTS/DAILY/090917//CALIBRATION\_PULSES/Transmit\_Power\_GM1\_SS3\_HH\_1.png...

Getting calibration pulses data for GM1 SS3 H/H from 2009-09-17 00:00:00 to 2009-09-17 23:59:59. Rows: 2/6/10/14/18/22/26/30  
Writing file ./RESULTS/DAILY/090917/CALIBRATION\_PULSES/Calibration\_pulses\_data\_GM1\_SS3\_HH\_2009-09-17\_2.dat...  
Writing ../../RESULTS/DAILY/090917//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_GM1\_SS3\_HH\_2.png...  
Writing ../../RESULTS/DAILY/090917//CALIBRATION\_PULSES/Transmit\_Power\_GM1\_SS3\_HH\_2.png...

Getting calibration pulses data for GM1 SS3 H/H from 2009-09-17 00:00:00 to 2009-09-17 23:59:59. Rows: 3/7/11/15/19/23/27/31  
Writing file ./RESULTS/DAILY/090917/CALIBRATION\_PULSES/Calibration\_pulses\_data\_GM1\_SS3\_HH\_2009-09-17\_3.dat...  
Writing ../../RESULTS/DAILY/090917//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_GM1\_SS3\_HH\_3.png...  
Writing ../../RESULTS/DAILY/090917//CALIBRATION\_PULSES/Transmit\_Power\_GM1\_SS3\_HH\_3.png...

Getting calibration pulses data for GM1 SS3 H/H from 2009-09-17 00:00:00 to 2009-09-17 23:59:59. Rows: 4/8/12/16/20/24/28/32  
Writing file ./RESULTS/DAILY/090917/CALIBRATION\_PULSES/Calibration\_pulses\_data\_GM1\_SS3\_HH\_2009-09-17\_4.dat...  
Writing ../../RESULTS/DAILY/090917//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_GM1\_SS3\_HH\_4.png...  
Writing ../../RESULTS/DAILY/090917//CALIBRATION\_PULSES/Transmit\_Power\_GM1\_SS3\_HH\_4.png...

CALIBRATION PULSES ANALYSIS completed  
#####

DOPPLER ANALYSIS  
#####  
Creating directory ./RESULTS/DAILY/090917/DOPPLER...

\*\*\*\*\*  
\*\*\*\*\*  
DOPPLER ANX Analysis will be performed from 2009-09-17 00:00:00 to 2009-09-17 23:59:59

Analysing products WVS IS2 V/V  
Getting doppler data for WVS IS2 V/V from 2009-09-17 00:00:00 to 2009-09-17 23:59:59...  
Writing file ./RESULTS/DAILY/090917/DOPPLER/Doppler\_data\_WVS\_IS2\_VV\_2009-09-17.dat...  
Running IDL program...  
Writing file ../../RESULTS/DAILY/090917/DOPPLER/DOPPLER\_ANX\_WVS\_IS2\_VV.png...

Analysing products GM1 SS1 H/H  
Getting doppler data for GM1 SS1 H/H from 2009-09-17 00:00:00 to 2009-09-17 23:59:59...  
Writing file ./RESULTS/DAILY/090917/DOPPLER/Doppler\_data\_GM1\_SS1\_HH\_2009-09-17.dat...  
Running IDL program...

Writing file ../../RESULTS/DAILY/090917/DOPPLER/DOPPLER\_ANX\_GM1\_SS1\_HH.png...

\*\*\*\*\*  
\*\*\*\*\*  
DOPPLER JUMPS Analysis will be performed on WSM products from 2009-09-17 00:00:00 to 2009-09-17 23:59:59

Analysing by default products WSM  
Getting doppler jumps data for WSM from 2009-09-17 00:00:00 to 2009-09-17 23:59:59...  
Writing file ./RESULTS/DAILY/090917/DOPPLER/Doppler\_Jumps\_data\_WSM\_2009-09-17.dat...  
Running IDL program...  
Writing file ../../RESULTS/DAILY/090917/DOPPLER/DOPPLER\_JUMPS\_ANX\_WSM.png...  
Writing file ../../RESULTS/DAILY/090917/DOPPLER/DOPPLER\_JUMPS\_Date\_WSM.png...

\*\*\*\*\*  
\*\*\*\*\*  
DOPPLER MAP Analysis will be performed from 2009-09-17 00:00:00 to 2009-09-17 23:59:59

Analysing products WVS IS2 V/V  
Loading predicted doppler values....  
Phase: descending  
Found data...  
Computing mean error doppler estimated-predicted...  
Mean error = -33.526806 Hz  
Writing file ../../RESULTS/DAILY/090917//DOPPLER/DOPPLER\_Estimated-Predicted-MeanError\_WVS\_IS2\_VV\_desc.jpg...  
Writing file ../../RESULTS/DAILY/090917//DOPPLER/DOPPLER\_Absolute\_WVS\_IS2\_VV\_desc.jpg...

\*\*\*\*\*  
Loading predicted doppler values....  
Phase: ascending  
Found data...  
Computing mean error doppler estimated-predicted...  
Mean error = -29.745714 Hz  
Writing file ../../RESULTS/DAILY/090917//DOPPLER/DOPPLER\_Estimated-Predicted-MeanError\_WVS\_IS2\_VV\_asc.jpg...  
Writing file ../../RESULTS/DAILY/090917//DOPPLER/DOPPLER\_Absolute\_WVS\_IS2\_VV\_asc.jpg...

\*\*\*\*\*  
Analysing products GM1 SS1 H/H  
Loading predicted doppler values....  
Phase: descending  
Found data...  
Computing mean error doppler estimated-predicted...  
Mean error = -23.646976 Hz  
Writing file ../../RESULTS/DAILY/090917//DOPPLER/DOPPLER\_Estimated-Predicted-MeanError\_GM1\_SS1\_HH\_desc.jpg...  
Writing file ../../RESULTS/DAILY/090917//DOPPLER/DOPPLER\_Absolute\_GM1\_SS1\_HH\_desc.jpg...

\*\*\*\*\*  
Loading predicted doppler values....  
Phase: ascending  
Found data...  
Computing mean error doppler estimated-predicted...  
Mean error = -28.190368 Hz  
Writing file ../../RESULTS/DAILY/090917//DOPPLER/DOPPLER\_Estimated-Predicted-MeanError\_GM1\_SS1\_HH\_asc.jpg...  
Writing file ../../RESULTS/DAILY/090917//DOPPLER/DOPPLER\_Absolute\_GM1\_SS1\_HH\_asc.jpg...

\*\*\*\*\*  
DOPPLER ANALYSIS completed  
#####



#####

Creating directory ./RESULTS/DAILY/090917/CHIRP...

\*\*\*\*\*  
\*\*\*\*\*  
CHIRP Analysis will be performed from 2009-09-17 00:00:00 to 2009-09-17 23:59:59

Analysing products WSM SS1 H/H

\*\*\*\*\*  
Getting ScaleFactor data for WSM SS1 H/H from 2009-09-17 00:00:00 to 2009-09-17 23:59:59...  
Writing file ./RESULTS/DAILY/090917/CHIRP/ScaleFactor\_data\_WSM\_SS1\_HH\_2009-09-17.dat...  
Running IDL program...  
Writing file ../../RESULTS/DAILY/090917/CHIRP/ScaleFactor\_ANX\_WSM\_SS1\_HH.png...  
Writing file ../../RESULTS/DAILY/090917/CHIRP/ScaleFactor\_DATE\_WSM\_SS1\_HH.png...

Analysing products WSM SS1 V/V

\*\*\*\*\*  
Getting ScaleFactor data for WSM SS1 V/V from 2009-09-17 00:00:00 to 2009-09-17 23:59:59...  
Writing file ./RESULTS/DAILY/090917/CHIRP/ScaleFactor\_data\_WSM\_SS1\_VV\_2009-09-17.dat...  
Running IDL program...  
Writing file ../../RESULTS/DAILY/090917/CHIRP/ScaleFactor\_ANX\_WSM\_SS1\_VV.png...  
Writing file ../../RESULTS/DAILY/090917/CHIRP/ScaleFactor\_DATE\_WSM\_SS1\_VV.png...

CHIRP ANALYSIS completed

#####

RAW DATA ANALYSIS

#####  
Analysis will be performed from 2009-09-17 00:00:00 to 2009-09-17 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/090917/RAW\_DATA

Creating directory ./RESULTS/DAILY/090917/RAW\_DATA...

\*\*\*\*\*  
Getting raw data for WVS from 2009-09-17 00:00:00 to 2009-09-17 23:59:59...  
Writing file ./RESULTS/DAILY/090917/RAW\_DATA/Raw\_data\_WVS\_2009-09-17.dat...  
Running IDL program to create graphs...

Creating image ../../RESULTS/DAILY/090917/RAW\_DATA/Raw\_data\_WVS\_input\_mean.png...  
Creating image ../../RESULTS/DAILY/090917/RAW\_DATA/Raw\_data\_WVS\_input\_stdev.png...  
Creating image ../../RESULTS/DAILY/090917/RAW\_DATA/Raw\_data\_WVS\_gain\_imbalance.png...

\*\*\*\*\*  
Getting raw data for IMM from 2009-09-17 00:00:00 to 2009-09-17 23:59:59...  
Writing file ./RESULTS/DAILY/090917/RAW\_DATA/Raw\_data\_IMM\_2009-09-17.dat...  
Running IDL program to create graphs...

Creating image ../../RESULTS/DAILY/090917/RAW\_DATA/Raw\_data\_IMM\_input\_mean.png...  
Creating image ../../RESULTS/DAILY/090917/RAW\_DATA/Raw\_data\_IMM\_input\_stdev.png...  
Creating image ../../RESULTS/DAILY/090917/RAW\_DATA/Raw\_data\_IMM\_gain\_imbalance.png...

RAW DATA ANALYSIS completed

#####

TELEMETRY ANALYSIS

#####  
Analysis will be performed from 2009-09-17 00:00:00 to 2009-09-17 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/090917/TELEMETRY

Creating directory ./RESULTS/DAILY/090917/TELEMETRY...

Looking for gaps and missing lines in WVS products...

\*\*\*\*\*

Checking 29 products from PDE...

Checking 21 products from PDK...

Looking for gaps and missing lines in GM1 products...

\*\*\*\*\*

Checking 45 products from PDE...

Checking 40 products from PDK...

Looking for gaps and missing lines in APM products...

\*\*\*\*\*

Checking 1 products from PDE...

Checking 1 products from PDK...

Looking for gaps and missing lines in IMM products...

\*\*\*\*\*

Checking 26 products from PDE...

Checking 4 products from PDK...

Looking for gaps and missing lines in WSM products...

\*\*\*\*\*

Checking 65 products from PDE...

Found product...ASA\_WSM\_1PNPDE20090917\_063622\_000001522082\_00335\_39467\_7794.N1 / 0 gaps / 1 missing lines

Found product...ASA\_WSM\_1PNPDE20090917\_081725\_00000922082\_00336\_39468\_7955.N1 / 0 gaps / 1 missing lines

Checking 17 products from PDK...

Creating graph of missing lines and gaps...

\*\*\*\*\*

Creating image: ./RESULTS/DAILY/090917/TELEMETRY/TELEMETRY\_Missing\_lines.png...

Creating image: ./RESULTS/DAILY/090917/TELEMETRY/TELEMETRY\_Gaps.png...

TELEMETRY ANALYSIS completed

#####

BROWSE PRODUCTS ANALYSIS

#####

Analysis will be performed on 2009-09-17

\*\*\*\*\*

Scanning directory /nfs-store/ASAR\_Data//ASA\_GM\_\_BP...

Results will be exported to the directory: /nfs-store/ASAR\_Data//ASA\_GM\_\_BP/JPG/20090917/

ANALYSIS COMPLETED: 0 GM browse products to see...

\*\*\*\*\*

\*\*\*\*\*

Scanning directory /nfs-store/ASAR\_Data//ASA\_AP\_\_BP...

Results will be exported to the directory: /nfs-store/ASAR\_Data//ASA\_AP\_\_BP/JPG/20090917/

ANALYSIS COMPLETED: 0 AP browse products to see...

\*\*\*\*\*

\*\*\*\*\*

Scanning directory /nfs-store/ASAR\_Data//ASA\_IM\_\_BP...

Results will be exported to the directory: /nfs-store/ASAR\_Data//ASA\_IM\_\_BP/JPG/20090917/

ANALYSIS COMPLETED: 0 IM browse products to see...

\*\*\*\*\*



\*\*\*\*\*  
Scanning directory /nfs-store/ASAR\_Data//ASA\_WS\_BP...  
Results will be exported to the directory: /nfs-store/ASAR\_Data//ASA\_WS\_BP/JPG/20090917/

ANALYSIS COMPLETED: 0 WS browse products to see...  
\*\*\*\*\*

BROWSE PRODUCTS ANALYSIS completed  
#####

HTML REPORT generation  
#####

Building file ./RESULTS/DAILY/090917/asarReport.html...  
Building DATA SUMMARY section...  
Building AUXILIARY FILES ANALYSIS section...  
Building MODULE STEPPING ANALYSIS section...  
Building CALIBRATION PULSES ANALYSIS section...  
Building DOPPLER ANALYSIS section...  
Building CHIRP ANALYSIS section...  
Building RAW DATA ANALYSIS section...  
Building TELEMETRY ANALYSIS section...

HTML REPORT generation completed  
#####





Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
ASA_APM_1PNPDE20090917_133100_000000542082_00339_39471_8045.N1	OK	OK	OK	OK
ASA_APM_1PNPDK20090917_131102_000000542082_00339_39471_2166.N1	OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_GM1_1PNPDE20090917_001023_000004162082_00331_39463_7204.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090917_002300_000003562082_00331_39463_7202.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090917_003902_000001812082_00331_39463_7197.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090917_005324_000002112082_00331_39463_7287.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090917_012324_000008942082_00332_39464_7332.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090917_015356_000001202082_00332_39464_7313.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090917_020336_000006102082_00332_39464_7330.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090917_021938_000001812082_00332_39464_7318.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090917_022717_000004892082_00332_39464_7427.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090917_023653_000003322082_00332_39464_7425.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090917_025138_000001692082_00333_39465_7409.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090917_025647_000001322082_00333_39465_7429.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090917_025950_000009722082_00333_39465_7550.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090917_031520_000000422082_00333_39465_7436.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090917_032215_000001322082_00333_39465_7444.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090917_034515_000012132082_00333_39465_7667.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090917_042715_000009302082_00334_39466_7585.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090917_042715_000011292082_00334_39466_7681.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090917_045034_000001752082_00334_39466_7583.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090917_050223_000001502082_00334_39466_7597.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090917_052448_000001502082_00334_39466_7814.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090917_053019_000001022082_00334_39466_7796.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090917_054050_000001812082_00334_39466_7798.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090917_060941_000001382082_00335_39467_7785.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090917_061503_000007002082_00335_39467_7768.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090917_063033_000003442082_00335_39467_7766.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090917_063855_000006822082_00335_39467_7869.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090917_065256_000001202082_00335_39467_7816.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090917_194622_000004712082_00343_39475_8278.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090917_195507_000001692082_00343_39475_8283.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090917_203011_000001502082_00343_39475_8287.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090917_203802_000005732082_00343_39475_8294.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090917_204613_000001812082_00343_39475_8411.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090917_205708_000010512082_00343_39475_8501.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090917_213029_000001932082_00344_39476_8420.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090917_213522_000001812082_00344_39476_8422.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090917_221047_000002232082_00344_39476_8427.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090917_221618_000002592082_00344_39476_8437.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090917_222649_000001812082_00344_39476_8439.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090917_224622_000004042082_00345_39477_9158.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090917_230822_000002172082_00345_39477_8568.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090917_230822_000002172082_00345_39477_9156.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090917_231720_000001022082_00345_39477_8575.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090917_234515_000000962082_00345_39477_8579.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20090917_235123_000002952082_00345_39477_8584.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090917_070524_000000842082_00335_39467_1720.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090917_071242_000001022082_00335_39467_1725.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090917_071943_000002832082_00335_39467_1727.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090917_080131_000004162082_00336_39468_1752.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090917_080743_000005492082_00336_39468_1802.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090917_082728_000005982082_00336_39468_1807.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090917_084600_000011412082_00336_39468_1897.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090917_093804_000005372082_00337_39469_1882.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090917_100421_000003442082_00337_39469_1936.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090917_102635_000003622082_00337_39469_1938.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090917_104238_000001812082_00337_39469_1946.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090917_111531_000006522082_00338_39470_1962.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090917_120711_000001382082_00338_39470_2073.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090917_121307_000007852082_00338_39470_2077.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090917_123230_000003082082_00338_39470_2085.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090917_125345_000003562082_00339_39471_2087.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090917_130112_000002832082_00339_39471_2158.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090917_130929_000000902082_00339_39471_2198.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20090917_133258_000005192082_00339_39471_2200.N1					OK	OK	OK	OK

ASA_GM1_1PNPDK20090917_134140_000015092082_00339_39471_2429.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20090917_135710_000005792082_00339_39471_2210.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20090917_141304_000002652082_00339_39471_2215.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20090917_142828_000007062082_00340_39472_2217.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20090917_144353_000000782082_00340_39472_2227.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20090917_145453_000003922082_00340_39472_2307.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20090917_152823_000011422082_00340_39472_2405.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20090917_160848_000000962082_00341_39473_2316.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20090917_161614_000003742082_00341_39473_2336.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20090917_163931_000005372082_00341_39473_2467.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20090917_170859_000006822082_00341_39473_2473.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20090917_172206_000003562082_00341_39473_2477.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20090917_175339_000001632082_00342_39474_2475.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20090917_175810_000001322082_00342_39474_2479.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20090917_181711_000001322082_00342_39474_2683.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20090917_184935_000006102082_00342_39474_2685.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20090917_190244_000003502082_00342_39474_2690.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20090917_192344_000001442082_00342_39474_2696.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20090917_192845_000000962082_00343_39475_2694.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20090917_193308_000001022082_00343_39475_2692.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20090917_193828_000001502082_00343_39475_2703.N1	OK	OK	OK	OK



Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_IMM_1PNPDE20090917_013927_000000532082_00332_39464_7399.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090917_014757_000000492082_00332_39464_7397.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090917_023524_000000792082_00332_39464_7536.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090917_025900_000000362082_00333_39465_7513.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090917_031559_000000632082_00333_39465_7538.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090917_031559_0000003632082_00333_39465_7603.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090917_031802_000000602082_00333_39465_7542.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090917_032002_000000602082_00333_39465_7546.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090917_045326_000000632082_00334_39466_7718.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090917_045326_000005272082_00334_39466_7758.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090917_045629_000001802082_00334_39466_7744.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090917_061320_000000912082_00335_39467_7880.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090917_082459_000001382082_00336_39468_7936.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090917_104926_000001022082_00337_39469_7998.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090917_133209_000000372082_00339_39471_8051.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090917_142139_000000392082_00339_39471_8055.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090917_161020_000000372082_00341_39473_8083.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090917_163100_000000672082_00341_39473_8186.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090917_175009_000000622082_00342_39474_8205.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090917_175009_000002002082_00342_39474_8231.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090917_181924_000001092082_00342_39474_8259.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090917_182214_000000942082_00342_39474_8262.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090917_195411_000000452082_00343_39475_8285.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090917_200847_000000702082_00343_39475_8407.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090917_213943_000000502082_00344_39476_8512.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20090917_225401_000000532082_00345_39477_8518.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20090917_075515_000001202082_00336_39468_1793.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20090917_095459_000001512082_00337_39469_1922.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20090917_123142_000000372082_00338_39470_2075.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20090917_145210_000000372082_00340_39472_2296.N1					OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WSM_1PNPDE20090917_011401_000000732082_00332_39464_7938.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_011401_000004092082_00332_39464_7534.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_011401_000004092082_00332_39464_7979.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_011615_000000552082_00332_39464_7942.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_011913_000000612082_00332_39464_7948.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_012159_000000732082_00332_39464_7401.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_021351_000001902082_00332_39464_7760.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_021351_000003422082_00332_39464_7904.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_021802_000000902082_00332_39464_7761.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_024557_000001902082_00333_39465_7554.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_024557_000002202082_00333_39465_7556.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_025116_000000182082_00333_39465_7517.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_025429_000001352082_00333_39465_7552.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_044607_000002512082_00334_39466_7736.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_052725_000000732082_00334_39466_7698.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_052725_000001712082_00334_39466_7764.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_052940_000000362082_00334_39466_7702.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_053205_000001342082_00334_39466_8219.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_053205_000001902082_00334_39466_7965.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_053205_000005192082_00334_39466_7969.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_053205_000005192082_00334_39466_8233.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_053515_000001822082_00334_39466_8220.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_053616_000001822082_00334_39466_7966.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_063622_000001522082_00335_39467_7794.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_070911_000001902082_00335_39467_7928.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_081725_000000922082_00336_39468_7955.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_081839_000000182082_00336_39468_7926.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_103243_000001892082_00337_39469_7977.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_103534_000004212082_00337_39469_8141.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_103749_000002852082_00337_39469_8034.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_115231_000001902082_00338_39470_7987.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_120934_000002082082_00338_39470_8057.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_121048_000000612082_00338_39470_8028.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_121244_000000182082_00338_39470_8032.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_144018_000000732082_00340_39472_8059.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_144018_000002142082_00340_39472_8174.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_144233_000000792082_00340_39472_8145.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_145259_000001102082_00340_39472_8176.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_150314_000001032082_00340_39472_8143.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_161141_000001902082_00341_39473_8172.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_161141_000002512082_00341_39473_8194.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_163318_000001892082_00341_39473_8217.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_163637_000001712082_00341_39473_8223.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_172026_000000972082_00341_39473_8203.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_175627_000000982082_00342_39474_8225.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_181056_000000982082_00342_39474_8235.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_181200_000003052082_00342_39474_8276.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_185951_000001702082_00342_39474_8274.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_192611_000001532082_00343_39475_8395.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_203248_000003062082_00343_39475_8409.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_205231_000000732082_00343_39475_8385.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_205231_000002752082_00343_39475_8551.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_205446_000001392082_00343_39475_8510.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_212838_000001102082_00344_39476_8683.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_213348_000000912082_00344_39476_8549.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_221434_000000982082_00344_39476_8547.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_222044_000002502082_00344_39476_8563.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_222044_000003602082_00344_39476_8676.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_222556_000000482082_00344_39476_8537.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_225828_000000732082_00345_39477_8539.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_225828_000002382082_00345_39477_8705.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_230043_000001032082_00345_39477_8678.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_231201_000003122082_00345_39477_8725.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20090917_235620_000001902082_00345_39477_8864.N1					OK	OK	OK	OK


ASA_WSM_1PNPDE20090917_235620_000005502082_00345_39477_9119.N1	OK	OK	OK	OK
ASA_WSM_1PNPDK20090917_062651_000002202082_00335_39467_1718.N1	OK	OK	OK	OK
ASA_WSM_1PNPDK20090917_071429_000003122082_00335_39467_1798.N1	OK	OK	OK	OK
ASA_WSM_1PNPDK20090917_075801_000001892082_00336_39468_1800.N1	OK	OK	OK	OK
ASA_WSM_1PNPDK20090917_094706_000004212082_00337_39469_1926.N1	OK	OK	OK	OK
ASA_WSM_1PNPDK20090917_112630_000004892082_00338_39470_2059.N1	OK	OK	OK	OK
ASA_WSM_1PNPDK20090917_125942_000000732082_00339_39471_2168.N1	OK	OK	OK	OK
ASA_WSM_1PNPDK20090917_130602_000001892082_00339_39471_2186.N1	OK	OK	OK	OK
ASA_WSM_1PNPDK20090917_131318_000001152082_00339_39471_2183.N1	OK	OK	OK	OK
ASA_WSM_1PNPDK20090917_144515_000004102082_00340_39472_2465.N1	OK	OK	OK	OK
ASA_WSM_1PNPDK20090917_162234_000004522082_00341_39473_2451.N1	OK	OK	OK	OK
ASA_WSM_1PNPDK20090917_180026_000005872082_00342_39474_2681.N1	OK	OK	OK	OK
ASA_WSM_1PNPDK20090917_194102_000000982082_00343_39475_2794.N1	OK	OK	OK	OK
ASA_WSM_1PNPDK20090917_194253_000001902082_00343_39475_2806.N1	OK	OK	OK	OK
ASA_WSM_1PNPDK20090917_211743_000004092082_00344_39476_2839.N1	OK	OK	OK	OK
ASA_WSM_1PNPDK20090917_212508_000002452082_00344_39476_2837.N1	OK	OK	OK	OK
ASA_WSM_1PNPDK20090917_230156_000001042082_00345_39477_2853.N1	OK	OK	OK	OK
ASA_WSM_1PNPDK20090917_230355_000002502082_00345_39477_2855.N1	OK	OK	OK	OK







Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WVS_1PNPDE20090917_001722_000003002082_00331_39463_7200.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090917_004203_000002392082_00331_39463_7195.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090917_004503_000004642082_00331_39463_7285.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090917_005654_000009442082_00331_39463_7290.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090917_014210_000003142082_00332_39464_7293.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090917_014854_000002542082_00332_39464_7311.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090917_015600_000004052082_00332_39464_7328.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090917_022238_00000302082_00332_39464_7316.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090917_022238_000002402082_00332_39464_7432.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090917_032429_000008242082_00333_39465_7448.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090917_033758_000002252082_00333_39465_7559.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090917_040531_000009892082_00333_39465_7590.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090917_050457_000009142082_00334_39466_7600.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090917_051957_000002402082_00334_39466_7771.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090917_054350_000014992082_00334_39466_7819.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090917_065021_000001042082_00335_39467_7809.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090917_065459_000003292082_00335_39467_7806.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090917_195759_000006142082_00343_39475_8281.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090917_201004_000011692082_00343_39475_8297.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090917_204914_000001502082_00343_39475_8418.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090917_214038_000017692082_00344_39476_8425.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090917_222950_000002852082_00344_39476_8430.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090917_223350_000007042082_00344_39476_8566.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090917_223350_000007042082_00344_39476_9170.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090917_225459_000001642082_00345_39477_8573.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090917_225459_000001642082_00345_39477_9161.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090917_231907_000012742082_00345_39477_8582.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20090917_234653_000002252082_00345_39477_8587.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090917_070014_000002702082_00335_39467_1723.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090917_072426_000018142082_00335_39467_1762.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090917_083725_000004652082_00336_39468_1805.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090917_090502_000019342082_00336_39468_1874.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090917_101006_000009442082_00337_39469_1941.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090917_104538_000001952082_00337_39469_1944.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090917_105114_000014092082_00337_39469_1960.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090917_113443_000010192082_00338_39470_2071.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090917_115549_000006442082_00338_39470_2080.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090917_122614_000002852082_00338_39470_2083.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090917_123742_000009242082_00338_39470_2095.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090917_131525_000008692082_00339_39471_2203.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090917_140650_000003302082_00339_39471_2206.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090917_141733_000002092082_00339_39471_2213.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090917_142224_000003142082_00339_39471_2220.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090917_151010_000010492082_00340_39472_2310.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090917_154726_000012442082_00340_39472_2334.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090917_164833_000011842082_00341_39473_2471.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090917_172802_000012892082_00341_39473_2482.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090917_182354_000014992082_00342_39474_2688.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20090917_190838_000008692082_00342_39474_2706.N1					OK	OK	OK	OK

### Calibration pulses for GM1 SS3 H/H




Calibration pulses for GM1 SS3 H/H







Calibration pulses for GM1 SS3 H/H




17-Sep



17-Sep







17-Sep



17-Sep


rows: \_ 3 \_ 7 \_ 11 \_ 15 \_ 19 \_ 23 \_ 27 \_ 31

### Calibration pulses for GM1 SS3 H/H




rows: \_ 4 \_ 8 \_ 12 \_ 16 \_ 20 <sup>17-Sep</sup> \_ 24 \_ 28 \_ 32

Calibration pulses for WVS IS2 V/V







Calibration pulses for WVS IS2 V/V




### Calibration pulses for WVS IS2 V/V




Calibration pulses for WVS IS2 V/V




17-Sep



17-Sep




17-Sep






17-Sep

rows: \_ 4 \_ 8 \_ 12 \_ 16 \_ 20 \_ 24 \_ 28 \_ 32













rows: \_ 1 \_ 5 \_ 9 \_ 13 \_ 17 \_ 21 \_ 25 \_ 29









rows: \_ 2 \_ 6 \_ 10 \_ 14 \_ 18 \_ 22 \_ 26 \_ 30





rows: **3** **7** **11** **15** **19** **23** **27** **31**













17-Sep  
rows: \_ 2 \_ 6 \_ 10 \_ 14 \_ 18 \_ 22 \_ 26 \_ 30





17-Sep  
rows: \_ 3 \_ 7 \_ 11 \_ 15 \_ 19 \_ 23 \_ 27 \_ 31





rows: \_ 4 \_ 8 \_ 12 \_ 16 \_ 20 \_ 24 \_ 28 \_ 32













Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion				
ASA_APM_1PNPDK20090917_131102_000000542082_00339_39471_2166.N1						IS4 V/H 82	39471	339	4.07	
ASA_APM_1PNPDE20090917_133100_000000542082_00339_39471_8045.N1						IS4 V/H 82	39471	339	4.07	

Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_GM1_1PNPDE20090917_001023_000004162082_00331_39463_7204.N1						SS1	H/H	82	39463	331	4.07
ASA_GM1_1PNPDE20090917_002300_000003562082_00331_39463_7202.N1						SS1	H/H	82	39463	331	4.07
ASA_GM1_1PNPDE20090917_003902_000001812082_00331_39463_7197.N1						SS1	H/H	82	39463	331	4.07
ASA_GM1_1PNPDE20090917_005324_000002112082_00331_39463_7287.N1						SS1	H/H	82	39463	331	4.07
ASA_GM1_1PNPDE20090917_012324_000008942082_00332_39464_7332.N1						SS1	H/H	82	39464	332	4.07
ASA_GM1_1PNPDE20090917_015356_000001202082_00332_39464_7313.N1						SS1	H/H	82	39464	332	4.07
ASA_GM1_1PNPDE20090917_020336_000006102082_00332_39464_7330.N1						SS1	H/H	82	39464	332	4.07
ASA_GM1_1PNPDE20090917_021938_000001812082_00332_39464_7318.N1						SS1	H/H	82	39464	332	4.07
ASA_GM1_1PNPDE20090917_022717_000004892082_00332_39464_7427.N1						SS1	H/H	82	39464	332	4.07
ASA_GM1_1PNPDE20090917_023653_000003322082_00332_39464_7425.N1						SS1	H/H	82	39464	332	4.07
ASA_GM1_1PNPDE20090917_025138_000001692082_00333_39465_7409.N1						SS1	H/H	82	39465	333	4.07
ASA_GM1_1PNPDE20090917_025647_000001322082_00333_39465_7429.N1						SS1	H/H	82	39465	333	4.07
ASA_GM1_1PNPDE20090917_025950_000009722082_00333_39465_7550.N1						SS1	H/H	82	39465	333	4.07
ASA_GM1_1PNPDE20090917_031520_00000422082_00333_39465_7436.N1						SS1	H/H	82	39465	333	4.07
ASA_GM1_1PNPDE20090917_032215_000001322082_00333_39465_7444.N1						SS1	H/H	82	39465	333	4.07
ASA_GM1_1PNPDE20090917_034515_000012132082_00333_39465_7667.N1						SS1	H/H	82	39465	333	4.07
ASA_GM1_1PNPDE20090917_042715_000009302082_00334_39466_7585.N1						SS1	H/H	82	39466	334	4.07
ASA_GM1_1PNPDE20090917_042715_000011292082_00334_39466_7681.N1						SS1	H/H	82	39466	334	4.07
ASA_GM1_1PNPDE20090917_045034_000001752082_00334_39466_7583.N1						SS1	H/H	82	39466	334	4.07
ASA_GM1_1PNPDE20090917_050223_000001502082_00334_39466_7597.N1						SS1	H/H	82	39466	334	4.07
ASA_GM1_1PNPDE20090917_052448_000001502082_00334_39466_7814.N1						SS1	H/H	82	39466	334	4.07
ASA_GM1_1PNPDE20090917_053019_000001022082_00334_39466_7796.N1						SS1	H/H	82	39466	334	4.07
ASA_GM1_1PNPDE20090917_054050_000001812082_00334_39466_7798.N1						SS1	H/H	82	39466	334	4.07
ASA_GM1_1PNPDE20090917_060941_000001382082_00335_39467_7785.N1						SS1	H/H	82	39467	335	4.07
ASA_GM1_1PNPDE20090917_061503_000007002082_00335_39467_7768.N1						SS1	H/H	82	39467	335	4.07
ASA_GM1_1PNPDE20090917_063033_000003442082_00335_39467_7766.N1						SS1	H/H	82	39467	335	4.07
ASA_GM1_1PNPDE20090917_063855_000006822082_00335_39467_7869.N1						SS1	H/H	82	39467	335	4.07
ASA_GM1_1PNPDE20090917_065256_000001202082_00335_39467_7816.N1						SS1	H/H	82	39467	335	4.07
ASA_GM1_1PNPDK20090917_070524_000000842082_00335_39467_1720.N1						SS1	H/H	82	39467	335	4.07
ASA_GM1_1PNPDK20090917_071242_000001022082_00335_39467_1725.N1						SS1	H/H	82	39467	335	4.07
ASA_GM1_1PNPDK20090917_071943_000002832082_00335_39467_1727.N1						SS1	H/H	82	39467	335	4.07
ASA_GM1_1PNPDK20090917_080131_000004162082_00336_39468_1752.N1						SS1	H/H	82	39468	336	4.07
ASA_GM1_1PNPDK20090917_080743_000005492082_00336_39468_1802.N1						SS1	H/H	82	39468	336	4.07
ASA_GM1_1PNPDK20090917_082728_000005982082_00336_39468_1807.N1						SS1	H/H	82	39468	336	4.07
ASA_GM1_1PNPDK20090917_084600_000011412082_00336_39468_1897.N1						SS1	H/H	82	39468	336	4.07
ASA_GM1_1PNPDK20090917_093804_000005372082_00337_39469_1882.N1						SS1	H/H	82	39469	337	4.07
ASA_GM1_1PNPDK20090917_100421_000003442082_00337_39469_1936.N1						SS1	H/H	82	39469	337	4.07
ASA_GM1_1PNPDK20090917_102635_000003622082_00337_39469_1938.N1						SS1	H/H	82	39469	337	4.07
ASA_GM1_1PNPDK20090917_104238_000001812082_00337_39469_1946.N1						SS1	H/H	82	39469	337	4.07
ASA_GM1_1PNPDK20090917_111531_000006522082_00338_39470_1962.N1						SS1	H/H	82	39470	338	4.07
ASA_GM1_1PNPDK20090917_120711_000001382082_00338_39470_2073.N1						SS1	H/H	82	39470	338	4.07
ASA_GM1_1PNPDK20090917_121307_000007852082_00338_39470_2077.N1						SS1	H/H	82	39470	338	4.07
ASA_GM1_1PNPDK20090917_123230_000003082082_00338_39470_2085.N1						SS1	H/H	82	39470	338	4.07
ASA_GM1_1PNPDK20090917_125345_000003562082_00339_39471_2087.N1						SS1	H/H	82	39471	339	4.07
ASA_GM1_1PNPDK20090917_130112_000002832082_00339_39471_2158.N1						SS1	H/H	82	39471	339	4.07
ASA_GM1_1PNPDK20090917_130929_000000902082_00339_39471_2198.N1						SS1	H/H	82	39471	339	4.07
ASA_GM1_1PNPDK20090917_133258_000005192082_00339_39471_2200.N1						SS1	H/H	82	39471	339	4.07
ASA_GM1_1PNPDK20090917_134140_000015092082_00339_39471_2429.N1						SS1	H/H	82	39471	339	4.07
ASA_GM1_1PNPDK20090917_135710_000005792082_00339_39471_2210.N1						SS1	H/H	82	39471	339	4.07
ASA_GM1_1PNPDK20090917_141304_000002652082_00339_39471_2215.N1						SS1	H/H	82	39471	339	4.07
ASA_GM1_1PNPDK20090917_142828_000007062082_00340_39472_2217.N1						SS1	H/H	82	39472	340	4.07
ASA_GM1_1PNPDK20090917_144353_000000782082_00340_39472_2227.N1						SS1	H/H	82	39472	340	4.07
ASA_GM1_1PNPDK20090917_145453_000003922082_00340_39472_2307.N1						SS1	H/H	82	39472	340	4.07
ASA_GM1_1PNPDK20090917_152823_000011422082_00340_39472_2405.N1						SS1	H/H	82	39472	340	4.07
ASA_GM1_1PNPDK20090917_160848_000000962082_00341_39473_2316.N1						SS1	H/H	82	39473	341	4.07
ASA_GM1_1PNPDK20090917_161614_000003742082_00341_39473_2336.N1						SS1	H/H	82	39473	341	4.07
ASA_GM1_1PNPDK20090917_163931_000005372082_00341_39473_2467.N1						SS1	H/H	82	39473	341	4.07
ASA_GM1_1PNPDK20090917_170859_000006822082_00341_39473_2473.N1						SS1	H/H	82	39473	341	4.07
ASA_GM1_1PNPDK20090917_172206_000003562082_00341_39473_2477.N1						SS1	H/H	82	39473	341	4.07
ASA_GM1_1PNPDK20090917_175339_000001632082_00342_39474_2475.N1						SS1	H/H	82	39474	342	4.07
ASA_GM1_1PNPDK20090917_175810_000001322082_00342_39474_2479.N1						SS1	H/H	82	39474	342	4.07
ASA_GM1_1PNPDK20090917_181711_000001322082_00342_39474_2683.N1						SS1	H/H	82	39474	342	4.07
ASA_GM1_1PNPDK20090917_184935_000006102082_00342_39474_2685.N1						SS1	H/H	82	39474	342	4.07
ASA_GM1_1PNPDK20090917_190244_000003502082_00342_39474_2690.N1						SS1	H/H	82	39474	342	4.07
ASA_GM1_1PNPDK20090917_192344_000001442082_00342_39474_2696.N1						SS1	H/H	82	39474	342	4.07
ASA_GM1_1PNPDK20090917_192845_000000962082_00343_39475_2694.N1						SS1	H/H	82	39475	343	4.07
ASA_GM1_1PNPDK20090917_193308_000001022082_00343_39475_2692.N1						SS1	H/H	82	39475	343	4.07

ASA_GM1_1PNPDK20090917_193828_000001502082_00343_39475_2703.N1	SS1	H/H	82	39475	343	4.07
ASA_GM1_1PNPDE20090917_194622_000004712082_00343_39475_8278.N1	SS1	H/H	82	39475	343	4.07
ASA_GM1_1PNPDE20090917_195507_000001692082_00343_39475_8283.N1	SS1	H/H	82	39475	343	4.07
ASA_GM1_1PNPDE20090917_203011_000001502082_00343_39475_8287.N1	SS1	H/H	82	39475	343	4.07
ASA_GM1_1PNPDE20090917_203802_000005732082_00343_39475_8294.N1	SS1	H/H	82	39475	343	4.07
ASA_GM1_1PNPDE20090917_204613_000001812082_00343_39475_8411.N1	SS1	H/H	82	39475	343	4.07
ASA_GM1_1PNPDE20090917_205708_000010512082_00343_39475_8501.N1	SS1	H/H	82	39475	343	4.07
ASA_GM1_1PNPDE20090917_213029_000001932082_00344_39476_8420.N1	SS1	H/H	82	39476	344	4.07
ASA_GM1_1PNPDE20090917_213522_000001812082_00344_39476_8422.N1	SS1	H/H	82	39476	344	4.07
ASA_GM1_1PNPDE20090917_221047_000002232082_00344_39476_8427.N1	SS1	H/H	82	39476	344	4.07
ASA_GM1_1PNPDE20090917_221618_000002592082_00344_39476_8437.N1	SS1	H/H	82	39476	344	4.07
ASA_GM1_1PNPDE20090917_222649_000001812082_00344_39476_8439.N1	SS1	H/H	82	39476	344	4.07
ASA_GM1_1PNPDE20090917_224622_000004042082_00345_39477_9158.N1	SS1	H/H	82	39477	345	4.07
ASA_GM1_1PNPDE20090917_230822_000002172082_00345_39477_9156.N1	SS1	H/H	82	39477	345	4.07
ASA_GM1_1PNPDE20090917_230822_000002172082_00345_39477_8568.N1	SS1	H/H	82	39477	345	4.07
ASA_GM1_1PNPDE20090917_231720_000001022082_00345_39477_8575.N1	SS1	H/H	82	39477	345	4.07
ASA_GM1_1PNPDE20090917_234515_000000962082_00345_39477_8579.N1	SS1	H/H	82	39477	345	4.07
ASA_GM1_1PNPDE20090917_235123_000002952082_00345_39477_8584.N1	SS1	H/H	82	39477	345	4.07

Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_IMM_1PNPDE20090917_013927_000000532082_00332_39464_7399.N1						IS3	V/V	82	39464	332	4.07
ASA_IMM_1PNPDE20090917_014757_000000492082_00332_39464_7397.N1						IS7	V/V	82	39464	332	4.07
ASA_IMM_1PNPDE20090917_023524_000000792082_00332_39464_7536.N1						IS2	H/H	82	39464	332	4.07
ASA_IMM_1PNPDE20090917_025900_000000362082_00333_39465_7513.N1						IS3	V/V	82	39465	333	4.07
ASA_IMM_1PNPDE20090917_031559_0000003632082_00333_39465_7603.N1						IS2	V/V	82	39465	333	4.07
ASA_IMM_1PNPDE20090917_031559_000000632082_00333_39465_7538.N1						IS2	V/V	82	39465	333	4.07
ASA_IMM_1PNPDE20090917_031802_000000602082_00333_39465_7542.N1						IS2	V/V	82	39465	333	4.07
ASA_IMM_1PNPDE20090917_032002_000000602082_00333_39465_7546.N1						IS2	V/V	82	39465	333	4.07
ASA_IMM_1PNPDE20090917_045326_000005272082_00334_39466_7758.N1						IS2	V/V	82	39466	334	4.07
ASA_IMM_1PNPDE20090917_045326_000000632082_00334_39466_7718.N1						IS2	V/V	82	39466	334	4.07
ASA_IMM_1PNPDE20090917_045629_000001802082_00334_39466_7744.N1						IS2	V/V	82	39466	334	4.07
ASA_IMM_1PNPDE20090917_061320_000000912082_00335_39467_7880.N1						IS2	V/V	82	39467	335	4.07
ASA_IMM_1PNPDK20090917_075515_000001202082_00336_39468_1793.N1						IS2	V/V	82	39468	336	4.07
ASA_IMM_1PNPDE20090917_082459_000001382082_00336_39468_7936.N1						IS2	V/V	82	39468	336	4.07
ASA_IMM_1PNPDK20090917_095459_000001512082_00337_39469_1922.N1						IS2	V/V	82	39469	337	4.07
ASA_IMM_1PNPDE20090917_104926_000001022082_00337_39469_7998.N1						IS2	V/V	82	39469	337	4.07
ASA_IMM_1PNPDK20090917_123142_000000372082_00338_39470_2075.N1						IS1	V/V	82	39470	338	4.07
ASA_IMM_1PNPDE20090917_133209_000000372082_00339_39471_8051.N1						IS2	V/V	82	39471	339	4.07
ASA_IMM_1PNPDE20090917_142139_000000392082_00339_39471_8055.N1						IS2	V/V	82	39471	339	4.07
ASA_IMM_1PNPDK20090917_145210_000000372082_00340_39472_2296.N1						IS2	V/V	82	39472	340	4.07
ASA_IMM_1PNPDE20090917_161020_000000372082_00341_39473_8083.N1						IS3	V/V	82	39473	341	4.07
ASA_IMM_1PNPDE20090917_163100_000000672082_00341_39473_8186.N1						IS2	H/H	82	39473	341	4.07
ASA_IMM_1PNPDE20090917_175009_000002002082_00342_39474_8231.N1						IS6	V/V	82	39474	342	4.07
ASA_IMM_1PNPDE20090917_175009_000000622082_00342_39474_8205.N1						IS6	V/V	82	39474	342	4.07
ASA_IMM_1PNPDE20090917_181924_000001092082_00342_39474_8259.N1						IS2	V/V	82	39474	342	4.07
ASA_IMM_1PNPDE20090917_182214_000000942082_00342_39474_8262.N1						IS2	V/V	82	39474	342	4.07
ASA_IMM_1PNPDE20090917_195411_000000452082_00343_39475_8285.N1						IS4	H/H	82	39475	343	4.07
ASA_IMM_1PNPDE20090917_200847_000000702082_00343_39475_8407.N1						IS6	V/V	82	39475	343	4.07
ASA_IMM_1PNPDE20090917_213943_000000502082_00344_39476_8512.N1						IS2	V/V	82	39476	344	4.07
ASA_IMM_1PNPDE20090917_225401_000000532082_00345_39477_8518.N1						IS2	V/V	82	39477	345	4.07



Filename	Pol	Timestamp	count(Module)
ASA_MS__0PNPDK20090917_070651_000000162082_00335_39467_0877.N1	H	2009-09-17 07:06:51	320





Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WSM_1PNPDE20090917_011401_000004092082_00332_39464_7979.N1						SS1	H/H	82	39464	332	4.07
ASA_WSM_1PNPDE20090917_011401_00000732082_00332_39464_7938.N1						SS1	H/H	82	39464	332	4.07
ASA_WSM_1PNPDE20090917_011401_000004092082_00332_39464_7534.N1						SS1	H/H	82	39464	332	4.07
ASA_WSM_1PNPDE20090917_011615_00000552082_00332_39464_7942.N1						SS1	H/H	82	39464	332	4.07
ASA_WSM_1PNPDE20090917_011913_00000612082_00332_39464_7948.N1						SS1	H/H	82	39464	332	4.07
ASA_WSM_1PNPDE20090917_012159_00000732082_00332_39464_7401.N1						SS1	H/H	82	39464	332	4.07
ASA_WSM_1PNPDE20090917_021351_000003422082_00332_39464_7904.N1						SS1	H/H	82	39464	332	4.07
ASA_WSM_1PNPDE20090917_021351_000001902082_00332_39464_7760.N1						SS1	H/H	82	39464	332	4.07
ASA_WSM_1PNPDE20090917_021802_00000902082_00332_39464_7761.N1						SS1	H/H	82	39464	332	4.07
ASA_WSM_1PNPDE20090917_024557_000002202082_00333_39465_7556.N1						SS1	V/V	82	39465	333	4.07
ASA_WSM_1PNPDE20090917_024557_000001902082_00333_39465_7554.N1						SS1	V/V	82	39465	333	4.07
ASA_WSM_1PNPDE20090917_025116_000000182082_00333_39465_7517.N1						SS1	H/H	82	39465	333	4.07
ASA_WSM_1PNPDE20090917_025429_000001352082_00333_39465_7552.N1						SS1	H/H	82	39465	333	4.07
ASA_WSM_1PNPDE20090917_044607_000002512082_00334_39466_7736.N1						SS1	H/H	82	39466	334	4.07
ASA_WSM_1PNPDE20090917_052725_000001712082_00334_39466_7764.N1						SS1	H/H	82	39466	334	4.07
ASA_WSM_1PNPDE20090917_052725_00000732082_00334_39466_7698.N1						SS1	H/H	82	39466	334	4.07
ASA_WSM_1PNPDE20090917_052940_00000362082_00334_39466_7702.N1						SS1	H/H	82	39466	334	4.07
ASA_WSM_1PNPDE20090917_053205_000005192082_00334_39466_8233.N1						SS1	H/H	82	39466	334	4.07
ASA_WSM_1PNPDE20090917_053205_000001902082_00334_39466_7965.N1						SS1	H/H	82	39466	334	4.07
ASA_WSM_1PNPDE20090917_053205_000001342082_00334_39466_8219.N1						SS1	H/H	82	39466	334	4.07
ASA_WSM_1PNPDE20090917_053205_000005192082_00334_39466_7969.N1						SS1	H/H	82	39466	334	4.07
ASA_WSM_1PNPDE20090917_053515_000001822082_00334_39466_8220.N1						SS1	H/H	82	39466	334	4.07
ASA_WSM_1PNPDE20090917_053616_000001822082_00334_39466_7966.N1						SS1	H/H	82	39466	334	4.07
ASA_WSM_1PNPDK20090917_062651_000002202082_00335_39467_1718.N1						SS1	H/H	82	39467	335	4.07
ASA_WSM_1PNPDE20090917_063622_000001522082_00335_39467_7794.N1						SS1	H/H	82	39467	335	4.07
ASA_WSM_1PNPDE20090917_070911_000001902082_00335_39467_7928.N1						SS1	H/H	82	39467	335	4.07
ASA_WSM_1PNPDK20090917_071429_000003122082_00335_39467_1798.N1						SS1	H/H	82	39467	335	4.07
ASA_WSM_1PNPDK20090917_075801_000001892082_00336_39468_1800.N1						SS1	H/H	82	39468	336	4.07
ASA_WSM_1PNPDE20090917_081725_00000922082_00336_39468_7955.N1						SS1	V/V	82	39468	336	4.07
ASA_WSM_1PNPDE20090917_081839_000000182082_00336_39468_7926.N1						SS1	V/V	82	39468	336	4.07
ASA_WSM_1PNPDK20090917_094706_000004212082_00337_39469_1926.N1						SS1	H/H	82	39469	337	4.07
ASA_WSM_1PNPDE20090917_103243_000001892082_00337_39469_7977.N1						SS1	H/H	82	39469	337	4.07
ASA_WSM_1PNPDE20090917_103534_000004212082_00337_39469_8141.N1						SS1	H/H	82	39469	337	4.07
ASA_WSM_1PNPDE20090917_103749_000002852082_00337_39469_8034.N1						SS1	H/H	82	39469	337	4.07
ASA_WSM_1PNPDK20090917_112630_000004892082_00338_39470_2059.N1						SS1	H/H	82	39470	338	4.07
ASA_WSM_1PNPDE20090917_115231_000001902082_00338_39470_7987.N1						SS1	H/H	82	39470	338	4.07
ASA_WSM_1PNPDE20090917_120934_000002082082_00338_39470_8057.N1						SS1	H/H	82	39470	338	4.07
ASA_WSM_1PNPDE20090917_121048_000000612082_00338_39470_8028.N1						SS1	H/H	82	39470	338	4.07
ASA_WSM_1PNPDE20090917_121244_000000182082_00338_39470_8032.N1						SS1	H/H	82	39470	338	4.07
ASA_WSM_1PNPDK20090917_125942_00000732082_00339_39471_2168.N1						SS1	V/V	82	39471	339	4.07
ASA_WSM_1PNPDK20090917_130602_000001892082_00339_39471_2186.N1						SS1	H/H	82	39471	339	4.07
ASA_WSM_1PNPDK20090917_131318_000001152082_00339_39471_2183.N1						SS1	H/H	82	39471	339	4.07
ASA_WSM_1PNPDE20090917_144018_00000732082_00340_39472_8059.N1						SS1	V/V	82	39472	340	4.07
ASA_WSM_1PNPDE20090917_144018_000002142082_00340_39472_8174.N1						SS1	V/V	82	39472	340	4.07
ASA_WSM_1PNPDE20090917_144233_00000792082_00340_39472_8145.N1						SS1	V/V	82	39472	340	4.07
ASA_WSM_1PNPDK20090917_144515_000004102082_00340_39472_2465.N1						SS1	H/H	82	39472	340	4.07
ASA_WSM_1PNPDE20090917_145259_000001102082_00340_39472_8176.N1						SS1	H/H	82	39472	340	4.07
ASA_WSM_1PNPDE20090917_150314_000001032082_00340_39472_8143.N1						SS1	V/V	82	39472	340	4.07
ASA_WSM_1PNPDE20090917_161141_000002512082_00341_39473_8194.N1						SS1	H/H	82	39473	341	4.07
ASA_WSM_1PNPDE20090917_161141_000001902082_00341_39473_8172.N1						SS1	H/H	82	39473	341	4.07
ASA_WSM_1PNPDK20090917_162234_000004522082_00341_39473_2451.N1						SS1	H/H	82	39473	341	4.07
ASA_WSM_1PNPDE20090917_163318_000001892082_00341_39473_8217.N1						SS1	H/H	82	39473	341	4.07
ASA_WSM_1PNPDE20090917_163637_000001712082_00341_39473_8223.N1						SS1	V/V	82	39473	341	4.07
ASA_WSM_1PNPDE20090917_172026_00000972082_00341_39473_8203.N1						SS1	H/H	82	39473	341	4.07
ASA_WSM_1PNPDE20090917_175627_00000982082_00342_39474_8225.N1						SS1	V/V	82	39474	342	4.07
ASA_WSM_1PNPDK20090917_180026_000005872082_00342_39474_2681.N1						SS1	H/H	82	39474	342	4.07
ASA_WSM_1PNPDE20090917_181056_00000982082_00342_39474_8235.N1						SS1	H/H	82	39474	342	4.07
ASA_WSM_1PNPDE20090917_181200_000003052082_00342_39474_8276.N1						SS1	H/H	82	39474	342	4.07
ASA_WSM_1PNPDE20090917_185951_000001702082_00342_39474_8274.N1						SS1	H/H	82	39474	342	4.07
ASA_WSM_1PNPDE20090917_192611_000001532082_00343_39475_8395.N1						SS1	H/H	82	39475	343	4.07
ASA_WSM_1PNPDK20090917_194102_00000982082_00343_39475_2794.N1						SS1	H/H	82	39475	343	4.07
ASA_WSM_1PNPDK20090917_194253_000001902082_00343_39475_2806.N1						SS1	V/V	82	39475	343	4.07
ASA_WSM_1PNPDE20090917_203248_000003062082_00343_39475_8409.N1						SS1	H/H	82	39475	343	4.07
ASA_WSM_1PNPDE20090917_205231_00000732082_00343_39475_8385.N1						SS1	V/V	82	39475	343	4.07
ASA_WSM_1PNPDE20090917_205231_000002752082_00343_39475_8551.N1						SS1	V/V	82	39475	343	4.07
ASA_WSM_1PNPDE20090917_205446_000001392082_00343_39475_8510.N1						SS1	V/V	82	39475	343	4.07
ASA_WSM_1PNPDK20090917_211743_000004092082_00344_39476_2839.N1						SS1	V/V	82	39476	344	4.07


ASA_WSM_1PNPDK20090917_212508_000002452082_00344_39476_2837.N1	SS1	H/H	82	39476	344	4.07
ASA_WSM_1PNPDE20090917_212838_000001102082_00344_39476_8683.N1	SS1	H/H	82	39476	344	4.07
ASA_WSM_1PNPDE20090917_213348_000000912082_00344_39476_8549.N1	SS1	H/H	82	39476	344	4.07
ASA_WSM_1PNPDE20090917_221434_000000982082_00344_39476_8547.N1	SS1	H/H	82	39476	344	4.07
ASA_WSM_1PNPDE20090917_222044_000003602082_00344_39476_8676.N1	SS1	H/H	82	39476	344	4.07
ASA_WSM_1PNPDE20090917_222044_000002502082_00344_39476_8563.N1	SS1	H/H	82	39476	344	4.07
ASA_WSM_1PNPDE20090917_222556_000000482082_00344_39476_8537.N1	SS1	H/H	82	39476	344	4.07
ASA_WSM_1PNPDE20090917_225828_000000732082_00345_39477_8539.N1	SS1	V/V	82	39477	345	4.07
ASA_WSM_1PNPDE20090917_225828_000002382082_00345_39477_8705.N1	SS1	V/V	82	39477	345	4.07
ASA_WSM_1PNPDE20090917_230043_000001032082_00345_39477_8678.N1	SS1	V/V	82	39477	345	4.07
ASA_WSM_1PNPDK20090917_230156_000001042082_00345_39477_2853.N1	SS1	V/V	82	39477	345	4.07
ASA_WSM_1PNPDK20090917_230355_000002502082_00345_39477_2855.N1	SS1	H/H	82	39477	345	4.07
ASA_WSM_1PNPDE20090917_231201_000003122082_00345_39477_8725.N1	SS1	H/H	82	39477	345	4.07
ASA_WSM_1PNPDE20090917_235620_000001902082_00345_39477_8864.N1	SS1	H/H	82	39477	345	4.07
ASA_WSM_1PNPDE20090917_235620_000005502082_00345_39477_9119.N1	SS1	H/H	82	39477	345	4.07

Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WVS_1PNPDE20090916_235307_000009892082_00331_39463_7207.N1						IS2	V/V	82	39463	331	4.07
ASA_WVS_1PNPDE20090917_001722_000003002082_00331_39463_7200.N1						IS2	V/V	82	39463	331	4.07
ASA_WVS_1PNPDE20090917_004203_000002392082_00331_39463_7195.N1						IS2	V/V	82	39463	331	4.07
ASA_WVS_1PNPDE20090917_004503_000004642082_00331_39463_7285.N1						IS2	V/V	82	39463	331	4.07
ASA_WVS_1PNPDE20090917_004203_000002392082_00331_39463_7195.N1						IS1	V/V	82	39463	331	4.07
ASA_WVS_1PNPDE20090917_005654_000009442082_00331_39463_7290.N1						IS2	V/V	82	39463	331	4.07
ASA_WVS_1PNPDE20090917_014210_000003142082_00332_39464_7293.N1						IS2	V/V	82	39464	332	4.07
ASA_WVS_1PNPDE20090917_014854_000002542082_00332_39464_7311.N1						IS2	V/V	82	39464	332	4.07
ASA_WVS_1PNPDE20090917_015600_000004052082_00332_39464_7328.N1						IS2	V/V	82	39464	332	4.07
ASA_WVS_1PNPDE20090917_022238_000000302082_00332_39464_7316.N1						IS2	V/V	82	39464	332	4.07
ASA_WVS_1PNPDE20090917_022238_000002402082_00332_39464_7432.N1						IS2	V/V	82	39464	332	4.07
ASA_WVS_1PNPDE20090917_032429_000008242082_00333_39465_7448.N1						IS2	V/V	82	39465	333	4.07
ASA_WVS_1PNPDE20090917_033758_000002252082_00333_39465_7559.N1						IS2	V/V	82	39465	333	4.07
ASA_WVS_1PNPDE20090917_040531_000009892082_00333_39465_7590.N1						IS2	V/V	82	39465	333	4.07
ASA_WVS_1PNPDE20090917_050457_000009142082_00334_39466_7600.N1						IS2	V/V	82	39466	334	4.07
ASA_WVS_1PNPDE20090917_051957_000002402082_00334_39466_7771.N1						IS2	V/V	82	39466	334	4.07
ASA_WVS_1PNPDE20090917_054350_000014992082_00334_39466_7819.N1						IS2	V/V	82	39466	334	4.07
ASA_WVS_1PNPDE20090917_065021_000001042082_00335_39467_7809.N1						IS2	V/V	82	39467	335	4.07
ASA_WVS_1PNPDE20090917_065459_000003292082_00335_39467_7806.N1						IS2	V/V	82	39467	335	4.07
ASA_WVS_1PNPDK20090917_070014_000002702082_00335_39467_1723.N1						IS2	V/V	82	39467	335	4.07
ASA_WVS_1PNPDK20090917_072426_000018142082_00335_39467_1762.N1						IS2	V/V	82	39467	335	4.07
ASA_WVS_1PNPDK20090917_083725_000004652082_00336_39468_1805.N1						IS2	V/V	82	39468	336	4.07
ASA_WVS_1PNPDK20090917_090502_000019342082_00336_39468_1874.N1						IS2	V/V	82	39468	336	4.07
ASA_WVS_1PNPDK20090917_101006_000009442082_00337_39469_1941.N1						IS2	V/V	82	39469	337	4.07
ASA_WVS_1PNPDK20090917_104538_000001952082_00337_39469_1944.N1						IS2	V/V	82	39469	337	4.07
ASA_WVS_1PNPDK20090917_105114_000014092082_00337_39469_1960.N1						IS2	V/V	82	39469	337	4.07
ASA_WVS_1PNPDK20090917_113443_000010192082_00338_39470_2071.N1						IS2	V/V	82	39470	338	4.07
ASA_WVS_1PNPDK20090917_115549_000006442082_00338_39470_2080.N1						IS2	V/V	82	39470	338	4.07
ASA_WVS_1PNPDK20090917_122614_000002852082_00338_39470_2083.N1						IS2	V/V	82	39470	338	4.07
ASA_WVS_1PNPDK20090917_123742_000009242082_00338_39470_2095.N1						IS2	V/V	82	39470	338	4.07
ASA_WVS_1PNPDK20090917_131525_000008692082_00339_39471_2203.N1						IS2	V/V	82	39471	339	4.07
ASA_WVS_1PNPDK20090917_140650_000003302082_00339_39471_2206.N1						IS2	V/V	82	39471	339	4.07
ASA_WVS_1PNPDK20090917_141733_000002092082_00339_39471_2213.N1						IS2	V/V	82	39471	339	4.07
ASA_WVS_1PNPDK20090917_142224_000003142082_00339_39471_2220.N1						IS2	V/V	82	39471	339	4.07
ASA_WVS_1PNPDK20090917_151010_000010492082_00340_39472_2310.N1						IS2	V/V	82	39472	340	4.07
ASA_WVS_1PNPDK20090917_154726_000012442082_00340_39472_2334.N1						IS2	V/V	82	39472	340	4.07
ASA_WVS_1PNPDK20090917_164833_000011842082_00341_39473_2471.N1						IS2	V/V	82	39473	341	4.07
ASA_WVS_1PNPDK20090917_172802_000012892082_00341_39473_2482.N1						IS2	V/V	82	39473	341	4.07
ASA_WVS_1PNPDK20090917_182354_000014992082_00342_39474_2688.N1						IS2	V/V	82	39474	342	4.07
ASA_WVS_1PNPDK20090917_190838_000008692082_00342_39474_2706.N1						IS2	V/V	82	39474	342	4.07
ASA_WVS_1PNPDE20090917_195759_000006142082_00343_39475_8281.N1						IS2	V/V	82	39475	343	4.07
ASA_WVS_1PNPDE20090917_201004_000011692082_00343_39475_8297.N1						IS2	V/V	82	39475	343	4.07
ASA_WVS_1PNPDE20090917_204914_000001502082_00343_39475_8418.N1						IS2	V/V	82	39475	343	4.07
ASA_WVS_1PNPDE20090917_214038_000017692082_00344_39476_8425.N1						IS2	V/V	82	39476	344	4.07
ASA_WVS_1PNPDE20090917_222950_000002852082_00344_39476_8430.N1						IS2	V/V	82	39476	344	4.07
ASA_WVS_1PNPDE20090917_223350_000007042082_00344_39476_8566.N1						IS2	V/V	82	39476	344	4.07
ASA_WVS_1PNPDE20090917_223350_000007042082_00344_39476_9170.N1						IS2	V/V	82	39476	344	4.07
ASA_WVS_1PNPDE20090917_225459_000001642082_00345_39477_9161.N1						IS2	V/V	82	39477	345	4.07
ASA_WVS_1PNPDE20090917_225459_000001642082_00345_39477_8573.N1						IS2	V/V	82	39477	345	4.07
ASA_WVS_1PNPDE20090917_231907_000012742082_00345_39477_8582.N1						IS2	V/V	82	39477	345	4.07
ASA_WVS_1PNPDE20090917_234653_000002252082_00345_39477_8587.N1						IS2	V/V	82	39477	345	4.07
















































































17-Sep




17-Sep




17-Sep




17-Sep




17-Sep




17-Sep











17-Sep



17-Sep



17-Sep



