



Analysis from 31-OCT-2009 00:00:00 to 31-OCT-2009 23:59:59. Page generated on 06-NOV-2009 14:28:16.
View log file: ASAR_Daily_Report_20091106_1418.log. For any anomalies please contact emma.griffiths@vega.co.uk.

This report is automatically generated every day, every 2 hours. No comments are provided on the results.

SUMMARY

1. DATA SUMMARY
 - 1.1 Summary tables
 - 1.2 Lists of products used
2. AUXILIARY FILES ANALYSIS
 - 2.1 IECF operational ADFs list
 - 2.2 Products with wrong ADFs
3. MODULE STEPPING PRODUCTS ANALYSIS
 - 3.1 V/V polarisation
 - 3.2 H/H polarisation
4. CALIBRATION PULSES ANALYSIS
 - 4.1 Analysis for WVS IS2 V/V
 - 4.1.1 Temporal Evolution Analysis for WVS IS2 V/V
 - 4.1.2 All Rows Analysis for WVS IS2 V/V
 - 4.2 Analysis for GM1 SS3 H/H
 - 4.2.1 Temporal Evolution Analysis for GM1 SS3 H/H
 - 4.2.2 All Rows Analysis for GM1 SS3 H/H
5. DOPPLER ANALYSIS
 - 5.1 Analysis for WVS IS2 V/V
 - 5.1.1 Doppler MAP Analysis for WVS IS2 V/V
 - 5.1.2 Doppler ANX Analysis for WVS IS2 V/V
 - 5.2 Analysis for GM1 SS1 H/H
 - 5.2.1 Doppler MAP Analysis for GM1 SS1 H/H
 - 5.2.2 Doppler ANX Analysis for GM1 SS1 H/H
 - 5.3 Doppler JUMPS Analysis for WSM
6. CHIRP ANALYSIS
 - 6.1 Analysis for WSM SS1 H/H
 - 6.1.1 ScaleFactor
 - 6.2 Analysis for WSM SS1 V/V
 - 6.2.1 ScaleFactor
7. RAW DATA ANALYSIS
 - 7.1 Analysis for WVS
 - 7.2 Analysis for IMM
8. TELEMETRY ANALYSIS
 - 8.1 Number of Missing Lines
 - 8.2 Number of Gaps

1 - DATA SUMMARY

1.1 - Summary tables

[[BACK TO MENU](#)]

WVS				GM1				APM				IMM				WSM				MS			
Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Time	Pol	Modules
PDE	IS1	V/V	2	PDE	WS	H/H	44	PDE	IS1	H/H	2	PDE	IS1	H/H	1	PDE	WS	H/H	29	PDE	2009-10-31 20:48:52	V	320
PDE	IS2	V/V	26	PDK	WS	H/H	52	PDE	IS2	V/H	1	PDE	IS1	V/V	2	PDE	WS	V/V	14				
PDK	IS2	V/V	20					PDE	IS6	H/H	1	PDE	IS2	H/H	28	PDK	WS	H/H	10				
												PDE	IS2	V/V	11	PDK	WS	V/V	3				
												PDE	IS3	H/H	1								
												PDE	IS6	V/V	1								
												PDE	IS7	***	1								
												PDE	IS7	H/H	1								
												PDE	IS7	V/V	1								
												PDK	IS2	H/H	4								
												PDK	IS2	V/V	5								
												PDK	IS7	V/V	1								

1.2 - Lists of products used

[[BACK TO MENU](#)]

[TXT] [XLS] [List_WVS_products_used](#)
 [TXT] [XLS] [List_GM1_products_used](#)
 [TXT] [XLS] [List_APM_products_used](#)
 [TXT] [XLS] [List_IMM_products_used](#)
 [TXT] [XLS] [List_WSM_products_used](#)
 [TXT] [XLS] [List_MS_products_used](#)

2 - AUXILIARY FILES ANALYSIS

2.1 - IECF operational ADFs list

[[BACK TO MENU](#)]

ADFs disseminated for ASAR
ASA_CON_AXVIEC20081215_141339_20070204_165113_20091231_000000
ASA_INS_AXVIEC20090525_114808_20090428_100000_20091231_235959
ASA_XCH_AXVIEC20081215_143642_20020301_000000_20091231_000000
ASA_XCA_AXVIEC20090311_104501_20080801_000000_20091231_235959

2.2 - Products with wrong ADFs

[[BACK TO MENU](#)]

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
WVS	0	0	0	0
GM1	0	0	0	0
APM	0	0	0	0
IMM	0	0	0	0

WSM	0	0	0	0
-----	---	---	---	---

- [TXT] [XLS] Check_ADFs_WVS
- [TXT] [XLS] Check_ADFs_GM1
- [TXT] [XLS] Check_ADFs_APM
- [TXT] [XLS] Check_ADFs_IMM
- [TXT] [XLS] Check_ADFs_WSM

3 - MODULE STEPPING PRODUCTS ANALYSIS









3.2 - H/H polarisation

[[BACK TO MENU](#)]

SECOND FIXED REFERENCE	PREVIOUS PRODUCT REFERENCE
After antenna maintenance (2005-09-22/23)	Previous product in the same polarisation



4 - CALIBRATION PULSES ANALYSIS

4.1 - Analysis for WVS IS2 V/V


4.1.1 - Temporal Evolution Analysis for WVS IS2 V/V

[BACK TO MENU]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Calibration pulses for WVS IS2 V/V




Transmit power (P1 - P1a) for WVS IS2 V/V



4.1.2 - All Rows Analysis for WVS IS2 V/V

[[BACK TO MENU](#)]





4.2 - Analysis for GM1 SS3 H/H





4.2.1 - Temporal Evolution Analysis for GM1 SS3 H/H

[BACK TO MENU]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Calibration pulses for GM1 SS3 H/H




rows: _ 1 _ 5 _ 9 _ 13 _ 17 _ 21 _ 25 _ 29

Transmit power (P1 - P1a) for GM1 SS3 H/H




Transmit power (P1 - P1a) for GM1 SS3 H/H




rows: _ 1 _ 5 _ 9 _ 13 _ 17 _ 21 _ 25 _ 29

4.2.2 - All Rows Analysis for GM1 SS3 H/H

[[BACK TO MENU](#)]






5 - DOPPLER ANALYSIS

5.1 - Analysis for WVS IS2 V/V

5.1.1 - Doppler MAP Analysis for WVS IS2 V/V

[[BACK TO MENU](#)]






5.1.2 - Doppler ANX Analysis for WVS IS2 V/V

[[BACK TO MENU](#)]






5.2 - Analysis for GM1 SS1 H/H

5.2.1 - Doppler MAP Analysis for GM1 SS1 H/H

[[BACK TO MENU](#)]






5.2.2 - Doppler ANX Analysis for GM1 SS1 H/H

[[BACK TO MENU](#)]






5.3 - Doppler JUMPS Analysis for WSM

[[BACK TO MENU](#)]







6 - CHIRP ANALYSIS

6.1 - Analysis for WSM SS1 H/H

6.1.1 - ScaleFactor

[[BACK TO MENU](#)]







6.2 - Analysis for WSM SS1 V/V

6.2.1 - ScaleFactor

[[BACK TO MENU](#)]






7 - RAW DATA ANALYSIS

7.1 - Analysis for WVS

[[BACK TO MENU](#)]

--	--	--






Channel	Statistics	DSS-B
MEAN I	mean	0.000489276
	stdev	2.32879e-07
MEAN Q	mean	0.000496430
	stdev	2.51553e-07
Channel	Statistics	DSS-B
STDEV I	mean	0.127791
	stdev	0.00114671
STDEV Q	mean	0.128107
	stdev	0.00115950

7.2 - Analysis for IMM

[[BACK TO MENU](#)]







Channel	Statistics	DSS-B
MEAN I	mean	0.000292645
	stdev	7.35283e-09
MEAN Q	mean	0.000540064
	stdev	7.07448e-09
Channel	Statistics	DSS-B
STDEV I	mean	0.0776344
	stdev	0.00122597
STDEV Q	mean	0.0779321
	stdev	0.00123640

8 - TELEMETRY ANALYSIS

8.1 - Number of Missing lines


[[BACK TO MENU](#)]





8.2 - Number of Gaps

[[BACK TO MENU](#)]



ASAR DAILY REPORT for 091031
#####

MODE: DAILY
ANALYSIS: ALL
DATE: 2009-10-31

Analysis will be performed from 2009-10-31 00:00:00 to 2009-10-31 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/091031/

DATA SUMMARY

Summary will be performed from 2009-10-31 00:00:00 to 2009-10-31 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/091031/DATA_SUMMARY

Creating directory ./RESULTS/DAILY/091031/DATA_SUMMARY...
Writing file ./RESULTS/DAILY/091031/DATA_SUMMARY/Data_summary.html...

Getting WVS products list from 2009-10-31 00:00:00 to 2009-10-31 23:59:59...
Writing file ./RESULTS/DAILY/091031/DATA_SUMMARY/List_WVS_products_used.xls...
Writing file ./RESULTS/DAILY/091031/DATA_SUMMARY/List_WVS_products_used.txt...

Getting GM1 products list from 2009-10-31 00:00:00 to 2009-10-31 23:59:59...
Writing file ./RESULTS/DAILY/091031/DATA_SUMMARY/List_GM1_products_used.xls...
Writing file ./RESULTS/DAILY/091031/DATA_SUMMARY/List_GM1_products_used.txt...

Getting APM products list from 2009-10-31 00:00:00 to 2009-10-31 23:59:59...
Writing file ./RESULTS/DAILY/091031/DATA_SUMMARY/List_APM_products_used.xls...
Writing file ./RESULTS/DAILY/091031/DATA_SUMMARY/List_APM_products_used.txt...

Getting IMM products list from 2009-10-31 00:00:00 to 2009-10-31 23:59:59...
Writing file ./RESULTS/DAILY/091031/DATA_SUMMARY/List_IMM_products_used.xls...
Writing file ./RESULTS/DAILY/091031/DATA_SUMMARY/List_IMM_products_used.txt...

Getting WSM products list from 2009-10-31 00:00:00 to 2009-10-31 23:59:59...
Writing file ./RESULTS/DAILY/091031/DATA_SUMMARY/List_WSM_products_used.xls...
Writing file ./RESULTS/DAILY/091031/DATA_SUMMARY/List_WSM_products_used.txt...

Getting MS products list from 2009-10-31 00:00:00 to 2009-10-31 23:59:59...
Writing file ./RESULTS/DAILY/091031/DATA_SUMMARY/List_MS_products_used.xls...
Writing file ./RESULTS/DAILY/091031/DATA_SUMMARY/List_MS_products_used.txt...

DATA SUMMARY completed
#####

AUXILIARY FILES ANALYSIS

Analysis will be performed from 2009-10-31 00:00:00 to 2009-10-31 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/091031/AUXILIARY

Creating directory ./RESULTS/DAILY/091031/AUXILIARY...

Looking for the IECF operational ADFs list...



ADF filter 20091031*current_3_IECF_ADFs.txt
 Found list 20091031_030003_current_3_IECF_ADFs.txt...
 Extracting ADFs...

ASA_CON_AXVIEC20081215_141339_20070204_165113_20091231_000000
 ASA_INS_AXVIEC20090525_114808_20090428_100000_20091231_235959
 ASA_XCH_AXVIEC20081215_143642_20020301_000000_20091231_000000
 ASA_XCA_AXVIEC20090311_104501_20080801_000000_20091231_235959

Writing file ./RESULTS/DAILY/091031/AUXILIARY/ASAR_ADFs_IECF_List3.html...
 Writing file ./RESULTS/DAILY/091031/AUXILIARY/Auxiliary_files_summary.html...

Analysing WVS products...

Writing file ./RESULTS/DAILY/091031/AUXILIARY/Check_ADFs_WVS.xls...
 Writing file ./RESULTS/DAILY/091031/AUXILIARY/Check_ADFs_WVS.txt...

ASA_WVS_1PNPDE20091031_000942_000001202083_00460_40093_4238.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091031_001307_000006742083_00460_40093_4244.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091031_002607_000000742083_00460_40093_4247.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091031_003356_000003302083_00460_40093_4254.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091031_005907_000002252083_00460_40093_4266.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091031_010152_000003002083_00460_40093_4328.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091031_011437_000008242083_00460_40093_4333.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091031_015414_000000592083_00461_40094_4340.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091031_020107_000010642083_00461_40094_4345.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091031_023952_000002252083_00461_40094_4529.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091031_034129_000008992083_00462_40095_4542.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091031_035558_000001352083_00462_40095_4466.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091031_042051_000011092083_00462_40095_4477.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091031_052051_000009742083_00463_40096_4480.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091031_053635_000002852083_00463_40096_4577.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091031_060104_000017992083_00463_40096_4613.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091031_201456_000006142083_00472_40105_4851.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091031_202647_000011992083_00472_40105_4862.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091031_210627_000001502083_00472_40105_4908.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091031_213634_000001652083_00473_40106_4922.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091031_215424_000001352083_00473_40106_4919.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091031_215807_000017542083_00473_40106_4929.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091031_224730_000001802083_00473_40106_4934.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091031_224945_000008392083_00473_40106_4988.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091031_231111_000004942083_00474_40107_4993.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20091031_233838_000010342083_00474_40107_5000.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091031_071918_000001502083_00464_40097_7608.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091031_074140_000017992083_00464_40097_7615.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091031_085053_000006892083_00465_40098_7647.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091031_092215_000019192083_00465_40098_7658.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091031_102700_000009592083_00466_40099_7698.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091031_110251_000002552083_00466_40099_7701.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091031_110851_000015292083_00466_40099_7710.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091031_115039_000011242083_00467_40100_7730.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091031_121705_000003902083_00467_40100_7741.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091031_124327_000001952083_00467_40100_7744.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091031_125559_000008202083_00467_40100_7751.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091031_133240_000005692083_00468_40101_7793.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091031_142403_000003002083_00468_40101_7807.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091031_143351_000006592083_00468_40101_7796.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091031_152720_000010492083_00469_40102_7833.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091031_160439_000011842083_00469_40102_7844.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091031_170456_000012292083_00470_40103_7875.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091031_174515_000012142083_00470_40103_7884.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091031_183835_000016492083_00471_40104_7908.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20091031_192551_000006302083_00471_40104_7913.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

Analysing GM1 products...

Writing file ./RESULTS/DAILY/091031/AUXILIARY/Check_ADFs_GM1.xls...

Writing file ./RESULTS/DAILY/091031/AUXILIARY/Check_ADFs_GM1.txt...

ASA_GM1_1PNPDE20091031_002809_000003442083_00460_40093_4256.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091031_004013_000000842083_00460_40093_4251.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091031_005208_000003142083_00460_40093_4270.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091031_010911_000003202083_00460_40093_4347.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091031_012911_000001202083_00461_40094_4330.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091031_013743_000009912083_00461_40094_4349.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091031_015654_00000902083_00461_40094_4342.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091031_022406_000006462083_00461_40094_4544.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091031_023704_000001632083_00461_40094_4407.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091031_024414_000005072083_00461_40094_4524.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091031_025406_000002472083_00461_40094_4526.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091031_030646_000012982083_00462_40095_4539.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091031_033201_000001382083_00462_40095_4409.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091031_033524_000003622083_00462_40095_4417.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091031_041255_000001322083_00462_40095_4463.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091031_041645_000002412083_00462_40095_4468.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091031_044005_000006822083_00463_40096_4470.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091031_045245_000008512083_00463_40096_4472.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091031_051237_000001872083_00463_40096_4474.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091031_051703_000002232083_00463_40096_4482.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091031_054201_000001262083_00463_40096_4568.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091031_055351_000004282083_00463_40096_4579.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091031_063141_000008332083_00464_40097_4589.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091031_065108_000000842083_00464_40097_4591.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091031_065558_000001502083_00464_40097_4593.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091031_065915_000004412083_00464_40097_4595.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091031_070724_000005012083_00464_40097_4597.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091031_200614_000003082083_00472_40105_4848.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091031_201216_000001572083_00472_40105_4855.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091031_204724_000000842083_00472_40105_4853.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091031_205404_000001322083_00472_40105_4857.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091031_210306_000000902083_00472_40105_4859.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091031_210333_000001752083_00472_40105_4905.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091031_211422_000010742083_00472_40105_4936.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091031_213407_000001442083_00473_40106_4910.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091031_214003_000001632083_00473_40106_4916.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091031_214618_000004832083_00473_40106_4924.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091031_222800_000001752083_00473_40106_4926.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091031_224304_000001142083_00473_40106_4931.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091031_230424_000000842083_00474_40107_4985.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091031_230730_000000962083_00474_40107_4995.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091031_232355_000008822083_00474_40107_4997.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20091031_235641_000004042083_00474_40107_5010.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_072557_000002472083_00464_40097_7610.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_073656_000002832083_00464_40097_7612.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_081330_000006642083_00465_40098_7617.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_082328_000007912083_00465_40098_7640.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_084343_000004282083_00465_40098_7642.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_090313_000001932083_00465_40098_7644.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_090807_000008452083_00465_40098_7649.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_095504_000004102083_00466_40099_7651.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_100151_000001262083_00466_40099_7660.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_101803_000001322083_00466_40099_7691.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_102401_000001752083_00466_40099_7693.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_104349_000001632083_00466_40099_7695.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_105626_000003802083_00466_40099_7703.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_113500_000002592083_00467_40100_7705.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_114047_000002232083_00467_40100_7707.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_114318_000001142083_00467_40100_7727.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_121006_000000902083_00467_40100_7732.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_122424_000001382083_00467_40100_7734.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

ASA_GM1_1PNPDK20091031_122826_000003202083_00467_40100_7736.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_123715_000003682083_00467_40100_7738.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_124927_000003922083_00467_40100_7746.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_131016_000008512083_00468_40101_7748.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_132625_000003742083_00468_40101_7780.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_134613_000002952083_00468_40101_7782.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_135238_000003682083_00468_40101_7784.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_135853_000002952083_00468_40101_7786.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_140500_000002292083_00468_40101_7788.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_141031_000008092083_00468_40101_7790.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_142947_000002412083_00468_40101_7804.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_144534_000008842083_00469_40102_7800.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_144932_000005252083_00469_40102_7802.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_150247_000008842083_00469_40102_7798.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_150256_000003742083_00469_40102_7826.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_151141_00000902083_00469_40102_7824.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_151413_000001382083_00469_40102_7828.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_151812_000008842083_00469_40102_7830.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_154536_000011422083_00469_40102_7846.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_162508_000001082083_00470_40103_7835.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_163331_000002112083_00470_40103_7837.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_164143_000003742083_00470_40103_7866.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_164900_000009302083_00470_40103_7870.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_172612_000001142083_00470_40103_7868.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_172947_00000782083_00470_40103_7872.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_173835_000003982083_00470_40103_7877.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_180616_000003382083_00471_40104_7879.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_181432_000003202083_00471_40104_7881.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_181839_000002112083_00471_40104_7901.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_182633_000001202083_00471_40104_7899.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_183311_000003202083_00471_40104_7903.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_190648_000002592083_00471_40104_7905.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_192256_000001752083_00471_40104_7910.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20091031_193700_000007912083_00471_40104_7915.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

Analysing APM products...

Writing file ./RESULTS/DAILY/091031/AUXILIARY/Check_ADFs_APM.xls...

Writing file ./RESULTS/DAILY/091031/AUXILIARY/Check_ADFs_APM.txt...

ASA_APM_1PNPDE20091031_015551_00000432083_00461_40094_4368.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20091031_015823_00000632083_00461_40094_4386.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20091031_033421_00000432083_00462_40095_4426.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20091031_151310_00000432083_00469_40102_4760.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

Analysing IMM products...

Writing file ./RESULTS/DAILY/091031/AUXILIARY/Check_ADFs_IMM.xls...

Writing file ./RESULTS/DAILY/091031/AUXILIARY/Check_ADFs_IMM.txt...

ASA_IMM_1PNPDE20091031_001223_00000372083_00460_40093_4278.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091031_002506_00000532083_00460_40093_4280.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091031_004344_000001232083_00460_40093_4353.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091031_004344_000004932083_00460_40093_4428.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091031_004747_000001802083_00460_40093_4354.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091031_023450_000001232083_00461_40094_4430.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091031_040511_000001622083_00462_40095_4459.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091031_040841_000002432083_00462_40095_4602.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091031_040945_000001792083_00462_40095_4585.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091031_045127_00000632083_00463_40096_4496.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091031_051545_00000672083_00463_40096_4548.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091031_054618_00000922083_00463_40096_4546.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

ASA_IMM_1PNPDE20091031_054838_000003022083_00463_40096_4620.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091031_065827_000000372083_00464_40097_4554.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091031_070635_000000372083_00464_40097_4581.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091031_083637_000000372083_00465_40098_4624.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091031_083747_000000372083_00465_40098_4626.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091031_101332_000001272083_00466_40099_4674.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091031_101715_000000372083_00466_40099_4664.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091031_104633_000003722083_00466_40099_4700.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091031_105218_000002372083_00466_40099_4734.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091031_110751_000000532083_00466_40099_4732.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091031_122643_000000912083_00467_40100_4736.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091031_135109_000000772083_00468_40101_4784.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091031_135212_000000142083_00468_40101_4744.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091031_140848_000000912083_00468_40101_4770.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091031_140951_000000282083_00468_40101_4748.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091031_144659_000001422083_00469_40102_4764.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091031_150917_000000422083_00469_40102_4766.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091031_164757_000000522083_00470_40103_4790.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091031_173102_000003012083_00470_40103_4818.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091031_173652_000000912083_00470_40103_4796.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091031_191108_000003012083_00471_40104_4846.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091031_191658_000003482083_00471_40104_4844.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091031_201117_000000482083_00472_40105_4864.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091031_202555_000000462083_00472_40105_4866.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091031_205110_000001602083_00472_40105_4901.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091031_205612_000002432083_00472_40105_4903.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091031_205612_000004022083_00472_40105_4981.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091031_210116_000000602083_00472_40105_4887.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091031_213319_000000372083_00473_40106_4950.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091031_215723_000000372083_00473_40106_4952.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091031_223053_000002302083_00473_40106_5016.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091031_223157_000001192083_00473_40106_4990.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091031_223533_000004412083_00473_40106_5063.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091031_223736_000000602083_00473_40106_4969.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20091031_230547_000000912083_00474_40107_5049.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20091031_064955_000000622083_00464_40097_7605.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20091031_073003_000004022083_00464_40097_7638.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20091031_081214_000000632083_00465_40098_7619.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20091031_101318_000000632083_00466_40099_7662.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20091031_123347_000001982083_00467_40100_7776.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20091031_124717_000000682083_00467_40100_7771.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20091031_124839_000000352083_00467_40100_7761.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20091031_150907_000000372083_00469_40102_7809.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20091031_214247_000002012083_00473_40106_7956.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20091031_232212_000000922083_00474_40107_7966.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

Analysing WSM products...

Writing file ./RESULTS/DAILY/091031/AUXILIARY/Check_ADFs_WSM.xls...
Writing file ./RESULTS/DAILY/091031/AUXILIARY/Check_ADFs_WSM.txt...

ASA_WSM_1PNPDE20091031_004143_000000922083_00460_40093_4323.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091031_005726_000000922083_00460_40093_4301.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091031_013114_000001352083_00461_40094_4457.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091031_013114_000003732083_00461_40094_4640.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091031_013424_000000612083_00461_40094_4378.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091031_013626_000000612083_00461_40094_4382.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091031_015937_000000732083_00461_40094_4370.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091031_021940_000002452083_00461_40094_4384.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091031_030310_000002082083_00462_40095_4461.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091031_032826_000001902083_00462_40095_4446.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091031_032826_000002142083_00462_40095_4550.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091031_040158_000000732083_00462_40095_4440.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091031_040158_000001532083_00462_40095_4566.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091031_040413_000000182083_00462_40095_4444.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK



ASA_WSM_1PNPDE20091031_041510_000000922083_00462_40095_4587.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091031_041624_000000182083_00462_40095_4512.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091031_050702_000003302083_00463_40096_4552.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091031_054411_000000922083_00463_40096_4615.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091031_054525_000000182083_00463_40096_4500.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091031_065239_000000732083_00464_40097_4570.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091031_065239_000001902083_00464_40097_4656.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091031_065454_000000552083_00464_40097_4574.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091031_071548_000002142083_00464_40097_4622.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091031_072322_000001532083_00464_40097_4642.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091031_084120_000001342083_00465_40098_4672.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091031_084233_000000612083_00465_40098_4630.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091031_100915_000000912083_00466_40099_4676.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091031_101547_000000912083_00466_40099_4696.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091031_101700_000000182083_00466_40099_4680.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091031_102022_000002142083_00466_40099_4730.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091031_113921_000000732083_00467_40100_4698.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091031_121142_000000732083_00467_40100_4722.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091031_121142_000002142083_00467_40100_4740.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091031_121357_000000792083_00467_40100_4738.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091031_151008_000000912083_00469_40102_4768.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091031_162700_000003732083_00470_40103_4798.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091031_172813_000000912083_00470_40103_4816.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091031_181158_000001522083_00471_40104_4820.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091031_182837_000002692083_00471_40104_5014.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091031_210946_000000732083_00472_40105_4891.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091031_210946_000002742083_00472_40105_4983.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091031_211255_000000842083_00472_40105_4938.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20091031_224500_000001532083_00473_40106_5065.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20091031_064537_000002142083_00464_40097_7978.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20091031_090632_000000922083_00465_40098_7674.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20091031_100404_000002992083_00466_40099_7687.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20091031_100915_000002452083_00466_40099_7689.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20091031_114515_000002752083_00467_40100_7725.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20091031_132431_000001092083_00468_40101_7778.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20091031_145824_000002502083_00469_40102_7822.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20091031_163704_000002752083_00470_40103_7864.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20091031_182214_000002512083_00471_40104_7897.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20091031_195404_000003732083_00472_40105_7946.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20091031_200028_000001642083_00472_40105_7944.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20091031_200413_000001152083_00472_40105_7942.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20091031_232002_000001222083_00474_40107_7968.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

AUXILIARY FILES ANALYSIS completed
#####

MODULE STEPPING ANALYSIS

Analysis will be performed from 2009-10-31 00:00:00 to 2009-10-31 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/091031/MODULE_STEPPING

Creating directory ./RESULTS/DAILY/091031/MODULE_STEPPING...
Creating directory ./RESULTS/DAILY/091031/MODULE_STEPPING/FIRST_REFERENCE...
Creating directory ./RESULTS/DAILY/091031/MODULE_STEPPING/SECOND_REFERENCE...
Creating directory ./RESULTS/DAILY/091031/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE...
Deleting old files...

Creating images comparing with second reference...

Exporting results to the directory ../../RESULTS/DAILY/091031/MODULE_STEPPING/SECOND_REFERENCE...

Polarization: H



Reference product: ASA_MS__0PNPDK20050922_062651_000000152041_00034_18625_0041.N1
Test product: ASA_MS__0PNPDK20091030_143805_000000162083_00454_40087_0904.N1

H
H

../../RESULTS/DAILY/091031/MODULE_STEPPING/SECOND_REFERENCE/TGH_20091030_143805-20050922_062651.png
../../RESULTS/DAILY/091031/MODULE_STEPPING/SECOND_REFERENCE/TPH_20091030_143805-20050922_062651.png
../../RESULTS/DAILY/091031/MODULE_STEPPING/SECOND_REFERENCE/RGH_20091030_143805-20050922_062651.png
../../RESULTS/DAILY/091031/MODULE_STEPPING/SECOND_REFERENCE/RPH_20091030_143805-20050922_062651.png

Polarization: V
Reference product: ASA_MS__0PNPDK20050923_055514_000000152041_00048_18639_0042.N1
Test product: ASA_MS__0PNPDE20091031_204852_000000162083_00472_40105_0468.N1

V
V

../../RESULTS/DAILY/091031/MODULE_STEPPING/SECOND_REFERENCE/TGV_20091031_204852-20050923_055514.png
../../RESULTS/DAILY/091031/MODULE_STEPPING/SECOND_REFERENCE/TPV_20091031_204852-20050923_055514.png
../../RESULTS/DAILY/091031/MODULE_STEPPING/SECOND_REFERENCE/RGV_20091031_204852-20050923_055514.png
../../RESULTS/DAILY/091031/MODULE_STEPPING/SECOND_REFERENCE/RPV_20091031_204852-20050923_055514.png

Creating images comparing with previous product reference...

Exporting results to the directory ../../RESULTS/DAILY/091031/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE...

Polarization: H
Reference product: ASA_MS__0PNPDK20091028_071819_000000162083_00421_40054_0902.N1
Test product: ASA_MS__0PNPDK20091030_143805_000000162083_00454_40087_0904.N1

H
H

../../RESULTS/DAILY/091031/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TGH_20091030_143805-20091028_071819.png
../../RESULTS/DAILY/091031/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TPH_20091030_143805-20091028_071819.png
../../RESULTS/DAILY/091031/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RGH_20091030_143805-20091028_071819.png
../../RESULTS/DAILY/091031/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RPH_20091030_143805-20091028_071819.png

Polarization: V
Reference product: ASA_MS__0PNPDK20091029_100754_000000162083_00437_40070_0903.N1
Test product: ASA_MS__0PNPDE20091031_204852_000000162083_00472_40105_0468.N1

V
V

../../RESULTS/DAILY/091031/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TGV_20091031_204852-20091029_100754.png
../../RESULTS/DAILY/091031/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TPV_20091031_204852-20091029_100754.png
../../RESULTS/DAILY/091031/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RGV_20091031_204852-20091029_100754.png
../../RESULTS/DAILY/091031/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RPV_20091031_204852-20091029_100754.png

MODULE_STEPPING ANALYSIS completed
#####

CALIBRATION PULSES ANALYSIS

Creating directory ./RESULTS/DAILY/091031/CALIBRATION_PULSES...

ALL ROWS Analysis will be performed from 2009-10-31 00:00:00 to 2009-10-31 23:59:59

Analysing products WVS IS2 V/V
Writing image ../../RESULTS/DAILY/091031//CALIBRATION_PULSES/Calibration_pulses_all_rows_WVS_IS2_VV.png...
Analysing products GM1 SS3 H/H
Writing image ../../RESULTS/DAILY/091031//CALIBRATION_PULSES/Calibration_pulses_all_rows_GM1_SS3_HH.png...



TEMPORAL EVOLUTION Analysis will be performed from 2009-10-31 00:00:00 to 2009-10-31 23:59:59

Analysing products WVS IS2 V/V

Getting calibration pulses data for WVS IS2 V/V from 2009-10-31 00:00:00 to 2009-10-31 23:59:59. Rows: 1/5/9/13/17/21/25/29
Writing file ./RESULTS/DAILY/091031/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2009-10-31_1.dat...
Writing ../../RESULTS/DAILY/091031//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_1.png...
Writing ../../RESULTS/DAILY/091031//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_1.png...

Getting calibration pulses data for WVS IS2 V/V from 2009-10-31 00:00:00 to 2009-10-31 23:59:59. Rows: 2/6/10/14/18/22/26/30
Writing file ./RESULTS/DAILY/091031/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2009-10-31_2.dat...
Writing ../../RESULTS/DAILY/091031//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_2.png...
Writing ../../RESULTS/DAILY/091031//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_2.png...

Getting calibration pulses data for WVS IS2 V/V from 2009-10-31 00:00:00 to 2009-10-31 23:59:59. Rows: 3/7/11/15/19/23/27/31
Writing file ./RESULTS/DAILY/091031/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2009-10-31_3.dat...
Writing ../../RESULTS/DAILY/091031//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_3.png...
Writing ../../RESULTS/DAILY/091031//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_3.png...

Getting calibration pulses data for WVS IS2 V/V from 2009-10-31 00:00:00 to 2009-10-31 23:59:59. Rows: 4/8/12/16/20/24/28/32
Writing file ./RESULTS/DAILY/091031/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2009-10-31_4.dat...
Writing ../../RESULTS/DAILY/091031//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_4.png...
Writing ../../RESULTS/DAILY/091031//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_4.png...

Analysing products GM1 SS3 H/H

Getting calibration pulses data for GM1 SS3 H/H from 2009-10-31 00:00:00 to 2009-10-31 23:59:59. Rows: 1/5/9/13/17/21/25/29
Writing file ./RESULTS/DAILY/091031/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2009-10-31_1.dat...
Writing ../../RESULTS/DAILY/091031//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_1.png...
Writing ../../RESULTS/DAILY/091031//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_1.png...

Getting calibration pulses data for GM1 SS3 H/H from 2009-10-31 00:00:00 to 2009-10-31 23:59:59. Rows: 2/6/10/14/18/22/26/30
Writing file ./RESULTS/DAILY/091031/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2009-10-31_2.dat...
Writing ../../RESULTS/DAILY/091031//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_2.png...
Writing ../../RESULTS/DAILY/091031//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_2.png...

Getting calibration pulses data for GM1 SS3 H/H from 2009-10-31 00:00:00 to 2009-10-31 23:59:59. Rows: 3/7/11/15/19/23/27/31
Writing file ./RESULTS/DAILY/091031/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2009-10-31_3.dat...
Writing ../../RESULTS/DAILY/091031//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_3.png...
Writing ../../RESULTS/DAILY/091031//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_3.png...

Getting calibration pulses data for GM1 SS3 H/H from 2009-10-31 00:00:00 to 2009-10-31 23:59:59. Rows: 4/8/12/16/20/24/28/32
Writing file ./RESULTS/DAILY/091031/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2009-10-31_4.dat...
Writing ../../RESULTS/DAILY/091031//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_4.png...
Writing ../../RESULTS/DAILY/091031//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_4.png...

CALIBRATION PULSES ANALYSIS completed
#####

DOPPLER ANALYSIS
#####
Creating directory ./RESULTS/DAILY/091031/DOPPLER...

DOPPLER ANX Analysis will be performed from 2009-10-31 00:00:00 to 2009-10-31 23:59:59

Analysing products WVS IS2 V/V
Getting doppler data for WVS IS2 V/V from 2009-10-31 00:00:00 to 2009-10-31 23:59:59...
Writing file ./RESULTS/DAILY/091031/DOPPLER/Doppler_data_WVS_IS2_VV_2009-10-31.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/091031/DOPPLER/DOPPLER_ANX_WVS_IS2_VV.png...

Analysing products GM1 SS1 H/H
Getting doppler data for GM1 SS1 H/H from 2009-10-31 00:00:00 to 2009-10-31 23:59:59...
Writing file ./RESULTS/DAILY/091031/DOPPLER/Doppler_data_GM1_SS1_HH_2009-10-31.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/091031/DOPPLER/DOPPLER_ANX_GM1_SS1_HH.png...

DOPPLER JUMPS Analysis will be performed on WSM products from 2009-10-31 00:00:00 to 2009-10-31 23:59:59

Analysing by default products WSM
Getting doppler jumps data for WSM from 2009-10-31 00:00:00 to 2009-10-31 23:59:59...
Writing file ./RESULTS/DAILY/091031/DOPPLER/Doppler_Jumps_data_WSM_2009-10-31.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/091031/DOPPLER/DOPPLER_JUMPS_ANX_WSM.png...
Writing file ../../RESULTS/DAILY/091031/DOPPLER/DOPPLER_JUMPS_Date_WSM.png...

DOPPLER MAP Analysis will be performed from 2009-10-31 00:00:00 to 2009-10-31 23:59:59

Analysing products WVS IS2 V/V
Loading predicted doppler values....
Phase: descending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -37.192138 Hz
Writing file ../../RESULTS/DAILY/091031//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_WVS_IS2_VV_desc.jpg...
Writing file ../../RESULTS/DAILY/091031//DOPPLER/DOPPLER_Absolute_WVS_IS2_VV_desc.jpg...

Loading predicted doppler values....
Phase: ascending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -37.576063 Hz
Writing file ../../RESULTS/DAILY/091031//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_WVS_IS2_VV_asc.jpg...
Writing file ../../RESULTS/DAILY/091031//DOPPLER/DOPPLER_Absolute_WVS_IS2_VV_asc.jpg...

Analysing products GM1 SS1 H/H
Loading predicted doppler values....
Phase: descending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -20.795689 Hz
Writing file ../../RESULTS/DAILY/091031//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_GM1_SS1_HH_desc.jpg...
Writing file ../../RESULTS/DAILY/091031//DOPPLER/DOPPLER_Absolute_GM1_SS1_HH_desc.jpg...

Loading predicted doppler values....
Phase: ascending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -32.701858 Hz
Writing file ../../RESULTS/DAILY/091031//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_GM1_SS1_HH_asc.jpg...
Writing file ../../RESULTS/DAILY/091031//DOPPLER/DOPPLER_Absolute_GM1_SS1_HH_asc.jpg...

DOPPLER ANALYSIS completed

#####

CHIRP ANALYSIS

#####

Creating directory ./RESULTS/DAILY/091031/CHIRP...

CHIRP Analysis will be performed from 2009-10-31 00:00:00 to 2009-10-31 23:59:59

Analysing products WSM SS1 H/H

Getting ScaleFactor data for WSM SS1 H/H from 2009-10-31 00:00:00 to 2009-10-31 23:59:59...

Writing file ./RESULTS/DAILY/091031/CHIRP/ScaleFactor_data_WSM_SS1_HH_2009-10-31.dat...

Running IDL program...

Writing file ../../RESULTS/DAILY/091031/CHIRP/ScaleFactor_ANX_WSM_SS1_HH.png...

Writing file ../../RESULTS/DAILY/091031/CHIRP/ScaleFactor_DATE_WSM_SS1_HH.png...

Analysing products WSM SS1 V/V

Getting ScaleFactor data for WSM SS1 V/V from 2009-10-31 00:00:00 to 2009-10-31 23:59:59...

Writing file ./RESULTS/DAILY/091031/CHIRP/ScaleFactor_data_WSM_SS1_VV_2009-10-31.dat...

Running IDL program...

Writing file ../../RESULTS/DAILY/091031/CHIRP/ScaleFactor_ANX_WSM_SS1_VV.png...

Writing file ../../RESULTS/DAILY/091031/CHIRP/ScaleFactor_DATE_WSM_SS1_VV.png...

CHIRP ANALYSIS completed

#####

RAW DATA ANALYSIS

#####

Analysis will be performed from 2009-10-31 00:00:00 to 2009-10-31 23:59:59

Results will be exported to the directory: ./RESULTS/DAILY/091031/RAW_DATA

Creating directory ./RESULTS/DAILY/091031/RAW_DATA...

Getting raw data for WVS from 2009-10-31 00:00:00 to 2009-10-31 23:59:59...

Writing file ./RESULTS/DAILY/091031/RAW_DATA/Raw_data_WVS_2009-10-31.dat...

Running IDL program to create graphs...

Creating image ../../RESULTS/DAILY/091031/RAW_DATA/Raw_data_WVS_input_mean.png...

Creating image ../../RESULTS/DAILY/091031/RAW_DATA/Raw_data_WVS_input_stdev.png...

Creating image ../../RESULTS/DAILY/091031/RAW_DATA/Raw_data_WVS_gain_imbalance.png...

Getting raw data for IMM from 2009-10-31 00:00:00 to 2009-10-31 23:59:59...

Writing file ./RESULTS/DAILY/091031/RAW_DATA/Raw_data_IMM_2009-10-31.dat...

Running IDL program to create graphs...

Creating image ../../RESULTS/DAILY/091031/RAW_DATA/Raw_data_IMM_input_mean.png...

Creating image ../../RESULTS/DAILY/091031/RAW_DATA/Raw_data_IMM_input_stdev.png...

Creating image ../../RESULTS/DAILY/091031/RAW_DATA/Raw_data_IMM_gain_imbalance.png...

RAW DATA ANALYSIS completed

#####

TELEMETRY ANALYSIS

#####

Analysis will be performed from 2009-10-31 00:00:00 to 2009-10-31 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/091031/TELEMETRY

Creating directory ./RESULTS/DAILY/091031/TELEMETRY...

Looking for gaps and missing lines in WVS products...

Checking 26 products from PDE...

Checking 20 products from PDK...

Looking for gaps and missing lines in GM1 products...

Checking 44 products from PDE...

Checking 52 products from PDK...

Looking for gaps and missing lines in APM products...

Checking 4 products from PDE...

No products from PDK...

Looking for gaps and missing lines in IMM products...

Checking 47 products from PDE...

Checking 10 products from PDK...

Looking for gaps and missing lines in WSM products...

Checking 43 products from PDE...

Checking 13 products from PDK...

Creating graph of missing lines and gaps...

Creating image: ./RESULTS/DAILY/091031/TELEMETRY/TELEMETRY_Missing_lines.png...

Creating image: ./RESULTS/DAILY/091031/TELEMETRY/TELEMETRY_Gaps.png...

TELEMETRY ANALYSIS completed

#####

BROWSE PRODUCTS ANALYSIS

#####

Analysis will be performed on 2009-10-31

Scanning directory /nfs-store/ASAR_Data//ASA_GM_BP...

Results will be exported to the directory: /nfs-store/ASAR_Data//ASA_GM_BP/JPG/20091031/

- Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091031_002809_000003442083_00460_40093_4257.N1 ...
- Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091031_004013_000000842083_00460_40093_4252.N1 ...
- Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091031_005208_000003142083_00460_40093_4271.N1 ...
- Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091031_010911_000003202083_00460_40093_4348.N1 ...
- Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091031_012911_000001202083_00461_40094_4331.N1 ...
- Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091031_013743_000009912083_00461_40094_4350.N1 ...
- Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091031_015654_000000902083_00461_40094_4343.N1 ...
- Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091031_022406_000006462083_00461_40094_4545.N1 ...
- Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091031_023704_000001632083_00461_40094_4408.N1 ...
- Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091031_024414_000005072083_00461_40094_4525.N1 ...
- Stripping browse product /nfs-store/ASAR_Data//ASA_GM_BP/ASA_GM_BPZPDE20091031_025406_000002472083_00461_40094_4527.N1 ...

ANALYSIS COMPLETED: 79 GM browse products to see...

Scanning directory /nfs-store/ASAR_Data//ASA_AP_BP...

Results will be exported to the directory: /nfs-store/ASAR_Data//ASA_AP_BP/JPG/20091031/

Stripping browse product /nfs-store/ASAR_Data//ASA_AP_BP/ASA_AP_BPZPDE20091031_015551_000000432083_00461_40094_4369.N1 ...

Stripping browse product /nfs-store/ASAR_Data//ASA_AP_BP/ASA_AP_BPZPDE20091031_015823_000000632083_00461_40094_4387.N1 ...

Stripping browse product /nfs-store/ASAR_Data//ASA_AP_BP/ASA_AP_BPZPDE20091031_033421_000000432083_00462_40095_4427.N1 ...

ANALYSIS COMPLETED: 3 AP browse products to see...

Scanning directory /nfs-store/ASAR_Data//ASA_IM_BP...

Results will be exported to the directory: /nfs-store/ASAR_Data//ASA_IM_BP/JPG/20091031/

Stripping browse product /nfs-store/ASAR_Data//ASA_IM_BP/ASA_IM_BPZPDK20091031_064955_000000622083_00464_40097_7606.N1 ...

Stripping browse product /nfs-store/ASAR_Data//ASA_IM_BP/ASA_IM_BPZPDK20091031_073003_000004022083_00464_40097_7639.N1 ...

Stripping browse product /nfs-store/ASAR_Data//ASA_IM_BP/ASA_IM_BPZPDK20091031_081214_000000632083_00465_40098_7620.N1 ...

Stripping browse product /nfs-store/ASAR_Data//ASA_IM_BP/ASA_IM_BPZPDK20091031_101318_000000632083_00466_40099_7663.N1 ...

Stripping browse product /nfs-store/ASAR_Data//ASA_IM_BP/ASA_IM_BPZPDK20091031_123347_000001982083_00467_40100_7777.N1 ...

Stripping browse product /nfs-store/ASAR_Data//ASA_IM_BP/ASA_IM_BPZPDK20091031_124717_000000682083_00467_40100_7772.N1 ...

Stripping browse product /nfs-store/ASAR_Data//ASA_IM_BP/ASA_IM_BPZPDK20091031_124839_000000352083_00467_40100_7762.N1 ...

Stripping browse product /nfs-store/ASAR_Data//ASA_IM_BP/ASA_IM_BPZPDK20091031_150907_000000372083_00469_40102_7810.N1 ...

ANALYSIS COMPLETED: 8 IM browse products to see...

Scanning directory /nfs-store/ASAR_Data//ASA_WS_BP...

Results will be exported to the directory: /nfs-store/ASAR_Data//ASA_WS_BP/JPG/20091031/

Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091031_004143_000000922083_00460_40093_4324.N1 ...

Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091031_005726_000000922083_00460_40093_4302.N1 ...

Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091031_013114_000001352083_00461_40094_4458.N1 ...

Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091031_013114_000003732083_00461_40094_4641.N1 ...

Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091031_013424_000000612083_00461_40094_4379.N1 ...

Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091031_013626_000000612083_00461_40094_4383.N1 ...

Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091031_015937_000000732083_00461_40094_4371.N1 ...

Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091031_021940_000002452083_00461_40094_4385.N1 ...

Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091031_030310_000002082083_00462_40095_4462.N1 ...

Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091031_032826_000001902083_00462_40095_4447.N1 ...

Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091031_032826_000002142083_00462_40095_4551.N1 ...

Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091031_040158_000000732083_00462_40095_4441.N1 ...

Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091031_040158_000001532083_00462_40095_4567.N1 ...

Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091031_040413_000000182083_00462_40095_4445.N1 ...

Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091031_041510_000000922083_00462_40095_4588.N1 ...

Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091031_041624_000000182083_00462_40095_4513.N1 ...

Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091031_050702_000003302083_00463_40096_4553.N1 ...

Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091031_054411_000000922083_00463_40096_4616.N1 ...

Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091031_054525_000000182083_00463_40096_4501.N1 ...

Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091031_065239_000000732083_00464_40097_4571.N1 ...

Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091031_065239_000001902083_00464_40097_4657.N1 ...

Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091031_065454_000000552083_00464_40097_4575.N1 ...

Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091031_071548_000002142083_00464_40097_4623.N1 ...

Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091031_072322_000001532083_00464_40097_4643.N1 ...

Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDE20091031_084233_000000612083_00465_40098_4631.N1 ...

Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDK20091031_090632_000000922083_00465_40098_7675.N1 ...

Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDK20091031_100404_000002992083_00466_40099_7688.N1 ...

Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDK20091031_100915_000002452083_00466_40099_7690.N1 ...

Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDK20091031_114515_000002752083_00467_40100_7726.N1 ...

Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDK20091031_132431_000001092083_00468_40101_7779.N1 ...

Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDK20091031_145824_000002502083_00469_40102_7823.N1 ...

Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDK20091031_163704_000002752083_00470_40103_7865.N1 ...

Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDK20091031_182214_000002512083_00471_40104_7898.N1 ...



Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDK20091031_195404_000003732083_00472_40105_7947.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDK20091031_200028_000001642083_00472_40105_7945.N1 ...
Stripping browse product /nfs-store/ASAR_Data//ASA_WS_BP/ASA_WS_BPZPDK20091031_200413_000001152083_00472_40105_7943.N1 ...

ANALYSIS COMPLETED: 36 WS browse products to see...

BROWSE PRODUCTS ANALYSIS completed
#####

HTML REPORT generation
#####

Building file ./RESULTS/DAILY/091031/asarReport.html...
Building DATA SUMMARY section...
Building AUXILIARY FILES ANALYSIS section...
Building MODULE STEPPING ANALYSIS section...
Building CALIBRATION PULSES ANALYSIS section...
Building DOPPLER ANALYSIS section...
Building CHIRP ANALYSIS section...
Building RAW DATA ANALYSIS section...
Building TELEMETRY ANALYSIS section...

HTML REPORT generation completed
#####



ADFs disseminated for ASAR

ASA_CON_AXVIEC20081215_141339_20070204_165113_20091231_000000

ASA_INS_AXVIEC20090525_114808_20090428_100000_20091231_235959

ASA_XCH_AXVIEC20081215_143642_20020301_000000_20091231_000000

ASA_XCA_AXVIEC20090311_104501_20080801_000000_20091231_235959

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
WVS	0	0	0	0
GM1	0	0	0	0
APM	0	0	0	0
IMM	0	0	0	0
WSM	0	0	0	0

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
ASA_APM_1PNPDE20091031_015551_000000432083_00461_40094_4368.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20091031_015823_000000632083_00461_40094_4386.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20091031_033421_000000432083_00462_40095_4426.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20091031_151310_000000432083_00469_40102_4760.N1	OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_GM1_1PNPDE20091031_002809_000003442083_00460_40093_4256.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091031_004013_000000842083_00460_40093_4251.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091031_005208_000003142083_00460_40093_4270.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091031_010911_000003202083_00460_40093_4347.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091031_012911_000001202083_00461_40094_4330.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091031_013743_000009912083_00461_40094_4349.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091031_015654_000000902083_00461_40094_4342.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091031_022406_000006462083_00461_40094_4544.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091031_023704_000001632083_00461_40094_4407.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091031_024414_000005072083_00461_40094_4524.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091031_025406_000002472083_00461_40094_4526.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091031_030646_000012982083_00462_40095_4539.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091031_033201_000001382083_00462_40095_4409.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091031_033524_000003622083_00462_40095_4417.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091031_041255_000001322083_00462_40095_4463.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091031_041645_000002412083_00462_40095_4468.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091031_044005_000006822083_00463_40096_4470.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091031_045245_000008512083_00463_40096_4472.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091031_051237_000001872083_00463_40096_4474.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091031_051703_000002232083_00463_40096_4482.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091031_054201_000001262083_00463_40096_4568.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091031_055351_000004282083_00463_40096_4579.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091031_063141_000008332083_00464_40097_4589.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091031_065108_000000842083_00464_40097_4591.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091031_065558_000001502083_00464_40097_4593.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091031_065915_000004412083_00464_40097_4595.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091031_070724_000005012083_00464_40097_4597.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091031_200614_000003082083_00472_40105_4848.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091031_201216_000001572083_00472_40105_4855.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091031_204724_000000842083_00472_40105_4853.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091031_205404_000001322083_00472_40105_4857.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091031_210306_000000902083_00472_40105_4859.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091031_210333_000001752083_00472_40105_4905.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091031_211422_000010742083_00472_40105_4936.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091031_213407_000001442083_00473_40106_4910.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091031_214003_000001632083_00473_40106_4916.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091031_214618_000004832083_00473_40106_4924.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091031_222800_000001752083_00473_40106_4926.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091031_224304_000001142083_00473_40106_4931.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091031_230424_000000842083_00474_40107_4985.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091031_230730_000000962083_00474_40107_4995.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091031_232355_000008822083_00474_40107_4997.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20091031_235641_000004042083_00474_40107_5010.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_072557_000002472083_00464_40097_7610.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_073656_000002832083_00464_40097_7612.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_081330_000006642083_00465_40098_7617.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_082328_000007912083_00465_40098_7640.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_084343_000004282083_00465_40098_7642.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_090313_000001932083_00465_40098_7644.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_090807_000008452083_00465_40098_7649.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_095504_000004102083_00466_40099_7651.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_100151_000001262083_00466_40099_7660.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_101803_000001322083_00466_40099_7691.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_102401_000001752083_00466_40099_7693.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_104349_000001632083_00466_40099_7695.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_105626_000003802083_00466_40099_7703.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_113500_000002592083_00467_40100_7705.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_114047_000002232083_00467_40100_7707.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_114318_000001142083_00467_40100_7727.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_121006_000000902083_00467_40100_7732.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_122424_000001382083_00467_40100_7734.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_122826_000003202083_00467_40100_7736.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_123715_000003682083_00467_40100_7738.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_124927_000003922083_00467_40100_7746.N1					OK	OK	OK	OK

ASA_GM1_1PNPDK20091031_131016_000008512083_00468_40101_7748.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_132625_000003742083_00468_40101_7780.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_134613_000002952083_00468_40101_7782.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_135238_000003682083_00468_40101_7784.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_135853_000002952083_00468_40101_7786.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_140500_000002292083_00468_40101_7788.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_141031_000008092083_00468_40101_7790.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_142947_000002412083_00468_40101_7804.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_144534_000000842083_00469_40102_7800.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_144932_000005252083_00469_40102_7802.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_150247_000000842083_00469_40102_7798.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_150256_000003742083_00469_40102_7826.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_151141_000000902083_00469_40102_7824.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_151413_000001382083_00469_40102_7828.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_151812_000000842083_00469_40102_7830.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_154536_000011422083_00469_40102_7846.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_162508_000001082083_00470_40103_7835.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_163331_000002112083_00470_40103_7837.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_164143_000003742083_00470_40103_7866.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_164900_000009302083_00470_40103_7870.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_172612_000001142083_00470_40103_7868.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_172947_000000782083_00470_40103_7872.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_173835_000003982083_00470_40103_7877.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_180616_000003382083_00471_40104_7879.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_181432_000003202083_00471_40104_7881.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_181839_000002112083_00471_40104_7901.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_182633_000001202083_00471_40104_7899.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_183311_000003202083_00471_40104_7903.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_190648_000002592083_00471_40104_7905.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_192256_000001752083_00471_40104_7910.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20091031_193700_000007912083_00471_40104_7915.N1	OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_IMM_1PNPDE20091031_001223_000000372083_00460_40093_4278.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091031_002506_000000532083_00460_40093_4280.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091031_004344_000001232083_00460_40093_4353.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091031_004344_000004932083_00460_40093_4428.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091031_004747_000001802083_00460_40093_4354.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091031_023450_000001232083_00461_40094_4430.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091031_040511_000001622083_00462_40095_4459.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091031_040841_000002432083_00462_40095_4602.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091031_040945_000001792083_00462_40095_4585.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091031_045127_000000632083_00463_40096_4496.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091031_051545_000000672083_00463_40096_4548.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091031_054618_000000922083_00463_40096_4546.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091031_054838_000003022083_00463_40096_4620.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091031_065827_000000372083_00464_40097_4554.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091031_070635_000000372083_00464_40097_4581.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091031_083637_000000372083_00465_40098_4624.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091031_083747_000000372083_00465_40098_4626.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091031_101332_000001272083_00466_40099_4674.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091031_101715_000000372083_00466_40099_4664.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091031_104633_000003722083_00466_40099_4700.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091031_105218_000002372083_00466_40099_4734.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091031_110751_000000532083_00466_40099_4732.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091031_122643_000000912083_00467_40100_4736.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091031_135109_000000772083_00468_40101_4784.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091031_135212_000000142083_00468_40101_4744.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091031_140848_000000912083_00468_40101_4770.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091031_140951_000000282083_00468_40101_4748.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091031_144659_000001422083_00469_40102_4764.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091031_150917_000000422083_00469_40102_4766.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091031_164757_000000522083_00470_40103_4790.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091031_173102_000003012083_00470_40103_4818.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091031_173652_000000912083_00470_40103_4796.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091031_191108_000003012083_00471_40104_4846.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091031_191658_000003482083_00471_40104_4844.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091031_201117_000000482083_00472_40105_4864.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091031_202555_000000462083_00472_40105_4866.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091031_205110_000001602083_00472_40105_4901.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091031_205612_000002432083_00472_40105_4903.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091031_205612_000004022083_00472_40105_4981.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091031_210116_000000602083_00472_40105_4887.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091031_213319_000000372083_00473_40106_4950.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091031_215723_000000372083_00473_40106_4952.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091031_223053_000002302083_00473_40106_5016.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091031_223157_000001192083_00473_40106_4990.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091031_223533_000004412083_00473_40106_5063.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091031_223736_000000602083_00473_40106_4969.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20091031_230547_000000912083_00474_40107_5049.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20091031_064955_000000622083_00464_40097_7605.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20091031_073003_000004022083_00464_40097_7638.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20091031_081214_000000632083_00465_40098_7619.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20091031_101318_000000632083_00466_40099_7662.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20091031_123347_000001982083_00467_40100_7776.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20091031_124717_000000682083_00467_40100_7771.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20091031_124839_000000352083_00467_40100_7761.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20091031_150907_000000372083_00469_40102_7809.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20091031_214247_000002012083_00473_40106_7956.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20091031_232212_000000922083_00474_40107_7966.N1					OK	OK	OK	OK


Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WSM_1PNPDE20091031_004143_000000922083_00460_40093_4323.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091031_005726_000000922083_00460_40093_4301.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091031_013114_000001352083_00461_40094_4457.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091031_013114_000003732083_00461_40094_4640.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091031_013424_000000612083_00461_40094_4378.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091031_013626_000000612083_00461_40094_4382.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091031_015937_000000732083_00461_40094_4370.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091031_021940_000002452083_00461_40094_4384.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091031_030310_000002082083_00462_40095_4461.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091031_032826_000001902083_00462_40095_4446.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091031_032826_000002142083_00462_40095_4550.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091031_040158_000000732083_00462_40095_4440.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091031_040158_000001532083_00462_40095_4566.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091031_040413_000000182083_00462_40095_4444.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091031_041510_000000922083_00462_40095_4587.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091031_041624_000000182083_00462_40095_4512.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091031_050702_000003302083_00463_40096_4552.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091031_054411_000000922083_00463_40096_4615.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091031_054525_000000182083_00463_40096_4500.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091031_065239_000000732083_00464_40097_4570.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091031_065239_000001902083_00464_40097_4656.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091031_065454_000000552083_00464_40097_4574.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091031_071548_000002142083_00464_40097_4622.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091031_072322_000001532083_00464_40097_4642.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091031_084120_000001342083_00465_40098_4672.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091031_084233_000000612083_00465_40098_4630.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091031_100915_000000912083_00466_40099_4676.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091031_101547_000000912083_00466_40099_4696.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091031_101700_000000182083_00466_40099_4680.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091031_102022_000002142083_00466_40099_4730.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091031_113921_000000732083_00467_40100_4698.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091031_121142_000000732083_00467_40100_4722.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091031_121142_000002142083_00467_40100_4740.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091031_121357_000000792083_00467_40100_4738.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091031_151008_000000912083_00469_40102_4768.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091031_162700_000003732083_00470_40103_4798.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091031_172813_000000912083_00470_40103_4816.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091031_181158_000001522083_00471_40104_4820.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091031_182837_000002692083_00471_40104_5014.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091031_210946_000000732083_00472_40105_4891.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091031_210946_000002742083_00472_40105_4983.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091031_211255_000000842083_00472_40105_4938.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20091031_224500_000001532083_00473_40106_5065.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20091031_064537_000002142083_00464_40097_7978.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20091031_090632_000000922083_00465_40098_7674.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20091031_100404_000002992083_00466_40099_7687.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20091031_100915_000002452083_00466_40099_7689.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20091031_114515_000002752083_00467_40100_7725.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20091031_132431_000001092083_00468_40101_7778.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20091031_145824_000002502083_00469_40102_7822.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20091031_163704_000002752083_00470_40103_7864.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20091031_182214_000002512083_00471_40104_7897.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20091031_195404_000003732083_00472_40105_7946.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20091031_200028_000001642083_00472_40105_7944.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20091031_200413_000001152083_00472_40105_7942.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20091031_232002_000001222083_00474_40107_7968.N1					OK	OK	OK	OK


Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WVS_1PNPDE20091031_000942_000001202083_00460_40093_4238.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091031_001307_000006742083_00460_40093_4244.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091031_002607_000000742083_00460_40093_4247.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091031_003356_000003302083_00460_40093_4254.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091031_005907_000002252083_00460_40093_4266.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091031_010152_000003002083_00460_40093_4328.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091031_011437_000008242083_00460_40093_4333.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091031_015414_000000592083_00461_40094_4340.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091031_020107_000010642083_00461_40094_4345.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091031_023952_000002252083_00461_40094_4529.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091031_034129_000008992083_00462_40095_4542.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091031_035558_000001352083_00462_40095_4466.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091031_042051_000011092083_00462_40095_4477.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091031_052051_000009742083_00463_40096_4480.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091031_053635_000002852083_00463_40096_4577.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091031_060104_000017992083_00463_40096_4613.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091031_201456_000006142083_00472_40105_4851.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091031_202647_000011992083_00472_40105_4862.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091031_210627_000001502083_00472_40105_4908.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091031_213634_000001652083_00473_40106_4922.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091031_215424_000001352083_00473_40106_4919.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091031_215807_000017542083_00473_40106_4929.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091031_224730_000001802083_00473_40106_4934.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091031_224945_000008392083_00473_40106_4988.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091031_231111_000004942083_00474_40107_4993.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20091031_233838_000010342083_00474_40107_5000.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091031_071918_000001502083_00464_40097_7608.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091031_074140_000017992083_00464_40097_7615.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091031_085053_000006892083_00465_40098_7647.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091031_092215_000019192083_00465_40098_7658.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091031_102700_000009592083_00466_40099_7698.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091031_110251_000002552083_00466_40099_7701.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091031_110851_000015292083_00466_40099_7710.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091031_115039_000011242083_00467_40100_7730.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091031_121705_000003902083_00467_40100_7741.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091031_124327_000001952083_00467_40100_7744.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091031_125559_000008202083_00467_40100_7751.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091031_133240_000005692083_00468_40101_7793.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091031_142403_000003002083_00468_40101_7807.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091031_143351_000006592083_00468_40101_7796.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091031_152720_000010492083_00469_40102_7833.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091031_160439_000011842083_00469_40102_7844.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091031_170456_000012292083_00470_40103_7875.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091031_174515_000012142083_00470_40103_7884.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091031_183835_000016492083_00471_40104_7908.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20091031_192551_000006302083_00471_40104_7913.N1					OK	OK	OK	OK





Calibration pulses for GM1 SS3 H/H



Calibration pulses for GM1 SS3 H/H







Calibration pulses for GM1 SS3 H/H




rows: _ 3 _ 7 _ 11 _ 15 _ 19 _ 23 _ 27 _ 31

Calibration pulses for GM1 SS3 H/H




rows: _ 4 _ 8 _ 12 _ 16 _ 20 _ 24 _ 28 _ 32


Calibration pulses for WVS IS2 V/V




Calibration pulses for WVS IS2 V/V





Calibration pulses for WVS IS2 V/V





Calibration pulses for WVS IS2 V/V















rows: _ 1 _ 5 _ 9 _ 13 _ 17 _ 21 _ 25 _ 29





rows: _ 2 _ 6 _ 10 _ 14 _ 18 _ 22 _ 26 _ 30







rows: _ 3 _ 7 _ 11 _ 15 _ 19 _ 23 _ 27 _ 31






rows: _ 4 _ 8 _ 12 _ 16 _ 20 _ 24 _ 28 _ 32




















WVS			
Center	Beam	Pol	#
PDE	IS1	V/V	2
PDE	IS2	V/V	26
PDK	IS2	V/V	20

GM1			
Center	Beam	Pol	#
PDE	WS	H/H	44
PDK	WS	H/H	52

APM			
Center	Beam	Pol	#
PDE	IS1	H/H	2
PDE	IS2	V/H	1
PDE	IS6	H/H	1

IMM			
Center	Beam	Pol	#
PDE	IS1	H/H	1
PDE	IS1	V/V	2
PDE	IS2	H/H	28
PDE	IS2	V/V	11
PDE	IS3	H/H	1
PDE	IS6	V/V	1
PDE	IS7	***	1
PDE	IS7	H/H	1
PDE	IS7	V/V	1
PDK	IS2	H/H	4
PDK	IS2	V/V	5
PDK	IS7	V/V	1

WSM			
Center	Beam	Pol	#
PDE	WS	H/H	29
PDE	WS	V/V	14
PDK	WS	H/H	10
PDK	WS	V/V	3

MS			
Center	Time	Pol	Modules
PDE	2009-10-31 20:48:52	V	320


Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_APM_1PNPDE20091031_015551_000000432083_00461_40094_4368.N1						IS6	H/H	83	40094	461	4.07
ASA_APM_1PNPDE20091031_015823_000000632083_00461_40094_4386.N1						IS2	V/H	83	40094	461	4.07
ASA_APM_1PNPDE20091031_033421_000000432083_00462_40095_4426.N1						IS1	H/H	83	40095	462	4.07
ASA_APM_1PNPDE20091031_151310_000000432083_00469_40102_4760.N1						IS1	H/H	83	40102	469	4.07


ASA_GM1_1PNPDK20091031_164143_000003742083_00470_40103_7866.N1	SS1	H/H	83	40103	470	4.07
ASA_GM1_1PNPDK20091031_164900_000009302083_00470_40103_7870.N1	SS1	H/H	83	40103	470	4.07
ASA_GM1_1PNPDK20091031_172612_000001142083_00470_40103_7868.N1	SS1	H/H	83	40103	470	4.07
ASA_GM1_1PNPDK20091031_172947_000000782083_00470_40103_7872.N1	SS1	H/H	83	40103	470	4.07
ASA_GM1_1PNPDK20091031_173835_000003982083_00470_40103_7877.N1	SS1	H/H	83	40103	470	4.07
ASA_GM1_1PNPDK20091031_180616_000003382083_00471_40104_7879.N1	SS1	H/H	83	40104	471	4.07
ASA_GM1_1PNPDK20091031_181432_000003202083_00471_40104_7881.N1	SS1	H/H	83	40104	471	4.07
ASA_GM1_1PNPDK20091031_181839_000002112083_00471_40104_7901.N1	SS1	H/H	83	40104	471	4.07
ASA_GM1_1PNPDK20091031_182633_000001202083_00471_40104_7899.N1	SS1	H/H	83	40104	471	4.07
ASA_GM1_1PNPDK20091031_183311_000003202083_00471_40104_7903.N1	SS1	H/H	83	40104	471	4.07
ASA_GM1_1PNPDK20091031_190648_000002592083_00471_40104_7905.N1	SS1	H/H	83	40104	471	4.07
ASA_GM1_1PNPDK20091031_192256_000001752083_00471_40104_7910.N1	SS1	H/H	83	40104	471	4.07
ASA_GM1_1PNPDK20091031_193700_000007912083_00471_40104_7915.N1	SS1	H/H	83	40104	471	4.07
ASA_GM1_1PNPDE20091031_200614_000003082083_00472_40105_4848.N1	SS1	H/H	83	40105	472	4.07
ASA_GM1_1PNPDE20091031_201216_000001572083_00472_40105_4855.N1	SS1	H/H	83	40105	472	4.07
ASA_GM1_1PNPDE20091031_204724_000000842083_00472_40105_4853.N1	SS1	H/H	83	40105	472	4.07
ASA_GM1_1PNPDE20091031_205404_000001322083_00472_40105_4857.N1	SS1	H/H	83	40105	472	4.07
ASA_GM1_1PNPDE20091031_210306_000000902083_00472_40105_4859.N1	SS1	H/H	83	40105	472	4.07
ASA_GM1_1PNPDE20091031_210333_000001752083_00472_40105_4905.N1	SS1	H/H	83	40105	472	4.07
ASA_GM1_1PNPDE20091031_211422_000010742083_00472_40105_4936.N1	SS1	H/H	83	40105	472	4.07
ASA_GM1_1PNPDE20091031_213407_000001442083_00473_40106_4910.N1	SS1	H/H	83	40106	473	4.07
ASA_GM1_1PNPDE20091031_214003_000001632083_00473_40106_4916.N1	SS1	H/H	83	40106	473	4.07
ASA_GM1_1PNPDE20091031_214618_000004832083_00473_40106_4924.N1	SS1	H/H	83	40106	473	4.07
ASA_GM1_1PNPDE20091031_222800_000001752083_00473_40106_4926.N1	SS1	H/H	83	40106	473	4.07
ASA_GM1_1PNPDE20091031_224304_000001142083_00473_40106_4931.N1	SS1	H/H	83	40106	473	4.07
ASA_GM1_1PNPDE20091031_230424_000000842083_00474_40107_4985.N1	SS1	H/H	83	40107	474	4.07
ASA_GM1_1PNPDE20091031_230730_000000962083_00474_40107_4995.N1	SS1	H/H	83	40107	474	4.07
ASA_GM1_1PNPDE20091031_232355_000008822083_00474_40107_4997.N1	SS1	H/H	83	40107	474	4.07
ASA_GM1_1PNPDE20091031_235641_000004042083_00474_40107_5010.N1	SS1	H/H	83	40107	474	4.07


Filename	Pol	Timestamp	count(Module)
ASA_MS__0PNPDE20091031_204852_000000162083_00472_40105_0468.N1	V	2009-10-31 20:48:52	320







Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WVS_1PNPDE20091031_000942_000001202083_00460_40093_4238.N1						IS2	V/V	83	40093	460	4.07
ASA_WVS_1PNPDE20091031_001307_000006742083_00460_40093_4244.N1						IS2	V/V	83	40093	460	4.07
ASA_WVS_1PNPDE20091031_002607_000000742083_00460_40093_4247.N1						IS2	V/V	83	40093	460	4.07
ASA_WVS_1PNPDE20091031_003356_000003302083_00460_40093_4254.N1						IS2	V/V	83	40093	460	4.07
ASA_WVS_1PNPDE20091031_005907_000002252083_00460_40093_4266.N1						IS2	V/V	83	40093	460	4.07
ASA_WVS_1PNPDE20091031_010152_000003002083_00460_40093_4328.N1						IS2	V/V	83	40093	460	4.07
ASA_WVS_1PNPDE20091031_011437_000008242083_00460_40093_4333.N1						IS2	V/V	83	40093	460	4.07
ASA_WVS_1PNPDE20091031_015414_000000592083_00461_40094_4340.N1						IS2	V/V	83	40094	461	4.07
ASA_WVS_1PNPDE20091031_020107_000010642083_00461_40094_4345.N1						IS2	V/V	83	40094	461	4.07
ASA_WVS_1PNPDE20091031_023952_000002252083_00461_40094_4529.N1						IS2	V/V	83	40094	461	4.07
ASA_WVS_1PNPDE20091031_034129_000008992083_00462_40095_4542.N1						IS2	V/V	83	40095	462	4.07
ASA_WVS_1PNPDE20091031_035558_000001352083_00462_40095_4466.N1						IS2	V/V	83	40095	462	4.07
ASA_WVS_1PNPDE20091031_034129_000008992083_00462_40095_4542.N1						IS1	V/V	83	40095	462	4.07
ASA_WVS_1PNPDE20091031_042051_000011092083_00462_40095_4477.N1						IS2	V/V	83	40095	462	4.07
ASA_WVS_1PNPDE20091031_052051_000009742083_00463_40096_4480.N1						IS2	V/V	83	40096	463	4.07
ASA_WVS_1PNPDE20091031_053635_000002852083_00463_40096_4577.N1						IS2	V/V	83	40096	463	4.07
ASA_WVS_1PNPDE20091031_052051_000009742083_00463_40096_4480.N1						IS1	V/V	83	40096	463	4.07
ASA_WVS_1PNPDE20091031_060104_000017992083_00463_40096_4613.N1						IS2	V/V	83	40096	463	4.07
ASA_WVS_1PNPDK20091031_071918_000001502083_00464_40097_7608.N1						IS2	V/V	83	40097	464	4.07
ASA_WVS_1PNPDK20091031_074140_000017992083_00464_40097_7615.N1						IS2	V/V	83	40097	464	4.07
ASA_WVS_1PNPDK20091031_085053_000006892083_00465_40098_7647.N1						IS2	V/V	83	40098	465	4.07
ASA_WVS_1PNPDK20091031_092215_000019192083_00465_40098_7658.N1						IS2	V/V	83	40098	465	4.07
ASA_WVS_1PNPDK20091031_102700_000009592083_00466_40099_7698.N1						IS2	V/V	83	40099	466	4.07
ASA_WVS_1PNPDK20091031_110251_000002552083_00466_40099_7701.N1						IS2	V/V	83	40099	466	4.07
ASA_WVS_1PNPDK20091031_110851_000015292083_00466_40099_7710.N1						IS2	V/V	83	40099	466	4.07
ASA_WVS_1PNPDK20091031_115039_000011242083_00467_40100_7730.N1						IS2	V/V	83	40100	467	4.07
ASA_WVS_1PNPDK20091031_121705_000003902083_00467_40100_7741.N1						IS2	V/V	83	40100	467	4.07
ASA_WVS_1PNPDK20091031_124327_000001952083_00467_40100_7744.N1						IS2	V/V	83	40100	467	4.07
ASA_WVS_1PNPDK20091031_125559_000008202083_00467_40100_7751.N1						IS2	V/V	83	40100	467	4.07
ASA_WVS_1PNPDK20091031_133240_000005692083_00468_40101_7793.N1						IS2	V/V	83	40101	468	4.07
ASA_WVS_1PNPDK20091031_142403_000003002083_00468_40101_7807.N1						IS2	V/V	83	40101	468	4.07
ASA_WVS_1PNPDK20091031_143351_000006592083_00468_40101_7796.N1						IS2	V/V	83	40101	468	4.07
ASA_WVS_1PNPDK20091031_152720_000010492083_00469_40102_7833.N1						IS2	V/V	83	40102	469	4.07
ASA_WVS_1PNPDK20091031_160439_000011842083_00469_40102_7844.N1						IS2	V/V	83	40102	469	4.07
ASA_WVS_1PNPDK20091031_170456_000012292083_00470_40103_7875.N1						IS2	V/V	83	40103	470	4.07
ASA_WVS_1PNPDK20091031_174515_000012142083_00470_40103_7884.N1						IS2	V/V	83	40103	470	4.07
ASA_WVS_1PNPDK20091031_183835_000016492083_00471_40104_7908.N1						IS2	V/V	83	40104	471	4.07
ASA_WVS_1PNPDK20091031_192551_000006302083_00471_40104_7913.N1						IS2	V/V	83	40104	471	4.07
ASA_WVS_1PNPDE20091031_201456_000006142083_00472_40105_4851.N1						IS2	V/V	83	40105	472	4.07
ASA_WVS_1PNPDE20091031_202647_000011992083_00472_40105_4862.N1						IS2	V/V	83	40105	472	4.07
ASA_WVS_1PNPDE20091031_210627_000001502083_00472_40105_4908.N1						IS2	V/V	83	40105	472	4.07
ASA_WVS_1PNPDE20091031_213634_000001652083_00473_40106_4922.N1						IS2	V/V	83	40106	473	4.07
ASA_WVS_1PNPDE20091031_215424_000001352083_00473_40106_4919.N1						IS2	V/V	83	40106	473	4.07
ASA_WVS_1PNPDE20091031_215807_000017542083_00473_40106_4929.N1						IS2	V/V	83	40106	473	4.07
ASA_WVS_1PNPDE20091031_224730_000001802083_00473_40106_4934.N1						IS2	V/V	83	40106	473	4.07
ASA_WVS_1PNPDE20091031_224945_000008392083_00473_40106_4988.N1						IS2	V/V	83	40106	473	4.07
ASA_WVS_1PNPDE20091031_231111_000004942083_00474_40107_4993.N1						IS2	V/V	83	40107	474	4.07
ASA_WVS_1PNPDE20091031_233838_000010342083_00474_40107_5000.N1						IS2	V/V	83	40107	474	4.07

















































31-Oct




31-Oct




31-Oct




31-Oct







31-Oct




31-Oct









31-Oct





31-Oct




31-Oct










```
<table border="1" cellspacing="0" cellpadding="2" bordercolor="#01669F" style="border-collapse: collapse" width=900>
<tr><td align=center><b>Processing Center</b></td><td align=center><b>Product
align=center><b>Missing lines</b></td></tr>
</table>
```

```
</b></td><td align=center><b>
Gaps</b></td><td
```



