



Analysis from 13-JUN-2010 00:00:00 to 13-JUN-2010 23:59:59. Page generated on 14-JUN-2010 07:32:21.
View log file: ASAR_Daily_Report_20100614_0731.log. For any anomalies please contact emma.griffiths@vega.co.uk, kajal.haria@vega.co.uk.

This report is automatically generated every day, every 2 hours. No comments are provided on the results.

SUMMARY

1. DATA SUMMARY
 - 1.1 Summary tables
 - 1.2 Lists of products used
2. AUXILIARY FILES ANALYSIS
 - 2.1 IECF operational ADFs list
 - 2.2 Products with wrong ADFs
3. MODULE STEPPING PRODUCTS ANALYSIS
 - 3.1 V/V polarisation
 - 3.2 H/H polarisation
4. CALIBRATION PULSES ANALYSIS
 - 4.1 Analysis for WVS IS2 V/V
 - 4.1.1 Temporal Evolution Analysis for WVS IS2 V/V
 - 4.1.2 All Rows Analysis for WVS IS2 V/V
 - 4.2 Analysis for GM1 SS3 H/H
 - 4.2.1 Temporal Evolution Analysis for GM1 SS3 H/H
 - 4.2.2 All Rows Analysis for GM1 SS3 H/H
5. DOPPLER ANALYSIS
 - 5.1 Analysis for WVS IS2 V/V
 - 5.1.1 Doppler MAP Analysis for WVS IS2 V/V
 - 5.1.2 Doppler ANX Analysis for WVS IS2 V/V
 - 5.2 Analysis for GM1 SS1 H/H
 - 5.2.1 Doppler MAP Analysis for GM1 SS1 H/H
 - 5.2.2 Doppler ANX Analysis for GM1 SS1 H/H
 - 5.3 Doppler JUMPS Analysis for WSM
6. CHIRP ANALYSIS
 - 6.1 Analysis for WSM SS1 H/H
 - 6.1.1 ScaleFactor
 - 6.2 Analysis for WSM SS1 V/V
 - 6.2.1 ScaleFactor
7. RAW DATA ANALYSIS
 - 7.1 Analysis for WVS
 - 7.2 Analysis for IMM
8. TELEMETRY ANALYSIS
 - 8.1 Number of Missing Lines
 - 8.2 Number of Gaps

1 - DATA SUMMARY

1.1 - Summary tables

[[BACK TO MENU](#)]

WVS				GM1				APM				IMM				WSM				MS			
Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Time	Pol	Modules
PDE	IS1	V/V	1	PDE	WS	H/H	24	PDE	IS3	H/H	1	PDE	IS2	H/H	1	PDE	WS	H/H	27	PDK	2010-06-13 06:12:09	H	320
PDE	IS2	V/V	24	PDK	WS	H/H	51	PDE	IS4	V/H	1	PDE	IS2	V/V	14	PDE	WS	V/V	11				
PDK	IS2	V/V	28					PDE	IS4	V/V	2	PDE	IS4	V/V	1	PDK	WS	H/H	13				
								PDK	IS6	H/H	1	PDE	IS6	V/V	1	PDK	WS	V/V	6				
												PDK	IS2	***	1								
												PDK	IS2	H/H	2								
												PDK	IS2	V/V	1								
												PDK	IS3	V/V	1								
												PDK	IS6	H/H	1								
												PDK	IS6	V/V	1								

1.2 - Lists of products used

[[BACK TO MENU](#)]

[[TXT](#)] [[XLS](#)] [List_WVS_products_used](#)
 [[TXT](#)] [[XLS](#)] [List_GM1_products_used](#)
 [[TXT](#)] [[XLS](#)] [List_APM_products_used](#)
 [[TXT](#)] [[XLS](#)] [List_IMM_products_used](#)
 [[TXT](#)] [[XLS](#)] [List_WSM_products_used](#)
 [[TXT](#)] [[XLS](#)] [List_MS_products_used](#)

2 - AUXILIARY FILES ANALYSIS

2.1 - IECF operational ADFs list

[[BACK TO MENU](#)]





ADFs disseminated for ASAR
ASA_CON_AXVIEC20100608_125449_20100317_120410_20101231_000000
ASA_INS_AXVIEC20091217_114637_20090428_100000_20101231_235959
ASA_XCH_AXVIEC20091217_113006_20020301_000000_20101231_000000
ASA_XCA_AXVIEC20100608_123419_20100317_120410_20110101_000000

2.2 - Products with wrong ADFs

[[BACK TO MENU](#)]

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
WVS	0	0	0	0
GM1	0	0	0	0
APM	0	0	0	0
IMM	0	0	0	0
WSM	0	0	0	0

[[TXT](#)] [[XLS](#)] [Check_ADFs_WVS](#)




3.2 - H/H polarisation

[[BACK TO MENU](#)]

SECOND FIXED REFERENCE	PREVIOUS PRODUCT REFERENCE
Pre-launch reference (2001-02-09)	Previous product in the same polarisation

Reference: 2001-02-09 13:50:42 H RxGain

Test : 2010-06-13 06:12:09 H



Reference: 2010-06-11 07:15:23 H RxGain

Test : 2010-06-13 06:12:09 H




Reference: 2001-02-09 13:50:42 H RxPhase





Test : 2010-06-13 06:12:09 H



Reference: 2010-06-11 07:15:23 H RxPhase

Test : 2010-06-13 06:12:09 H





4 - CALIBRATION PULSES ANALYSIS

4.1 - Analysis for WVS IS2 V/V


4.1.1 - Temporal Evolution Analysis for WVS IS2 V/V

[BACK TO MENU]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Calibration pulses for WVS IS2 V/V




Transmit power (P1 - P1a) for WVS IS2 V/V



4.1.2 - All Rows Analysis for WVS IS2 V/V

[[BACK TO MENU](#)]





4.2 - Analysis for GM1 SS3 H/H


4.2.1 - Temporal Evolution Analysis for GM1 SS3 H/H

[BACK TO MENU]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Calibration pulses for GM1 SS3 H/H




Transmit power (P1 - P1a) for GM1 SS3 H/H



4.2.2 - All Rows Analysis for GM1 SS3 H/H

[[BACK TO MENU](#)]






5 - DOPPLER ANALYSIS

5.1 - Analysis for WVS IS2 V/V

5.1.1 - Doppler MAP Analysis for WVS IS2 V/V

[[BACK TO MENU](#)]






5.1.2 - Doppler ANX Analysis for WVS IS2 V/V

[[BACK TO MENU](#)]






5.2 - Analysis for GM1 SS1 H/H

5.2.1 - Doppler MAP Analysis for GM1 SS1 H/H

[[BACK TO MENU](#)]






5.2.2 - Doppler ANX Analysis for GM1 SS1 H/H

[[BACK TO MENU](#)]






5.3 - Doppler JUMPS Analysis for WSM

[[BACK TO MENU](#)]







6 - CHIRP ANALYSIS

6.1 - Analysis for WSM SS1 H/H

6.1.1 - ScaleFactor

[[BACK TO MENU](#)]







6.2 - Analysis for WSM SS1 V/V

6.2.1 - ScaleFactor

[[BACK TO MENU](#)]






7 - RAW DATA ANALYSIS

7.1 - Analysis for WVS

[[BACK TO MENU](#)]

--	--	--




Channel	Statistics	DSS-B
MEAN I	mean	0.000617384
	stdev	1.27503e-07
MEAN Q	mean	0.000519127
	stdev	2.10139e-07
Channel	Statistics	DSS-B
STDEV I	mean	0.147822
	stdev	0.00121524
STDEV Q	mean	0.148357
	stdev	0.00123816

7.2 - Analysis for IMM

[[BACK TO MENU](#)]







8 - TELEMETRY ANALYSIS

Processing Center	Product	Gaps	Missing lines
PDE	ASA_WSM_1PNPDE20100613_032858_000002452090_00176_43316_8412.N1	0	39
PDE	ASA_WSM_1PNPDE20100613_032858_000002452090_00176_43316_8524.N1	0	39
PDE	ASA_WSM_1PNPDE20100613_183447_000002022090_00185_43325_8539.N1	0	65
PDK	ASA_WSM_1PNPDK20100613_132332_000000982090_00181_43321_3954.N1	0	1

8.1 - Number of Missing lines


[BACK TO MENU]





8.2 - Number of Gaps

[\[BACK TO MENU \]](#)



ASAR DAILY REPORT for 100613
#####

MODE: DAILY
ANALYSIS: ALL
DATE: YESTERDAY

Analysis will be performed from 2010-06-13 00:00:00 to 2010-06-13 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_100613/

DATA SUMMARY

Summary will be performed from 2010-06-13 00:00:00 to 2010-06-13 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_100613/DATA_SUMMARY

Creating directory ./RESULTS/DAILY/_100613/DATA_SUMMARY...
Writing file ./RESULTS/DAILY/_100613/DATA_SUMMARY/Data_summary.html...

Getting WVS products list from 2010-06-13 00:00:00 to 2010-06-13 23:59:59...
Writing file ./RESULTS/DAILY/_100613/DATA_SUMMARY/List_WVS_products_used.xls...
Writing file ./RESULTS/DAILY/_100613/DATA_SUMMARY/List_WVS_products_used.txt...

Getting GM1 products list from 2010-06-13 00:00:00 to 2010-06-13 23:59:59...
Writing file ./RESULTS/DAILY/_100613/DATA_SUMMARY/List_GM1_products_used.xls...
Writing file ./RESULTS/DAILY/_100613/DATA_SUMMARY/List_GM1_products_used.txt...

Getting APM products list from 2010-06-13 00:00:00 to 2010-06-13 23:59:59...
Writing file ./RESULTS/DAILY/_100613/DATA_SUMMARY/List_APM_products_used.xls...
Writing file ./RESULTS/DAILY/_100613/DATA_SUMMARY/List_APM_products_used.txt...

Getting IMM products list from 2010-06-13 00:00:00 to 2010-06-13 23:59:59...
Writing file ./RESULTS/DAILY/_100613/DATA_SUMMARY/List_IMM_products_used.xls...
Writing file ./RESULTS/DAILY/_100613/DATA_SUMMARY/List_IMM_products_used.txt...

Getting WSM products list from 2010-06-13 00:00:00 to 2010-06-13 23:59:59...
Writing file ./RESULTS/DAILY/_100613/DATA_SUMMARY/List_WSM_products_used.xls...
Writing file ./RESULTS/DAILY/_100613/DATA_SUMMARY/List_WSM_products_used.txt...

Getting MS products list from 2010-06-13 00:00:00 to 2010-06-13 23:59:59...
Writing file ./RESULTS/DAILY/_100613/DATA_SUMMARY/List_MS_products_used.xls...
Writing file ./RESULTS/DAILY/_100613/DATA_SUMMARY/List_MS_products_used.txt...

DATA SUMMARY completed
#####

AUXILIARY FILES ANALYSIS

Analysis will be performed from 2010-06-13 00:00:00 to 2010-06-13 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_100613/AUXILIARY

Creating directory ./RESULTS/DAILY/_100613/AUXILIARY...

Looking for the IECF operational ADFs list...



ADF filter 20100613*current_3_IECF_ADFs.txt
 Found list 20100613_030002_current_3_IECF_ADFs.txt...
 Extracting ADFs...

ASA_CON_AXVIEC20100608_125449_20100317_120410_20101231_000000
 ASA_INS_AXVIEC20091217_114637_20090428_100000_20101231_235959
 ASA_XCH_AXVIEC20091217_113006_20020301_000000_20101231_000000
 ASA_XCA_AXVIEC20100608_123419_20100317_120410_20110101_000000

Writing file ./RESULTS/DAILY/_100613/AUXILIARY/ASAR_ADFs_IECF_List3.html...
 Writing file ./RESULTS/DAILY/_100613/AUXILIARY/Auxiliary_files_summary.html...

Analysing WVS products...

Writing file ./RESULTS/DAILY/_100613/AUXILIARY/Check_ADFs_WVS.xls...
 Writing file ./RESULTS/DAILY/_100613/AUXILIARY/Check_ADFs_WVS.txt...

ASA_WVS_1PNPDE20100613_003656_000009472090_00174_43314_8364.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100613_010315_000003902090_00174_43314_8366.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100613_012634_000002252090_00174_43314_8369.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100613_012934_000003002090_00174_43314_8378.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100613_014508_000006292090_00175_43315_8381.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100613_023904_000002392090_00175_43315_8383.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100613_024249_000004502090_00175_43315_8395.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100613_030654_000002102090_00175_43315_8403.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100613_032703_000000742090_00176_43316_8399.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100613_040920_000009592090_00176_43316_8397.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100613_042505_000000902090_00176_43316_8421.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100613_042933_000000752090_00176_43316_8419.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100613_044739_000012892090_00176_43316_8426.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100613_054822_000010792090_00177_43317_8425.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100613_204418_000019492090_00186_43326_8544.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100613_213351_000003142090_00186_43326_8546.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100613_213821_000001202090_00186_43326_8559.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100613_214359_000004192090_00186_43326_8560.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100613_220511_000001652090_00187_43327_8563.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100613_222501_000019492090_00187_43327_8565.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100613_231434_000003152090_00187_43327_8566.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100613_231904_000013192090_00187_43327_8575.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100613_234223_000002702090_00188_43328_8576.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100613_060606_000003302090_00177_43317_3850.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100613_062815_000019642090_00177_43317_3852.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100613_074759_000002402090_00178_43318_3877.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100613_080851_000012742090_00178_43318_3879.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100613_083200_000006742090_00179_43319_3881.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100613_091545_000010192090_00179_43319_3904.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100613_094927_000018892090_00179_43319_3908.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100613_103845_000001052090_00180_43320_3919.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100613_105414_000011392090_00180_43320_3921.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100613_113003_000019342090_00180_43320_3924.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100613_122105_000009742090_00181_43321_3934.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100613_124741_000003752090_00181_43321_3936.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100613_131030_000003152090_00181_43321_3939.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100613_132757_000002992090_00182_43322_3940.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100613_133629_000000892090_00182_43322_3947.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100613_140356_000006292090_00182_43322_3958.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100613_142318_000006752090_00182_43322_3960.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100613_145115_000003752090_00182_43322_3961.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100613_150139_000001942090_00182_43322_3965.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100613_150850_000000742090_00183_43323_3966.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100613_155449_000012142090_00183_43323_3981.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100613_163142_000011242090_00183_43323_3986.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100613_173241_000013792090_00184_43324_4006.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100613_181630_000009892090_00184_43324_4009.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100613_181630_000009892090_00184_43324_4011.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

```
ASA_WVS_1PNPDK20100613_190601_000018142090_00185_43325_4031.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100613_195254_000001202090_00185_43325_4030.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100613_195705_000003302090_00185_43325_4038.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```

Analysing GM1 products...

Writing file ./RESULTS/DAILY/_100613/AUXILIARY/Check_ADFs_GM1.xls...

Writing file ./RESULTS/DAILY/_100613/AUXILIARY/Check_ADFs_GM1.txt...

```
ASA_GM1_1PNPDE20100613_003127_000003262090_00174_43314_8363.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100613_005327_000005862090_00174_43314_8367.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100613_011023_000006892090_00174_43314_8368.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100613_013655_000004892090_00174_43314_8379.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100613_015612_000002712090_00175_43315_8380.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100613_020425_000010752090_00175_43315_8382.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100613_025059_000006222090_00175_43315_8396.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100613_031110_000001872090_00175_43315_8404.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100613_031423_000007552090_00175_43315_8402.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100613_033315_000006832090_00176_43316_8401.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100613_034528_000009792090_00176_43316_8400.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100613_040745_000000902090_00176_43316_8398.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100613_043134_000005312090_00176_43316_8420.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100613_044549_000001022090_00176_43316_8422.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100613_051610_000001872090_00177_43317_8418.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100613_052155_000012332090_00177_43317_8423.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100613_203625_000000782090_00186_43326_8542.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100613_204100_000001992090_00186_43326_8543.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100613_211734_000006712090_00186_43326_8545.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100613_215137_000005132090_00187_43327_8562.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100613_220846_000001022090_00187_43327_8561.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100613_221450_000001442090_00187_43327_8564.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100613_225811_000005612090_00187_43327_8567.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100613_235912_000004712090_00188_43328_8579.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_061328_000005732090_00177_43317_3849.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_062613_000001142090_00177_43317_3851.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_070814_000003862090_00178_43318_3853.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_070814_000003862090_00178_43318_3857.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_070814_000003862090_00178_43318_3859.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_071351_000001632090_00178_43318_3873.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_071853_000004162090_00178_43318_3874.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_073007_000003382090_00178_43318_3875.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_074015_000001932090_00178_43318_3876.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_075247_000006162090_00178_43318_3878.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_080731_000000722090_00178_43318_3880.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_084357_000007672090_00179_43319_3882.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_085602_000002292090_00179_43319_3900.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_090230_000000902090_00179_43319_3901.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_090718_000002052090_00179_43319_3902.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_093324_000005792090_00179_43319_3903.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_094812_000000662090_00179_43319_3905.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_102557_000000842090_00180_43320_3906.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_102956_000001442090_00180_43320_3907.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_105028_000002232090_00180_43320_3920.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_111359_000005672090_00180_43320_3922.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_112830_000000842090_00180_43320_3923.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_120304_000005252090_00181_43321_3925.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_123808_000005732090_00181_43321_3935.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_125435_000005612090_00181_43321_3937.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_131629_000004162090_00181_43321_3938.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_132516_000001572090_00181_43321_3941.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_133842_000005792090_00182_43322_3944.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_135041_000001692090_00182_43322_3949.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_135242_000006712090_00182_43322_3956.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_141503_000002712090_00182_43322_3957.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_142114_000001202090_00182_43322_3959.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```


ASA_GM1_1PNPDK20100613_143510_000009612090_00182_43322_3963.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_145811_000002052090_00182_43322_3962.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_150542_000001872090_00182_43322_3964.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_151043_000011602090_00183_43323_3967.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_154437_000003022090_00183_43323_3979.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_155242_000000722090_00183_43323_3980.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_161546_000007732090_00183_43323_3982.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_165109_000003982090_00184_43324_3983.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_165924_000001992090_00184_43324_3985.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_171640_000000722090_00184_43324_4003.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_171845_000001022090_00184_43324_4002.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_172232_000001142090_00184_43324_4004.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_172537_000001202090_00184_43324_4005.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_175622_000007792090_00184_43324_4007.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_183809_000005012090_00185_43325_4008.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_183809_000005012090_00185_43325_4010.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_185544_000004772090_00185_43325_4029.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_193658_000006162090_00185_43325_4032.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100613_200318_000009062090_00185_43325_4039.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

Analysing APM products...

Writing file ./RESULTS/DAILY/_100613/AUXILIARY/Check_ADFs_APM.xls...

Writing file ./RESULTS/DAILY/_100613/AUXILIARY/Check_ADFs_APM.txt...

ASA_APM_1PNPDE20100613_051045_000001782090_00177_43317_8417.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20100613_073546_000001732090_00178_43318_8441.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20100613_073857_000000572090_00178_43318_8442.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20100613_172431_000000442090_00184_43324_8536.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDK20100613_090126_000000432090_00179_43319_3892.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

Analysing IMM products...

Writing file ./RESULTS/DAILY/_100613/AUXILIARY/Check_ADFs_IMM.xls...

Writing file ./RESULTS/DAILY/_100613/AUXILIARY/Check_ADFs_IMM.txt...

ASA_IMM_1PNPDE20100613_002147_000002382090_00174_43314_8375.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100613_022314_000001682090_00175_43315_8434.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100613_022631_000000832090_00175_43315_8435.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100613_040148_000003462090_00176_43316_8394.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100613_051452_000000682090_00177_43317_8428.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100613_051916_000001462090_00177_43317_8432.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100613_054248_000001502090_00177_43317_8437.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100613_054630_000001062090_00177_43317_8495.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100613_091040_000003002090_00179_43319_8469.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100613_104822_000001142090_00180_43320_8497.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100613_155357_000000332090_00183_43323_8532.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100613_155357_000000332090_00183_43323_8537.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100613_165746_000000872090_00184_43324_8529.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100613_171754_000000392090_00184_43324_8534.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100613_172741_000002932090_00184_43324_8538.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100613_190342_000001332090_00185_43325_8541.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100613_220217_000000372090_00187_43327_8554.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20100613_070158_000000922090_00178_43318_3863.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20100613_083045_000000692090_00179_43319_3887.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20100613_104248_000000532090_00180_43320_3918.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20100613_133514_000000682090_00182_43322_3955.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20100613_202325_000000192090_00186_43326_4026.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20100613_202358_000000372090_00186_43326_4027.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20100613_221031_000002522090_00187_43327_4049.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

Analysing WSM products...

Writing file ./RESULTS/DAILY/_100613/AUXILIARY/Check_ADFs_WSM.xls...

Writing file ./RESULTS/DAILY/_100613/AUXILIARY/Check_ADFs_WSM.txt...

ASA_WSM_1PNPDE20100613_001856_000001472090_00174_43314_8361.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100613_002617_000003062090_00174_43314_8377.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100613_012200_000002752090_00174_43314_8393.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100613_020048_000002142090_00175_43315_8436.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100613_023037_000005082090_00175_43315_8389.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100613_030128_000002942090_00175_43315_8411.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100613_032858_000002452090_00176_43316_8412.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100613_032858_000002452090_00176_43316_8524.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100613_044034_000002202090_00176_43316_8414.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100613_044432_000000672090_00176_43316_8415.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100613_071643_000001282090_00178_43318_8439.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100613_072558_000002452090_00178_43318_8440.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100613_074331_000002692090_00178_43318_8443.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100613_085957_000000922090_00179_43319_8468.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100613_094309_000003002090_00179_43319_8500.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100613_102142_000002452090_00180_43320_8501.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100613_102734_000001282090_00180_43320_8503.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100613_112332_000002942090_00180_43320_8522.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100613_141938_000000922090_00182_43322_8525.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100613_153630_000001282090_00183_43323_8527.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100613_154005_000002692090_00183_43323_8528.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100613_154943_000001472090_00183_43323_8531.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100613_162844_000001282090_00183_43323_8526.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100613_170249_000001652090_00184_43324_8530.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100613_172036_000001102090_00184_43324_8535.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100613_180930_000001162090_00184_43324_8533.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100613_183447_000002022090_00185_43325_8539.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100613_194719_000002812090_00185_43325_8540.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100613_203436_000001042090_00186_43326_8556.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100613_203756_000001772090_00186_43326_8557.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100613_212848_000003062090_00186_43326_8553.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100613_214111_000001712090_00186_43326_8558.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100613_220338_000000862090_00187_43327_8555.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100613_221721_000004592090_00187_43327_8627.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100613_230741_000004162090_00187_43327_8574.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100613_234745_000002142090_00188_43328_8577.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100613_235155_000002942090_00188_43328_8592.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100613_235728_000000982090_00188_43328_8593.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100613_062305_000001842090_00177_43317_3862.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100613_070431_000002202090_00178_43318_3868.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100613_080306_000002632090_00178_43318_3891.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100613_085957_000000862090_00179_43319_3893.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100613_103226_000003672090_00180_43320_3917.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100613_104116_000000862090_00180_43320_3916.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100613_121157_000005442090_00181_43321_3933.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100613_130403_000003302090_00181_43321_3952.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100613_132332_000000982090_00181_43321_3954.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100613_134825_000001282090_00182_43322_3942.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100613_153012_000004532090_00183_43323_3976.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100613_170507_000004162090_00184_43324_3992.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100613_171305_000002082090_00184_43324_3993.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100613_184639_000005382090_00185_43325_4018.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100613_202458_000001162090_00186_43326_4033.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100613_202458_000001162090_00186_43326_4034.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100613_202458_000001162090_00186_43326_4036.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100613_202719_000004712090_00186_43326_4043.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100613_235028_000001472090_00188_43328_4052.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

AUXILIARY FILES ANALYSIS completed

#####

MODULE STEPPING ANALYSIS

#####

Analysis will be performed from 2010-06-13 00:00:00 to 2010-06-13 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_100613/MODULE_STEPPING

Creating directory ./RESULTS/DAILY/_100613/MODULE_STEPPING...
Creating directory ./RESULTS/DAILY/_100613/MODULE_STEPPING/FIRST_REFERENCE...
Creating directory ./RESULTS/DAILY/_100613/MODULE_STEPPING/SECOND_REFERENCE...
Creating directory ./RESULTS/DAILY/_100613/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE...
Deleting old files...

Creating images comparing with second reference...

Exporting results to the directory ../../RESULTS/DAILY/_100613/MODULE_STEPPING/SECOND_REFERENCE...

Polarization: H
Reference product: ASA_MS__0PNPDK20010209_135042_0000009A024_00180_11700_0052.N1
Test product: ASA_MS__0PNPDK20100613_061209_000000162090_00177_43317_0143.N1

H
H
../../RESULTS/DAILY/_100613/MODULE_STEPPING/SECOND_REFERENCE/TGH_20100613_061209-20010209_135042.png
../../RESULTS/DAILY/_100613/MODULE_STEPPING/SECOND_REFERENCE/TPH_20100613_061209-20010209_135042.png
../../RESULTS/DAILY/_100613/MODULE_STEPPING/SECOND_REFERENCE/RGH_20100613_061209-20010209_135042.png
../../RESULTS/DAILY/_100613/MODULE_STEPPING/SECOND_REFERENCE/RPH_20100613_061209-20010209_135042.png

Polarization: V
Reference product: ASA_MS__0PNPDK20010209_140823_0000009A024_00180_11700_0054.N1
Test product: ASA_MS__0PNPDK20100612_064346_000000162090_00163_43303_0142.N1

V
V
../../RESULTS/DAILY/_100613/MODULE_STEPPING/SECOND_REFERENCE/TGV_20100612_064346-20010209_140823.png
../../RESULTS/DAILY/_100613/MODULE_STEPPING/SECOND_REFERENCE/TPV_20100612_064346-20010209_140823.png
../../RESULTS/DAILY/_100613/MODULE_STEPPING/SECOND_REFERENCE/RGV_20100612_064346-20010209_140823.png
../../RESULTS/DAILY/_100613/MODULE_STEPPING/SECOND_REFERENCE/RPV_20100612_064346-20010209_140823.png

Creating images comparing with previous product reference...

Exporting results to the directory ../../RESULTS/DAILY/_100613/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE...

Polarization: H
Reference product: ASA_MS__0PNPDK20100611_071523_000000162090_00149_43289_0141.N1
Test product: ASA_MS__0PNPDK20100613_061209_000000162090_00177_43317_0143.N1

H
H
../../RESULTS/DAILY/_100613/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TGH_20100613_061209-20100611_071523.png
../../RESULTS/DAILY/_100613/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TPH_20100613_061209-20100611_071523.png
../../RESULTS/DAILY/_100613/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RGH_20100613_061209-20100611_071523.png
../../RESULTS/DAILY/_100613/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RPH_20100613_061209-20100611_071523.png

Polarization: V
Reference product: ASA_MS__0PNPDK20100610_074700_000000162090_00135_43275_0140.N1
Test product: ASA_MS__0PNPDK20100612_064346_000000162090_00163_43303_0142.N1

V
V
../../RESULTS/DAILY/_100613/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TGV_20100612_064346-20100610_074700.png
../../RESULTS/DAILY/_100613/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TPV_20100612_064346-20100610_074700.png
../../RESULTS/DAILY/_100613/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RGV_20100612_064346-20100610_074700.png
../../RESULTS/DAILY/_100613/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RPV_20100612_064346-20100610_074700.png

MODULE_STEPPING ANALYSIS completed

#####

CALIBRATION PULSES ANALYSIS

#####

Creating directory ./RESULTS/DAILY/_100613/CALIBRATION_PULSES...

ALL ROWS Analysis will be performed from 2010-06-13 00:00:00 to 2010-06-13 23:59:59

Analysing products WVS IS2 V/V

Writing image ../../RESULTS/DAILY/_100613//CALIBRATION_PULSES/Calibration_pulses_all_rows_WVS_IS2_VV.png...

Analysing products GM1 SS3 H/H

Writing image ../../RESULTS/DAILY/_100613//CALIBRATION_PULSES/Calibration_pulses_all_rows_GM1_SS3_HH.png...

TEMPORAL EVOLUTION Analysis will be performed from 2010-06-13 00:00:00 to 2010-06-13 23:59:59

Analysing products WVS IS2 V/V

Getting calibration pulses data for WVS IS2 V/V from 2010-06-13 00:00:00 to 2010-06-13 23:59:59. Rows: 1/5/9/13/17/21/25/29

Writing file ./RESULTS/DAILY/_100613/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2010-06-13_1.dat...

Writing ../../RESULTS/DAILY/_100613//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_1.png...

Writing ../../RESULTS/DAILY/_100613//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_1.png...

Getting calibration pulses data for WVS IS2 V/V from 2010-06-13 00:00:00 to 2010-06-13 23:59:59. Rows: 2/6/10/14/18/22/26/30

Writing file ./RESULTS/DAILY/_100613/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2010-06-13_2.dat...

Writing ../../RESULTS/DAILY/_100613//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_2.png...

Writing ../../RESULTS/DAILY/_100613//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_2.png...

Getting calibration pulses data for WVS IS2 V/V from 2010-06-13 00:00:00 to 2010-06-13 23:59:59. Rows: 3/7/11/15/19/23/27/31

Writing file ./RESULTS/DAILY/_100613/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2010-06-13_3.dat...

Writing ../../RESULTS/DAILY/_100613//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_3.png...

Writing ../../RESULTS/DAILY/_100613//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_3.png...

Getting calibration pulses data for WVS IS2 V/V from 2010-06-13 00:00:00 to 2010-06-13 23:59:59. Rows: 4/8/12/16/20/24/28/32

Writing file ./RESULTS/DAILY/_100613/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2010-06-13_4.dat...

Writing ../../RESULTS/DAILY/_100613//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_4.png...

Writing ../../RESULTS/DAILY/_100613//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_4.png...

Analysing products GM1 SS3 H/H

Getting calibration pulses data for GM1 SS3 H/H from 2010-06-13 00:00:00 to 2010-06-13 23:59:59. Rows: 1/5/9/13/17/21/25/29

Writing file ./RESULTS/DAILY/_100613/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2010-06-13_1.dat...

Writing ../../RESULTS/DAILY/_100613//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_1.png...

Writing ../../RESULTS/DAILY/_100613//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_1.png...

Getting calibration pulses data for GM1 SS3 H/H from 2010-06-13 00:00:00 to 2010-06-13 23:59:59. Rows: 2/6/10/14/18/22/26/30

Writing file ./RESULTS/DAILY/_100613/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2010-06-13_2.dat...

Writing ../../RESULTS/DAILY/_100613//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_2.png...

Writing ../../RESULTS/DAILY/_100613//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_2.png...

Getting calibration pulses data for GM1 SS3 H/H from 2010-06-13 00:00:00 to 2010-06-13 23:59:59. Rows: 3/7/11/15/19/23/27/31

Writing file ./RESULTS/DAILY/_100613/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2010-06-13_3.dat...

Writing ../../RESULTS/DAILY/_100613//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_3.png...

Writing ../../RESULTS/DAILY/_100613//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_3.png...



Getting calibration pulses data for GM1 SS3 H/H from 2010-06-13 00:00:00 to 2010-06-13 23:59:59. Rows: 4/8/12/16/20/24/28/32
Writing file ./RESULTS/DAILY/_100613/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2010-06-13_4.dat...
Writing ../../RESULTS/DAILY/_100613//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_4.png...
Writing ../../RESULTS/DAILY/_100613//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_4.png...

CALIBRATION PULSES ANALYSIS completed

#####

DOPPLER ANALYSIS

#####

Creating directory ./RESULTS/DAILY/_100613/DOPPLER...

DOPPLER ANX Analysis will be performed from 2010-06-13 00:00:00 to 2010-06-13 23:59:59

Analysing products WVS IS2 V/V

Getting doppler data for WVS IS2 V/V from 2010-06-13 00:00:00 to 2010-06-13 23:59:59...

Writing file ./RESULTS/DAILY/_100613/DOPPLER/Doppler_data_WVS_IS2_VV_2010-06-13.dat...

Running IDL program...

Writing file ../../RESULTS/DAILY/_100613/DOPPLER/DOPPLER_ANX_WVS_IS2_VV.png...

Analysing products GM1 SS1 H/H

Getting doppler data for GM1 SS1 H/H from 2010-06-13 00:00:00 to 2010-06-13 23:59:59...

Writing file ./RESULTS/DAILY/_100613/DOPPLER/Doppler_data_GM1_SS1_HH_2010-06-13.dat...

Running IDL program...

Writing file ../../RESULTS/DAILY/_100613/DOPPLER/DOPPLER_ANX_GM1_SS1_HH.png...

DOPPLER JUMPS Analysis will be performed on WSM products from 2010-06-13 00:00:00 to 2010-06-13 23:59:59

Analysing by default products WSM

Getting doppler jumps data for WSM from 2010-06-13 00:00:00 to 2010-06-13 23:59:59...

Writing file ./RESULTS/DAILY/_100613/DOPPLER/Doppler_Jumps_data_WSM_2010-06-13.dat...

Running IDL program...

Writing file ../../RESULTS/DAILY/_100613/DOPPLER/DOPPLER_JUMPS_ANX_WSM.png...

Writing file ../../RESULTS/DAILY/_100613/DOPPLER/DOPPLER_JUMPS_Date_WSM.png...

DOPPLER MAP Analysis will be performed from 2010-06-13 00:00:00 to 2010-06-13 23:59:59

Analysing products WVS IS2 V/V

Loading predicted doppler values....

Phase: descending

Found data...

Computing mean error doppler estimated-predicted...

Mean error = -23.403706 Hz

Writing file ../../RESULTS/DAILY/_100613//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_WVS_IS2_VV_desc.jpg...

Writing file ../../RESULTS/DAILY/_100613//DOPPLER/DOPPLER_Absolute_WVS_IS2_VV_desc.jpg...

Loading predicted doppler values....

Phase: ascending

Found data...

Computing mean error doppler estimated-predicted...

Mean error = -27.327601 Hz

Writing file ../../RESULTS/DAILY/_100613//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_WVS_IS2_VV_asc.jpg...

Writing file ../../RESULTS/DAILY/_100613//DOPPLER/DOPPLER_Absolute_WVS_IS2_VV_asc.jpg...

Analysing products GM1 SS1 H/H
Loading predicted doppler values....
Phase: descending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = 3.4455122 Hz
Writing file ../../RESULTS/DAILY/_100613//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_GM1_SS1_HH_desc.jpg...
Writing file ../../RESULTS/DAILY/_100613//DOPPLER/DOPPLER_Absolute_GM1_SS1_HH_desc.jpg...

Loading predicted doppler values....
Phase: ascending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -10.425034 Hz
Writing file ../../RESULTS/DAILY/_100613//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_GM1_SS1_HH_asc.jpg...
Writing file ../../RESULTS/DAILY/_100613//DOPPLER/DOPPLER_Absolute_GM1_SS1_HH_asc.jpg...

DOPPLER ANALYSIS completed
#####

CHIRP ANALYSIS

Creating directory ./RESULTS/DAILY/_100613/CHIRP...

CHIRP Analysis will be performed from 2010-06-13 00:00:00 to 2010-06-13 23:59:59

Analysing products WSM SS1 H/H

Getting ScaleFactor data for WSM SS1 H/H from 2010-06-13 00:00:00 to 2010-06-13 23:59:59...
Writing file ./RESULTS/DAILY/_100613/CHIRP/ScaleFactor_data_WSM_SS1_HH_2010-06-13.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/_100613/CHIRP/ScaleFactor_ANX_WSM_SS1_HH.png...
Writing file ../../RESULTS/DAILY/_100613/CHIRP/ScaleFactor_DATE_WSM_SS1_HH.png...

Analysing products WSM SS1 V/V

Getting ScaleFactor data for WSM SS1 V/V from 2010-06-13 00:00:00 to 2010-06-13 23:59:59...
Writing file ./RESULTS/DAILY/_100613/CHIRP/ScaleFactor_data_WSM_SS1_VV_2010-06-13.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/_100613/CHIRP/ScaleFactor_ANX_WSM_SS1_VV.png...
Writing file ../../RESULTS/DAILY/_100613/CHIRP/ScaleFactor_DATE_WSM_SS1_VV.png...

CHIRP ANALYSIS completed
#####

RAW DATA ANALYSIS

Analysis will be performed from 2010-06-13 00:00:00 to 2010-06-13 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_100613/RAW_DATA

Creating directory ./RESULTS/DAILY/_100613/RAW_DATA...

Getting raw data for WVS from 2010-06-13 00:00:00 to 2010-06-13 23:59:59...
Writing file ./RESULTS/DAILY/_100613/RAW_DATA/Raw_data_WVS_2010-06-13.dat...
Running IDL program to create graphs...

Creating image ../../RESULTS/DAILY/_100613/RAW_DATA/Raw_data_WVS_input_mean.png...
Creating image ../../RESULTS/DAILY/_100613/RAW_DATA/Raw_data_WVS_input_stdev.png...
Creating image ../../RESULTS/DAILY/_100613/RAW_DATA/Raw_data_WVS_gain_imbalance.png...

Getting raw data for IMM from 2010-06-13 00:00:00 to 2010-06-13 23:59:59...
Writing file ./RESULTS/DAILY/_100613/RAW_DATA/Raw_data_IMM_2010-06-13.dat...
Running IDL program to create graphs...

Creating image ../../RESULTS/DAILY/_100613/RAW_DATA/Raw_data_IMM_input_mean.png...
Creating image ../../RESULTS/DAILY/_100613/RAW_DATA/Raw_data_IMM_input_stdev.png...
Creating image ../../RESULTS/DAILY/_100613/RAW_DATA/Raw_data_IMM_gain_imbalance.png...

RAW DATA ANALYSIS completed
#####

TELEMETRY ANALYSIS

Analysis will be performed from 2010-06-13 00:00:00 to 2010-06-13 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_100613/TELEMETRY

Creating directory ./RESULTS/DAILY/_100613/TELEMETRY...

Looking for gaps and missing lines in WVS products...

Checking 24 products from PDE...
Checking 28 products from PDK...

Looking for gaps and missing lines in GM1 products...

Checking 24 products from PDE...
Checking 51 products from PDK...

Looking for gaps and missing lines in APM products...

Checking 4 products from PDE...
Checking 1 products from PDK...

Looking for gaps and missing lines in IMM products...

Checking 17 products from PDE...
Checking 7 products from PDK...

Looking for gaps and missing lines in WSM products...

Checking 38 products from PDE...
Found product...ASA_WSM_1PNPDE20100613_032858_000002452090_00176_43316_8412.N1 / 0 gaps / 39 missing lines
Found product...ASA_WSM_1PNPDE20100613_032858_000002452090_00176_43316_8524.N1 / 0 gaps / 39 missing lines
Found product...ASA_WSM_1PNPDE20100613_183447_000002022090_00185_43325_8539.N1 / 0 gaps / 65 missing lines
Checking 19 products from PDK...
Found product...ASA_WSM_1PNPDK20100613_132332_00000982090_00181_43321_3954.N1 / 0 gaps / 1 missing lines

Creating graph of missing lines and gaps...

Creating image: ./RESULTS/DAILY/_100613/TELEMETRY/TELEMETRY_Missing_lines.png...
Creating image: ./RESULTS/DAILY/_100613/TELEMETRY/TELEMETRY_Gaps.png...

TELEMETRY ANALYSIS completed
#####

HTML REPORT generation
#####

Building file ./RESULTS/DAILY/_100613/asarReport.html...
Building DATA SUMMARY section...
Building AUXILIARY FILES ANALYSIS section...
Building MODULE STEPPING ANALYSIS section...
Building CALIBRATION PULSES ANALYSIS section...
Building DOPPLER ANALYSIS section...
Building CHIRP ANALYSIS section...
Building RAW DATA ANALYSIS section...
Building TELEMETRY ANALYSIS section...

HTML REPORT generation completed
#####



Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
ASA_APM_1PNPDE20100613_051045_000001782090_00177_43317_8417.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20100613_073546_000001732090_00178_43318_8441.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20100613_073857_000000572090_00178_43318_8442.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20100613_172431_000000442090_00184_43324_8536.N1	OK	OK	OK	OK
ASA_APM_1PNPDK20100613_090126_000000432090_00179_43319_3892.N1	OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_GM1_1PNPDE20100613_003127_000003262090_00174_43314_8363.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100613_005327_000005862090_00174_43314_8367.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100613_011023_000006892090_00174_43314_8368.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100613_013655_000004892090_00174_43314_8379.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100613_015612_000002712090_00175_43315_8380.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100613_020425_000010752090_00175_43315_8382.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100613_025059_000006222090_00175_43315_8396.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100613_031110_000001872090_00175_43315_8404.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100613_031423_000007552090_00175_43315_8402.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100613_033315_000006832090_00176_43316_8401.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100613_034528_000009792090_00176_43316_8400.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100613_040745_00000902090_00176_43316_8398.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100613_043134_000005312090_00176_43316_8420.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100613_044549_000001022090_00176_43316_8422.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100613_051610_000001872090_00177_43317_8418.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100613_052155_000012332090_00177_43317_8423.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100613_203625_000000782090_00186_43326_8542.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100613_204100_000001992090_00186_43326_8543.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100613_211734_000006712090_00186_43326_8545.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100613_215137_000005132090_00187_43327_8562.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100613_220846_000001022090_00187_43327_8561.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100613_221450_000001442090_00187_43327_8564.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100613_225811_000005612090_00187_43327_8567.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100613_235912_000004712090_00188_43328_8579.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_061328_000005732090_00177_43317_3849.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_062613_000001142090_00177_43317_3851.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_070814_000003862090_00178_43318_3853.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_070814_000003862090_00178_43318_3857.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_070814_000003862090_00178_43318_3859.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_071351_000001632090_00178_43318_3873.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_071853_000004162090_00178_43318_3874.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_073007_000003382090_00178_43318_3875.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_074015_000001932090_00178_43318_3876.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_075247_000006162090_00178_43318_3878.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_080731_000000722090_00178_43318_3880.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_084357_000007672090_00179_43319_3882.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_085602_000002292090_00179_43319_3900.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_090230_00000902090_00179_43319_3901.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_090718_000002052090_00179_43319_3902.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_093324_000005792090_00179_43319_3903.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_094812_000000662090_00179_43319_3905.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_102557_000008842090_00180_43320_3906.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_102956_000001442090_00180_43320_3907.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_105028_000002232090_00180_43320_3920.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_111359_000005672090_00180_43320_3922.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_112830_00000842090_00180_43320_3923.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_120304_000005252090_00181_43321_3925.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_123808_000005732090_00181_43321_3935.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_125435_000005612090_00181_43321_3937.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_131629_000004162090_00181_43321_3938.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_132516_000001572090_00181_43321_3941.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_133842_000005792090_00182_43322_3944.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_135041_000001692090_00182_43322_3949.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_135242_000006712090_00182_43322_3956.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_141503_000002712090_00182_43322_3957.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_142114_000001202090_00182_43322_3959.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_143510_000009612090_00182_43322_3963.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_145811_000002052090_00182_43322_3962.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_150542_000001872090_00182_43322_3964.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_151043_000011602090_00183_43323_3967.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_154437_000003022090_00183_43323_3979.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_155242_000000722090_00183_43323_3980.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_161546_000007732090_00183_43323_3982.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_165109_000003982090_00184_43324_3983.N1					OK	OK	OK	OK

ASA_GM1_1PNPDK20100613_165924_000001992090_00184_43324_3985.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_171640_000000722090_00184_43324_4003.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_171845_000001022090_00184_43324_4002.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_172232_000001142090_00184_43324_4004.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_172537_000001202090_00184_43324_4005.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_175622_000007792090_00184_43324_4007.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_183809_000005012090_00185_43325_4008.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_183809_000005012090_00185_43325_4010.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_185544_000004772090_00185_43325_4029.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_193658_000006162090_00185_43325_4032.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100613_200318_000009062090_00185_43325_4039.N1	OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_IMM_1PNPDE20100613_002147_000002382090_00174_43314_8375.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100613_022314_000001682090_00175_43315_8434.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100613_022631_000000832090_00175_43315_8435.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100613_040148_000003462090_00176_43316_8394.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100613_051452_000000682090_00177_43317_8428.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100613_051916_000001462090_00177_43317_8432.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100613_054248_000001502090_00177_43317_8437.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100613_054630_000001062090_00177_43317_8495.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100613_091040_000003002090_00179_43319_8469.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100613_104822_000001142090_00180_43320_8497.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100613_155357_000000332090_00183_43323_8532.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100613_155357_000000332090_00183_43323_8537.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100613_165746_000000872090_00184_43324_8529.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100613_171754_000000392090_00184_43324_8534.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100613_172741_000002932090_00184_43324_8538.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100613_190342_000001332090_00185_43325_8541.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100613_220217_000000372090_00187_43327_8554.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20100613_070158_000000922090_00178_43318_3863.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20100613_083045_000000692090_00179_43319_3887.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20100613_104248_000000532090_00180_43320_3918.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20100613_133514_000000682090_00182_43322_3955.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20100613_202325_000000192090_00186_43326_4026.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20100613_202358_000000372090_00186_43326_4027.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20100613_221031_000002522090_00187_43327_4049.N1					OK	OK	OK	OK


Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WSM_1PNPDE20100613_001856_000001472090_00174_43314_8361.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100613_002617_000003062090_00174_43314_8377.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100613_012200_000002752090_00174_43314_8393.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100613_020048_000002142090_00175_43315_8436.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100613_023037_000005082090_00175_43315_8389.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100613_030128_000002942090_00175_43315_8411.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100613_032858_000002452090_00176_43316_8412.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100613_032858_000002452090_00176_43316_8524.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100613_044034_000002202090_00176_43316_8414.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100613_044432_000000672090_00176_43316_8415.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100613_071643_000001282090_00178_43318_8439.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100613_072558_000002452090_00178_43318_8440.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100613_074331_000002692090_00178_43318_8443.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100613_085957_000000922090_00179_43319_8468.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100613_094309_000003002090_00179_43319_8500.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100613_102142_000002452090_00180_43320_8501.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100613_102734_000001282090_00180_43320_8503.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100613_112332_000002942090_00180_43320_8522.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100613_141938_000000922090_00182_43322_8525.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100613_153630_000001282090_00183_43323_8527.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100613_154005_000002692090_00183_43323_8528.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100613_154943_000001472090_00183_43323_8531.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100613_162844_000001282090_00183_43323_8526.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100613_170249_000001652090_00184_43324_8530.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100613_172036_000001102090_00184_43324_8535.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100613_180930_000001162090_00184_43324_8533.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100613_183447_000002022090_00185_43325_8539.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100613_194719_000002812090_00185_43325_8540.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100613_203436_000001042090_00186_43326_8556.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100613_203756_000001772090_00186_43326_8557.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100613_212848_000003062090_00186_43326_8553.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100613_214111_000001712090_00186_43326_8558.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100613_220338_000000862090_00187_43327_8555.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100613_221721_000004592090_00187_43327_8627.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100613_230741_000004162090_00187_43327_8574.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100613_234745_000002142090_00188_43328_8577.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100613_235155_000002942090_00188_43328_8592.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100613_235728_000000982090_00188_43328_8593.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100613_062305_000001842090_00177_43317_3862.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100613_070431_000002202090_00178_43318_3868.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100613_080306_000002632090_00178_43318_3891.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100613_085957_000000862090_00179_43319_3893.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100613_103226_000003672090_00180_43320_3917.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100613_104116_000000862090_00180_43320_3916.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100613_121157_000005442090_00181_43321_3933.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100613_130403_000003302090_00181_43321_3952.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100613_132332_000000982090_00181_43321_3954.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100613_134825_000001282090_00182_43322_3942.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100613_153012_000004532090_00183_43323_3976.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100613_170507_000004162090_00184_43324_3992.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100613_171305_000002082090_00184_43324_3993.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100613_184639_000005382090_00185_43325_4018.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100613_202458_000001162090_00186_43326_4033.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100613_202458_000001162090_00186_43326_4034.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100613_202458_000001162090_00186_43326_4036.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100613_202719_000004712090_00186_43326_4043.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100613_235028_000001472090_00188_43328_4052.N1					OK	OK	OK	OK


Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WVS_1PNPDE20100613_003656_000009472090_00174_43314_8364.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100613_010315_000003902090_00174_43314_8366.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100613_012634_000002252090_00174_43314_8369.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100613_012934_000003002090_00174_43314_8378.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100613_014508_000006292090_00175_43315_8381.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100613_023904_000002392090_00175_43315_8383.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100613_024249_000004502090_00175_43315_8395.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100613_030654_000002102090_00175_43315_8403.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100613_032703_000000742090_00176_43316_8399.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100613_040920_000009592090_00176_43316_8397.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100613_042505_000000902090_00176_43316_8421.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100613_042933_000000752090_00176_43316_8419.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100613_044739_000012892090_00176_43316_8426.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100613_054822_000010792090_00177_43317_8425.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100613_204418_000019492090_00186_43326_8544.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100613_213351_000003142090_00186_43326_8546.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100613_213821_000001202090_00186_43326_8559.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100613_214359_000004192090_00186_43326_8560.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100613_220511_000001652090_00187_43327_8563.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100613_222501_000019492090_00187_43327_8565.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100613_231434_000003152090_00187_43327_8566.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100613_231904_000013192090_00187_43327_8575.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100613_234223_000002702090_00188_43328_8576.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100613_060606_000003302090_00177_43317_3850.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100613_062815_000019642090_00177_43317_3852.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100613_074759_000002402090_00178_43318_3877.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100613_080851_000012742090_00178_43318_3879.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100613_083200_000006742090_00179_43319_3881.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100613_091545_000010192090_00179_43319_3904.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100613_094927_000018892090_00179_43319_3908.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100613_103845_000001052090_00180_43320_3919.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100613_105414_000011392090_00180_43320_3921.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100613_113003_000019342090_00180_43320_3924.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100613_122105_000009742090_00181_43321_3934.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100613_124741_000003752090_00181_43321_3936.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100613_131030_000003152090_00181_43321_3939.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100613_132757_000002992090_00182_43322_3940.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100613_133629_000000892090_00182_43322_3947.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100613_140356_000006292090_00182_43322_3958.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100613_142318_000006752090_00182_43322_3960.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100613_145115_000003752090_00182_43322_3961.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100613_150139_000001942090_00182_43322_3965.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100613_150850_000000742090_00183_43323_3966.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100613_155449_000012142090_00183_43323_3981.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100613_163142_000011242090_00183_43323_3986.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100613_173241_000013792090_00184_43324_4006.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100613_181630_000009892090_00184_43324_4009.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100613_181630_000009892090_00184_43324_4011.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100613_190601_000018142090_00185_43325_4031.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100613_195254_000001202090_00185_43325_4030.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100613_195705_000003302090_00185_43325_4038.N1					OK	OK	OK	OK


Calibration pulses for GM1 SS3 H/H




Calibration pulses for GM1 SS3 H/H




13-Jun



13-Jun




13-Jun




13-Jun

rows: _ 2 _ 6 _ 10 _ 14 _ 18 _ 22 _ 26 _ 30


Calibration pulses for GM1 SS3 H/H




13-Jun



13-Jun




13-Jun




rows: _ 3 _ 7 _ 11 _ 15 _ 19 _ 23 _ 27 _ 31


Calibration pulses for GM1 SS3 H/H




13-Jun



13-Jun




13-Jun




13-Jun

rows: _ 4 _ 8 _ 12 _ 16 _ 20 _ 24 _ 28 _ 32





Calibration pulses for WVS IS2 V/V



Calibration pulses for WVS IS2 V/V








Calibration pulses for WVS IS2 V/V






rows: _ 3 _ 7 _ 11 _ 15 _ 19 **13-Jun** _ 23 _ 27 _ 31



Calibration pulses for WVS IS2 V/V



















13-Jun
rows: _ 2 _ 6 _ 10 _ 14 _ 18 _ 22 _ 26 _ 30










13-Jun
rows: _ 4 _ 8 _ 12 _ 16 _ 20 _ 24 _ 28 _ 32




















Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_APM_1PNPDE20100613_051045_000001782090_00177_43317_8417.N1						IS4	V/V	90	43317	177	5.03
ASA_APM_1PNPDE20100613_073546_000001732090_00178_43318_8441.N1						IS4	V/V	90	43318	178	5.03
ASA_APM_1PNPDE20100613_073857_000000572090_00178_43318_8442.N1						IS4	V/H	90	43318	178	5.03
ASA_APM_1PNPDK20100613_090126_000000432090_00179_43319_3892.N1						IS6	H/H	90	43319	179	5.03
ASA_APM_1PNPDE20100613_172431_000000442090_00184_43324_8536.N1						IS3	H/H	90	43324	184	5.03

Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_GM1_1PNPDE20100613_003127_000003262090_00174_43314_8363.N1						SS1	H/H	90	43314	174	5.03
ASA_GM1_1PNPDE20100613_005327_000005862090_00174_43314_8367.N1						SS1	H/H	90	43314	174	5.03
ASA_GM1_1PNPDE20100613_011023_000006892090_00174_43314_8368.N1						SS1	H/H	90	43314	174	5.03
ASA_GM1_1PNPDE20100613_013655_000004892090_00174_43314_8379.N1						SS1	H/H	90	43314	174	5.03
ASA_GM1_1PNPDE20100613_015612_000002712090_00175_43315_8380.N1						SS1	H/H	90	43315	175	5.03
ASA_GM1_1PNPDE20100613_020425_000010752090_00175_43315_8382.N1						SS1	H/H	90	43315	175	5.03
ASA_GM1_1PNPDE20100613_025059_000006222090_00175_43315_8396.N1						SS1	H/H	90	43315	175	5.03
ASA_GM1_1PNPDE20100613_031110_000001872090_00175_43315_8404.N1						SS1	H/H	90	43315	175	5.03
ASA_GM1_1PNPDE20100613_031423_000007552090_00175_43315_8402.N1						SS1	H/H	90	43315	175	5.03
ASA_GM1_1PNPDE20100613_033315_000006832090_00176_43316_8401.N1						SS1	H/H	90	43316	176	5.03
ASA_GM1_1PNPDE20100613_034528_000009792090_00176_43316_8400.N1						SS1	H/H	90	43316	176	5.03
ASA_GM1_1PNPDE20100613_040745_000000902090_00176_43316_8398.N1						SS1	H/H	90	43316	176	5.03
ASA_GM1_1PNPDE20100613_043134_000005312090_00176_43316_8420.N1						SS1	H/H	90	43316	176	5.03
ASA_GM1_1PNPDE20100613_044549_000001022090_00176_43316_8422.N1						SS1	H/H	90	43316	176	5.03
ASA_GM1_1PNPDE20100613_051610_000001872090_00177_43317_8418.N1						SS1	H/H	90	43317	177	5.03
ASA_GM1_1PNPDE20100613_052155_000012332090_00177_43317_8423.N1						SS1	H/H	90	43317	177	5.03
ASA_GM1_1PNPDK20100613_061328_000005732090_00177_43317_3849.N1						SS1	H/H	90	43317	177	5.03
ASA_GM1_1PNPDK20100613_062613_000001142090_00177_43317_3851.N1						SS1	H/H	90	43317	177	5.03
ASA_GM1_1PNPDK20100613_070814_000003862090_00178_43318_3859.N1						SS1	H/H	90	43318	178	5.03
ASA_GM1_1PNPDK20100613_070814_000003862090_00178_43318_3853.N1						SS1	H/H	90	43318	178	5.03
ASA_GM1_1PNPDK20100613_070814_000003862090_00178_43318_3857.N1						SS1	H/H	90	43318	178	5.03
ASA_GM1_1PNPDK20100613_071351_000001632090_00178_43318_3873.N1						SS1	H/H	90	43318	178	5.03
ASA_GM1_1PNPDK20100613_071853_000004162090_00178_43318_3874.N1						SS1	H/H	90	43318	178	5.03
ASA_GM1_1PNPDK20100613_073007_000003382090_00178_43318_3875.N1						SS1	H/H	90	43318	178	5.03
ASA_GM1_1PNPDK20100613_074015_000001932090_00178_43318_3876.N1						SS1	H/H	90	43318	178	5.03
ASA_GM1_1PNPDK20100613_075247_000006162090_00178_43318_3878.N1						SS1	H/H	90	43318	178	5.03
ASA_GM1_1PNPDK20100613_080731_000000722090_00178_43318_3880.N1						SS1	H/H	90	43318	178	5.03
ASA_GM1_1PNPDK20100613_084357_000007672090_00179_43319_3882.N1						SS1	H/H	90	43319	179	5.03
ASA_GM1_1PNPDK20100613_085602_000002292090_00179_43319_3900.N1						SS1	H/H	90	43319	179	5.03
ASA_GM1_1PNPDK20100613_090230_000000902090_00179_43319_3901.N1						SS1	H/H	90	43319	179	5.03
ASA_GM1_1PNPDK20100613_090718_000002052090_00179_43319_3902.N1						SS1	H/H	90	43319	179	5.03
ASA_GM1_1PNPDK20100613_093324_000005792090_00179_43319_3903.N1						SS1	H/H	90	43319	179	5.03
ASA_GM1_1PNPDK20100613_094812_000000662090_00179_43319_3905.N1						SS1	H/H	90	43319	179	5.03
ASA_GM1_1PNPDK20100613_102557_000000842090_00180_43320_3906.N1						SS1	H/H	90	43320	180	5.03
ASA_GM1_1PNPDK20100613_102956_000001442090_00180_43320_3907.N1						SS1	H/H	90	43320	180	5.03
ASA_GM1_1PNPDK20100613_105028_000002232090_00180_43320_3920.N1						SS1	H/H	90	43320	180	5.03
ASA_GM1_1PNPDK20100613_111359_000005672090_00180_43320_3922.N1						SS1	H/H	90	43320	180	5.03
ASA_GM1_1PNPDK20100613_112830_000000842090_00180_43320_3923.N1						SS1	H/H	90	43320	180	5.03
ASA_GM1_1PNPDK20100613_120304_000005252090_00181_43321_3925.N1						SS1	H/H	90	43321	181	5.03
ASA_GM1_1PNPDK20100613_123808_000005732090_00181_43321_3935.N1						SS1	H/H	90	43321	181	5.03
ASA_GM1_1PNPDK20100613_125435_000005612090_00181_43321_3937.N1						SS1	H/H	90	43321	181	5.03
ASA_GM1_1PNPDK20100613_131629_000004162090_00181_43321_3938.N1						SS1	H/H	90	43321	181	5.03
ASA_GM1_1PNPDK20100613_132516_000001572090_00181_43321_3941.N1						SS1	H/H	90	43321	181	5.03
ASA_GM1_1PNPDK20100613_133842_000005792090_00182_43322_3944.N1						SS1	H/H	90	43322	182	5.03
ASA_GM1_1PNPDK20100613_135041_000001692090_00182_43322_3949.N1						SS1	H/H	90	43322	182	5.03
ASA_GM1_1PNPDK20100613_135242_000006712090_00182_43322_3956.N1						SS1	H/H	90	43322	182	5.03
ASA_GM1_1PNPDK20100613_141503_000002712090_00182_43322_3957.N1						SS1	H/H	90	43322	182	5.03
ASA_GM1_1PNPDK20100613_142114_000001202090_00182_43322_3959.N1						SS1	H/H	90	43322	182	5.03
ASA_GM1_1PNPDK20100613_143510_000009612090_00182_43322_3963.N1						SS1	H/H	90	43322	182	5.03
ASA_GM1_1PNPDK20100613_145811_000002052090_00182_43322_3962.N1						SS1	H/H	90	43322	182	5.03
ASA_GM1_1PNPDK20100613_150542_000001872090_00182_43322_3964.N1						SS1	H/H	90	43322	182	5.03
ASA_GM1_1PNPDK20100613_151043_000011602090_00183_43323_3967.N1						SS1	H/H	90	43323	183	5.03
ASA_GM1_1PNPDK20100613_154437_000003022090_00183_43323_3979.N1						SS1	H/H	90	43323	183	5.03
ASA_GM1_1PNPDK20100613_155242_000000722090_00183_43323_3980.N1						SS1	H/H	90	43323	183	5.03
ASA_GM1_1PNPDK20100613_161546_000007732090_00183_43323_3982.N1						SS1	H/H	90	43323	183	5.03
ASA_GM1_1PNPDK20100613_165109_000003982090_00184_43324_3983.N1						SS1	H/H	90	43324	184	5.03
ASA_GM1_1PNPDK20100613_165924_000001992090_00184_43324_3985.N1						SS1	H/H	90	43324	184	5.03
ASA_GM1_1PNPDK20100613_171640_000000722090_00184_43324_4003.N1						SS1	H/H	90	43324	184	5.03
ASA_GM1_1PNPDK20100613_171845_000001022090_00184_43324_4002.N1						SS1	H/H	90	43324	184	5.03
ASA_GM1_1PNPDK20100613_172232_000001142090_00184_43324_4004.N1						SS1	H/H	90	43324	184	5.03
ASA_GM1_1PNPDK20100613_172537_000001202090_00184_43324_4005.N1						SS1	H/H	90	43324	184	5.03
ASA_GM1_1PNPDK20100613_175622_000007792090_00184_43324_4007.N1						SS1	H/H	90	43324	184	5.03
ASA_GM1_1PNPDK20100613_183809_000005012090_00185_43325_4008.N1						SS1	H/H	90	43325	185	5.03
ASA_GM1_1PNPDK20100613_183809_000005012090_00185_43325_4010.N1						SS1	H/H	90	43325	185	5.03
ASA_GM1_1PNPDK20100613_185544_000004772090_00185_43325_4029.N1						SS1	H/H	90	43325	185	5.03
ASA_GM1_1PNPDK20100613_193658_000006162090_00185_43325_4032.N1						SS1	H/H	90	43325	185	5.03
ASA_GM1_1PNPDK20100613_200318_000009062090_00185_43325_4039.N1						SS1	H/H	90	43325	185	5.03

ASA_GM1_1PNPDE20100613_203625_000000782090_00186_43326_8542.N1	SS1	H/H	90	43326	186	5.03
ASA_GM1_1PNPDE20100613_204100_000001992090_00186_43326_8543.N1	SS1	H/H	90	43326	186	5.03
ASA_GM1_1PNPDE20100613_211734_000006712090_00186_43326_8545.N1	SS1	H/H	90	43326	186	5.03
ASA_GM1_1PNPDE20100613_215137_000005132090_00187_43327_8562.N1	SS1	H/H	90	43327	187	5.03
ASA_GM1_1PNPDE20100613_220846_000001022090_00187_43327_8561.N1	SS1	H/H	90	43327	187	5.03
ASA_GM1_1PNPDE20100613_221450_000001442090_00187_43327_8564.N1	SS1	H/H	90	43327	187	5.03
ASA_GM1_1PNPDE20100613_225811_000005612090_00187_43327_8567.N1	SS1	H/H	90	43327	187	5.03
ASA_GM1_1PNPDE20100613_235912_000004712090_00188_43328_8579.N1	SS1	H/H	90	43328	188	5.03


Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_IMM_1PNPDE20100613_002147_000002382090_00174_43314_8375.N1						IS2	H/H	90	43314	174	5.03
ASA_IMM_1PNPDE20100613_022314_000001682090_00175_43315_8434.N1						IS2	V/V	90	43315	175	5.03
ASA_IMM_1PNPDE20100613_022631_000000832090_00175_43315_8435.N1						IS2	V/V	90	43315	175	5.03
ASA_IMM_1PNPDE20100613_040148_000003462090_00176_43316_8394.N1						IS2	V/V	90	43316	176	5.03
ASA_IMM_1PNPDE20100613_051452_000000682090_00177_43317_8428.N1						IS2	V/V	90	43317	177	5.03
ASA_IMM_1PNPDE20100613_051916_000001462090_00177_43317_8432.N1						IS2	V/V	90	43317	177	5.03
ASA_IMM_1PNPDE20100613_054248_000001502090_00177_43317_8437.N1						IS2	V/V	90	43317	177	5.03
ASA_IMM_1PNPDE20100613_054630_000001062090_00177_43317_8495.N1						IS2	V/V	90	43317	177	5.03
ASA_IMM_1PNPDK20100613_070158_000000922090_00178_43318_3863.N1						IS2	V/V	90	43318	178	5.03
ASA_IMM_1PNPDK20100613_083045_000000692090_00179_43319_3887.N1						IS6	V/V	90	43319	179	5.03
ASA_IMM_1PNPDE20100613_091040_000003002090_00179_43319_8469.N1						IS2	V/V	90	43319	179	5.03
ASA_IMM_1PNPDK20100613_104248_000000532090_00180_43320_3918.N1						IS2	H/H	90	43320	180	5.03
ASA_IMM_1PNPDE20100613_104822_000001142090_00180_43320_8497.N1						IS2	V/V	90	43320	180	5.03
ASA_IMM_1PNPDK20100613_133514_000000682090_00182_43322_3955.N1						IS3	V/V	90	43322	182	5.03
ASA_IMM_1PNPDE20100613_155357_000000332090_00183_43323_8532.N1						IS2	V/V	90	43323	183	5.03
ASA_IMM_1PNPDE20100613_155357_000000332090_00183_43323_8537.N1						IS2	V/V	90	43323	183	5.03
ASA_IMM_1PNPDE20100613_165746_000000872090_00184_43324_8529.N1						IS6	V/V	90	43324	184	5.03
ASA_IMM_1PNPDE20100613_171754_000000392090_00184_43324_8534.N1						IS4	V/V	90	43324	184	5.03
ASA_IMM_1PNPDE20100613_172741_000002932090_00184_43324_8538.N1						IS2	V/V	90	43324	184	5.03
ASA_IMM_1PNPDE20100613_190342_000001332090_00185_43325_8541.N1						IS2	V/V	90	43325	185	5.03
ASA_IMM_1PNPDK20100613_202325_000000192090_00186_43326_4026.N1						IS2	***	90	43326	186	5.03
ASA_IMM_1PNPDK20100613_202358_000000372090_00186_43326_4027.N1						IS6	H/H	90	43326	186	5.03
ASA_IMM_1PNPDE20100613_220217_000000372090_00187_43327_8554.N1						IS2	V/V	90	43327	187	5.03
ASA_IMM_1PNPDK20100613_221031_000002522090_00187_43327_4049.N1						IS2	H/H	90	43327	187	5.03


Filename	Pol	Timestamp	count(Module)
ASA_MS__0PNPDK20100613_061209_000000162090_00177_43317_0143.N1	H	2010-06-13 06:12:09	320





Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WSM_1PNPDE20100613_001856_000001472090_00174_43314_8361.N1						SS1	H/H	90	43314	174	5.03
ASA_WSM_1PNPDE20100613_002617_000003062090_00174_43314_8377.N1						SS1	H/H	90	43314	174	5.03
ASA_WSM_1PNPDE20100613_012200_000002752090_00174_43314_8393.N1						SS1	H/H	90	43314	174	5.03
ASA_WSM_1PNPDE20100613_020048_000002142090_00175_43315_8436.N1						SS1	H/H	90	43315	175	5.03
ASA_WSM_1PNPDE20100613_023037_000005082090_00175_43315_8389.N1						SS1	V/V	90	43315	175	5.03
ASA_WSM_1PNPDE20100613_030128_000002942090_00175_43315_8411.N1						SS1	H/H	90	43315	175	5.03
ASA_WSM_1PNPDE20100613_032858_000002452090_00176_43316_8524.N1						SS1	V/V	90	43316	176	5.03
ASA_WSM_1PNPDE20100613_032858_000002452090_00176_43316_8412.N1						SS1	V/V	90	43316	176	5.03
ASA_WSM_1PNPDE20100613_044034_000002202090_00176_43316_8414.N1						SS1	H/H	90	43316	176	5.03
ASA_WSM_1PNPDE20100613_044432_000000672090_00176_43316_8415.N1						SS1	H/H	90	43316	176	5.03
ASA_WSM_1PNPDK20100613_062305_000001842090_00177_43317_3862.N1						SS1	H/H	90	43317	177	5.03
ASA_WSM_1PNPDK20100613_070431_000002202090_00178_43318_3868.N1						SS1	H/H	90	43318	178	5.03
ASA_WSM_1PNPDE20100613_071643_000001282090_00178_43318_8439.N1						SS1	H/H	90	43318	178	5.03
ASA_WSM_1PNPDE20100613_072558_000002452090_00178_43318_8440.N1						SS1	V/V	90	43318	178	5.03
ASA_WSM_1PNPDE20100613_074331_000002692090_00178_43318_8443.N1						SS1	V/V	90	43318	178	5.03
ASA_WSM_1PNPDK20100613_080306_000002632090_00178_43318_3891.N1						SS1	H/H	90	43318	178	5.03
ASA_WSM_1PNPDK20100613_085957_000000862090_00179_43319_3893.N1						SS1	V/V	90	43319	179	5.03
ASA_WSM_1PNPDE20100613_085957_000000922090_00179_43319_8468.N1						SS1	V/V	90	43319	179	5.03
ASA_WSM_1PNPDE20100613_094309_000003002090_00179_43319_8500.N1						SS1	H/H	90	43319	179	5.03
ASA_WSM_1PNPDE20100613_102142_000002452090_00180_43320_8501.N1						SS1	H/H	90	43320	180	5.03
ASA_WSM_1PNPDE20100613_102734_000001282090_00180_43320_8503.N1						SS1	H/H	90	43320	180	5.03
ASA_WSM_1PNPDK20100613_103226_000003672090_00180_43320_3917.N1						SS1	H/H	90	43320	180	5.03
ASA_WSM_1PNPDK20100613_104116_000000862090_00180_43320_3916.N1						SS1	V/V	90	43320	180	5.03
ASA_WSM_1PNPDE20100613_112332_000002942090_00180_43320_8522.N1						SS1	H/H	90	43320	180	5.03
ASA_WSM_1PNPDK20100613_121157_000005442090_00181_43321_3933.N1						SS1	H/H	90	43321	181	5.03
ASA_WSM_1PNPDK20100613_130403_000003302090_00181_43321_3952.N1						SS1	H/H	90	43321	181	5.03
ASA_WSM_1PNPDK20100613_132332_000000982090_00181_43321_3954.N1						SS1	V/V	90	43321	181	5.03
ASA_WSM_1PNPDK20100613_134825_000001282090_00182_43322_3942.N1						SS1	H/H	90	43322	182	5.03
ASA_WSM_1PNPDE20100613_141938_000000922090_00182_43322_8525.N1						SS1	V/V	90	43322	182	5.03
ASA_WSM_1PNPDK20100613_153012_000004532090_00183_43323_3976.N1						SS1	H/H	90	43323	183	5.03
ASA_WSM_1PNPDE20100613_153630_000001282090_00183_43323_8527.N1						SS1	H/H	90	43323	183	5.03
ASA_WSM_1PNPDE20100613_154005_000002692090_00183_43323_8528.N1						SS1	H/H	90	43323	183	5.03
ASA_WSM_1PNPDE20100613_154943_000001472090_00183_43323_8531.N1						SS1	V/V	90	43323	183	5.03
ASA_WSM_1PNPDE20100613_162844_000001282090_00183_43323_8526.N1						SS1	H/H	90	43323	183	5.03
ASA_WSM_1PNPDE20100613_170249_000001652090_00184_43324_8530.N1						SS1	H/H	90	43324	184	5.03
ASA_WSM_1PNPDK20100613_170507_000004162090_00184_43324_3992.N1						SS1	H/H	90	43324	184	5.03
ASA_WSM_1PNPDK20100613_171305_000002082090_00184_43324_3993.N1						SS1	H/H	90	43324	184	5.03
ASA_WSM_1PNPDE20100613_172036_000001102090_00184_43324_8535.N1						SS1	H/H	90	43324	184	5.03
ASA_WSM_1PNPDE20100613_180930_000001162090_00184_43324_8533.N1						SS1	H/H	90	43324	184	5.03
ASA_WSM_1PNPDE20100613_183447_000002022090_00185_43325_8539.N1						SS1	V/V	90	43325	185	5.03
ASA_WSM_1PNPDK20100613_184639_000005382090_00185_43325_4018.N1						SS1	H/H	90	43325	185	5.03
ASA_WSM_1PNPDE20100613_194719_000002812090_00185_43325_8540.N1						SS1	H/H	90	43325	185	5.03
ASA_WSM_1PNPDK20100613_202458_000001162090_00186_43326_4034.N1						SS1	V/V	90	43326	186	5.03
ASA_WSM_1PNPDK20100613_202458_000001162090_00186_43326_4036.N1						SS1	V/V	90	43326	186	5.03
ASA_WSM_1PNPDK20100613_202458_000001162090_00186_43326_4033.N1						SS1	V/V	90	43326	186	5.03
ASA_WSM_1PNPDK20100613_202719_000004712090_00186_43326_4043.N1						SS1	H/H	90	43326	186	5.03
ASA_WSM_1PNPDE20100613_203436_000001042090_00186_43326_8556.N1						SS1	H/H	90	43326	186	5.03
ASA_WSM_1PNPDE20100613_203756_000001772090_00186_43326_8557.N1						SS1	H/H	90	43326	186	5.03
ASA_WSM_1PNPDE20100613_212848_000003062090_00186_43326_8553.N1						SS1	H/H	90	43326	186	5.03
ASA_WSM_1PNPDE20100613_214111_000001712090_00186_43326_8558.N1						SS1	V/V	90	43326	186	5.03
ASA_WSM_1PNPDE20100613_220338_000000862090_00187_43327_8555.N1						SS1	V/V	90	43327	187	5.03
ASA_WSM_1PNPDE20100613_221721_000004592090_00187_43327_8627.N1						SS1	H/H	90	43327	187	5.03
ASA_WSM_1PNPDE20100613_230741_000004162090_00187_43327_8574.N1						SS1	H/H	90	43327	187	5.03
ASA_WSM_1PNPDE20100613_234745_000002142090_00188_43328_8577.N1						SS1	H/H	90	43328	188	5.03
ASA_WSM_1PNPDK20100613_235028_000001472090_00188_43328_4052.N1						SS1	H/H	90	43328	188	5.03
ASA_WSM_1PNPDE20100613_235155_000002942090_00188_43328_8592.N1						SS1	H/H	90	43328	188	5.03
ASA_WSM_1PNPDE20100613_235728_000000982090_00188_43328_8593.N1						SS1	H/H	90	43328	188	5.03




Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WVS_1PNPDE20100612_235011_000016792090_00173_43313_8362.N1						IS2	V/V	90	43313	173	5.03
ASA_WVS_1PNPDE20100613_003656_000009472090_00174_43314_8364.N1						IS2	V/V	90	43314	174	5.03
ASA_WVS_1PNPDE20100613_010315_000003902090_00174_43314_8366.N1						IS2	V/V	90	43314	174	5.03
ASA_WVS_1PNPDE20100613_012634_000002252090_00174_43314_8369.N1						IS2	V/V	90	43314	174	5.03
ASA_WVS_1PNPDE20100613_012934_000003002090_00174_43314_8378.N1						IS2	V/V	90	43314	174	5.03
ASA_WVS_1PNPDE20100613_014508_000006292090_00175_43315_8381.N1						IS2	V/V	90	43315	175	5.03
ASA_WVS_1PNPDE20100613_023904_000002392090_00175_43315_8383.N1						IS2	V/V	90	43315	175	5.03
ASA_WVS_1PNPDE20100613_024249_000004502090_00175_43315_8395.N1						IS2	V/V	90	43315	175	5.03
ASA_WVS_1PNPDE20100613_030654_000002102090_00175_43315_8403.N1						IS2	V/V	90	43315	175	5.03
ASA_WVS_1PNPDE20100613_032703_000000742090_00176_43316_8399.N1						IS2	V/V	90	43316	176	5.03
ASA_WVS_1PNPDE20100613_040920_000009592090_00176_43316_8397.N1						IS2	V/V	90	43316	176	5.03
ASA_WVS_1PNPDE20100613_042505_000000902090_00176_43316_8421.N1						IS2	V/V	90	43316	176	5.03
ASA_WVS_1PNPDE20100613_042933_000000752090_00176_43316_8419.N1						IS2	V/V	90	43316	176	5.03
ASA_WVS_1PNPDE20100613_044739_000012892090_00176_43316_8426.N1						IS2	V/V	90	43316	176	5.03
ASA_WVS_1PNPDE20100613_054822_000010792090_00177_43317_8425.N1						IS2	V/V	90	43317	177	5.03
ASA_WVS_1PNPDK20100613_060606_000003302090_00177_43317_3850.N1						IS2	V/V	90	43317	177	5.03
ASA_WVS_1PNPDK20100613_062815_000019642090_00177_43317_3852.N1						IS2	V/V	90	43317	177	5.03
ASA_WVS_1PNPDK20100613_074759_000002402090_00178_43318_3877.N1						IS2	V/V	90	43318	178	5.03
ASA_WVS_1PNPDK20100613_080851_000012742090_00178_43318_3879.N1						IS2	V/V	90	43318	178	5.03
ASA_WVS_1PNPDK20100613_083200_000006742090_00179_43319_3881.N1						IS2	V/V	90	43319	179	5.03
ASA_WVS_1PNPDK20100613_091545_000010192090_00179_43319_3904.N1						IS2	V/V	90	43319	179	5.03
ASA_WVS_1PNPDK20100613_094927_000018892090_00179_43319_3908.N1						IS2	V/V	90	43319	179	5.03
ASA_WVS_1PNPDK20100613_103845_000001052090_00180_43320_3919.N1						IS2	V/V	90	43320	180	5.03
ASA_WVS_1PNPDK20100613_105414_000011392090_00180_43320_3921.N1						IS2	V/V	90	43320	180	5.03
ASA_WVS_1PNPDK20100613_113003_000019342090_00180_43320_3924.N1						IS2	V/V	90	43320	180	5.03
ASA_WVS_1PNPDK20100613_122105_000009742090_00181_43321_3934.N1						IS2	V/V	90	43321	181	5.03
ASA_WVS_1PNPDK20100613_124741_000003752090_00181_43321_3936.N1						IS2	V/V	90	43321	181	5.03
ASA_WVS_1PNPDK20100613_131030_000003152090_00181_43321_3939.N1						IS2	V/V	90	43321	181	5.03
ASA_WVS_1PNPDK20100613_132757_000002992090_00182_43322_3940.N1						IS2	V/V	90	43322	182	5.03
ASA_WVS_1PNPDK20100613_133629_000000892090_00182_43322_3947.N1						IS2	V/V	90	43322	182	5.03
ASA_WVS_1PNPDK20100613_140356_000006292090_00182_43322_3958.N1						IS2	V/V	90	43322	182	5.03
ASA_WVS_1PNPDK20100613_142318_000006752090_00182_43322_3960.N1						IS2	V/V	90	43322	182	5.03
ASA_WVS_1PNPDK20100613_145115_000003752090_00182_43322_3961.N1						IS2	V/V	90	43322	182	5.03
ASA_WVS_1PNPDK20100613_150139_000001942090_00182_43322_3965.N1						IS2	V/V	90	43322	182	5.03
ASA_WVS_1PNPDK20100613_150850_000000742090_00183_43323_3966.N1						IS2	V/V	90	43323	183	5.03
ASA_WVS_1PNPDK20100613_155449_000012142090_00183_43323_3981.N1						IS2	V/V	90	43323	183	5.03
ASA_WVS_1PNPDK20100613_163142_000011242090_00183_43323_3986.N1						IS2	V/V	90	43323	183	5.03
ASA_WVS_1PNPDK20100613_173241_000013792090_00184_43324_4006.N1						IS2	V/V	90	43324	184	5.03
ASA_WVS_1PNPDK20100613_181630_000009892090_00184_43324_4011.N1						IS2	V/V	90	43324	184	5.03
ASA_WVS_1PNPDK20100613_181630_000009892090_00184_43324_4009.N1						IS2	V/V	90	43324	184	5.03
ASA_WVS_1PNPDK20100613_190601_000018142090_00185_43325_4031.N1						IS2	V/V	90	43325	185	5.03
ASA_WVS_1PNPDK20100613_195254_000001202090_00185_43325_4030.N1						IS2	V/V	90	43325	185	5.03
ASA_WVS_1PNPDK20100613_195705_000003302090_00185_43325_4038.N1						IS2	V/V	90	43325	185	5.03
ASA_WVS_1PNPDE20100613_204418_000019492090_00186_43326_8544.N1						IS2	V/V	90	43326	186	5.03
ASA_WVS_1PNPDE20100613_213351_000003142090_00186_43326_8546.N1						IS2	V/V	90	43326	186	5.03
ASA_WVS_1PNPDE20100613_213821_000001202090_00186_43326_8559.N1						IS2	V/V	90	43326	186	5.03
ASA_WVS_1PNPDE20100613_213351_000003142090_00186_43326_8546.N1						IS1	V/V	90	43326	186	5.03
ASA_WVS_1PNPDE20100613_214359_000004192090_00186_43326_8560.N1						IS2	V/V	90	43326	186	5.03
ASA_WVS_1PNPDE20100613_220511_000001652090_00187_43327_8563.N1						IS2	V/V	90	43327	187	5.03
ASA_WVS_1PNPDE20100613_222501_000019492090_00187_43327_8565.N1						IS2	V/V	90	43327	187	5.03
ASA_WVS_1PNPDE20100613_231434_000003152090_00187_43327_8566.N1						IS2	V/V	90	43327	187	5.03
ASA_WVS_1PNPDE20100613_231904_000013192090_00187_43327_8575.N1						IS2	V/V	90	43327	187	5.03
ASA_WVS_1PNPDE20100613_234223_000002702090_00188_43328_8576.N1						IS2	V/V	90	43328	188	5.03

















































13-Jun





13-Jun




13-Jun








13-Jun



13-Jun



13-Jun

Reference: 2001-02-09 13:50:42 H RxGain

Test : 2010-06-13 06:12:09 H

