



Analysis from 02-AUG-2010 00:00:00 to 02-AUG-2010 23:59:59. Page generated on 03-AUG-2010 07:32:22.
View log file: ASAR_Daily_Report_20100803_0731.log. For any anomalies please contact emma.griffiths@vega.co.uk, kajal.haria@vega.co.uk.

This report is automatically generated every day, every 2 hours. No comments are provided on the results.

SUMMARY

1. DATA SUMMARY
 - 1.1 Summary tables
 - 1.2 Lists of products used
2. AUXILIARY FILES ANALYSIS
 - 2.1 IECF operational ADFs list
 - 2.2 Products with wrong ADFs
3. MODULE STEPPING PRODUCTS ANALYSIS
 - 3.1 V/V polarisation
 - 3.2 H/H polarisation
4. CALIBRATION PULSES ANALYSIS
 - 4.1 Analysis for WVS IS2 V/V
 - 4.1.1 Temporal Evolution Analysis for WVS IS2 V/V
 - 4.1.2 All Rows Analysis for WVS IS2 V/V
 - 4.2 Analysis for GM1 SS3 H/H
 - 4.2.1 Temporal Evolution Analysis for GM1 SS3 H/H
 - 4.2.2 All Rows Analysis for GM1 SS3 H/H
5. DOPPLER ANALYSIS
 - 5.1 Analysis for WVS IS2 V/V
 - 5.1.1 Doppler MAP Analysis for WVS IS2 V/V
 - 5.1.2 Doppler ANX Analysis for WVS IS2 V/V
 - 5.2 Analysis for GM1 SS1 H/H
 - 5.2.1 Doppler MAP Analysis for GM1 SS1 H/H
 - 5.2.2 Doppler ANX Analysis for GM1 SS1 H/H
 - 5.3 Doppler JUMPS Analysis for WSM
6. CHIRP ANALYSIS
 - 6.1 Analysis for WSM SS1 H/H
 - 6.1.1 ScaleFactor
 - 6.2 Analysis for WSM SS1 V/V
 - 6.2.1 ScaleFactor
7. RAW DATA ANALYSIS
 - 7.1 Analysis for WVS
 - 7.2 Analysis for IMM
8. TELEMETRY ANALYSIS
 - 8.1 Number of Missing Lines
 - 8.2 Number of Gaps

1 - DATA SUMMARY

1.1 - Summary tables

[[BACK TO MENU](#)]

WVS				GM1				APM				IMM				WSM				MS			
Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Time	Pol	Modules
PDE	IS1	V/V	5	PDE	WS	H/H	30	PDE	IS2	H/H	1	PDE	IS2	H/H	13	PDE	WS	1		PDE	2010-08-02 05:00:19	H	320
PDE	IS2	V/V	24	PDK	WS	H/H	57	PDE	IS4	V/H	2	PDE	IS2	V/V	15	PDE	WS	H/H	21				
PDK	IS1	V/V	1					PDE	IS4	V/V	3	PDE	IS4	V/V	1	PDE	WS	V/V	6				
PDK	IS2	V/V	21					PDK	IS4	V/V	1	PDE	IS7	H/H	1	PDK	WS	H/H	19				
												PDK	IS2	H/H	1	PDK	WS	V/V	2				
												PDK	IS2	V/V	2								
												PDK	IS4	H/H	1								

1.2 - Lists of products used

[[BACK TO MENU](#)]

[[TXT](#)] [[XLS](#)] [List_WVS_products_used](#)
 [[TXT](#)] [[XLS](#)] [List_GM1_products_used](#)
 [[TXT](#)] [[XLS](#)] [List_APM_products_used](#)
 [[TXT](#)] [[XLS](#)] [List_IMM_products_used](#)
 [[TXT](#)] [[XLS](#)] [List_WSM_products_used](#)
 [[TXT](#)] [[XLS](#)] [List_MS_products_used](#)

2 - AUXILIARY FILES ANALYSIS

2.1 - IECF operational ADFs list

[[BACK TO MENU](#)]

ADFs disseminated for ASAR
ASA_CON_AXVIEC20100608_125449_20100317_120410_20101231_000000
ASA_INS_AXVIEC20091217_114637_20090428_100000_20101231_235959
ASA_XCH_AXVIEC20091217_113006_20020301_000000_20101231_000000
ASA_XCA_AXVIEC20100608_123419_20100317_120410_20110101_000000

2.2 - Products with wrong ADFs




[[BACK TO MENU](#)]

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
WVS	0	0	0	0
GM1	0	0	0	0
APM	0	0	0	0
IMM	0	0	0	0
WSM	0	0	0	0

[[TXT](#)] [[XLS](#)] [Check_ADFs_WVS](#)
 [[TXT](#)] [[XLS](#)] [Check_ADFs_GM1](#)
 [[TXT](#)] [[XLS](#)] [Check_ADFs_APM](#)
 [[TXT](#)] [[XLS](#)] [Check_ADFs_IMM](#)
 [[TXT](#)] [[XLS](#)] [Check_ADFs_WSM](#)

3 - MODULE STEPPING PRODUCTS ANALYSIS






3.2 - H/H polarisation


[[BACK TO MENU](#)]

SECOND FIXED REFERENCE	PREVIOUS PRODUCT REFERENCE
Pre-launch reference (2001-02-09)	Previous product in the same polarisation


Reference: 2001-02-09 13:50:42 H RxGain
 Test : 2010-08-02 05:00:19 H




Reference: 2010-07-31 06:03:33 H RxGain
 Test : 2010-08-02 05:00:19 H







Reference: 2001-02-09 13:50:42 H RxPhase
 Test : 2010-08-02 05:00:19 H



Reference: 2010-07-31 06:03:33 H RxPhase
 Test : 2010-08-02 05:00:19 H





4 - CALIBRATION PULSES ANALYSIS

4.1 - Analysis for WVS IS2 V/V


4.1.1 - Temporal Evolution Analysis for WVS IS2 V/V

[BACK TO MENU]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Calibration pulses for WVS IS2 V/V




Transmit power (P1 - P1a) for WVS IS2 V/V



4.1.2 - All Rows Analysis for WVS IS2 V/V

[BACK TO MENU]





4.2 - Analysis for GM1 SS3 H/H


4.2.1 - Temporal Evolution Analysis for GM1 SS3 H/H

[BACK TO MENU]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Calibration pulses for GM1 SS3 H/H




Transmit power (P1 - P1a) for GM1 SS3 H/H



4.2.2 - All Rows Analysis for GM1 SS3 H/H

[[BACK TO MENU](#)]






5 - DOPPLER ANALYSIS

5.1 - Analysis for WVS IS2 V/V

5.1.1 - Doppler MAP Analysis for WVS IS2 V/V

[[BACK TO MENU](#)]






5.1.2 - Doppler ANX Analysis for WVS IS2 V/V

[[BACK TO MENU](#)]






5.2 - Analysis for GM1 SS1 H/H

5.2.1 - Doppler MAP Analysis for GM1 SS1 H/H

[[BACK TO MENU](#)]






5.2.2 - Doppler ANX Analysis for GM1 SS1 H/H

[[BACK TO MENU](#)]






5.3 - Doppler JUMPS Analysis for WSM

[[BACK TO MENU](#)]

--	--





6 - CHIRP ANALYSIS

6.1 - Analysis for WSM SS1 H/H

6.1.1 - ScaleFactor

[[BACK TO MENU](#)]







6.2 - Analysis for WSM SS1 V/V

6.2.1 - ScaleFactor

[[BACK TO MENU](#)]






7 - RAW DATA ANALYSIS

7.1 - Analysis for WVS

[[BACK TO MENU](#)]

--	--	--




Channel	Statistics	DSS-B
MEAN I	mean	0.000622732
	stdev	1.20251e-07
MEAN Q	mean	0.000508158
	stdev	2.05875e-07
Channel	Statistics	DSS-B
STDEV I	mean	0.149463
	stdev	0.00127129
STDEV Q	mean	0.149996
	stdev	0.00129584

7.2 - Analysis for IMM

[[BACK TO MENU](#)]







8 - TELEMETRY ANALYSIS

8.1 - Number of Missing lines


[BACK TO MENU]





8.2 - Number of Gaps

[\[BACK TO MENU \]](#)



ASAR DAILY REPORT for 100802
#####

MODE: DAILY
ANALYSIS: ALL
DATE: YESTERDAY

Analysis will be performed from 2010-08-02 00:00:00 to 2010-08-02 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_100802/

DATA SUMMARY

Summary will be performed from 2010-08-02 00:00:00 to 2010-08-02 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_100802/DATA_SUMMARY

Creating directory ./RESULTS/DAILY/_100802/DATA_SUMMARY...
Writing file ./RESULTS/DAILY/_100802/DATA_SUMMARY/Data_summary.html...

Getting WVS products list from 2010-08-02 00:00:00 to 2010-08-02 23:59:59...
Writing file ./RESULTS/DAILY/_100802/DATA_SUMMARY/List_WVS_products_used.xls...
Writing file ./RESULTS/DAILY/_100802/DATA_SUMMARY/List_WVS_products_used.txt...

Getting GM1 products list from 2010-08-02 00:00:00 to 2010-08-02 23:59:59...
Writing file ./RESULTS/DAILY/_100802/DATA_SUMMARY/List_GM1_products_used.xls...
Writing file ./RESULTS/DAILY/_100802/DATA_SUMMARY/List_GM1_products_used.txt...

Getting APM products list from 2010-08-02 00:00:00 to 2010-08-02 23:59:59...
Writing file ./RESULTS/DAILY/_100802/DATA_SUMMARY/List_APM_products_used.xls...
Writing file ./RESULTS/DAILY/_100802/DATA_SUMMARY/List_APM_products_used.txt...

Getting IMM products list from 2010-08-02 00:00:00 to 2010-08-02 23:59:59...
Writing file ./RESULTS/DAILY/_100802/DATA_SUMMARY/List_IMM_products_used.xls...
Writing file ./RESULTS/DAILY/_100802/DATA_SUMMARY/List_IMM_products_used.txt...

Getting WSM products list from 2010-08-02 00:00:00 to 2010-08-02 23:59:59...
Writing file ./RESULTS/DAILY/_100802/DATA_SUMMARY/List_WSM_products_used.xls...
Writing file ./RESULTS/DAILY/_100802/DATA_SUMMARY/List_WSM_products_used.txt...

Getting MS products list from 2010-08-02 00:00:00 to 2010-08-02 23:59:59...
Writing file ./RESULTS/DAILY/_100802/DATA_SUMMARY/List_MS_products_used.xls...
Writing file ./RESULTS/DAILY/_100802/DATA_SUMMARY/List_MS_products_used.txt...

DATA SUMMARY completed
#####

AUXILIARY FILES ANALYSIS

Analysis will be performed from 2010-08-02 00:00:00 to 2010-08-02 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_100802/AUXILIARY

Creating directory ./RESULTS/DAILY/_100802/AUXILIARY...

Looking for the IECF operational ADFs list...



ADF filter 20100802*current_3_IECF_ADFs.txt
 Found list 20100802_030004_current_3_IECF_ADFs.txt...
 Extracting ADFs...

ASA_CON_AXVIEC20100608_125449_20100317_120410_20101231_000000
 ASA_INS_AXVIEC20091217_114637_20090428_100000_20101231_235959
 ASA_XCH_AXVIEC20091217_113006_20020301_000000_20101231_000000
 ASA_XCA_AXVIEC20100608_123419_20100317_120410_20110101_000000

Writing file ./RESULTS/DAILY/_100802/AUXILIARY/ASAR_ADFs_IECF_List3.html...
 Writing file ./RESULTS/DAILY/_100802/AUXILIARY/Auxiliary_files_summary.html...

Analysing WVS products...

Writing file ./RESULTS/DAILY/_100802/AUXILIARY/Check_ADFs_WVS.xls...
 Writing file ./RESULTS/DAILY/_100802/AUXILIARY/Check_ADFs_WVS.txt...

ASA_WVS_1PNPDE20100802_001557_000002392091_00388_44029_1115.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100802_001912_000016642091_00388_44029_1134.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100802_010959_000000592091_00389_44030_1135.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100802_011316_000003272091_00389_44030_1139.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100802_012511_000000592091_00389_44030_1141.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100802_013204_000002852091_00389_44030_1145.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100802_015642_000000892091_00389_44030_1149.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100802_015712_000003002091_00389_44030_1166.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100802_030354_000005402091_00390_44031_1170.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100802_031224_000002702091_00390_44031_1193.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100802_034242_000007192091_00390_44031_1197.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100802_044114_000007792091_00391_44032_1199.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100802_045359_000002552091_00391_44032_1223.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100802_051754_000013042091_00391_44032_1229.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100802_062049_000003292091_00392_44033_1227.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100802_063115_000001952091_00392_44033_1225.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100802_211409_000017992091_00401_44042_1366.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100802_220345_000001802091_00401_44042_1367.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100802_220600_000008392091_00401_44042_1385.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100802_223223_000002552091_00402_44043_1387.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100802_225259_000013792091_00402_44043_1390.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100802_232253_000001052091_00402_44043_1391.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100802_234420_000002392091_00402_44043_1392.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100802_234736_000016642091_00402_44043_1414.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100802_063400_000002852091_00392_44033_1337.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100802_065830_000019042091_00392_44033_1342.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100802_081406_000003152091_00393_44034_1374.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100802_083906_000019642091_00393_44034_1376.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100802_094351_000005242091_00394_44035_1408.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100802_095250_000004202091_00394_44035_1412.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100802_101942_000017842091_00394_44035_1414.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100802_111107_000002392091_00395_44036_1441.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100802_112059_000011692091_00395_44036_1443.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100802_120018_000016642091_00395_44036_1448.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100802_125003_000008692091_00396_44037_1473.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100802_134054_000002852091_00396_44037_1480.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100802_145029_000006742091_00397_44038_1507.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100802_152130_000008242091_00397_44038_1510.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100802_162308_000011542091_00398_44039_1534.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100802_170206_000012142091_00398_44039_1536.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100802_175859_000014392091_00399_44040_1565.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100802_184515_000007942091_00399_44040_1572.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100802_193237_000018592091_00400_44041_1602.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100802_202318_000003602091_00400_44041_1605.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100802_202318_000003602091_00400_44041_1606.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

Analysing GM1 products...

Writing file ./RESULTS/DAILY/_100802/AUXILIARY/Check_ADFs_GM1.xls...

Writing file ./RESULTS/DAILY/_100802/AUXILIARY/Check_ADFs_GM1.txt...

ASA_GM1_1PNPDE20100802_005241_000010332091_00389_44030_1137.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100802_011929_000003382091_00389_44030_1140.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100802_012652_000003082091_00389_44030_1142.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100802_013737_000001382091_00389_44030_1144.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100802_014140_000001022091_00389_44030_1147.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100802_014620_000002412091_00389_44030_1146.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100802_015510_000000842091_00389_44030_1148.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100802_020252_000007252091_00389_44030_1165.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100802_021942_000020242091_00390_44031_1167.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100802_025735_000002592091_00390_44031_1169.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100802_032450_000001022091_00390_44031_1196.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100802_032819_000000842091_00390_44031_1194.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100802_033505_000004532091_00390_44031_1192.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100802_035522_000000902091_00391_44032_1191.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100802_040201_000011482091_00391_44032_1190.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100802_042357_000006282091_00391_44032_1195.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100802_043619_000002952091_00391_44032_1200.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100802_045852_000000782091_00391_44032_1220.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100802_050137_000004282091_00391_44032_1218.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100802_051418_000002112091_00391_44032_1232.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100802_054541_000008822091_00392_44033_1231.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100802_060915_000004832091_00392_44033_1230.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100802_061809_000000902091_00392_44033_1228.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100802_062712_000002412091_00392_44033_1226.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100802_205423_000001022091_00401_44042_1365.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100802_214451_000007312091_00401_44042_1368.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100802_222045_000004832091_00402_44043_1386.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100802_224328_000000962091_00402_44043_1388.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100802_231642_000001502091_00402_44043_1389.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100802_232527_000007852091_00402_44043_1393.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_063928_000007132091_00392_44033_1338.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_065502_000002052091_00392_44033_1340.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_073053_000001442091_00393_44034_1339.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_073638_000000782091_00393_44034_1341.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_073944_000001932091_00393_44034_1344.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_075529_000002412091_00393_44034_1370.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_080130_000000722091_00393_44034_1371.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_080825_000003382091_00393_44034_1372.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_082003_000007132091_00393_44034_1373.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_083618_000001632091_00393_44034_1375.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_091239_000005432091_00394_44035_1378.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_092704_000000962091_00394_44035_1407.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_094049_000001812091_00394_44035_1409.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_100039_000001812091_00394_44035_1410.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_101007_000001142091_00394_44035_1411.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_101653_000001632091_00394_44035_1413.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_105111_000006282091_00395_44036_1415.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_114113_000001442091_00395_44036_1442.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_114848_000002832091_00395_44036_1444.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_115725_000001692091_00395_44036_1445.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_122850_000002892091_00396_44037_1446.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_123753_000003502091_00396_44037_1449.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_124259_000001992091_00396_44037_1469.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_130520_000002052091_00396_44037_1470.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_131059_000002772091_00396_44037_1471.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_131544_000009912091_00396_44037_1475.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_133807_000001632091_00396_44037_1476.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_134624_000003682091_00396_44037_1478.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_135335_000004222091_00396_44037_1477.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_140252_000001142091_00397_44038_1479.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_140740_000008342091_00397_44038_1484.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_142051_000003142091_00397_44038_1502.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

ASA_GM1_1PNPDK20100802_142752_000006282091_00397_44038_1503.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_144407_000001812091_00397_44038_1504.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_150226_000005432091_00397_44038_1505.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_151413_000001502091_00397_44038_1506.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_151906_000001382091_00397_44038_1508.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_153554_000004772091_00397_44038_1509.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_155019_000005372091_00398_44039_1511.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_155829_000003922091_00398_44039_1530.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_160702_000006282091_00398_44039_1531.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_164304_000004412091_00398_44039_1532.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_165320_000001022091_00398_44039_1533.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_170001_000001202091_00398_44039_1535.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_172301_000005072091_00399_44040_1537.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_173826_000001992091_00399_44040_1558.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_174448_000000962091_00399_44040_1557.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_174721_000002472091_00399_44040_1561.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_175248_000003682091_00399_44040_1563.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_182337_000002772091_00399_44040_1566.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_185922_000005982091_00400_44041_1567.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_191541_000001992091_00400_44041_1597.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_192354_000001572091_00400_44041_1598.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_192815_000002592091_00400_44041_1599.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_200415_000008582091_00400_44041_1600.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_202051_000001442091_00400_44041_1601.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100802_203443_000007792091_00400_44041_1603.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

Analysing APM products...

Writing file ./RESULTS/DAILY/_100802/AUXILIARY/Check_ADFs_APM.xls...

Writing file ./RESULTS/DAILY/_100802/AUXILIARY/Check_ADFs_APM.txt...

ASA_APM_1PNPDE20100802_025635_00000432091_00390_44031_1163.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20100802_030156_000001132091_00390_44031_1164.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20100802_054023_000001222091_00392_44033_1222.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20100802_080249_000003152091_00393_44034_1244.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20100802_144707_000001832091_00397_44038_1347.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20100802_232119_000000872091_00402_44043_1404.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDK20100802_130846_000001142091_00396_44037_1472.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

Analysing IMM products...

Writing file ./RESULTS/DAILY/_100802/AUXILIARY/Check_ADFs_IMM.xls...

Writing file ./RESULTS/DAILY/_100802/AUXILIARY/Check_ADFs_IMM.txt...

ASA_IMM_1PNPDE20100802_000150_000004432091_00388_44029_1110.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100802_013955_000000922091_00389_44030_1131.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100802_014325_000001622091_00389_44030_1132.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100802_025328_000000742091_00390_44031_1160.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100802_025519_000000372091_00390_44031_1161.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100802_032045_000002322091_00390_44031_1168.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100802_032635_000000922091_00390_44031_1187.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100802_042108_000001592091_00391_44032_1185.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100802_043450_000000792091_00391_44032_1186.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100802_054252_000000832091_00392_44033_1221.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100802_054453_000000342091_00392_44033_1224.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100802_060400_000003032091_00392_44033_1214.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100802_061720_000000372091_00392_44033_1215.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100802_061951_000000522091_00392_44033_1216.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100802_075926_000001142091_00393_44034_1243.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100802_100342_000003732091_00394_44035_1272.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100802_105001_000000572091_00395_44036_1309.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100802_111721_000002122091_00395_44036_1300.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

ASA_IMM_1PNPDE20100802_114337_000003032091_00395_44036_1310.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100802_154348_000000362091_00398_44039_1349.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100802_154538_000002712091_00398_44039_1346.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100802_165025_000001612091_00398_44039_1355.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100802_165505_000001622091_00398_44039_1351.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100802_175127_000000682091_00399_44040_1360.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100802_182811_000003022091_00399_44040_1361.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100802_183401_000002332091_00399_44040_1357.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100802_192629_000000992091_00400_44041_1362.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100802_211253_000000682091_00401_44042_1380.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100802_231914_000000372091_00402_44043_1405.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20100802_110833_000001492091_00395_44036_1436.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20100802_140035_000000622091_00397_44038_1490.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20100802_205100_000001912091_00401_44042_1608.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20100802_223947_000002082091_00402_44043_1631.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

Analysing WSM products...

Writing file ./RESULTS/DAILY/_100802/AUXILIARY/Check_ADFs_WSM.xls...

Writing file ./RESULTS/DAILY/_100802/AUXILIARY/Check_ADFs_WSM.txt...

ASA_WSM_1PNPDE20100802_001016_000002812091_00388_44029_1116.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100802_004737_000003002091_00389_44030_1150.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100802_011149_000000862091_00389_44030_1151.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100802_015025_000002812091_00389_44030_1143.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100802_021504_000001842091_00390_44031_1159.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100802_032953_000003062091_00390_44031_1188.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100802_035700_000002942091_00391_44032_1189.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100802_050853_000001842091_00391_44032_1217.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100802_051227_000001042091_00391_44032_1219.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100802_074302_000004532091_00393_44034_1242.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100802_092431_000001472091_00394_44035_1264.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100802_093905_000001042091_00394_44035_1266.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100802_101211_000002812091_00394_44035_1304.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100802_151136_000001532091_00397_44038_1348.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100802_151651_000001282091_00397_44038_1350.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100802_160504_000001162091_00398_44039_1353.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100802_161840_000002452091_00398_44039_1354.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100802_165817_000000982091_00398_44039_1352.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100802_173135_000002082091_00399_44040_1356.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100802_183818_000001162091_00399_44040_1358.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100802_201837_000001282091_00400_44041_1363.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100802_203031_000002452091_00400_44041_1364.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100802_210303_000001042091_00401_44042_1377.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100802_210604_000003792091_00401_44042_1378.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100802_215707_000003432091_00401_44042_1376.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100802_224514_000004652091_00402_44043_1403.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100802_233836_000003002091_00402_44043_1396.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100802_233836_000003002091_00402_44043_1400.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100802_060029_000002082091_00392_44033_1323.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100802_065125_000002142091_00392_44033_1352.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100802_073325_000001842091_00393_44034_1353.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100802_073808_000000922091_00393_44034_1354.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100802_083202_000002452091_00393_44034_1382.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100802_092151_000001222091_00394_44035_1381.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100802_092849_000002022091_00394_44035_1397.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100802_110202_000003612091_00395_44036_1435.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100802_115340_000002262091_00395_44036_1453.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100802_123348_000002392091_00396_44037_1456.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100802_124624_000002202091_00396_44037_1457.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100802_133223_000003432091_00396_44037_1488.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100802_142609_000000982091_00397_44038_1491.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100802_173433_000002262091_00399_44040_1544.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100802_174151_000001712091_00399_44040_1546.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100802_191112_000002632091_00400_44041_1581.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK



```
ASA_WSM_1PNPDK20100802_191112_000002632091_00400_44041_1582.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100802_191904_000002882091_00400_44041_1592.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100802_205617_000000862091_00401_44042_1607.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100802_205829_000003062091_00401_44042_1617.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100802_223725_000001222091_00402_44043_1630.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```

AUXILIARY FILES ANALYSIS completed

#####

MODULE STEPPING ANALYSIS

#####

Analysis will be performed from 2010-08-02 00:00:00 to 2010-08-02 23:59:59

Results will be exported to the directory: ./RESULTS/DAILY/_100802/MODULE_STEPPING

Creating directory ./RESULTS/DAILY/_100802/MODULE_STEPPING...

Creating directory ./RESULTS/DAILY/_100802/MODULE_STEPPING/FIRST_REFERENCE...

Creating directory ./RESULTS/DAILY/_100802/MODULE_STEPPING/SECOND_REFERENCE...

Creating directory ./RESULTS/DAILY/_100802/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE...

Deleting old files...

Creating images comparing with second reference...

Exporting results to the directory ../../RESULTS/DAILY/_100802/MODULE_STEPPING/SECOND_REFERENCE...

Polarization: H

Reference product: ASA_MS__0PNPDK20010209_135042_0000009A024_00180_11700_0052.N1

Test product: ASA_MS__0PNPDE20100802_050019_00000162091_00391_44032_0568.N1

H

H

../../RESULTS/DAILY/_100802/MODULE_STEPPING/SECOND_REFERENCE/TGH_20100802_050019-20010209_135042.png

../../RESULTS/DAILY/_100802/MODULE_STEPPING/SECOND_REFERENCE/TPH_20100802_050019-20010209_135042.png

../../RESULTS/DAILY/_100802/MODULE_STEPPING/SECOND_REFERENCE/RGH_20100802_050019-20010209_135042.png

../../RESULTS/DAILY/_100802/MODULE_STEPPING/SECOND_REFERENCE/RPH_20100802_050019-20010209_135042.png

Polarization: V

Reference product: ASA_MS__0PNPDK20010209_140823_0000009A024_00180_11700_0054.N1

Test product: ASA_MS__0PNPDE20100801_053156_00000162091_00377_44018_0567.N1

V

V

../../RESULTS/DAILY/_100802/MODULE_STEPPING/SECOND_REFERENCE/TGV_20100801_053156-20010209_140823.png

../../RESULTS/DAILY/_100802/MODULE_STEPPING/SECOND_REFERENCE/TPV_20100801_053156-20010209_140823.png

../../RESULTS/DAILY/_100802/MODULE_STEPPING/SECOND_REFERENCE/RGV_20100801_053156-20010209_140823.png

../../RESULTS/DAILY/_100802/MODULE_STEPPING/SECOND_REFERENCE/RPV_20100801_053156-20010209_140823.png

Creating images comparing with previous product reference...

Exporting results to the directory ../../RESULTS/DAILY/_100802/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE...

Polarization: H

Reference product: ASA_MS__0PNPDK20100731_060333_00000162091_00363_44004_0173.N1

Test product: ASA_MS__0PNPDE20100802_050019_00000162091_00391_44032_0568.N1

H

H

../../RESULTS/DAILY/_100802/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TGH_20100802_050019-20100731_060333.png

../../RESULTS/DAILY/_100802/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TPH_20100802_050019-20100731_060333.png

../../RESULTS/DAILY/_100802/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RGH_20100802_050019-20100731_060333.png

../../RESULTS/DAILY/_100802/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RPH_20100802_050019-20100731_060333.png

Polarization: V

Reference product: ASA_MS__0PNPDK20100730_063510_00000162091_00349_43990_0172.N1



Test product: ASA_MS__0PNPDE20100801_053156_000000162091_00377_44018_0567.N1

V
V

../../../../RESULTS/DAILY/_100802/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TGV_20100801_053156-20100730_063510.png
../../../../RESULTS/DAILY/_100802/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TPV_20100801_053156-20100730_063510.png
../../../../RESULTS/DAILY/_100802/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RGV_20100801_053156-20100730_063510.png
../../../../RESULTS/DAILY/_100802/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RPV_20100801_053156-20100730_063510.png

MODULE_STEPPING ANALYSIS completed

#####

CALIBRATION PULSES ANALYSIS

#####

Creating directory ./RESULTS/DAILY/_100802/CALIBRATION_PULSES...

ALL ROWS Analysis will be performed from 2010-08-02 00:00:00 to 2010-08-02 23:59:59

Analysing products WVS IS2 V/V

Writing image ../../RESULTS/DAILY/_100802//CALIBRATION_PULSES/Calibration_pulses_all_rows_WVS_IS2_VV.png...

Analysing products GM1 SS3 H/H

Writing image ../../RESULTS/DAILY/_100802//CALIBRATION_PULSES/Calibration_pulses_all_rows_GM1_SS3_HH.png...

TEMPORAL EVOLUTION Analysis will be performed from 2010-08-02 00:00:00 to 2010-08-02 23:59:59

Analysing products WVS IS2 V/V

Getting calibration pulses data for WVS IS2 V/V from 2010-08-02 00:00:00 to 2010-08-02 23:59:59. Rows: 1/5/9/13/17/21/25/29

Writing file ./RESULTS/DAILY/_100802/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2010-08-02_1.dat...

Writing ../../RESULTS/DAILY/_100802//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_1.png...

Writing ../../RESULTS/DAILY/_100802//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_1.png...

Getting calibration pulses data for WVS IS2 V/V from 2010-08-02 00:00:00 to 2010-08-02 23:59:59. Rows: 2/6/10/14/18/22/26/30

Writing file ./RESULTS/DAILY/_100802/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2010-08-02_2.dat...

Writing ../../RESULTS/DAILY/_100802//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_2.png...

Writing ../../RESULTS/DAILY/_100802//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_2.png...

Getting calibration pulses data for WVS IS2 V/V from 2010-08-02 00:00:00 to 2010-08-02 23:59:59. Rows: 3/7/11/15/19/23/27/31

Writing file ./RESULTS/DAILY/_100802/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2010-08-02_3.dat...

Writing ../../RESULTS/DAILY/_100802//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_3.png...

Writing ../../RESULTS/DAILY/_100802//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_3.png...

Getting calibration pulses data for WVS IS2 V/V from 2010-08-02 00:00:00 to 2010-08-02 23:59:59. Rows: 4/8/12/16/20/24/28/32

Writing file ./RESULTS/DAILY/_100802/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2010-08-02_4.dat...

Writing ../../RESULTS/DAILY/_100802//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_4.png...

Writing ../../RESULTS/DAILY/_100802//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_4.png...

Analysing products GM1 SS3 H/H

Getting calibration pulses data for GM1 SS3 H/H from 2010-08-02 00:00:00 to 2010-08-02 23:59:59. Rows: 1/5/9/13/17/21/25/29

Writing file ./RESULTS/DAILY/_100802/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2010-08-02_1.dat...

Writing ../../RESULTS/DAILY/_100802//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_1.png...

Writing ../../RESULTS/DAILY/_100802//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_1.png...

Getting calibration pulses data for GM1 SS3 H/H from 2010-08-02 00:00:00 to 2010-08-02 23:59:59. Rows: 2/6/10/14/18/22/26/30

Writing file ./RESULTS/DAILY/_100802/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2010-08-02_2.dat...

Writing ../../RESULTS/DAILY/_100802//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_2.png...

Writing ../../RESULTS/DAILY/_100802//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_2.png...

Getting calibration pulses data for GM1 SS3 H/H from 2010-08-02 00:00:00 to 2010-08-02 23:59:59. Rows: 3/7/11/15/19/23/27/31

Writing file ./RESULTS/DAILY/_100802/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2010-08-02_3.dat...

Writing ../../RESULTS/DAILY/_100802//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_3.png...

Writing ../../RESULTS/DAILY/_100802//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_3.png...

Getting calibration pulses data for GM1 SS3 H/H from 2010-08-02 00:00:00 to 2010-08-02 23:59:59. Rows: 4/8/12/16/20/24/28/32

Writing file ./RESULTS/DAILY/_100802/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2010-08-02_4.dat...

Writing ../../RESULTS/DAILY/_100802//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_4.png...

Writing ../../RESULTS/DAILY/_100802//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_4.png...

CALIBRATION PULSES ANALYSIS completed

#####

DOPPLER ANALYSIS

#####

Creating directory ./RESULTS/DAILY/_100802/DOPPLER...

DOPPLER ANX Analysis will be performed from 2010-08-02 00:00:00 to 2010-08-02 23:59:59

Analysing products WVS IS2 V/V

Getting doppler data for WVS IS2 V/V from 2010-08-02 00:00:00 to 2010-08-02 23:59:59...

Writing file ./RESULTS/DAILY/_100802/DOPPLER/Doppler_data_WVS_IS2_VV_2010-08-02.dat...

Running IDL program...

Writing file ../../RESULTS/DAILY/_100802/DOPPLER/DOPPLER_ANX_WVS_IS2_VV.png...

Analysing products GM1 SS1 H/H

Getting doppler data for GM1 SS1 H/H from 2010-08-02 00:00:00 to 2010-08-02 23:59:59...

Writing file ./RESULTS/DAILY/_100802/DOPPLER/Doppler_data_GM1_SS1_HH_2010-08-02.dat...

Running IDL program...

Writing file ../../RESULTS/DAILY/_100802/DOPPLER/DOPPLER_ANX_GM1_SS1_HH.png...

DOPPLER JUMPS Analysis will be performed on WSM products from 2010-08-02 00:00:00 to 2010-08-02 23:59:59

Analysing by default products WSM

Getting doppler jumps data for WSM from 2010-08-02 00:00:00 to 2010-08-02 23:59:59...

Writing file ./RESULTS/DAILY/_100802/DOPPLER/Doppler_Jumps_data_WSM_2010-08-02.dat...

Running IDL program...

Writing file ../../RESULTS/DAILY/_100802/DOPPLER/DOPPLER_JUMPS_ANX_WSM.png...

Writing file ../../RESULTS/DAILY/_100802/DOPPLER/DOPPLER_JUMPS_Date_WSM.png...

DOPPLER MAP Analysis will be performed from 2010-08-02 00:00:00 to 2010-08-02 23:59:59

Analysing products WVS IS2 V/V

Loading predicted doppler values....

Phase: descending

Found data...

Computing mean error doppler estimated-predicted...

Mean error = -36.757211 Hz

Writing file ../../RESULTS/DAILY/_100802//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_WVS_IS2_VV_desc.jpg...

Writing file ../../RESULTS/DAILY/_100802//DOPPLER/DOPPLER_Absolute_WVS_IS2_VV_desc.jpg...

```
*****
Loading predicted doppler values....
Phase: ascending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -20.380955 Hz
Writing file ../../RESULTS/DAILY/_100802//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_WVS_IS2_VV_asc.jpg...
Writing file ../../RESULTS/DAILY/_100802//DOPPLER/DOPPLER_Absolute_WVS_IS2_VV_asc.jpg...
*****
```

```
Analysing products GM1 SS1 H/H
Loading predicted doppler values....
Phase: descending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -0.25546916 Hz
Writing file ../../RESULTS/DAILY/_100802//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_GM1_SS1_HH_desc.jpg...
Writing file ../../RESULTS/DAILY/_100802//DOPPLER/DOPPLER_Absolute_GM1_SS1_HH_desc.jpg...
*****
```

```
Loading predicted doppler values....
Phase: ascending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -7.0605314 Hz
Writing file ../../RESULTS/DAILY/_100802//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_GM1_SS1_HH_asc.jpg...
Writing file ../../RESULTS/DAILY/_100802//DOPPLER/DOPPLER_Absolute_GM1_SS1_HH_asc.jpg...
*****
```

```
DOPPLER ANALYSIS completed
#####
```

```
CHIRP ANALYSIS
#####
Creating directory ./RESULTS/DAILY/_100802/CHIRP...
```

```
*****
*****
CHIRP Analysis will be performed from 2010-08-02 00:00:00 to 2010-08-02 23:59:59
```

```
Analysing products WSM SS1 H/H
*****
Getting ScaleFactor data for WSM SS1 H/H from 2010-08-02 00:00:00 to 2010-08-02 23:59:59...
Writing file ./RESULTS/DAILY/_100802/CHIRP/ScaleFactor_data_WSM_SS1_HH_2010-08-02.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/_100802/CHIRP/ScaleFactor_ANX_WSM_SS1_HH.png...
Writing file ../../RESULTS/DAILY/_100802/CHIRP/ScaleFactor_DATE_WSM_SS1_HH.png...
```

```
Analysing products WSM SS1 V/V
*****
Getting ScaleFactor data for WSM SS1 V/V from 2010-08-02 00:00:00 to 2010-08-02 23:59:59...
Writing file ./RESULTS/DAILY/_100802/CHIRP/ScaleFactor_data_WSM_SS1_VV_2010-08-02.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/_100802/CHIRP/ScaleFactor_ANX_WSM_SS1_VV.png...
Writing file ../../RESULTS/DAILY/_100802/CHIRP/ScaleFactor_DATE_WSM_SS1_VV.png...
```

```
CHIRP ANALYSIS completed
```

#####

RAW DATA ANALYSIS

#####

Analysis will be performed from 2010-08-02 00:00:00 to 2010-08-02 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_100802/RAW_DATA

Creating directory ./RESULTS/DAILY/_100802/RAW_DATA...

Getting raw data for WVS from 2010-08-02 00:00:00 to 2010-08-02 23:59:59...
Writing file ./RESULTS/DAILY/_100802/RAW_DATA/Raw_data_WVS_2010-08-02.dat...
Running IDL program to create graphs...

Creating image ../../RESULTS/DAILY/_100802/RAW_DATA/Raw_data_WVS_input_mean.png...
Creating image ../../RESULTS/DAILY/_100802/RAW_DATA/Raw_data_WVS_input_stdev.png...
Creating image ../../RESULTS/DAILY/_100802/RAW_DATA/Raw_data_WVS_gain_imbalance.png...

Getting raw data for IMM from 2010-08-02 00:00:00 to 2010-08-02 23:59:59...
Writing file ./RESULTS/DAILY/_100802/RAW_DATA/Raw_data_IMM_2010-08-02.dat...
Running IDL program to create graphs...

Creating image ../../RESULTS/DAILY/_100802/RAW_DATA/Raw_data_IMM_input_mean.png...
Creating image ../../RESULTS/DAILY/_100802/RAW_DATA/Raw_data_IMM_input_stdev.png...
Creating image ../../RESULTS/DAILY/_100802/RAW_DATA/Raw_data_IMM_gain_imbalance.png...

RAW DATA ANALYSIS completed

#####

TELEMETRY ANALYSIS

#####

Analysis will be performed from 2010-08-02 00:00:00 to 2010-08-02 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_100802/TELEMETRY

Creating directory ./RESULTS/DAILY/_100802/TELEMETRY...

Looking for gaps and missing lines in WVS products...

Checking 24 products from PDE...
Checking 21 products from PDK...

Looking for gaps and missing lines in GM1 products...

Checking 30 products from PDE...
Checking 57 products from PDK...

Looking for gaps and missing lines in APM products...

Checking 6 products from PDE...
Checking 1 products from PDK...

Looking for gaps and missing lines in IMM products...

Checking 30 products from PDE...
Checking 4 products from PDK...

Looking for gaps and missing lines in WSM products...

Checking 28 products from PDE...
Checking 21 products from PDK...

Creating graph of missing lines and gaps...

Creating image: ./RESULTS/DAILY/_100802/TELEMETRY/TELEMETRY_Missing_lines.png...
Creating image: ./RESULTS/DAILY/_100802/TELEMETRY/TELEMETRY_Gaps.png...

TELEMETRY ANALYSIS completed
#####

HTML REPORT generation
#####

Building file ./RESULTS/DAILY/_100802/asarReport.html...
Building DATA SUMMARY section...
Building AUXILIARY FILES ANALYSIS section...
Building MODULE STEPPING ANALYSIS section...
Building CALIBRATION PULSES ANALYSIS section...
Building DOPPLER ANALYSIS section...
Building CHIRP ANALYSIS section...
Building RAW DATA ANALYSIS section...
Building TELEMETRY ANALYSIS section...

HTML REPORT generation completed
#####



Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
ASA_APM_1PNPDE20100802_025635_000000432091_00390_44031_1163.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20100802_030156_000001132091_00390_44031_1164.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20100802_054023_000001222091_00392_44033_1222.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20100802_080249_000003152091_00393_44034_1244.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20100802_144707_000001832091_00397_44038_1347.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20100802_232119_000000872091_00402_44043_1404.N1	OK	OK	OK	OK
ASA_APM_1PNPDK20100802_130846_000001142091_00396_44037_1472.N1	OK	OK	OK	OK

ASA_GM1_1PNPDK20100802_150226_000005432091_00397_44038_1505.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100802_151413_000001502091_00397_44038_1506.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100802_151906_000001382091_00397_44038_1508.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100802_153554_000004772091_00397_44038_1509.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100802_155019_000005372091_00398_44039_1511.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100802_155829_000003922091_00398_44039_1530.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100802_160702_000006282091_00398_44039_1531.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100802_164304_000004412091_00398_44039_1532.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100802_165320_000001022091_00398_44039_1533.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100802_170001_000001202091_00398_44039_1535.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100802_172301_000005072091_00399_44040_1537.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100802_173826_000001992091_00399_44040_1558.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100802_174448_000000962091_00399_44040_1557.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100802_174721_000002472091_00399_44040_1561.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100802_175248_000003682091_00399_44040_1563.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100802_182337_000002772091_00399_44040_1566.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100802_185922_000005982091_00400_44041_1567.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100802_191541_000001992091_00400_44041_1597.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100802_192354_000001572091_00400_44041_1598.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100802_192815_000002592091_00400_44041_1599.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100802_200415_000008582091_00400_44041_1600.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100802_202051_000001442091_00400_44041_1601.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100802_203443_000007792091_00400_44041_1603.N1	OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_IMM_1PNPDE20100802_000150_000004432091_00388_44029_1110.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100802_013955_00000922091_00389_44030_1131.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100802_014325_000001622091_00389_44030_1132.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100802_025328_000000742091_00390_44031_1160.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100802_025519_000000372091_00390_44031_1161.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100802_032045_000002322091_00390_44031_1168.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100802_032635_000000922091_00390_44031_1187.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100802_042108_000001592091_00391_44032_1185.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100802_043450_000000792091_00391_44032_1186.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100802_054252_000000832091_00392_44033_1221.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100802_054453_000000342091_00392_44033_1224.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100802_060400_000003032091_00392_44033_1214.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100802_061720_000000372091_00392_44033_1215.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100802_061951_000000522091_00392_44033_1216.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100802_075926_000001142091_00393_44034_1243.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100802_100342_000003732091_00394_44035_1272.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100802_105001_000000572091_00395_44036_1309.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100802_111721_000002122091_00395_44036_1300.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100802_114337_000003032091_00395_44036_1310.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100802_154348_000000362091_00398_44039_1349.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100802_154538_000002712091_00398_44039_1346.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100802_165025_000001612091_00398_44039_1355.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100802_165505_000001622091_00398_44039_1351.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100802_175127_000000682091_00399_44040_1360.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100802_182811_000003022091_00399_44040_1361.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100802_183401_000002332091_00399_44040_1357.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100802_192629_000000992091_00400_44041_1362.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100802_211253_000000682091_00401_44042_1380.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100802_231914_000000372091_00402_44043_1405.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20100802_110833_000001492091_00395_44036_1436.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20100802_140035_000000622091_00397_44038_1490.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20100802_205100_000001912091_00401_44042_1608.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20100802_223947_000002082091_00402_44043_1631.N1					OK	OK	OK	OK


Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WSM_1PNPDE20100802_001016_000002812091_00388_44029_1116.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100802_004737_000003002091_00389_44030_1150.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100802_011149_000000862091_00389_44030_1151.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100802_015025_000002812091_00389_44030_1143.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100802_021504_000001842091_00390_44031_1159.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100802_032953_000003062091_00390_44031_1188.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100802_035700_000002942091_00391_44032_1189.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100802_050853_000001842091_00391_44032_1217.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100802_051227_000001042091_00391_44032_1219.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100802_074302_000004532091_00393_44034_1242.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100802_092431_000001472091_00394_44035_1264.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100802_093905_000001042091_00394_44035_1266.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100802_101211_000002812091_00394_44035_1304.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100802_151136_000001532091_00397_44038_1348.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100802_151651_000001282091_00397_44038_1350.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100802_160504_000001162091_00398_44039_1353.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100802_161840_000002452091_00398_44039_1354.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100802_165817_000000982091_00398_44039_1352.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100802_173135_000002082091_00399_44040_1356.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100802_183818_000001162091_00399_44040_1358.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100802_201837_000001282091_00400_44041_1363.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100802_203031_000002452091_00400_44041_1364.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100802_210303_000001042091_00401_44042_1377.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100802_210604_000003792091_00401_44042_1378.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100802_215707_000003432091_00401_44042_1376.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100802_224514_000004652091_00402_44043_1403.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100802_233836_000003002091_00402_44043_1396.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100802_233836_000003002091_00402_44043_1400.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100802_060029_000002082091_00392_44033_1323.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100802_065125_000002142091_00392_44033_1352.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100802_073325_000001842091_00393_44034_1353.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100802_073808_000000922091_00393_44034_1354.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100802_083202_000002452091_00393_44034_1382.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100802_092151_000001222091_00394_44035_1381.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100802_092849_000002022091_00394_44035_1397.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100802_110202_000003612091_00395_44036_1435.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100802_115340_000002262091_00395_44036_1453.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100802_123348_000002392091_00396_44037_1456.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100802_124624_000002202091_00396_44037_1457.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100802_133223_000003432091_00396_44037_1488.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100802_142609_000000982091_00397_44038_1491.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100802_173433_000002262091_00399_44040_1544.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100802_174151_000001712091_00399_44040_1546.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100802_191112_000002632091_00400_44041_1581.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100802_191112_000002632091_00400_44041_1582.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100802_191904_000002882091_00400_44041_1592.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100802_205617_000000862091_00401_44042_1607.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100802_205829_000003062091_00401_44042_1617.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100802_223725_000001222091_00402_44043_1630.N1					OK	OK	OK	OK





Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WVS_1PNPDE20100802_001557_000002392091_00388_44029_1115.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100802_001912_000016642091_00388_44029_1134.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100802_010959_000000592091_00389_44030_1135.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100802_011316_000003272091_00389_44030_1139.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100802_012511_000000592091_00389_44030_1141.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100802_013204_000002852091_00389_44030_1145.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100802_015642_000000892091_00389_44030_1149.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100802_015712_000003002091_00389_44030_1166.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100802_030354_000005402091_00390_44031_1170.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100802_031224_000002702091_00390_44031_1193.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100802_034242_000007192091_00390_44031_1197.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100802_044114_000007792091_00391_44032_1199.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100802_045359_000002552091_00391_44032_1223.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100802_051754_000013042091_00391_44032_1229.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100802_062049_000003292091_00392_44033_1227.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100802_063115_000001952091_00392_44033_1225.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100802_211409_000017992091_00401_44042_1366.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100802_220345_000001802091_00401_44042_1367.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100802_220600_000008392091_00401_44042_1385.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100802_223223_000002552091_00402_44043_1387.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100802_225259_000013792091_00402_44043_1390.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100802_232253_000001052091_00402_44043_1391.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100802_234420_000002392091_00402_44043_1392.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100802_234736_000016642091_00402_44043_1414.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100802_063400_000002852091_00392_44033_1337.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100802_065830_000019042091_00392_44033_1342.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100802_081406_000003152091_00393_44034_1374.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100802_083906_000019642091_00393_44034_1376.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100802_094351_000005242091_00394_44035_1408.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100802_095250_000004202091_00394_44035_1412.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100802_101942_000017842091_00394_44035_1414.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100802_111107_000002392091_00395_44036_1441.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100802_112059_000011692091_00395_44036_1443.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100802_120018_000016642091_00395_44036_1448.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100802_125003_000008692091_00396_44037_1473.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100802_134054_000002852091_00396_44037_1480.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100802_145029_000006742091_00397_44038_1507.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100802_152130_000008242091_00397_44038_1510.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100802_162308_000011542091_00398_44039_1534.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100802_170206_000012142091_00398_44039_1536.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100802_175859_000014392091_00399_44040_1565.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100802_184515_000007942091_00399_44040_1572.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100802_193237_000018592091_00400_44041_1602.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100802_202318_000003602091_00400_44041_1605.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100802_202318_000003602091_00400_44041_1606.N1					OK	OK	OK	OK





Calibration pulses for GM1 SS3 H/H







Calibration pulses for GM1 SS3 H/H




Calibration pulses for GM1 SS3 H/H




Calibration pulses for GM1 SS3 H/H







Calibration pulses for WVS IS2 V/V







Calibration pulses for WVS IS2 V/V




Calibration pulses for WVS IS2 V/V






Calibration pulses for WVS IS2 V/V







rows: 4 8 12 16 20 24 28 32



































rows: _ 4 _ 8 _ 12 _ 16 _ 20 _ 24 _ 28 _ 32









Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_APM_1PNPDE20100802_025635_000000432091_00390_44031_1163.N1						IS2	H/H	91	44031	390	5.03
ASA_APM_1PNPDE20100802_030156_000001132091_00390_44031_1164.N1						IS4	V/V	91	44031	390	5.03
ASA_APM_1PNPDE20100802_054023_000001222091_00392_44033_1222.N1						IS4	V/V	91	44033	392	5.03
ASA_APM_1PNPDE20100802_080249_000003152091_00393_44034_1244.N1						IS4	V/H	91	44034	393	5.03
ASA_APM_1PNPDK20100802_130846_000001142091_00396_44037_1472.N1						IS4	V/V	91	44037	396	5.03
ASA_APM_1PNPDE20100802_144707_000001832091_00397_44038_1347.N1						IS4	V/V	91	44038	397	5.03
ASA_APM_1PNPDE20100802_232119_000000872091_00402_44043_1404.N1						IS4	V/H	91	44043	402	5.03

ASA_GM1_1PNPDK20100802_170001_000001202091_00398_44039_1535.N1	SS1	H/H	91	44039	398	5.03
ASA_GM1_1PNPDK20100802_172301_000005072091_00399_44040_1537.N1	SS1	H/H	91	44040	399	5.03
ASA_GM1_1PNPDK20100802_173826_000001992091_00399_44040_1558.N1	SS1	H/H	91	44040	399	5.03
ASA_GM1_1PNPDK20100802_174448_000000962091_00399_44040_1557.N1	SS1	H/H	91	44040	399	5.03
ASA_GM1_1PNPDK20100802_174721_000002472091_00399_44040_1561.N1	SS1	H/H	91	44040	399	5.03
ASA_GM1_1PNPDK20100802_175248_000003682091_00399_44040_1563.N1	SS1	H/H	91	44040	399	5.03
ASA_GM1_1PNPDK20100802_182337_000002772091_00399_44040_1566.N1	SS1	H/H	91	44040	399	5.03
ASA_GM1_1PNPDK20100802_185922_000005982091_00400_44041_1567.N1	SS1	H/H	91	44041	400	5.03
ASA_GM1_1PNPDK20100802_191541_000001992091_00400_44041_1597.N1	SS1	H/H	91	44041	400	5.03
ASA_GM1_1PNPDK20100802_192354_000001572091_00400_44041_1598.N1	SS1	H/H	91	44041	400	5.03
ASA_GM1_1PNPDK20100802_192815_000002592091_00400_44041_1599.N1	SS1	H/H	91	44041	400	5.03
ASA_GM1_1PNPDK20100802_200415_000008582091_00400_44041_1600.N1	SS1	H/H	91	44041	400	5.03
ASA_GM1_1PNPDK20100802_202051_000001442091_00400_44041_1601.N1	SS1	H/H	91	44041	400	5.03
ASA_GM1_1PNPDK20100802_203443_000007792091_00400_44041_1603.N1	SS1	H/H	91	44041	400	5.03
ASA_GM1_1PNPDE20100802_205423_000001022091_00401_44042_1365.N1	SS1	H/H	91	44042	401	5.03
ASA_GM1_1PNPDE20100802_214451_000007312091_00401_44042_1368.N1	SS1	H/H	91	44042	401	5.03
ASA_GM1_1PNPDE20100802_222045_000004832091_00402_44043_1386.N1	SS1	H/H	91	44043	402	5.03
ASA_GM1_1PNPDE20100802_224328_000000962091_00402_44043_1388.N1	SS1	H/H	91	44043	402	5.03
ASA_GM1_1PNPDE20100802_231642_000001502091_00402_44043_1389.N1	SS1	H/H	91	44043	402	5.03
ASA_GM1_1PNPDE20100802_232527_000007852091_00402_44043_1393.N1	SS1	H/H	91	44043	402	5.03


Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_IMM_1PNPDE20100801_235930_000000912091_00388_44029_1120.N1						IS2	H/H	91	44029	388	5.03
ASA_IMM_1PNPDE20100802_000150_000004432091_00388_44029_1110.N1						IS2	H/H	91	44029	388	5.03
ASA_IMM_1PNPDE20100802_013955_000000922091_00389_44030_1131.N1						IS2	H/H	91	44030	389	5.03
ASA_IMM_1PNPDE20100802_014325_000001622091_00389_44030_1132.N1						IS2	H/H	91	44030	389	5.03
ASA_IMM_1PNPDE20100802_025328_000000742091_00390_44031_1160.N1						IS2	V/V	91	44031	390	5.03
ASA_IMM_1PNPDE20100802_025519_000000372091_00390_44031_1161.N1						IS2	V/V	91	44031	390	5.03
ASA_IMM_1PNPDE20100802_032045_000002322091_00390_44031_1168.N1						IS2	H/H	91	44031	390	5.03
ASA_IMM_1PNPDE20100802_032635_000000922091_00390_44031_1187.N1						IS2	H/H	91	44031	390	5.03
ASA_IMM_1PNPDE20100802_042108_000001592091_00391_44032_1185.N1						IS2	V/V	91	44032	391	5.03
ASA_IMM_1PNPDE20100802_043450_000000792091_00391_44032_1186.N1						IS2	V/V	91	44032	391	5.03
ASA_IMM_1PNPDE20100802_054252_000000832091_00392_44033_1221.N1						IS2	V/V	91	44033	392	5.03
ASA_IMM_1PNPDE20100802_054453_000000342091_00392_44033_1224.N1						IS2	V/V	91	44033	392	5.03
ASA_IMM_1PNPDE20100802_060400_000003032091_00392_44033_1214.N1						IS2	V/V	91	44033	392	5.03
ASA_IMM_1PNPDE20100802_061720_000000372091_00392_44033_1215.N1						IS2	V/V	91	44033	392	5.03
ASA_IMM_1PNPDE20100802_061951_000000522091_00392_44033_1216.N1						IS7	H/H	91	44033	392	5.03
ASA_IMM_1PNPDE20100802_075926_000001142091_00393_44034_1243.N1						IS2	H/H	91	44034	393	5.03
ASA_IMM_1PNPDE20100802_100342_000003732091_00394_44035_1272.N1						IS2	H/H	91	44035	394	5.03
ASA_IMM_1PNPDE20100802_105001_000000572091_00395_44036_1309.N1						IS2	V/V	91	44036	395	5.03
ASA_IMM_1PNPDK20100802_110833_000001492091_00395_44036_1436.N1						IS2	V/V	91	44036	395	5.03
ASA_IMM_1PNPDE20100802_111721_000002122091_00395_44036_1300.N1						IS2	V/V	91	44036	395	5.03
ASA_IMM_1PNPDE20100802_114337_000003032091_00395_44036_1310.N1						IS2	H/H	91	44036	395	5.03
ASA_IMM_1PNPDK20100802_140035_000000622091_00397_44038_1490.N1						IS4	H/H	91	44038	397	5.03
ASA_IMM_1PNPDE20100802_154348_000000362091_00398_44039_1349.N1						IS2	V/V	91	44039	398	5.03
ASA_IMM_1PNPDE20100802_154538_000002712091_00398_44039_1346.N1						IS2	V/V	91	44039	398	5.03
ASA_IMM_1PNPDE20100802_165025_000001612091_00398_44039_1355.N1						IS2	H/H	91	44039	398	5.03
ASA_IMM_1PNPDE20100802_165505_000001622091_00398_44039_1351.N1						IS2	H/H	91	44039	398	5.03
ASA_IMM_1PNPDE20100802_175127_000000682091_00399_44040_1360.N1						IS4	V/V	91	44040	399	5.03
ASA_IMM_1PNPDE20100802_182811_000003022091_00399_44040_1361.N1						IS2	H/H	91	44040	399	5.03
ASA_IMM_1PNPDE20100802_183401_000002332091_00399_44040_1357.N1						IS2	H/H	91	44040	399	5.03
ASA_IMM_1PNPDE20100802_192629_000000992091_00400_44041_1362.N1						IS2	V/V	91	44041	400	5.03
ASA_IMM_1PNPDK20100802_205100_000001912091_00401_44042_1608.N1						IS2	V/V	91	44042	401	5.03
ASA_IMM_1PNPDE20100802_211253_000000682091_00401_44042_1380.N1						IS2	V/V	91	44042	401	5.03
ASA_IMM_1PNPDK20100802_223947_000002082091_00402_44043_1631.N1						IS2	H/H	91	44043	402	5.03
ASA_IMM_1PNPDE20100802_231914_000000372091_00402_44043_1405.N1						IS2	V/V	91	44043	402	5.03


Filename	Pol	Timestamp	count(Module)
ASA_MS__0PNPDE20100802_050019_000000162091_00391_44032_0568.N1	H	2010-08-02 05:00:19	320





Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WSM_1PNPDE20100802_001016_000002812091_00388_44029_1116.N1						SS1		91	44029	388	5.03
ASA_WSM_1PNPDE20100802_004737_000003002091_00389_44030_1150.N1						SS1	H/H	91	44030	389	5.03
ASA_WSM_1PNPDE20100802_011149_000000862091_00389_44030_1151.N1						SS1	V/V	91	44030	389	5.03
ASA_WSM_1PNPDE20100802_015025_000002812091_00389_44030_1143.N1						SS1	H/H	91	44030	389	5.03
ASA_WSM_1PNPDE20100802_021504_000001842091_00390_44031_1159.N1						SS1	V/V	91	44031	390	5.03
ASA_WSM_1PNPDE20100802_032953_000003062091_00390_44031_1188.N1						SS1	H/H	91	44031	390	5.03
ASA_WSM_1PNPDE20100802_035700_000002942091_00391_44032_1189.N1						SS1	V/V	91	44032	391	5.03
ASA_WSM_1PNPDE20100802_050853_000001842091_00391_44032_1217.N1						SS1	H/H	91	44032	391	5.03
ASA_WSM_1PNPDE20100802_051227_000001042091_00391_44032_1219.N1						SS1	H/H	91	44032	391	5.03
ASA_WSM_1PNPDK20100802_060029_000002082091_00392_44033_1323.N1						SS1	H/H	91	44033	392	5.03
ASA_WSM_1PNPDK20100802_065125_000002142091_00392_44033_1352.N1						SS1	H/H	91	44033	392	5.03
ASA_WSM_1PNPDK20100802_073325_000001842091_00393_44034_1353.N1						SS1	H/H	91	44034	393	5.03
ASA_WSM_1PNPDK20100802_073808_000000922091_00393_44034_1354.N1						SS1	H/H	91	44034	393	5.03
ASA_WSM_1PNPDE20100802_074302_000004532091_00393_44034_1242.N1						SS1	H/H	91	44034	393	5.03
ASA_WSM_1PNPDK20100802_083202_000002452091_00393_44034_1382.N1						SS1	H/H	91	44034	393	5.03
ASA_WSM_1PNPDK20100802_092151_000001222091_00394_44035_1381.N1						SS1	H/H	91	44035	394	5.03
ASA_WSM_1PNPDE20100802_092431_000001472091_00394_44035_1264.N1						SS1	V/V	91	44035	394	5.03
ASA_WSM_1PNPDK20100802_092849_000002022091_00394_44035_1397.N1						SS1	V/V	91	44035	394	5.03
ASA_WSM_1PNPDE20100802_093905_000001042091_00394_44035_1266.N1						SS1	V/V	91	44035	394	5.03
ASA_WSM_1PNPDE20100802_101211_000002812091_00394_44035_1304.N1						SS1	H/H	91	44035	394	5.03
ASA_WSM_1PNPDK20100802_110202_000003612091_00395_44036_1435.N1						SS1	H/H	91	44036	395	5.03
ASA_WSM_1PNPDK20100802_115340_000002262091_00395_44036_1453.N1						SS1	H/H	91	44036	395	5.03
ASA_WSM_1PNPDK20100802_123348_000002392091_00396_44037_1456.N1						SS1	H/H	91	44037	396	5.03
ASA_WSM_1PNPDK20100802_124624_000002202091_00396_44037_1457.N1						SS1	H/H	91	44037	396	5.03
ASA_WSM_1PNPDK20100802_133223_000003432091_00396_44037_1488.N1						SS1	H/H	91	44037	396	5.03
ASA_WSM_1PNPDK20100802_142609_000000982091_00397_44038_1491.N1						SS1	H/H	91	44038	397	5.03
ASA_WSM_1PNPDE20100802_151136_000001532091_00397_44038_1348.N1						SS1	H/H	91	44038	397	5.03
ASA_WSM_1PNPDE20100802_151651_000001282091_00397_44038_1350.N1						SS1	H/H	91	44038	397	5.03
ASA_WSM_1PNPDE20100802_160504_000001162091_00398_44039_1353.N1						SS1	H/H	91	44039	398	5.03
ASA_WSM_1PNPDE20100802_161840_000002452091_00398_44039_1354.N1						SS1	V/V	91	44039	398	5.03
ASA_WSM_1PNPDE20100802_165817_000000982091_00398_44039_1352.N1						SS1	H/H	91	44039	398	5.03
ASA_WSM_1PNPDE20100802_173135_000002082091_00399_44040_1356.N1						SS1	H/H	91	44040	399	5.03
ASA_WSM_1PNPDK20100802_173433_000002262091_00399_44040_1544.N1						SS1	H/H	91	44040	399	5.03
ASA_WSM_1PNPDK20100802_174151_000001712091_00399_44040_1546.N1						SS1	H/H	91	44040	399	5.03
ASA_WSM_1PNPDE20100802_183818_000001162091_00399_44040_1358.N1						SS1	H/H	91	44040	399	5.03
ASA_WSM_1PNPDK20100802_191112_000002632091_00400_44041_1581.N1						SS1	H/H	91	44041	400	5.03
ASA_WSM_1PNPDK20100802_191112_000002632091_00400_44041_1582.N1						SS1	H/H	91	44041	400	5.03
ASA_WSM_1PNPDK20100802_191904_000002882091_00400_44041_1592.N1						SS1	H/H	91	44041	400	5.03
ASA_WSM_1PNPDE20100802_201837_000001282091_00400_44041_1363.N1						SS1	H/H	91	44041	400	5.03
ASA_WSM_1PNPDE20100802_203031_000002452091_00400_44041_1364.N1						SS1	H/H	91	44041	400	5.03
ASA_WSM_1PNPDK20100802_205617_000000862091_00401_44042_1607.N1						SS1	V/V	91	44042	401	5.03
ASA_WSM_1PNPDK20100802_205829_000003062091_00401_44042_1617.N1						SS1	H/H	91	44042	401	5.03
ASA_WSM_1PNPDE20100802_210303_000001042091_00401_44042_1377.N1						SS1	H/H	91	44042	401	5.03
ASA_WSM_1PNPDE20100802_210604_000003792091_00401_44042_1378.N1						SS1	H/H	91	44042	401	5.03
ASA_WSM_1PNPDE20100802_215707_000003432091_00401_44042_1376.N1						SS1	H/H	91	44042	401	5.03
ASA_WSM_1PNPDK20100802_223725_000001222091_00402_44043_1630.N1						SS1	H/H	91	44043	402	5.03
ASA_WSM_1PNPDE20100802_224514_000004652091_00402_44043_1403.N1						SS1	H/H	91	44043	402	5.03
ASA_WSM_1PNPDE20100802_233836_000003002091_00402_44043_1400.N1						SS1	H/H	91	44043	402	5.03
ASA_WSM_1PNPDE20100802_233836_000003002091_00402_44043_1396.N1						SS1	H/H	91	44043	402	5.03




Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion
ASA_WVS_1PNPDE20100802_001557_000002392091_00388_44029_1115.N1						IS2 V/V 91 44029 388 5.03
ASA_WVS_1PNPDE20100802_001912_000016642091_00388_44029_1134.N1						IS2 V/V 91 44029 388 5.03
ASA_WVS_1PNPDE20100802_001557_000002392091_00388_44029_1115.N1						IS1 V/V 91 44029 388 5.03
ASA_WVS_1PNPDE20100802_010959_000000592091_00389_44030_1135.N1						IS2 V/V 91 44030 389 5.03
ASA_WVS_1PNPDE20100802_011316_000003272091_00389_44030_1139.N1						IS2 V/V 91 44030 389 5.03
ASA_WVS_1PNPDE20100802_012511_000000592091_00389_44030_1141.N1						IS2 V/V 91 44030 389 5.03
ASA_WVS_1PNPDE20100802_013204_000002852091_00389_44030_1145.N1						IS2 V/V 91 44030 389 5.03
ASA_WVS_1PNPDE20100802_015642_000000892091_00389_44030_1149.N1						IS2 V/V 91 44030 389 5.03
ASA_WVS_1PNPDE20100802_015712_000003002091_00389_44030_1166.N1						IS2 V/V 91 44030 389 5.03
ASA_WVS_1PNPDE20100802_015642_000000892091_00389_44030_1149.N1						IS1 V/V 91 44030 389 5.03
ASA_WVS_1PNPDE20100802_030354_000005402091_00390_44031_1170.N1						IS2 V/V 91 44031 390 5.03
ASA_WVS_1PNPDE20100802_031224_000002702091_00390_44031_1193.N1						IS2 V/V 91 44031 390 5.03
ASA_WVS_1PNPDE20100802_030354_000005402091_00390_44031_1170.N1						IS1 V/V 91 44031 390 5.03
ASA_WVS_1PNPDE20100802_034242_000007192091_00390_44031_1197.N1						IS2 V/V 91 44031 390 5.03
ASA_WVS_1PNPDE20100802_044114_000007792091_00391_44032_1199.N1						IS2 V/V 91 44032 391 5.03
ASA_WVS_1PNPDE20100802_045359_000002552091_00391_44032_1223.N1						IS2 V/V 91 44032 391 5.03
ASA_WVS_1PNPDE20100802_051754_000013042091_00391_44032_1229.N1						IS2 V/V 91 44032 391 5.03
ASA_WVS_1PNPDE20100802_062049_000003292091_00392_44033_1227.N1						IS2 V/V 91 44033 392 5.03
ASA_WVS_1PNPDE20100802_063115_000001952091_00392_44033_1225.N1						IS2 V/V 91 44033 392 5.03
ASA_WVS_1PNPDK20100802_063400_000002852091_00392_44033_1337.N1						IS2 V/V 91 44033 392 5.03
ASA_WVS_1PNPDE20100802_063115_000001952091_00392_44033_1225.N1						IS1 V/V 91 44033 392 5.03
ASA_WVS_1PNPDK20100802_065830_000019042091_00392_44033_1342.N1						IS2 V/V 91 44033 392 5.03
ASA_WVS_1PNPDK20100802_081406_000003152091_00393_44034_1374.N1						IS2 V/V 91 44034 393 5.03
ASA_WVS_1PNPDK20100802_083906_000019642091_00393_44034_1376.N1						IS2 V/V 91 44034 393 5.03
ASA_WVS_1PNPDK20100802_094351_000005242091_00394_44035_1408.N1						IS2 V/V 91 44035 394 5.03
ASA_WVS_1PNPDK20100802_094351_000005242091_00394_44035_1408.N1						IS1 V/V 91 44035 394 5.03
ASA_WVS_1PNPDK20100802_095250_000004202091_00394_44035_1412.N1						IS2 V/V 91 44035 394 5.03
ASA_WVS_1PNPDK20100802_101942_000017842091_00394_44035_1414.N1						IS2 V/V 91 44035 394 5.03
ASA_WVS_1PNPDK20100802_111107_000002392091_00395_44036_1441.N1						IS2 V/V 91 44036 395 5.03
ASA_WVS_1PNPDK20100802_112059_000011692091_00395_44036_1443.N1						IS2 V/V 91 44036 395 5.03
ASA_WVS_1PNPDK20100802_120018_000016642091_00395_44036_1448.N1						IS2 V/V 91 44036 395 5.03
ASA_WVS_1PNPDK20100802_125003_000008692091_00396_44037_1473.N1						IS2 V/V 91 44037 396 5.03
ASA_WVS_1PNPDK20100802_134054_000002852091_00396_44037_1480.N1						IS2 V/V 91 44037 396 5.03
ASA_WVS_1PNPDK20100802_145029_000006742091_00397_44038_1507.N1						IS2 V/V 91 44038 397 5.03
ASA_WVS_1PNPDK20100802_152130_000008242091_00397_44038_1510.N1						IS2 V/V 91 44038 397 5.03
ASA_WVS_1PNPDK20100802_162308_000011542091_00398_44039_1534.N1						IS2 V/V 91 44039 398 5.03
ASA_WVS_1PNPDK20100802_170206_000012142091_00398_44039_1536.N1						IS2 V/V 91 44039 398 5.03
ASA_WVS_1PNPDK20100802_175859_000014392091_00399_44040_1565.N1						IS2 V/V 91 44040 399 5.03
ASA_WVS_1PNPDK20100802_184515_000007942091_00399_44040_1572.N1						IS2 V/V 91 44040 399 5.03
ASA_WVS_1PNPDK20100802_193237_000018592091_00400_44041_1602.N1						IS2 V/V 91 44041 400 5.03
ASA_WVS_1PNPDK20100802_202318_000003602091_00400_44041_1606.N1						IS2 V/V 91 44041 400 5.03
ASA_WVS_1PNPDK20100802_202318_000003602091_00400_44041_1605.N1						IS2 V/V 91 44041 400 5.03
ASA_WVS_1PNPDE20100802_211409_000017992091_00401_44042_1366.N1						IS2 V/V 91 44042 401 5.03
ASA_WVS_1PNPDE20100802_220345_000001802091_00401_44042_1367.N1						IS2 V/V 91 44042 401 5.03
ASA_WVS_1PNPDE20100802_220600_000008392091_00401_44042_1385.N1						IS2 V/V 91 44042 401 5.03
ASA_WVS_1PNPDE20100802_223223_000002552091_00402_44043_1387.N1						IS2 V/V 91 44043 402 5.03
ASA_WVS_1PNPDE20100802_225259_000013792091_00402_44043_1390.N1						IS2 V/V 91 44043 402 5.03
ASA_WVS_1PNPDE20100802_232253_000001052091_00402_44043_1391.N1						IS2 V/V 91 44043 402 5.03
ASA_WVS_1PNPDE20100802_234420_000002392091_00402_44043_1392.N1						IS2 V/V 91 44043 402 5.03
ASA_WVS_1PNPDE20100802_234736_000016642091_00402_44043_1414.N1						IS2 V/V 91 44043 402 5.03
ASA_WVS_1PNPDE20100802_234420_000002392091_00402_44043_1392.N1						IS1 V/V 91 44043 402 5.03



























































02-Aug



02-Aug



02-Aug

