



Analysis from 23-AUG-2010 00:00:00 to 23-AUG-2010 23:59:59. Page generated on 24-AUG-2010 07:32:20.  
View log file: ASAR\_Daily\_Report\_20100824\_0731.log. For any anomalies please contact emma.griffiths@vega.co.uk, kajal.haria@vega.co.uk.

This report is automatically generated every day, every 2 hours. No comments are provided on the results.

## SUMMARY

1. DATA SUMMARY
  - 1.1 Summary tables
  - 1.2 Lists of products used
2. AUXILIARY FILES ANALYSIS
  - 2.1 IECF operational ADFs list
  - 2.2 Products with wrong ADFs
3. MODULE STEPPING PRODUCTS ANALYSIS
  - 3.1 V/V polarisation
  - 3.2 H/H polarisation
4. CALIBRATION PULSES ANALYSIS
  - 4.1 Analysis for WVS IS2 V/V
    - 4.1.1 Temporal Evolution Analysis for WVS IS2 V/V
    - 4.1.2 All Rows Analysis for WVS IS2 V/V
  - 4.2 Analysis for GM1 SS3 H/H
    - 4.2.1 Temporal Evolution Analysis for GM1 SS3 H/H
    - 4.2.2 All Rows Analysis for GM1 SS3 H/H
5. DOPPLER ANALYSIS
  - 5.1 Analysis for WVS IS2 V/V
    - 5.1.1 Doppler MAP Analysis for WVS IS2 V/V
    - 5.1.2 Doppler ANX Analysis for WVS IS2 V/V
  - 5.2 Analysis for GM1 SS1 H/H
    - 5.2.1 Doppler MAP Analysis for GM1 SS1 H/H
    - 5.2.2 Doppler ANX Analysis for GM1 SS1 H/H
  - 5.3 Doppler JUMPS Analysis for WSM
6. CHIRP ANALYSIS
  - 6.1 Analysis for WSM SS1 H/H
    - 6.1.1 ScaleFactor
  - 6.2 Analysis for WSM SS1 V/V
    - 6.2.1 ScaleFactor
7. RAW DATA ANALYSIS
  - 7.1 Analysis for WVS
  - 7.2 Analysis for IMM
8. TELEMETRY ANALYSIS
  - 8.1 Number of Missing Lines
  - 8.2 Number of Gaps

---

## 1 - DATA SUMMARY

### 1.1 - Summary tables

[ [BACK TO MENU](#) ]

WVS				GM1				APM				IMM				WSM				MS			
Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Time	Pol	Modules
PDE	IS2	V/V	24	PDE	WS	H/H	44	PDE	IS1	V/H	1	PDE	IS1	V/V	1	PDE	WS	H/H	20	PDE	2010-08-23 05:40:33	V	320
PDK	IS2	V/V	26	PDK	WS	H/H	47	PDE	IS2	H/H	1	PDE	IS2	V/V	10	PDE	WS	V/V	15				
								PDE	IS4	V/H	2	PDE	IS4	H/H	1	PDK	WS	H/H	15				
								PDE	IS5	H/H	1	PDE	IS6	V/V	2	PDK	WS	V/V	7				
												PDK	IS2	H/H	2								
												PDK	IS2	V/V	2								

## 1.2 - Lists of products used

[ [BACK TO MENU](#) ]

[\[TXT\]](#) [\[XLS\]](#) List\_WVS\_products\_used  
[\[TXT\]](#) [\[XLS\]](#) List\_GM1\_products\_used  
[\[TXT\]](#) [\[XLS\]](#) List\_APM\_products\_used  
[\[TXT\]](#) [\[XLS\]](#) List\_IMM\_products\_used  
[\[TXT\]](#) [\[XLS\]](#) List\_WSM\_products\_used  
[\[TXT\]](#) [\[XLS\]](#) List\_MS\_products\_used

## 2 - AUXILIARY FILES ANALYSIS

### 2.1 - IECF operational ADFs list

[ [BACK TO MENU](#) ]

ADFs disseminated for ASAR
ASA_CON_AXVIEC20100608_125449_20100317_120410_20101231_000000
ASA_INS_AXVIEC20091217_114637_20090428_100000_20101231_235959
ASA_XCH_AXVIEC20091217_113006_20020301_000000_20101231_000000
ASA_XCA_AXVIEC20100608_123419_20100317_120410_20110101_000000

### 2.2 - Products with wrong ADFs




[ [BACK TO MENU](#) ]

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
WVS	0	0	0	0
GM1	0	0	0	0
APM	0	0	0	0
IMM	0	0	0	0
WSM	0	0	0	0

[\[TXT\]](#) [\[XLS\]](#) Check\_ADFs\_WVS  
[\[TXT\]](#) [\[XLS\]](#) Check\_ADFs\_GM1  
[\[TXT\]](#) [\[XLS\]](#) Check\_ADFs\_APM  
[\[TXT\]](#) [\[XLS\]](#) Check\_ADFs\_IMM  
[\[TXT\]](#) [\[XLS\]](#) Check\_ADFs\_WSM

### 3 - MODULE STEPPING PRODUCTS ANALYSIS













### 3.2 - H/H polarisation

[ [BACK TO MENU](#) ]

SECOND FIXED REFERENCE	PREVIOUS PRODUCT REFERENCE
Pre-launch reference (2001-02-09)	Previous product in the same polarisation





## 4 - CALIBRATION PULSES ANALYSIS

### 4.1 - Analysis for WVS IS2 V/V


#### 4.1.1 - Temporal Evolution Analysis for WVS IS2 V/V

[ BACK TO MENU ]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Calibration pulses for WVS IS2 V/V




Transmit power (P1 - P1a) for WVS IS2 V/V



#### 4.1.2 - All Rows Analysis for WVS IS2 V/V

[ [BACK TO MENU](#) ]





## 4.2 - Analysis for GM1 SS3 H/H

### 4.2.1 - Temporal Evolution Analysis for GM1 SS3 H/H


[ BACK TO MENU ]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]



Calibration pulses for GM1 SS3 H/H





Transmit power (P1 - P1a) for GM1 SS3 H/H



#### 4.2.2 - All Rows Analysis for GM1 SS3 H/H

[ [BACK TO MENU](#) ]






## 5 - DOPPLER ANALYSIS

### 5.1 - Analysis for WVS IS2 V/V

#### 5.1.1 - Doppler MAP Analysis for WVS IS2 V/V

[ [BACK TO MENU](#) ]






### 5.1.2 - Doppler ANX Analysis for WVS IS2 V/V

[ [BACK TO MENU](#) ]






## 5.2 - Analysis for GM1 SS1 H/H

### 5.2.1 - Doppler MAP Analysis for GM1 SS1 H/H

[ [BACK TO MENU](#) ]






### 5.2.2 - Doppler ANX Analysis for GM1 SS1 H/H

[ [BACK TO MENU](#) ]






### 5.3 - Doppler JUMPS Analysis for WSM

[ [BACK TO MENU](#) ]







## 6 - CHIRP ANALYSIS

### 6.1 - Analysis for WSM SS1 H/H

#### 6.1.1 - ScaleFactor

[ [BACK TO MENU](#) ]







## 6.2 - Analysis for WSM SS1 V/V

### 6.2.1 - ScaleFactor

[ [BACK TO MENU](#) ]






## 7 - RAW DATA ANALYSIS

### 7.1 - Analysis for WVS

[ [BACK TO MENU](#) ]

--	--	--	--






Channel	Statistics	DSS-B
MEAN I	mean	0.000629386
	stdev	1.04292e-07
MEAN Q	mean	0.000520800
	stdev	2.03704e-07
Channel	Statistics	DSS-B
STDEV I	mean	0.149813
	stdev	0.00115527
STDEV Q	mean	0.150312
	stdev	0.00117967

## 7.2 - Analysis for IMM

[ [BACK TO MENU](#) ]







## 8 - TELEMETRY ANALYSIS

Processing Center	Product	Gaps	Missing lines
PDE	ASA_WSM_1PNPDE20100823_043759_000001282092_00191_44333_6814.N1	0	34
PDK	ASA_WSM_1PNPDK20100823_025903_000002882092_00190_44332_9547.N1	10	3049
PDK	ASA_WSM_1PNPDK20100823_025903_000002882092_00190_44332_0021.N1	10	3049
PDK	ASA_WSM_1PNPDK20100823_043759_000001472092_00191_44333_9575.N1	0	34

### 8.1 - Number of Missing lines


[ BACK TO MENU ]





## 8.2 - Number of Gaps

[ [BACK TO MENU](#) ]



#####  
ASAR DAILY REPORT for 100823  
#####

MODE: DAILY  
ANALYSIS: ALL  
DATE: YESTERDAY

Analysis will be performed from 2010-08-23 00:00:00 to 2010-08-23 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/\_100823/

DATA SUMMARY

#####  
Summary will be performed from 2010-08-23 00:00:00 to 2010-08-23 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/\_100823/DATA\_SUMMARY

Creating directory ./RESULTS/DAILY/\_100823/DATA\_SUMMARY...  
Writing file ./RESULTS/DAILY/\_100823/DATA\_SUMMARY/Data\_summary.html...

\*\*\*\*\*  
Getting WVS products list from 2010-08-23 00:00:00 to 2010-08-23 23:59:59...  
Writing file ./RESULTS/DAILY/\_100823/DATA\_SUMMARY/List\_WVS\_products\_used.xls...  
Writing file ./RESULTS/DAILY/\_100823/DATA\_SUMMARY/List\_WVS\_products\_used.txt...

\*\*\*\*\*  
Getting GM1 products list from 2010-08-23 00:00:00 to 2010-08-23 23:59:59...  
Writing file ./RESULTS/DAILY/\_100823/DATA\_SUMMARY/List\_GM1\_products\_used.xls...  
Writing file ./RESULTS/DAILY/\_100823/DATA\_SUMMARY/List\_GM1\_products\_used.txt...

\*\*\*\*\*  
Getting APM products list from 2010-08-23 00:00:00 to 2010-08-23 23:59:59...  
Writing file ./RESULTS/DAILY/\_100823/DATA\_SUMMARY/List\_APM\_products\_used.xls...  
Writing file ./RESULTS/DAILY/\_100823/DATA\_SUMMARY/List\_APM\_products\_used.txt...

\*\*\*\*\*  
Getting IMM products list from 2010-08-23 00:00:00 to 2010-08-23 23:59:59...  
Writing file ./RESULTS/DAILY/\_100823/DATA\_SUMMARY/List\_IMM\_products\_used.xls...  
Writing file ./RESULTS/DAILY/\_100823/DATA\_SUMMARY/List\_IMM\_products\_used.txt...

\*\*\*\*\*  
Getting WSM products list from 2010-08-23 00:00:00 to 2010-08-23 23:59:59...  
Writing file ./RESULTS/DAILY/\_100823/DATA\_SUMMARY/List\_WSM\_products\_used.xls...  
Writing file ./RESULTS/DAILY/\_100823/DATA\_SUMMARY/List\_WSM\_products\_used.txt...

\*\*\*\*\*  
Getting MS products list from 2010-08-23 00:00:00 to 2010-08-23 23:59:59...  
Writing file ./RESULTS/DAILY/\_100823/DATA\_SUMMARY/List\_MS\_products\_used.xls...  
Writing file ./RESULTS/DAILY/\_100823/DATA\_SUMMARY/List\_MS\_products\_used.txt...

DATA SUMMARY completed  
#####

AUXILIARY FILES ANALYSIS

#####  
Analysis will be performed from 2010-08-23 00:00:00 to 2010-08-23 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/\_100823/AUXILIARY

Creating directory ./RESULTS/DAILY/\_100823/AUXILIARY...

\*\*\*\*\*  
Looking for the IECF operational ADFs list...



ADF filter 20100823\*current\_3\_IECF\_ADFs.txt  
 Found list 20100823\_030003\_current\_3\_IECF\_ADFs.txt...  
 Extracting ADFs...

ASA\_CON\_AXVIEC20100608\_125449\_20100317\_120410\_20101231\_000000  
 ASA\_INS\_AXVIEC20091217\_114637\_20090428\_100000\_20101231\_235959  
 ASA\_XCH\_AXVIEC20091217\_113006\_20020301\_000000\_20101231\_000000  
 ASA\_XCA\_AXVIEC20100608\_123419\_20100317\_120410\_20110101\_000000

Writing file ./RESULTS/DAILY/\_100823/AUXILIARY/ASAR\_ADFs\_IECF\_List3.html...  
 Writing file ./RESULTS/DAILY/\_100823/AUXILIARY/Auxiliary\_files\_summary.html...

\*\*\*\*\*

Analysing WVS products...

Writing file ./RESULTS/DAILY/\_100823/AUXILIARY/Check\_ADFs\_WVS.xls...  
 Writing file ./RESULTS/DAILY/\_100823/AUXILIARY/Check\_ADFs\_WVS.txt...

ASA_WVS_1PNPDE20100823_000850_000007792092_00188_44330_6755.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100823_002428_00000592092_00188_44330_6753.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100823_003102_000003302092_00188_44330_6757.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100823_005612_000003302092_00188_44330_6758.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100823_010057_000001802092_00188_44330_6772.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100823_011135_000008392092_00188_44330_6776.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100823_015140_00000592092_00189_44331_6780.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100823_020459_000007342092_00189_44331_6784.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100823_023657_000002252092_00189_44331_6795.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100823_033836_000001492092_00190_44332_6794.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100823_034051_000008692092_00190_44332_6811.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100823_041819_000010942092_00190_44332_6818.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100823_051749_000010492092_00191_44333_6813.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100823_055809_000017392092_00191_44333_6854.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100823_201204_000005842092_00200_44342_6983.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100823_202422_000011692092_00200_44342_6987.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100823_210332_000001502092_00200_44342_6999.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100823_215249_00000602092_00201_44343_7000.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100823_215511_000002692092_00201_44343_7001.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100823_220152_000013492092_00201_44343_7003.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100823_224359_000002702092_00201_44343_7005.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100823_224744_000007642092_00201_44343_7017.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100823_230927_000004202092_00202_44344_7018.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100823_233532_000008692092_00202_44344_7022.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100823_071624_000001502092_00192_44334_9678.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100823_073845_000017992092_00192_44334_9682.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100823_084954_000005852092_00193_44335_9719.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100823_091921_000019342092_00193_44335_9724.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100823_102422_000009442092_00194_44336_9754.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100823_105957_000002402092_00194_44336_9753.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100823_110601_000001942092_00194_44336_9756.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100823_111054_000010042092_00194_44336_9755.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100823_113008_000000752092_00195_44337_9759.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100823_114744_000010942092_00195_44337_9796.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100823_121331_000004352092_00195_44337_9798.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100823_124032_000002402092_00195_44337_9800.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100823_125534_000006692092_00195_44337_9802.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100823_132946_000005842092_00196_44338_9833.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100823_134147_000000892092_00196_44338_9835.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100823_142108_000003002092_00196_44338_9839.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100823_143103_000001192092_00196_44338_9840.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100823_143813_000001192092_00197_44339_9843.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100823_152428_000010492092_00197_44339_9867.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100823_160144_000011992092_00197_44339_9872.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100823_170216_000012142092_00198_44340_0002.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100823_174220_000012292092_00198_44340_0006.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100823_174220_000012292092_00198_44340_0008.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100823_183630_000016042092_00199_44341_0044.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK



ASA\_WVS\_1PNPDK20100823\_192256\_000004502092\_00199\_44341\_0042.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_WVS\_1PNPDK20100823\_193349\_000001342092\_00199\_44341\_0046.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK

\*\*\*\*\*

Analysing GM1 products...

Writing file ./RESULTS/DAILY/\_100823/AUXILIARY/Check\_ADFs\_GM1.xls...

Writing file ./RESULTS/DAILY/\_100823/AUXILIARY/Check\_ADFs\_GM1.txt...

ASA\_GM1\_1PNPDE20100823\_002233\_000001082092\_00188\_44330\_6754.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDE20100823\_002604\_000002952092\_00188\_44330\_6756.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDE20100823\_003718\_000007912092\_00188\_44330\_6759.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDE20100823\_010616\_000003142092\_00188\_44330\_6773.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDE20100823\_012620\_000001082092\_00189\_44331\_6774.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDE20100823\_013255\_000011242092\_00189\_44331\_6777.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDE20100823\_015328\_000001322092\_00189\_44331\_6778.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDE20100823\_015623\_000005132092\_00189\_44331\_6781.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDE20100823\_021754\_000007492092\_00189\_44331\_6782.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDE20100823\_023430\_000001442092\_00189\_44331\_6783.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDE20100823\_024119\_000005012092\_00189\_44331\_6786.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDE20100823\_025124\_000004532092\_00189\_44331\_6785.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDE20100823\_030357\_000005552092\_00190\_44332\_6787.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDE20100823\_031402\_000010692092\_00190\_44332\_6797.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDE20100823\_033644\_000001082092\_00190\_44332\_6796.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDE20100823\_035903\_000006222092\_00190\_44332\_6812.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDE20100823\_041443\_000002112092\_00190\_44332\_6822.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDE20100823\_044031\_000002952092\_00191\_44333\_6823.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDE20100823\_044716\_000000842092\_00191\_44333\_6821.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDE20100823\_044950\_000006282092\_00191\_44333\_6820.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDE20100823\_050426\_000004342092\_00191\_44333\_6819.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDE20100823\_051345\_000001202092\_00191\_44333\_6815.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDE20100823\_053907\_000000782092\_00191\_44333\_6845.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDE20100823\_054154\_000005982092\_00191\_44333\_6846.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDE20100823\_055430\_000002172092\_00191\_44333\_6863.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDE20100823\_063404\_000003922092\_00192\_44334\_6862.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDE20100823\_064715\_000001992092\_00192\_44334\_6858.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDE20100823\_065309\_000001442092\_00192\_44334\_6857.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDE20100823\_065634\_000005132092\_00192\_44334\_6856.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDE20100823\_070624\_000003862092\_00192\_44334\_6855.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDE20100823\_195555\_000000962092\_00200\_44342\_6981.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDE20100823\_200320\_000001872092\_00200\_44342\_6982.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDE20100823\_200833\_000002112092\_00200\_44342\_6984.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDE20100823\_204429\_000008642092\_00200\_44342\_6986.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDE20100823\_210134\_000000602092\_00200\_44342\_6988.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDE20100823\_210136\_000001082092\_00200\_44342\_6997.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDE20100823\_211127\_000010512092\_00200\_44342\_6998.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDE20100823\_213707\_000001502092\_00201\_44343\_7002.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDE20100823\_222505\_000008162092\_00201\_44343\_7004.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDE20100823\_230118\_000003082092\_00202\_44344\_7019.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDE20100823\_233405\_000000782092\_00202\_44344\_7020.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDE20100823\_235051\_000001202092\_00202\_44344\_7021.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDE20100823\_235402\_000004042092\_00202\_44344\_7023.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDK20100823\_071942\_000006892092\_00192\_44334\_9679.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDK20100823\_073529\_000001932092\_00192\_44334\_9680.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDK20100823\_081034\_000004472092\_00193\_44335\_9681.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDK20100823\_081938\_000002052092\_00193\_44335\_9683.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDK20100823\_082218\_000001872092\_00193\_44335\_9717.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDK20100823\_083930\_000006222092\_00193\_44335\_9718.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDK20100823\_090018\_000006712092\_00193\_44335\_9720.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDK20100823\_091639\_000001572092\_00193\_44335\_9721.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDK20100823\_095212\_000004412092\_00194\_44336\_9725.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDK20100823\_101533\_000001082092\_00194\_44336\_9751.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDK20100823\_104054\_000006712092\_00194\_44336\_9752.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDK20100823\_105646\_000001872092\_00194\_44336\_9757.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDK20100823\_113209\_000006042092\_00195\_44337\_9760.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK  
 ASA\_GM1\_1PNPDK20100823\_113209\_000006042092\_00195\_44337\_9761.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK

ASA_GM1_1PNPDK20100823_122130_000006892092_00195_44337_9797.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100823_123805_000001442092_00195_44337_9799.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100823_124517_000006162092_00195_44337_9801.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100823_130731_000006042092_00196_44338_9803.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100823_132327_000003742092_00196_44338_9832.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100823_134538_000006162092_00196_44338_9834.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100823_135558_000011422092_00196_44338_9836.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100823_141837_000001442092_00196_44338_9838.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100823_142658_000002412092_00196_44338_9837.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100823_143342_000002712092_00196_44338_9841.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100823_144327_000007432092_00197_44339_9842.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100823_145952_000000722092_00197_44339_9844.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100823_150815_000003262092_00197_44339_9866.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100823_154242_000008642092_00197_44339_9868.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100823_155910_000001502092_00197_44339_9869.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100823_162224_000002232092_00198_44340_9870.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100823_162838_000003262092_00198_44340_9871.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100823_163653_000000842092_00198_44340_9873.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100823_163658_000001502092_00198_44340_9899.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100823_164051_000000962092_00198_44340_9900.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100823_164615_000001262092_00198_44340_0000.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100823_165142_000004712092_00198_44340_0001.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100823_172318_000008882092_00198_44340_0003.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100823_174018_000001142092_00198_44340_0005.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100823_180840_000000722092_00199_44341_0004.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100823_181131_000002592092_00199_44341_0007.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100823_181131_000002592092_00199_44341_0009.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100823_181438_000001692092_00199_44341_0037.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100823_182341_000003142092_00199_44341_0040.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100823_190354_000008342092_00199_44341_0041.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100823_192023_000001502092_00199_44341_0043.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100823_193102_000001632092_00199_44341_0045.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100823_193649_000006042092_00199_44341_0047.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

\*\*\*\*\*

Analysing APM products...

Writing file ./RESULTS/DAILY/\_100823/AUXILIARY/Check\_ADFs\_APM.xls...

Writing file ./RESULTS/DAILY/\_100823/AUXILIARY/Check\_ADFs\_APM.txt...

ASA_APM_1PNPDE20100823_024939_000000852092_00189_44331_6803.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20100823_051548_000000432092_00191_44333_6809.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20100823_065533_000000432092_00192_44334_6843.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20100823_070509_000000572092_00192_44334_6864.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20100823_134410_000000682092_00196_44338_6963.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

\*\*\*\*\*

Analysing IMM products...

Writing file ./RESULTS/DAILY/\_100823/AUXILIARY/Check\_ADFs\_IMM.xls...

Writing file ./RESULTS/DAILY/\_100823/AUXILIARY/Check\_ADFs\_IMM.txt...

ASA_IMM_1PNPDE20100823_000730_000000732092_00188_44330_6769.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100823_031312_000000382092_00190_44332_6804.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100823_033150_000002822092_00190_44332_6791.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100823_044847_000000512092_00191_44333_6824.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100823_050052_000002032092_00191_44333_6806.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100823_101244_000000532092_00194_44336_6905.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100823_110427_000000882092_00194_44336_6932.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100823_110956_000000532092_00194_44336_6933.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100823_162604_000001422092_00198_44340_6969.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100823_165929_000001302092_00198_44340_6975.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100823_180430_000002392092_00199_44341_6976.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100823_200628_000001142092_00200_44342_6980.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

```

ASA_IMM_1PNPDE20100823_202232_000001032092_00200_44342_6985.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100823_215005_000001592092_00201_44343_7016.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20100823_064456_000001292092_00192_44334_9675.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20100823_080921_000000622092_00193_44335_9692.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20100823_163931_000000672092_00198_44340_9875.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20100823_163931_000000672092_00198_44340_9876.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

```

```
*****
```

```
Analysing WSM products...
```

```
Writing file ./RESULTS/DAILY/_100823/AUXILIARY/Check_ADFs_WSM.xls...
```

```
Writing file ./RESULTS/DAILY/_100823/AUXILIARY/Check_ADFs_WSM.txt...
```

```

ASA_WSM_1PNPDE20100823_005037_000002882092_00188_44330_6767.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100823_012821_000002692092_00189_44331_6801.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100823_023030_000002392092_00189_44331_6802.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100823_040929_000003062092_00190_44332_6817.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100823_043759_000001282092_00191_44333_6814.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100823_044533_000000982092_00191_44333_6827.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100823_051145_000001162092_00191_44333_6808.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100823_055158_000001472092_00191_44333_6844.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100823_062756_000003672092_00192_44334_6847.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100823_062756_000003672092_00192_44334_6848.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100823_065040_000001472092_00192_44334_6842.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100823_071255_000002082092_00192_44334_6865.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100823_082531_000002322092_00193_44335_6885.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100823_083007_000000982092_00193_44335_6886.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100823_095942_000001222092_00194_44336_6902.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100823_100202_000001222092_00194_44336_6903.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100823_100438_000000982092_00194_44336_6904.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100823_101728_000004162092_00194_44336_6906.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100823_105209_000002752092_00194_44336_6931.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100823_112831_000000982092_00195_44337_6935.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100823_120637_000004162092_00195_44337_6937.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100823_141505_000002082092_00196_44338_6965.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100823_150517_000001772092_00197_44339_6966.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100823_151903_000001712092_00197_44339_6968.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100823_155711_000001162092_00197_44339_6962.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100823_181001_000000862092_00199_44341_6977.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100823_182902_000003982092_00199_44341_6979.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100823_191755_000001472092_00199_44341_6978.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100823_205900_000001532092_00200_44342_6995.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100823_210652_000002692092_00200_44342_6996.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100823_214249_000004102092_00201_44343_7013.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100823_220024_000000862092_00201_44343_7014.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100823_223848_000002452092_00201_44343_7012.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100823_232142_000003002092_00202_44344_7034.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100823_232723_000003922092_00202_44344_7035.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100823_025903_000002882092_00190_44332_0021.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100823_025903_000002882092_00190_44332_9547.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100823_043759_000001472092_00191_44333_9575.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100823_064043_000002392092_00192_44334_9674.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100823_073119_000002452092_00192_44334_9691.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100823_081807_000000862092_00193_44335_9693.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100823_091137_000003002092_00193_44335_9731.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100823_100546_000003922092_00194_44336_9732.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100823_114222_000003062092_00195_44337_9772.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100823_123301_000003002092_00195_44337_9814.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100823_131739_000003492092_00196_44338_9816.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100823_145555_000002322092_00197_44339_9848.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100823_150114_000003432092_00197_44339_9853.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100823_151548_000005082092_00197_44339_9883.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100823_163411_000001592092_00198_44340_9878.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100823_164239_000001652092_00198_44340_9884.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100823_181734_000000672092_00199_44341_0016.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100823_181915_000002632092_00199_44341_0018.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

```





```

ASA_WSM_1PNPDK20100823_195115_000002752092_00200_44342_0054.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100823_195742_000003362092_00200_44342_0055.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100823_213946_000002142092_00201_44343_0075.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100823_231709_000002942092_00202_44344_0091.N1   ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

```

```

AUXILIARY FILES ANALYSIS completed
#####

```

```

MODULE STEPPING ANALYSIS
#####
Analysis will be performed from 2010-08-23 00:00:00 to 2010-08-23 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_100823/MODULE_STEPPING

```

```

Creating directory ./RESULTS/DAILY/_100823/MODULE_STEPPING...
Creating directory ./RESULTS/DAILY/_100823/MODULE_STEPPING/FIRST_REFERENCE...
Creating directory ./RESULTS/DAILY/_100823/MODULE_STEPPING/SECOND_REFERENCE...
Creating directory ./RESULTS/DAILY/_100823/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE...
Deleting old files...

```

```

*****
*****

```

```

Creating images comparing with second reference...

Exporting results to the directory ../../RESULTS/DAILY/_100823/MODULE_STEPPING/SECOND_REFERENCE...

```

```

Polarization: H
Reference product: ASA_MS_0PNPDK20010209_135042_0000009A024_00180_11700_0052.N1
Test product: ASA_MS_0PNPDK20100822_061210_000000162092_00177_44319_0191.N1
  H
  H
../../RESULTS/DAILY/_100823/MODULE_STEPPING/SECOND_REFERENCE/TGH_20100822_061210-20010209_135042.png
../../RESULTS/DAILY/_100823/MODULE_STEPPING/SECOND_REFERENCE/TPH_20100822_061210-20010209_135042.png
../../RESULTS/DAILY/_100823/MODULE_STEPPING/SECOND_REFERENCE/RGH_20100822_061210-20010209_135042.png
../../RESULTS/DAILY/_100823/MODULE_STEPPING/SECOND_REFERENCE/RPH_20100822_061210-20010209_135042.png

```

```

Polarization: V
Reference product: ASA_MS_0PNPDK20010209_140823_0000009A024_00180_11700_0054.N1
Test product: ASA_MS_0PNPDE20100823_054033_000000162092_00191_44333_0571.N1
  V
  V
../../RESULTS/DAILY/_100823/MODULE_STEPPING/SECOND_REFERENCE/TGV_20100823_054033-20010209_140823.png
../../RESULTS/DAILY/_100823/MODULE_STEPPING/SECOND_REFERENCE/TPV_20100823_054033-20010209_140823.png
../../RESULTS/DAILY/_100823/MODULE_STEPPING/SECOND_REFERENCE/RGV_20100823_054033-20010209_140823.png
../../RESULTS/DAILY/_100823/MODULE_STEPPING/SECOND_REFERENCE/RPV_20100823_054033-20010209_140823.png

```

```

*****
*****

```

```

Creating images comparing with previous product reference...

Exporting results to the directory ../../RESULTS/DAILY/_100823/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE...

```

```

Polarization: H
Reference product: ASA_MS_0PNPDK20100820_071525_000000162092_00149_44291_0189.N1
Test product: ASA_MS_0PNPDK20100822_061210_000000162092_00177_44319_0191.N1
  H
  H
../../RESULTS/DAILY/_100823/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TGH_20100822_061210-20100820_071525.png
../../RESULTS/DAILY/_100823/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TPH_20100822_061210-20100820_071525.png
../../RESULTS/DAILY/_100823/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RGH_20100822_061210-20100820_071525.png
../../RESULTS/DAILY/_100823/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RPH_20100822_061210-20100820_071525.png

```

```

Polarization: V
Reference product: ASA_MS_0PNPDK20100821_064348_000000162092_00163_44305_0190.N1
Test product: ASA_MS_0PNPDE20100823_054033_000000162092_00191_44333_0571.N1

```

```
V
V
../../../../RESULTS/DAILY/_100823/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TGV_20100823_054033-20100821_064348.png
../../../../RESULTS/DAILY/_100823/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TPV_20100823_054033-20100821_064348.png
../../../../RESULTS/DAILY/_100823/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RGV_20100823_054033-20100821_064348.png
../../../../RESULTS/DAILY/_100823/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RPV_20100823_054033-20100821_064348.png
```

MODULE\_STEPPING ANALYSIS completed

#####

CALIBRATION PULSES ANALYSIS

#####

Creating directory ./RESULTS/DAILY/\_100823/CALIBRATION\_PULSES...

\*\*\*\*\*  
\*\*\*\*\*

ALL ROWS Analysis will be performed from 2010-08-23 00:00:00 to 2010-08-23 23:59:59

Analysing products WVS IS2 V/V

Writing image ../../RESULTS/DAILY/\_100823//CALIBRATION\_PULSES/Calibration\_pulses\_all\_rows\_WVS\_IS2\_VV.png...

Analysing products GM1 SS3 H/H

Writing image ../../RESULTS/DAILY/\_100823//CALIBRATION\_PULSES/Calibration\_pulses\_all\_rows\_GM1\_SS3\_HH.png...

\*\*\*\*\*  
\*\*\*\*\*

TEMPORAL EVOLUTION Analysis will be performed from 2010-08-23 00:00:00 to 2010-08-23 23:59:59

Analysing products WVS IS2 V/V

Getting calibration pulses data for WVS IS2 V/V from 2010-08-23 00:00:00 to 2010-08-23 23:59:59. Rows: 1/5/9/13/17/21/25/29

Writing file ./RESULTS/DAILY/\_100823/CALIBRATION\_PULSES/Calibration\_pulses\_data\_WVS\_IS2\_VV\_2010-08-23\_1.dat...

Writing ../../RESULTS/DAILY/\_100823//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_WVS\_IS2\_VV\_1.png...

Writing ../../RESULTS/DAILY/\_100823//CALIBRATION\_PULSES/Transmit\_Power\_WVS\_IS2\_VV\_1.png...

Getting calibration pulses data for WVS IS2 V/V from 2010-08-23 00:00:00 to 2010-08-23 23:59:59. Rows: 2/6/10/14/18/22/26/30

Writing file ./RESULTS/DAILY/\_100823/CALIBRATION\_PULSES/Calibration\_pulses\_data\_WVS\_IS2\_VV\_2010-08-23\_2.dat...

Writing ../../RESULTS/DAILY/\_100823//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_WVS\_IS2\_VV\_2.png...

Writing ../../RESULTS/DAILY/\_100823//CALIBRATION\_PULSES/Transmit\_Power\_WVS\_IS2\_VV\_2.png...

Getting calibration pulses data for WVS IS2 V/V from 2010-08-23 00:00:00 to 2010-08-23 23:59:59. Rows: 3/7/11/15/19/23/27/31

Writing file ./RESULTS/DAILY/\_100823/CALIBRATION\_PULSES/Calibration\_pulses\_data\_WVS\_IS2\_VV\_2010-08-23\_3.dat...

Writing ../../RESULTS/DAILY/\_100823//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_WVS\_IS2\_VV\_3.png...

Writing ../../RESULTS/DAILY/\_100823//CALIBRATION\_PULSES/Transmit\_Power\_WVS\_IS2\_VV\_3.png...

Getting calibration pulses data for WVS IS2 V/V from 2010-08-23 00:00:00 to 2010-08-23 23:59:59. Rows: 4/8/12/16/20/24/28/32

Writing file ./RESULTS/DAILY/\_100823/CALIBRATION\_PULSES/Calibration\_pulses\_data\_WVS\_IS2\_VV\_2010-08-23\_4.dat...

Writing ../../RESULTS/DAILY/\_100823//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_WVS\_IS2\_VV\_4.png...

Writing ../../RESULTS/DAILY/\_100823//CALIBRATION\_PULSES/Transmit\_Power\_WVS\_IS2\_VV\_4.png...

Analysing products GM1 SS3 H/H

Getting calibration pulses data for GM1 SS3 H/H from 2010-08-23 00:00:00 to 2010-08-23 23:59:59. Rows: 1/5/9/13/17/21/25/29

Writing file ./RESULTS/DAILY/\_100823/CALIBRATION\_PULSES/Calibration\_pulses\_data\_GM1\_SS3\_HH\_2010-08-23\_1.dat...

Writing ../../RESULTS/DAILY/\_100823//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_GM1\_SS3\_HH\_1.png...

Writing ../../RESULTS/DAILY/\_100823//CALIBRATION\_PULSES/Transmit\_Power\_GM1\_SS3\_HH\_1.png...

Getting calibration pulses data for GM1 SS3 H/H from 2010-08-23 00:00:00 to 2010-08-23 23:59:59. Rows: 2/6/10/14/18/22/26/30

Writing file ./RESULTS/DAILY/\_100823/CALIBRATION\_PULSES/Calibration\_pulses\_data\_GM1\_SS3\_HH\_2010-08-23\_2.dat...

Writing ../../RESULTS/DAILY/\_100823//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_GM1\_SS3\_HH\_2.png...

Writing ../../RESULTS/DAILY/\_100823//CALIBRATION\_PULSES/Transmit\_Power\_GM1\_SS3\_HH\_2.png...

Getting calibration pulses data for GM1 SS3 H/H from 2010-08-23 00:00:00 to 2010-08-23 23:59:59. Rows: 3/7/11/15/19/23/27/31  
Writing file ./RESULTS/DAILY/\_100823/CALIBRATION\_PULSES/Calibration\_pulses\_data\_GM1\_SS3\_HH\_2010-08-23\_3.dat...  
Writing ../../RESULTS/DAILY/\_100823//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_GM1\_SS3\_HH\_3.png...  
Writing ../../RESULTS/DAILY/\_100823//CALIBRATION\_PULSES/Transmit\_Power\_GM1\_SS3\_HH\_3.png...

Getting calibration pulses data for GM1 SS3 H/H from 2010-08-23 00:00:00 to 2010-08-23 23:59:59. Rows: 4/8/12/16/20/24/28/32  
Writing file ./RESULTS/DAILY/\_100823/CALIBRATION\_PULSES/Calibration\_pulses\_data\_GM1\_SS3\_HH\_2010-08-23\_4.dat...  
Writing ../../RESULTS/DAILY/\_100823//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_GM1\_SS3\_HH\_4.png...  
Writing ../../RESULTS/DAILY/\_100823//CALIBRATION\_PULSES/Transmit\_Power\_GM1\_SS3\_HH\_4.png...

CALIBRATION PULSES ANALYSIS completed  
#####

DOPPLER ANALYSIS  
#####  
Creating directory ./RESULTS/DAILY/\_100823/DOPPLER...

\*\*\*\*\*  
\*\*\*\*\*  
DOPPLER ANX Analysis will be performed from 2010-08-23 00:00:00 to 2010-08-23 23:59:59

Analysing products WVS IS2 V/V  
Getting doppler data for WVS IS2 V/V from 2010-08-23 00:00:00 to 2010-08-23 23:59:59...  
Writing file ./RESULTS/DAILY/\_100823/DOPPLER/Doppler\_data\_WVS\_IS2\_VV\_2010-08-23.dat...  
Running IDL program...  
Writing file ../../RESULTS/DAILY/\_100823/DOPPLER/DOPPLER\_ANX\_WVS\_IS2\_VV.png...

Analysing products GM1 SS1 H/H  
Getting doppler data for GM1 SS1 H/H from 2010-08-23 00:00:00 to 2010-08-23 23:59:59...  
Writing file ./RESULTS/DAILY/\_100823/DOPPLER/Doppler\_data\_GM1\_SS1\_HH\_2010-08-23.dat...  
Running IDL program...  
Writing file ../../RESULTS/DAILY/\_100823/DOPPLER/DOPPLER\_ANX\_GM1\_SS1\_HH.png...

\*\*\*\*\*  
\*\*\*\*\*  
DOPPLER JUMPS Analysis will be performed on WSM products from 2010-08-23 00:00:00 to 2010-08-23 23:59:59

Analysing by default products WSM  
Getting doppler jumps data for WSM from 2010-08-23 00:00:00 to 2010-08-23 23:59:59...  
Writing file ./RESULTS/DAILY/\_100823/DOPPLER/Doppler\_Jumps\_data\_WSM\_2010-08-23.dat...  
Running IDL program...  
Writing file ../../RESULTS/DAILY/\_100823/DOPPLER/DOPPLER\_JUMPS\_ANX\_WSM.png...  
Writing file ../../RESULTS/DAILY/\_100823/DOPPLER/DOPPLER\_JUMPS\_Date\_WSM.png...

\*\*\*\*\*  
\*\*\*\*\*  
DOPPLER MAP Analysis will be performed from 2010-08-23 00:00:00 to 2010-08-23 23:59:59

Analysing products WVS IS2 V/V  
Loading predicted doppler values....  
Phase: descending  
Found data...  
Computing mean error doppler estimated-predicted...  
Mean error = -33.075523 Hz  
Writing file ../../RESULTS/DAILY/\_100823//DOPPLER/DOPPLER\_Estimated-Predicted-MeanError\_WVS\_IS2\_VV\_desc.jpg...  
Writing file ../../RESULTS/DAILY/\_100823//DOPPLER/DOPPLER\_Absolute\_WVS\_IS2\_VV\_desc.jpg...

```
*****
Loading predicted doppler values....
Phase: ascending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -24.521140 Hz
Writing file ../../RESULTS/DAILY/_100823//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_WVS_IS2_VV_asc.jpg...
Writing file ../../RESULTS/DAILY/_100823//DOPPLER/DOPPLER_Absolute_WVS_IS2_VV_asc.jpg...
*****
```

```
Analysing products GM1 SS1 H/H
Loading predicted doppler values....
Phase: descending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -4.1227965 Hz
Writing file ../../RESULTS/DAILY/_100823//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_GM1_SS1_HH_desc.jpg...
Writing file ../../RESULTS/DAILY/_100823//DOPPLER/DOPPLER_Absolute_GM1_SS1_HH_desc.jpg...
*****
```

```
Loading predicted doppler values....
Phase: ascending
Found data...
Computing mean error doppler estimated-predicted...
Mean error = -10.599196 Hz
Writing file ../../RESULTS/DAILY/_100823//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_GM1_SS1_HH_asc.jpg...
Writing file ../../RESULTS/DAILY/_100823//DOPPLER/DOPPLER_Absolute_GM1_SS1_HH_asc.jpg...
*****
```

```
DOPPLER ANALYSIS completed
#####
```

```
CHIRP ANALYSIS
#####
Creating directory ./RESULTS/DAILY/_100823/CHIRP...
```

```
*****
*****
CHIRP Analysis will be performed from 2010-08-23 00:00:00 to 2010-08-23 23:59:59
```

```
Analysing products WSM SS1 H/H
*****
Getting ScaleFactor data for WSM SS1 H/H from 2010-08-23 00:00:00 to 2010-08-23 23:59:59...
Writing file ./RESULTS/DAILY/_100823/CHIRP/ScaleFactor_data_WSM_SS1_HH_2010-08-23.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/_100823/CHIRP/ScaleFactor_ANX_WSM_SS1_HH.png...
Writing file ../../RESULTS/DAILY/_100823/CHIRP/ScaleFactor_DATE_WSM_SS1_HH.png...
```

```
Analysing products WSM SS1 V/V
*****
Getting ScaleFactor data for WSM SS1 V/V from 2010-08-23 00:00:00 to 2010-08-23 23:59:59...
Writing file ./RESULTS/DAILY/_100823/CHIRP/ScaleFactor_data_WSM_SS1_VV_2010-08-23.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/_100823/CHIRP/ScaleFactor_ANX_WSM_SS1_VV.png...
Writing file ../../RESULTS/DAILY/_100823/CHIRP/ScaleFactor_DATE_WSM_SS1_VV.png...
```

```
CHIRP ANALYSIS completed
#####
```

RAW DATA ANALYSIS

#####  
Analysis will be performed from 2010-08-23 00:00:00 to 2010-08-23 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/\_100823/RAW\_DATA

Creating directory ./RESULTS/DAILY/\_100823/RAW\_DATA...

\*\*\*\*\*  
Getting raw data for WVS from 2010-08-23 00:00:00 to 2010-08-23 23:59:59...  
Writing file ./RESULTS/DAILY/\_100823/RAW\_DATA/Raw\_data\_WVS\_2010-08-23.dat...  
Running IDL program to create graphs...

Creating image ../../RESULTS/DAILY/\_100823/RAW\_DATA/Raw\_data\_WVS\_input\_mean.png...  
Creating image ../../RESULTS/DAILY/\_100823/RAW\_DATA/Raw\_data\_WVS\_input\_stdev.png...  
Creating image ../../RESULTS/DAILY/\_100823/RAW\_DATA/Raw\_data\_WVS\_gain\_imbalance.png...

\*\*\*\*\*  
Getting raw data for IMM from 2010-08-23 00:00:00 to 2010-08-23 23:59:59...  
Writing file ./RESULTS/DAILY/\_100823/RAW\_DATA/Raw\_data\_IMM\_2010-08-23.dat...  
Running IDL program to create graphs...

Creating image ../../RESULTS/DAILY/\_100823/RAW\_DATA/Raw\_data\_IMM\_input\_mean.png...  
Creating image ../../RESULTS/DAILY/\_100823/RAW\_DATA/Raw\_data\_IMM\_input\_stdev.png...  
Creating image ../../RESULTS/DAILY/\_100823/RAW\_DATA/Raw\_data\_IMM\_gain\_imbalance.png...

RAW DATA ANALYSIS completed

#####

TELEMETRY ANALYSIS

#####  
Analysis will be performed from 2010-08-23 00:00:00 to 2010-08-23 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/\_100823/TELEMETRY

Creating directory ./RESULTS/DAILY/\_100823/TELEMETRY...

Looking for gaps and missing lines in WVS products...

\*\*\*\*\*  
Checking 24 products from PDE...  
Checking 26 products from PDK...

Looking for gaps and missing lines in GM1 products...

\*\*\*\*\*  
Checking 44 products from PDE...  
Checking 47 products from PDK...

Looking for gaps and missing lines in APM products...

\*\*\*\*\*  
Checking 5 products from PDE...  
No products from PDK...

Looking for gaps and missing lines in IMM products...

\*\*\*\*\*  
Checking 14 products from PDE...  
Checking 4 products from PDK...

Looking for gaps and missing lines in WSM products...

\*\*\*\*\*  
Checking 35 products from PDE...  
Found product...ASA\_WSM\_1PNPDE20100823\_043759\_000001282092\_00191\_44333\_6814.N1 / 0 gaps / 34 missing lines  
Checking 22 products from PDK...  
Found product...ASA\_WSM\_1PNPDK20100823\_025903\_000002882092\_00190\_44332\_9547.N1 / 10 gaps / 3049 missing lines

Found product...ASA\_WSM\_1PNPDK20100823\_025903\_000002882092\_00190\_44332\_0021.N1 / 10 gaps / 3049 missing lines  
Found product...ASA\_WSM\_1PNPDK20100823\_043759\_000001472092\_00191\_44333\_9575.N1 / 0 gaps / 34 missing lines

Creating graph of missing lines and gaps...  
\*\*\*\*\*  
Creating image: ./RESULTS/DAILY/\_100823/TELEMETRY/TELEMETRY\_Missing\_lines.png...  
Creating image: ./RESULTS/DAILY/\_100823/TELEMETRY/TELEMETRY\_Gaps.png...

TELEMETRY ANALYSIS completed  
#####

HTML REPORT generation  
#####

Building file ./RESULTS/DAILY/\_100823/asarReport.html...  
Building DATA SUMMARY section...  
Building AUXILIARY FILES ANALYSIS section...  
Building MODULE STEPPING ANALYSIS section...  
Building CALIBRATION PULSES ANALYSIS section...  
Building DOPPLER ANALYSIS section...  
Building CHIRP ANALYSIS section...  
Building RAW DATA ANALYSIS section...  
Building TELEMETRY ANALYSIS section...

HTML REPORT generation completed  
#####



Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
ASA_APM_1PNPDE20100823_024939_000000852092_00189_44331_6803.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20100823_051548_000000432092_00191_44333_6809.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20100823_065533_000000432092_00192_44334_6843.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20100823_070509_000000572092_00192_44334_6864.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20100823_134410_000000682092_00196_44338_6963.N1	OK	OK	OK	OK





ASA_GM1_1PNPDK20100823_141837_000001442092_00196_44338_9838.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100823_142658_000002412092_00196_44338_9837.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100823_143342_000002712092_00196_44338_9841.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100823_144327_000007432092_00197_44339_9842.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100823_145952_00000722092_00197_44339_9844.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100823_150815_000003262092_00197_44339_9866.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100823_154242_000008642092_00197_44339_9868.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100823_155910_000001502092_00197_44339_9869.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100823_162224_000002232092_00198_44340_9870.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100823_162838_000003262092_00198_44340_9871.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100823_163653_000000842092_00198_44340_9873.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100823_163658_000001502092_00198_44340_9899.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100823_164051_000000962092_00198_44340_9900.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100823_164615_000001262092_00198_44340_0000.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100823_165142_000004712092_00198_44340_0001.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100823_172318_000008882092_00198_44340_0003.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100823_174018_000001142092_00198_44340_0005.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100823_180840_000000722092_00199_44341_0004.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100823_181131_000002592092_00199_44341_0007.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100823_181131_000002592092_00199_44341_0009.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100823_181438_000001692092_00199_44341_0037.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100823_182341_000003142092_00199_44341_0040.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100823_190354_000008342092_00199_44341_0041.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100823_192023_000001502092_00199_44341_0043.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100823_193102_000001632092_00199_44341_0045.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100823_193649_000006042092_00199_44341_0047.N1	OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.


Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_IMM_1PNPDE20100823_000730_000000732092_00188_44330_6769.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100823_031312_000000382092_00190_44332_6804.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100823_033150_000002822092_00190_44332_6791.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100823_044847_000000512092_00191_44333_6824.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100823_050052_000002032092_00191_44333_6806.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100823_101244_000000532092_00194_44336_6905.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100823_110427_000000882092_00194_44336_6932.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100823_110956_000000532092_00194_44336_6933.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100823_162604_000001422092_00198_44340_6969.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100823_165929_000001302092_00198_44340_6975.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100823_180430_000002392092_00199_44341_6976.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100823_200628_000001142092_00200_44342_6980.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100823_202232_000001032092_00200_44342_6985.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100823_215005_000001592092_00201_44343_7016.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20100823_064456_000001292092_00192_44334_9675.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20100823_080921_000000622092_00193_44335_9692.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20100823_163931_000000672092_00198_44340_9875.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20100823_163931_000000672092_00198_44340_9876.N1					OK	OK	OK	OK




Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WVS_1PNPDE20100823_000850_000007792092_00188_44330_6755.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100823_002428_00000592092_00188_44330_6753.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100823_003102_000003302092_00188_44330_6757.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100823_005612_000003302092_00188_44330_6758.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100823_010057_000001802092_00188_44330_6772.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100823_011135_000008392092_00188_44330_6776.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100823_015140_00000592092_00189_44331_6780.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100823_020459_000007342092_00189_44331_6784.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100823_023657_000002252092_00189_44331_6795.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100823_033836_000001492092_00190_44332_6794.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100823_034051_000008692092_00190_44332_6811.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100823_041819_000010942092_00190_44332_6818.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100823_051749_000010492092_00191_44333_6813.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100823_055809_000017392092_00191_44333_6854.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100823_201204_000005842092_00200_44342_6983.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100823_202422_000011692092_00200_44342_6987.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100823_210332_000001502092_00200_44342_6999.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100823_215249_00000602092_00201_44343_7000.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100823_215511_000002692092_00201_44343_7001.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100823_220152_000013492092_00201_44343_7003.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100823_224359_000002702092_00201_44343_7005.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100823_224744_000007642092_00201_44343_7017.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100823_230927_000004202092_00202_44344_7018.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100823_233532_000008692092_00202_44344_7022.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100823_071624_000001502092_00192_44334_9678.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100823_073845_000017992092_00192_44334_9682.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100823_084954_000005852092_00193_44335_9719.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100823_091921_000019342092_00193_44335_9724.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100823_102422_000009442092_00194_44336_9754.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100823_105957_000002402092_00194_44336_9753.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100823_110601_000001942092_00194_44336_9756.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100823_111054_000010042092_00194_44336_9755.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100823_113008_000000752092_00195_44337_9759.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100823_114744_000010942092_00195_44337_9796.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100823_121331_000004352092_00195_44337_9798.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100823_124032_000002402092_00195_44337_9800.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100823_125534_000006692092_00195_44337_9802.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100823_132946_000005842092_00196_44338_9833.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100823_134147_000000892092_00196_44338_9835.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100823_142108_000003002092_00196_44338_9839.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100823_143103_000001192092_00196_44338_9840.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100823_143813_000001192092_00197_44339_9843.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100823_152428_000010492092_00197_44339_9867.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100823_160144_000011992092_00197_44339_9872.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100823_170216_000012142092_00198_44340_0002.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100823_174220_000012292092_00198_44340_0006.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100823_174220_000012292092_00198_44340_0008.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100823_183630_000016042092_00199_44341_0044.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100823_192256_000004502092_00199_44341_0042.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100823_193349_000001342092_00199_44341_0046.N1					OK	OK	OK	OK


### Calibration pulses for GM1 SS3 H/H




Calibration pulses for GM1 SS3 H/H




23-Aug



23-Aug




23-Aug




23-Aug

rows: 2 6 10 14 18 22 26 30


### Calibration pulses for GM1 SS3 H/H




23-Aug



23-Aug



23-Aug




23-Aug


rows: - 3 - 7 - 11 - 15 - 19 - 23 - 27 - 31




### Calibration pulses for GM1 SS3 H/H




Calibration pulses for WVS IS2 V/V




Calibration pulses for WVS IS2 V/V




Calibration pulses for WVS IS2 V/V




23-Aug



23-Aug




23-Aug




23-Aug

rows: \_ 3 \_ 7 \_ 11 \_ 15 \_ 19 \_ 23 \_ 27 \_ 31


### Calibration pulses for WVS IS2 V/V




23-Aug



23-Aug





23-Aug





23-Aug

rows: \_ 4 \_ 8 \_ 12 \_ 16 \_ 20 \_ 24 \_ 28 \_ 32











rows: \_ 1 \_ 5 \_ 9 \_ 13 \_ 17 \_ 21 \_ 25 \_ 29









rows: \_ 2 \_ 6 \_ 10 \_ 14 \_ 18 \_ 22 \_ 26 \_ 30







rows: **3** **7** **11** **15** **19** **23** **27** **31**






23-Aug  
rows: \_ 4 \_ 8 \_ 12 \_ 16 \_ 20 \_ 24 \_ 28 \_ 32






















Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_APM_1PNPDE20100823_024939_000000852092_00189_44331_6803.N1						IS5	H/H	92	44331	189	5.03
ASA_APM_1PNPDE20100823_051548_000000432092_00191_44333_6809.N1						IS1	V/H	92	44333	191	5.03
ASA_APM_1PNPDE20100823_065533_000000432092_00192_44334_6843.N1						IS2	H/H	92	44334	192	5.03
ASA_APM_1PNPDE20100823_070509_000000572092_00192_44334_6864.N1						IS4	V/H	92	44334	192	5.03
ASA_APM_1PNPDE20100823_134410_000000682092_00196_44338_6963.N1						IS4	V/H	92	44338	196	5.03



ASA_GM1_1PNPDK20100823_172318_000008882092_00198_44340_0003.N1	SS1	H/H	92	44340	198	5.03
ASA_GM1_1PNPDK20100823_174018_000001142092_00198_44340_0005.N1	SS1	H/H	92	44340	198	5.03
ASA_GM1_1PNPDK20100823_180840_000000722092_00199_44341_0004.N1	SS1	H/H	92	44341	199	5.03
ASA_GM1_1PNPDK20100823_181131_000002592092_00199_44341_0007.N1	SS1	H/H	92	44341	199	5.03
ASA_GM1_1PNPDK20100823_181131_000002592092_00199_44341_0009.N1	SS1	H/H	92	44341	199	5.03
ASA_GM1_1PNPDK20100823_181438_000001692092_00199_44341_0037.N1	SS1	H/H	92	44341	199	5.03
ASA_GM1_1PNPDK20100823_182341_000003142092_00199_44341_0040.N1	SS1	H/H	92	44341	199	5.03
ASA_GM1_1PNPDK20100823_190354_000008342092_00199_44341_0041.N1	SS1	H/H	92	44341	199	5.03
ASA_GM1_1PNPDK20100823_192023_000001502092_00199_44341_0043.N1	SS1	H/H	92	44341	199	5.03
ASA_GM1_1PNPDK20100823_193102_000001632092_00199_44341_0045.N1	SS1	H/H	92	44341	199	5.03
ASA_GM1_1PNPDK20100823_193649_000006042092_00199_44341_0047.N1	SS1	H/H	92	44341	199	5.03
ASA_GM1_1PNPDE20100823_195555_000000962092_00200_44342_6981.N1	SS1	H/H	92	44342	200	5.03
ASA_GM1_1PNPDE20100823_200320_000001872092_00200_44342_6982.N1	SS1	H/H	92	44342	200	5.03
ASA_GM1_1PNPDE20100823_200833_000002112092_00200_44342_6984.N1	SS1	H/H	92	44342	200	5.03
ASA_GM1_1PNPDE20100823_204429_000008642092_00200_44342_6986.N1	SS1	H/H	92	44342	200	5.03
ASA_GM1_1PNPDE20100823_210134_000000602092_00200_44342_6988.N1	SS1	H/H	92	44342	200	5.03
ASA_GM1_1PNPDE20100823_210136_000001082092_00200_44342_6997.N1	SS1	H/H	92	44342	200	5.03
ASA_GM1_1PNPDE20100823_211127_000010512092_00200_44342_6998.N1	SS1	H/H	92	44342	200	5.03
ASA_GM1_1PNPDE20100823_213707_000001502092_00201_44343_7002.N1	SS1	H/H	92	44343	201	5.03
ASA_GM1_1PNPDE20100823_222505_000008162092_00201_44343_7004.N1	SS1	H/H	92	44343	201	5.03
ASA_GM1_1PNPDE20100823_230118_000003082092_00202_44344_7019.N1	SS1	H/H	92	44344	202	5.03
ASA_GM1_1PNPDE20100823_233405_000000782092_00202_44344_7020.N1	SS1	H/H	92	44344	202	5.03
ASA_GM1_1PNPDE20100823_235051_000001202092_00202_44344_7021.N1	SS1	H/H	92	44344	202	5.03
ASA_GM1_1PNPDE20100823_235402_000004042092_00202_44344_7023.N1	SS1	H/H	92	44344	202	5.03

Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_IMM_1PNPDE20100823_000730_000000732092_00188_44330_6769.N1						IS2	V/V	92	44330	188	5.03
ASA_IMM_1PNPDE20100823_031312_000000382092_00190_44332_6804.N1						IS4	H/H	92	44332	190	5.03
ASA_IMM_1PNPDE20100823_033150_000002822092_00190_44332_6791.N1						IS2	V/V	92	44332	190	5.03
ASA_IMM_1PNPDE20100823_044847_000000512092_00191_44333_6824.N1						IS1	V/V	92	44333	191	5.03
ASA_IMM_1PNPDE20100823_050052_000002032092_00191_44333_6806.N1						IS2	V/V	92	44333	191	5.03
ASA_IMM_1PNPDK20100823_064456_000001292092_00192_44334_9675.N1						IS2	V/V	92	44334	192	5.03
ASA_IMM_1PNPDK20100823_080921_000000622092_00193_44335_9692.N1						IS2	V/V	92	44335	193	5.03
ASA_IMM_1PNPDE20100823_101244_000000532092_00194_44336_6905.N1						IS2	V/V	92	44336	194	5.03
ASA_IMM_1PNPDE20100823_110427_000000882092_00194_44336_6932.N1						IS2	V/V	92	44336	194	5.03
ASA_IMM_1PNPDE20100823_110956_000000532092_00194_44336_6933.N1						IS2	V/V	92	44336	194	5.03
ASA_IMM_1PNPDE20100823_162604_000001422092_00198_44340_6969.N1						IS6	V/V	92	44340	198	5.03
ASA_IMM_1PNPDK20100823_163931_000000672092_00198_44340_9875.N1						IS2	H/H	92	44340	198	5.03
ASA_IMM_1PNPDK20100823_163931_000000672092_00198_44340_9876.N1						IS2	H/H	92	44340	198	5.03
ASA_IMM_1PNPDE20100823_165929_000001302092_00198_44340_6975.N1						IS2	V/V	92	44340	198	5.03
ASA_IMM_1PNPDE20100823_180430_000002392092_00199_44341_6976.N1						IS6	V/V	92	44341	199	5.03
ASA_IMM_1PNPDE20100823_200628_000001142092_00200_44342_6980.N1						IS2	V/V	92	44342	200	5.03
ASA_IMM_1PNPDE20100823_202232_000001032092_00200_44342_6985.N1						IS2	V/V	92	44342	200	5.03
ASA_IMM_1PNPDE20100823_215005_000001592092_00201_44343_7016.N1						IS2	V/V	92	44343	201	5.03


Filename	Pol	Timestamp	count(Module)
ASA_MS__0PNPDE20100823_054033_000000162092_00191_44333_0571.N1	V	2010-08-23 05:40:33	320








Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WSM_1PNPDE20100823_005037_000002882092_00188_44330_6767.N1						SS1	H/H	92	44330	188	5.03
ASA_WSM_1PNPDE20100823_012821_000002692092_00189_44331_6801.N1						SS1	H/H	92	44331	189	5.03
ASA_WSM_1PNPDE20100823_023030_000002392092_00189_44331_6802.N1						SS1	H/H	92	44331	189	5.03
ASA_WSM_1PNPDK20100823_025903_000002882092_00190_44332_9547.N1						SS1	V/V	92	44332	190	5.03
ASA_WSM_1PNPDK20100823_025903_000002882092_00190_44332_0021.N1						SS1	V/V	92	44332	190	5.03
ASA_WSM_1PNPDE20100823_040929_000003062092_00190_44332_6817.N1						SS1	H/H	92	44332	190	5.03
ASA_WSM_1PNPDK20100823_043759_000001472092_00191_44333_9575.N1						SS1	V/V	92	44333	191	5.03
ASA_WSM_1PNPDE20100823_043759_000001282092_00191_44333_6814.N1						SS1	V/V	92	44333	191	5.03
ASA_WSM_1PNPDE20100823_044533_000000982092_00191_44333_6827.N1						SS1	V/V	92	44333	191	5.03
ASA_WSM_1PNPDE20100823_051145_000001162092_00191_44333_6808.N1						SS1	V/V	92	44333	191	5.03
ASA_WSM_1PNPDE20100823_055158_000001472092_00191_44333_6844.N1						SS1	H/H	92	44333	191	5.03
ASA_WSM_1PNPDE20100823_062756_000003672092_00192_44334_6847.N1						SS1	V/V	92	44334	192	5.03
ASA_WSM_1PNPDE20100823_062756_000003672092_00192_44334_6848.N1						SS1	V/V	92	44334	192	5.03
ASA_WSM_1PNPDK20100823_064043_000002392092_00192_44334_9674.N1						SS1	H/H	92	44334	192	5.03
ASA_WSM_1PNPDE20100823_065040_000001472092_00192_44334_6842.N1						SS1	H/H	92	44334	192	5.03
ASA_WSM_1PNPDE20100823_071255_000002082092_00192_44334_6865.N1						SS1	V/V	92	44334	192	5.03
ASA_WSM_1PNPDK20100823_073119_000002452092_00192_44334_9691.N1						SS1	H/H	92	44334	192	5.03
ASA_WSM_1PNPDK20100823_081807_000000862092_00193_44335_9693.N1						SS1	H/H	92	44335	193	5.03
ASA_WSM_1PNPDE20100823_082531_000002322092_00193_44335_6885.N1						SS1	V/V	92	44335	193	5.03
ASA_WSM_1PNPDE20100823_083007_000000982092_00193_44335_6886.N1						SS1	V/V	92	44335	193	5.03
ASA_WSM_1PNPDK20100823_091137_000003002092_00193_44335_9731.N1						SS1	H/H	92	44335	193	5.03
ASA_WSM_1PNPDE20100823_095942_000001222092_00194_44336_6902.N1						SS1	H/H	92	44336	194	5.03
ASA_WSM_1PNPDE20100823_100202_000001222092_00194_44336_6903.N1						SS1	H/H	92	44336	194	5.03
ASA_WSM_1PNPDE20100823_100438_000000982092_00194_44336_6904.N1						SS1	V/V	92	44336	194	5.03
ASA_WSM_1PNPDK20100823_100546_000003922092_00194_44336_9732.N1						SS1	V/V	92	44336	194	5.03
ASA_WSM_1PNPDE20100823_101728_000004162092_00194_44336_6906.N1						SS1	V/V	92	44336	194	5.03
ASA_WSM_1PNPDE20100823_105209_000002752092_00194_44336_6931.N1						SS1	H/H	92	44336	194	5.03
ASA_WSM_1PNPDE20100823_112831_000000982092_00195_44337_6935.N1						SS1	H/H	92	44337	195	5.03
ASA_WSM_1PNPDK20100823_114222_000003062092_00195_44337_9772.N1						SS1	H/H	92	44337	195	5.03
ASA_WSM_1PNPDE20100823_120637_000004162092_00195_44337_6937.N1						SS1	V/V	92	44337	195	5.03
ASA_WSM_1PNPDK20100823_123301_000003002092_00195_44337_9814.N1						SS1	H/H	92	44337	195	5.03
ASA_WSM_1PNPDK20100823_131739_000003492092_00196_44338_9816.N1						SS1	H/H	92	44338	196	5.03
ASA_WSM_1PNPDE20100823_141505_000002082092_00196_44338_6965.N1						SS1	H/H	92	44338	196	5.03
ASA_WSM_1PNPDK20100823_145555_000002322092_00197_44339_9848.N1						SS1	H/H	92	44339	197	5.03
ASA_WSM_1PNPDK20100823_150114_000003432092_00197_44339_9853.N1						SS1	H/H	92	44339	197	5.03
ASA_WSM_1PNPDE20100823_150517_000001772092_00197_44339_6966.N1						SS1	H/H	92	44339	197	5.03
ASA_WSM_1PNPDK20100823_151548_000005082092_00197_44339_9883.N1						SS1	V/V	92	44339	197	5.03
ASA_WSM_1PNPDE20100823_151903_000001712092_00197_44339_6968.N1						SS1	V/V	92	44339	197	5.03
ASA_WSM_1PNPDE20100823_155711_000001162092_00197_44339_6962.N1						SS1	H/H	92	44339	197	5.03
ASA_WSM_1PNPDK20100823_163411_000001592092_00198_44340_9878.N1						SS1	H/H	92	44340	198	5.03
ASA_WSM_1PNPDK20100823_164239_000001652092_00198_44340_9884.N1						SS1	H/H	92	44340	198	5.03
ASA_WSM_1PNPDE20100823_181001_000000862092_00199_44341_6977.N1						SS1	H/H	92	44341	199	5.03
ASA_WSM_1PNPDK20100823_181734_000000672092_00199_44341_0016.N1						SS1	V/V	92	44341	199	5.03
ASA_WSM_1PNPDK20100823_181915_000002632092_00199_44341_0018.N1						SS1	H/H	92	44341	199	5.03
ASA_WSM_1PNPDE20100823_182902_000003982092_00199_44341_6979.N1						SS1	V/V	92	44341	199	5.03
ASA_WSM_1PNPDE20100823_191755_000001472092_00199_44341_6978.N1						SS1	H/H	92	44341	199	5.03
ASA_WSM_1PNPDK20100823_195115_000002752092_00200_44342_0054.N1						SS1	V/V	92	44342	200	5.03
ASA_WSM_1PNPDK20100823_195742_000003362092_00200_44342_0055.N1						SS1	H/H	92	44342	200	5.03
ASA_WSM_1PNPDE20100823_205900_000001532092_00200_44342_6995.N1						SS1	H/H	92	44342	200	5.03
ASA_WSM_1PNPDE20100823_210652_000002692092_00200_44342_6996.N1						SS1	V/V	92	44342	200	5.03
ASA_WSM_1PNPDK20100823_213946_000002142092_00201_44343_0075.N1						SS1	H/H	92	44343	201	5.03
ASA_WSM_1PNPDE20100823_214249_000004102092_00201_44343_7013.N1						SS1	H/H	92	44343	201	5.03
ASA_WSM_1PNPDE20100823_220024_000000862092_00201_44343_7014.N1						SS1	V/V	92	44343	201	5.03
ASA_WSM_1PNPDE20100823_223848_000002452092_00201_44343_7012.N1						SS1	H/H	92	44343	201	5.03
ASA_WSM_1PNPDK20100823_231709_000002942092_00202_44344_0091.N1						SS1	H/H	92	44344	202	5.03
ASA_WSM_1PNPDE20100823_232142_000003002092_00202_44344_7034.N1						SS1	H/H	92	44344	202	5.03
ASA_WSM_1PNPDE20100823_232723_000003922092_00202_44344_7035.N1						SS1	H/H	92	44344	202	5.03




Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WVS_1PNPDE20100823_000850_000007792092_00188_44330_6755.N1						IS2	V/V	92	44330	188	5.03
ASA_WVS_1PNPDE20100823_002428_000000592092_00188_44330_6753.N1						IS2	V/V	92	44330	188	5.03
ASA_WVS_1PNPDE20100823_003102_000003302092_00188_44330_6757.N1						IS2	V/V	92	44330	188	5.03
ASA_WVS_1PNPDE20100823_005612_000003302092_00188_44330_6758.N1						IS2	V/V	92	44330	188	5.03
ASA_WVS_1PNPDE20100823_010057_000001802092_00188_44330_6772.N1						IS2	V/V	92	44330	188	5.03
ASA_WVS_1PNPDE20100823_011135_000008392092_00188_44330_6776.N1						IS2	V/V	92	44330	188	5.03
ASA_WVS_1PNPDE20100823_015140_000000592092_00189_44331_6780.N1						IS2	V/V	92	44331	189	5.03
ASA_WVS_1PNPDE20100823_020459_000007342092_00189_44331_6784.N1						IS2	V/V	92	44331	189	5.03
ASA_WVS_1PNPDE20100823_023657_000002252092_00189_44331_6795.N1						IS2	V/V	92	44331	189	5.03
ASA_WVS_1PNPDE20100823_033836_000001492092_00190_44332_6794.N1						IS2	V/V	92	44332	190	5.03
ASA_WVS_1PNPDE20100823_034051_000008692092_00190_44332_6811.N1						IS2	V/V	92	44332	190	5.03
ASA_WVS_1PNPDE20100823_041819_000010942092_00190_44332_6818.N1						IS2	V/V	92	44332	190	5.03
ASA_WVS_1PNPDE20100823_051749_000010492092_00191_44333_6813.N1						IS2	V/V	92	44333	191	5.03
ASA_WVS_1PNPDE20100823_055809_000017392092_00191_44333_6854.N1						IS2	V/V	92	44333	191	5.03
ASA_WVS_1PNPDK20100823_071624_000001502092_00192_44334_9678.N1						IS2	V/V	92	44334	192	5.03
ASA_WVS_1PNPDK20100823_073845_000017992092_00192_44334_9682.N1						IS2	V/V	92	44334	192	5.03
ASA_WVS_1PNPDK20100823_084954_000005852092_00193_44335_9719.N1						IS2	V/V	92	44335	193	5.03
ASA_WVS_1PNPDK20100823_091921_000019342092_00193_44335_9724.N1						IS2	V/V	92	44335	193	5.03
ASA_WVS_1PNPDK20100823_102422_000009442092_00194_44336_9754.N1						IS2	V/V	92	44336	194	5.03
ASA_WVS_1PNPDK20100823_105957_000002402092_00194_44336_9753.N1						IS2	V/V	92	44336	194	5.03
ASA_WVS_1PNPDK20100823_110601_000001942092_00194_44336_9756.N1						IS2	V/V	92	44336	194	5.03
ASA_WVS_1PNPDK20100823_111054_000010042092_00194_44336_9755.N1						IS2	V/V	92	44336	194	5.03
ASA_WVS_1PNPDK20100823_113008_000000752092_00195_44337_9759.N1						IS2	V/V	92	44337	195	5.03
ASA_WVS_1PNPDK20100823_114744_000010942092_00195_44337_9796.N1						IS2	V/V	92	44337	195	5.03
ASA_WVS_1PNPDK20100823_121331_000004352092_00195_44337_9798.N1						IS2	V/V	92	44337	195	5.03
ASA_WVS_1PNPDK20100823_124032_000002402092_00195_44337_9800.N1						IS2	V/V	92	44337	195	5.03
ASA_WVS_1PNPDK20100823_125534_000006692092_00195_44337_9802.N1						IS2	V/V	92	44337	195	5.03
ASA_WVS_1PNPDK20100823_132946_000005842092_00196_44338_9833.N1						IS2	V/V	92	44338	196	5.03
ASA_WVS_1PNPDK20100823_134147_000000892092_00196_44338_9835.N1						IS2	V/V	92	44338	196	5.03
ASA_WVS_1PNPDK20100823_142108_000003002092_00196_44338_9839.N1						IS2	V/V	92	44338	196	5.03
ASA_WVS_1PNPDK20100823_143103_000001192092_00196_44338_9840.N1						IS2	V/V	92	44338	196	5.03
ASA_WVS_1PNPDK20100823_143813_000001192092_00197_44339_9843.N1						IS2	V/V	92	44339	197	5.03
ASA_WVS_1PNPDK20100823_152428_000010492092_00197_44339_9867.N1						IS2	V/V	92	44339	197	5.03
ASA_WVS_1PNPDK20100823_160144_000011992092_00197_44339_9872.N1						IS2	V/V	92	44339	197	5.03
ASA_WVS_1PNPDK20100823_170216_000012142092_00198_44340_0002.N1						IS2	V/V	92	44340	198	5.03
ASA_WVS_1PNPDK20100823_174220_000012292092_00198_44340_0008.N1						IS2	V/V	92	44340	198	5.03
ASA_WVS_1PNPDK20100823_174220_000012292092_00198_44340_0006.N1						IS2	V/V	92	44340	198	5.03
ASA_WVS_1PNPDK20100823_183630_000016042092_00199_44341_0044.N1						IS2	V/V	92	44341	199	5.03
ASA_WVS_1PNPDK20100823_192256_000004502092_00199_44341_0042.N1						IS2	V/V	92	44341	199	5.03
ASA_WVS_1PNPDK20100823_193349_000001342092_00199_44341_0046.N1						IS2	V/V	92	44341	199	5.03
ASA_WVS_1PNPDE20100823_201204_000005842092_00200_44342_6983.N1						IS2	V/V	92	44342	200	5.03
ASA_WVS_1PNPDE20100823_202422_000011692092_00200_44342_6987.N1						IS2	V/V	92	44342	200	5.03
ASA_WVS_1PNPDE20100823_210332_000001502092_00200_44342_6999.N1						IS2	V/V	92	44342	200	5.03
ASA_WVS_1PNPDE20100823_215249_000000602092_00201_44343_7000.N1						IS2	V/V	92	44343	201	5.03
ASA_WVS_1PNPDE20100823_215511_000002692092_00201_44343_7001.N1						IS2	V/V	92	44343	201	5.03
ASA_WVS_1PNPDE20100823_220152_000013492092_00201_44343_7003.N1						IS2	V/V	92	44343	201	5.03
ASA_WVS_1PNPDE20100823_224359_000002702092_00201_44343_7005.N1						IS2	V/V	92	44343	201	5.03
ASA_WVS_1PNPDE20100823_224744_000007642092_00201_44343_7017.N1						IS2	V/V	92	44343	201	5.03
ASA_WVS_1PNPDE20100823_230927_000004202092_00202_44344_7018.N1						IS2	V/V	92	44344	202	5.03
ASA_WVS_1PNPDE20100823_233532_000008692092_00202_44344_7022.N1						IS2	V/V	92	44344	202	5.03




































































23-Aug




23-Aug




23-Aug







23-Aug





23-Aug




23-Aug








23-Aug



23-Aug



23-Aug





















