



Analysis from 30-AUG-2010 00:00:00 to 30-AUG-2010 23:59:59. Page generated on 31-AUG-2010 15:15:08.  
View log file: ASAR\_Daily\_Report\_20100831\_1513.log. For any anomalies please contact emma.griffiths@vega.co.uk, kajal.haria@vega.co.uk.

This report is automatically generated every day, every 2 hours. No comments are provided on the results.

## SUMMARY

1. DATA SUMMARY
  - 1.1 Summary tables
  - 1.2 Lists of products used
2. AUXILIARY FILES ANALYSIS
  - 2.1 IECF operational ADFs list
  - 2.2 Products with wrong ADFs
3. MODULE STEPPING PRODUCTS ANALYSIS
  - 3.1 V/V polarisation
  - 3.2 H/H polarisation
4. CALIBRATION PULSES ANALYSIS
  - 4.1 Analysis for WVS IS2 V/V
    - 4.1.1 Temporal Evolution Analysis for WVS IS2 V/V
    - 4.1.2 All Rows Analysis for WVS IS2 V/V
  - 4.2 Analysis for GM1 SS3 H/H
    - 4.2.1 Temporal Evolution Analysis for GM1 SS3 H/H
    - 4.2.2 All Rows Analysis for GM1 SS3 H/H
5. DOPPLER ANALYSIS
  - 5.1 Analysis for WVS IS2 V/V
    - 5.1.1 Doppler MAP Analysis for WVS IS2 V/V
    - 5.1.2 Doppler ANX Analysis for WVS IS2 V/V
  - 5.2 Analysis for GM1 SS1 H/H
    - 5.2.1 Doppler MAP Analysis for GM1 SS1 H/H
    - 5.2.2 Doppler ANX Analysis for GM1 SS1 H/H
  - 5.3 Doppler JUMPS Analysis for WSM
6. CHIRP ANALYSIS
  - 6.1 Analysis for WSM SS1 H/H
    - 6.1.1 ScaleFactor
  - 6.2 Analysis for WSM SS1 V/V
    - 6.2.1 ScaleFactor
7. RAW DATA ANALYSIS
  - 7.1 Analysis for WVS
  - 7.2 Analysis for IMM
8. TELEMETRY ANALYSIS
  - 8.1 Number of Missing Lines
  - 8.2 Number of Gaps

---

## 1 - DATA SUMMARY

### 1.1 - Summary tables

[ BACK TO MENU ]

WVS				GM1				APM				IMM				WSM				MS			
Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Time	Pol	Modules
PDE	IS1	V/V	3	PDE	WS	H/H	40	PDE	IS4	H/H	1	PDE	IS2	H/H	18	PDE	WS	H/H	24	PDE	2010-08-30 01:59:14	H	320
PDE	IS2	V/V	25	PDK	WS	H/H	32	PDK	IS2	V/H	1	PDE	IS2	V/V	14	PDE	WS	V/V	5	PDK	2010-08-30 08:41:38	V	320
PDK	IS2	V/V	22									PDE	IS7	V/V	1	PDK	WS	H/H	8				
												PDK	IS2	V/V	2	PDK	WS	V/V	2				

## 1.2 - Lists of products used

[ BACK TO MENU ]

[TXT] [XLS] List\_WVS\_products\_used  
 [TXT] [XLS] List\_GM1\_products\_used  
 [TXT] [XLS] List\_APM\_products\_used  
 [TXT] [XLS] List\_IMM\_products\_used  
 [TXT] [XLS] List\_WSM\_products\_used  
 [TXT] [XLS] List\_MS\_products\_used

## 2 - AUXILIARY FILES ANALYSIS

### 2.1 - IECF operational ADFs list

[ BACK TO MENU ]

ADFs disseminated for ASAR
ASA_CON_AXVIEC20100608_125449_20100317_120410_20101231_000000
ASA_INS_AXVIEC20091217_114637_20090428_100000_20101231_235959
ASA_XCH_AXVIEC20091217_113006_20020301_000000_20101231_000000
ASA_XCA_AXVIEC20100608_123419_20100317_120410_20110101_000000

### 2.2 - Products with wrong ADFs

[ BACK TO MENU ]

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
WVS	0	0	0	0
GM1	0	0	0	0
APM	0	0	0	0
IMM	0	0	0	0
WSM	0	0	0	0

[TXT] [XLS] Check\_ADFs\_WVS  
 [TXT] [XLS] Check\_ADFs\_GM1  
 [TXT] [XLS] Check\_ADFs\_APM  
 [TXT] [XLS] Check\_ADFs\_IMM  
 [TXT] [XLS] Check\_ADFs\_WSM

## 3 - MODULE STEPPING PRODUCTS ANALYSIS



SECOND FIXED REFERENCE	PREVIOUS PRODUCT REFERENCE
------------------------	----------------------------

Pre-launch reference (2001-02-09)

Previous product in the same polarisation


Reference: 2001-02-09 14:08:23 V RxGain  
 Test : 2010-08-30 08:41:38 V

Reference: 2010-08-29 02:30:51 V RxGain  
 Test : 2010-08-30 08:41:38 V



Reference: 2001-02-09 14:08:23 V RxPhase  
 Test : 2010-08-30 08:41:38 V

Reference: 2010-08-29 02:30:51 V RxPhase  
 Test : 2010-08-30 08:41:38 V









### 3.2 - H/H polarisation

[ [BACK TO MENU](#) ]

SECOND FIXED REFERENCE	PREVIOUS PRODUCT REFERENCE
Pre-launch reference (2001-02-09)	Previous product in the same polarisation





## 4 - CALIBRATION PULSES ANALYSIS

### 4.1 - Analysis for WVS IS2 V/V


#### 4.1.1 - Temporal Evolution Analysis for WVS IS2 V/V

[ BACK TO MENU ]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Calibration pulses for WVS IS2 V/V




Transmit power (P1 - P1a) for WVS IS2 V/V



4.1.2 - All Rows Analysis for WVS IS2 V/V

[ BACK TO MENU ]





## 4.2 - Analysis for GM1 SS3 H/H

### 4.2.1 - Temporal Evolution Analysis for GM1 SS3 H/H


[ BACK TO MENU ]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]



Calibration pulses for GM1 SS3 H/H




Transmit power (P1 - P1a) for GM1 SS3 H/H



4.2.2 - All Rows Analysis for GM1 SS3 H/H

[ BACK TO MENU ]






## 5 - DOPPLER ANALYSIS

### 5.1 - Analysis for WVS IS2 V/V

#### 5.1.1 - Doppler MAP Analysis for WVS IS2 V/V

[ [BACK TO MENU](#) ]






### 5.1.2 - Doppler ANX Analysis for WVS IS2 V/V

[ [BACK TO MENU](#) ]






## 5.2 - Analysis for GM1 SS1 H/H

### 5.2.1 - Doppler MAP Analysis for GM1 SS1 H/H

[ [BACK TO MENU](#) ]






### 5.2.2 - Doppler ANX Analysis for GM1 SS1 H/H

[ [BACK TO MENU](#) ]






### 5.3 - Doppler JUMPS Analysis for WSM

[ BACK TO MENU ]







## 6 - CHIRP ANALYSIS

### 6.1 - Analysis for WSM SS1 H/H

#### 6.1.1 - ScaleFactor

[ BACK TO MENU ]







## 6.2 - Analysis for WSM SS1 V/V

### 6.2.1 - ScaleFactor

[ [BACK TO MENU](#) ]






## 7 - RAW DATA ANALYSIS

### 7.1 - Analysis for WVS

[ [BACK TO MENU](#) ]

--	--	--	--








Channel	Statistics	DSS-B
MEAN I	mean	0.000623055
	stdev	1.19503e-07
MEAN Q	mean	0.000525721
	stdev	2.10783e-07
Channel	Statistics	DSS-B
STDEV I	mean	0.147610
	stdev	0.00116308
STDEV Q	mean	0.148141
	stdev	0.00118801

7.2 - Analysis for IMM

[ BACK TO MENU ]






Channel	Statistics	DSS-B
MEAN I	mean	0.000261502
	stdev	8.49340e-09
MEAN Q	mean	0.000524405
	stdev	7.92362e-09
Channel	Statistics	DSS-B
STDEV I	mean	0.0792425
	stdev	0.000927917
STDEV Q	mean	0.0795686
	stdev	0.000938811

## 8 - TELEMETRY ANALYSIS

### 8.1 - Number of Missing lines


[ BACK TO MENU ]





## 8.2 - Number of Gaps

[ [BACK TO MENU](#) ]



#####  
ASAR DAILY REPORT for 100830  
#####

MODE: DAILY  
ANALYSIS: ALL  
DATE: YESTERDAY

Analysis will be performed from 2010-08-30 00:00:00 to 2010-08-30 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/\_100830/

DATA SUMMARY

#####  
Summary will be performed from 2010-08-30 00:00:00 to 2010-08-30 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/\_100830/DATA\_SUMMARY

Creating directory ./RESULTS/DAILY/\_100830/DATA\_SUMMARY...  
Writing file ./RESULTS/DAILY/\_100830/DATA\_SUMMARY/Data\_summary.html...

\*\*\*\*\*  
Getting WVS products list from 2010-08-30 00:00:00 to 2010-08-30 23:59:59...  
Writing file ./RESULTS/DAILY/\_100830/DATA\_SUMMARY/List\_WVS\_products\_used.xls...  
Writing file ./RESULTS/DAILY/\_100830/DATA\_SUMMARY/List\_WVS\_products\_used.txt...

\*\*\*\*\*  
Getting GM1 products list from 2010-08-30 00:00:00 to 2010-08-30 23:59:59...  
Writing file ./RESULTS/DAILY/\_100830/DATA\_SUMMARY/List\_GM1\_products\_used.xls...  
Writing file ./RESULTS/DAILY/\_100830/DATA\_SUMMARY/List\_GM1\_products\_used.txt...

\*\*\*\*\*  
Getting APM products list from 2010-08-30 00:00:00 to 2010-08-30 23:59:59...  
Writing file ./RESULTS/DAILY/\_100830/DATA\_SUMMARY/List\_APM\_products\_used.xls...  
Writing file ./RESULTS/DAILY/\_100830/DATA\_SUMMARY/List\_APM\_products\_used.txt...

\*\*\*\*\*  
Getting IMM products list from 2010-08-30 00:00:00 to 2010-08-30 23:59:59...  
Writing file ./RESULTS/DAILY/\_100830/DATA\_SUMMARY/List\_IMM\_products\_used.xls...  
Writing file ./RESULTS/DAILY/\_100830/DATA\_SUMMARY/List\_IMM\_products\_used.txt...

\*\*\*\*\*  
Getting WSM products list from 2010-08-30 00:00:00 to 2010-08-30 23:59:59...  
Writing file ./RESULTS/DAILY/\_100830/DATA\_SUMMARY/List\_WSM\_products\_used.xls...  
Writing file ./RESULTS/DAILY/\_100830/DATA\_SUMMARY/List\_WSM\_products\_used.txt...

\*\*\*\*\*  
Getting MS products list from 2010-08-30 00:00:00 to 2010-08-30 23:59:59...  
Writing file ./RESULTS/DAILY/\_100830/DATA\_SUMMARY/List\_MS\_products\_used.xls...  
Writing file ./RESULTS/DAILY/\_100830/DATA\_SUMMARY/List\_MS\_products\_used.txt...

DATA SUMMARY completed  
#####

AUXILIARY FILES ANALYSIS

#####  
Analysis will be performed from 2010-08-30 00:00:00 to 2010-08-30 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/\_100830/AUXILIARY

Creating directory ./RESULTS/DAILY/\_100830/AUXILIARY...

\*\*\*\*\*  
Looking for the IECF operational ADFs list...



ADF filter 20100830\*current\_3\_IECF\_ADFs.txt  
 Found list 20100830\_030001\_current\_3\_IECF\_ADFs.txt...  
 Extracting ADFs...

ASA\_CON\_AXVIEC20100608\_125449\_20100317\_120410\_20101231\_000000  
 ASA\_INS\_AXVIEC20091217\_114637\_20090428\_100000\_20101231\_235959  
 ASA\_XCH\_AXVIEC20091217\_113006\_20020301\_000000\_20101231\_000000  
 ASA\_XCA\_AXVIEC20100608\_123419\_20100317\_120410\_20110101\_000000

Writing file ./RESULTS/DAILY/\_100830/AUXILIARY/ASAR\_ADFs\_IECF\_List3.html...  
 Writing file ./RESULTS/DAILY/\_100830/AUXILIARY/Auxiliary\_files\_summary.html...

\*\*\*\*\*

Analysing WVS products...

Writing file ./RESULTS/DAILY/\_100830/AUXILIARY/Check\_ADFs\_WVS.xls...  
 Writing file ./RESULTS/DAILY/\_100830/AUXILIARY/Check\_ADFs\_WVS.txt...

ASA_WVS_1PNPDE20100830_001138_000002852092_00288_44430_8594.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100830_003605_000002552092_00288_44430_8595.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100830_003935_000004792092_00288_44430_8610.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100830_005102_000009592092_00288_44430_8617.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100830_014505_000001342092_00289_44431_8621.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100830_015047_000003752092_00289_44431_8622.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100830_021649_000000152092_00289_44431_8623.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100830_021649_000002852092_00289_44431_8639.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100830_032222_000005842092_00290_44432_8638.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100830_033151_000002852092_00290_44432_8663.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100830_040022_000009442092_00290_44432_8661.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100830_045941_000008542092_00291_44433_8668.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100830_051340_000001052092_00291_44433_8683.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100830_053801_000014542092_00291_44433_8699.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100830_064402_000006292092_00292_44434_8698.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100830_195215_000018892092_00300_44442_8811.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100830_204325_000001492092_00300_44442_8812.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100830_204510_000002102092_00300_44442_8831.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100830_213244_000018892092_00301_44443_8830.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100830_222352_000003152092_00301_44443_8829.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100830_222822_000006892092_00301_44443_8847.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100830_224740_000004792092_00302_44444_8845.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100830_231306_000013042092_00302_44444_8850.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20100830_234110_000002252092_00302_44444_8853.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100830_065402_000002852092_00292_44434_2463.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100830_071837_000018742092_00292_44434_2467.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100830_083219_000004202092_00293_44435_2498.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100830_085913_000019492092_00293_44435_2503.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100830_100407_000009592092_00294_44436_2539.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100830_103949_000017542092_00294_44436_2544.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100830_112854_000006592092_00295_44437_2560.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100830_114127_000011542092_00295_44437_2562.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100830_122025_000003152092_00295_44437_2564.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100830_123029_000001042092_00295_44437_2566.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100830_123458_000005572092_00295_44437_2568.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100830_124624_000000592092_00296_44438_2572.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100830_130938_000008692092_00296_44438_2599.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100830_140101_000003302092_00296_44438_2601.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100830_141939_000001342092_00297_44439_2604.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100830_150855_000007792092_00297_44439_2644.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100830_154137_000012442092_00297_44439_2636.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100830_164305_000011542092_00298_44440_2653.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100830_172213_000012892092_00298_44440_2657.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100830_181836_000014692092_00299_44441_2682.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100830_190407_000004202092_00299_44441_2685.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20100830_191447_000001642092_00299_44441_2689.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

\*\*\*\*\*

Analysing GM1 products...

Writing file ./RESULTS/DAILY/\_100830/AUXILIARY/Check\_ADFs\_GM1.xls...

Writing file ./RESULTS/DAILY/\_100830/AUXILIARY/Check\_ADFs\_GM1.txt...

ASA_GM1_1PNPDE20100830_000237_000005372092_00288_44430_8593.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100830_001712_000002112092_00288_44430_8596.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100830_004818_000001632092_00288_44430_8611.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100830_011538_000003382092_00289_44431_8612.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100830_012319_000005552092_00289_44431_8614.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100830_013723_000004592092_00289_44431_8616.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100830_014757_000001692092_00289_44431_8620.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100830_015747_000000782092_00289_44431_8619.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100830_020034_000004592092_00289_44431_8618.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100830_021511_000000902092_00289_44431_8624.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100830_022219_000008882092_00289_44431_8637.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100830_024531_000004652092_00290_44432_8644.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100830_025403_000004472092_00290_44432_8642.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100830_034348_000004102092_00290_44432_8665.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100830_035436_000003442092_00290_44432_8664.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100830_042208_000014502092_00291_44433_8662.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100830_045143_000003442092_00291_44433_8672.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100830_051856_000003922092_00291_44433_8684.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100830_053422_000002172092_00291_44433_8682.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100830_060307_000006222092_00292_44434_8681.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100830_061511_000003322092_00292_44434_8689.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100830_062711_000001992092_00292_44434_8688.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100830_063210_000004772092_00292_44434_8701.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100830_064121_000001572092_00292_44434_8700.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100830_193413_000001992092_00300_44442_8807.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100830_194253_000002052092_00300_44442_8806.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100830_194926_000001632092_00300_44442_8809.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100830_202424_000002352092_00300_44442_8810.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100830_204113_000001262092_00300_44442_8813.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100830_204924_000010942092_00300_44442_8835.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100830_212346_000001932092_00301_44443_8834.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100830_212935_000001872092_00301_44443_8833.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100830_220458_000001872092_00301_44443_8832.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100830_221209_000001022092_00301_44443_8828.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100830_224037_000004222092_00302_44444_8846.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100830_230342_000004592092_00302_44444_8849.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100830_233542_000002172092_00302_44444_8848.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100830_233928_000000962092_00302_44444_8852.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100830_234532_000001502092_00302_44444_8851.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20100830_234947_000001022092_00302_44444_8855.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100830_065936_000002232092_00292_44434_2462.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100830_070721_000002952092_00292_44434_2464.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100830_071514_000001992092_00292_44434_2465.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100830_075035_000002112092_00293_44435_2466.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100830_075543_000002712092_00293_44435_2469.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100830_080713_000001752092_00293_44435_2494.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100830_082311_000005492092_00293_44435_2496.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100830_084011_000000782092_00293_44435_2495.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100830_084258_000005862092_00293_44435_2497.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100830_085629_000001632092_00293_44435_2499.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100830_093219_000005372092_00294_44436_2502.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100830_095733_000003922092_00294_44436_2538.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100830_102046_000001752092_00294_44436_2541.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100830_103115_000001022092_00294_44436_2540.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100830_103655_000001692092_00294_44436_2542.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100830_110949_000003682092_00295_44437_2543.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100830_111739_000001812092_00295_44437_2545.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100830_120119_000001322092_00295_44437_2561.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100830_120740_000003322092_00295_44437_2563.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100830_121747_000001572092_00295_44437_2565.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100830_122627_000002412092_00295_44437_2567.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

ASA_GM1_1PNPDK20100830_123254_000001202092_00295_44437_2569.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100830_124808_000005072092_00296_44438_2570.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100830_125824_000003142092_00296_44438_2571.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100830_130249_000002772092_00296_44438_2596.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100830_132452_000006282092_00296_44438_2597.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100830_133551_000010942092_00296_44438_2600.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100830_135820_000001572092_00296_44438_2598.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100830_140716_000002892092_00296_44438_2602.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100830_141319_000003802092_00296_44438_2603.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100830_152234_000008702092_00297_44439_2641.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20100830_153918_000001322092_00297_44439_2639.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

\*\*\*\*\*

Analysing APM products...

Writing file ./RESULTS/DAILY/\_100830/AUXILIARY/Check\_ADFs\_APM.xls...  
Writing file ./RESULTS/DAILY/\_100830/AUXILIARY/Check\_ADFs\_APM.txt...

ASA_APM_1PNPDE20100830_064006_000000562092_00292_44434_8679.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDK20100830_081009_000000432092_00293_44435_2479.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

\*\*\*\*\*

Analysing IMM products...

Writing file ./RESULTS/DAILY/\_100830/AUXILIARY/Check\_ADFs\_IMM.xls...  
Writing file ./RESULTS/DAILY/\_100830/AUXILIARY/Check\_ADFs\_IMM.txt...

ASA_IMM_1PNPDE20100830_002045_000005122092_00288_44430_8587.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100830_002045_000005122092_00288_44430_8658.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100830_012116_000001122092_00289_44431_8615.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100830_020814_000000922092_00289_44431_8613.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100830_031052_000003322092_00290_44432_8633.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100830_034056_000001622092_00290_44432_8652.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100830_044613_000003182092_00291_44433_8659.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100830_052526_000003732092_00291_44433_8680.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100830_070319_000002322092_00292_44434_8690.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100830_094711_000000702092_00294_44436_8745.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100830_095223_000000512092_00294_44436_8746.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100830_095643_000000372092_00294_44436_8747.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100830_102340_000004432092_00294_44436_8748.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100830_114029_000000532092_00295_44437_8768.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100830_120336_000002322092_00295_44437_8771.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100830_160356_000001652092_00298_44440_8794.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100830_160756_000001422092_00298_44440_8795.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100830_162631_000001122092_00298_44440_8798.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100830_164136_000000832092_00298_44440_8799.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100830_170808_000003022092_00298_44440_8800.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100830_171358_000002332092_00298_44440_8796.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100830_181305_000001462092_00299_44441_8803.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100830_181606_000001442092_00299_44441_8804.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100830_184813_000003022092_00299_44441_8805.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100830_185403_000002332092_00299_44441_8801.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100830_194620_000001772092_00300_44442_8822.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100830_202818_000003022092_00300_44442_8823.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100830_203408_000002332092_00300_44442_8808.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100830_211139_000000372092_00301_44443_8825.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100830_220804_000002322092_00301_44443_8838.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100830_221354_000002332092_00301_44443_8824.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100830_234802_000000912092_00302_44444_8864.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20100830_235132_000003732092_00302_44444_8844.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20100830_080440_000001442092_00293_44435_2480.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20100830_095136_000000702092_00294_44436_2524.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK



\*\*\*\*\*

Analysing WSM products...

Writing file ./RESULTS/DAILY/\_100830/AUXILIARY/Check\_ADFs\_WSM.xls...

Writing file ./RESULTS/DAILY/\_100830/AUXILIARY/Check\_ADFs\_WSM.txt...

ASA_WSM_1PNPDE20100830_003028_000002692092_00288_44430_8603.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100830_010814_000004402092_00289_44431_8609.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100830_021019_000002882092_00289_44431_8627.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100830_024010_000002142092_00290_44432_8634.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100830_030136_000001472092_00290_44432_8650.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100830_035042_000002262092_00290_44432_8667.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100830_041700_000003062092_00291_44433_8676.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100830_045733_000000922092_00291_44433_8660.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100830_053207_000001282092_00291_44433_8685.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100830_061337_000000862092_00292_44434_8691.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100830_063035_000000922092_00292_44434_8678.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100830_080021_000002452092_00293_44435_8725.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100830_081944_000002022092_00293_44435_8726.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100830_094124_000002142092_00294_44436_8743.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100830_094515_000000922092_00294_44436_8744.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100830_103309_000002262092_00294_44436_8769.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100830_111605_000000922092_00295_44437_8770.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100830_112623_000001472092_00295_44437_8767.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100830_135413_000002452092_00296_44438_8791.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100830_142356_000000862092_00297_44439_8792.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100830_144528_000002142092_00297_44439_8793.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100830_153707_000001282092_00297_44439_8790.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100830_171806_000001162092_00298_44440_8797.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100830_185807_000001282092_00299_44441_8802.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100830_203906_000001222092_00300_44442_8820.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100830_212704_000001472092_00301_44443_8836.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100830_221857_000002322092_00301_44443_8827.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100830_231126_000000982092_00302_44444_8867.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20100830_235846_000002942092_00302_44444_8859.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100830_062050_000003672092_00292_44434_2451.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100830_071221_000001712092_00292_44434_2476.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100830_075413_000000862092_00293_44435_2477.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100830_085250_000002202092_00293_44435_2522.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100830_094846_000001222092_00294_44436_2523.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100830_121318_000002692092_00295_44437_2581.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100830_124457_000000862092_00296_44438_2580.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100830_125642_000000982092_00296_44438_2584.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100830_130731_000001222092_00296_44438_2582.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20100830_143641_000005142092_00297_44439_2611.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

AUXILIARY FILES ANALYSIS completed

#####

MODULE STEPPING ANALYSIS

#####

Analysis will be performed from 2010-08-30 00:00:00 to 2010-08-30 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/\_100830/MODULE\_STEPPING

Creating directory ./RESULTS/DAILY/\_100830/MODULE\_STEPPING...  
Creating directory ./RESULTS/DAILY/\_100830/MODULE\_STEPPING/FIRST\_REFERENCE...  
Creating directory ./RESULTS/DAILY/\_100830/MODULE\_STEPPING/SECOND\_REFERENCE...  
Creating directory ./RESULTS/DAILY/\_100830/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE...  
Deleting old files...

\*\*\*\*\*

\*\*\*\*\*

Creating images comparing with second reference...



Exporting results to the directory ../../RESULTS/DAILY/\_100830/MODULE\_STEPPING/SECOND\_REFERENCE...

Polarization: H  
Reference product: ASA\_MS\_\_0PNPDK20010209\_135042\_0000009A024\_00180\_11700\_0052.N1  
Test product: ASA\_MS\_\_0PNPDE20100830\_015914\_000000162092\_00289\_44431\_0562.N1  
H  
H  
../../RESULTS/DAILY/\_100830/MODULE\_STEPPING/SECOND\_REFERENCE/TGH\_20100830\_015914-20010209\_135042.png  
../../RESULTS/DAILY/\_100830/MODULE\_STEPPING/SECOND\_REFERENCE/TPH\_20100830\_015914-20010209\_135042.png  
../../RESULTS/DAILY/\_100830/MODULE\_STEPPING/SECOND\_REFERENCE/RGH\_20100830\_015914-20010209\_135042.png  
../../RESULTS/DAILY/\_100830/MODULE\_STEPPING/SECOND\_REFERENCE/RPH\_20100830\_015914-20010209\_135042.png

Polarization: V  
Reference product: ASA\_MS\_\_0PNPDK20010209\_140823\_0000009A024\_00180\_11700\_0054.N1  
Test product: ASA\_MS\_\_0PNPDK20100830\_084138\_000000162092\_00293\_44435\_0192.N1  
V  
V  
../../RESULTS/DAILY/\_100830/MODULE\_STEPPING/SECOND\_REFERENCE/TGV\_20100830\_084138-20010209\_140823.png  
../../RESULTS/DAILY/\_100830/MODULE\_STEPPING/SECOND\_REFERENCE/TPV\_20100830\_084138-20010209\_140823.png  
../../RESULTS/DAILY/\_100830/MODULE\_STEPPING/SECOND\_REFERENCE/RGV\_20100830\_084138-20010209\_140823.png  
../../RESULTS/DAILY/\_100830/MODULE\_STEPPING/SECOND\_REFERENCE/RPV\_20100830\_084138-20010209\_140823.png

\*\*\*\*\*  
\*\*\*\*\*  
Creating images comparing with previous product reference...

Exporting results to the directory ../../RESULTS/DAILY/\_100830/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE...

Polarization: H  
Reference product: ASA\_MS\_\_0PNPDE20100828\_030228\_000000162092\_00261\_44403\_0560.N1  
Test product: ASA\_MS\_\_0PNPDE20100830\_015914\_000000162092\_00289\_44431\_0562.N1  
H  
H  
../../RESULTS/DAILY/\_100830/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/TGH\_20100830\_015914-20100828\_030228.png  
../../RESULTS/DAILY/\_100830/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/TPH\_20100830\_015914-20100828\_030228.png  
../../RESULTS/DAILY/\_100830/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/RGH\_20100830\_015914-20100828\_030228.png  
../../RESULTS/DAILY/\_100830/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/RPH\_20100830\_015914-20100828\_030228.png

Polarization: V  
Reference product: ASA\_MS\_\_0PNPDE20100829\_023051\_000000162092\_00275\_44417\_0561.N1  
Test product: ASA\_MS\_\_0PNPDK20100830\_084138\_000000162092\_00293\_44435\_0192.N1  
V  
V  
../../RESULTS/DAILY/\_100830/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/TGV\_20100830\_084138-20100829\_023051.png  
../../RESULTS/DAILY/\_100830/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/TPV\_20100830\_084138-20100829\_023051.png  
../../RESULTS/DAILY/\_100830/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/RGV\_20100830\_084138-20100829\_023051.png  
../../RESULTS/DAILY/\_100830/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/RPV\_20100830\_084138-20100829\_023051.png

MODULE\_STEPPING ANALYSIS completed  
#####

CALIBRATION PULSES ANALYSIS  
#####  
Creating directory ./RESULTS/DAILY/\_100830/CALIBRATION\_PULSES...

\*\*\*\*\*  
\*\*\*\*\*  
ALL ROWS Analysis will be performed from 2010-08-30 00:00:00 to 2010-08-30 23:59:59

Analysing products WVS IS2 V/V  
Writing image ../../RESULTS/DAILY/\_100830//CALIBRATION\_PULSES/Calibration\_pulses\_all\_rows\_WVS\_IS2\_VV.png...  
Analysing products GM1 SS3 H/H  
Writing image ../../RESULTS/DAILY/\_100830//CALIBRATION\_PULSES/Calibration\_pulses\_all\_rows\_GM1\_SS3\_HH.png...

\*\*\*\*\*  
\*\*\*\*\*

TEMPORAL EVOLUTION Analysis will be performed from 2010-08-30 00:00:00 to 2010-08-30 23:59:59

Analysing products WVS IS2 V/V

Getting calibration pulses data for WVS IS2 V/V from 2010-08-30 00:00:00 to 2010-08-30 23:59:59. Rows: 1/5/9/13/17/21/25/29  
Writing file ./RESULTS/DAILY/\_100830/CALIBRATION\_PULSES/Calibration\_pulses\_data\_WVS\_IS2\_VV\_2010-08-30\_1.dat...  
Writing ../../RESULTS/DAILY/\_100830//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_WVS\_IS2\_VV\_1.png...  
Writing ../../RESULTS/DAILY/\_100830//CALIBRATION\_PULSES/Transmit\_Power\_WVS\_IS2\_VV\_1.png...

Getting calibration pulses data for WVS IS2 V/V from 2010-08-30 00:00:00 to 2010-08-30 23:59:59. Rows: 2/6/10/14/18/22/26/30  
Writing file ./RESULTS/DAILY/\_100830/CALIBRATION\_PULSES/Calibration\_pulses\_data\_WVS\_IS2\_VV\_2010-08-30\_2.dat...  
Writing ../../RESULTS/DAILY/\_100830//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_WVS\_IS2\_VV\_2.png...  
Writing ../../RESULTS/DAILY/\_100830//CALIBRATION\_PULSES/Transmit\_Power\_WVS\_IS2\_VV\_2.png...

Getting calibration pulses data for WVS IS2 V/V from 2010-08-30 00:00:00 to 2010-08-30 23:59:59. Rows: 3/7/11/15/19/23/27/31  
Writing file ./RESULTS/DAILY/\_100830/CALIBRATION\_PULSES/Calibration\_pulses\_data\_WVS\_IS2\_VV\_2010-08-30\_3.dat...  
Writing ../../RESULTS/DAILY/\_100830//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_WVS\_IS2\_VV\_3.png...  
Writing ../../RESULTS/DAILY/\_100830//CALIBRATION\_PULSES/Transmit\_Power\_WVS\_IS2\_VV\_3.png...

Getting calibration pulses data for WVS IS2 V/V from 2010-08-30 00:00:00 to 2010-08-30 23:59:59. Rows: 4/8/12/16/20/24/28/32  
Writing file ./RESULTS/DAILY/\_100830/CALIBRATION\_PULSES/Calibration\_pulses\_data\_WVS\_IS2\_VV\_2010-08-30\_4.dat...  
Writing ../../RESULTS/DAILY/\_100830//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_WVS\_IS2\_VV\_4.png...  
Writing ../../RESULTS/DAILY/\_100830//CALIBRATION\_PULSES/Transmit\_Power\_WVS\_IS2\_VV\_4.png...

Analysing products GM1 SS3 H/H

Getting calibration pulses data for GM1 SS3 H/H from 2010-08-30 00:00:00 to 2010-08-30 23:59:59. Rows: 1/5/9/13/17/21/25/29  
Writing file ./RESULTS/DAILY/\_100830/CALIBRATION\_PULSES/Calibration\_pulses\_data\_GM1\_SS3\_HH\_2010-08-30\_1.dat...  
Writing ../../RESULTS/DAILY/\_100830//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_GM1\_SS3\_HH\_1.png...  
Writing ../../RESULTS/DAILY/\_100830//CALIBRATION\_PULSES/Transmit\_Power\_GM1\_SS3\_HH\_1.png...

Getting calibration pulses data for GM1 SS3 H/H from 2010-08-30 00:00:00 to 2010-08-30 23:59:59. Rows: 2/6/10/14/18/22/26/30  
Writing file ./RESULTS/DAILY/\_100830/CALIBRATION\_PULSES/Calibration\_pulses\_data\_GM1\_SS3\_HH\_2010-08-30\_2.dat...  
Writing ../../RESULTS/DAILY/\_100830//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_GM1\_SS3\_HH\_2.png...  
Writing ../../RESULTS/DAILY/\_100830//CALIBRATION\_PULSES/Transmit\_Power\_GM1\_SS3\_HH\_2.png...

Getting calibration pulses data for GM1 SS3 H/H from 2010-08-30 00:00:00 to 2010-08-30 23:59:59. Rows: 3/7/11/15/19/23/27/31  
Writing file ./RESULTS/DAILY/\_100830/CALIBRATION\_PULSES/Calibration\_pulses\_data\_GM1\_SS3\_HH\_2010-08-30\_3.dat...  
Writing ../../RESULTS/DAILY/\_100830//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_GM1\_SS3\_HH\_3.png...  
Writing ../../RESULTS/DAILY/\_100830//CALIBRATION\_PULSES/Transmit\_Power\_GM1\_SS3\_HH\_3.png...

Getting calibration pulses data for GM1 SS3 H/H from 2010-08-30 00:00:00 to 2010-08-30 23:59:59. Rows: 4/8/12/16/20/24/28/32  
Writing file ./RESULTS/DAILY/\_100830/CALIBRATION\_PULSES/Calibration\_pulses\_data\_GM1\_SS3\_HH\_2010-08-30\_4.dat...  
Writing ../../RESULTS/DAILY/\_100830//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_GM1\_SS3\_HH\_4.png...  
Writing ../../RESULTS/DAILY/\_100830//CALIBRATION\_PULSES/Transmit\_Power\_GM1\_SS3\_HH\_4.png...

CALIBRATION PULSES ANALYSIS completed

#####

DOPPLER ANALYSIS

#####

Creating directory ./RESULTS/DAILY/\_100830/DOPPLER...

\*\*\*\*\*  
\*\*\*\*\*  
DOPPLER ANX Analysis will be performed from 2010-08-30 00:00:00 to 2010-08-30 23:59:59

Analysing products WVS IS2 V/V  
Getting doppler data for WVS IS2 V/V from 2010-08-30 00:00:00 to 2010-08-30 23:59:59...  
Writing file ./RESULTS/DAILY/\_100830/DOPPLER/Doppler\_data\_WVS\_IS2\_VV\_2010-08-30.dat...  
Running IDL program...  
Writing file ../../RESULTS/DAILY/\_100830/DOPPLER/DOPPLER\_ANX\_WVS\_IS2\_VV.png...

Analysing products GM1 SS1 H/H  
Getting doppler data for GM1 SS1 H/H from 2010-08-30 00:00:00 to 2010-08-30 23:59:59...  
Writing file ./RESULTS/DAILY/\_100830/DOPPLER/Doppler\_data\_GM1\_SS1\_HH\_2010-08-30.dat...  
Running IDL program...  
Writing file ../../RESULTS/DAILY/\_100830/DOPPLER/DOPPLER\_ANX\_GM1\_SS1\_HH.png...

\*\*\*\*\*  
\*\*\*\*\*  
DOPPLER JUMPS Analysis will be performed on WSM products from 2010-08-30 00:00:00 to 2010-08-30 23:59:59

Analysing by default products WSM  
Getting doppler jumps data for WSM from 2010-08-30 00:00:00 to 2010-08-30 23:59:59...  
Writing file ./RESULTS/DAILY/\_100830/DOPPLER/Doppler\_Jumps\_data\_WSM\_2010-08-30.dat...  
Running IDL program...  
Writing file ../../RESULTS/DAILY/\_100830/DOPPLER/DOPPLER\_JUMPS\_ANX\_WSM.png...  
Writing file ../../RESULTS/DAILY/\_100830/DOPPLER/DOPPLER\_JUMPS\_Date\_WSM.png...

\*\*\*\*\*  
\*\*\*\*\*  
DOPPLER MAP Analysis will be performed from 2010-08-30 00:00:00 to 2010-08-30 23:59:59

Analysing products WVS IS2 V/V  
Loading predicted doppler values....  
Phase: descending  
Found data...  
Computing mean error doppler estimated-predicted...  
Mean error = -38.972050 Hz  
Writing file ../../RESULTS/DAILY/\_100830//DOPPLER/DOPPLER\_Estimated-Predicted-MeanError\_WVS\_IS2\_VV\_desc.jpg...  
Writing file ../../RESULTS/DAILY/\_100830//DOPPLER/DOPPLER\_Absolute\_WVS\_IS2\_VV\_desc.jpg...

\*\*\*\*\*  
Loading predicted doppler values....  
Phase: ascending  
Found data...  
Computing mean error doppler estimated-predicted...  
Mean error = -26.301476 Hz  
Writing file ../../RESULTS/DAILY/\_100830//DOPPLER/DOPPLER\_Estimated-Predicted-MeanError\_WVS\_IS2\_VV\_asc.jpg...  
Writing file ../../RESULTS/DAILY/\_100830//DOPPLER/DOPPLER\_Absolute\_WVS\_IS2\_VV\_asc.jpg...

\*\*\*\*\*  
Analysing products GM1 SS1 H/H  
Loading predicted doppler values....  
Phase: descending  
Found data...  
Computing mean error doppler estimated-predicted...  
Mean error = -0.66237904 Hz  
Writing file ../../RESULTS/DAILY/\_100830//DOPPLER/DOPPLER\_Estimated-Predicted-MeanError\_GM1\_SS1\_HH\_desc.jpg...  
Writing file ../../RESULTS/DAILY/\_100830//DOPPLER/DOPPLER\_Absolute\_GM1\_SS1\_HH\_desc.jpg...

\*\*\*\*\*  
Loading predicted doppler values....  
Phase: ascending  
Found data...  
Computing mean error doppler estimated-predicted...

Mean error = -9.9443170 Hz  
Writing file ../../RESULTS/DAILY/\_100830//DOPPLER/DOPPLER\_Estimated-Predicted-MeanError\_GM1\_SS1\_HH\_asc.jpg...  
Writing file ../../RESULTS/DAILY/\_100830//DOPPLER/DOPPLER\_Absolute\_GM1\_SS1\_HH\_asc.jpg...

\*\*\*\*\*

DOPPLER ANALYSIS completed  
#####

CHIRP ANALYSIS  
#####  
Creating directory ./RESULTS/DAILY/\_100830/CHIRP...

\*\*\*\*\*  
\*\*\*\*\*  
CHIRP Analysis will be performed from 2010-08-30 00:00:00 to 2010-08-30 23:59:59

Analysing products WSM SS1 H/H  
\*\*\*\*\*  
Getting ScaleFactor data for WSM SS1 H/H from 2010-08-30 00:00:00 to 2010-08-30 23:59:59...  
Writing file ./RESULTS/DAILY/\_100830/CHIRP/ScaleFactor\_data\_WSM\_SS1\_HH\_2010-08-30.dat...  
Running IDL program...  
Writing file ../../RESULTS/DAILY/\_100830/CHIRP/ScaleFactor\_ANX\_WSM\_SS1\_HH.png...  
Writing file ../../RESULTS/DAILY/\_100830/CHIRP/ScaleFactor\_DATE\_WSM\_SS1\_HH.png...

Analysing products WSM SS1 V/V  
\*\*\*\*\*  
Getting ScaleFactor data for WSM SS1 V/V from 2010-08-30 00:00:00 to 2010-08-30 23:59:59...  
Writing file ./RESULTS/DAILY/\_100830/CHIRP/ScaleFactor\_data\_WSM\_SS1\_VV\_2010-08-30.dat...  
Running IDL program...  
Writing file ../../RESULTS/DAILY/\_100830/CHIRP/ScaleFactor\_ANX\_WSM\_SS1\_VV.png...  
Writing file ../../RESULTS/DAILY/\_100830/CHIRP/ScaleFactor\_DATE\_WSM\_SS1\_VV.png...

CHIRP ANALYSIS completed  
#####

RAW DATA ANALYSIS  
#####  
Analysis will be performed from 2010-08-30 00:00:00 to 2010-08-30 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/\_100830/RAW\_DATA

Creating directory ./RESULTS/DAILY/\_100830/RAW\_DATA...

\*\*\*\*\*  
Getting raw data for WVS from 2010-08-30 00:00:00 to 2010-08-30 23:59:59...  
Writing file ./RESULTS/DAILY/\_100830/RAW\_DATA/Raw\_data\_WVS\_2010-08-30.dat...  
Running IDL program to create graphs...

Creating image ../../RESULTS/DAILY/\_100830/RAW\_DATA/Raw\_data\_WVS\_input\_mean.png...  
Creating image ../../RESULTS/DAILY/\_100830/RAW\_DATA/Raw\_data\_WVS\_input\_stdev.png...  
Creating image ../../RESULTS/DAILY/\_100830/RAW\_DATA/Raw\_data\_WVS\_gain\_imbalance.png...

\*\*\*\*\*  
Getting raw data for IMM from 2010-08-30 00:00:00 to 2010-08-30 23:59:59...  
Writing file ./RESULTS/DAILY/\_100830/RAW\_DATA/Raw\_data\_IMM\_2010-08-30.dat...  
Running IDL program to create graphs...

Creating image ../../RESULTS/DAILY/\_100830/RAW\_DATA/Raw\_data\_IMM\_input\_mean.png...

Creating image ../../RESULTS/DAILY/\_100830/RAW\_DATA/Raw\_data\_IMM\_input\_stdev.png...  
Creating image ../../RESULTS/DAILY/\_100830/RAW\_DATA/Raw\_data\_IMM\_gain\_imbalance.png...

RAW DATA ANALYSIS completed

#####

TELEMETRY ANALYSIS

#####

Analysis will be performed from 2010-08-30 00:00:00 to 2010-08-30 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/\_100830/TELEMETRY

Creating directory ./RESULTS/DAILY/\_100830/TELEMETRY...

Looking for gaps and missing lines in WVS products...

\*\*\*\*\*

Checking 25 products from PDE...

Checking 22 products from PDK...

Looking for gaps and missing lines in GM1 products...

\*\*\*\*\*

Checking 40 products from PDE...

Checking 32 products from PDK...

Looking for gaps and missing lines in APM products...

\*\*\*\*\*

Checking 1 products from PDE...

Checking 1 products from PDK...

Looking for gaps and missing lines in IMM products...

\*\*\*\*\*

Checking 33 products from PDE...

Checking 2 products from PDK...

Looking for gaps and missing lines in WSM products...

\*\*\*\*\*

Checking 29 products from PDE...

Checking 10 products from PDK...

Creating graph of missing lines and gaps...

\*\*\*\*\*

Creating image: ./RESULTS/DAILY/\_100830/TELEMETRY/TELEMETRY\_Missing\_lines.png...

Creating image: ./RESULTS/DAILY/\_100830/TELEMETRY/TELEMETRY\_Gaps.png...

TELEMETRY ANALYSIS completed

#####

HTML REPORT generation

#####

Building file ./RESULTS/DAILY/\_100830/asarReport.html...

Building DATA SUMMARY section...

Building AUXILIARY FILES ANALYSIS section...

Building MODULE STEPPING ANALYSIS section...

Building CALIBRATION PULSES ANALYSIS section...

Building DOPPLER ANALYSIS section...

Building CHIRP ANALYSIS section...

Building RAW DATA ANALYSIS section...

Building TELEMETRY ANALYSIS section...

HTML REPORT generation completed

#####





Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
ASA_APM_1PNPDE20100830_064006_000000562092_00292_44434_8679.N1	OK	OK	OK	OK
ASA_APM_1PNPDK20100830_081009_000000432092_00293_44435_2479.N1	OK	OK	OK	OK



Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_GM1_1PNPDE20100830_000237_000005372092_00288_44430_8593.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100830_001712_000002112092_00288_44430_8596.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100830_004818_000001632092_00288_44430_8611.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100830_011538_000003382092_00289_44431_8612.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100830_012319_000005552092_00289_44431_8614.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100830_013723_000004592092_00289_44431_8616.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100830_014757_000001692092_00289_44431_8620.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100830_015747_000000782092_00289_44431_8619.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100830_020034_000004592092_00289_44431_8618.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100830_021511_000000902092_00289_44431_8624.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100830_022219_000008882092_00289_44431_8637.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100830_024531_000004652092_00290_44432_8644.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100830_025403_000004472092_00290_44432_8642.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100830_034348_000004102092_00290_44432_8665.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100830_035436_000003442092_00290_44432_8664.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100830_042208_000014502092_00291_44433_8662.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100830_045143_000003442092_00291_44433_8672.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100830_051856_000003922092_00291_44433_8684.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100830_053422_000002172092_00291_44433_8682.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100830_060307_000006222092_00292_44434_8681.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100830_061511_000003322092_00292_44434_8689.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100830_062711_000001992092_00292_44434_8688.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100830_063210_000004772092_00292_44434_8701.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100830_064121_000001572092_00292_44434_8700.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100830_193413_000001992092_00300_44442_8807.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100830_194253_000002052092_00300_44442_8806.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100830_194926_000001632092_00300_44442_8809.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100830_202424_000002352092_00300_44442_8810.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100830_204113_000001262092_00300_44442_8813.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100830_204924_000010942092_00300_44442_8835.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100830_212346_000001932092_00301_44443_8834.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100830_212935_000001872092_00301_44443_8833.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100830_220458_000001872092_00301_44443_8832.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100830_221209_000001022092_00301_44443_8828.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100830_224037_000004222092_00302_44444_8846.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100830_230342_000004592092_00302_44444_8849.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100830_233542_000002172092_00302_44444_8848.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100830_233928_000000962092_00302_44444_8852.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100830_234532_000001502092_00302_44444_8851.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20100830_234947_000001022092_00302_44444_8855.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100830_065936_000002232092_00292_44434_2462.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100830_070721_000002952092_00292_44434_2464.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100830_071514_000001992092_00292_44434_2465.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100830_075035_000002112092_00293_44435_2466.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100830_075543_000002712092_00293_44435_2469.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100830_080713_000001752092_00293_44435_2494.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100830_082311_000005492092_00293_44435_2496.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100830_084011_000000782092_00293_44435_2495.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100830_084258_000005862092_00293_44435_2497.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100830_085629_000001632092_00293_44435_2499.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100830_093219_000005372092_00294_44436_2502.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100830_095733_000003922092_00294_44436_2538.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100830_102046_000001752092_00294_44436_2541.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100830_103115_000001022092_00294_44436_2540.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100830_103655_000001692092_00294_44436_2542.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100830_110949_000003682092_00295_44437_2543.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100830_111739_000001812092_00295_44437_2545.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100830_120119_000001322092_00295_44437_2561.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100830_120740_000003322092_00295_44437_2563.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100830_121747_000001572092_00295_44437_2565.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100830_122627_000002412092_00295_44437_2567.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100830_123254_000001202092_00295_44437_2569.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100830_124808_000005072092_00296_44438_2570.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20100830_125824_000003142092_00296_44438_2571.N1					OK	OK	OK	OK

ASA_GM1_1PNPDK20100830_130249_000002772092_00296_44438_2596.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100830_132452_000006282092_00296_44438_2597.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100830_133551_000010942092_00296_44438_2600.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100830_135820_000001572092_00296_44438_2598.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100830_140716_000002892092_00296_44438_2602.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100830_141319_000003802092_00296_44438_2603.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100830_152234_000008702092_00297_44439_2641.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20100830_153918_000001322092_00297_44439_2639.N1	OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_IMM_1PNPDE20100830_002045_000005122092_00288_44430_8587.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100830_002045_000005122092_00288_44430_8658.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100830_012116_000001122092_00289_44431_8615.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100830_020814_000000922092_00289_44431_8613.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100830_031052_000003322092_00290_44432_8633.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100830_034056_000001622092_00290_44432_8652.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100830_044613_000003182092_00291_44433_8659.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100830_052526_000003732092_00291_44433_8680.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100830_070319_000002322092_00292_44434_8690.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100830_094711_000000702092_00294_44436_8745.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100830_095223_000000512092_00294_44436_8746.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100830_095643_000000372092_00294_44436_8747.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100830_102340_000004432092_00294_44436_8748.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100830_114029_000000532092_00295_44437_8768.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100830_120336_000002322092_00295_44437_8771.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100830_160356_000001652092_00298_44440_8794.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100830_160756_000001422092_00298_44440_8795.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100830_162631_000001122092_00298_44440_8798.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100830_164136_000000832092_00298_44440_8799.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100830_170808_000003022092_00298_44440_8800.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100830_171358_000002332092_00298_44440_8796.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100830_181305_000001462092_00299_44441_8803.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100830_181606_000001442092_00299_44441_8804.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100830_184813_000003022092_00299_44441_8805.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100830_185403_000002332092_00299_44441_8801.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100830_194620_000001772092_00300_44442_8822.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100830_202818_000003022092_00300_44442_8823.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100830_203408_000002332092_00300_44442_8808.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100830_211139_000000372092_00301_44443_8825.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100830_220804_000002322092_00301_44443_8838.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100830_221354_000002332092_00301_44443_8824.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100830_234802_000000912092_00302_44444_8864.N1					OK	OK	OK	OK
ASA_IMM_1PNPDE20100830_235132_000003732092_00302_44444_8844.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20100830_080440_000001442092_00293_44435_2480.N1					OK	OK	OK	OK
ASA_IMM_1PNPDK20100830_095136_000000702092_00294_44436_2524.N1					OK	OK	OK	OK


Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WSM_1PNPDE20100830_003028_000002692092_00288_44430_8603.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100830_010814_000004402092_00289_44431_8609.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100830_021019_000002882092_00289_44431_8627.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100830_024010_000002142092_00290_44432_8634.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100830_030136_000001472092_00290_44432_8650.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100830_035042_000002262092_00290_44432_8667.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100830_041700_000003062092_00291_44433_8676.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100830_045733_000000922092_00291_44433_8660.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100830_053207_000001282092_00291_44433_8685.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100830_061337_000000862092_00292_44434_8691.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100830_063035_000000922092_00292_44434_8678.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100830_080021_000002452092_00293_44435_8725.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100830_081944_000002022092_00293_44435_8726.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100830_094124_000002142092_00294_44436_8743.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100830_094515_000000922092_00294_44436_8744.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100830_103309_000002262092_00294_44436_8769.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100830_111605_000000922092_00295_44437_8770.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100830_112623_000001472092_00295_44437_8767.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100830_135413_000002452092_00296_44438_8791.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100830_142356_000000862092_00297_44439_8792.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100830_144528_000002142092_00297_44439_8793.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100830_153707_000001282092_00297_44439_8790.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100830_171806_000001162092_00298_44440_8797.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100830_185807_000001282092_00299_44441_8802.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100830_203906_000001222092_00300_44442_8820.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100830_212704_000001472092_00301_44443_8836.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100830_221857_000002322092_00301_44443_8827.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100830_231126_000000982092_00302_44444_8867.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20100830_235846_000002942092_00302_44444_8859.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100830_062050_000003672092_00292_44434_2451.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100830_071221_000001712092_00292_44434_2476.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100830_075413_000000862092_00293_44435_2477.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100830_085250_000002202092_00293_44435_2522.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100830_094846_000001222092_00294_44436_2523.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100830_121318_000002692092_00295_44437_2581.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100830_124457_000000862092_00296_44438_2580.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100830_125642_000000982092_00296_44438_2584.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100830_130731_000001222092_00296_44438_2582.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20100830_143641_000005142092_00297_44439_2611.N1					OK	OK	OK	OK





Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WVS_1PNPDE20100830_001138_000002852092_00288_44430_8594.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100830_003605_000002552092_00288_44430_8595.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100830_003935_000004792092_00288_44430_8610.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100830_005102_000009592092_00288_44430_8617.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100830_014505_000001342092_00289_44431_8621.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100830_015047_000003752092_00289_44431_8622.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100830_021649_00000152092_00289_44431_8623.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100830_021649_000002852092_00289_44431_8639.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100830_032222_000005842092_00290_44432_8638.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100830_033151_000002852092_00290_44432_8663.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100830_040022_000009442092_00290_44432_8661.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100830_045941_000008542092_00291_44433_8668.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100830_051340_000001052092_00291_44433_8683.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100830_053801_000014542092_00291_44433_8699.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100830_064402_000006292092_00292_44434_8698.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100830_195215_000018892092_00300_44442_8811.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100830_204325_000001492092_00300_44442_8812.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100830_204510_000002102092_00300_44442_8831.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100830_213244_000018892092_00301_44443_8830.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100830_222352_000003152092_00301_44443_8829.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100830_222822_000006892092_00301_44443_8847.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100830_224740_000004792092_00302_44444_8845.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100830_231306_000013042092_00302_44444_8850.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20100830_234110_000002252092_00302_44444_8853.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100830_065402_000002852092_00292_44434_2463.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100830_071837_000018742092_00292_44434_2467.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100830_083219_000004202092_00293_44435_2498.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100830_085913_000019492092_00293_44435_2503.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100830_100407_000009592092_00294_44436_2539.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100830_103949_000017542092_00294_44436_2544.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100830_112854_000006592092_00295_44437_2560.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100830_114127_000011542092_00295_44437_2562.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100830_122025_000003152092_00295_44437_2564.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100830_123029_000001042092_00295_44437_2566.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100830_123458_000005572092_00295_44437_2568.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100830_124624_000000592092_00296_44438_2572.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100830_130938_000008692092_00296_44438_2599.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100830_140101_000003302092_00296_44438_2601.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100830_141939_000001342092_00297_44439_2604.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100830_150855_000007792092_00297_44439_2644.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100830_154137_000012442092_00297_44439_2636.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100830_164305_000011542092_00298_44440_2653.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100830_172213_000012892092_00298_44440_2657.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100830_181836_000014692092_00299_44441_2682.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100830_190407_000004202092_00299_44441_2685.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20100830_191447_000001642092_00299_44441_2689.N1					OK	OK	OK	OK





Calibration pulses for GM1 SS3 H/H



### Calibration pulses for GM1 SS3 H/H







Calibration pulses for GM1 SS3 H/H



rows: \_ 3 \_ 7 \_ 11 \_ 15 \_ 19 \_ 23 \_ 27 \_ 31




### Calibration pulses for GM1 SS3 H/H




rows: \_ 4 \_ 8 \_ 12 \_ 16 \_ 20 \_ 24 \_ 28 \_ 32

Calibration pulses for WVS IS2 V/V




rows: 1 5 9 13 17 21 25 29


### Calibration pulses for WVS IS2 V/V




Calibration pulses for WVS IS2 V/V




### Calibration pulses for WVS IS2 V/V




30-Aug



30-Aug





30-Aug





30-Aug

rows: \_ 4 \_ 8 \_ 12 \_ 16 \_ 20 \_ 24 \_ 28 \_ 32















30-Aug  
rows: \_ 1 \_ 5 \_ 9 \_ 13 \_ 17 \_ 21 \_ 25 \_ 29





































Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion			
ASA_APM_1PNPDE20100830_064006_000000562092_00292_44434_8679.N1						IS4 H/H 92	44434	292	5.03
ASA_APM_1PNPDK20100830_081009_000000432092_00293_44435_2479.N1						IS2 V/H 92	44435	293	5.03

Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_GM1_1PNPDE20100830_000237_000005372092_00288_44430_8593.N1						SS1	H/H	92	44430	288	5.03
ASA_GM1_1PNPDE20100830_001712_000002112092_00288_44430_8596.N1						SS1	H/H	92	44430	288	5.03
ASA_GM1_1PNPDE20100830_004818_000001632092_00288_44430_8611.N1						SS1	H/H	92	44430	288	5.03
ASA_GM1_1PNPDE20100830_011538_000003382092_00289_44431_8612.N1						SS1	H/H	92	44431	289	5.03
ASA_GM1_1PNPDE20100830_012319_000005552092_00289_44431_8614.N1						SS1	H/H	92	44431	289	5.03
ASA_GM1_1PNPDE20100830_013723_000004592092_00289_44431_8616.N1						SS1	H/H	92	44431	289	5.03
ASA_GM1_1PNPDE20100830_014757_000001692092_00289_44431_8620.N1						SS1	H/H	92	44431	289	5.03
ASA_GM1_1PNPDE20100830_015747_000000782092_00289_44431_8619.N1						SS1	H/H	92	44431	289	5.03
ASA_GM1_1PNPDE20100830_020034_000004592092_00289_44431_8618.N1						SS1	H/H	92	44431	289	5.03
ASA_GM1_1PNPDE20100830_021511_000000902092_00289_44431_8624.N1						SS1	H/H	92	44431	289	5.03
ASA_GM1_1PNPDE20100830_022219_000008882092_00289_44431_8637.N1						SS1	H/H	92	44431	289	5.03
ASA_GM1_1PNPDE20100830_024531_000004652092_00290_44432_8644.N1						SS1	H/H	92	44432	290	5.03
ASA_GM1_1PNPDE20100830_025403_000004472092_00290_44432_8642.N1						SS1	H/H	92	44432	290	5.03
ASA_GM1_1PNPDE20100830_034348_000004102092_00290_44432_8665.N1						SS1	H/H	92	44432	290	5.03
ASA_GM1_1PNPDE20100830_035436_000003442092_00290_44432_8664.N1						SS1	H/H	92	44432	290	5.03
ASA_GM1_1PNPDE20100830_042208_000014502092_00291_44433_8662.N1						SS1	H/H	92	44433	291	5.03
ASA_GM1_1PNPDE20100830_045143_000003442092_00291_44433_8672.N1						SS1	H/H	92	44433	291	5.03
ASA_GM1_1PNPDE20100830_051856_000003922092_00291_44433_8684.N1						SS1	H/H	92	44433	291	5.03
ASA_GM1_1PNPDE20100830_053422_000002172092_00291_44433_8682.N1						SS1	H/H	92	44433	291	5.03
ASA_GM1_1PNPDE20100830_060307_000006222092_00292_44434_8681.N1						SS1	H/H	92	44434	292	5.03
ASA_GM1_1PNPDE20100830_061511_000003322092_00292_44434_8689.N1						SS1	H/H	92	44434	292	5.03
ASA_GM1_1PNPDE20100830_062711_000001992092_00292_44434_8688.N1						SS1	H/H	92	44434	292	5.03
ASA_GM1_1PNPDE20100830_063210_000004772092_00292_44434_8701.N1						SS1	H/H	92	44434	292	5.03
ASA_GM1_1PNPDE20100830_064121_000001572092_00292_44434_8700.N1						SS1	H/H	92	44434	292	5.03
ASA_GM1_1PNPDK20100830_065936_000002232092_00292_44434_2462.N1						SS1	H/H	92	44434	292	5.03
ASA_GM1_1PNPDK20100830_070721_000002952092_00292_44434_2464.N1						SS1	H/H	92	44434	292	5.03
ASA_GM1_1PNPDK20100830_071514_000001992092_00292_44434_2465.N1						SS1	H/H	92	44434	292	5.03
ASA_GM1_1PNPDK20100830_075035_000002112092_00293_44435_2466.N1						SS1	H/H	92	44435	293	5.03
ASA_GM1_1PNPDK20100830_075543_000002712092_00293_44435_2469.N1						SS1	H/H	92	44435	293	5.03
ASA_GM1_1PNPDK20100830_080713_000001752092_00293_44435_2494.N1						SS1	H/H	92	44435	293	5.03
ASA_GM1_1PNPDK20100830_082311_000005492092_00293_44435_2496.N1						SS1	H/H	92	44435	293	5.03
ASA_GM1_1PNPDK20100830_084011_000000782092_00293_44435_2495.N1						SS1	H/H	92	44435	293	5.03
ASA_GM1_1PNPDK20100830_084258_000005862092_00293_44435_2497.N1						SS1	H/H	92	44435	293	5.03
ASA_GM1_1PNPDK20100830_085629_000001632092_00293_44435_2499.N1						SS1	H/H	92	44435	293	5.03
ASA_GM1_1PNPDK20100830_093219_000005372092_00294_44436_2502.N1						SS1	H/H	92	44436	294	5.03
ASA_GM1_1PNPDK20100830_095733_000003922092_00294_44436_2538.N1						SS1	H/H	92	44436	294	5.03
ASA_GM1_1PNPDK20100830_102046_000001752092_00294_44436_2541.N1						SS1	H/H	92	44436	294	5.03
ASA_GM1_1PNPDK20100830_103115_000001022092_00294_44436_2540.N1						SS1	H/H	92	44436	294	5.03
ASA_GM1_1PNPDK20100830_103655_000001692092_00294_44436_2542.N1						SS1	H/H	92	44436	294	5.03
ASA_GM1_1PNPDK20100830_110949_000003682092_00295_44437_2543.N1						SS1	H/H	92	44437	295	5.03
ASA_GM1_1PNPDK20100830_111739_000001812092_00295_44437_2545.N1						SS1	H/H	92	44437	295	5.03
ASA_GM1_1PNPDK20100830_120119_000001322092_00295_44437_2561.N1						SS1	H/H	92	44437	295	5.03
ASA_GM1_1PNPDK20100830_120740_000003322092_00295_44437_2563.N1						SS1	H/H	92	44437	295	5.03
ASA_GM1_1PNPDK20100830_121747_000001572092_00295_44437_2565.N1						SS1	H/H	92	44437	295	5.03
ASA_GM1_1PNPDK20100830_122627_000002412092_00295_44437_2567.N1						SS1	H/H	92	44437	295	5.03
ASA_GM1_1PNPDK20100830_123254_000001202092_00295_44437_2569.N1						SS1	H/H	92	44437	295	5.03
ASA_GM1_1PNPDK20100830_124808_000005072092_00296_44438_2570.N1						SS1	H/H	92	44438	296	5.03
ASA_GM1_1PNPDK20100830_125824_000003142092_00296_44438_2571.N1						SS1	H/H	92	44438	296	5.03
ASA_GM1_1PNPDK20100830_130249_000002772092_00296_44438_2596.N1						SS1	H/H	92	44438	296	5.03
ASA_GM1_1PNPDK20100830_132452_000006282092_00296_44438_2597.N1						SS1	H/H	92	44438	296	5.03
ASA_GM1_1PNPDK20100830_133551_000010942092_00296_44438_2600.N1						SS1	H/H	92	44438	296	5.03
ASA_GM1_1PNPDK20100830_135820_000001572092_00296_44438_2598.N1						SS1	H/H	92	44438	296	5.03
ASA_GM1_1PNPDK20100830_140716_000002892092_00296_44438_2602.N1						SS1	H/H	92	44438	296	5.03
ASA_GM1_1PNPDK20100830_141319_000003802092_00296_44438_2603.N1						SS1	H/H	92	44438	296	5.03
ASA_GM1_1PNPDK20100830_152234_000008702092_00297_44439_2641.N1						SS1	H/H	92	44439	297	5.03
ASA_GM1_1PNPDK20100830_153918_000001322092_00297_44439_2639.N1						SS1	H/H	92	44439	297	5.03
ASA_GM1_1PNPDE20100830_193413_000001992092_00300_44442_8807.N1						SS1	H/H	92	44442	300	5.03
ASA_GM1_1PNPDE20100830_194253_000002052092_00300_44442_8806.N1						SS1	H/H	92	44442	300	5.03
ASA_GM1_1PNPDE20100830_194926_000001632092_00300_44442_8809.N1						SS1	H/H	92	44442	300	5.03
ASA_GM1_1PNPDE20100830_202424_000002352092_00300_44442_8810.N1						SS1	H/H	92	44442	300	5.03
ASA_GM1_1PNPDE20100830_204113_000001262092_00300_44442_8813.N1						SS1	H/H	92	44442	300	5.03
ASA_GM1_1PNPDE20100830_204924_000010942092_00300_44442_8835.N1						SS1	H/H	92	44442	300	5.03
ASA_GM1_1PNPDE20100830_212346_000001932092_00301_44443_8834.N1						SS1	H/H	92	44443	301	5.03
ASA_GM1_1PNPDE20100830_212935_000001872092_00301_44443_8833.N1						SS1	H/H	92	44443	301	5.03
ASA_GM1_1PNPDE20100830_220458_000001872092_00301_44443_8832.N1						SS1	H/H	92	44443	301	5.03
ASA_GM1_1PNPDE20100830_221209_000001022092_00301_44443_8828.N1						SS1	H/H	92	44443	301	5.03
ASA_GM1_1PNPDE20100830_224037_000004222092_00302_44444_8846.N1						SS1	H/H	92	44444	302	5.03

ASA_GM1_1PNPDE20100830_230342_000004592092_00302_44444_8849.N1	SS1	H/H	92	44444	302	5.03
ASA_GM1_1PNPDE20100830_233542_000002172092_00302_44444_8848.N1	SS1	H/H	92	44444	302	5.03
ASA_GM1_1PNPDE20100830_233928_000000962092_00302_44444_8852.N1	SS1	H/H	92	44444	302	5.03
ASA_GM1_1PNPDE20100830_234532_000001502092_00302_44444_8851.N1	SS1	H/H	92	44444	302	5.03
ASA_GM1_1PNPDE20100830_234947_000001022092_00302_44444_8855.N1	SS1	H/H	92	44444	302	5.03


Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_IMM_1PNPDE20100830_002045_000005122092_00288_44430_8587.N1						IS2	H/H	92	44430	288	5.03
ASA_IMM_1PNPDE20100830_002045_000005122092_00288_44430_8658.N1						IS2	H/H	92	44430	288	5.03
ASA_IMM_1PNPDE20100830_012116_000001122092_00289_44431_8615.N1						IS2	V/V	92	44431	289	5.03
ASA_IMM_1PNPDE20100830_020814_000000922092_00289_44431_8613.N1						IS2	H/H	92	44431	289	5.03
ASA_IMM_1PNPDE20100830_031052_000003322092_00290_44432_8633.N1						IS2	V/V	92	44432	290	5.03
ASA_IMM_1PNPDE20100830_034056_000001622092_00290_44432_8652.N1						IS2	H/H	92	44432	290	5.03
ASA_IMM_1PNPDE20100830_044613_000003182092_00291_44433_8659.N1						IS2	V/V	92	44433	291	5.03
ASA_IMM_1PNPDE20100830_052526_000003732092_00291_44433_8680.N1						IS2	H/H	92	44433	291	5.03
ASA_IMM_1PNPDE20100830_070319_000002322092_00292_44434_8690.N1						IS2	H/H	92	44434	292	5.03
ASA_IMM_1PNPDK20100830_080440_000001442092_00293_44435_2480.N1						IS2	V/V	92	44435	293	5.03
ASA_IMM_1PNPDE20100830_094711_000000702092_00294_44436_8745.N1						IS7	V/V	92	44436	294	5.03
ASA_IMM_1PNPDK20100830_095136_000000702092_00294_44436_2524.N1						IS2	V/V	92	44436	294	5.03
ASA_IMM_1PNPDE20100830_095223_000000512092_00294_44436_8746.N1						IS2	V/V	92	44436	294	5.03
ASA_IMM_1PNPDE20100830_095643_000000372092_00294_44436_8747.N1						IS2	V/V	92	44436	294	5.03
ASA_IMM_1PNPDE20100830_102340_000004432092_00294_44436_8748.N1						IS2	H/H	92	44436	294	5.03
ASA_IMM_1PNPDE20100830_114029_000000532092_00295_44437_8768.N1						IS2	V/V	92	44437	295	5.03
ASA_IMM_1PNPDE20100830_120336_000002322092_00295_44437_8771.N1						IS2	H/H	92	44437	295	5.03
ASA_IMM_1PNPDE20100830_160356_000001652092_00298_44440_8794.N1						IS2	V/V	92	44440	298	5.03
ASA_IMM_1PNPDE20100830_160756_000001422092_00298_44440_8795.N1						IS2	V/V	92	44440	298	5.03
ASA_IMM_1PNPDE20100830_162631_000001122092_00298_44440_8798.N1						IS2	V/V	92	44440	298	5.03
ASA_IMM_1PNPDE20100830_164136_000000832092_00298_44440_8799.N1						IS2	V/V	92	44440	298	5.03
ASA_IMM_1PNPDE20100830_170808_000003022092_00298_44440_8800.N1						IS2	H/H	92	44440	298	5.03
ASA_IMM_1PNPDE20100830_171358_000002332092_00298_44440_8796.N1						IS2	H/H	92	44440	298	5.03
ASA_IMM_1PNPDE20100830_181305_000001462092_00299_44441_8803.N1						IS2	V/V	92	44441	299	5.03
ASA_IMM_1PNPDE20100830_181606_000001442092_00299_44441_8804.N1						IS2	V/V	92	44441	299	5.03
ASA_IMM_1PNPDE20100830_184813_000003022092_00299_44441_8805.N1						IS2	H/H	92	44441	299	5.03
ASA_IMM_1PNPDE20100830_185403_000002332092_00299_44441_8801.N1						IS2	H/H	92	44441	299	5.03
ASA_IMM_1PNPDE20100830_194620_000001772092_00300_44442_8822.N1						IS2	V/V	92	44442	300	5.03
ASA_IMM_1PNPDE20100830_202818_000003022092_00300_44442_8823.N1						IS2	H/H	92	44442	300	5.03
ASA_IMM_1PNPDE20100830_203408_000002332092_00300_44442_8808.N1						IS2	H/H	92	44442	300	5.03
ASA_IMM_1PNPDE20100830_211139_000000372092_00301_44443_8825.N1						IS2	V/V	92	44443	301	5.03
ASA_IMM_1PNPDE20100830_220804_000002322092_00301_44443_8838.N1						IS2	H/H	92	44443	301	5.03
ASA_IMM_1PNPDE20100830_221354_000002332092_00301_44443_8824.N1						IS2	H/H	92	44443	301	5.03
ASA_IMM_1PNPDE20100830_234802_000000912092_00302_44444_8864.N1						IS2	H/H	92	44444	302	5.03
ASA_IMM_1PNPDE20100830_235132_000003732092_00302_44444_8844.N1						IS2	H/H	92	44444	302	5.03


Filename	Pol	Timestamp	count(Module)				
ASA_MS__0PNPDE20100830_015914_000000162092_00289_44431_0562.N1	H	2010-08-30 01:59:14	320				
ASA_MS__0PNPDK20100830_084138_000000162092_00293_44435_0192.N1	V	2010-08-30 08:41:38	320				





Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WSM_1PNPDE20100830_003028_000002692092_00288_44430_8603.N1						SS1	H/H	92	44430	288	5.03
ASA_WSM_1PNPDE20100830_010814_000004402092_00289_44431_8609.N1						SS1	H/H	92	44431	289	5.03
ASA_WSM_1PNPDE20100830_021019_000002882092_00289_44431_8627.N1						SS1	H/H	92	44431	289	5.03
ASA_WSM_1PNPDE20100830_024010_000002142092_00290_44432_8634.N1						SS1	V/V	92	44432	290	5.03
ASA_WSM_1PNPDE20100830_030136_000001472092_00290_44432_8650.N1						SS1	H/H	92	44432	290	5.03
ASA_WSM_1PNPDE20100830_035042_000002262092_00290_44432_8667.N1						SS1	H/H	92	44432	290	5.03
ASA_WSM_1PNPDE20100830_041700_000003062092_00291_44433_8676.N1						SS1	V/V	92	44433	291	5.03
ASA_WSM_1PNPDE20100830_045733_000000922092_00291_44433_8660.N1						SS1	V/V	92	44433	291	5.03
ASA_WSM_1PNPDE20100830_053207_000001282092_00291_44433_8685.N1						SS1	H/H	92	44433	291	5.03
ASA_WSM_1PNPDE20100830_061337_000000862092_00292_44434_8691.N1						SS1	H/H	92	44434	292	5.03
ASA_WSM_1PNPDK20100830_062050_000003672092_00292_44434_2451.N1						SS1	H/H	92	44434	292	5.03
ASA_WSM_1PNPDE20100830_063035_000000922092_00292_44434_8678.N1						SS1	H/H	92	44434	292	5.03
ASA_WSM_1PNPDK20100830_071221_000001712092_00292_44434_2476.N1						SS1	H/H	92	44434	292	5.03
ASA_WSM_1PNPDK20100830_075413_000000862092_00293_44435_2477.N1						SS1	H/H	92	44435	293	5.03
ASA_WSM_1PNPDE20100830_080021_000002452092_00293_44435_8725.N1						SS1	H/H	92	44435	293	5.03
ASA_WSM_1PNPDE20100830_081944_000002022092_00293_44435_8726.N1						SS1	V/V	92	44435	293	5.03
ASA_WSM_1PNPDK20100830_085250_000002202092_00293_44435_2522.N1						SS1	H/H	92	44435	293	5.03
ASA_WSM_1PNPDE20100830_094124_000002142092_00294_44436_8743.N1						SS1	H/H	92	44436	294	5.03
ASA_WSM_1PNPDE20100830_094515_000000922092_00294_44436_8744.N1						SS1	V/V	92	44436	294	5.03
ASA_WSM_1PNPDK20100830_094846_000001222092_00294_44436_2523.N1						SS1	V/V	92	44436	294	5.03
ASA_WSM_1PNPDE20100830_103309_000002262092_00294_44436_8769.N1						SS1	H/H	92	44436	294	5.03
ASA_WSM_1PNPDE20100830_111605_000000922092_00295_44437_8770.N1						SS1	H/H	92	44437	295	5.03
ASA_WSM_1PNPDE20100830_112623_000001472092_00295_44437_8767.N1						SS1	H/H	92	44437	295	5.03
ASA_WSM_1PNPDK20100830_121318_000002692092_00295_44437_2581.N1						SS1	H/H	92	44437	295	5.03
ASA_WSM_1PNPDK20100830_124457_000000862092_00296_44438_2580.N1						SS1	V/V	92	44438	296	5.03
ASA_WSM_1PNPDK20100830_125642_000000982092_00296_44438_2584.N1						SS1	H/H	92	44438	296	5.03
ASA_WSM_1PNPDK20100830_130731_000001222092_00296_44438_2582.N1						SS1	H/H	92	44438	296	5.03
ASA_WSM_1PNPDE20100830_135413_000002452092_00296_44438_8791.N1						SS1	H/H	92	44438	296	5.03
ASA_WSM_1PNPDE20100830_142356_000000862092_00297_44439_8792.N1						SS1	H/H	92	44439	297	5.03
ASA_WSM_1PNPDK20100830_143641_000005142092_00297_44439_2611.N1						SS1	H/H	92	44439	297	5.03
ASA_WSM_1PNPDE20100830_144528_000002142092_00297_44439_8793.N1						SS1	H/H	92	44439	297	5.03
ASA_WSM_1PNPDE20100830_153707_000001282092_00297_44439_8790.N1						SS1	H/H	92	44439	297	5.03
ASA_WSM_1PNPDE20100830_171806_000001162092_00298_44440_8797.N1						SS1	H/H	92	44440	298	5.03
ASA_WSM_1PNPDE20100830_185807_000001282092_00299_44441_8802.N1						SS1	H/H	92	44441	299	5.03
ASA_WSM_1PNPDE20100830_203906_000001222092_00300_44442_8820.N1						SS1	H/H	92	44442	300	5.03
ASA_WSM_1PNPDE20100830_212704_000001472092_00301_44443_8836.N1						SS1	H/H	92	44443	301	5.03
ASA_WSM_1PNPDE20100830_221857_000002322092_00301_44443_8827.N1						SS1	H/H	92	44443	301	5.03
ASA_WSM_1PNPDE20100830_231126_000000982092_00302_44444_8867.N1						SS1	H/H	92	44444	302	5.03
ASA_WSM_1PNPDE20100830_235846_000002942092_00302_44444_8859.N1						SS1	H/H	92	44444	302	5.03




Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WVS_1PNPDE20100829_234712_000008842092_00288_44430_8592.N1						IS2	V/V	92	44430	288	5.03
ASA_WVS_1PNPDE20100830_001138_000002852092_00288_44430_8594.N1						IS2	V/V	92	44430	288	5.03
ASA_WVS_1PNPDE20100830_003605_000002552092_00288_44430_8595.N1						IS2	V/V	92	44430	288	5.03
ASA_WVS_1PNPDE20100830_003935_000004792092_00288_44430_8610.N1						IS2	V/V	92	44430	288	5.03
ASA_WVS_1PNPDE20100830_005102_000009592092_00288_44430_8617.N1						IS2	V/V	92	44430	288	5.03
ASA_WVS_1PNPDE20100830_014505_000001342092_00289_44431_8621.N1						IS2	V/V	92	44431	289	5.03
ASA_WVS_1PNPDE20100830_015047_000003752092_00289_44431_8622.N1						IS2	V/V	92	44431	289	5.03
ASA_WVS_1PNPDE20100830_021649_000002852092_00289_44431_8639.N1						IS2	V/V	92	44431	289	5.03
ASA_WVS_1PNPDE20100830_021649_000000152092_00289_44431_8623.N1						IS2	V/V	92	44431	289	5.03
ASA_WVS_1PNPDE20100830_032222_000005842092_00290_44432_8638.N1						IS2	V/V	92	44432	290	5.03
ASA_WVS_1PNPDE20100830_033151_000002852092_00290_44432_8663.N1						IS2	V/V	92	44432	290	5.03
ASA_WVS_1PNPDE20100830_040022_000009442092_00290_44432_8661.N1						IS2	V/V	92	44432	290	5.03
ASA_WVS_1PNPDE20100830_045941_000008542092_00291_44433_8668.N1						IS2	V/V	92	44433	291	5.03
ASA_WVS_1PNPDE20100830_051340_000001052092_00291_44433_8683.N1						IS2	V/V	92	44433	291	5.03
ASA_WVS_1PNPDE20100830_045941_000008542092_00291_44433_8668.N1						IS1	V/V	92	44433	291	5.03
ASA_WVS_1PNPDE20100830_053801_000014542092_00291_44433_8699.N1						IS2	V/V	92	44433	291	5.03
ASA_WVS_1PNPDE20100830_064402_000006292092_00292_44434_8698.N1						IS2	V/V	92	44434	292	5.03
ASA_WVS_1PNPDK20100830_065402_000002852092_00292_44434_2463.N1						IS2	V/V	92	44434	292	5.03
ASA_WVS_1PNPDE20100830_064402_000006292092_00292_44434_8698.N1						IS1	V/V	92	44434	292	5.03
ASA_WVS_1PNPDK20100830_071837_000018742092_00292_44434_2467.N1						IS2	V/V	92	44434	292	5.03
ASA_WVS_1PNPDK20100830_083219_000004202092_00293_44435_2498.N1						IS2	V/V	92	44435	293	5.03
ASA_WVS_1PNPDK20100830_085913_000019492092_00293_44435_2503.N1						IS2	V/V	92	44435	293	5.03
ASA_WVS_1PNPDK20100830_100407_000009592092_00294_44436_2539.N1						IS2	V/V	92	44436	294	5.03
ASA_WVS_1PNPDK20100830_103949_000017542092_00294_44436_2544.N1						IS2	V/V	92	44436	294	5.03
ASA_WVS_1PNPDK20100830_112854_000006592092_00295_44437_2560.N1						IS2	V/V	92	44437	295	5.03
ASA_WVS_1PNPDK20100830_114127_000011542092_00295_44437_2562.N1						IS2	V/V	92	44437	295	5.03
ASA_WVS_1PNPDK20100830_122025_000003152092_00295_44437_2564.N1						IS2	V/V	92	44437	295	5.03
ASA_WVS_1PNPDK20100830_123029_000001042092_00295_44437_2566.N1						IS2	V/V	92	44437	295	5.03
ASA_WVS_1PNPDK20100830_123458_000005572092_00295_44437_2568.N1						IS2	V/V	92	44437	295	5.03
ASA_WVS_1PNPDK20100830_124624_000000592092_00296_44438_2572.N1						IS2	V/V	92	44438	296	5.03
ASA_WVS_1PNPDK20100830_130938_000008692092_00296_44438_2599.N1						IS2	V/V	92	44438	296	5.03
ASA_WVS_1PNPDK20100830_140101_000003302092_00296_44438_2601.N1						IS2	V/V	92	44438	296	5.03
ASA_WVS_1PNPDK20100830_141939_000001342092_00297_44439_2604.N1						IS2	V/V	92	44439	297	5.03
ASA_WVS_1PNPDK20100830_150855_000007792092_00297_44439_2644.N1						IS2	V/V	92	44439	297	5.03
ASA_WVS_1PNPDK20100830_154137_000012442092_00297_44439_2636.N1						IS2	V/V	92	44439	297	5.03
ASA_WVS_1PNPDK20100830_164305_000011542092_00298_44440_2653.N1						IS2	V/V	92	44440	298	5.03
ASA_WVS_1PNPDK20100830_172213_000012892092_00298_44440_2657.N1						IS2	V/V	92	44440	298	5.03
ASA_WVS_1PNPDK20100830_181836_000014692092_00299_44441_2682.N1						IS2	V/V	92	44441	299	5.03
ASA_WVS_1PNPDK20100830_190407_000004202092_00299_44441_2685.N1						IS2	V/V	92	44441	299	5.03
ASA_WVS_1PNPDK20100830_191447_000001642092_00299_44441_2689.N1						IS2	V/V	92	44441	299	5.03
ASA_WVS_1PNPDE20100830_195215_000018892092_00300_44442_8811.N1						IS2	V/V	92	44442	300	5.03
ASA_WVS_1PNPDE20100830_204325_000001492092_00300_44442_8812.N1						IS2	V/V	92	44442	300	5.03
ASA_WVS_1PNPDE20100830_204510_000002102092_00300_44442_8831.N1						IS2	V/V	92	44442	300	5.03
ASA_WVS_1PNPDE20100830_204325_000001492092_00300_44442_8812.N1						IS1	V/V	92	44442	300	5.03
ASA_WVS_1PNPDE20100830_213244_000018892092_00301_44443_8830.N1						IS2	V/V	92	44443	301	5.03
ASA_WVS_1PNPDE20100830_222352_000003152092_00301_44443_8829.N1						IS2	V/V	92	44443	301	5.03
ASA_WVS_1PNPDE20100830_222822_000006892092_00301_44443_8847.N1						IS2	V/V	92	44443	301	5.03
ASA_WVS_1PNPDE20100830_224740_000004792092_00302_44444_8845.N1						IS2	V/V	92	44444	302	5.03
ASA_WVS_1PNPDE20100830_231306_000013042092_00302_44444_8850.N1						IS2	V/V	92	44444	302	5.03
ASA_WVS_1PNPDE20100830_234110_000002252092_00302_44444_8853.N1						IS2	V/V	92	44444	302	5.03

































































30-Aug




30-Aug




30-Aug







30-Aug





30-Aug




30-Aug








30-Aug



30-Aug



30-Aug



















