



Analysis from 17-NOV-2010 00:00:00 to 17-NOV-2010 23:59:59. Page generated on 18-NOV-2010 07:32:14.  
View log file: ASAR\_Daily\_Report\_20101118\_0731.log. For any anomalies please contact emma.griffiths@vega.co.uk, kajal.haria@vega.co.uk.

This report is automatically generated every day, every 2 hours. No comments are provided on the results.

## SUMMARY

1. DATA SUMMARY
  - 1.1 Summary tables
  - 1.2 Lists of products used
2. AUXILIARY FILES ANALYSIS
  - 2.1 IECF operational ADFs list
  - 2.2 Products with wrong ADFs
3. MODULE STEPPING PRODUCTS ANALYSIS
  - 3.1 V/V polarisation
  - 3.2 H/H polarisation
4. CALIBRATION PULSES ANALYSIS
  - 4.1 Analysis for WVS IS2 V/V
    - 4.1.1 Temporal Evolution Analysis for WVS IS2 V/V
    - 4.1.2 All Rows Analysis for WVS IS2 V/V
  - 4.2 Analysis for GM1 SS3 H/H
    - 4.2.1 Temporal Evolution Analysis for GM1 SS3 H/H
    - 4.2.2 All Rows Analysis for GM1 SS3 H/H
5. DOPPLER ANALYSIS
  - 5.1 Analysis for WVS IS2 V/V
    - 5.1.1 Doppler MAP Analysis for WVS IS2 V/V
    - 5.1.2 Doppler ANX Analysis for WVS IS2 V/V
  - 5.2 Analysis for GM1 SS1 H/H
    - 5.2.1 Doppler MAP Analysis for GM1 SS1 H/H
    - 5.2.2 Doppler ANX Analysis for GM1 SS1 H/H
  - 5.3 Doppler JUMPS Analysis for WSM
6. CHIRP ANALYSIS
  - 6.1 Analysis for WSM SS1 H/H
    - 6.1.1 ScaleFactor
  - 6.2 Analysis for WSM SS1 V/V
    - 6.2.1 ScaleFactor
7. RAW DATA ANALYSIS
  - 7.1 Analysis for WVS
  - 7.2 Analysis for IMM
8. TELEMETRY ANALYSIS
  - 8.1 Number of Missing Lines
  - 8.2 Number of Gaps

---

## 1 - DATA SUMMARY

### 1.1 - Summary tables

[ [BACK TO MENU](#) ]

WVS				GM1				APM				IMM				WSM				MS			
Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Time	Pol	Modules
PDE	IS1	V/V	3	PDE	WS	H/H	34	PDE	IS4	V/H	3	PDE	IS6	H/H	3	PDE	WS	H/H	21	PDE	2010-11-17 00:12:12	H	320
PDE	IS2	V/V	27	PDK	WS	H/H	51					PDK	IS6	H/H	1	PDE	WS	V/V	5	PDE	2010-11-17 05:12:54	V	320
PDK	IS2	V/V	24													PDK	WS	H/H	10	PDK	2010-11-17 10:13:36	H	320
																PDK	WS	V/V	2	PDK	2010-11-17 15:14:18	V	320
																				PDK	2010-11-17 20:15:00	H	320

## 1.2 - Lists of products used

[ [BACK TO MENU](#) ]

[\[TXT\]](#) [\[XLS\]](#) List\_WVS\_products\_used  
[\[TXT\]](#) [\[XLS\]](#) List\_GM1\_products\_used  
[\[TXT\]](#) [\[XLS\]](#) List\_APM\_products\_used  
[\[TXT\]](#) [\[XLS\]](#) List\_IMM\_products\_used  
[\[TXT\]](#) [\[XLS\]](#) List\_WSM\_products\_used  
[\[TXT\]](#) [\[XLS\]](#) List\_MS\_products\_used

## 2 - AUXILIARY FILES ANALYSIS

### 2.1 - IECF operational ADFs list

[ [BACK TO MENU](#) ]

ADFs disseminated for ASAR
ASA_CON_AXVIEC20100608_125449_20100317_120410_20101231_000000
ASA_INS_AXVIEC20101028_095209_20101022_000000_20101231_235959
ASA_XCH_AXVIEC20091217_113006_20020301_000000_20101231_000000
ASA_XCA_AXVIEC20101111_113830_20100601_000000_20141231_000000

### 2.2 - Products with wrong ADFs

[ [BACK TO MENU](#) ]

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
WVS	0	0	0	0
GM1	0	0	0	0
APM	0	0	0	0
IMM	0	0	0	0
WSM	0	0	0	0


[\[TXT\]](#) [\[XLS\]](#) Check\_ADFs\_WVS  
[\[TXT\]](#) [\[XLS\]](#) Check\_ADFs\_GM1  
[\[TXT\]](#) [\[XLS\]](#) Check\_ADFs\_APM  
[\[TXT\]](#) [\[XLS\]](#) Check\_ADFs\_IMM  
[\[TXT\]](#) [\[XLS\]](#) Check\_ADFs\_WSM

## 3 - MODULE STEPPING PRODUCTS ANALYSIS

SECOND FIXED REFERENCE

Pre-launch reference (2001-02-09)


Reference: 2001-02-09 14:08:23 V RxGain  
 Test : 2010-11-17 15:14:18 V



PREVIOUS PRODUCT REFERENCE

Previous product in the same polarisation


Reference: 2010-11-17 05:12:54 V RxGain  
 Test : 2010-11-17 15:14:18 V



Reference: 2001-02-09 14:08:23 V RxPhase  
 Test : 2010-11-17 15:14:18 V



Reference: 2010-11-17 05:12:54 V RxPhase  
 Test : 2010-11-17 15:14:18 V








### 3.2 - H/H polarisation


[ [BACK TO MENU](#) ]

SECOND FIXED REFERENCE	PREVIOUS PRODUCT REFERENCE
Pre-launch reference (2001-02-09)	Previous product in the same polarisation

Reference: 2001-02-09 13:50:42 H RxGain  
 Test : 2010-11-17 20:15:00 H




Reference: 2010-11-17 10:13:36 H RxGain  
 Test : 2010-11-17 20:15:00 H







Reference: 2001-02-09 13:50:42 H RxPhase  
 Test : 2010-11-17 20:15:00 H



Reference: 2010-11-17 10:13:36 H RxPhase  
 Test : 2010-11-17 20:15:00 H







## 4 - CALIBRATION PULSES ANALYSIS

### 4.1 - Analysis for WVS IS2 V/V


#### 4.1.1 - Temporal Evolution Analysis for WVS IS2 V/V

[ BACK TO MENU ]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Calibration pulses for WVS IS2 V/V




Transmit power (P1 - P1a) for WVS IS2 V/V



4.1.2 - All Rows Analysis for WVS IS2 V/V

[ BACK TO MENU ]





## 4.2 - Analysis for GM1 SS3 H/H

### 4.2.1 - Temporal Evolution Analysis for GM1 SS3 H/H


[ BACK TO MENU ]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]



Calibration pulses for GM1 SS3 H/H




Transmit power (P1 - P1a) for GM1 SS3 H/H



#### 4.2.2 - All Rows Analysis for GM1 SS3 H/H

[ [BACK TO MENU](#) ]






## 5 - DOPPLER ANALYSIS


### 5.1 - Analysis for WVS IS2 V/V

#### 5.1.1 - Doppler MAP Analysis for WVS IS2 V/V

[ [BACK TO MENU](#) ]








### 5.1.2 - Doppler ANX Analysis for WVS IS2 V/V

[ [BACK TO MENU](#) ]






## 5.2 - Analysis for GM1 SS1 H/H

### 5.2.1 - Doppler MAP Analysis for GM1 SS1 H/H

[ [BACK TO MENU](#) ]








### 5.2.2 - Doppler ANX Analysis for GM1 SS1 H/H

[ [BACK TO MENU](#) ]









### 5.3 - Doppler JUMPS Analysis for WSM

[ [BACK TO MENU](#) ]









## 6 - CHIRP ANALYSIS

### 6.1 - Analysis for WSM SS1 H/H

#### 6.1.1 - ScaleFactor

[ BACK TO MENU ]







## 6.2 - Analysis for WSM SS1 V/V

### 6.2.1 - ScaleFactor

[ [BACK TO MENU](#) ]






## 7 - RAW DATA ANALYSIS

### 7.1 - Analysis for WVS

[ [BACK TO MENU](#) ]

--	--	--









Channel	Statistics	DSS-B
MEAN I	mean	0.000623297
	stdev	1.15579e-07
MEAN Q	mean	0.000527313
	stdev	2.03834e-07
Channel	Statistics	DSS-B
STDEV I	mean	0.150339
	stdev	0.00133867
STDEV Q	mean	0.150881
	stdev	0.00136476

## 7.2 - Analysis for IMM

[ [BACK TO MENU](#) ]





Channel	Statistics	DSS-B
MEAN I	mean	0.000274719
	stdev	3.87252e-09
MEAN Q	mean	0.000551968
	stdev	4.11241e-09
Channel	Statistics	DSS-B
STDEV I	mean	0.0693836
	stdev	0.000450660
STDEV Q	mean	0.0696874
	stdev	0.000456677

### 8 - TELEMETRY ANALYSIS


Processing Center	Product	Gaps	Missing lines
PDK	ASA_WSM_1PNPDK20101117_093646_000001533096_00295_45568_3385.N1	0	1

#### 8.1 - Number of Missing lines

[ BACK TO MENU ]








## 8.2 - Number of Gaps

[ [BACK TO MENU](#) ]



#####  
ASAR DAILY REPORT for 101117  
#####

MODE: DAILY  
ANALYSIS: ALL  
DATE: 2010-11-17 00:00:00

Analysis will be performed from 2010-11-17 00:00:00 to 2010-11-17 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/\_101117/

DATA SUMMARY  
#####  
Summary will be performed from 2010-11-17 00:00:00 to 2010-11-17 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/\_101117/DATA\_SUMMARY

Creating directory ./RESULTS/DAILY/\_101117/DATA\_SUMMARY...  
Writing file ./RESULTS/DAILY/\_101117/DATA\_SUMMARY/Data\_summary.html...

\*\*\*\*\*  
Getting WVS products list from 2010-11-17 00:00:00 to 2010-11-17 23:59:59...  
Writing file ./RESULTS/DAILY/\_101117/DATA\_SUMMARY/List\_WVS\_products\_used.xls...  
Writing file ./RESULTS/DAILY/\_101117/DATA\_SUMMARY/List\_WVS\_products\_used.txt...

\*\*\*\*\*  
Getting GM1 products list from 2010-11-17 00:00:00 to 2010-11-17 23:59:59...  
Writing file ./RESULTS/DAILY/\_101117/DATA\_SUMMARY/List\_GM1\_products\_used.xls...  
Writing file ./RESULTS/DAILY/\_101117/DATA\_SUMMARY/List\_GM1\_products\_used.txt...

\*\*\*\*\*  
Getting APM products list from 2010-11-17 00:00:00 to 2010-11-17 23:59:59...  
Writing file ./RESULTS/DAILY/\_101117/DATA\_SUMMARY/List\_APM\_products\_used.xls...  
Writing file ./RESULTS/DAILY/\_101117/DATA\_SUMMARY/List\_APM\_products\_used.txt...

\*\*\*\*\*  
Getting IMM products list from 2010-11-17 00:00:00 to 2010-11-17 23:59:59...  
Writing file ./RESULTS/DAILY/\_101117/DATA\_SUMMARY/List\_IMM\_products\_used.xls...  
Writing file ./RESULTS/DAILY/\_101117/DATA\_SUMMARY/List\_IMM\_products\_used.txt...

\*\*\*\*\*  
Getting WSM products list from 2010-11-17 00:00:00 to 2010-11-17 23:59:59...  
Writing file ./RESULTS/DAILY/\_101117/DATA\_SUMMARY/List\_WSM\_products\_used.xls...  
Writing file ./RESULTS/DAILY/\_101117/DATA\_SUMMARY/List\_WSM\_products\_used.txt...

\*\*\*\*\*  
Getting MS products list from 2010-11-17 00:00:00 to 2010-11-17 23:59:59...  
Writing file ./RESULTS/DAILY/\_101117/DATA\_SUMMARY/List\_MS\_products\_used.xls...  
Writing file ./RESULTS/DAILY/\_101117/DATA\_SUMMARY/List\_MS\_products\_used.txt...

DATA SUMMARY completed  
#####

AUXILIARY FILES ANALYSIS  
#####  
Analysis will be performed from 2010-11-17 00:00:00 to 2010-11-17 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/\_101117/AUXILIARY

Creating directory ./RESULTS/DAILY/\_101117/AUXILIARY...

\*\*\*\*\*  
Looking for the IECF operational ADFs list...





ADF filter 20101117\*current\_3\_IECF\_ADFs.txt  
 Found list 20101117\_030001\_current\_3\_IECF\_ADFs.txt...  
 Extracting ADFs...

ASA\_CON\_AXVIEC20100608\_125449\_20100317\_120410\_20101231\_000000  
 ASA\_INS\_AXVIEC20101028\_095209\_20101022\_000000\_20101231\_235959  
 ASA\_XCH\_AXVIEC20091217\_113006\_20020301\_000000\_20101231\_000000  
 ASA\_XCA\_AXVIEC20101111\_113830\_20100601\_000000\_20141231\_000000

Writing file ./RESULTS/DAILY/\_101117/AUXILIARY/ASAR\_ADFs\_IECF\_List3.html...  
 Writing file ./RESULTS/DAILY/\_101117/AUXILIARY/Auxiliary\_files\_summary.html...

\*\*\*\*\*

Analysing WVS products...

Writing file ./RESULTS/DAILY/\_101117/AUXILIARY/Check\_ADFs\_WVS.xls...  
 Writing file ./RESULTS/DAILY/\_101117/AUXILIARY/Check\_ADFs\_WVS.txt...

ASA_WVS_1PNPDE20101117_000522_000003753096_00289_45562_6409.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101117_002815_000004203096_00289_45562_6408.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101117_003415_000004343096_00289_45562_6437.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101117_004408_000010043096_00289_45562_6434.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101117_012406_000003913096_00290_45563_6438.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101117_013825_000001193096_00290_45563_6439.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101117_014512_000003903096_00290_45563_6442.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101117_020821_000001193096_00290_45563_6444.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101117_020936_000002403096_00290_45563_6468.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101117_022830_000004493096_00291_45564_6470.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101117_031549_000005393096_00291_45564_6477.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101117_032433_000003003096_00291_45564_6488.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101117_035401_000008693096_00291_45564_6486.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101117_041115_000001043096_00292_45565_6499.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101117_045322_000008243096_00292_45565_6502.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101117_050652_000003153096_00292_45565_6507.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101117_052848_000015293096_00292_45565_6512.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101117_063509_000002693096_00293_45566_6508.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101117_064255_000002403096_00293_45566_6513.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101117_212148_000019643096_00302_45575_6600.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101117_221556_00000153096_00302_45575_6599.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101117_221556_000007643096_00302_45575_6633.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101117_224310_00000603096_00303_45576_6635.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101117_230135_000013493096_00303_45576_6638.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101117_232944_000003003096_00303_45576_6640.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101117_235132_000004503096_00303_45576_6648.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20101117_235817_000011243096_00303_45576_6680.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101117_070911_000019643096_00293_45566_3353.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101117_082449_000004653096_00294_45567_3377.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101117_084925_000020243096_00294_45567_3380.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101117_095527_000010493096_00295_45568_3393.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101117_102939_000018443096_00295_45568_3395.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101117_111854_000001503096_00296_45569_3419.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101117_112925_000014243096_00296_45569_3424.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101117_120953_000004503096_00296_45569_3423.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101117_122019_000001493096_00296_45569_3421.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101117_122555_000005643096_00296_45569_3429.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101117_125908_000009443096_00297_45570_3460.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101117_135007_000004203096_00297_45570_3466.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101117_144547_000004493096_00298_45571_3494.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101117_150010_000008103096_00298_45571_3496.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101117_153021_000009743096_00298_45571_3497.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101117_154851_000001193096_00299_45572_3500.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101117_163303_000012443096_00299_45572_3518.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101117_171405_000011093096_00299_45572_3520.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101117_180828_000015293096_00300_45573_3533.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101117_185429_000004353096_00300_45573_3534.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101117_190429_000001793096_00300_45573_3537.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK



```
ASA_WVS_1PNPDK20101117_194144_000019493096_00301_45574_3565.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101117_203506_000001803096_00301_45574_3570.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20101117_203506_000001803096_00301_45574_3573.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```

\*\*\*\*\*

Analysing GM1 products...

Writing file ./RESULTS/DAILY/\_101117/AUXILIARY/Check\_ADFs\_GM1.xls...

Writing file ./RESULTS/DAILY/\_101117/AUXILIARY/Check\_ADFs\_GM1.txt...

```
ASA_GM1_1PNPDE20101117_001331_000003503096_00289_45562_6411.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101117_002627_000001023096_00289_45562_6410.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101117_004215_000001083096_00289_45562_6435.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101117_010744_000009793096_00290_45563_6436.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101117_013121_000004223096_00290_45563_6440.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101117_014102_000001933096_00290_45563_6441.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101117_015224_000005013096_00290_45563_6455.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101117_021658_000006893096_00290_45563_6467.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101117_023646_000002413096_00291_45564_6465.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101117_024728_000010093096_00291_45564_6471.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101117_030635_000001023096_00291_45564_6469.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101117_031354_000001083096_00291_45564_6472.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101117_031354_000001083096_00291_45564_6473.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101117_033300_000004653096_00291_45564_6489.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101117_034937_000002593096_00291_45564_6487.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101117_040918_000001083096_00292_45565_6485.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101117_041343_000005433096_00292_45565_6492.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101117_042626_000007913096_00292_45565_6501.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101117_044027_000001083096_00292_45565_6500.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101117_044643_000003983096_00292_45565_6498.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101117_051410_000002773096_00292_45565_6511.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101117_055459_000011603096_00293_45566_6510.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101117_061759_000007013096_00293_45566_6509.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101117_064027_000001443096_00293_45566_6514.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101117_210512_000005253096_00302_45575_6597.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101117_211640_000003083096_00302_45575_6598.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101117_215516_000008883096_00302_45575_6601.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101117_222930_000003563096_00303_45576_6634.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101117_224625_000009063096_00303_45576_6637.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101117_232454_000001753096_00303_45576_6636.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101117_232755_000001023096_00303_45576_6639.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101117_233532_000005983096_00303_45576_6641.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20101117_234825_000001873096_00303_45576_6645.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_065307_000002713096_00293_45566_3349.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_070233_000003983096_00293_45566_3351.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_074238_000004283096_00294_45567_3352.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_075126_00000603096_00294_45567_3354.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_075128_000001143096_00294_45567_3373.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_075653_000003563096_00294_45567_3374.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_081640_000004893096_00294_45567_3375.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_083321_000003863096_00294_45567_3376.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_084425_000002953096_00294_45567_3378.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_092400_000007493096_00295_45568_3381.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_093521_000000783096_00295_45568_3390.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_094637_000005313096_00295_45568_3391.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_101453_000002953096_00295_45568_3392.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_102226_000004283096_00295_45568_3394.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_111344_000003083096_00296_45569_3420.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_120126_000005073096_00296_45569_3426.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_121812_000001203096_00296_45569_3422.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_122332_000001383096_00296_45569_3427.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_123924_000008703096_00297_45570_3430.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_125239_000003863096_00297_45570_3454.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_131545_000002293096_00297_45570_3456.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_132109_000003143096_00297_45570_3457.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_132627_000003863096_00297_45570_3458.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```



ASA_GM1_1PNPDK20101117_134050_000005553096_00297_45570_3459.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_135749_000006833096_00297_45570_3461.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_141324_000001753096_00298_45571_3462.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_141821_000007913096_00298_45571_3463.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_141821_000007913096_00298_45571_3465.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_143021_000009243096_00298_45571_3493.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_145410_000003563096_00298_45571_3495.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_151536_000008823096_00298_45571_3498.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_154718_000000843096_00299_45572_3499.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_155131_000010943096_00299_45572_3501.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_160859_000012753096_00299_45572_3517.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_170351_000003983096_00299_45572_3519.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_173325_000008643096_00300_45573_3521.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_174636_000005493096_00300_45573_3528.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_175722_000006283096_00300_45573_3529.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_183450_000002413096_00300_45573_3530.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_184235_000001203096_00300_45573_3531.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_184914_000000663096_00300_45573_3532.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_190231_000001143096_00300_45573_3535.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_190817_000005673096_00301_45574_3536.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_192023_000001443096_00301_45574_3538.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_193102_000006283096_00301_45574_3563.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_201617_000004163096_00301_45574_3564.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_202551_000003083096_00301_45574_3567.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_203848_000010813096_00301_45574_3569.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_203848_000010813096_00301_45574_3572.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_210501_000000783096_00302_45575_3568.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20101117_210501_000000783096_00302_45575_3571.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

\*\*\*\*\*

Analysing APM products...

Writing file ./RESULTS/DAILY/\_101117/AUXILIARY/Check\_ADFs\_APM.xls...

Writing file ./RESULTS/DAILY/\_101117/AUXILIARY/Check\_ADFs\_APM.txt...

ASA_APM_1PNPDE20101117_131936_000000733096_00297_45570_6582.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20101117_163012_000000443096_00299_45572_6585.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20101117_163130_000000443096_00299_45572_6586.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

\*\*\*\*\*

Analysing IMM products...

Writing file ./RESULTS/DAILY/\_101117/AUXILIARY/Check\_ADFs\_IMM.xls...

Writing file ./RESULTS/DAILY/\_101117/AUXILIARY/Check\_ADFs\_IMM.txt...

ASA_IMM_1PNPDE20101117_030415_000001273096_00291_45564_6463.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20101117_043937_000000373096_00292_45565_6482.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20101117_044220_000002543096_00292_45565_6483.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20101117_123553_000001423096_00297_45570_3428.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

\*\*\*\*\*

Analysing WSM products...

Writing file ./RESULTS/DAILY/\_101117/AUXILIARY/Check\_ADFs\_WSM.xls...

Writing file ./RESULTS/DAILY/\_101117/AUXILIARY/Check\_ADFs\_WSM.txt...

ASA_WSM_1PNPDE20101117_001924_000004163096_00289_45562_6398.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101117_010151_000003493096_00290_45563_6433.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101117_020051_000004533096_00290_45563_6456.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101117_021423_000001533096_00290_45563_6459.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101117_030825_000001533096_00291_45564_6464.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101117_031155_000001163096_00291_45564_6466.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK



ASA_WSM_1PNPDE20101117_034051_000004533096_00291_45564_6484.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101117_042251_000002083096_00292_45565_6490.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101117_051851_000005693096_00292_45565_6505.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101117_062945_000002813096_00293_45566_6506.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101117_065740_000001283096_00293_45566_6522.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101117_080937_000004163096_00294_45567_6526.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101117_101951_000001533096_00295_45568_6537.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101117_112200_000004343096_00296_45569_6562.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101117_115435_000002263096_00296_45569_6564.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101117_133514_000003303096_00297_45570_6583.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101117_165524_000004893096_00299_45572_6587.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101117_171034_000002143096_00299_45572_6584.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101117_183855_000002143096_00300_45573_6593.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101117_184443_000002513096_00300_45573_6591.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101117_202316_000001533096_00301_45574_6594.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101117_203134_000002143096_00301_45574_6595.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101117_211402_000001533096_00302_45575_6596.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101117_221009_000003493096_00302_45575_6602.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101117_223529_000004653096_00303_45576_6613.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20101117_234531_000001713096_00303_45576_6632.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20101117_061424_000002083096_00293_45566_3336.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20101117_070020_000001283096_00293_45566_3360.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20101117_074951_000000923096_00294_45567_3361.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20101117_075328_000001903096_00294_45567_3359.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20101117_083951_000002693096_00294_45567_3384.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20101117_093646_000001533096_00295_45568_3385.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20101117_093936_000001653096_00295_45568_3387.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20101117_115907_000001353096_00296_45569_3425.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20101117_192250_000002083096_00301_45574_3551.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20101117_192647_000002513096_00301_45574_3549.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20101117_210150_000001843096_00302_45575_3566.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20101117_224451_000000923096_00303_45576_3592.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

AUXILIARY FILES ANALYSIS completed

#####

MODULE STEPPING ANALYSIS

#####

Analysis will be performed from 2010-11-17 00:00:00 to 2010-11-17 23:59:59  
 Results will be exported to the directory: ./RESULTS/DAILY/\_101117/MODULE\_STEPPING

Creating directory ./RESULTS/DAILY/\_101117/MODULE\_STEPPING...  
 Creating directory ./RESULTS/DAILY/\_101117/MODULE\_STEPPING/FIRST\_REFERENCE...  
 Creating directory ./RESULTS/DAILY/\_101117/MODULE\_STEPPING/SECOND\_REFERENCE...  
 Creating directory ./RESULTS/DAILY/\_101117/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE...  
 Deleting old files...

\*\*\*\*\*  
 \*\*\*\*\*

Creating images comparing with second reference...

Exporting results to the directory ../../RESULTS/DAILY/\_101117/MODULE\_STEPPING/SECOND\_REFERENCE...

Polarization: H  
 Reference product: ASA\_MS\_0PNPDK20010209\_135042\_0000009A024\_00180\_11700\_0052.N1  
 Test product: ASA\_MS\_0PNPDK20101117\_201500\_00000163096\_00301\_45574\_0300.N1  
 H  
 H  
 ../../RESULTS/DAILY/\_101117/MODULE\_STEPPING/SECOND\_REFERENCE/TGH\_20101117\_201500-20010209\_135042.png  
 ../../RESULTS/DAILY/\_101117/MODULE\_STEPPING/SECOND\_REFERENCE/TPH\_20101117\_201500-20010209\_135042.png  
 ../../RESULTS/DAILY/\_101117/MODULE\_STEPPING/SECOND\_REFERENCE/RGH\_20101117\_201500-20010209\_135042.png  
 ../../RESULTS/DAILY/\_101117/MODULE\_STEPPING/SECOND\_REFERENCE/RPH\_20101117\_201500-20010209\_135042.png

Polarization: V



Reference product: ASA\_MS\_0PNPDK20010209\_140823\_0000009A024\_00180\_11700\_0054.N1  
Test product: ASA\_MS\_0PNPDK20101117\_151418\_000000163096\_00298\_45571\_0299.N1

V  
V

../../RESULTS/DAILY/\_101117/MODULE\_STEPPING/SECOND\_REFERENCE/TGV\_20101117\_151418-20010209\_140823.png  
../../RESULTS/DAILY/\_101117/MODULE\_STEPPING/SECOND\_REFERENCE/TPV\_20101117\_151418-20010209\_140823.png  
../../RESULTS/DAILY/\_101117/MODULE\_STEPPING/SECOND\_REFERENCE/RGV\_20101117\_151418-20010209\_140823.png  
../../RESULTS/DAILY/\_101117/MODULE\_STEPPING/SECOND\_REFERENCE/RPV\_20101117\_151418-20010209\_140823.png

\*\*\*\*\*  
\*\*\*\*\*

Creating images comparing with previous product reference...

Exporting results to the directory ../../RESULTS/DAILY/\_101117/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE...

Polarization: H  
Reference product: ASA\_MS\_0PNPDK20101117\_101336\_000000163096\_00295\_45568\_0298.N1  
Test product: ASA\_MS\_0PNPDK20101117\_201500\_000000163096\_00301\_45574\_0300.N1

H  
H

../../RESULTS/DAILY/\_101117/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/TGH\_20101117\_201500-20101117\_101336.png  
../../RESULTS/DAILY/\_101117/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/TPH\_20101117\_201500-20101117\_101336.png  
../../RESULTS/DAILY/\_101117/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/RGH\_20101117\_201500-20101117\_101336.png  
../../RESULTS/DAILY/\_101117/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/RPH\_20101117\_201500-20101117\_101336.png

Polarization: V  
Reference product: ASA\_MS\_0PNPDE20101117\_051254\_000000163096\_00292\_45565\_0070.N1  
Test product: ASA\_MS\_0PNPDK20101117\_151418\_000000163096\_00298\_45571\_0299.N1

V  
V

../../RESULTS/DAILY/\_101117/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/TGV\_20101117\_151418-20101117\_051254.png  
../../RESULTS/DAILY/\_101117/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/TPV\_20101117\_151418-20101117\_051254.png  
../../RESULTS/DAILY/\_101117/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/RGV\_20101117\_151418-20101117\_051254.png  
../../RESULTS/DAILY/\_101117/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/RPV\_20101117\_151418-20101117\_051254.png

MODULE\_STEPPING ANALYSIS completed  
#####

CALIBRATION PULSES ANALYSIS  
#####  
Creating directory ./RESULTS/DAILY/\_101117/CALIBRATION\_PULSES...

\*\*\*\*\*  
\*\*\*\*\*

ALL ROWS Analysis will be performed from 2010-11-17 00:00:00 to 2010-11-17 23:59:59

Analysing products WVS IS2 V/V  
Writing image ../../RESULTS/DAILY/\_101117//CALIBRATION\_PULSES/Calibration\_pulses\_all\_rows\_WVS\_IS2\_VV.png...  
Analysing products GM1 SS3 H/H  
Writing image ../../RESULTS/DAILY/\_101117//CALIBRATION\_PULSES/Calibration\_pulses\_all\_rows\_GM1\_SS3\_HH.png...

\*\*\*\*\*  
\*\*\*\*\*

TEMPORAL EVOLUTION Analysis will be performed from 2010-11-17 00:00:00 to 2010-11-17 23:59:59

Analysing products WVS IS2 V/V  
Getting calibration pulses data for WVS IS2 V/V from 2010-11-17 00:00:00 to 2010-11-17 23:59:59. Rows: 1/5/9/13/17/21/25/29  
Writing file ./RESULTS/DAILY/\_101117/CALIBRATION\_PULSES/Calibration\_pulses\_data\_WVS\_IS2\_VV\_2010-11-17\_1.dat...  
Writing ../../RESULTS/DAILY/\_101117//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_WVS\_IS2\_VV\_1.png...  
Writing ../../RESULTS/DAILY/\_101117//CALIBRATION\_PULSES/Transmit\_Power\_WVS\_IS2\_VV\_1.png...

Getting calibration pulses data for WVS IS2 V/V from 2010-11-17 00:00:00 to 2010-11-17 23:59:59. Rows: 2/6/10/14/18/22/26/30



Writing file ./RESULTS/DAILY/\_101117/CALIBRATION\_PULSES/Calibration\_pulses\_data\_WVS\_IS2\_VV\_2010-11-17\_2.dat...  
Writing ../../RESULTS/DAILY/\_101117//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_WVS\_IS2\_VV\_2.png...  
Writing ../../RESULTS/DAILY/\_101117//CALIBRATION\_PULSES/Transmit\_Power\_WVS\_IS2\_VV\_2.png...

Getting calibration pulses data for WVS IS2 V/V from 2010-11-17 00:00:00 to 2010-11-17 23:59:59. Rows: 3/7/11/15/19/23/27/31  
Writing file ./RESULTS/DAILY/\_101117/CALIBRATION\_PULSES/Calibration\_pulses\_data\_WVS\_IS2\_VV\_2010-11-17\_3.dat...  
Writing ../../RESULTS/DAILY/\_101117//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_WVS\_IS2\_VV\_3.png...  
Writing ../../RESULTS/DAILY/\_101117//CALIBRATION\_PULSES/Transmit\_Power\_WVS\_IS2\_VV\_3.png...

Getting calibration pulses data for WVS IS2 V/V from 2010-11-17 00:00:00 to 2010-11-17 23:59:59. Rows: 4/8/12/16/20/24/28/32  
Writing file ./RESULTS/DAILY/\_101117/CALIBRATION\_PULSES/Calibration\_pulses\_data\_WVS\_IS2\_VV\_2010-11-17\_4.dat...  
Writing ../../RESULTS/DAILY/\_101117//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_WVS\_IS2\_VV\_4.png...  
Writing ../../RESULTS/DAILY/\_101117//CALIBRATION\_PULSES/Transmit\_Power\_WVS\_IS2\_VV\_4.png...

Analysing products GM1 SS3 H/H  
Getting calibration pulses data for GM1 SS3 H/H from 2010-11-17 00:00:00 to 2010-11-17 23:59:59. Rows: 1/5/9/13/17/21/25/29  
Writing file ./RESULTS/DAILY/\_101117/CALIBRATION\_PULSES/Calibration\_pulses\_data\_GM1\_SS3\_HH\_2010-11-17\_1.dat...  
Writing ../../RESULTS/DAILY/\_101117//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_GM1\_SS3\_HH\_1.png...  
Writing ../../RESULTS/DAILY/\_101117//CALIBRATION\_PULSES/Transmit\_Power\_GM1\_SS3\_HH\_1.png...

Getting calibration pulses data for GM1 SS3 H/H from 2010-11-17 00:00:00 to 2010-11-17 23:59:59. Rows: 2/6/10/14/18/22/26/30  
Writing file ./RESULTS/DAILY/\_101117/CALIBRATION\_PULSES/Calibration\_pulses\_data\_GM1\_SS3\_HH\_2010-11-17\_2.dat...  
Writing ../../RESULTS/DAILY/\_101117//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_GM1\_SS3\_HH\_2.png...  
Writing ../../RESULTS/DAILY/\_101117//CALIBRATION\_PULSES/Transmit\_Power\_GM1\_SS3\_HH\_2.png...

Getting calibration pulses data for GM1 SS3 H/H from 2010-11-17 00:00:00 to 2010-11-17 23:59:59. Rows: 3/7/11/15/19/23/27/31  
Writing file ./RESULTS/DAILY/\_101117/CALIBRATION\_PULSES/Calibration\_pulses\_data\_GM1\_SS3\_HH\_2010-11-17\_3.dat...  
Writing ../../RESULTS/DAILY/\_101117//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_GM1\_SS3\_HH\_3.png...  
Writing ../../RESULTS/DAILY/\_101117//CALIBRATION\_PULSES/Transmit\_Power\_GM1\_SS3\_HH\_3.png...

Getting calibration pulses data for GM1 SS3 H/H from 2010-11-17 00:00:00 to 2010-11-17 23:59:59. Rows: 4/8/12/16/20/24/28/32  
Writing file ./RESULTS/DAILY/\_101117/CALIBRATION\_PULSES/Calibration\_pulses\_data\_GM1\_SS3\_HH\_2010-11-17\_4.dat...  
Writing ../../RESULTS/DAILY/\_101117//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_GM1\_SS3\_HH\_4.png...  
Writing ../../RESULTS/DAILY/\_101117//CALIBRATION\_PULSES/Transmit\_Power\_GM1\_SS3\_HH\_4.png...

CALIBRATION PULSES ANALYSIS completed  
#####

DOPPLER ANALYSIS  
#####  
Creating directory ./RESULTS/DAILY/\_101117/DOPPLER...

\*\*\*\*\*  
\*\*\*\*\*  
DOPPLER ANX Analysis will be performed from 2010-11-17 00:00:00 to 2010-11-17 23:59:59

Analysing products WVS IS2 V/V  
Getting doppler data for WVS IS2 V/V from 2010-11-17 00:00:00 to 2010-11-17 23:59:59...  
Writing file ./RESULTS/DAILY/\_101117/DOPPLER/Doppler\_data\_WVS\_IS2\_VV\_2010-11-17.dat...  
Running IDL program...  
Writing file ../../RESULTS/DAILY/\_101117/DOPPLER/DOPPLER\_ANX\_WVS\_IS2\_VV.png...

Analysing products GM1 SS1 H/H  
Getting doppler data for GM1 SS1 H/H from 2010-11-17 00:00:00 to 2010-11-17 23:59:59...  
Writing file ./RESULTS/DAILY/\_101117/DOPPLER/Doppler\_data\_GM1\_SS1\_HH\_2010-11-17.dat...  
Running IDL program...



Writing file ../../RESULTS/DAILY/\_101117/DOPPLER/DOPPLER\_ANX\_GM1\_SS1\_HH.png...

\*\*\*\*\*  
\*\*\*\*\*  
DOPPLER JUMPS Analysis will be performed on WSM products from 2010-11-17 00:00:00 to 2010-11-17 23:59:59

Analysing by default products WSM  
Getting doppler jumps data for WSM from 2010-11-17 00:00:00 to 2010-11-17 23:59:59...  
Writing file ./RESULTS/DAILY/\_101117/DOPPLER/Doppler\_Jumps\_data\_WSM\_2010-11-17.dat...  
Running IDL program...  
Writing file ../../RESULTS/DAILY/\_101117/DOPPLER/DOPPLER\_JUMPS\_ANX\_WSM.png...  
Writing file ../../RESULTS/DAILY/\_101117/DOPPLER/DOPPLER\_JUMPS\_Date\_WSM.png...

\*\*\*\*\*  
\*\*\*\*\*  
DOPPLER MAP Analysis will be performed from 2010-11-17 00:00:00 to 2010-11-17 23:59:59

Analysing products WVS IS2 V/V  
Loading predicted doppler values....  
Phase: descending  
Found data...  
Computing mean error doppler estimated-predicted...  
Mean error = -73.998742 Hz  
Writing file ../../RESULTS/DAILY/\_101117//DOPPLER/DOPPLER\_Estimated-Predicted-MeanError\_WVS\_IS2\_VV\_desc.jpg...  
Writing file ../../RESULTS/DAILY/\_101117//DOPPLER/DOPPLER\_Absolute\_WVS\_IS2\_VV\_desc.jpg...

\*\*\*\*\*  
Loading predicted doppler values....  
Phase: ascending  
Found data...  
Computing mean error doppler estimated-predicted...  
Mean error = -65.519399 Hz  
Writing file ../../RESULTS/DAILY/\_101117//DOPPLER/DOPPLER\_Estimated-Predicted-MeanError\_WVS\_IS2\_VV\_asc.jpg...  
Writing file ../../RESULTS/DAILY/\_101117//DOPPLER/DOPPLER\_Absolute\_WVS\_IS2\_VV\_asc.jpg...

\*\*\*\*\*  
Analysing products GM1 SS1 H/H  
Loading predicted doppler values....  
Phase: descending  
Found data...  
Computing mean error doppler estimated-predicted...  
Mean error = -56.164632 Hz  
Writing file ../../RESULTS/DAILY/\_101117//DOPPLER/DOPPLER\_Estimated-Predicted-MeanError\_GM1\_SS1\_HH\_desc.jpg...  
Writing file ../../RESULTS/DAILY/\_101117//DOPPLER/DOPPLER\_Absolute\_GM1\_SS1\_HH\_desc.jpg...

\*\*\*\*\*  
Loading predicted doppler values....  
Phase: ascending  
Found data...  
Computing mean error doppler estimated-predicted...  
Mean error = -61.474739 Hz  
Writing file ../../RESULTS/DAILY/\_101117//DOPPLER/DOPPLER\_Estimated-Predicted-MeanError\_GM1\_SS1\_HH\_asc.jpg...  
Writing file ../../RESULTS/DAILY/\_101117//DOPPLER/DOPPLER\_Absolute\_GM1\_SS1\_HH\_asc.jpg...

\*\*\*\*\*  
DOPPLER ANALYSIS completed  
#####

#####

Creating directory ./RESULTS/DAILY/\_101117/CHIRP...

\*\*\*\*\*  
\*\*\*\*\*  
CHIRP Analysis will be performed from 2010-11-17 00:00:00 to 2010-11-17 23:59:59

Analysing products WSM SS1 H/H

\*\*\*\*\*  
Getting ScaleFactor data for WSM SS1 H/H from 2010-11-17 00:00:00 to 2010-11-17 23:59:59...  
Writing file ./RESULTS/DAILY/\_101117/CHIRP/ScaleFactor\_data\_WSM\_SS1\_HH\_2010-11-17.dat...  
Running IDL program...  
Writing file ../../RESULTS/DAILY/\_101117/CHIRP/ScaleFactor\_ANX\_WSM\_SS1\_HH.png...  
Writing file ../../RESULTS/DAILY/\_101117/CHIRP/ScaleFactor\_DATE\_WSM\_SS1\_HH.png...

Analysing products WSM SS1 V/V

\*\*\*\*\*  
Getting ScaleFactor data for WSM SS1 V/V from 2010-11-17 00:00:00 to 2010-11-17 23:59:59...  
Writing file ./RESULTS/DAILY/\_101117/CHIRP/ScaleFactor\_data\_WSM\_SS1\_VV\_2010-11-17.dat...  
Running IDL program...  
Writing file ../../RESULTS/DAILY/\_101117/CHIRP/ScaleFactor\_ANX\_WSM\_SS1\_VV.png...  
Writing file ../../RESULTS/DAILY/\_101117/CHIRP/ScaleFactor\_DATE\_WSM\_SS1\_VV.png...

CHIRP ANALYSIS completed

#####

RAW DATA ANALYSIS

#####  
Analysis will be performed from 2010-11-17 00:00:00 to 2010-11-17 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/\_101117/RAW\_DATA

Creating directory ./RESULTS/DAILY/\_101117/RAW\_DATA...

\*\*\*\*\*  
Getting raw data for WVS from 2010-11-17 00:00:00 to 2010-11-17 23:59:59...  
Writing file ./RESULTS/DAILY/\_101117/RAW\_DATA/Raw\_data\_WVS\_2010-11-17.dat...  
Running IDL program to create graphs...

Creating image ../../RESULTS/DAILY/\_101117/RAW\_DATA/Raw\_data\_WVS\_input\_mean.png...  
Creating image ../../RESULTS/DAILY/\_101117/RAW\_DATA/Raw\_data\_WVS\_input\_stdev.png...  
Creating image ../../RESULTS/DAILY/\_101117/RAW\_DATA/Raw\_data\_WVS\_gain\_imbalance.png...

\*\*\*\*\*  
Getting raw data for IMM from 2010-11-17 00:00:00 to 2010-11-17 23:59:59...  
Writing file ./RESULTS/DAILY/\_101117/RAW\_DATA/Raw\_data\_IMM\_2010-11-17.dat...  
Running IDL program to create graphs...

Creating image ../../RESULTS/DAILY/\_101117/RAW\_DATA/Raw\_data\_IMM\_input\_mean.png...  
Creating image ../../RESULTS/DAILY/\_101117/RAW\_DATA/Raw\_data\_IMM\_input\_stdev.png...  
Creating image ../../RESULTS/DAILY/\_101117/RAW\_DATA/Raw\_data\_IMM\_gain\_imbalance.png...

RAW DATA ANALYSIS completed

#####

TELEMETRY ANALYSIS

#####  
Analysis will be performed from 2010-11-17 00:00:00 to 2010-11-17 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/\_101117/TELEMETRY



```
Creating directory ./RESULTS/DAILY/_101117/TELEMETRY...

Looking for gaps and missing lines in WVS products...
*****
Checking 27 products from PDE...
Checking 24 products from PDK...

Looking for gaps and missing lines in GM1 products...
*****
Checking 34 products from PDE...
Checking 51 products from PDK...

Looking for gaps and missing lines in APM products...
*****
Checking 3 products from PDE...
No products from PDK...

Looking for gaps and missing lines in IMM products...
*****
Checking 3 products from PDE...
Checking 1 products from PDK...

Looking for gaps and missing lines in WSM products...
*****
Checking 26 products from PDE...
Checking 12 products from PDK...
Found product...ASA_WSM_1PNPDK20101117_093646_000001533096_00295_45568_3385.N1 / 0 gaps / 1 missing lines
```

```
Creating graph of missing lines and gaps...
*****
Creating image: ./RESULTS/DAILY/_101117/TELEMETRY/TELEMETRY_Missing_lines.png...
Creating image: ./RESULTS/DAILY/_101117/TELEMETRY/TELEMETRY_Gaps.png...
```

```
TELEMETRY ANALYSIS completed
#####
```

```
HTML REPORT generation
#####
```

```
Building file ./RESULTS/DAILY/_101117/asarReport.html...
Building DATA SUMMARY section...
Building AUXILIARY FILES ANALYSIS section...
Building MODULE STEPPING ANALYSIS section...
Building CALIBRATION PULSES ANALYSIS section...
Building DOPPLER ANALYSIS section...
Building CHIRP ANALYSIS section...
Building RAW DATA ANALYSIS section...
Building TELEMETRY ANALYSIS section...
```

```
HTML REPORT generation completed
#####
```





Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
ASA_APM_1PNPDE20101117_131936_000000733096_00297_45570_6582.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20101117_163012_000000443096_00299_45572_6585.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20101117_163130_000000443096_00299_45572_6586.N1	OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_GM1_1PNPDE20101117_001331_000003503096_00289_45562_6411.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101117_002627_000001023096_00289_45562_6410.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101117_004215_000001083096_00289_45562_6435.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101117_010744_000009793096_00290_45563_6436.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101117_013121_000004223096_00290_45563_6440.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101117_014102_000001933096_00290_45563_6441.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101117_015224_000005013096_00290_45563_6455.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101117_021658_000006893096_00290_45563_6467.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101117_023646_000002413096_00291_45564_6465.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101117_024728_000010093096_00291_45564_6471.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101117_030635_000001023096_00291_45564_6469.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101117_031354_000001083096_00291_45564_6472.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101117_031354_000001083096_00291_45564_6473.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101117_033300_000004653096_00291_45564_6489.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101117_034937_000002593096_00291_45564_6487.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101117_040918_000001083096_00292_45565_6485.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101117_041343_000005433096_00292_45565_6492.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101117_042626_000007913096_00292_45565_6501.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101117_044027_000001083096_00292_45565_6500.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101117_044643_000003983096_00292_45565_6498.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101117_051410_000002773096_00292_45565_6511.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101117_055459_000011603096_00293_45566_6510.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101117_061759_000007013096_00293_45566_6509.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101117_064027_000001443096_00293_45566_6514.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101117_210512_000005253096_00302_45575_6597.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101117_211640_000003083096_00302_45575_6598.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101117_215516_000008883096_00302_45575_6601.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101117_222930_000003563096_00303_45576_6634.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101117_224625_000009063096_00303_45576_6637.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101117_232454_000001753096_00303_45576_6636.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101117_232755_000001023096_00303_45576_6639.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101117_233532_000005983096_00303_45576_6641.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20101117_234825_000001873096_00303_45576_6645.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_065307_000002713096_00293_45566_3349.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_070233_000003983096_00293_45566_3351.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_074238_000004283096_00294_45567_3352.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_075126_000000603096_00294_45567_3354.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_075128_000001143096_00294_45567_3373.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_075653_000003563096_00294_45567_3374.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_081640_000004893096_00294_45567_3375.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_083321_000003863096_00294_45567_3376.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_084425_000002953096_00294_45567_3378.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_092400_000007493096_00295_45568_3381.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_093521_000000783096_00295_45568_3390.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_094637_000005313096_00295_45568_3391.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_101453_000002953096_00295_45568_3392.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_102226_000004283096_00295_45568_3394.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_111344_000003083096_00296_45569_3420.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_120126_000005073096_00296_45569_3426.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_121812_000001203096_00296_45569_3422.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_122332_000001383096_00296_45569_3427.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_123924_000008703096_00297_45570_3430.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_125239_000003863096_00297_45570_3454.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_131545_000002293096_00297_45570_3456.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_132109_000003143096_00297_45570_3457.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_132627_000003863096_00297_45570_3458.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_134050_000005553096_00297_45570_3459.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_135749_000006833096_00297_45570_3461.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_141324_000001753096_00298_45571_3462.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_141821_000007913096_00298_45571_3463.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_141821_000007913096_00298_45571_3465.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_143021_000009243096_00298_45571_3493.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_145410_000003563096_00298_45571_3495.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_151536_000008823096_00298_45571_3498.N1					OK	OK	OK	OK



ASA_GM1_1PNPDK20101117_154718_000008843096_00299_45572_3499.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_155131_000010943096_00299_45572_3501.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_160859_000012753096_00299_45572_3517.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_170351_000003983096_00299_45572_3519.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_173325_000008643096_00300_45573_3521.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_174636_000005493096_00300_45573_3528.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_175722_000006283096_00300_45573_3529.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_183450_000002413096_00300_45573_3530.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_184235_000001203096_00300_45573_3531.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_184914_000000663096_00300_45573_3532.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_190231_000001143096_00300_45573_3535.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_190817_000005673096_00301_45574_3536.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_192023_000001443096_00301_45574_3538.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_193102_000006283096_00301_45574_3563.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_201617_000004163096_00301_45574_3564.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_202551_000003083096_00301_45574_3567.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_203848_000010813096_00301_45574_3569.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_203848_000010813096_00301_45574_3572.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_210501_000000783096_00302_45575_3568.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20101117_210501_000000783096_00302_45575_3571.N1	OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
ASA_IMM_1PNPDE20101117_030415_000001273096_00291_45564_6463.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20101117_043937_000000373096_00292_45565_6482.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20101117_044220_000002543096_00292_45565_6483.N1	OK	OK	OK	OK
ASA_IMM_1PNPDK20101117_123553_000001423096_00297_45570_3428.N1	OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.


Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WSM_1PNPDE20101117_001924_000004163096_00289_45562_6398.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101117_010151_000003493096_00290_45563_6433.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101117_020051_000004533096_00290_45563_6456.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101117_021423_000001533096_00290_45563_6459.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101117_030825_000001533096_00291_45564_6464.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101117_031155_000001163096_00291_45564_6466.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101117_034051_000004533096_00291_45564_6484.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101117_042251_000002083096_00292_45565_6490.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101117_051851_000005693096_00292_45565_6505.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101117_062945_000002813096_00293_45566_6506.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101117_065740_000001283096_00293_45566_6522.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101117_080937_000004163096_00294_45567_6526.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101117_101951_000001533096_00295_45568_6537.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101117_112200_000004343096_00296_45569_6562.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101117_115435_000002263096_00296_45569_6564.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101117_133514_000003303096_00297_45570_6583.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101117_165524_000004893096_00299_45572_6587.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101117_171034_000002143096_00299_45572_6584.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101117_183855_000002143096_00300_45573_6593.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101117_184443_000002513096_00300_45573_6591.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101117_202316_000001533096_00301_45574_6594.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101117_203134_000002143096_00301_45574_6595.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101117_211402_000001533096_00302_45575_6596.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101117_221009_000003493096_00302_45575_6602.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101117_223529_000004653096_00303_45576_6613.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20101117_234531_000001713096_00303_45576_6632.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20101117_061424_000002083096_00293_45566_3336.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20101117_070020_000001283096_00293_45566_3360.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20101117_074951_000000923096_00294_45567_3361.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20101117_075328_000001903096_00294_45567_3359.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20101117_083951_000002693096_00294_45567_3384.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20101117_093646_000001533096_00295_45568_3385.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20101117_093936_000001653096_00295_45568_3387.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20101117_115907_000001353096_00296_45569_3425.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20101117_192250_000002083096_00301_45574_3551.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20101117_192647_000002513096_00301_45574_3549.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20101117_210150_000001843096_00302_45575_3566.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20101117_224451_000000923096_00303_45576_3592.N1					OK	OK	OK	OK




Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WVS_1PNPDE20101117_000522_000003753096_00289_45562_6409.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101117_002815_000004203096_00289_45562_6408.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101117_003415_000004343096_00289_45562_6437.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101117_004408_000010043096_00289_45562_6434.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101117_012406_000003913096_00290_45563_6438.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101117_013825_000001193096_00290_45563_6439.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101117_014512_000003903096_00290_45563_6442.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101117_020821_000001193096_00290_45563_6444.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101117_020936_000002403096_00290_45563_6468.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101117_022830_000004493096_00291_45564_6470.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101117_031549_000005393096_00291_45564_6477.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101117_032433_000003003096_00291_45564_6488.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101117_035401_000008693096_00291_45564_6486.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101117_041115_000001043096_00292_45565_6499.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101117_045322_000008243096_00292_45565_6502.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101117_050652_000003153096_00292_45565_6507.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101117_052848_000015293096_00292_45565_6512.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101117_063509_000002693096_00293_45566_6508.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101117_064255_000002403096_00293_45566_6513.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101117_212148_000019643096_00302_45575_6600.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101117_221556_000000153096_00302_45575_6599.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101117_221556_000007643096_00302_45575_6633.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101117_224310_00000603096_00303_45576_6635.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101117_230135_000013493096_00303_45576_6638.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101117_232944_000003003096_00303_45576_6640.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101117_235132_000004503096_00303_45576_6648.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20101117_235817_000011243096_00303_45576_6680.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101117_070911_000019643096_00293_45566_3353.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101117_082449_000004653096_00294_45567_3377.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101117_084925_000020243096_00294_45567_3380.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101117_095527_000010493096_00295_45568_3393.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101117_102939_000018443096_00295_45568_3395.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101117_111854_000001503096_00296_45569_3419.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101117_112925_000014243096_00296_45569_3424.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101117_120953_000004503096_00296_45569_3423.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101117_122019_000001493096_00296_45569_3421.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101117_122555_000005643096_00296_45569_3429.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101117_125908_000009443096_00297_45570_3460.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101117_135007_000004203096_00297_45570_3466.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101117_144547_000004493096_00298_45571_3494.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101117_150010_000008103096_00298_45571_3496.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101117_153021_000009743096_00298_45571_3497.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101117_154851_000001193096_00299_45572_3500.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101117_163303_000012443096_00299_45572_3518.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101117_171405_000011093096_00299_45572_3520.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101117_180828_000015293096_00300_45573_3533.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101117_185429_000004353096_00300_45573_3534.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101117_190429_000001793096_00300_45573_3537.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101117_194144_000019493096_00301_45574_3565.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101117_203506_000001803096_00301_45574_3570.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20101117_203506_000001803096_00301_45574_3573.N1					OK	OK	OK	OK

### Calibration pulses for GM1 SS3 H/H




### Calibration pulses for GM1 SS3 H/H







### Calibration pulses for GM1 SS3 H/H




Calibration pulses for GM1 SS3 H/H




17-Nov



17-Nov




17-Nov



17-Nov


rows: 4 8 12 16 20 24 28 32

Calibration pulses for WVS IS2 V/V







Calibration pulses for WVS IS2 V/V




### Calibration pulses for WVS IS2 V/V




17-Nov



17-Nov




17-Nov




17-Nov

rows: \_ 3 \_ 7 \_ 11 \_ 15 \_ 19 \_ 23 \_ 27 \_ 31


### Calibration pulses for WVS IS2 V/V




17-Nov



17-Nov




17-Nov






17-Nov

rows: \_ 4 \_ 8 \_ 12 \_ 16 \_ 20 \_ 24 \_ 28 \_ 32













17-Nov



rows: \_ 1 \_ 5 \_ 9 \_ 13 \_ 17 \_ 21 \_ 25 \_ 29













17-Nov  
rows: - 3 - 7 - 11 - 15 - 19 - 23 - 27 - 31































Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_APM_1PNPDE20101117_131936_000000733096_00297_45570_6582.N1						IS4	V/H	96	45570	297	5.04
ASA_APM_1PNPDE20101117_163012_000000443096_00299_45572_6585.N1						IS4	V/H	96	45572	299	5.04
ASA_APM_1PNPDE20101117_163130_000000443096_00299_45572_6586.N1						IS4	V/H	96	45572	299	5.04

Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_GM1_1PNPDE20101116_235600_000005073096_00289_45562_6412.N1						SS1	H/H	96	45562	289	5.04
ASA_GM1_1PNPDE20101117_001331_000003503096_00289_45562_6411.N1						SS1	H/H	96	45562	289	5.04
ASA_GM1_1PNPDE20101117_002627_000001023096_00289_45562_6410.N1						SS1	H/H	96	45562	289	5.04
ASA_GM1_1PNPDE20101117_004215_000001083096_00289_45562_6435.N1						SS1	H/H	96	45562	289	5.04
ASA_GM1_1PNPDE20101117_010744_000009793096_00290_45563_6436.N1						SS1	H/H	96	45563	290	5.04
ASA_GM1_1PNPDE20101117_013121_000004223096_00290_45563_6440.N1						SS1	H/H	96	45563	290	5.04
ASA_GM1_1PNPDE20101117_014102_000001933096_00290_45563_6441.N1						SS1	H/H	96	45563	290	5.04
ASA_GM1_1PNPDE20101117_015224_000005013096_00290_45563_6455.N1						SS1	H/H	96	45563	290	5.04
ASA_GM1_1PNPDE20101117_021658_000006893096_00290_45563_6467.N1						SS1	H/H	96	45563	290	5.04
ASA_GM1_1PNPDE20101117_023646_000002413096_00291_45564_6465.N1						SS1	H/H	96	45564	291	5.04
ASA_GM1_1PNPDE20101117_024728_000010093096_00291_45564_6471.N1						SS1	H/H	96	45564	291	5.04
ASA_GM1_1PNPDE20101117_030635_000001023096_00291_45564_6469.N1						SS1	H/H	96	45564	291	5.04
ASA_GM1_1PNPDE20101117_031354_000001083096_00291_45564_6473.N1						SS1	H/H	96	45564	291	5.04
ASA_GM1_1PNPDE20101117_031354_000001083096_00291_45564_6472.N1						SS1	H/H	96	45564	291	5.04
ASA_GM1_1PNPDE20101117_033300_000004653096_00291_45564_6489.N1						SS1	H/H	96	45564	291	5.04
ASA_GM1_1PNPDE20101117_034937_000002593096_00291_45564_6487.N1						SS1	H/H	96	45564	291	5.04
ASA_GM1_1PNPDE20101117_040918_000001083096_00292_45565_6485.N1						SS1	H/H	96	45565	292	5.04
ASA_GM1_1PNPDE20101117_041343_000005433096_00292_45565_6492.N1						SS1	H/H	96	45565	292	5.04
ASA_GM1_1PNPDE20101117_042626_000007913096_00292_45565_6501.N1						SS1	H/H	96	45565	292	5.04
ASA_GM1_1PNPDE20101117_044027_000001083096_00292_45565_6500.N1						SS1	H/H	96	45565	292	5.04
ASA_GM1_1PNPDE20101117_044643_000003983096_00292_45565_6498.N1						SS1	H/H	96	45565	292	5.04
ASA_GM1_1PNPDE20101117_051410_000002773096_00292_45565_6511.N1						SS1	H/H	96	45565	292	5.04
ASA_GM1_1PNPDE20101117_055459_000011603096_00293_45566_6510.N1						SS1	H/H	96	45566	293	5.04
ASA_GM1_1PNPDE20101117_061759_000007013096_00293_45566_6509.N1						SS1	H/H	96	45566	293	5.04
ASA_GM1_1PNPDE20101117_064027_000001443096_00293_45566_6514.N1						SS1	H/H	96	45566	293	5.04
ASA_GM1_1PNPDK20101117_065307_000002713096_00293_45566_3349.N1						SS1	H/H	96	45566	293	5.04
ASA_GM1_1PNPDK20101117_070233_000003983096_00293_45566_3351.N1						SS1	H/H	96	45566	293	5.04
ASA_GM1_1PNPDK20101117_074238_000004283096_00294_45567_3352.N1						SS1	H/H	96	45567	294	5.04
ASA_GM1_1PNPDK20101117_075126_000000603096_00294_45567_3354.N1						SS1	H/H	96	45567	294	5.04
ASA_GM1_1PNPDK20101117_075128_000001143096_00294_45567_3373.N1						SS1	H/H	96	45567	294	5.04
ASA_GM1_1PNPDK20101117_075653_000003563096_00294_45567_3374.N1						SS1	H/H	96	45567	294	5.04
ASA_GM1_1PNPDK20101117_081640_000004893096_00294_45567_3375.N1						SS1	H/H	96	45567	294	5.04
ASA_GM1_1PNPDK20101117_083321_000003863096_00294_45567_3376.N1						SS1	H/H	96	45567	294	5.04
ASA_GM1_1PNPDK20101117_084425_000002953096_00294_45567_3378.N1						SS1	H/H	96	45567	294	5.04
ASA_GM1_1PNPDK20101117_092400_000007493096_00295_45568_3381.N1						SS1	H/H	96	45568	295	5.04
ASA_GM1_1PNPDK20101117_093521_000000783096_00295_45568_3390.N1						SS1	H/H	96	45568	295	5.04
ASA_GM1_1PNPDK20101117_094637_000005313096_00295_45568_3391.N1						SS1	H/H	96	45568	295	5.04
ASA_GM1_1PNPDK20101117_101453_000002953096_00295_45568_3392.N1						SS1	H/H	96	45568	295	5.04
ASA_GM1_1PNPDK20101117_102226_000004283096_00295_45568_3394.N1						SS1	H/H	96	45568	295	5.04
ASA_GM1_1PNPDK20101117_111344_000003083096_00296_45569_3420.N1						SS1	H/H	96	45569	296	5.04
ASA_GM1_1PNPDK20101117_120126_000005073096_00296_45569_3426.N1						SS1	H/H	96	45569	296	5.04
ASA_GM1_1PNPDK20101117_121812_000001203096_00296_45569_3422.N1						SS1	H/H	96	45569	296	5.04
ASA_GM1_1PNPDK20101117_122332_000001383096_00296_45569_3427.N1						SS1	H/H	96	45569	296	5.04
ASA_GM1_1PNPDK20101117_123924_000008703096_00297_45570_3430.N1						SS1	H/H	96	45570	297	5.04
ASA_GM1_1PNPDK20101117_125239_000003863096_00297_45570_3454.N1						SS1	H/H	96	45570	297	5.04
ASA_GM1_1PNPDK20101117_131545_000002293096_00297_45570_3456.N1						SS1	H/H	96	45570	297	5.04
ASA_GM1_1PNPDK20101117_132109_000003143096_00297_45570_3457.N1						SS1	H/H	96	45570	297	5.04
ASA_GM1_1PNPDK20101117_132627_000003863096_00297_45570_3458.N1						SS1	H/H	96	45570	297	5.04
ASA_GM1_1PNPDK20101117_134050_000005553096_00297_45570_3459.N1						SS1	H/H	96	45570	297	5.04
ASA_GM1_1PNPDK20101117_135749_000006833096_00297_45570_3461.N1						SS1	H/H	96	45570	297	5.04
ASA_GM1_1PNPDK20101117_141324_000001753096_00298_45571_3462.N1						SS1	H/H	96	45571	298	5.04
ASA_GM1_1PNPDK20101117_141821_000007913096_00298_45571_3465.N1						SS1	H/H	96	45571	298	5.04
ASA_GM1_1PNPDK20101117_141821_000007913096_00298_45571_3463.N1						SS1	H/H	96	45571	298	5.04
ASA_GM1_1PNPDK20101117_143021_000009243096_00298_45571_3493.N1						SS1	H/H	96	45571	298	5.04
ASA_GM1_1PNPDK20101117_145410_000003563096_00298_45571_3495.N1						SS1	H/H	96	45571	298	5.04
ASA_GM1_1PNPDK20101117_151536_000008823096_00298_45571_3498.N1						SS1	H/H	96	45571	298	5.04
ASA_GM1_1PNPDK20101117_154718_000000843096_00299_45572_3499.N1						SS1	H/H	96	45572	299	5.04
ASA_GM1_1PNPDK20101117_155131_000010943096_00299_45572_3501.N1						SS1	H/H	96	45572	299	5.04
ASA_GM1_1PNPDK20101117_160859_000012753096_00299_45572_3517.N1						SS1	H/H	96	45572	299	5.04
ASA_GM1_1PNPDK20101117_170351_000003983096_00299_45572_3519.N1						SS1	H/H	96	45572	299	5.04
ASA_GM1_1PNPDK20101117_173325_000008643096_00300_45573_3521.N1						SS1	H/H	96	45573	300	5.04
ASA_GM1_1PNPDK20101117_174636_000005493096_00300_45573_3528.N1						SS1	H/H	96	45573	300	5.04
ASA_GM1_1PNPDK20101117_175722_000006283096_00300_45573_3529.N1						SS1	H/H	96	45573	300	5.04
ASA_GM1_1PNPDK20101117_183450_000002413096_00300_45573_3530.N1						SS1	H/H	96	45573	300	5.04
ASA_GM1_1PNPDK20101117_184235_000001203096_00300_45573_3531.N1						SS1	H/H	96	45573	300	5.04
ASA_GM1_1PNPDK20101117_184914_000000663096_00300_45573_3532.N1						SS1	H/H	96	45573	300	5.04
ASA_GM1_1PNPDK20101117_190231_000001143096_00300_45573_3535.N1						SS1	H/H	96	45573	300	5.04

ASA_GM1_1PNPDK20101117_190817_000005673096_00301_45574_3536.N1	SS1	H/H	96	45574	301	5.04
ASA_GM1_1PNPDK20101117_192023_000001443096_00301_45574_3538.N1	SS1	H/H	96	45574	301	5.04
ASA_GM1_1PNPDK20101117_193102_000006283096_00301_45574_3563.N1	SS1	H/H	96	45574	301	5.04
ASA_GM1_1PNPDK20101117_201617_000004163096_00301_45574_3564.N1	SS1	H/H	96	45574	301	5.04
ASA_GM1_1PNPDK20101117_202551_000003083096_00301_45574_3567.N1	SS1	H/H	96	45574	301	5.04
ASA_GM1_1PNPDK20101117_203848_000010813096_00301_45574_3569.N1	SS1	H/H	96	45574	301	5.04
ASA_GM1_1PNPDK20101117_203848_000010813096_00301_45574_3572.N1	SS1	H/H	96	45574	301	5.04
ASA_GM1_1PNPDK20101117_210501_000000783096_00302_45575_3568.N1	SS1	H/H	96	45575	302	5.04
ASA_GM1_1PNPDK20101117_210501_000000783096_00302_45575_3571.N1	SS1	H/H	96	45575	302	5.04
ASA_GM1_1PNPDE20101117_210512_000005253096_00302_45575_6597.N1	SS1	H/H	96	45575	302	5.04
ASA_GM1_1PNPDE20101117_211640_000003083096_00302_45575_6598.N1	SS1	H/H	96	45575	302	5.04
ASA_GM1_1PNPDE20101117_215516_000008883096_00302_45575_6601.N1	SS1	H/H	96	45575	302	5.04
ASA_GM1_1PNPDE20101117_222930_000003563096_00303_45576_6634.N1	SS1	H/H	96	45576	303	5.04
ASA_GM1_1PNPDE20101117_224625_000009063096_00303_45576_6637.N1	SS1	H/H	96	45576	303	5.04
ASA_GM1_1PNPDE20101117_232454_000001753096_00303_45576_6636.N1	SS1	H/H	96	45576	303	5.04
ASA_GM1_1PNPDE20101117_232755_000001023096_00303_45576_6639.N1	SS1	H/H	96	45576	303	5.04
ASA_GM1_1PNPDE20101117_233532_000005983096_00303_45576_6641.N1	SS1	H/H	96	45576	303	5.04
ASA_GM1_1PNPDE20101117_234825_000001873096_00303_45576_6645.N1	SS1	H/H	96	45576	303	5.04


Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_IMM_1PNPDE20101117_030415_000001273096_00291_45564_6463.N1						IS6	H/H	96	45564	291	5.04
ASA_IMM_1PNPDE20101117_043937_000000373096_00292_45565_6482.N1						IS6	H/H	96	45565	292	5.04
ASA_IMM_1PNPDE20101117_044220_000002543096_00292_45565_6483.N1						IS6	H/H	96	45565	292	5.04
ASA_IMM_1PNPDK20101117_123553_000001423096_00297_45570_3428.N1						IS6	H/H	96	45570	297	5.04




Filename	Pol	Timestamp	count(Module)				
ASA_MS__0PNPDE20101117_001212_000000163096_00289_45562_0069.N1	H	2010-11-17 00:12:12	320				
ASA_MS__0PNPDE20101117_051254_000000163096_00292_45565_0070.N1	V	2010-11-17 05:12:54	320				
ASA_MS__0PNPDK20101117_101336_000000163096_00295_45568_0298.N1	H	2010-11-17 10:13:36	320				
ASA_MS__0PNPDK20101117_151418_000000163096_00298_45571_0299.N1	V	2010-11-17 15:14:18	320				
ASA_MS__0PNPDK20101117_201500_000000163096_00301_45574_0300.N1	H	2010-11-17 20:15:00	320				


Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WSM_1PNPDE20101117_001924_000004163096_00289_45562_6398.N1						SS1	H/H	96	45562	289	5.04
ASA_WSM_1PNPDE20101117_010151_000003493096_00290_45563_6433.N1						SS1	H/H	96	45563	290	5.04
ASA_WSM_1PNPDE20101117_020051_000004533096_00290_45563_6456.N1						SS1	H/H	96	45563	290	5.04
ASA_WSM_1PNPDE20101117_021423_000001533096_00290_45563_6459.N1						SS1	V/V	96	45563	290	5.04
ASA_WSM_1PNPDE20101117_030825_000001533096_00291_45564_6464.N1						SS1	H/H	96	45564	291	5.04
ASA_WSM_1PNPDE20101117_031155_000001163096_00291_45564_6466.N1						SS1	H/H	96	45564	291	5.04
ASA_WSM_1PNPDE20101117_034051_000004533096_00291_45564_6484.N1						SS1	H/H	96	45564	291	5.04
ASA_WSM_1PNPDE20101117_042251_000002083096_00292_45565_6490.N1						SS1	H/H	96	45565	292	5.04
ASA_WSM_1PNPDE20101117_051851_000005693096_00292_45565_6505.N1						SS1	H/H	96	45565	292	5.04
ASA_WSM_1PNPDK20101117_061424_000002083096_00293_45566_3336.N1						SS1	H/H	96	45566	293	5.04
ASA_WSM_1PNPDE20101117_062945_000002813096_00293_45566_6506.N1						SS1	H/H	96	45566	293	5.04
ASA_WSM_1PNPDE20101117_065740_000001283096_00293_45566_6522.N1						SS1	H/H	96	45566	293	5.04
ASA_WSM_1PNPDK20101117_070020_000001283096_00293_45566_3360.N1						SS1	H/H	96	45566	293	5.04
ASA_WSM_1PNPDK20101117_074951_000000923096_00294_45567_3361.N1						SS1	H/H	96	45567	294	5.04
ASA_WSM_1PNPDK20101117_075328_000001903096_00294_45567_3359.N1						SS1	H/H	96	45567	294	5.04
ASA_WSM_1PNPDE20101117_080937_000004163096_00294_45567_6526.N1						SS1	V/V	96	45567	294	5.04
ASA_WSM_1PNPDK20101117_083951_000002693096_00294_45567_3384.N1						SS1	H/H	96	45567	294	5.04
ASA_WSM_1PNPDK20101117_093646_000001533096_00295_45568_3385.N1						SS1	H/H	96	45568	295	5.04
ASA_WSM_1PNPDK20101117_093936_000001653096_00295_45568_3387.N1						SS1	V/V	96	45568	295	5.04
ASA_WSM_1PNPDE20101117_101951_000001533096_00295_45568_6537.N1						SS1	H/H	96	45568	295	5.04
ASA_WSM_1PNPDE20101117_112200_000004343096_00296_45569_6562.N1						SS1	V/V	96	45569	296	5.04
ASA_WSM_1PNPDE20101117_115435_000002263096_00296_45569_6564.N1						SS1	H/H	96	45569	296	5.04
ASA_WSM_1PNPDK20101117_115907_000001353096_00296_45569_3425.N1						SS1	H/H	96	45569	296	5.04
ASA_WSM_1PNPDE20101117_133514_000003303096_00297_45570_6583.N1						SS1	H/H	96	45570	297	5.04
ASA_WSM_1PNPDE20101117_165524_000004893096_00299_45572_6587.N1						SS1	H/H	96	45572	299	5.04
ASA_WSM_1PNPDE20101117_171034_000002143096_00299_45572_6584.N1						SS1	H/H	96	45572	299	5.04
ASA_WSM_1PNPDE20101117_183855_000002143096_00300_45573_6593.N1						SS1	H/H	96	45573	300	5.04
ASA_WSM_1PNPDE20101117_184443_000002513096_00300_45573_6591.N1						SS1	H/H	96	45573	300	5.04
ASA_WSM_1PNPDK20101117_192250_000002083096_00301_45574_3551.N1						SS1	H/H	96	45574	301	5.04
ASA_WSM_1PNPDK20101117_192647_000002513096_00301_45574_3549.N1						SS1	H/H	96	45574	301	5.04
ASA_WSM_1PNPDE20101117_202316_000001533096_00301_45574_6594.N1						SS1	H/H	96	45574	301	5.04
ASA_WSM_1PNPDE20101117_203134_000002143096_00301_45574_6595.N1						SS1	H/H	96	45574	301	5.04
ASA_WSM_1PNPDK20101117_210150_000001843096_00302_45575_3566.N1						SS1	V/V	96	45575	302	5.04
ASA_WSM_1PNPDE20101117_211402_000001533096_00302_45575_6596.N1						SS1	V/V	96	45575	302	5.04
ASA_WSM_1PNPDE20101117_221009_000003493096_00302_45575_6602.N1						SS1	H/H	96	45575	302	5.04
ASA_WSM_1PNPDE20101117_223529_000004653096_00303_45576_6613.N1						SS1	V/V	96	45576	303	5.04
ASA_WSM_1PNPDK20101117_224451_000000923096_00303_45576_3592.N1						SS1	H/H	96	45576	303	5.04
ASA_WSM_1PNPDE20101117_234531_000001713096_00303_45576_6632.N1						SS1	H/H	96	45576	303	5.04


Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WVS_1PNPDE20101117_000522_000003753096_00289_45562_6409.N1						IS2	V/V	96	45562	289	5.04
ASA_WVS_1PNPDE20101117_002815_000004203096_00289_45562_6408.N1						IS2	V/V	96	45562	289	5.04
ASA_WVS_1PNPDE20101117_003415_000004343096_00289_45562_6437.N1						IS2	V/V	96	45562	289	5.04
ASA_WVS_1PNPDE20101117_004408_000010043096_00289_45562_6434.N1						IS2	V/V	96	45562	289	5.04
ASA_WVS_1PNPDE20101117_012406_000003913096_00290_45563_6438.N1						IS2	V/V	96	45563	290	5.04
ASA_WVS_1PNPDE20101117_013825_000001193096_00290_45563_6439.N1						IS2	V/V	96	45563	290	5.04
ASA_WVS_1PNPDE20101117_014512_000003903096_00290_45563_6442.N1						IS2	V/V	96	45563	290	5.04
ASA_WVS_1PNPDE20101117_020821_000001193096_00290_45563_6444.N1						IS2	V/V	96	45563	290	5.04
ASA_WVS_1PNPDE20101117_020936_000002403096_00290_45563_6468.N1						IS2	V/V	96	45563	290	5.04
ASA_WVS_1PNPDE20101117_020821_000001193096_00290_45563_6444.N1						IS1	V/V	96	45563	290	5.04
ASA_WVS_1PNPDE20101117_022830_000004493096_00291_45564_6470.N1						IS2	V/V	96	45564	291	5.04
ASA_WVS_1PNPDE20101117_031549_000005393096_00291_45564_6477.N1						IS2	V/V	96	45564	291	5.04
ASA_WVS_1PNPDE20101117_032433_000003003096_00291_45564_6488.N1						IS2	V/V	96	45564	291	5.04
ASA_WVS_1PNPDE20101117_035401_000008693096_00291_45564_6486.N1						IS2	V/V	96	45564	291	5.04
ASA_WVS_1PNPDE20101117_041115_000001043096_00292_45565_6499.N1						IS2	V/V	96	45565	292	5.04
ASA_WVS_1PNPDE20101117_045322_000008243096_00292_45565_6502.N1						IS2	V/V	96	45565	292	5.04
ASA_WVS_1PNPDE20101117_050652_000003153096_00292_45565_6507.N1						IS2	V/V	96	45565	292	5.04
ASA_WVS_1PNPDE20101117_045322_000008243096_00292_45565_6502.N1						IS1	V/V	96	45565	292	5.04
ASA_WVS_1PNPDE20101117_052848_000015293096_00292_45565_6512.N1						IS2	V/V	96	45565	292	5.04
ASA_WVS_1PNPDE20101117_063509_000002693096_00293_45566_6508.N1						IS2	V/V	96	45566	293	5.04
ASA_WVS_1PNPDE20101117_064255_000002403096_00293_45566_6513.N1						IS2	V/V	96	45566	293	5.04
ASA_WVS_1PNPDE20101117_064255_000002403096_00293_45566_6513.N1						IS1	V/V	96	45566	293	5.04
ASA_WVS_1PNPDK20101117_070911_000019643096_00293_45566_3353.N1						IS2	V/V	96	45566	293	5.04
ASA_WVS_1PNPDK20101117_082449_000004653096_00294_45567_3377.N1						IS2	V/V	96	45567	294	5.04
ASA_WVS_1PNPDK20101117_084925_000020243096_00294_45567_3380.N1						IS2	V/V	96	45567	294	5.04
ASA_WVS_1PNPDK20101117_095527_000010493096_00295_45568_3393.N1						IS2	V/V	96	45568	295	5.04
ASA_WVS_1PNPDK20101117_102939_000018443096_00295_45568_3395.N1						IS2	V/V	96	45568	295	5.04
ASA_WVS_1PNPDK20101117_111854_000001503096_00296_45569_3419.N1						IS2	V/V	96	45569	296	5.04
ASA_WVS_1PNPDK20101117_112925_000014243096_00296_45569_3424.N1						IS2	V/V	96	45569	296	5.04
ASA_WVS_1PNPDK20101117_120953_000004503096_00296_45569_3423.N1						IS2	V/V	96	45569	296	5.04
ASA_WVS_1PNPDK20101117_122019_000001493096_00296_45569_3421.N1						IS2	V/V	96	45569	296	5.04
ASA_WVS_1PNPDK20101117_122555_000005643096_00296_45569_3429.N1						IS2	V/V	96	45569	296	5.04
ASA_WVS_1PNPDK20101117_125908_000009443096_00297_45570_3460.N1						IS2	V/V	96	45570	297	5.04
ASA_WVS_1PNPDK20101117_135007_000004203096_00297_45570_3466.N1						IS2	V/V	96	45570	297	5.04
ASA_WVS_1PNPDK20101117_144547_000004493096_00298_45571_3494.N1						IS2	V/V	96	45571	298	5.04
ASA_WVS_1PNPDK20101117_150010_000008103096_00298_45571_3496.N1						IS2	V/V	96	45571	298	5.04
ASA_WVS_1PNPDK20101117_153021_000009743096_00298_45571_3497.N1						IS2	V/V	96	45571	298	5.04
ASA_WVS_1PNPDK20101117_154851_000001193096_00299_45572_3500.N1						IS2	V/V	96	45572	299	5.04
ASA_WVS_1PNPDK20101117_163303_000012443096_00299_45572_3518.N1						IS2	V/V	96	45572	299	5.04
ASA_WVS_1PNPDK20101117_171405_000011093096_00299_45572_3520.N1						IS2	V/V	96	45572	299	5.04
ASA_WVS_1PNPDK20101117_180828_000015293096_00300_45573_3533.N1						IS2	V/V	96	45573	300	5.04
ASA_WVS_1PNPDK20101117_185429_000004353096_00300_45573_3534.N1						IS2	V/V	96	45573	300	5.04
ASA_WVS_1PNPDK20101117_190429_000001793096_00300_45573_3537.N1						IS2	V/V	96	45573	300	5.04
ASA_WVS_1PNPDK20101117_194144_000019493096_00301_45574_3565.N1						IS2	V/V	96	45574	301	5.04
ASA_WVS_1PNPDK20101117_203506_000001803096_00301_45574_3570.N1						IS2	V/V	96	45574	301	5.04
ASA_WVS_1PNPDK20101117_203506_000001803096_00301_45574_3573.N1						IS2	V/V	96	45574	301	5.04
ASA_WVS_1PNPDE20101117_212148_000019643096_00302_45575_6600.N1						IS2	V/V	96	45575	302	5.04
ASA_WVS_1PNPDE20101117_221556_000000153096_00302_45575_6599.N1						IS2	V/V	96	45575	302	5.04
ASA_WVS_1PNPDE20101117_221556_000007643096_00302_45575_6633.N1						IS2	V/V	96	45575	302	5.04
ASA_WVS_1PNPDE20101117_224310_000000603096_00303_45576_6635.N1						IS2	V/V	96	45576	303	5.04
ASA_WVS_1PNPDE20101117_230135_000013493096_00303_45576_6638.N1						IS2	V/V	96	45576	303	5.04
ASA_WVS_1PNPDE20101117_232944_000003003096_00303_45576_6640.N1						IS2	V/V	96	45576	303	5.04
ASA_WVS_1PNPDE20101117_235132_000004503096_00303_45576_6648.N1						IS2	V/V	96	45576	303	5.04
ASA_WVS_1PNPDE20101117_235817_000011243096_00303_45576_6680.N1						IS2	V/V	96	45576	303	5.04


















































































17-Nov





17-Nov




17-Nov








17-Nov



17-Nov



17-Nov























