



Analysis from 09-JAN-2011 00:00:00 to 09-JAN-2011 23:59:59. Page generated on 10-JAN-2011 07:32:40.
View log file: ASAR_Daily_Report_20110110_0731.log. For any anomalies please contact emma.griffiths@vega.co.uk, kajal.haria@vega.co.uk.

This report is automatically generated every day, every 2 hours. No comments are provided on the results.

SUMMARY

1. DATA SUMMARY
 - 1.1 Summary tables
 - 1.2 Lists of products used
2. AUXILIARY FILES ANALYSIS
 - 2.1 IECF operational ADFs list
 - 2.2 Products with wrong ADFs
3. MODULE STEPPING PRODUCTS ANALYSIS
 - 3.1 V/V polarisation
 - 3.2 H/H polarisation
4. CALIBRATION PULSES ANALYSIS
 - 4.1 Analysis for WVS IS2 V/V
 - 4.1.1 Temporal Evolution Analysis for WVS IS2 V/V
 - 4.1.2 All Rows Analysis for WVS IS2 V/V
 - 4.2 Analysis for GM1 SS3 H/H
 - 4.2.1 Temporal Evolution Analysis for GM1 SS3 H/H
 - 4.2.2 All Rows Analysis for GM1 SS3 H/H
5. DOPPLER ANALYSIS
 - 5.1 Analysis for WVS IS2 V/V
 - 5.1.1 Doppler MAP Analysis for WVS IS2 V/V
 - 5.1.2 Doppler ANX Analysis for WVS IS2 V/V
 - 5.2 Analysis for GM1 SS1 H/H
 - 5.2.1 Doppler MAP Analysis for GM1 SS1 H/H
 - 5.2.2 Doppler ANX Analysis for GM1 SS1 H/H
 - 5.3 Doppler JUMPS Analysis for WSM
6. CHIRP ANALYSIS
 - 6.1 Analysis for WSM SS1 H/H
 - 6.1.1 ScaleFactor
 - 6.2 Analysis for WSM SS1 V/V
 - 6.2.1 ScaleFactor
7. RAW DATA ANALYSIS
 - 7.1 Analysis for WVS
 - 7.2 Analysis for IMM
8. TELEMETRY ANALYSIS
 - 8.1 Number of Missing Lines
 - 8.2 Number of Gaps

1 - DATA SUMMARY

1.1 - Summary tables

[[BACK TO MENU](#)]

WVS				GM1				APM				IMM				WSM				MS			
Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Time	Pol	Modules
PDE	IS1	V/V	2	PDE	WS	H/H	25	PDE	IS4	V/H	1	PDE	IS2	H/H	1	PDE	WS	H/H	18	PDK	2011-01-09 14:32:13	H	320
PDE	IS2	V/V	25	PDK	WS	H/H	44	PDE	IS6	V/H	1	PDE	IS6	H/H	3	PDE	WS	V/V	10	PDK	2011-01-09 16:12:27	V	320
PDK	IS2	V/V	26									PDK	IS6	***	1	PDK	WS	H/H	7				
																PDK	WS	V/V	3				

1.2 - Lists of products used

[[BACK TO MENU](#)]

[TXT] [XLS] [List_WVS_products_used](#)
 [TXT] [XLS] [List_GM1_products_used](#)
 [TXT] [XLS] [List_APM_products_used](#)
 [TXT] [XLS] [List_IMM_products_used](#)
 [TXT] [XLS] [List_WSM_products_used](#)
 [TXT] [XLS] [List_MS_products_used](#)

2 - AUXILIARY FILES ANALYSIS

2.1 - IECF operational ADFs list

[[BACK TO MENU](#)]

ADFs disseminated for ASAR
ASA_CON_AXVIEC20101222_141422_20100317_120410_20141231_000000
ASA_INS_AXVIEC20101222_143805_20101022_000000_20141231_235959
ASA_XCH_AXVIEC20101222_143057_20020301_000000_20141231_000000
ASA_XCA_AXVIEC20101111_113830_20100601_000000_20141231_000000

2.2 - Products with wrong ADFs

[[BACK TO MENU](#)]

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
WVS	0	0	0	0
GM1	0	0	0	0
APM	0	0	0	0
IMM	0	0	0	0
WSM	0	0	0	0

[TXT] [XLS] [Check_ADFs_WVS](#)
 [TXT] [XLS] [Check_ADFs_GM1](#)
 [TXT] [XLS] [Check_ADFs_APM](#)
 [TXT] [XLS] [Check_ADFs_IMM](#)
 [TXT] [XLS] [Check_ADFs_WSM](#)

3 - MODULE STEPPING PRODUCTS ANALYSIS


SECOND FIXED REFERENCE	PREVIOUS PRODUCT REFERENCE
------------------------	----------------------------

Pre-launch reference (2001-02-09)

Previous product in the same polarisation


Reference: 2001-02-09 14:08:23 V RxGain
 Test : 2011-01-09 16:12:27 V





Reference: 2011-01-08 16:49:11 V RxGain
 Test : 2011-01-09 16:12:27 V



Reference: 2001-02-09 14:08:23 V RxPhase
 Test : 2011-01-09 16:12:27 V

Reference: 2011-01-08 16:49:11 V RxPhase
 Test : 2011-01-09 16:12:27 V









3.2 - H/H polarisation

[[BACK TO MENU](#)]

SECOND FIXED REFERENCE	PREVIOUS PRODUCT REFERENCE
Pre-launch reference (2001-02-09)	Previous product in the same polarisation



4 - CALIBRATION PULSES ANALYSIS

4.1 - Analysis for WVS IS2 V/V


4.1.1 - Temporal Evolution Analysis for WVS IS2 V/V

[BACK TO MENU]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Calibration pulses for WVS IS2 V/V




Transmit power (P1 - P1a) for WVS IS2 V/V



4.1.2 - All Rows Analysis for WVS IS2 V/V

[[BACK TO MENU](#)]





4.2 - Analysis for GM1 SS3 H/H


4.2.1 - Temporal Evolution Analysis for GM1 SS3 H/H

[BACK TO MENU]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]

Calibration pulses for GM1 SS3 H/H




Transmit power (P1 - P1a) for GM1 SS3 H/H



4.2.2 - All Rows Analysis for GM1 SS3 H/H

[[BACK TO MENU](#)]






5 - DOPPLER ANALYSIS

5.1 - Analysis for WVS IS2 V/V

5.1.1 - Doppler MAP Analysis for WVS IS2 V/V

[[BACK TO MENU](#)]






5.1.2 - Doppler ANX Analysis for WVS IS2 V/V

[[BACK TO MENU](#)]






5.2 - Analysis for GM1 SS1 H/H

5.2.1 - Doppler MAP Analysis for GM1 SS1 H/H

[[BACK TO MENU](#)]






5.2.2 - Doppler ANX Analysis for GM1 SS1 H/H

[[BACK TO MENU](#)]






5.3 - Doppler JUMPS Analysis for WSM

[BACK TO MENU]







6 - CHIRP ANALYSIS

6.1 - Analysis for WSM SS1 H/H

6.1.1 - ScaleFactor

[[BACK TO MENU](#)]







6.2 - Analysis for WSM SS1 V/V

6.2.1 - ScaleFactor

[[BACK TO MENU](#)]






7 - RAW DATA ANALYSIS

7.1 - Analysis for WVS

[[BACK TO MENU](#)]


--	--	--	--




Channel	Statistics	DSS-B
MEAN I	mean	0.000635535
	stdev	1.11497e-07
MEAN Q	mean	0.000482614
	stdev	1.96984e-07
Channel	Statistics	DSS-B
STDEV I	mean	0.154380
	stdev	0.00126764
STDEV Q	mean	0.154988
	stdev	0.00129694

7.2 - Analysis for IMM

[[BACK TO MENU](#)]







8 - TELEMETRY ANALYSIS

Processing Center	Product	Gaps	Missing lines
PDE	ASA_WSM_1PNPDE20110109_122151_000001533098_00196_46331_0756.N1	0	1

8.1 - Number of Missing lines


[BACK TO MENU]





8.2 - Number of Gaps

[[BACK TO MENU](#)]



ASAR DAILY REPORT for 110109
#####

MODE: DAILY
ANALYSIS: ALL
DATE: 2011-01-09 00:00:00

Analysis will be performed from 2011-01-09 00:00:00 to 2011-01-09 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_110109/

DATA SUMMARY

Summary will be performed from 2011-01-09 00:00:00 to 2011-01-09 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_110109/DATA_SUMMARY

Creating directory ./RESULTS/DAILY/_110109/DATA_SUMMARY...
Writing file ./RESULTS/DAILY/_110109/DATA_SUMMARY/Data_summary.html...

Getting WVS products list from 2011-01-09 00:00:00 to 2011-01-09 23:59:59...
Writing file ./RESULTS/DAILY/_110109/DATA_SUMMARY/List_WVS_products_used.xls...
Writing file ./RESULTS/DAILY/_110109/DATA_SUMMARY/List_WVS_products_used.txt...

Getting GM1 products list from 2011-01-09 00:00:00 to 2011-01-09 23:59:59...
Writing file ./RESULTS/DAILY/_110109/DATA_SUMMARY/List_GM1_products_used.xls...
Writing file ./RESULTS/DAILY/_110109/DATA_SUMMARY/List_GM1_products_used.txt...

Getting APM products list from 2011-01-09 00:00:00 to 2011-01-09 23:59:59...
Writing file ./RESULTS/DAILY/_110109/DATA_SUMMARY/List_APM_products_used.xls...
Writing file ./RESULTS/DAILY/_110109/DATA_SUMMARY/List_APM_products_used.txt...

Getting IMM products list from 2011-01-09 00:00:00 to 2011-01-09 23:59:59...
Writing file ./RESULTS/DAILY/_110109/DATA_SUMMARY/List_IMM_products_used.xls...
Writing file ./RESULTS/DAILY/_110109/DATA_SUMMARY/List_IMM_products_used.txt...

Getting WSM products list from 2011-01-09 00:00:00 to 2011-01-09 23:59:59...
Writing file ./RESULTS/DAILY/_110109/DATA_SUMMARY/List_WSM_products_used.xls...
Writing file ./RESULTS/DAILY/_110109/DATA_SUMMARY/List_WSM_products_used.txt...

Getting MS products list from 2011-01-09 00:00:00 to 2011-01-09 23:59:59...
Writing file ./RESULTS/DAILY/_110109/DATA_SUMMARY/List_MS_products_used.xls...
Writing file ./RESULTS/DAILY/_110109/DATA_SUMMARY/List_MS_products_used.txt...

DATA SUMMARY completed
#####

AUXILIARY FILES ANALYSIS

Analysis will be performed from 2011-01-09 00:00:00 to 2011-01-09 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_110109/AUXILIARY

Creating directory ./RESULTS/DAILY/_110109/AUXILIARY...

Looking for the IECF operational ADFs list...



ADF filter 20110109*current_3_IECF_ADFs.txt
 Found list 20110109_030001_current_3_IECF_ADFs.txt...
 Extracting ADFs...

ASA_CON_AXVIEC20101222_141422_20100317_120410_20141231_000000
 ASA_INS_AXVIEC20101222_143805_20101022_000000_20141231_235959
 ASA_XCH_AXVIEC20101222_143057_20020301_000000_20141231_000000
 ASA_XCA_AXVIEC20101111_113830_20100601_000000_20141231_000000

Writing file ./RESULTS/DAILY/_110109/AUXILIARY/ASAR_ADFs_IECF_List3.html...
 Writing file ./RESULTS/DAILY/_110109/AUXILIARY/Auxiliary_files_summary.html...

Analysing WVS products...

Writing file ./RESULTS/DAILY/_110109/AUXILIARY/Check_ADFs_WVS.xls...
 Writing file ./RESULTS/DAILY/_110109/AUXILIARY/Check_ADFs_WVS.txt...

ASA_WVS_1PNPDE20110109_001421_000002403098_00189_46324_0646.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110109_003701_000009463098_00189_46324_0643.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110109_010315_000004803098_00189_46324_0658.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110109_012746_000001643098_00189_46324_0657.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110109_012946_000003453098_00189_46324_0660.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110109_014500_000006293098_00190_46325_0673.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110109_022757_000002393098_00190_46325_0671.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110109_023554_000004193098_00190_46325_0669.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110109_024239_000005253098_00190_46325_0684.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110109_030721_000001653098_00190_46325_0686.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110109_032554_000002243098_00191_46326_0689.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110109_040817_000010343098_00191_46326_0692.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110109_042502_00000603098_00191_46326_0704.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110109_042906_000001503098_00191_46326_0705.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110109_044644_000012743098_00191_46326_0707.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110109_054703_000010793098_00192_46327_0709.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110109_203955_000020393098_00201_46336_0771.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110109_212801_00000453098_00201_46336_0773.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110109_213405_000001353098_00201_46336_0788.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110109_214150_000002843098_00201_46336_0784.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110109_221836_000021293098_00202_46337_0794.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110109_230747_000005253098_00202_46337_0793.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110109_231532_000011243098_00202_46337_0838.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110109_233821_000002253098_00203_46338_0843.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110109_060448_000004203098_00192_46327_6006.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110109_062526_000019343098_00192_46327_6017.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110109_074627_000003453098_00193_46328_6063.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110109_080550_000021443098_00193_46328_6065.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110109_091447_000010193098_00194_46329_6104.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110109_094603_000020843098_00194_46329_6107.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110109_105224_000012143098_00195_46330_6130.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110109_112608_000020393098_00195_46330_6132.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110109_121654_000002553098_00196_46331_6156.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110109_122421_000004943098_00196_46331_6158.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110109_124441_000004803098_00196_46331_6160.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110109_131108_000001203098_00196_46331_6163.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110109_132509_000002993098_00197_46332_6164.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110109_133115_000001493098_00197_46332_6166.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110109_135915_000007343098_00197_46332_6210.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110109_142143_000005853098_00197_46332_6212.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110109_144645_000004653098_00197_46332_6213.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110109_145902_000001643098_00197_46332_6218.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110109_154722_00000893098_00198_46333_6260.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110109_155156_000011843098_00198_46333_6263.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110109_162823_000011393098_00198_46333_6265.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110109_162823_000011393098_00198_46333_6267.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110109_172826_000014993098_00199_46334_6291.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110109_181223_000010193098_00199_46334_6295.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK



ASA_WVS_1PNPDK20110109_190405_000017843098_00200_46335_6319.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110109_195304_000004043098_00200_46335_6322.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

Analysing GM1 products...

Writing file ./RESULTS/DAILY/_110109/AUXILIARY/Check_ADFs_GM1.xls...

Writing file ./RESULTS/DAILY/_110109/AUXILIARY/Check_ADFs_GM1.txt...

ASA_GM1_1PNPDE20110109_002732_000005673098_00189_46324_0645.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110109_005333_000005793098_00189_46324_0642.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110109_011150_000005013098_00189_46324_0656.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110109_013618_000005193098_00189_46324_0677.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110109_015608_000001993098_00190_46325_0676.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110109_020602_000002953098_00190_46325_0675.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110109_021415_000004713098_00190_46325_0674.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110109_022419_000001443098_00190_46325_0672.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110109_023245_000001873098_00190_46325_0670.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110109_025205_000003983098_00190_46325_0685.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110109_031048_000002053098_00190_46325_0683.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110109_031415_000006953098_00190_46325_0687.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110109_033027_000008163098_00191_46326_0688.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110109_034508_0000010153098_00191_46326_0693.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110109_043220_000002893098_00191_46326_0706.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110109_050850_0000018793098_00192_46327_0710.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110109_202505_000000903098_00201_46336_0769.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110109_203018_000005733098_00201_46336_0770.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110109_213658_000002893098_00201_46336_0787.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110109_214713_000004533098_00202_46337_0786.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110109_220658_000000843098_00202_46337_0785.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110109_221106_000002473098_00202_46337_0790.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110109_225458_000004713098_00202_46337_0795.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110109_234620_000001083098_00203_46338_0835.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110109_235220_000005983098_00203_46338_0842.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110109_061235_000003083098_00192_46327_6012.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110109_070051_000006953098_00193_46328_6018.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110109_071111_000005433098_00193_46328_6060.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110109_072457_000005553098_00193_46328_6061.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110109_073655_000003563098_00193_46328_6062.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110109_075249_000007793098_00193_46328_6064.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110109_084217_000005253098_00194_46329_6066.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110109_090025_000002113098_00194_46329_6103.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110109_094100_000003023098_00194_46329_6105.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110109_102126_000005613098_00195_46330_6106.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110109_103423_000000783098_00195_46330_6127.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110109_104526_000000663098_00195_46330_6128.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110109_104913_000001873098_00195_46330_6129.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110109_111318_000004533098_00195_46330_6131.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110109_120051_000006283098_00196_46331_6133.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110109_121011_000000663098_00196_46331_6157.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110109_124021_000002593098_00196_46331_6159.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110109_125331_000007793098_00196_46331_6161.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110109_131351_000001023098_00196_46331_6162.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110109_131540_000005673098_00196_46331_6165.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110109_133433_000009183098_00197_46332_6178.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110109_134841_000001323098_00197_46332_6207.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110109_135521_000002353098_00197_46332_6208.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110109_141217_000002773098_00197_46332_6209.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110109_141802_000002173098_00197_46332_6211.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110109_143345_000007793098_00197_46332_6214.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110109_145516_000002233098_00197_46332_6215.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110109_150238_000001873098_00197_46332_6216.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110109_151230_000010333098_00198_46333_6217.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110109_152841_000001083098_00198_46333_6259.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110109_154144_000003383098_00198_46333_6261.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110109_154930_000001383098_00198_46333_6262.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK


```
ASA_GM1_1PNPDK20110109_161402_000005983098_00198_46333_6264.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110109_164803_000010393098_00199_46334_6268.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110109_170803_000001933098_00199_46334_6289.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110109_171259_000000783098_00199_46334_6288.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110109_171524_000007793098_00199_46334_6290.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110109_175414_000005553098_00199_46334_6293.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110109_183009_000004473098_00200_46335_6294.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110109_183912_000001993098_00200_46335_6296.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110109_184626_000007553098_00200_46335_6318.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110109_193428_000006103098_00200_46335_6320.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110109_200313_000006953098_00200_46335_6321.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110109_201724_000001633098_00201_46336_6323.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```

Analysing APM products...

Writing file ./RESULTS/DAILY/_110109/AUXILIARY/Check_ADFs_APM.xls...

Writing file ./RESULTS/DAILY/_110109/AUXILIARY/Check_ADFs_APM.txt...

```
ASA_APM_1PNPDE20110109_073414_000001383098_00193_46328_0727.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20110109_141657_000000433098_00197_46332_0757.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```

Analysing IMM products...

Writing file ./RESULTS/DAILY/_110109/AUXILIARY/Check_ADFs_IMM.xls...

Writing file ./RESULTS/DAILY/_110109/AUXILIARY/Check_ADFs_IMM.txt...

```
ASA_IMM_1PNPDE20110109_040203_000003143098_00191_46326_0681.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20110109_054010_000003843098_00192_46327_0703.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20110109_072014_000002733098_00193_46328_0726.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20110109_200115_000001083098_00200_46335_0767.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20110109_184310_000000103098_00200_46335_6292.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```

Analysing WSM products...

Writing file ./RESULTS/DAILY/_110109/AUXILIARY/Check_ADFs_WSM.xls...

Writing file ./RESULTS/DAILY/_110109/AUXILIARY/Check_ADFs_WSM.txt...

```
ASA_WSM_1PNPDE20110109_001151_000001533098_00189_46324_0639.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110109_001856_000005143098_00189_46324_0648.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110109_001856_000005143098_00189_46324_0649.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110109_012014_000004533098_00189_46324_0644.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110109_015928_000003923098_00190_46325_0661.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110109_015928_000003923098_00190_46325_0662.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110109_021059_000001903098_00190_46325_0678.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110109_025849_000005143098_00190_46325_0680.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110109_043711_000005753098_00191_46326_0702.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110109_074256_000002143098_00193_46328_0728.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110109_122151_000001533098_00196_46331_0756.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110109_123315_000004223098_00196_46331_0755.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110109_153336_000001533098_00198_46333_0759.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110109_153644_000002943098_00198_46333_0760.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110109_162406_000002513098_00198_46333_0758.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110109_180333_000002693098_00199_46334_0761.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110109_183737_000000923098_00200_46335_0763.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110109_185906_000003003098_00200_46335_0766.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110109_194442_000002143098_00200_46335_0764.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110109_194933_000002143098_00200_46335_0765.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110109_212933_000002753098_00201_46336_0772.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110109_215751_000002143098_00202_46337_0782.N1 ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```



ASA_WSM_1PNPDE20110109_220828_000001533098_00202_46337_0789.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110109_221519_000001903098_00202_46337_0791.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110109_230254_000002813098_00202_46337_0783.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110109_233451_000002083098_00203_46338_0803.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110109_234243_000002083098_00203_46338_0857.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDE20110109_234818_000002323098_00203_46338_0839.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20110109_061749_000004343098_00192_46327_6025.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20110109_065816_000001533098_00193_46328_6026.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20110109_085105_000005443098_00194_46329_6075.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20110109_103048_000002083098_00195_46330_6114.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20110109_103551_000003433098_00195_46330_6115.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20110109_130658_000002513098_00196_46331_6239.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20110109_135101_000002513098_00197_46332_6182.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20110109_135101_000002513098_00197_46332_6183.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20110109_153035_000001533098_00198_46333_6232.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WSM_1PNPDK20110109_184351_000001533098_00200_46335_6299.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

AUXILIARY FILES ANALYSIS completed

#####

MODULE STEPPING ANALYSIS

#####

Analysis will be performed from 2011-01-09 00:00:00 to 2011-01-09 23:59:59
 Results will be exported to the directory: ./RESULTS/DAILY/_110109/MODULE_STEPPING

Creating directory ./RESULTS/DAILY/_110109/MODULE_STEPPING...
 Creating directory ./RESULTS/DAILY/_110109/MODULE_STEPPING/FIRST_REFERENCE...
 Creating directory ./RESULTS/DAILY/_110109/MODULE_STEPPING/SECOND_REFERENCE...
 Creating directory ./RESULTS/DAILY/_110109/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE...
 Deleting old files...

Creating images comparing with second reference...

Exporting results to the directory ../../RESULTS/DAILY/_110109/MODULE_STEPPING/SECOND_REFERENCE...

Polarization: H
 Reference product: ASA_MS__0PNPDK20010209_135042_0000009A024_00180_11700_0052.N1
 Test product: ASA_MS__0PNPDK20110109_143213_00000163098_00197_46332_0388.N1

H
 H
 ../../RESULTS/DAILY/_110109/MODULE_STEPPING/SECOND_REFERENCE/TGH_20110109_143213-20010209_135042.png
 ../../RESULTS/DAILY/_110109/MODULE_STEPPING/SECOND_REFERENCE/TPH_20110109_143213-20010209_135042.png
 ../../RESULTS/DAILY/_110109/MODULE_STEPPING/SECOND_REFERENCE/RGH_20110109_143213-20010209_135042.png
 ../../RESULTS/DAILY/_110109/MODULE_STEPPING/SECOND_REFERENCE/RPH_20110109_143213-20010209_135042.png

Polarization: V
 Reference product: ASA_MS__0PNPDK20010209_140823_0000009A024_00180_11700_0054.N1
 Test product: ASA_MS__0PNPDK20110109_161227_00000163098_00198_46333_0389.N1

V
 V
 ../../RESULTS/DAILY/_110109/MODULE_STEPPING/SECOND_REFERENCE/TGV_20110109_161227-20010209_140823.png
 ../../RESULTS/DAILY/_110109/MODULE_STEPPING/SECOND_REFERENCE/TPV_20110109_161227-20010209_140823.png
 ../../RESULTS/DAILY/_110109/MODULE_STEPPING/SECOND_REFERENCE/RGV_20110109_161227-20010209_140823.png
 ../../RESULTS/DAILY/_110109/MODULE_STEPPING/SECOND_REFERENCE/RPV_20110109_161227-20010209_140823.png

Creating images comparing with previous product reference...

Exporting results to the directory ../../RESULTS/DAILY/_110109/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE...

Polarization: H

Reference product: ASA_MS__0PNPDK20110108_150857_000000163098_00183_46318_0386.N1

Test product: ASA_MS__0PNPDK20110109_143213_000000163098_00197_46332_0388.N1

H

H

../../../../RESULTS/DAILY/_110109/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TGH_20110109_143213-20110108_150857.png

../../../../RESULTS/DAILY/_110109/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TPH_20110109_143213-20110108_150857.png

../../../../RESULTS/DAILY/_110109/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RGH_20110109_143213-20110108_150857.png

../../../../RESULTS/DAILY/_110109/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RPH_20110109_143213-20110108_150857.png

Polarization: V

Reference product: ASA_MS__0PNPDK20110108_164911_000000163098_00184_46319_0387.N1

Test product: ASA_MS__0PNPDK20110109_161227_000000163098_00198_46333_0389.N1

V

V

../../../../RESULTS/DAILY/_110109/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TGV_20110109_161227-20110108_164911.png

../../../../RESULTS/DAILY/_110109/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/TPV_20110109_161227-20110108_164911.png

../../../../RESULTS/DAILY/_110109/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RGV_20110109_161227-20110108_164911.png

../../../../RESULTS/DAILY/_110109/MODULE_STEPPING/PREVIOUS_PRODUCT_REFERENCE/RPV_20110109_161227-20110108_164911.png

MODULE_STEPPING ANALYSIS completed

#####

CALIBRATION PULSES ANALYSIS

#####

Creating directory ./RESULTS/DAILY/_110109/CALIBRATION_PULSES...

ALL ROWS Analysis will be performed from 2011-01-09 00:00:00 to 2011-01-09 23:59:59

Analysing products WVS IS2 V/V

Writing image ../../RESULTS/DAILY/_110109//CALIBRATION_PULSES/Calibration_pulses_all_rows_WVS_IS2_VV.png...

Analysing products GM1 SS3 H/H

Writing image ../../RESULTS/DAILY/_110109//CALIBRATION_PULSES/Calibration_pulses_all_rows_GM1_SS3_HH.png...

TEMPORAL EVOLUTION Analysis will be performed from 2011-01-09 00:00:00 to 2011-01-09 23:59:59

Analysing products WVS IS2 V/V

Getting calibration pulses data for WVS IS2 V/V from 2011-01-09 00:00:00 to 2011-01-09 23:59:59. Rows: 1/5/9/13/17/21/25/29

Writing file ./RESULTS/DAILY/_110109/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2011-01-09_1.dat...

Writing ../../RESULTS/DAILY/_110109//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_1.png...

Writing ../../RESULTS/DAILY/_110109//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_1.png...

Getting calibration pulses data for WVS IS2 V/V from 2011-01-09 00:00:00 to 2011-01-09 23:59:59. Rows: 2/6/10/14/18/22/26/30

Writing file ./RESULTS/DAILY/_110109/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2011-01-09_2.dat...

Writing ../../RESULTS/DAILY/_110109//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_2.png...

Writing ../../RESULTS/DAILY/_110109//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_2.png...

Getting calibration pulses data for WVS IS2 V/V from 2011-01-09 00:00:00 to 2011-01-09 23:59:59. Rows: 3/7/11/15/19/23/27/31

Writing file ./RESULTS/DAILY/_110109/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2011-01-09_3.dat...

Writing ../../RESULTS/DAILY/_110109//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_3.png...

Writing ../../RESULTS/DAILY/_110109//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_3.png...

Getting calibration pulses data for WVS IS2 V/V from 2011-01-09 00:00:00 to 2011-01-09 23:59:59. Rows: 4/8/12/16/20/24/28/32

Writing file ./RESULTS/DAILY/_110109/CALIBRATION_PULSES/Calibration_pulses_data_WVS_IS2_VV_2011-01-09_4.dat...

Writing ../../RESULTS/DAILY/_110109//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_WVS_IS2_VV_4.png...

Writing ../../RESULTS/DAILY/_110109//CALIBRATION_PULSES/Transmit_Power_WVS_IS2_VV_4.png...

Analysing products GM1 SS3 H/H
Getting calibration pulses data for GM1 SS3 H/H from 2011-01-09 00:00:00 to 2011-01-09 23:59:59. Rows: 1/5/9/13/17/21/25/29
Writing file ./RESULTS/DAILY/_110109/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2011-01-09_1.dat...
Writing ../../RESULTS/DAILY/_110109//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_1.png...
Writing ../../RESULTS/DAILY/_110109//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_1.png...

Getting calibration pulses data for GM1 SS3 H/H from 2011-01-09 00:00:00 to 2011-01-09 23:59:59. Rows: 2/6/10/14/18/22/26/30
Writing file ./RESULTS/DAILY/_110109/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2011-01-09_2.dat...
Writing ../../RESULTS/DAILY/_110109//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_2.png...
Writing ../../RESULTS/DAILY/_110109//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_2.png...

Getting calibration pulses data for GM1 SS3 H/H from 2011-01-09 00:00:00 to 2011-01-09 23:59:59. Rows: 3/7/11/15/19/23/27/31
Writing file ./RESULTS/DAILY/_110109/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2011-01-09_3.dat...
Writing ../../RESULTS/DAILY/_110109//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_3.png...
Writing ../../RESULTS/DAILY/_110109//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_3.png...

Getting calibration pulses data for GM1 SS3 H/H from 2011-01-09 00:00:00 to 2011-01-09 23:59:59. Rows: 4/8/12/16/20/24/28/32
Writing file ./RESULTS/DAILY/_110109/CALIBRATION_PULSES/Calibration_pulses_data_GM1_SS3_HH_2011-01-09_4.dat...
Writing ../../RESULTS/DAILY/_110109//CALIBRATION_PULSES/Average_P1_P1a_P2_P3_GM1_SS3_HH_4.png...
Writing ../../RESULTS/DAILY/_110109//CALIBRATION_PULSES/Transmit_Power_GM1_SS3_HH_4.png...

CALIBRATION PULSES ANALYSIS completed
#####

DOPPLER ANALYSIS

Creating directory ./RESULTS/DAILY/_110109/DOPPLER...

DOPPLER ANX Analysis will be performed from 2011-01-09 00:00:00 to 2011-01-09 23:59:59

Analysing products WVS IS2 V/V
Getting doppler data for WVS IS2 V/V from 2011-01-09 00:00:00 to 2011-01-09 23:59:59...
Writing file ./RESULTS/DAILY/_110109/DOPPLER/Doppler_data_WVS_IS2_VV_2011-01-09.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/_110109/DOPPLER/DOPPLER_ANX_WVS_IS2_VV.png...

Analysing products GM1 SS1 H/H
Getting doppler data for GM1 SS1 H/H from 2011-01-09 00:00:00 to 2011-01-09 23:59:59...
Writing file ./RESULTS/DAILY/_110109/DOPPLER/Doppler_data_GM1_SS1_HH_2011-01-09.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/_110109/DOPPLER/DOPPLER_ANX_GM1_SS1_HH.png...

DOPPLER JUMPS Analysis will be performed on WSM products from 2011-01-09 00:00:00 to 2011-01-09 23:59:59

Analysing by default products WSM
Getting doppler jumps data for WSM from 2011-01-09 00:00:00 to 2011-01-09 23:59:59...
Writing file ./RESULTS/DAILY/_110109/DOPPLER/Doppler_Jumps_data_WSM_2011-01-09.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/_110109/DOPPLER/DOPPLER_JUMPS_ANX_WSM.png...
Writing file ../../RESULTS/DAILY/_110109/DOPPLER/DOPPLER_JUMPS_Date_WSM.png...

DOPPLER MAP Analysis will be performed from 2011-01-09 00:00:00 to 2011-01-09 23:59:59

Analysing products WVS IS2 V/V

Loading predicted doppler values....

Phase: descending

Found data...

Computing mean error doppler estimated-predicted...

Mean error = -66.368625 Hz

Writing file ../../RESULTS/DAILY/_110109//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_WVS_IS2_VV_desc.jpg...

Writing file ../../RESULTS/DAILY/_110109//DOPPLER/DOPPLER_Absolute_WVS_IS2_VV_desc.jpg...

Loading predicted doppler values....

Phase: ascending

Found data...

Computing mean error doppler estimated-predicted...

Mean error = -58.913364 Hz

Writing file ../../RESULTS/DAILY/_110109//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_WVS_IS2_VV_asc.jpg...

Writing file ../../RESULTS/DAILY/_110109//DOPPLER/DOPPLER_Absolute_WVS_IS2_VV_asc.jpg...

Analysing products GM1 SS1 H/H

Loading predicted doppler values....

Phase: descending

Found data...

Computing mean error doppler estimated-predicted...

Mean error = -53.652631 Hz

Writing file ../../RESULTS/DAILY/_110109//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_GM1_SS1_HH_desc.jpg...

Writing file ../../RESULTS/DAILY/_110109//DOPPLER/DOPPLER_Absolute_GM1_SS1_HH_desc.jpg...

Loading predicted doppler values....

Phase: ascending

Found data...

Computing mean error doppler estimated-predicted...

Mean error = -52.071398 Hz

Writing file ../../RESULTS/DAILY/_110109//DOPPLER/DOPPLER_Estimated-Predicted-MeanError_GM1_SS1_HH_asc.jpg...

Writing file ../../RESULTS/DAILY/_110109//DOPPLER/DOPPLER_Absolute_GM1_SS1_HH_asc.jpg...

DOPPLER ANALYSIS completed

#####

CHIRP ANALYSIS

#####

Creating directory ./RESULTS/DAILY/_110109/CHIRP...

CHIRP Analysis will be performed from 2011-01-09 00:00:00 to 2011-01-09 23:59:59

Analysing products WSM SS1 H/H

Getting ScaleFactor data for WSM SS1 H/H from 2011-01-09 00:00:00 to 2011-01-09 23:59:59...

Writing file ./RESULTS/DAILY/_110109/CHIRP/ScaleFactor_data_WSM_SS1_HH_2011-01-09.dat...

Running IDL program...

Writing file ../../RESULTS/DAILY/_110109/CHIRP/ScaleFactor_ANX_WSM_SS1_HH.png...

Writing file ../../RESULTS/DAILY/_110109/CHIRP/ScaleFactor_DATE_WSM_SS1_HH.png...

Analysing products WSM SS1 V/V

```
*****
Getting ScaleFactor data for WSM SS1 V/V from 2011-01-09 00:00:00 to 2011-01-09 23:59:59...
Writing file ./RESULTS/DAILY/_110109/CHIRP/ScaleFactor_data_WSM_SS1_VV_2011-01-09.dat...
Running IDL program...
Writing file ../../RESULTS/DAILY/_110109/CHIRP/ScaleFactor_ANX_WSM_SS1_VV.png...
Writing file ../../RESULTS/DAILY/_110109/CHIRP/ScaleFactor_DATE_WSM_SS1_VV.png...
```

CHIRP ANALYSIS completed

#####

RAW DATA ANALYSIS

```
#####
Analysis will be performed from 2011-01-09 00:00:00 to 2011-01-09 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_110109/RAW_DATA
```

Creating directory ./RESULTS/DAILY/_110109/RAW_DATA...

```
*****
Getting raw data for WVS from 2011-01-09 00:00:00 to 2011-01-09 23:59:59...
Writing file ./RESULTS/DAILY/_110109/RAW_DATA/Raw_data_WVS_2011-01-09.dat...
Running IDL program to create graphs...
```

```
Creating image ../../RESULTS/DAILY/_110109/RAW_DATA/Raw_data_WVS_input_mean.png...
Creating image ../../RESULTS/DAILY/_110109/RAW_DATA/Raw_data_WVS_input_stdev.png...
Creating image ../../RESULTS/DAILY/_110109/RAW_DATA/Raw_data_WVS_gain_imbalance.png...
```

```
*****
Getting raw data for IMM from 2011-01-09 00:00:00 to 2011-01-09 23:59:59...
Writing file ./RESULTS/DAILY/_110109/RAW_DATA/Raw_data_IMM_2011-01-09.dat...
Running IDL program to create graphs...
```

```
Creating image ../../RESULTS/DAILY/_110109/RAW_DATA/Raw_data_IMM_input_mean.png...
Creating image ../../RESULTS/DAILY/_110109/RAW_DATA/Raw_data_IMM_input_stdev.png...
Creating image ../../RESULTS/DAILY/_110109/RAW_DATA/Raw_data_IMM_gain_imbalance.png...
```

RAW DATA ANALYSIS completed

#####

TELEMETRY ANALYSIS

```
#####
Analysis will be performed from 2011-01-09 00:00:00 to 2011-01-09 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/_110109/TELEMETRY
```

Creating directory ./RESULTS/DAILY/_110109/TELEMETRY...

```
Looking for gaps and missing lines in WVS products...
*****
Checking 25 products from PDE...
Checking 26 products from PDK...
```

```
Looking for gaps and missing lines in GM1 products...
*****
Checking 25 products from PDE...
Checking 44 products from PDK...
```

```
Looking for gaps and missing lines in APM products...
*****
Checking 2 products from PDE...
No products from PDK...
```


Looking for gaps and missing lines in IMM products...

Checking 4 products from PDE...

Checking 1 products from PDK...

Looking for gaps and missing lines in WSM products...

Checking 28 products from PDE...

Found product...ASA_WSM_1PNPDE20110109_122151_000001533098_00196_46331_0756.N1 / 0 gaps / 1 missing lines

Checking 10 products from PDK...

Creating graph of missing lines and gaps...

Creating image: ./RESULTS/DAILY/_110109/TELEMETRY/TELEMETRY_Missing_lines.png...

Creating image: ./RESULTS/DAILY/_110109/TELEMETRY/TELEMETRY_Gaps.png...

TELEMETRY ANALYSIS completed

#####

HTML REPORT generation

#####

Building file ./RESULTS/DAILY/_110109/asarReport.html...

Building DATA SUMMARY section...

Building AUXILIARY FILES ANALYSIS section...

Building MODULE STEPPING ANALYSIS section...

Building CALIBRATION PULSES ANALYSIS section...

Building DOPPLER ANALYSIS section...

Building CHIRP ANALYSIS section...

Building RAW DATA ANALYSIS section...

Building TELEMETRY ANALYSIS section...

HTML REPORT generation completed

#####



Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
ASA_APM_1PNPDE20110109_073414_000001383098_00193_46328_0727.N1	OK	OK	OK	OK
ASA_APM_1PNPDE20110109_141657_000000433098_00197_46332_0757.N1	OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_GM1_1PNPDE20110109_002732_000005673098_00189_46324_0645.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110109_005333_000005793098_00189_46324_0642.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110109_011150_000005013098_00189_46324_0656.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110109_013618_000005193098_00189_46324_0677.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110109_015608_000001993098_00190_46325_0676.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110109_020602_000002953098_00190_46325_0675.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110109_021415_000004713098_00190_46325_0674.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110109_022419_000001443098_00190_46325_0672.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110109_023245_000001873098_00190_46325_0670.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110109_025205_000003983098_00190_46325_0685.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110109_031048_000002053098_00190_46325_0683.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110109_031415_000006953098_00190_46325_0687.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110109_033027_000008163098_00191_46326_0688.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110109_034508_000010153098_00191_46326_0693.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110109_043220_000002893098_00191_46326_0706.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110109_050850_000018793098_00192_46327_0710.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110109_202505_00000903098_00201_46336_0769.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110109_203018_000005733098_00201_46336_0770.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110109_213658_000002893098_00201_46336_0787.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110109_214713_000004533098_00202_46337_0786.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110109_220658_000000843098_00202_46337_0785.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110109_221106_000002473098_00202_46337_0790.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110109_225458_000004713098_00202_46337_0795.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110109_234620_000001083098_00203_46338_0835.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110109_235220_000005983098_00203_46338_0842.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110109_061235_000003083098_00192_46327_6012.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110109_070051_000006953098_00193_46328_6018.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110109_071111_000005433098_00193_46328_6060.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110109_072457_000005553098_00193_46328_6061.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110109_073655_000003563098_00193_46328_6062.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110109_075249_000007793098_00193_46328_6064.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110109_084217_000005253098_00194_46329_6066.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110109_090025_000002113098_00194_46329_6103.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110109_094100_000003023098_00194_46329_6105.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110109_102126_000005613098_00195_46330_6106.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110109_103423_000000783098_00195_46330_6127.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110109_104526_000000663098_00195_46330_6128.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110109_104913_000001873098_00195_46330_6129.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110109_111318_000004533098_00195_46330_6131.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110109_120051_000006283098_00196_46331_6133.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110109_121011_000000663098_00196_46331_6157.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110109_124021_000002593098_00196_46331_6159.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110109_125331_000007793098_00196_46331_6161.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110109_131351_000001023098_00196_46331_6162.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110109_131540_000005673098_00196_46331_6165.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110109_133433_000009183098_00197_46332_6178.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110109_134841_000001323098_00197_46332_6207.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110109_135521_000002353098_00197_46332_6208.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110109_141217_000002773098_00197_46332_6209.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110109_141802_000002173098_00197_46332_6211.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110109_143345_000007793098_00197_46332_6214.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110109_145516_000002233098_00197_46332_6215.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110109_150238_000001873098_00197_46332_6216.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110109_151230_000010333098_00198_46333_6217.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110109_152841_000001083098_00198_46333_6259.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110109_154144_000003383098_00198_46333_6261.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110109_154930_000001383098_00198_46333_6262.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110109_161402_000005983098_00198_46333_6264.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110109_164803_000010393098_00199_46334_6268.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110109_170803_000001933098_00199_46334_6289.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110109_171259_000000783098_00199_46334_6288.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110109_171524_000007793098_00199_46334_6290.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110109_175414_000005553098_00199_46334_6293.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110109_183009_000004473098_00200_46335_6294.N1					OK	OK	OK	OK

ASA_GM1_1PNPDK20110109_183912_000001993098_00200_46335_6296.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20110109_184626_000007553098_00200_46335_6318.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20110109_193428_000006103098_00200_46335_6320.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20110109_200313_000006953098_00200_46335_6321.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20110109_201724_000001633098_00201_46336_6323.N1	OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
ASA_IMM_1PNPDE20110109_040203_000003143098_00191_46326_0681.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20110109_054010_000003843098_00192_46327_0703.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20110109_072014_000002733098_00193_46328_0726.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20110109_200115_000001083098_00200_46335_0767.N1	OK	OK	OK	OK
ASA_IMM_1PNPDK20110109_184310_000000103098_00200_46335_6292.N1	OK	OK	OK	OK


Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WSM_1PNPDE20110109_001151_000001533098_00189_46324_0639.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110109_001856_000005143098_00189_46324_0648.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110109_001856_000005143098_00189_46324_0649.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110109_012014_000004533098_00189_46324_0644.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110109_015928_000003923098_00190_46325_0661.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110109_015928_000003923098_00190_46325_0662.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110109_021059_000001903098_00190_46325_0678.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110109_025849_000005143098_00190_46325_0680.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110109_043711_000005753098_00191_46326_0702.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110109_074256_000002143098_00193_46328_0728.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110109_122151_000001533098_00196_46331_0756.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110109_123315_000004223098_00196_46331_0755.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110109_153336_000001533098_00198_46333_0759.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110109_153644_000002943098_00198_46333_0760.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110109_162406_000002513098_00198_46333_0758.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110109_180333_000002693098_00199_46334_0761.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110109_183737_000000923098_00200_46335_0763.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110109_185906_000003003098_00200_46335_0766.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110109_194442_000002143098_00200_46335_0764.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110109_194933_000002143098_00200_46335_0765.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110109_212933_000002753098_00201_46336_0772.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110109_215751_000002143098_00202_46337_0782.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110109_220828_000001533098_00202_46337_0789.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110109_221519_000001903098_00202_46337_0791.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110109_230254_000002813098_00202_46337_0783.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110109_233451_000002083098_00203_46338_0803.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110109_234243_000002083098_00203_46338_0857.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110109_234818_000002323098_00203_46338_0839.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20110109_061749_000004343098_00192_46327_6025.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20110109_065816_000001533098_00193_46328_6026.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20110109_085105_000005443098_00194_46329_6075.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20110109_103048_000002083098_00195_46330_6114.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20110109_103551_000003433098_00195_46330_6115.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20110109_130658_000002513098_00196_46331_6239.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20110109_135101_000002513098_00197_46332_6182.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20110109_135101_000002513098_00197_46332_6183.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20110109_153035_000001533098_00198_46333_6232.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20110109_184351_000001533098_00200_46335_6299.N1					OK	OK	OK	OK





Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WVS_1PNPDE20110109_001421_000002403098_00189_46324_0646.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110109_003701_000009463098_00189_46324_0643.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110109_010315_000004803098_00189_46324_0658.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110109_012746_000001643098_00189_46324_0657.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110109_012946_000003453098_00189_46324_0660.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110109_014500_000006293098_00190_46325_0673.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110109_022757_000002393098_00190_46325_0671.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110109_023554_000004193098_00190_46325_0669.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110109_024239_000005253098_00190_46325_0684.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110109_030721_000001653098_00190_46325_0686.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110109_032554_000002243098_00191_46326_0689.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110109_040817_000010343098_00191_46326_0692.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110109_042502_000000603098_00191_46326_0704.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110109_042906_000001503098_00191_46326_0705.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110109_044644_000012743098_00191_46326_0707.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110109_054703_000010793098_00192_46327_0709.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110109_203955_000020393098_00201_46336_0771.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110109_212801_000000453098_00201_46336_0773.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110109_213405_000001353098_00201_46336_0788.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110109_214150_000002843098_00201_46336_0784.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110109_221836_000021293098_00202_46337_0794.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110109_230747_000005253098_00202_46337_0793.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110109_231532_000011243098_00202_46337_0838.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110109_233821_000002253098_00203_46338_0843.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110109_060448_000004203098_00192_46327_6006.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110109_062526_000019343098_00192_46327_6017.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110109_074627_000003453098_00193_46328_6063.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110109_080550_000021443098_00193_46328_6065.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110109_091447_000010193098_00194_46329_6104.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110109_094603_000020843098_00194_46329_6107.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110109_105224_000012143098_00195_46330_6130.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110109_112608_000020393098_00195_46330_6132.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110109_121654_000002553098_00196_46331_6156.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110109_122421_000004943098_00196_46331_6158.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110109_124441_000004803098_00196_46331_6160.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110109_131108_000001203098_00196_46331_6163.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110109_132509_000002993098_00197_46332_6164.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110109_133115_000001493098_00197_46332_6166.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110109_135915_000007343098_00197_46332_6210.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110109_142143_000005853098_00197_46332_6212.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110109_144645_000004653098_00197_46332_6213.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110109_145902_000001643098_00197_46332_6218.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110109_154722_000000893098_00198_46333_6260.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110109_155156_000011843098_00198_46333_6263.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110109_162823_000011393098_00198_46333_6265.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110109_162823_000011393098_00198_46333_6267.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110109_172826_000014993098_00199_46334_6291.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110109_181223_000010193098_00199_46334_6295.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110109_190405_000017843098_00200_46335_6319.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110109_195304_000004043098_00200_46335_6322.N1					OK	OK	OK	OK


Calibration pulses for GM1 SS3 H/H







Calibration pulses for GM1 SS3 H/H



Calibration pulses for GM1 SS3 H/H




Calibration pulses for GM1 SS3 H/H




rows: 4 8 12 16 20 24 28 32


Calibration pulses for WVS IS2 V/V




Calibration pulses for WVS IS2 V/V





Calibration pulses for WVS IS2 V/V







Calibration pulses for WVS IS2 V/V



















09-Jan
rows: _ 2 _ 6 _ 10 _ 14 _ 18 _ 22 _ 26 _ 30










rows: - 1 - 5 - 9 - 13 - 17 - 21 - 25 - 29








rows: - 3 - 7 - 11 - 15 - 19 - 23 - 27 - 31




rows: - 4 - 8 - 12 - 16 - 20 - 24 - 28 - 32









Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion				
ASA_APM_1PNPDE20110109_073414_000001383098_00193_46328_0727.N1						IS4 V/H 98	46328	193	5.04	
ASA_APM_1PNPDE20110109_141657_000000433098_00197_46332_0757.N1						IS6 V/H 98	46332	197	5.04	

Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_GM1_1PNPDE20110109_002732_000005673098_00189_46324_0645.N1						SS1	H/H	98	46324	189	5.04
ASA_GM1_1PNPDE20110109_005333_000005793098_00189_46324_0642.N1						SS1	H/H	98	46324	189	5.04
ASA_GM1_1PNPDE20110109_011150_000005013098_00189_46324_0656.N1						SS1	H/H	98	46324	189	5.04
ASA_GM1_1PNPDE20110109_013618_000005193098_00189_46324_0677.N1						SS1	H/H	98	46324	189	5.04
ASA_GM1_1PNPDE20110109_015608_000001993098_00190_46325_0676.N1						SS1	H/H	98	46325	190	5.04
ASA_GM1_1PNPDE20110109_020602_000002953098_00190_46325_0675.N1						SS1	H/H	98	46325	190	5.04
ASA_GM1_1PNPDE20110109_021415_000004713098_00190_46325_0674.N1						SS1	H/H	98	46325	190	5.04
ASA_GM1_1PNPDE20110109_022419_000001443098_00190_46325_0672.N1						SS1	H/H	98	46325	190	5.04
ASA_GM1_1PNPDE20110109_023245_000001873098_00190_46325_0670.N1						SS1	H/H	98	46325	190	5.04
ASA_GM1_1PNPDE20110109_025205_000003983098_00190_46325_0685.N1						SS1	H/H	98	46325	190	5.04
ASA_GM1_1PNPDE20110109_031048_000002053098_00190_46325_0683.N1						SS1	H/H	98	46325	190	5.04
ASA_GM1_1PNPDE20110109_031415_000006953098_00190_46325_0687.N1						SS1	H/H	98	46325	190	5.04
ASA_GM1_1PNPDE20110109_033027_000008163098_00191_46326_0688.N1						SS1	H/H	98	46326	191	5.04
ASA_GM1_1PNPDE20110109_034508_000010153098_00191_46326_0693.N1						SS1	H/H	98	46326	191	5.04
ASA_GM1_1PNPDE20110109_043220_000002893098_00191_46326_0706.N1						SS1	H/H	98	46326	191	5.04
ASA_GM1_1PNPDE20110109_050850_000018793098_00192_46327_0710.N1						SS1	H/H	98	46327	192	5.04
ASA_GM1_1PNPDK20110109_061235_000003083098_00192_46327_6012.N1						SS1	H/H	98	46327	192	5.04
ASA_GM1_1PNPDK20110109_070051_000006953098_00193_46328_6018.N1						SS1	H/H	98	46328	193	5.04
ASA_GM1_1PNPDK20110109_071111_000005433098_00193_46328_6060.N1						SS1	H/H	98	46328	193	5.04
ASA_GM1_1PNPDK20110109_072457_000005553098_00193_46328_6061.N1						SS1	H/H	98	46328	193	5.04
ASA_GM1_1PNPDK20110109_073655_000003563098_00193_46328_6062.N1						SS1	H/H	98	46328	193	5.04
ASA_GM1_1PNPDK20110109_075249_000007793098_00193_46328_6064.N1						SS1	H/H	98	46328	193	5.04
ASA_GM1_1PNPDK20110109_084217_000005253098_00194_46329_6066.N1						SS1	H/H	98	46329	194	5.04
ASA_GM1_1PNPDK20110109_090025_000002113098_00194_46329_6103.N1						SS1	H/H	98	46329	194	5.04
ASA_GM1_1PNPDK20110109_094100_000003023098_00194_46329_6105.N1						SS1	H/H	98	46329	194	5.04
ASA_GM1_1PNPDK20110109_102126_000005613098_00195_46330_6106.N1						SS1	H/H	98	46330	195	5.04
ASA_GM1_1PNPDK20110109_103423_000000783098_00195_46330_6127.N1						SS1	H/H	98	46330	195	5.04
ASA_GM1_1PNPDK20110109_104526_000000663098_00195_46330_6128.N1						SS1	H/H	98	46330	195	5.04
ASA_GM1_1PNPDK20110109_104913_000001873098_00195_46330_6129.N1						SS1	H/H	98	46330	195	5.04
ASA_GM1_1PNPDK20110109_111318_000004533098_00195_46330_6131.N1						SS1	H/H	98	46330	195	5.04
ASA_GM1_1PNPDK20110109_120051_000006283098_00196_46331_6133.N1						SS1	H/H	98	46331	196	5.04
ASA_GM1_1PNPDK20110109_121011_000000663098_00196_46331_6157.N1						SS1	H/H	98	46331	196	5.04
ASA_GM1_1PNPDK20110109_124021_000002593098_00196_46331_6159.N1						SS1	H/H	98	46331	196	5.04
ASA_GM1_1PNPDK20110109_125331_000007793098_00196_46331_6161.N1						SS1	H/H	98	46331	196	5.04
ASA_GM1_1PNPDK20110109_131351_000001023098_00196_46331_6162.N1						SS1	H/H	98	46331	196	5.04
ASA_GM1_1PNPDK20110109_131540_000005673098_00196_46331_6165.N1						SS1	H/H	98	46331	196	5.04
ASA_GM1_1PNPDK20110109_133433_000009183098_00197_46332_6178.N1						SS1	H/H	98	46332	197	5.04
ASA_GM1_1PNPDK20110109_134841_000001323098_00197_46332_6207.N1						SS1	H/H	98	46332	197	5.04
ASA_GM1_1PNPDK20110109_135521_000002353098_00197_46332_6208.N1						SS1	H/H	98	46332	197	5.04
ASA_GM1_1PNPDK20110109_141217_000002773098_00197_46332_6209.N1						SS1	H/H	98	46332	197	5.04
ASA_GM1_1PNPDK20110109_141802_000002173098_00197_46332_6211.N1						SS1	H/H	98	46332	197	5.04
ASA_GM1_1PNPDK20110109_143345_000007793098_00197_46332_6214.N1						SS1	H/H	98	46332	197	5.04
ASA_GM1_1PNPDK20110109_145516_000002233098_00197_46332_6215.N1						SS1	H/H	98	46332	197	5.04
ASA_GM1_1PNPDK20110109_150238_000001873098_00197_46332_6216.N1						SS1	H/H	98	46332	197	5.04
ASA_GM1_1PNPDK20110109_151230_000010333098_00198_46333_6217.N1						SS1	H/H	98	46333	198	5.04
ASA_GM1_1PNPDK20110109_152841_000001083098_00198_46333_6259.N1						SS1	H/H	98	46333	198	5.04
ASA_GM1_1PNPDK20110109_154144_000003383098_00198_46333_6261.N1						SS1	H/H	98	46333	198	5.04
ASA_GM1_1PNPDK20110109_154930_000001383098_00198_46333_6262.N1						SS1	H/H	98	46333	198	5.04
ASA_GM1_1PNPDK20110109_161402_000005983098_00198_46333_6264.N1						SS1	H/H	98	46333	198	5.04
ASA_GM1_1PNPDK20110109_164803_000010393098_00199_46334_6268.N1						SS1	H/H	98	46334	199	5.04
ASA_GM1_1PNPDK20110109_170803_000001933098_00199_46334_6289.N1						SS1	H/H	98	46334	199	5.04
ASA_GM1_1PNPDK20110109_171259_000000783098_00199_46334_6288.N1						SS1	H/H	98	46334	199	5.04
ASA_GM1_1PNPDK20110109_171524_000007793098_00199_46334_6290.N1						SS1	H/H	98	46334	199	5.04
ASA_GM1_1PNPDK20110109_175414_000005553098_00199_46334_6293.N1						SS1	H/H	98	46334	199	5.04
ASA_GM1_1PNPDK20110109_183009_000004473098_00200_46335_6294.N1						SS1	H/H	98	46335	200	5.04
ASA_GM1_1PNPDK20110109_183912_000001993098_00200_46335_6296.N1						SS1	H/H	98	46335	200	5.04
ASA_GM1_1PNPDK20110109_184626_000007553098_00200_46335_6318.N1						SS1	H/H	98	46335	200	5.04
ASA_GM1_1PNPDK20110109_193428_000006103098_00200_46335_6320.N1						SS1	H/H	98	46335	200	5.04
ASA_GM1_1PNPDK20110109_200313_000006953098_00200_46335_6321.N1						SS1	H/H	98	46335	200	5.04
ASA_GM1_1PNPDK20110109_201724_000001633098_00201_46336_6323.N1						SS1	H/H	98	46336	201	5.04
ASA_GM1_1PNPDE20110109_202505_000000903098_00201_46336_0769.N1						SS1	H/H	98	46336	201	5.04
ASA_GM1_1PNPDE20110109_203018_000005733098_00201_46336_0770.N1						SS1	H/H	98	46336	201	5.04
ASA_GM1_1PNPDE20110109_213658_000002893098_00201_46336_0787.N1						SS1	H/H	98	46336	201	5.04
ASA_GM1_1PNPDE20110109_214713_000004533098_00202_46337_0786.N1						SS1	H/H	98	46337	202	5.04
ASA_GM1_1PNPDE20110109_220658_000000843098_00202_46337_0785.N1						SS1	H/H	98	46337	202	5.04
ASA_GM1_1PNPDE20110109_221106_000002473098_00202_46337_0790.N1						SS1	H/H	98	46337	202	5.04
ASA_GM1_1PNPDE20110109_225458_000004713098_00202_46337_0795.N1						SS1	H/H	98	46337	202	5.04

ASA_GM1_1PNPDE20110109_234620_000001083098_00203_46338_0835.N1	SS1	H/H	98	46338	203	5.04
ASA_GM1_1PNPDE20110109_235220_000005983098_00203_46338_0842.N1	SS1	H/H	98	46338	203	5.04





Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_IMM_1PNPDE20110109_040203_000003143098_00191_46326_0681.N1						IS6	H/H	98	46326	191	5.04
ASA_IMM_1PNPDE20110109_054010_000003843098_00192_46327_0703.N1						IS6	H/H	98	46327	192	5.04
ASA_IMM_1PNPDE20110109_072014_000002733098_00193_46328_0726.N1						IS6	H/H	98	46328	193	5.04
ASA_IMM_1PNPDK20110109_184310_000000103098_00200_46335_6292.N1						IS6	***	98	46335	200	5.04
ASA_IMM_1PNPDE20110109_200115_000001083098_00200_46335_0767.N1						IS2	H/H	98	46335	200	5.04


Filename	Pol	Timestamp	count(Module)				
ASA_MS__0PNPDK20110109_143213_000000163098_00197_46332_0388.N1	H	2011-01-09 14:32:13	320				
ASA_MS__0PNPDK20110109_161227_000000163098_00198_46333_0389.N1	V	2011-01-09 16:12:27	320				


Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WSM_1PNPDE20110109_001151_000001533098_00189_46324_0639.N1						SS1	V/V	98	46324	189	5.04
ASA_WSM_1PNPDE20110109_001856_000005143098_00189_46324_0648.N1						SS1	H/H	98	46324	189	5.04
ASA_WSM_1PNPDE20110109_001856_000005143098_00189_46324_0649.N1						SS1	H/H	98	46324	189	5.04
ASA_WSM_1PNPDE20110109_012014_000004533098_00189_46324_0644.N1						SS1	H/H	98	46324	189	5.04
ASA_WSM_1PNPDE20110109_015928_000003923098_00190_46325_0662.N1						SS1	H/H	98	46325	190	5.04
ASA_WSM_1PNPDE20110109_015928_000003923098_00190_46325_0661.N1						SS1	H/H	98	46325	190	5.04
ASA_WSM_1PNPDE20110109_021059_000001903098_00190_46325_0678.N1						SS1	V/V	98	46325	190	5.04
ASA_WSM_1PNPDE20110109_025849_000005143098_00190_46325_0680.N1						SS1	H/H	98	46325	190	5.04
ASA_WSM_1PNPDE20110109_043711_000005753098_00191_46326_0702.N1						SS1	H/H	98	46326	191	5.04
ASA_WSM_1PNPDK20110109_061749_000004343098_00192_46327_6025.N1						SS1	H/H	98	46327	192	5.04
ASA_WSM_1PNPDK20110109_065816_000001533098_00193_46328_6026.N1						SS1	V/V	98	46328	193	5.04
ASA_WSM_1PNPDE20110109_074256_000002143098_00193_46328_0728.N1						SS1	V/V	98	46328	193	5.04
ASA_WSM_1PNPDK20110109_085105_000005443098_00194_46329_6075.N1						SS1	H/H	98	46329	194	5.04
ASA_WSM_1PNPDK20110109_103048_000002083098_00195_46330_6114.N1						SS1	H/H	98	46330	195	5.04
ASA_WSM_1PNPDK20110109_103551_000003433098_00195_46330_6115.N1						SS1	V/V	98	46330	195	5.04
ASA_WSM_1PNPDE20110109_122151_000001533098_00196_46331_0756.N1						SS1	V/V	98	46331	196	5.04
ASA_WSM_1PNPDE20110109_123315_000004223098_00196_46331_0755.N1						SS1	V/V	98	46331	196	5.04
ASA_WSM_1PNPDK20110109_130658_000002513098_00196_46331_6239.N1						SS1	H/H	98	46331	196	5.04
ASA_WSM_1PNPDK20110109_135101_000002513098_00197_46332_6182.N1						SS1	H/H	98	46332	197	5.04
ASA_WSM_1PNPDK20110109_135101_000002513098_00197_46332_6183.N1						SS1	H/H	98	46332	197	5.04
ASA_WSM_1PNPDK20110109_153035_000001533098_00198_46333_6232.N1						SS1	H/H	98	46333	198	5.04
ASA_WSM_1PNPDE20110109_153336_000001533098_00198_46333_0759.N1						SS1	H/H	98	46333	198	5.04
ASA_WSM_1PNPDE20110109_153644_000002943098_00198_46333_0760.N1						SS1	V/V	98	46333	198	5.04
ASA_WSM_1PNPDE20110109_162406_000002513098_00198_46333_0758.N1						SS1	H/H	98	46333	198	5.04
ASA_WSM_1PNPDE20110109_180333_000002693098_00199_46334_0761.N1						SS1	H/H	98	46334	199	5.04
ASA_WSM_1PNPDE20110109_183737_000000923098_00200_46335_0763.N1						SS1	H/H	98	46335	200	5.04
ASA_WSM_1PNPDK20110109_184351_000001533098_00200_46335_6299.N1						SS1	V/V	98	46335	200	5.04
ASA_WSM_1PNPDE20110109_185906_000003003098_00200_46335_0766.N1						SS1	V/V	98	46335	200	5.04
ASA_WSM_1PNPDE20110109_194442_000002143098_00200_46335_0764.N1						SS1	H/H	98	46335	200	5.04
ASA_WSM_1PNPDE20110109_194933_000002143098_00200_46335_0765.N1						SS1	H/H	98	46335	200	5.04
ASA_WSM_1PNPDE20110109_212933_000002753098_00201_46336_0772.N1						SS1	H/H	98	46336	201	5.04
ASA_WSM_1PNPDE20110109_215751_000002143098_00202_46337_0782.N1						SS1	V/V	98	46337	202	5.04
ASA_WSM_1PNPDE20110109_220828_000001533098_00202_46337_0789.N1						SS1	H/H	98	46337	202	5.04
ASA_WSM_1PNPDE20110109_221519_000001903098_00202_46337_0791.N1						SS1	V/V	98	46337	202	5.04
ASA_WSM_1PNPDE20110109_230254_000002813098_00202_46337_0783.N1						SS1	H/H	98	46337	202	5.04
ASA_WSM_1PNPDE20110109_233451_000002083098_00203_46338_0803.N1						SS1	V/V	98	46338	203	5.04
ASA_WSM_1PNPDE20110109_234243_000002083098_00203_46338_0857.N1						SS1	H/H	98	46338	203	5.04
ASA_WSM_1PNPDE20110109_234818_000002323098_00203_46338_0839.N1						SS1	H/H	98	46338	203	5.04




Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WVS_1PNPDE20110108_235215_000011393098_00188_46323_0647.N1						IS2	V/V	98	46323	188	5.04
ASA_WVS_1PNPDE20110109_001421_000002403098_00189_46324_0646.N1						IS2	V/V	98	46324	189	5.04
ASA_WVS_1PNPDE20110109_003701_000009463098_00189_46324_0643.N1						IS2	V/V	98	46324	189	5.04
ASA_WVS_1PNPDE20110109_010315_000004803098_00189_46324_0658.N1						IS2	V/V	98	46324	189	5.04
ASA_WVS_1PNPDE20110109_012746_000001643098_00189_46324_0657.N1						IS2	V/V	98	46324	189	5.04
ASA_WVS_1PNPDE20110109_012946_000003453098_00189_46324_0660.N1						IS2	V/V	98	46324	189	5.04
ASA_WVS_1PNPDE20110109_012746_000001643098_00189_46324_0657.N1						IS1	V/V	98	46324	189	5.04
ASA_WVS_1PNPDE20110109_014500_000006293098_00190_46325_0673.N1						IS2	V/V	98	46325	190	5.04
ASA_WVS_1PNPDE20110109_022757_000002393098_00190_46325_0671.N1						IS2	V/V	98	46325	190	5.04
ASA_WVS_1PNPDE20110109_023554_000004193098_00190_46325_0669.N1						IS2	V/V	98	46325	190	5.04
ASA_WVS_1PNPDE20110109_024239_000005253098_00190_46325_0684.N1						IS2	V/V	98	46325	190	5.04
ASA_WVS_1PNPDE20110109_030721_000001653098_00190_46325_0686.N1						IS2	V/V	98	46325	190	5.04
ASA_WVS_1PNPDE20110109_032554_000002243098_00191_46326_0689.N1						IS2	V/V	98	46326	191	5.04
ASA_WVS_1PNPDE20110109_040817_000010343098_00191_46326_0692.N1						IS2	V/V	98	46326	191	5.04
ASA_WVS_1PNPDE20110109_042502_00000603098_00191_46326_0704.N1						IS2	V/V	98	46326	191	5.04
ASA_WVS_1PNPDE20110109_040817_000010343098_00191_46326_0692.N1						IS1	V/V	98	46326	191	5.04
ASA_WVS_1PNPDE20110109_042906_000001503098_00191_46326_0705.N1						IS2	V/V	98	46326	191	5.04
ASA_WVS_1PNPDE20110109_044644_000012743098_00191_46326_0707.N1						IS2	V/V	98	46326	191	5.04
ASA_WVS_1PNPDE20110109_054703_000010793098_00192_46327_0709.N1						IS2	V/V	98	46327	192	5.04
ASA_WVS_1PNPDK20110109_060448_000004203098_00192_46327_6006.N1						IS2	V/V	98	46327	192	5.04
ASA_WVS_1PNPDK20110109_062526_000019343098_00192_46327_6017.N1						IS2	V/V	98	46327	192	5.04
ASA_WVS_1PNPDK20110109_074627_000003453098_00193_46328_6063.N1						IS2	V/V	98	46328	193	5.04
ASA_WVS_1PNPDK20110109_080550_000021443098_00193_46328_6065.N1						IS2	V/V	98	46328	193	5.04
ASA_WVS_1PNPDK20110109_091447_000010193098_00194_46329_6104.N1						IS2	V/V	98	46329	194	5.04
ASA_WVS_1PNPDK20110109_094603_000020843098_00194_46329_6107.N1						IS2	V/V	98	46329	194	5.04
ASA_WVS_1PNPDK20110109_105224_000012143098_00195_46330_6130.N1						IS2	V/V	98	46330	195	5.04
ASA_WVS_1PNPDK20110109_112608_000020393098_00195_46330_6132.N1						IS2	V/V	98	46330	195	5.04
ASA_WVS_1PNPDK20110109_121654_000002553098_00196_46331_6156.N1						IS2	V/V	98	46331	196	5.04
ASA_WVS_1PNPDK20110109_122421_000004943098_00196_46331_6158.N1						IS2	V/V	98	46331	196	5.04
ASA_WVS_1PNPDK20110109_124441_000004803098_00196_46331_6160.N1						IS2	V/V	98	46331	196	5.04
ASA_WVS_1PNPDK20110109_131108_000001203098_00196_46331_6163.N1						IS2	V/V	98	46331	196	5.04
ASA_WVS_1PNPDK20110109_132509_000002993098_00197_46332_6164.N1						IS2	V/V	98	46332	197	5.04
ASA_WVS_1PNPDK20110109_133115_000001493098_00197_46332_6166.N1						IS2	V/V	98	46332	197	5.04
ASA_WVS_1PNPDK20110109_135915_000007343098_00197_46332_6210.N1						IS2	V/V	98	46332	197	5.04
ASA_WVS_1PNPDK20110109_142143_000005853098_00197_46332_6212.N1						IS2	V/V	98	46332	197	5.04
ASA_WVS_1PNPDK20110109_144645_000004653098_00197_46332_6213.N1						IS2	V/V	98	46332	197	5.04
ASA_WVS_1PNPDK20110109_145902_000001643098_00197_46332_6218.N1						IS2	V/V	98	46332	197	5.04
ASA_WVS_1PNPDK20110109_154722_00000893098_00198_46333_6260.N1						IS2	V/V	98	46333	198	5.04
ASA_WVS_1PNPDK20110109_155156_000011843098_00198_46333_6263.N1						IS2	V/V	98	46333	198	5.04
ASA_WVS_1PNPDK20110109_162823_000011393098_00198_46333_6265.N1						IS2	V/V	98	46333	198	5.04
ASA_WVS_1PNPDK20110109_162823_000011393098_00198_46333_6267.N1						IS2	V/V	98	46333	198	5.04
ASA_WVS_1PNPDK20110109_172826_000014993098_00199_46334_6291.N1						IS2	V/V	98	46334	199	5.04
ASA_WVS_1PNPDK20110109_181223_000010193098_00199_46334_6295.N1						IS2	V/V	98	46334	199	5.04
ASA_WVS_1PNPDK20110109_190405_000017843098_00200_46335_6319.N1						IS2	V/V	98	46335	200	5.04
ASA_WVS_1PNPDK20110109_195304_000004043098_00200_46335_6322.N1						IS2	V/V	98	46335	200	5.04
ASA_WVS_1PNPDE20110109_203955_000020393098_00201_46336_0771.N1						IS2	V/V	98	46336	201	5.04
ASA_WVS_1PNPDE20110109_212801_00000453098_00201_46336_0773.N1						IS2	V/V	98	46336	201	5.04
ASA_WVS_1PNPDE20110109_213405_000001353098_00201_46336_0788.N1						IS2	V/V	98	46336	201	5.04
ASA_WVS_1PNPDE20110109_214150_000002843098_00201_46336_0784.N1						IS2	V/V	98	46336	201	5.04
ASA_WVS_1PNPDE20110109_221836_000021293098_00202_46337_0794.N1						IS2	V/V	98	46337	202	5.04
ASA_WVS_1PNPDE20110109_230747_000005253098_00202_46337_0793.N1						IS2	V/V	98	46337	202	5.04
ASA_WVS_1PNPDE20110109_231532_000011243098_00202_46337_0838.N1						IS2	V/V	98	46337	202	5.04
ASA_WVS_1PNPDE20110109_233821_000002253098_00203_46338_0843.N1						IS2	V/V	98	46338	203	5.04
















































09-Jan





09-Jan




09-Jan









09-Jan




09-Jan




09-Jan



09-Jan



09-Jan



09-Jan

