



Analysis from 26-JUN-2011 00:00:00 to 26-JUN-2011 23:59:59. Page generated on 27-JUN-2011 12:15:59.  
View log file: ASAR\_Daily\_Report\_20110627\_1215.log. For any anomalies please contact [emma.griffiths@vegaspace.com](mailto:emma.griffiths@vegaspace.com), [kajal.haria@vegaspace.com](mailto:kajal.haria@vegaspace.com).

This report is automatically generated every day, every 2 hours. No comments are provided on the results.

## SUMMARY

1. DATA SUMMARY
  - 1.1 Summary tables
  - 1.2 Lists of products used
2. AUXILIARY FILES ANALYSIS
  - 2.1 IECF operational ADFs list
  - 2.2 Products with wrong ADFs
3. MODULE STEPPING PRODUCTS ANALYSIS
  - 3.1 V/V polarisation
  - 3.2 H/H polarisation
4. CALIBRATION PULSES ANALYSIS
  - 4.1 Analysis for WVS IS2 V/V
    - 4.1.1 Temporal Evolution Analysis for WVS IS2 V/V
    - 4.1.2 All Rows Analysis for WVS IS2 V/V
  - 4.2 Analysis for GM1 SS3 H/H
    - 4.2.1 Temporal Evolution Analysis for GM1 SS3 H/H
    - 4.2.2 All Rows Analysis for GM1 SS3 H/H
5. DOPPLER ANALYSIS
  - 5.1 Analysis for WVS IS2 V/V
    - 5.1.1 Doppler MAP Analysis for WVS IS2 V/V
    - 5.1.2 Doppler ANX Analysis for WVS IS2 V/V
  - 5.2 Analysis for GM1 SS1 H/H
    - 5.2.1 Doppler MAP Analysis for GM1 SS1 H/H
    - 5.2.2 Doppler ANX Analysis for GM1 SS1 H/H
  - 5.3 Doppler JUMPS Analysis for WSM
6. CHIRP ANALYSIS
  - 6.1 Analysis for WSM SS1 H/H
    - 6.1.1 ScaleFactor
  - 6.2 Analysis for WSM SS1 V/V
    - 6.2.1 ScaleFactor
7. RAW DATA ANALYSIS
  - 7.1 Analysis for WVS
  - 7.2 Analysis for IMM
8. TELEMETRY ANALYSIS
  - 8.1 Number of Missing Lines
  - 8.2 Number of Gaps

---

## 1 - DATA SUMMARY

### 1.1 - Summary tables

[ [BACK TO MENU](#) ]

WVS				GM1				APM				IMM				WSM				MS			
Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Beam	Pol	#	Center	Time	Pol	Modules
PDE	IS1	V/V	5	PDE	WS	H/H	33	PDE	IS1	H/H	1	PDE	IS2	H/H	1	PDE	WS	H/H	25	PDE	2011-06-26 00:13:15	V	320
PDE	IS2	V/V	28	PDK	WS	H/H	47	PDE	IS2	H/H	1	PDE	IS6	H/H	9	PDE	WS	V/V	4	PDE	2011-06-26 21:56:17	H	320
PDK	IS2	V/V	26					PDE	IS4	V/H	4	PDK	IS6	H/H	1	PDK	WS	H/H	13	PDE	2011-06-26 23:36:31	V	320
								PDE	IS4	V/V	1					PDK	WS	V/V	1				
								PDK	IS4	H/H	1												
								PDK	IS4	V/H	1												

## 1.2 - Lists of products used

[ [BACK TO MENU](#) ]

[\[TXT\]](#) [\[XLS\]](#) List\_WVS\_products\_used  
[\[TXT\]](#) [\[XLS\]](#) List\_GM1\_products\_used  
[\[TXT\]](#) [\[XLS\]](#) List\_APM\_products\_used  
[\[TXT\]](#) [\[XLS\]](#) List\_IMM\_products\_used  
[\[TXT\]](#) [\[XLS\]](#) List\_WSM\_products\_used  
[\[TXT\]](#) [\[XLS\]](#) List\_MS\_products\_used

## 2 - AUXILIARY FILES ANALYSIS

### 2.1 - IECF operational ADFs list

[ [BACK TO MENU](#) ]

ADFs disseminated for ASAR
ASA_CON_AXVIEC20110526_075001_20101027_215740_20141231_000000
ASA_INS_AXVIEC20110124_114858_20101228_112000_20141231_235959
ASA_XCH_AXVIEC20101222_143057_20020301_000000_20141231_000000
ASA_XCA_AXVIEC20110526_075734_20101027_215740_20141231_000000

### 2.2 - Products with wrong ADFs

[ [BACK TO MENU](#) ]




Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
WVS	0	0	0	0
GM1	0	0	0	0
APM	0	0	0	0
IMM	0	0	0	0
WSM	0	0	0	0

[\[TXT\]](#) [\[XLS\]](#) Check\_ADFs\_WVS  
[\[TXT\]](#) [\[XLS\]](#) Check\_ADFs\_GM1  
[\[TXT\]](#) [\[XLS\]](#) Check\_ADFs\_APM  
[\[TXT\]](#) [\[XLS\]](#) Check\_ADFs\_IMM  
[\[TXT\]](#) [\[XLS\]](#) Check\_ADFs\_WSM

### 3 - MODULE STEPPING PRODUCTS ANALYSIS







### 3.2 - H/H polarisation


[ [BACK TO MENU](#) ]

SECOND FIXED REFERENCE	PREVIOUS PRODUCT REFERENCE
Pre-launch reference (2001-02-09)	Previous product in the same polarisation

Reference: 2001-02-09 13:50:42 H RxGain  
 Test : 2011-06-26 21:56:17 H




Reference: 2011-06-25 22:33:01 H RxGain  
 Test : 2011-06-26 21:56:17 H







Reference: 2001-02-09 13:50:42 H RxPhase  
 Test : 2011-06-26 21:56:17 H



Reference: 2011-06-25 22:33:01 H RxPhase  
 Test : 2011-06-26 21:56:17 H







## 4 - CALIBRATION PULSES ANALYSIS

### 4.1 - Analysis for WVS IS2 V/V

#### 4.1.1 - Temporal Evolution Analysis for WVS IS2 V/V


[ BACK TO MENU ]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]




Calibration pulses for WVS IS2 V/V




26-Jun



26-Jun




26-Jun



26-Jun


rows: - 1 - 5 - 9 - 13 - 17 - 21 - 25 - 29

Transmit power (P1 - P1a) for WVS IS2 V/V



26-Jun

Transmit power (P1 - P1a) for WVS IS2 V/V




26-Jun

rows: - 1 - 5 - 9 - 13 - 17 - 21 - 25 - 29

#### 4.1.2 - All Rows Analysis for WVS IS2 V/V

[ [BACK TO MENU](#) ]





## 4.2 - Analysis for GM1 SS3 H/H

### 4.2.1 - Temporal Evolution Analysis for GM1 SS3 H/H


[ BACK TO MENU ]

Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]


Rows: [2/6/10/14/18/22/26/30] [3/7/11/15/19/23/27/31] [4/8/12/16/20/24/28/32]



Calibration pulses for GM1 SS3 H/H




Transmit power (P1 - P1a) for GM1 SS3 H/H



#### 4.2.2 - All Rows Analysis for GM1 SS3 H/H

[ [BACK TO MENU](#) ]





## 5 - DOPPLER ANALYSIS


### 5.1 - Analysis for WVS IS2 V/V

#### 5.1.1 - Doppler MAP Analysis for WVS IS2 V/V

[ [BACK TO MENU](#) ]








### 5.1.2 - Doppler ANX Analysis for WVS IS2 V/V

[ [BACK TO MENU](#) ]






## 5.2 - Analysis for GM1 SS1 H/H

### 5.2.1 - Doppler MAP Analysis for GM1 SS1 H/H

[ [BACK TO MENU](#) ]








### 5.2.2 - Doppler ANX Analysis for GM1 SS1 H/H

[ [BACK TO MENU](#) ]






### 5.3 - Doppler JUMPS Analysis for WSM

[ [BACK TO MENU](#) ]









## 6 - CHIRP ANALYSIS

### 6.1 - Analysis for WSM SS1 H/H

#### 6.1.1 - ScaleFactor

[ [BACK TO MENU](#) ]







## 6.2 - Analysis for WSM SS1 V/V

### 6.2.1 - ScaleFactor

[ [BACK TO MENU](#) ]






## 7 - RAW DATA ANALYSIS

### 7.1 - Analysis for WVS

[ [BACK TO MENU](#) ]

--	--	--








Channel	Statistics	DSS-B
MEAN I	mean	0.000642668
	stdev	1.00741e-07
MEAN Q	mean	0.000481868
	stdev	1.84314e-07
Channel	Statistics	DSS-B
STDEV I	mean	0.152637
	stdev	0.00135466
STDEV Q	mean	0.153227
	stdev	0.00138168

## 7.2 - Analysis for IMM

[ [BACK TO MENU](#) ]






Channel	Statistics	DSS-B
MEAN I	mean	0.000272240
	stdev	5.28357e-09
MEAN Q	mean	0.000535519
	stdev	7.09169e-09
Channel	Statistics	DSS-B
STDEV I	mean	0.0672705
	stdev	0.000400172
STDEV Q	mean	0.0675391
	stdev	0.000404708


## 8 - TELEMETRY ANALYSIS

### 8.1 - Number of Missing lines

[ [BACK TO MENU](#) ]








## 8.2 - Number of Gaps

[ [BACK TO MENU](#) ]



#####  
ASAR DAILY REPORT for 110626  
#####

MODE: DAILY  
ANALYSIS: ALL  
DATE: 2011-06-26 00:00:00

Analysis will be performed from 2011-06-26 00:00:00 to 2011-06-26 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/\_110626/

DATA SUMMARY  
#####  
Summary will be performed from 2011-06-26 00:00:00 to 2011-06-26 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/\_110626/DATA\_SUMMARY

Creating directory ./RESULTS/DAILY/\_110626/DATA\_SUMMARY...  
Writing file ./RESULTS/DAILY/\_110626/DATA\_SUMMARY/Data\_summary.html...

\*\*\*\*\*  
Getting WVS products list from 2011-06-26 00:00:00 to 2011-06-26 23:59:59...  
Writing file ./RESULTS/DAILY/\_110626/DATA\_SUMMARY/List\_WVS\_products\_used.xls...  
Writing file ./RESULTS/DAILY/\_110626/DATA\_SUMMARY/List\_WVS\_products\_used.txt...

\*\*\*\*\*  
Getting GM1 products list from 2011-06-26 00:00:00 to 2011-06-26 23:59:59...  
Writing file ./RESULTS/DAILY/\_110626/DATA\_SUMMARY/List\_GM1\_products\_used.xls...  
Writing file ./RESULTS/DAILY/\_110626/DATA\_SUMMARY/List\_GM1\_products\_used.txt...

\*\*\*\*\*  
Getting APM products list from 2011-06-26 00:00:00 to 2011-06-26 23:59:59...  
Writing file ./RESULTS/DAILY/\_110626/DATA\_SUMMARY/List\_APM\_products\_used.xls...  
Writing file ./RESULTS/DAILY/\_110626/DATA\_SUMMARY/List\_APM\_products\_used.txt...

\*\*\*\*\*  
Getting IMM products list from 2011-06-26 00:00:00 to 2011-06-26 23:59:59...  
Writing file ./RESULTS/DAILY/\_110626/DATA\_SUMMARY/List\_IMM\_products\_used.xls...  
Writing file ./RESULTS/DAILY/\_110626/DATA\_SUMMARY/List\_IMM\_products\_used.txt...

\*\*\*\*\*  
Getting WSM products list from 2011-06-26 00:00:00 to 2011-06-26 23:59:59...  
Writing file ./RESULTS/DAILY/\_110626/DATA\_SUMMARY/List\_WSM\_products\_used.xls...  
Writing file ./RESULTS/DAILY/\_110626/DATA\_SUMMARY/List\_WSM\_products\_used.txt...

\*\*\*\*\*  
Getting MS products list from 2011-06-26 00:00:00 to 2011-06-26 23:59:59...  
Writing file ./RESULTS/DAILY/\_110626/DATA\_SUMMARY/List\_MS\_products\_used.xls...  
Writing file ./RESULTS/DAILY/\_110626/DATA\_SUMMARY/List\_MS\_products\_used.txt...

DATA SUMMARY completed  
#####

AUXILIARY FILES ANALYSIS  
#####  
Analysis will be performed from 2011-06-26 00:00:00 to 2011-06-26 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/\_110626/AUXILIARY

Creating directory ./RESULTS/DAILY/\_110626/AUXILIARY...

\*\*\*\*\*  
Looking for the IECF operational ADFs list...





ADF filter 20110626\*current\_3\_IECF\_ADFs.txt  
 Found list 20110626\_030001\_current\_3\_IECF\_ADFs.txt...  
 Extracting ADFs...

ASA\_CON\_AXVIEC20110526\_075001\_20101027\_215740\_20141231\_000000  
 ASA\_INS\_AXVIEC20110124\_114858\_20101228\_112000\_20141231\_235959  
 ASA\_XCH\_AXVIEC20101222\_143057\_20020301\_000000\_20141231\_000000  
 ASA\_XCA\_AXVIEC20110526\_075734\_20101027\_215740\_20141231\_000000

Writing file ./RESULTS/DAILY/\_110626/AUXILIARY/ASAR\_ADFs\_IECF\_List3.html...  
 Writing file ./RESULTS/DAILY/\_110626/AUXILIARY/Auxiliary\_files\_summary.html...

\*\*\*\*\*

Analysing WVS products...

Writing file ./RESULTS/DAILY/\_110626/AUXILIARY/Check\_ADFs\_WVS.xls...  
 Writing file ./RESULTS/DAILY/\_110626/AUXILIARY/Check\_ADFs\_WVS.txt...

ASA_WVS_1PNPDE20110626_000642_000003603104_00016_48737_2439.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110626_003016_000002993104_00016_48737_2438.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110626_003431_000004943104_00016_48737_2448.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110626_004459_000007043104_00016_48737_2449.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110626_012458_000004183104_00017_48738_2452.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110626_013931_000001043104_00017_48738_2454.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110626_014619_000003903104_00017_48738_2456.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110626_021045_000000303104_00017_48738_2457.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110626_021045_000003153104_00017_48738_2472.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110626_022931_000003293104_00018_48739_2474.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110626_031658_000005853104_00018_48739_2475.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110626_032613_000002703104_00018_48739_2491.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110626_035611_000007943104_00018_48739_2493.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110626_041247_000000743104_00019_48740_2496.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110626_045514_000007643104_00019_48740_2498.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110626_045514_000007643104_00019_48740_2500.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110626_050743_000003303104_00019_48740_2513.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110626_053001_000015143104_00019_48740_2528.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110626_063557_000002843104_00020_48741_2526.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110626_064424_000002543104_00020_48741_2525.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110626_212244_000012143104_00029_48750_2643.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110626_214507_000006303104_00029_48750_2645.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110626_221241_000003143104_00029_48750_2650.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110626_221241_000003143104_00029_48750_2653.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110626_221711_000007343104_00029_48750_2666.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110626_230235_000013643104_00030_48751_2670.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110626_233144_000002403104_00030_48751_2671.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDE20110626_235339_000002543104_00030_48751_2672.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110626_064824_000003003104_00020_48741_4506.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110626_071015_000019643104_00020_48741_4511.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110626_082610_000004503104_00021_48742_4544.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110626_085020_000019943104_00021_48742_4547.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110626_095649_000010343104_00022_48743_4567.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110626_103039_000006303104_00022_48743_4568.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110626_104315_000010943104_00022_48743_4571.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110626_104315_000010943104_00022_48743_4572.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110626_112937_000014693104_00023_48744_4611.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110626_121106_000004653104_00023_48744_4614.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110626_122103_000001793104_00023_48744_4612.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110626_122704_000006183104_00023_48744_4617.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110626_130011_000009593104_00024_48745_4646.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110626_135115_000004053104_00024_48745_4650.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110626_144742_000004043104_00025_48746_4674.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110626_150123_000007953104_00025_48746_4677.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110626_153140_000009293104_00025_48746_4678.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110626_154957_000001193104_00026_48747_4681.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110626_163421_000012293104_00026_48747_4707.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110626_171159_000012743104_00026_48747_4710.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

```
ASA_WVS_1PNPDK20110626_180937_000015293104_00027_48748_4723.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110626_185326_000005853104_00027_48748_4724.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110626_190536_000001943104_00027_48748_4728.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110626_194457_000018293104_00028_48749_4763.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110626_203158_000003603104_00028_48749_4767.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_WVS_1PNPDK20110626_205808_000000443104_00029_48750_4769.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```

\*\*\*\*\*

Analysing GM1 products...

Writing file ./RESULTS/DAILY/\_110626/AUXILIARY/Check\_ADFs\_GM1.xls...

Writing file ./RESULTS/DAILY/\_110626/AUXILIARY/Check\_ADFs\_GM1.txt...

```
ASA_GM1_1PNPDE20110626_000011_000003263104_00016_48737_2428.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110626_001433_000005553104_00016_48737_2437.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110626_004330_000000843104_00016_48737_2447.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110626_011109_000008283104_00017_48738_2451.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110626_013243_000004043104_00017_48738_2453.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110626_014158_000002593104_00017_48738_2455.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110626_015331_000006283104_00017_48738_2458.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110626_021640_000007673104_00017_48738_2471.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110626_024047_000001503104_00018_48739_2470.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110626_024502_000001383104_00018_48739_2473.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110626_024812_000010513104_00018_48739_2476.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110626_033405_000005373104_00018_48739_2492.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110626_035048_000002053104_00018_48739_2494.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110626_041448_000018253104_00019_48740_2495.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110626_044849_000002293104_00019_48740_2499.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110626_044849_000002293104_00019_48740_2501.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110626_051402_000004833104_00019_48740_2514.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110626_052846_000000663104_00019_48740_2515.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110626_055556_000002113104_00020_48741_2516.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110626_060145_000005673104_00020_48741_2530.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110626_061325_000005673104_00020_48741_2529.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110626_062916_000003983104_00020_48741_2527.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110626_064126_000001753104_00020_48741_2524.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110626_210656_000001383104_00029_48750_2642.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110626_211457_000003083104_00029_48750_2644.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110626_215735_000006223104_00029_48750_2646.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110626_215735_000006223104_00029_48750_2648.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110626_223338_000001933104_00030_48751_2663.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110626_224949_000000963104_00030_48751_2664.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110626_225627_000003683104_00030_48751_2667.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110626_232608_000001633104_00030_48751_2668.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110626_232858_000000963104_00030_48751_2669.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDE20110626_233749_000006163104_00030_48751_2673.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110626_065411_000003983104_00020_48741_4507.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110626_070857_00000723104_00020_48741_4509.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110626_074347_000001753104_00021_48742_4510.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110626_074822_000004893104_00021_48742_4512.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110626_075548_000003143104_00021_48742_4542.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110626_081844_000004473104_00021_48742_4543.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110626_083429_000005863104_00021_48742_4545.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110626_092555_000004893104_00022_48743_4546.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110626_094803_000001993104_00022_48743_4566.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110626_101441_000005613104_00022_48743_4569.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110626_110219_000007013104_00023_48744_4570.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110626_111638_000001993104_00023_48744_4610.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110626_115453_000005193104_00023_48744_4615.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110626_121939_000000783104_00023_48744_4613.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110626_122438_000001383104_00023_48744_4616.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110626_124036_000009003104_00024_48745_4623.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110626_125448_000003203104_00024_48745_4642.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110626_131654_000002233104_00024_48745_4643.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110626_132213_000003143104_00024_48745_4644.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110626_132733_000009063104_00024_48745_4648.N1  ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
```



ASA_GM1_1PNPDK20110626_135851_000003203104_00024_48745_4647.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110626_140508_000005193104_00024_48745_4649.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110626_141432_000011843104_00025_48746_4653.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110626_143328_000004043104_00025_48746_4673.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110626_145513_000001143104_00025_48746_4676.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110626_151521_000004043104_00025_48746_4675.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110626_152534_000001503104_00025_48746_4679.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110626_154757_000001143104_00025_48746_4680.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110626_155237_000009613104_00026_48747_4682.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110626_161828_000003443104_00026_48747_4704.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110626_162602_000000783104_00026_48747_4703.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110626_162826_000003503104_00026_48747_4706.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110626_165537_000007673104_00026_48747_4708.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110626_173403_000008523104_00027_48748_4709.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110626_174708_000000843104_00027_48748_4721.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110626_175826_000003923104_00027_48748_4722.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110626_183551_000007253104_00027_48748_4725.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110626_190357_000000903104_00027_48748_4726.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110626_190932_000006893104_00028_48749_4727.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110626_192334_000001383104_00028_48749_4729.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110626_192450_000002413104_00028_48749_4756.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110626_193601_000003383104_00028_48749_4762.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110626_201605_000007313104_00028_48749_4764.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110626_204107_000001573104_00028_48749_4765.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110626_204519_000007673104_00028_48749_4768.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110626_205940_000001083104_00029_48750_4766.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_GM1_1PNPDK20110626_210411_000002353104_00029_48750_4770.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

\*\*\*\*\*

Analysing APM products...

Writing file ./RESULTS/DAILY/\_110626/AUXILIARY/Check\_ADFs\_APM.xls...

Writing file ./RESULTS/DAILY/\_110626/AUXILIARY/Check\_ADFs\_APM.txt...

ASA_APM_1PNPDE20110626_031339_000001803104_00018_48739_2467.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20110626_041113_000000853104_00019_48740_2487.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20110626_094247_000000433104_00022_48743_2578.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20110626_145711_000000423104_00025_48746_2625.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20110626_145901_000001203104_00025_48746_2626.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20110626_204346_000000743104_00028_48749_2640.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDE20110626_233055_000000423104_00030_48751_2662.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDK20110626_132040_000000733104_00024_48745_4645.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_APM_1PNPDK20110626_210306_000000423104_00029_48750_4761.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

\*\*\*\*\*

Analysing IMM products...

Writing file ./RESULTS/DAILY/\_110626/AUXILIARY/Check\_ADFs\_IMM.xls...

Writing file ./RESULTS/DAILY/\_110626/AUXILIARY/Check\_ADFs\_IMM.txt...

ASA_IMM_1PNPDE20110626_030542_000003973104_00018_48739_2466.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20110626_035412_000001133104_00018_48739_2488.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20110626_044513_000002033104_00019_48740_2489.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20110626_062251_000003763104_00020_48741_2512.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20110626_080551_000000533104_00021_48742_2551.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20110626_081236_000001093104_00021_48742_2552.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20110626_093752_000002583104_00022_48743_2577.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20110626_094442_000001903104_00022_48743_2579.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20110626_162721_000000523104_00026_48747_2631.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDE20110626_180458_000002733104_00027_48748_2635.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK
ASA_IMM_1PNPDK20110626_123804_000001163104_00024_48745_4628.N1	ASA_CON -> OKASA_INS -> OKASA_XCH -> OKASA_XCA -> OK

\*\*\*\*\*



Analysing WSM products...

Writing file ./RESULTS/DAILY/\_110626/AUXILIARY/Check\_ADFs\_WSM.xls...
Writing file ./RESULTS/DAILY/\_110626/AUXILIARY/Check\_ADFs\_WSM.txt...

ASA\_WSM\_1PNPDE20110626\_002352\_000003733104\_00016\_48737\_2422.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
ASA\_WSM\_1PNPDE20110626\_010446\_000003733104\_00017\_48738\_2446.N1 ASA\_CON -> OKASA\_INS -> OKASA\_XCH -> OKASA\_XCA -> OK
... (repeating pattern of file names and status checks) ...

AUXILIARY FILES ANALYSIS completed
#####

MODULE STEPPING ANALYSIS
#####
Analysis will be performed from 2011-06-26 00:00:00 to 2011-06-26 23:59:59
Results will be exported to the directory: ./RESULTS/DAILY/\_110626/MODULE\_STEPPING

Creating directory ./RESULTS/DAILY/\_110626/MODULE\_STEPPING...
Creating directory ./RESULTS/DAILY/\_110626/MODULE\_STEPPING/FIRST\_REFERENCE...
Creating directory ./RESULTS/DAILY/\_110626/MODULE\_STEPPING/SECOND\_REFERENCE...
Creating directory ./RESULTS/DAILY/\_110626/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE...
Deleting old files...



\*\*\*\*\*  
\*\*\*\*\*

Creating images comparing with second reference...

Exporting results to the directory ../../RESULTS/DAILY/\_110626/MODULE\_STEPPING/SECOND\_REFERENCE...

Polarization: H  
Reference product: ASA\_MS\_\_0PNPK20010209\_135042\_0000009A024\_00180\_11700\_0052.N1  
Test product: ASA\_MS\_\_0PNPDE20110626\_215617\_000000163104\_00029\_48750\_0345.N1  
H  
H

../../RESULTS/DAILY/\_110626/MODULE\_STEPPING/SECOND\_REFERENCE/TGH\_20110626\_215617-20010209\_135042.png  
../../RESULTS/DAILY/\_110626/MODULE\_STEPPING/SECOND\_REFERENCE/TPH\_20110626\_215617-20010209\_135042.png  
../../RESULTS/DAILY/\_110626/MODULE\_STEPPING/SECOND\_REFERENCE/RGH\_20110626\_215617-20010209\_135042.png  
../../RESULTS/DAILY/\_110626/MODULE\_STEPPING/SECOND\_REFERENCE/RPH\_20110626\_215617-20010209\_135042.png

Polarization: V  
Reference product: ASA\_MS\_\_0PNPK20010209\_140823\_0000009A024\_00180\_11700\_0054.N1  
Test product: ASA\_MS\_\_0PNPDE20110626\_233631\_000000163104\_00030\_48751\_0346.N1  
V  
V

../../RESULTS/DAILY/\_110626/MODULE\_STEPPING/SECOND\_REFERENCE/TGV\_20110626\_233631-20010209\_140823.png  
../../RESULTS/DAILY/\_110626/MODULE\_STEPPING/SECOND\_REFERENCE/TPV\_20110626\_233631-20010209\_140823.png  
../../RESULTS/DAILY/\_110626/MODULE\_STEPPING/SECOND\_REFERENCE/RGV\_20110626\_233631-20010209\_140823.png  
../../RESULTS/DAILY/\_110626/MODULE\_STEPPING/SECOND\_REFERENCE/RPV\_20110626\_233631-20010209\_140823.png

\*\*\*\*\*  
\*\*\*\*\*

Creating images comparing with previous product reference...

Exporting results to the directory ../../RESULTS/DAILY/\_110626/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE...

Polarization: H  
Reference product: ASA\_MS\_\_0PNPDE20110625\_223301\_000000163104\_00015\_48736\_0343.N1  
Test product: ASA\_MS\_\_0PNPDE20110626\_215617\_000000163104\_00029\_48750\_0345.N1  
H  
H

../../RESULTS/DAILY/\_110626/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/TGH\_20110626\_215617-20110625\_223301.png  
../../RESULTS/DAILY/\_110626/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/TPH\_20110626\_215617-20110625\_223301.png  
../../RESULTS/DAILY/\_110626/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/RGH\_20110626\_215617-20110625\_223301.png  
../../RESULTS/DAILY/\_110626/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/RPH\_20110626\_215617-20110625\_223301.png

Polarization: V  
Reference product: ASA\_MS\_\_0PNPDE20110626\_001315\_000000163104\_00016\_48737\_0344.N1  
Test product: ASA\_MS\_\_0PNPDE20110626\_233631\_000000163104\_00030\_48751\_0346.N1  
V  
V

../../RESULTS/DAILY/\_110626/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/TGV\_20110626\_233631-20110626\_001315.png  
../../RESULTS/DAILY/\_110626/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/TPV\_20110626\_233631-20110626\_001315.png  
../../RESULTS/DAILY/\_110626/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/RGV\_20110626\_233631-20110626\_001315.png  
../../RESULTS/DAILY/\_110626/MODULE\_STEPPING/PREVIOUS\_PRODUCT\_REFERENCE/RPV\_20110626\_233631-20110626\_001315.png

MODULE\_STEPPING ANALYSIS completed  
#####

CALIBRATION PULSES ANALYSIS  
#####

Creating directory ./RESULTS/DAILY/\_110626/CALIBRATION\_PULSES...

\*\*\*\*\*  
\*\*\*\*\*

ALL ROWS Analysis will be performed from 2011-06-26 00:00:00 to 2011-06-26 23:59:59

Analysing products WVS IS2 V/V

Writing image ../../RESULTS/DAILY/\_110626//CALIBRATION\_PULSES/Calibration\_pulses\_all\_rows\_WVS\_IS2\_VV.png...  
Analysing products GM1 SS3 H/H  
Writing image ../../RESULTS/DAILY/\_110626//CALIBRATION\_PULSES/Calibration\_pulses\_all\_rows\_GM1\_SS3\_HH.png...

\*\*\*\*\*  
\*\*\*\*\*  
TEMPORAL EVOLUTION Analysis will be performed from 2011-06-26 00:00:00 to 2011-06-26 23:59:59

Analysing products WVS IS2 V/V  
Getting calibration pulses data for WVS IS2 V/V from 2011-06-26 00:00:00 to 2011-06-26 23:59:59. Rows: 1/5/9/13/17/21/25/29  
Writing file ./RESULTS/DAILY/\_110626/CALIBRATION\_PULSES/Calibration\_pulses\_data\_WVS\_IS2\_VV\_2011-06-26\_1.dat...  
Writing ../../RESULTS/DAILY/\_110626//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_WVS\_IS2\_VV\_1.png...  
Writing ../../RESULTS/DAILY/\_110626//CALIBRATION\_PULSES/Transmit\_Power\_WVS\_IS2\_VV\_1.png...

Getting calibration pulses data for WVS IS2 V/V from 2011-06-26 00:00:00 to 2011-06-26 23:59:59. Rows: 2/6/10/14/18/22/26/30  
Writing file ./RESULTS/DAILY/\_110626/CALIBRATION\_PULSES/Calibration\_pulses\_data\_WVS\_IS2\_VV\_2011-06-26\_2.dat...  
Writing ../../RESULTS/DAILY/\_110626//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_WVS\_IS2\_VV\_2.png...  
Writing ../../RESULTS/DAILY/\_110626//CALIBRATION\_PULSES/Transmit\_Power\_WVS\_IS2\_VV\_2.png...

Getting calibration pulses data for WVS IS2 V/V from 2011-06-26 00:00:00 to 2011-06-26 23:59:59. Rows: 3/7/11/15/19/23/27/31  
Writing file ./RESULTS/DAILY/\_110626/CALIBRATION\_PULSES/Calibration\_pulses\_data\_WVS\_IS2\_VV\_2011-06-26\_3.dat...  
Writing ../../RESULTS/DAILY/\_110626//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_WVS\_IS2\_VV\_3.png...  
Writing ../../RESULTS/DAILY/\_110626//CALIBRATION\_PULSES/Transmit\_Power\_WVS\_IS2\_VV\_3.png...

Getting calibration pulses data for WVS IS2 V/V from 2011-06-26 00:00:00 to 2011-06-26 23:59:59. Rows: 4/8/12/16/20/24/28/32  
Writing file ./RESULTS/DAILY/\_110626/CALIBRATION\_PULSES/Calibration\_pulses\_data\_WVS\_IS2\_VV\_2011-06-26\_4.dat...  
Writing ../../RESULTS/DAILY/\_110626//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_WVS\_IS2\_VV\_4.png...  
Writing ../../RESULTS/DAILY/\_110626//CALIBRATION\_PULSES/Transmit\_Power\_WVS\_IS2\_VV\_4.png...

Analysing products GM1 SS3 H/H  
Getting calibration pulses data for GM1 SS3 H/H from 2011-06-26 00:00:00 to 2011-06-26 23:59:59. Rows: 1/5/9/13/17/21/25/29  
Writing file ./RESULTS/DAILY/\_110626/CALIBRATION\_PULSES/Calibration\_pulses\_data\_GM1\_SS3\_HH\_2011-06-26\_1.dat...  
Writing ../../RESULTS/DAILY/\_110626//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_GM1\_SS3\_HH\_1.png...  
Writing ../../RESULTS/DAILY/\_110626//CALIBRATION\_PULSES/Transmit\_Power\_GM1\_SS3\_HH\_1.png...

Getting calibration pulses data for GM1 SS3 H/H from 2011-06-26 00:00:00 to 2011-06-26 23:59:59. Rows: 2/6/10/14/18/22/26/30  
Writing file ./RESULTS/DAILY/\_110626/CALIBRATION\_PULSES/Calibration\_pulses\_data\_GM1\_SS3\_HH\_2011-06-26\_2.dat...  
Writing ../../RESULTS/DAILY/\_110626//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_GM1\_SS3\_HH\_2.png...  
Writing ../../RESULTS/DAILY/\_110626//CALIBRATION\_PULSES/Transmit\_Power\_GM1\_SS3\_HH\_2.png...

Getting calibration pulses data for GM1 SS3 H/H from 2011-06-26 00:00:00 to 2011-06-26 23:59:59. Rows: 3/7/11/15/19/23/27/31  
Writing file ./RESULTS/DAILY/\_110626/CALIBRATION\_PULSES/Calibration\_pulses\_data\_GM1\_SS3\_HH\_2011-06-26\_3.dat...  
Writing ../../RESULTS/DAILY/\_110626//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_GM1\_SS3\_HH\_3.png...  
Writing ../../RESULTS/DAILY/\_110626//CALIBRATION\_PULSES/Transmit\_Power\_GM1\_SS3\_HH\_3.png...

Getting calibration pulses data for GM1 SS3 H/H from 2011-06-26 00:00:00 to 2011-06-26 23:59:59. Rows: 4/8/12/16/20/24/28/32  
Writing file ./RESULTS/DAILY/\_110626/CALIBRATION\_PULSES/Calibration\_pulses\_data\_GM1\_SS3\_HH\_2011-06-26\_4.dat...  
Writing ../../RESULTS/DAILY/\_110626//CALIBRATION\_PULSES/Average\_P1\_P1a\_P2\_P3\_GM1\_SS3\_HH\_4.png...  
Writing ../../RESULTS/DAILY/\_110626//CALIBRATION\_PULSES/Transmit\_Power\_GM1\_SS3\_HH\_4.png...

CALIBRATION PULSES ANALYSIS completed  
#####

DOPPLER ANALYSIS  
#####



Creating directory ./RESULTS/DAILY/\_110626/DOPPLER...

\*\*\*\*\*  
\*\*\*\*\*  
DOPPLER ANX Analysis will be performed from 2011-06-26 00:00:00 to 2011-06-26 23:59:59

Analysing products WVS IS2 V/V  
Getting doppler data for WVS IS2 V/V from 2011-06-26 00:00:00 to 2011-06-26 23:59:59...  
Writing file ./RESULTS/DAILY/\_110626/DOPPLER/Doppler\_data\_WVS\_IS2\_VV\_2011-06-26.dat...  
Running IDL program...  
Writing file ../../RESULTS/DAILY/\_110626/DOPPLER/DOPPLER\_ANX\_WVS\_IS2\_VV.png...

Analysing products GM1 SS1 H/H  
Getting doppler data for GM1 SS1 H/H from 2011-06-26 00:00:00 to 2011-06-26 23:59:59...  
Writing file ./RESULTS/DAILY/\_110626/DOPPLER/Doppler\_data\_GM1\_SS1\_HH\_2011-06-26.dat...  
Running IDL program...  
Writing file ../../RESULTS/DAILY/\_110626/DOPPLER/DOPPLER\_ANX\_GM1\_SS1\_HH.png...

\*\*\*\*\*  
\*\*\*\*\*  
DOPPLER JUMPS Analysis will be performed on WSM products from 2011-06-26 00:00:00 to 2011-06-26 23:59:59

Analysing by default products WSM  
Getting doppler jumps data for WSM from 2011-06-26 00:00:00 to 2011-06-26 23:59:59...  
Writing file ./RESULTS/DAILY/\_110626/DOPPLER/Doppler\_Jumps\_data\_WSM\_2011-06-26.dat...  
Running IDL program...  
Writing file ../../RESULTS/DAILY/\_110626/DOPPLER/DOPPLER\_JUMPS\_ANX\_WSM.png...  
Writing file ../../RESULTS/DAILY/\_110626/DOPPLER/DOPPLER\_JUMPS\_Date\_WSM.png...

\*\*\*\*\*  
\*\*\*\*\*  
DOPPLER MAP Analysis will be performed from 2011-06-26 00:00:00 to 2011-06-26 23:59:59

Analysing products WVS IS2 V/V  
Loading predicted doppler values....  
Phase: descending  
Found data...  
Computing mean error doppler estimated-predicted...  
Mean error = -79.411175 Hz  
Writing file ../../RESULTS/DAILY/\_110626//DOPPLER/DOPPLER\_Estimated-Predicted-MeanError\_WVS\_IS2\_VV\_desc.jpg...  
Writing file ../../RESULTS/DAILY/\_110626//DOPPLER/DOPPLER\_Absolute\_WVS\_IS2\_VV\_desc.jpg...

\*\*\*\*\*  
Loading predicted doppler values....  
Phase: ascending  
Found data...  
Computing mean error doppler estimated-predicted...  
Mean error = -69.921160 Hz  
Writing file ../../RESULTS/DAILY/\_110626//DOPPLER/DOPPLER\_Estimated-Predicted-MeanError\_WVS\_IS2\_VV\_asc.jpg...  
Writing file ../../RESULTS/DAILY/\_110626//DOPPLER/DOPPLER\_Absolute\_WVS\_IS2\_VV\_asc.jpg...

\*\*\*\*\*  
Analysing products GM1 SS1 H/H  
Loading predicted doppler values....  
Phase: descending  
Found data...  
Computing mean error doppler estimated-predicted...  
Mean error = -49.847664 Hz  
Writing file ../../RESULTS/DAILY/\_110626//DOPPLER/DOPPLER\_Estimated-Predicted-MeanError\_GM1\_SS1\_HH\_desc.jpg...  
Writing file ../../RESULTS/DAILY/\_110626//DOPPLER/DOPPLER\_Absolute\_GM1\_SS1\_HH\_desc.jpg...

\*\*\*\*\*  
Loading predicted doppler values....

Phase: ascending  
Found data...  
Computing mean error doppler estimated-predicted...  
Mean error = -56.316249 Hz  
Writing file ../../RESULTS/DAILY/\_110626//DOPPLER/DOPPLER\_Estimated-Predicted-MeanError\_GM1\_SS1\_HH\_asc.jpg...  
Writing file ../../RESULTS/DAILY/\_110626//DOPPLER/DOPPLER\_Absolute\_GM1\_SS1\_HH\_asc.jpg...

\*\*\*\*\*

DOPPLER ANALYSIS completed  
#####

CHIRP ANALYSIS  
#####  
Creating directory ./RESULTS/DAILY/\_110626/CHIRP...

\*\*\*\*\*  
\*\*\*\*\*  
CHIRP Analysis will be performed from 2011-06-26 00:00:00 to 2011-06-26 23:59:59

Analysing products WSM SS1 H/H  
\*\*\*\*\*  
Getting ScaleFactor data for WSM SS1 H/H from 2011-06-26 00:00:00 to 2011-06-26 23:59:59...  
Writing file ./RESULTS/DAILY/\_110626/CHIRP/ScaleFactor\_data\_WSM\_SS1\_HH\_2011-06-26.dat...  
Running IDL program...  
Writing file ../../RESULTS/DAILY/\_110626/CHIRP/ScaleFactor\_ANX\_WSM\_SS1\_HH.png...  
Writing file ../../RESULTS/DAILY/\_110626/CHIRP/ScaleFactor\_DATE\_WSM\_SS1\_HH.png...

Analysing products WSM SS1 V/V  
\*\*\*\*\*  
Getting ScaleFactor data for WSM SS1 V/V from 2011-06-26 00:00:00 to 2011-06-26 23:59:59...  
Writing file ./RESULTS/DAILY/\_110626/CHIRP/ScaleFactor\_data\_WSM\_SS1\_VV\_2011-06-26.dat...  
Running IDL program...  
Writing file ../../RESULTS/DAILY/\_110626/CHIRP/ScaleFactor\_ANX\_WSM\_SS1\_VV.png...  
Writing file ../../RESULTS/DAILY/\_110626/CHIRP/ScaleFactor\_DATE\_WSM\_SS1\_VV.png...

CHIRP ANALYSIS completed  
#####

RAW DATA ANALYSIS  
#####  
Analysis will be performed from 2011-06-26 00:00:00 to 2011-06-26 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/\_110626/RAW\_DATA

Creating directory ./RESULTS/DAILY/\_110626/RAW\_DATA...

\*\*\*\*\*  
Getting raw data for WVS from 2011-06-26 00:00:00 to 2011-06-26 23:59:59...  
Writing file ./RESULTS/DAILY/\_110626/RAW\_DATA/Raw\_data\_WVS\_2011-06-26.dat...  
Running IDL program to create graphs...

Creating image ../../RESULTS/DAILY/\_110626/RAW\_DATA/Raw\_data\_WVS\_input\_mean.png...  
Creating image ../../RESULTS/DAILY/\_110626/RAW\_DATA/Raw\_data\_WVS\_input\_stdev.png...  
Creating image ../../RESULTS/DAILY/\_110626/RAW\_DATA/Raw\_data\_WVS\_gain\_imbalance.png...

\*\*\*\*\*  
Getting raw data for IMM from 2011-06-26 00:00:00 to 2011-06-26 23:59:59...  
Writing file ./RESULTS/DAILY/\_110626/RAW\_DATA/Raw\_data\_IMM\_2011-06-26.dat...



Running IDL program to create graphs...

Creating image ../../RESULTS/DAILY/\_110626/RAW\_DATA/Raw\_data\_IMM\_input\_mean.png...  
Creating image ../../RESULTS/DAILY/\_110626/RAW\_DATA/Raw\_data\_IMM\_input\_stdev.png...  
Creating image ../../RESULTS/DAILY/\_110626/RAW\_DATA/Raw\_data\_IMM\_gain\_imbalance.png...

RAW DATA ANALYSIS completed

#####

TELEMETRY ANALYSIS

#####

Analysis will be performed from 2011-06-26 00:00:00 to 2011-06-26 23:59:59  
Results will be exported to the directory: ./RESULTS/DAILY/\_110626/TELEMETRY

Creating directory ./RESULTS/DAILY/\_110626/TELEMETRY...

Looking for gaps and missing lines in WVS products...

\*\*\*\*\*

Checking 28 products from PDE...  
Checking 26 products from PDK...

Looking for gaps and missing lines in GM1 products...

\*\*\*\*\*

Checking 33 products from PDE...  
Checking 47 products from PDK...

Looking for gaps and missing lines in APM products...

\*\*\*\*\*

Checking 7 products from PDE...  
Checking 2 products from PDK...

Looking for gaps and missing lines in IMM products...

\*\*\*\*\*

Checking 10 products from PDE...  
Checking 1 products from PDK...

Looking for gaps and missing lines in WSM products...

\*\*\*\*\*

Checking 29 products from PDE...  
Checking 14 products from PDK...

Creating graph of missing lines and gaps...

\*\*\*\*\*

Creating image: ./RESULTS/DAILY/\_110626/TELEMETRY/TELEMETRY\_Missing\_lines.png...  
Creating image: ./RESULTS/DAILY/\_110626/TELEMETRY/TELEMETRY\_Gaps.png...

TELEMETRY ANALYSIS completed

#####

HTML REPORT generation

#####

Building file ./RESULTS/DAILY/\_110626/asarReport.html...

Building DATA SUMMARY section...  
Building AUXILIARY FILES ANALYSIS section...  
Building MODULE STEPPING ANALYSIS section...  
Building CALIBRATION PULSES ANALYSIS section...  
Building DOPPLER ANALYSIS section...  
Building CHIRP ANALYSIS section...  
Building RAW DATA ANALYSIS section...  
Building TELEMETRY ANALYSIS section...

HTML REPORT generation completed

#####







Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_APM_1PNPDE20110626_031339_000001803104_00018_48739_2467.N1					OK	OK	OK	OK
ASA_APM_1PNPDE20110626_041113_000000853104_00019_48740_2487.N1					OK	OK	OK	OK
ASA_APM_1PNPDE20110626_094247_000000433104_00022_48743_2578.N1					OK	OK	OK	OK
ASA_APM_1PNPDE20110626_145711_000000423104_00025_48746_2625.N1					OK	OK	OK	OK
ASA_APM_1PNPDE20110626_145901_000001203104_00025_48746_2626.N1					OK	OK	OK	OK
ASA_APM_1PNPDE20110626_204346_000000743104_00028_48749_2640.N1					OK	OK	OK	OK
ASA_APM_1PNPDE20110626_233055_000000423104_00030_48751_2662.N1					OK	OK	OK	OK
ASA_APM_1PNPDK20110626_132040_000000733104_00024_48745_4645.N1					OK	OK	OK	OK
ASA_APM_1PNPDK20110626_210306_000000423104_00029_48750_4761.N1					OK	OK	OK	OK



Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_GM1_1PNPDE20110626_000011_000003263104_00016_48737_2428.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110626_001433_000005553104_00016_48737_2437.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110626_004330_000000843104_00016_48737_2447.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110626_011109_000008283104_00017_48738_2451.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110626_013243_000004043104_00017_48738_2453.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110626_014158_000002593104_00017_48738_2455.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110626_015331_000006283104_00017_48738_2458.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110626_021640_000007673104_00017_48738_2471.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110626_024047_000001503104_00018_48739_2470.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110626_024502_000001383104_00018_48739_2473.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110626_024812_000010513104_00018_48739_2476.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110626_033405_000005373104_00018_48739_2492.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110626_035048_000002053104_00018_48739_2494.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110626_041448_000018253104_00019_48740_2495.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110626_044849_000002293104_00019_48740_2499.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110626_044849_000002293104_00019_48740_2501.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110626_051402_000004833104_00019_48740_2514.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110626_052846_000000663104_00019_48740_2515.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110626_055556_000002113104_00020_48741_2516.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110626_060145_000005673104_00020_48741_2530.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110626_061325_000005673104_00020_48741_2529.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110626_062916_000003983104_00020_48741_2527.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110626_064126_000001753104_00020_48741_2524.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110626_210656_000001383104_00029_48750_2642.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110626_211457_000003083104_00029_48750_2644.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110626_215735_000006223104_00029_48750_2646.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110626_215735_000006223104_00029_48750_2648.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110626_223338_000001933104_00030_48751_2663.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110626_224949_000000963104_00030_48751_2664.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110626_225627_000003683104_00030_48751_2667.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110626_232608_000001633104_00030_48751_2668.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110626_232858_000000963104_00030_48751_2669.N1					OK	OK	OK	OK
ASA_GM1_1PNPDE20110626_233749_000006163104_00030_48751_2673.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110626_065411_000003983104_00020_48741_4507.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110626_070857_000000723104_00020_48741_4509.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110626_074347_000001753104_00021_48742_4510.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110626_074822_000004893104_00021_48742_4512.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110626_075548_000003143104_00021_48742_4542.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110626_081844_000004473104_00021_48742_4543.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110626_083429_000005863104_00021_48742_4545.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110626_092555_000004893104_00022_48743_4546.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110626_094803_000001993104_00022_48743_4566.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110626_101441_000005613104_00022_48743_4569.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110626_110219_000007013104_00023_48744_4570.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110626_111638_000001993104_00023_48744_4610.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110626_115453_000005193104_00023_48744_4615.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110626_121939_000000783104_00023_48744_4613.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110626_122438_000001383104_00023_48744_4616.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110626_124036_000009003104_00024_48745_4623.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110626_125448_000003203104_00024_48745_4642.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110626_131654_000002233104_00024_48745_4643.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110626_132213_000003143104_00024_48745_4644.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110626_132733_000009063104_00024_48745_4648.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110626_135851_000003203104_00024_48745_4647.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110626_140508_000005193104_00024_48745_4649.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110626_141432_000011843104_00025_48746_4653.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110626_143328_000004043104_00025_48746_4673.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110626_145513_000001143104_00025_48746_4676.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110626_151521_000004043104_00025_48746_4675.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110626_152534_000001503104_00025_48746_4679.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110626_154757_000001143104_00025_48746_4680.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110626_155237_000009613104_00026_48747_4682.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110626_161828_000003443104_00026_48747_4704.N1					OK	OK	OK	OK
ASA_GM1_1PNPDK20110626_162602_000000783104_00026_48747_4703.N1					OK	OK	OK	OK

ASA_GM1_1PNPDK20110626_162826_000003503104_00026_48747_4706.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20110626_165537_000007673104_00026_48747_4708.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20110626_173403_000008523104_00027_48748_4709.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20110626_174708_00000843104_00027_48748_4721.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20110626_175826_000003923104_00027_48748_4722.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20110626_183551_000007253104_00027_48748_4725.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20110626_190357_00000903104_00027_48748_4726.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20110626_190932_000006893104_00028_48749_4727.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20110626_192334_000001383104_00028_48749_4729.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20110626_192450_000002413104_00028_48749_4756.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20110626_193601_000003383104_00028_48749_4762.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20110626_201605_000007313104_00028_48749_4764.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20110626_204107_000001573104_00028_48749_4765.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20110626_204519_000007673104_00028_48749_4768.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20110626_205940_000001083104_00029_48750_4766.N1	OK	OK	OK	OK
ASA_GM1_1PNPDK20110626_210411_000002353104_00029_48750_4770.N1	OK	OK	OK	OK



Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.

Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA
ASA_IMM_1PNPDE20110626_030542_000003973104_00018_48739_2466.N1				
ASA_IMM_1PNPDE20110626_035412_000001133104_00018_48739_2488.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20110626_044513_000002033104_00019_48740_2489.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20110626_062251_000003763104_00020_48741_2512.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20110626_080551_000000533104_00021_48742_2551.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20110626_081236_000001093104_00021_48742_2552.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20110626_093752_000002583104_00022_48743_2577.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20110626_094442_000001903104_00022_48743_2579.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20110626_162721_000000523104_00026_48747_2631.N1	OK	OK	OK	OK
ASA_IMM_1PNPDE20110626_180458_000002733104_00027_48748_2635.N1	OK	OK	OK	OK
ASA_IMM_1PNPDK20110626_123804_000001163104_00024_48745_4628.N1	OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.


Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WSM_1PNPDE20110626_002352_000003733104_00016_48737_2422.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110626_010446_000003733104_00017_48738_2446.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110626_020413_000003923104_00017_48738_2450.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110626_023536_000003123104_00018_48739_2468.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110626_034308_000003923104_00018_48739_2486.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110626_045241_000001533104_00019_48740_2490.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110626_052210_000003923104_00019_48740_2510.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110626_061118_000001223104_00020_48741_2511.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110626_080106_000002813104_00021_48742_2549.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110626_081527_000001903104_00021_48742_2553.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110626_095122_000003123104_00022_48743_2580.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110626_102407_000003923104_00022_48743_2603.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110626_104145_000000923104_00022_48743_2604.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110626_152206_000001903104_00025_48746_2627.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110626_152809_000002083104_00025_48746_2628.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110626_161245_000003363104_00026_48747_2630.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110626_170827_000002143104_00026_48747_2629.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110626_175158_000002753104_00027_48748_2632.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110626_175653_000000923104_00027_48748_2633.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110626_184801_000003123104_00027_48748_2634.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110626_193150_000002453104_00028_48749_2637.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110626_194143_000001533104_00028_48749_2638.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110626_202820_000002143104_00028_48749_2636.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110626_203839_000001353104_00028_48749_2639.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110626_210922_000003303104_00029_48750_2654.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110626_212008_000000923104_00029_48750_2655.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110626_214344_000000733104_00029_48750_2659.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110626_220802_000002813104_00029_48750_2641.N1					OK	OK	OK	OK
ASA_WSM_1PNPDE20110626_223003_000002143104_00030_48751_2660.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20110626_070056_000001843104_00020_48741_4515.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20110626_070421_000002753104_00020_48741_4514.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20110626_074643_000000923104_00021_48742_4522.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20110626_084418_000003303104_00021_48742_4554.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20110626_092416_000000923104_00022_48743_4557.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20110626_093410_000002083104_00022_48743_4553.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20110626_111403_000001533104_00023_48744_4573.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20110626_120333_000004533104_00023_48744_4629.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20110626_134242_000005143104_00024_48745_4660.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20110626_160838_000002693104_00026_48747_4691.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20110626_174839_000002323104_00027_48748_4717.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20110626_192857_000002083104_00028_48749_4737.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20110626_210231_000000363104_00029_48750_4757.N1					OK	OK	OK	OK
ASA_WSM_1PNPDK20110626_224713_000001533104_00030_48751_4793.N1					OK	OK	OK	OK

Differences with IECF operational ADFs list. If a wrong ADF is used, the filename is reported.





Product	ASA_CON	ASA_INS	ASA_XCH	ASA_XCA				
ASA_WVS_1PNPDE20110626_000642_000003603104_00016_48737_2439.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110626_003016_000002993104_00016_48737_2438.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110626_003431_000004943104_00016_48737_2448.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110626_004459_000007043104_00016_48737_2449.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110626_012458_000004183104_00017_48738_2452.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110626_013931_000001043104_00017_48738_2454.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110626_014619_000003903104_00017_48738_2456.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110626_021045_000000303104_00017_48738_2457.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110626_021045_000003153104_00017_48738_2472.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110626_022931_000003293104_00018_48739_2474.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110626_031658_000005853104_00018_48739_2475.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110626_032613_000002703104_00018_48739_2491.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110626_035611_000007943104_00018_48739_2493.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110626_041247_000000743104_00019_48740_2496.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110626_045514_000007643104_00019_48740_2498.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110626_045514_000007643104_00019_48740_2500.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110626_050743_000003303104_00019_48740_2513.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110626_053001_000015143104_00019_48740_2528.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110626_063557_000002843104_00020_48741_2526.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110626_064424_000002543104_00020_48741_2525.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110626_212244_000012143104_00029_48750_2643.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110626_214507_000006303104_00029_48750_2645.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110626_221241_000003143104_00029_48750_2650.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110626_221241_000003143104_00029_48750_2653.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110626_221711_000007343104_00029_48750_2666.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110626_230235_000013643104_00030_48751_2670.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110626_233144_000002403104_00030_48751_2671.N1					OK	OK	OK	OK
ASA_WVS_1PNPDE20110626_235339_000002543104_00030_48751_2672.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110626_064824_000003003104_00020_48741_4506.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110626_071015_000019643104_00020_48741_4511.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110626_082610_000004503104_00021_48742_4544.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110626_085020_000019943104_00021_48742_4547.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110626_095649_000010343104_00022_48743_4567.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110626_103039_000006303104_00022_48743_4568.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110626_104315_000010943104_00022_48743_4571.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110626_104315_000010943104_00022_48743_4572.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110626_112937_000014693104_00023_48744_4611.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110626_121106_000004653104_00023_48744_4614.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110626_122103_000001793104_00023_48744_4612.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110626_122704_000006183104_00023_48744_4617.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110626_130011_000009593104_00024_48745_4646.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110626_135115_000004053104_00024_48745_4650.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110626_144742_000004043104_00025_48746_4674.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110626_150123_000007953104_00025_48746_4677.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110626_153140_000009293104_00025_48746_4678.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110626_154957_000001193104_00026_48747_4681.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110626_163421_000012293104_00026_48747_4707.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110626_171159_000012743104_00026_48747_4710.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110626_180937_000015293104_00027_48748_4723.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110626_185326_000005853104_00027_48748_4724.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110626_190536_000001943104_00027_48748_4728.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110626_194457_000018293104_00028_48749_4763.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110626_203158_000003603104_00028_48749_4767.N1					OK	OK	OK	OK
ASA_WVS_1PNPDK20110626_205808_000000443104_00029_48750_4769.N1					OK	OK	OK	OK




Calibration pulses for GM1 SS3 H/H



Calibration pulses for GM1 SS3 H/H







### Calibration pulses for GM1 SS3 H/H






### Calibration pulses for GM1 SS3 H/H




rows: 4 8 12 16 20 24 28 32

### Calibration pulses for WVS IS2 V/V




### Calibration pulses for WVS IS2 V/V







Calibration pulses for WVS IS2 V/V




26-Jun



26-Jun




26-Jun




26-Jun

rows: \_ 3 \_ 7 \_ 11 \_ 15 \_ 19 \_ 23 \_ 27 \_ 31


Calibration pulses for WVS IS2 V/V




26-Jun



26-Jun




26-Jun






26-Jun

rows: — 4 — 8 — 12 — 16 — 20 — 24 — 28 — 32















rows: \_ 1 \_ 5 \_ 9 \_ 13 \_ 17 \_ 21 \_ 25 \_ 29











26-Jun  
rows: \_ 3 \_ 7 \_ 11 \_ 15 \_ 19 \_ 23 \_ 27 \_ 31







26-Jun  
rows: \_ 4 \_ 8 \_ 12 \_ 16 \_ 20 \_ 24 \_ 28 \_ 32

























Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_APM_1PNPDE20110626_031339_000001803104_00018_48739_2467.N1						IS4	V/H	104	48739	18	5.04
ASA_APM_1PNPDE20110626_041113_000000853104_00019_48740_2487.N1						IS4	V/H	104	48740	19	5.04
ASA_APM_1PNPDE20110626_094247_000000433104_00022_48743_2578.N1						IS2	H/H	104	48743	22	5.04
ASA_APM_1PNPDK20110626_132040_000000733104_00024_48745_4645.N1						IS4	V/H	104	48745	24	5.04
ASA_APM_1PNPDE20110626_145711_000000423104_00025_48746_2625.N1						IS4	V/H	104	48746	25	5.04
ASA_APM_1PNPDE20110626_145901_000001203104_00025_48746_2626.N1						IS4	V/V	104	48746	25	5.04
ASA_APM_1PNPDE20110626_204346_000000743104_00028_48749_2640.N1						IS1	H/H	104	48749	28	5.04
ASA_APM_1PNPDK20110626_210306_000000423104_00029_48750_4761.N1						IS4	H/H	104	48750	29	5.04
ASA_APM_1PNPDE20110626_233055_000000423104_00030_48751_2662.N1						IS4	V/H	104	48751	30	5.04



Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_GM1_1PNPDE20110626_000011_000003263104_00016_48737_2428.N1						SS1	H/H	104	48737	16	5.04
ASA_GM1_1PNPDE20110626_001433_000005553104_00016_48737_2437.N1						SS1	H/H	104	48737	16	5.04
ASA_GM1_1PNPDE20110626_004330_000000843104_00016_48737_2447.N1						SS1	H/H	104	48737	16	5.04
ASA_GM1_1PNPDE20110626_011109_000008283104_00017_48738_2451.N1						SS1	H/H	104	48738	17	5.04
ASA_GM1_1PNPDE20110626_013243_000004043104_00017_48738_2453.N1						SS1	H/H	104	48738	17	5.04
ASA_GM1_1PNPDE20110626_014158_000002593104_00017_48738_2455.N1						SS1	H/H	104	48738	17	5.04
ASA_GM1_1PNPDE20110626_015331_000006283104_00017_48738_2458.N1						SS1	H/H	104	48738	17	5.04
ASA_GM1_1PNPDE20110626_021640_000007673104_00017_48738_2471.N1						SS1	H/H	104	48738	17	5.04
ASA_GM1_1PNPDE20110626_024047_000001503104_00018_48739_2470.N1						SS1	H/H	104	48739	18	5.04
ASA_GM1_1PNPDE20110626_024502_000001383104_00018_48739_2473.N1						SS1	H/H	104	48739	18	5.04
ASA_GM1_1PNPDE20110626_024812_000010513104_00018_48739_2476.N1						SS1	H/H	104	48739	18	5.04
ASA_GM1_1PNPDE20110626_033405_000005373104_00018_48739_2492.N1						SS1	H/H	104	48739	18	5.04
ASA_GM1_1PNPDE20110626_035048_000002053104_00018_48739_2494.N1						SS1	H/H	104	48739	18	5.04
ASA_GM1_1PNPDE20110626_041448_000018253104_00019_48740_2495.N1						SS1	H/H	104	48740	19	5.04
ASA_GM1_1PNPDE20110626_044849_000002293104_00019_48740_2499.N1						SS1	H/H	104	48740	19	5.04
ASA_GM1_1PNPDE20110626_044849_000002293104_00019_48740_2501.N1						SS1	H/H	104	48740	19	5.04
ASA_GM1_1PNPDE20110626_051402_000004833104_00019_48740_2514.N1						SS1	H/H	104	48740	19	5.04
ASA_GM1_1PNPDE20110626_052846_000000663104_00019_48740_2515.N1						SS1	H/H	104	48740	19	5.04
ASA_GM1_1PNPDE20110626_055556_000002113104_00020_48741_2516.N1						SS1	H/H	104	48741	20	5.04
ASA_GM1_1PNPDE20110626_060145_000005673104_00020_48741_2530.N1						SS1	H/H	104	48741	20	5.04
ASA_GM1_1PNPDE20110626_061325_000005673104_00020_48741_2529.N1						SS1	H/H	104	48741	20	5.04
ASA_GM1_1PNPDE20110626_062916_000003983104_00020_48741_2527.N1						SS1	H/H	104	48741	20	5.04
ASA_GM1_1PNPDE20110626_064126_000001753104_00020_48741_2524.N1						SS1	H/H	104	48741	20	5.04
ASA_GM1_1PNPDK20110626_065411_000003983104_00020_48741_4507.N1						SS1	H/H	104	48741	20	5.04
ASA_GM1_1PNPDK20110626_070857_000000723104_00020_48741_4509.N1						SS1	H/H	104	48741	20	5.04
ASA_GM1_1PNPDK20110626_074347_000001753104_00021_48742_4510.N1						SS1	H/H	104	48742	21	5.04
ASA_GM1_1PNPDK20110626_074822_000004893104_00021_48742_4512.N1						SS1	H/H	104	48742	21	5.04
ASA_GM1_1PNPDK20110626_075548_000003143104_00021_48742_4542.N1						SS1	H/H	104	48742	21	5.04
ASA_GM1_1PNPDK20110626_081844_000004473104_00021_48742_4543.N1						SS1	H/H	104	48742	21	5.04
ASA_GM1_1PNPDK20110626_083429_000005863104_00021_48742_4545.N1						SS1	H/H	104	48742	21	5.04
ASA_GM1_1PNPDK20110626_092555_000004893104_00022_48743_4546.N1						SS1	H/H	104	48743	22	5.04
ASA_GM1_1PNPDK20110626_094803_000001993104_00022_48743_4566.N1						SS1	H/H	104	48743	22	5.04
ASA_GM1_1PNPDK20110626_101441_000005613104_00022_48743_4569.N1						SS1	H/H	104	48743	22	5.04
ASA_GM1_1PNPDK20110626_110219_000007013104_00023_48744_4570.N1						SS1	H/H	104	48744	23	5.04
ASA_GM1_1PNPDK20110626_111638_000001993104_00023_48744_4610.N1						SS1	H/H	104	48744	23	5.04
ASA_GM1_1PNPDK20110626_115453_000005193104_00023_48744_4615.N1						SS1	H/H	104	48744	23	5.04
ASA_GM1_1PNPDK20110626_121939_000000783104_00023_48744_4613.N1						SS1	H/H	104	48744	23	5.04
ASA_GM1_1PNPDK20110626_122438_000001383104_00023_48744_4616.N1						SS1	H/H	104	48744	23	5.04
ASA_GM1_1PNPDK20110626_124036_000009003104_00024_48745_4623.N1						SS1	H/H	104	48745	24	5.04
ASA_GM1_1PNPDK20110626_125448_000003203104_00024_48745_4642.N1						SS1	H/H	104	48745	24	5.04
ASA_GM1_1PNPDK20110626_131654_000002233104_00024_48745_4643.N1						SS1	H/H	104	48745	24	5.04
ASA_GM1_1PNPDK20110626_132213_000003143104_00024_48745_4644.N1						SS1	H/H	104	48745	24	5.04
ASA_GM1_1PNPDK20110626_132733_000009063104_00024_48745_4648.N1						SS1	H/H	104	48745	24	5.04
ASA_GM1_1PNPDK20110626_135851_000003203104_00024_48745_4647.N1						SS1	H/H	104	48745	24	5.04
ASA_GM1_1PNPDK20110626_140508_000005193104_00024_48745_4649.N1						SS1	H/H	104	48745	24	5.04
ASA_GM1_1PNPDK20110626_141432_000011843104_00025_48746_4653.N1						SS1	H/H	104	48746	25	5.04
ASA_GM1_1PNPDK20110626_143328_000004043104_00025_48746_4673.N1						SS1	H/H	104	48746	25	5.04
ASA_GM1_1PNPDK20110626_145513_000001143104_00025_48746_4676.N1						SS1	H/H	104	48746	25	5.04
ASA_GM1_1PNPDK20110626_151521_000004043104_00025_48746_4675.N1						SS1	H/H	104	48746	25	5.04
ASA_GM1_1PNPDK20110626_152534_000001503104_00025_48746_4679.N1						SS1	H/H	104	48746	25	5.04
ASA_GM1_1PNPDK20110626_154757_000001143104_00025_48746_4680.N1						SS1	H/H	104	48746	25	5.04
ASA_GM1_1PNPDK20110626_155237_000009613104_00026_48747_4682.N1						SS1	H/H	104	48747	26	5.04
ASA_GM1_1PNPDK20110626_161828_000003443104_00026_48747_4704.N1						SS1	H/H	104	48747	26	5.04
ASA_GM1_1PNPDK20110626_162602_000000783104_00026_48747_4703.N1						SS1	H/H	104	48747	26	5.04
ASA_GM1_1PNPDK20110626_162826_000003503104_00026_48747_4706.N1						SS1	H/H	104	48747	26	5.04
ASA_GM1_1PNPDK20110626_165537_000007673104_00026_48747_4708.N1						SS1	H/H	104	48747	26	5.04
ASA_GM1_1PNPDK20110626_173403_000008523104_00027_48748_4709.N1						SS1	H/H	104	48748	27	5.04
ASA_GM1_1PNPDK20110626_174708_000000843104_00027_48748_4721.N1						SS1	H/H	104	48748	27	5.04
ASA_GM1_1PNPDK20110626_175826_000003923104_00027_48748_4722.N1						SS1	H/H	104	48748	27	5.04
ASA_GM1_1PNPDK20110626_183551_000007253104_00027_48748_4725.N1						SS1	H/H	104	48748	27	5.04
ASA_GM1_1PNPDK20110626_190357_000000903104_00027_48748_4726.N1						SS1	H/H	104	48748	27	5.04
ASA_GM1_1PNPDK20110626_190932_000006893104_00028_48749_4727.N1						SS1	H/H	104	48749	28	5.04
ASA_GM1_1PNPDK20110626_192334_000001383104_00028_48749_4729.N1						SS1	H/H	104	48749	28	5.04
ASA_GM1_1PNPDK20110626_192450_000002413104_00028_48749_4756.N1						SS1	H/H	104	48749	28	5.04
ASA_GM1_1PNPDK20110626_193601_000003383104_00028_48749_4762.N1						SS1	H/H	104	48749	28	5.04
ASA_GM1_1PNPDK20110626_201605_000007313104_00028_48749_4764.N1						SS1	H/H	104	48749	28	5.04
ASA_GM1_1PNPDK20110626_204107_000001573104_00028_48749_4765.N1						SS1	H/H	104	48749	28	5.04

ASA_GM1_1PNPDK20110626_204519_000007673104_00028_48749_4768.N1	SS1	H/H	104	48749	28	5.04
ASA_GM1_1PNPDK20110626_205940_000001083104_00029_48750_4766.N1	SS1	H/H	104	48750	29	5.04
ASA_GM1_1PNPDK20110626_210411_000002353104_00029_48750_4770.N1	SS1	H/H	104	48750	29	5.04
ASA_GM1_1PNPDE20110626_210656_000001383104_00029_48750_2642.N1	SS1	H/H	104	48750	29	5.04
ASA_GM1_1PNPDE20110626_211457_000003083104_00029_48750_2644.N1	SS1	H/H	104	48750	29	5.04
ASA_GM1_1PNPDE20110626_215735_000006223104_00029_48750_2646.N1	SS1	H/H	104	48750	29	5.04
ASA_GM1_1PNPDE20110626_215735_000006223104_00029_48750_2648.N1	SS1	H/H	104	48750	29	5.04
ASA_GM1_1PNPDE20110626_223338_000001933104_00030_48751_2663.N1	SS1	H/H	104	48751	30	5.04
ASA_GM1_1PNPDE20110626_224949_000000963104_00030_48751_2664.N1	SS1	H/H	104	48751	30	5.04
ASA_GM1_1PNPDE20110626_225627_000003683104_00030_48751_2667.N1	SS1	H/H	104	48751	30	5.04
ASA_GM1_1PNPDE20110626_232608_000001633104_00030_48751_2668.N1	SS1	H/H	104	48751	30	5.04
ASA_GM1_1PNPDE20110626_232858_000000963104_00030_48751_2669.N1	SS1	H/H	104	48751	30	5.04
ASA_GM1_1PNPDE20110626_233749_000006163104_00030_48751_2673.N1	SS1	H/H	104	48751	30	5.04


Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_IMM_1PNPDE20110626_030542_000003973104_00018_48739_2466.N1						IS6	H/H	104	48739	18	5.04
ASA_IMM_1PNPDE20110626_035412_000001133104_00018_48739_2488.N1						IS6	H/H	104	48739	18	5.04
ASA_IMM_1PNPDE20110626_044513_000002033104_00019_48740_2489.N1						IS6	H/H	104	48740	19	5.04
ASA_IMM_1PNPDE20110626_062251_000003763104_00020_48741_2512.N1						IS6	H/H	104	48741	20	5.04
ASA_IMM_1PNPDE20110626_080551_000000533104_00021_48742_2551.N1						IS6	H/H	104	48742	21	5.04
ASA_IMM_1PNPDE20110626_081236_000001093104_00021_48742_2552.N1						IS2	H/H	104	48742	21	5.04
ASA_IMM_1PNPDE20110626_093752_000002583104_00022_48743_2577.N1						IS6	H/H	104	48743	22	5.04
ASA_IMM_1PNPDE20110626_094442_000001903104_00022_48743_2579.N1						IS6	H/H	104	48743	22	5.04
ASA_IMM_1PNPDK20110626_123804_000001163104_00024_48745_4628.N1						IS6	H/H	104	48745	24	5.04
ASA_IMM_1PNPDE20110626_162721_000000523104_00026_48747_2631.N1						IS6	H/H	104	48747	26	5.04
ASA_IMM_1PNPDE20110626_180458_000002733104_00027_48748_2635.N1						IS6	H/H	104	48748	27	5.04

Filename	Pol	Timestamp	count(Module)				
ASA_MS__0PNPDE20110626_001315_000000163104_00016_48737_0344.N1	V			2011-06-26	00:13:15	320	
ASA_MS__0PNPDE20110626_215617_000000163104_00029_48750_0345.N1	H			2011-06-26	21:56:17	320	
ASA_MS__0PNPDE20110626_233631_000000163104_00030_48751_0346.N1	V			2011-06-26	23:36:31	320	




Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WSM_1PNPDE20110626_002352_000003733104_00016_48737_2422.N1						SS1	H/H	104	48737	16	5.04
ASA_WSM_1PNPDE20110626_010446_000003733104_00017_48738_2446.N1						SS1	H/H	104	48738	17	5.04
ASA_WSM_1PNPDE20110626_020413_000003923104_00017_48738_2450.N1						SS1	H/H	104	48738	17	5.04
ASA_WSM_1PNPDE20110626_023536_000003123104_00018_48739_2468.N1						SS1	V/V	104	48739	18	5.04
ASA_WSM_1PNPDE20110626_034308_000003923104_00018_48739_2486.N1						SS1	H/H	104	48739	18	5.04
ASA_WSM_1PNPDE20110626_045241_000001533104_00019_48740_2490.N1						SS1	V/V	104	48740	19	5.04
ASA_WSM_1PNPDE20110626_052210_000003923104_00019_48740_2510.N1						SS1	H/H	104	48740	19	5.04
ASA_WSM_1PNPDE20110626_061118_000001223104_00020_48741_2511.N1						SS1	H/H	104	48741	20	5.04
ASA_WSM_1PNPDK20110626_070056_000001843104_00020_48741_4515.N1						SS1	H/H	104	48741	20	5.04
ASA_WSM_1PNPDK20110626_070421_000002753104_00020_48741_4514.N1						SS1	H/H	104	48741	20	5.04
ASA_WSM_1PNPDK20110626_074643_000000923104_00021_48742_4522.N1						SS1	H/H	104	48742	21	5.04
ASA_WSM_1PNPDE20110626_080106_000002813104_00021_48742_2549.N1						SS1	H/H	104	48742	21	5.04
ASA_WSM_1PNPDE20110626_081527_000001903104_00021_48742_2553.N1						SS1	H/H	104	48742	21	5.04
ASA_WSM_1PNPDK20110626_084418_000003303104_00021_48742_4554.N1						SS1	H/H	104	48742	21	5.04
ASA_WSM_1PNPDK20110626_092416_000000923104_00022_48743_4557.N1						SS1	H/H	104	48743	22	5.04
ASA_WSM_1PNPDK20110626_093410_000002083104_00022_48743_4553.N1						SS1	H/H	104	48743	22	5.04
ASA_WSM_1PNPDE20110626_095122_000003123104_00022_48743_2580.N1						SS1	H/H	104	48743	22	5.04
ASA_WSM_1PNPDE20110626_102407_000003923104_00022_48743_2603.N1						SS1	H/H	104	48743	22	5.04
ASA_WSM_1PNPDE20110626_104145_000000923104_00022_48743_2604.N1						SS1	H/H	104	48743	22	5.04
ASA_WSM_1PNPDK20110626_111403_000001533104_00023_48744_4573.N1						SS1	H/H	104	48744	23	5.04
ASA_WSM_1PNPDK20110626_120333_000004533104_00023_48744_4629.N1						SS1	H/H	104	48744	23	5.04
ASA_WSM_1PNPDK20110626_134242_000005143104_00024_48745_4660.N1						SS1	H/H	104	48745	24	5.04
ASA_WSM_1PNPDE20110626_152206_000001903104_00025_48746_2627.N1						SS1	H/H	104	48746	25	5.04
ASA_WSM_1PNPDE20110626_152809_000002083104_00025_48746_2628.N1						SS1	H/H	104	48746	25	5.04
ASA_WSM_1PNPDK20110626_160838_000002693104_00026_48747_4691.N1						SS1	H/H	104	48747	26	5.04
ASA_WSM_1PNPDE20110626_161245_000003363104_00026_48747_2630.N1						SS1	H/H	104	48747	26	5.04
ASA_WSM_1PNPDE20110626_170827_000002143104_00026_48747_2629.N1						SS1	H/H	104	48747	26	5.04
ASA_WSM_1PNPDK20110626_174839_000002323104_00027_48748_4717.N1						SS1	H/H	104	48748	27	5.04
ASA_WSM_1PNPDE20110626_175158_000002753104_00027_48748_2632.N1						SS1	H/H	104	48748	27	5.04
ASA_WSM_1PNPDE20110626_175653_000000923104_00027_48748_2633.N1						SS1	H/H	104	48748	27	5.04
ASA_WSM_1PNPDE20110626_184801_000003123104_00027_48748_2634.N1						SS1	H/H	104	48748	27	5.04
ASA_WSM_1PNPDK20110626_192857_000002083104_00028_48749_4737.N1						SS1	H/H	104	48749	28	5.04
ASA_WSM_1PNPDE20110626_193150_000002453104_00028_48749_2637.N1						SS1	H/H	104	48749	28	5.04
ASA_WSM_1PNPDE20110626_194143_000001533104_00028_48749_2638.N1						SS1	V/V	104	48749	28	5.04
ASA_WSM_1PNPDE20110626_202820_000002143104_00028_48749_2636.N1						SS1	H/H	104	48749	28	5.04
ASA_WSM_1PNPDE20110626_203839_000001353104_00028_48749_2639.N1						SS1	V/V	104	48749	28	5.04
ASA_WSM_1PNPDK20110626_210231_000000363104_00029_48750_4757.N1						SS1	V/V	104	48750	29	5.04
ASA_WSM_1PNPDE20110626_210922_000003303104_00029_48750_2654.N1						SS1	H/H	104	48750	29	5.04
ASA_WSM_1PNPDE20110626_212008_000000923104_00029_48750_2655.N1						SS1	H/H	104	48750	29	5.04
ASA_WSM_1PNPDE20110626_214344_000000733104_00029_48750_2659.N1						SS1	H/H	104	48750	29	5.04
ASA_WSM_1PNPDE20110626_220802_000002813104_00029_48750_2641.N1						SS1	H/H	104	48750	29	5.04
ASA_WSM_1PNPDE20110626_223003_000002143104_00030_48751_2660.N1						SS1	H/H	104	48751	30	5.04
ASA_WSM_1PNPDK20110626_224713_000001533104_00030_48751_4793.N1						SS1	H/H	104	48751	30	5.04


Filename	Beam	Pol	CycleNumber	absOrbit	relOrbit	procVersion					
ASA_WVS_1PNPDE20110626_000642_000003603104_00016_48737_2439.N1						IS2	V/V	104	48737	16	5.04
ASA_WVS_1PNPDE20110626_003016_000002993104_00016_48737_2438.N1						IS2	V/V	104	48737	16	5.04
ASA_WVS_1PNPDE20110626_003431_000004943104_00016_48737_2448.N1						IS2	V/V	104	48737	16	5.04
ASA_WVS_1PNPDE20110626_003016_000002993104_00016_48737_2438.N1						IS1	V/V	104	48737	16	5.04
ASA_WVS_1PNPDE20110626_004459_000007043104_00016_48737_2449.N1						IS2	V/V	104	48737	16	5.04
ASA_WVS_1PNPDE20110626_012458_000004183104_00017_48738_2452.N1						IS2	V/V	104	48738	17	5.04
ASA_WVS_1PNPDE20110626_013931_000001043104_00017_48738_2454.N1						IS2	V/V	104	48738	17	5.04
ASA_WVS_1PNPDE20110626_014619_000003903104_00017_48738_2456.N1						IS2	V/V	104	48738	17	5.04
ASA_WVS_1PNPDE20110626_021045_000000303104_00017_48738_2457.N1						IS2	V/V	104	48738	17	5.04
ASA_WVS_1PNPDE20110626_021045_000003153104_00017_48738_2472.N1						IS2	V/V	104	48738	17	5.04
ASA_WVS_1PNPDE20110626_022931_000003293104_00018_48739_2474.N1						IS2	V/V	104	48739	18	5.04
ASA_WVS_1PNPDE20110626_031658_000005853104_00018_48739_2475.N1						IS2	V/V	104	48739	18	5.04
ASA_WVS_1PNPDE20110626_032613_000002703104_00018_48739_2491.N1						IS2	V/V	104	48739	18	5.04
ASA_WVS_1PNPDE20110626_031658_000005853104_00018_48739_2475.N1						IS1	V/V	104	48739	18	5.04
ASA_WVS_1PNPDE20110626_035611_000007943104_00018_48739_2493.N1						IS2	V/V	104	48739	18	5.04
ASA_WVS_1PNPDE20110626_041247_000000743104_00019_48740_2496.N1						IS2	V/V	104	48740	19	5.04
ASA_WVS_1PNPDE20110626_045514_000007643104_00019_48740_2498.N1						IS2	V/V	104	48740	19	5.04
ASA_WVS_1PNPDE20110626_045514_000007643104_00019_48740_2500.N1						IS2	V/V	104	48740	19	5.04
ASA_WVS_1PNPDE20110626_050743_000003303104_00019_48740_2513.N1						IS2	V/V	104	48740	19	5.04
ASA_WVS_1PNPDE20110626_053001_000015143104_00019_48740_2528.N1						IS2	V/V	104	48740	19	5.04
ASA_WVS_1PNPDE20110626_063557_000002843104_00020_48741_2526.N1						IS2	V/V	104	48741	20	5.04
ASA_WVS_1PNPDE20110626_064424_000002543104_00020_48741_2525.N1						IS2	V/V	104	48741	20	5.04
ASA_WVS_1PNPDK20110626_064824_000003003104_00020_48741_4506.N1						IS2	V/V	104	48741	20	5.04
ASA_WVS_1PNPDK20110626_071015_000019643104_00020_48741_4511.N1						IS2	V/V	104	48741	20	5.04
ASA_WVS_1PNPDK20110626_082610_000004503104_00021_48742_4544.N1						IS2	V/V	104	48742	21	5.04
ASA_WVS_1PNPDK20110626_085020_000019943104_00021_48742_4547.N1						IS2	V/V	104	48742	21	5.04
ASA_WVS_1PNPDK20110626_095649_000010343104_00022_48743_4567.N1						IS2	V/V	104	48743	22	5.04
ASA_WVS_1PNPDK20110626_103039_000006303104_00022_48743_4568.N1						IS2	V/V	104	48743	22	5.04
ASA_WVS_1PNPDK20110626_104315_000010943104_00022_48743_4571.N1						IS2	V/V	104	48743	22	5.04
ASA_WVS_1PNPDK20110626_104315_000010943104_00022_48743_4572.N1						IS2	V/V	104	48743	22	5.04
ASA_WVS_1PNPDK20110626_112937_000014693104_00023_48744_4611.N1						IS2	V/V	104	48744	23	5.04
ASA_WVS_1PNPDK20110626_121106_000004653104_00023_48744_4614.N1						IS2	V/V	104	48744	23	5.04
ASA_WVS_1PNPDK20110626_122103_000001793104_00023_48744_4612.N1						IS2	V/V	104	48744	23	5.04
ASA_WVS_1PNPDK20110626_122704_000006183104_00023_48744_4617.N1						IS2	V/V	104	48744	23	5.04
ASA_WVS_1PNPDK20110626_130011_000009593104_00024_48745_4646.N1						IS2	V/V	104	48745	24	5.04
ASA_WVS_1PNPDK20110626_135115_000004053104_00024_48745_4650.N1						IS2	V/V	104	48745	24	5.04
ASA_WVS_1PNPDK20110626_144742_000004043104_00025_48746_4674.N1						IS2	V/V	104	48746	25	5.04
ASA_WVS_1PNPDK20110626_150123_000007953104_00025_48746_4677.N1						IS2	V/V	104	48746	25	5.04
ASA_WVS_1PNPDK20110626_153140_000009293104_00025_48746_4678.N1						IS2	V/V	104	48746	25	5.04
ASA_WVS_1PNPDK20110626_154957_000001193104_00026_48747_4681.N1						IS2	V/V	104	48747	26	5.04
ASA_WVS_1PNPDK20110626_163421_000012293104_00026_48747_4707.N1						IS2	V/V	104	48747	26	5.04
ASA_WVS_1PNPDK20110626_171159_000012743104_00026_48747_4710.N1						IS2	V/V	104	48747	26	5.04
ASA_WVS_1PNPDK20110626_180937_000015293104_00027_48748_4723.N1						IS2	V/V	104	48748	27	5.04
ASA_WVS_1PNPDK20110626_185326_000005853104_00027_48748_4724.N1						IS2	V/V	104	48748	27	5.04
ASA_WVS_1PNPDK20110626_190536_000001943104_00027_48748_4728.N1						IS2	V/V	104	48748	27	5.04
ASA_WVS_1PNPDK20110626_194457_000018293104_00028_48749_4763.N1						IS2	V/V	104	48749	28	5.04
ASA_WVS_1PNPDK20110626_203158_000003603104_00028_48749_4767.N1						IS2	V/V	104	48749	28	5.04
ASA_WVS_1PNPDK20110626_205808_00000443104_00029_48750_4769.N1						IS2	V/V	104	48750	29	5.04
ASA_WVS_1PNPDE20110626_212244_000012143104_00029_48750_2643.N1						IS2	V/V	104	48750	29	5.04
ASA_WVS_1PNPDE20110626_214507_000006303104_00029_48750_2645.N1						IS2	V/V	104	48750	29	5.04
ASA_WVS_1PNPDE20110626_221241_000003143104_00029_48750_2653.N1						IS2	V/V	104	48750	29	5.04
ASA_WVS_1PNPDE20110626_221241_000003143104_00029_48750_2650.N1						IS2	V/V	104	48750	29	5.04
ASA_WVS_1PNPDE20110626_221711_000007343104_00029_48750_2666.N1						IS2	V/V	104	48750	29	5.04
ASA_WVS_1PNPDE20110626_221241_000003143104_00029_48750_2650.N1						IS1	V/V	104	48750	29	5.04
ASA_WVS_1PNPDE20110626_221241_000003143104_00029_48750_2653.N1						IS1	V/V	104	48750	29	5.04
ASA_WVS_1PNPDE20110626_230235_000013643104_00030_48751_2670.N1						IS2	V/V	104	48751	30	5.04
ASA_WVS_1PNPDE20110626_233144_000002403104_00030_48751_2671.N1						IS2	V/V	104	48751	30	5.04
ASA_WVS_1PNPDE20110626_235339_000002543104_00030_48751_2672.N1						IS2	V/V	104	48751	30	5.04
ASA_WVS_1PNPDE20110626_235339_000002543104_00030_48751_2672.N1						IS1	V/V	104	48751	30	5.04

































































































26-Jun




26-Jun




26-Jun



26-Jun



26-Jun



26-Jun

