
Summary of Anomalies:

1 - GOME timeline interruption, operation in Nadir Static View
 due to a Spacecraft anomaly, Orb. 30025 at KS
 15:17:40 - 16:56:58
 (see unavailability fax ER2-UNA-2001/005)

2 - Memory Dump (change to the day before):
 address 1300B in E2PROMCOPY changed back to template value 10

Station ID	OK	
MPH Product Confidence	OK	
SPH Window Information	OK	
Command Word Echo Summary	OK	
Instrument Status 1A	OK	
Instrument Status 1B	OK	
Instrument Status 2	OK	
Integration Times Channel 1	OK	
Co-Adding and Cluster Mode Flags	OK	
Integration Times Band 2A	OK	
Integration Times Band 2B	OK	
Integration Times Band 3	OK	
Integration Times Band 4	OK	
Scan Mirror Position		>>timeline interruption
Polarisation Detectors	OK	
FPA Temperatures A	OK	
FPA Temperatures B	OK	
Charge Amp Temperatures	OK	
Other Temperatures A	OK	
DDHU Temperatures	OK	
Optical Bench Temperatures	OK	
Other Temperatures B	OK	
Calibr. Lamp and Instr. Status 3	OK	
Scan Mirror Motor Current	OK	
Selected Temperature A	OK	
Selected Temperature B	OK	
Selected Temperature C	OK	
Channel 1 Summation	OK	
Channel 2 Summation	OK	
Channel 3 Summation	OK	
Channel 4 Summation	OK	
Log pages	OK	
331/318 nm Uncal. Line Ratio	OK	
Uncal. PMDs as RGB signal	OK	
780 nm Uncal. Intensity	OK	

8958 differences found in RAM1 area
 1 differences found in PROMCOPY area

Address	Actual	Template
---------	--------	----------

F0CE	E3	EB
------	----	----

6 differences found in E2PROMCOPY area

Address	Actual	Template
---------	--------	----------

12FDE	0	FF
-------	---	----

12FDF	7	FF
-------	---	----

13003	0	1
-------	---	---

13007	0	1
-------	---	---

16C0D	2D	25
-------	----	----

17D93	2D	25
-------	----	----

0 differences found in E2PROM area

0 differences found in RAM2 area
0 differences found in PROM area