
 Summary of Anomalies:

1 DATA GAPS
 - small gap at KS, dump Orb. 27601
 05:25:06 - 05:25:55

2 - Memory Dump (change to the day before):
 address 1300B in E2PROMCOPY changed from template value 10 to actual 1

 Station ID >>small gap at KS, dump Orb. 27601
 05:25:06 - 05:25:55

MPH Product Confidence OK
 SPH Window Information OK
 Command Word Echo Summary OK
 Instrument Status 1A OK
 Instrument Status 1B OK
 Instrument Status 2 OK
 Integration Times Channel 1 OK
 Co-Adding and Cluster Mode Flags OK
 Integration Times Band 2A OK
 Integration Times Band 2B OK
 Integration Times Band 3 OK
 Integration Times Band 4 OK
 Scan Mirror Position OK
 Polarisation Detectors OK
 FPA Temperatures A OK
 FPA Temperatures B OK
 Charge Amp Temperatures OK
 Other Temperatures A OK
 DDHU Temperatures OK
 Optical Bench Temperatures OK
 Other Temperatures B OK
 Calibr. Lamp and Instr. Status 3 OK
 Scan Mirror Motor Current OK
 Selected Temperature A OK
 Selected Temperature B OK
 Selected Temperature C OK
 Channel 1 Summation OK
 Channel 2 Summation OK
 Channel 3 Summation OK
 Channel 4 Summation OK
 Log pages OK
 331/318 nm Uncal. Line Ratio OK
 Uncal. PMDs as RGB signal OK
 780 nm Uncal. Intensity OK

8980 differences found in RAM1 area
 0 differences found in PROMCOPY area
 35 differences found in E2PROMCOPY area

Address	Actual	Template
10040	7F	47
10041	C0	C7
10042	A3	E0
10043	D	2
10044	B4	C7
10045	44	10
10046	44	FA
10047	B0	46

10048	EB	0
10049	86	2C
1004A	C8	46
1004B	55	C7
1004C	C0	0
1004D	7F	FC
1004E	D	C4
1004F	A3	0
10050	44	FA
10051	B4	5E
10052	B0	C7
10053	44	26
10054	86	0
10055	EB	7
10056	55	26
10057	C8	0
10058	55	47
10059	1	C7
1005A	86	E0
1005B	C8	2
1005C	35	C7
1005D	EB	10
12FDE	0	FF
12FDF	7	FF
13003	0	1
13007	0	1
1300B	1	10

0 differences found in E2PROM area

0 differences found in RAM2 area

0 differences found in PROM area