
Summary of Anomalies:

1 - small gaps at KS, dump Orb. 27850
 16:35:17 - 16:35:26
 16:41:18 - 16:42:05

2 - Memory Dump (change to the day before):
 address 1300B in E2PROMCOPY changed from template value 10 to actual 1

Station ID >>small gaps at KS, dump Orb. 27850
 16:35:17 - 16:35:26
 16:41:18 - 16:42:05

MPH Product Confidence OK
 SPH Window Information OK
 Command Word Echo Summary OK
 Instrument Status 1A OK
 Instrument Status 1B OK
 Instrument Status 2 OK
 Integration Times Channel 1 OK
 Co-Adding and Cluster Mode Flags OK
 Integration Times Band 2A OK
 Integration Times Band 2B OK
 Integration Times Band 3 OK
 Integration Times Band 4 OK
 Scan Mirror Position OK
 Polarisation Detectors OK
 FPA Temperatures A OK
 FPA Temperatures B OK
 Charge Amp Temperatures OK
 Other Temperatures A OK
 DDHU Temperatures OK
 Optical Bench Temperatures OK
 Other Temperatures B OK
 Calibr. Lamp and Instr. Status 3 OK
 Scan Mirror Motor Current OK
 Selected Temperature A OK
 Selected Temperature B OK
 Selected Temperature C OK
 Channel 1 Summation OK
 Channel 2 Summation OK
 Channel 3 Summation OK
 Channel 4 Summation OK
 Log pages OK
 331/318 nm Uncal. Line Ratio OK
 Uncal. PMDs as RGB signal OK
 780 nm Uncal. Intensity OK

8957 differences found in RAM1 area
 0 differences found in PROMCOPY area
 5 differences found in E2PROMCOPY area

Address	Actual	Template
12FDE	0	FF
12FDF	7	FF
13003	0	1
13007	0	1
1300B	1	10

0 differences found in E2PROM area
 0 differences found in RAM2 area
 0 differences found in PROM area

