
Summary of Anomalies:

- 1 - Memory Dump (change to the day before):
 address 1300B in E2PROMCOPY changed from template value 10 to actual 1

Station ID	OK
MPH Product Confidence	OK
SPH Window Information	OK
Command Word Echo Summary	OK
Instrument Status 1A	OK
Instrument Status 1B	OK
Instrument Status 2	OK
Integration Times Channel 1	OK
Co-Adding and Cluster Mode Flags	OK
Integration Times Band 2A	OK
Integration Times Band 2B	OK
Integration Times Band 3	OK
Integration Times Band 4	OK
Scan Mirror Position	OK
Polarisation Detectors	OK
FPA Temperatures A	OK
FPA Temperatures B	OK
Charge Amp Temperatures	OK
Other Temperatures A	OK
DDHU Temperatures	OK
Optical Bench Temperatures	OK
Other Temperatures B	OK
Calibr. Lamp and Instr. Status 3	OK
Scan Mirror Motor Current	OK
Selected Temperature A	OK
Selected Temperature B	OK
Selected Temperature C	OK
Channel 1 Summation	OK
Channel 2 Summation	OK
Channel 3 Summation	OK
Channel 4 Summation	OK
Log pages	OK
331/318 nm Uncal. Line Ratio	OK
Uncal. PMDs as RGB signal	OK
780 nm Uncal. Intensity	OK

8887 differences found in RAM1 area
 0 differences found in PROMCOPY area
 37 differences found in E2PROMCOPY area

Address	Actual	Template
10040	7F	47
10041	C0	C7
10042	A3	E0
10043	D	2
10044	B4	C7
10045	44	10
10046	44	FA
10047	B0	46
10048	89	0
10049	1E	2C
1004A	8B	46
1004B	45	C7
1004C	C0	0

1004D	7F	FC
1004E	D	C4
1004F	A3	0
10050	44	FA
10051	B4	5E
10052	B0	C7
10053	44	26
10054	1E	0
10055	89	7
10056	45	26
10057	8B	0
10058	45	47
10059	1	C7
1005A	1E	E0
1005B	8B	2
1005C	20	C7
1005D	89	10
12FDE	0	FF
12FDF	7	FF
13003	0	1
13007	0	1
1300B	1	10
16EEB	1	0
17FFF	FD	FF

0 differences found in E2PROM area

0 differences found in RAM2 area

0 differences found in PROM area